





The subject aircraft was involved in an incident / accident on <u>8/14/2025</u> rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: <u>8927871627US</u>.

Signed: Underwriters Salvage Company

Date: **10/27/2025**

AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100 Atlanta. GA 30326

| | Engine hours: | Mayle wasta was all | Signature & Licence no.: | |
|-----------|---------------|---------------------------|---------------------------------------------------------------------------------------------|------------------------------|
| Date: | TSN: | TSO: | Work performed: | Licence no.: |
| | | Elemental Aviation | PIPISTRELY- | |
| | | N464LP-1144 | AT 912 LSA | |
| | | 6/24/2024 | | |
| | | AFTT: 1048.4 | | |
| | | | ine Cooling Modification Service Bulletin_ Pipistrel SB-160-00-80-007. Aircraft vice. | |
| | | Jake Perkins LSRM 2743790 | 4-28-2025 | |
| 128/25 11 | 106.2 | Perte | ormed 100hr: inspection WRT Rotax MI | ML-912 Drainedo land resille |
| 43 litres | HeroshellSp | at Plus 4. Install | ed New 01/ fifter PN 1825016, gaste | tring PN#250-010. Performed |
| b smuch t | Engine retu | rwed to service i | James Charles IRINT6623 James | Charles |

| | Engine hours: | | | Signature & | |
|--------------------------------|----------------------------------------------------|----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|---------------------|
| Date: | TSN: | TSO: | Work performed: | Licence no.: | |
| wo: MC | 1895 | i | | Rotax Engine - page 1 of 1 | |
| Wo. IVIC | | 10.0000 | AeroMeph | 000770004 | |
| | Aeromec | h Aircraft Maintena | ance · 6799 N Glen Harbor Blvd · Glendale, AZ 85307 · 6 | 238779334 | · |
| N464L TACH: | | | | October 31, 2024 | |
| bearing 83958 u Roller B | and seal using sing ROTAX 91 earing C3 25-52 | Rotax MMH Ch 2 MMH and 912 2-15. | on Gear Box P/N: 966605, S/N: 85614 Removed hap. 72-10-00, reinstalled customer supplied geal. MML Installed P/N 950-200 - Oil Seal 30X52X7, | r box:P/N 966605, S/N Installed P/N 232-246 - | |
| be in air | worthy condition | and is approved | ordance with a 100HR CONDITION INSPECTION of for return to service at this time. Details of work pork order: MO_1895. | and was determined to erformed are on file with | |
| Alexand | re Velasco A&P | 4813355 | John State of the | | |
| 14/24 N# 26 nd appr | 875.3 5-249.F roved for | Ryn up go returnto | Replaced #2 bottom span od. Engine determined to b service James Charles 152M-A | k plug connector ein girworthy c 4978232 James (| ondition Charles |
| | | | | | |
| | | | | | |

| | Data | Engine | hours: | Work performed: | Signature & Licence no.: |
|---|------------|--------------|--------------|--------------------------------------|------------------------------|
| | Date: | TSN: | TSO: | | Licence no., |
| | 12-21-24 | 910,6 | | Performed annual inspection It | W Rotax MML-912. Drained |
| | oi and re | filled with | 3 litres As | ernshell Sport Plus 4, Installed New | woilfilter PN#825016, |
| | Neurocsk | set ring PN | #250-010. | Cleaned und reuse spark plugs, Per | formed carb sync, Run up |
| | good, Eng | ine determin | ned to be in | airworthy condition and approved | for return to service. |
| | 0 y | | | James Charles LSRM-A 4978232 | ames Charles |
| | 4/14/25 | 1008.0 | | Performed 100 hr inspection wat | Rotax mmL-912, Drained oil |
| | and refill | ed with 31i | tres Acrosh | Ell Sport Plus 4, Installed new oil- | filter PN#825016, New gasket |
| ŀ | Cina PN# 1 | SO NA THE | tall done | KMARK NUGS NGK DCPRTEXS, PERTON | ned carb sync with run-up |
| | and NON. | Engine det | ermined to | be in airworthy condition and ay | proved for return to |
| | Service. | James Char | os iRMIIda | 13 James Charles | |
| | 4/15/25 | 1008 8 | | Replaced EGT#2 SCASOr PN# 9Lda | 370. Performed run-up, NDN. |
| | Engine ap | proved for | return to se | -vice James Charles IRMT 6623 9 | ames Charles |
| | 0 | | | · · | |
| | | | | | |
| Ŋ | | | | | |

Colby Hines IRMT 5264

| | Engine | e hours: | | Signature & | |
|--------------|-----------------------------------------------|-----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|---|
| ate: | TSN: | TSO: | Work performed: | Licence no.: | |
| wo: M | IO_1668 | | AeroMeph | Rotax Engine Squawk page 1 of 1 | |
| | | Aeromech · 6799 | N Glen Harbor Blvd - Glendale, AZ 85307 - 623877 | 9334 | |
| N464 TACH | LP 1: 441.2 | | | April 23, 2024 | |
| balanc | e check of carbs | s using Rotax MM. Pe | bowl flooded due to very small contamination ghed floats. No defects noted. reassembled fu erformed functional run of engine with no defe | el bowl and performed vacuum cts noted at this time. | - |
| With re | espect to the wo with Aeromech | rk performed, this en under work order: MO | gine squawk is approved for return to service 0_1668. | Details of work performed are | |
| Colby F | Hines IRMT 526 | 4 Colly | Min | | - |
| wo | o: MO_1696 | | AeroMeph | Rotax Engine · page 1 of 1 | |
| | | Aeromech · 679 | | 770334 | |
| | | | N Glen Harbor Blvd · Glendale, AZ 85307 · 62387 | 73004 | |
| | 464LP ACH: 514.6 | | 9 N Glen Harbor Blvd · Glendale, AZ 85307 · 62387 | May 16, 2024 | |
| Per | ACH: 514.6 formed engine led P/N 250-01 | 0 - Gasket Ring Rot | nspection as required using manufacturers ax, Installed P/N 825-016 - Oil Filter Rotax, 861-192 - Float Bracket ND, Installed P/N 26 | May 16, 2024 Rotax line MM 05-20-00. In- | |

| | Data | Engine | hours: | Mante wanta uma a de | Signature & |
|---|-----------|------------|--------------|-----------------------------------------------------------|--------------------------|
| 9 | Date: | TSN: | TSO: | Work performed: | Licence no.: |
| | 6-25-24 | 611.9 | 4 | Performed 100hr. inspection | I IAW Rotax MML-912 |
| | | | | FWORKON file at Relentless F | |
| | James | Charles L | 5RM-A 49 | 78232 James Charles A/C app | roved for RTS. |
| | 8-8-24 | | | Performed 100 hr inspection I | W Rotax MML-912 |
| | | | | ledwith 31, tres Aeroshell Sport | |
| | oil filte | ~ PN#82 | 5016-insta | Hed gasket ring PN#250-010. | Installed new spack |
| | plug con | nector PN | #265-249 | Installed new Regulator PNIED | 165-349 Installed |
| | newEG | Tprobe PN | t 966-370 | Installed new Regulator PN#0 for #2 EGT. Engine determine | d to be in airworthy |
| | conditi | appoint | proved fo | r return to service. James Cha | des LSRM-A4978232 |
| | | | * | | James Charles |
|) | | 811.0 | | Performed ongiNe 100 hr. inspection | ON IAW Rotax MML-912 |
| | PN#89910 | 6. Drained | oil replaced | Pwith 3 litres Heroshell Sport Pl | 45 4, Installed New oil |
| ŀ | filter PN | #825-016 | New gaske | tring PN#250-010, Engine determ | nined to be in airworthy |
| | conditio | n and appr | oved for r | otyrn to service. James Charles | es 15 RM-A 4978232 |
| 7 | | | | | James Chriles |

| Date: | Engine | hours: | Work performed: | Signature & Licence no.: |
|-----------------------------|-----------------------------------------------|------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|
| Date. | TSN: | TSO: | Production and the second | |
| 8 | DATE: 02/2 | 14/2024 | | <u>ENGINE</u> |
| Rand | FNG M/N: | 912UL2-01, S/N: 95 | 81147, ENG TT: 313.6, ENG TSO: NEW | |
| E D N B U L | | | TT: 313.6, HOBBS: 313.6 | |
| -Complied with | <u>s:</u> n 100 Hr. Inspection IA | W Rotax Maintenance | Manual for Rotax Engine Type 912 Series, Ref. # MML-912, (P/N: 89 | 9196), Rev. 1 dated July 01, 2021, Chapter 05- |
| 20, Check List/ | Maintenance Schedule | е. | | |
| AD's & SB's -AD research c | ompleted thru Bi-week | kly 2024-03. | | |
| OTHER MAIL | VTENANCE: | Il Sport Plus and new | Rotax Oil Filter, P/N: 825016 IAW Rotax Maintenance Manual for Ro | otax Engine Type 912 Series, Ref. # MML-912, |
| (P/N: 899196), | , Rev. 1 dated July 01, | 2021, Chapter 12-00-0 | 0, Par. 5. otax Maintenance Manual for Rotax Engine Type 912 Series, Ref. # N | MML-912, (P/N: 899196), Rev. 1 dated July 01, |
| -Replaced spa | rk plugs with 4 ea. nev 12-00-00, Par. 6.2 | W P/N: DCPR/E IAW RO | reax iviaintenance includes for the season of the season o | |
| | | ed in accordance with | an Annual / 100 Hr. Inspection, and found to be in airworthy condit | ion |
| | lighte has been maped | | | |
| Chad Barta A&P 5027054 | 46IA | | | |
| | | | END | |
| | | 2/16/2024 | | <u>ENGINE</u> |
| | | | 9581147, ENG TT: 317.3, ENG TSO: NEW AC TT: 317.3, HOBBS: 317.3 | |
| | AINTENANCE: | | | |
| -Removed a | ind replaced #2 (L/H) E | GT Probe with service 0 dated March 2, 2023 | able probe, removed from N474LP, S/N: 1134 and TSN: 374.3, IAW F , Chapter 77-20, as applicable. | ipistrel LSA Aircraft Maintenance Manual, Doc |
| _ | | | | \dashv |
| Chad Barta — A&P 502705 | 446IA Assisted by Sevin | Offver, A&P2827041 & John Sha | rples A&P4088321 | |
| | | | END | |
| | | | | |
| | | | | |

| | Engine | hours: | Moule novformed | Signature & Licence no.: |
|----------------------------------------------------------------|------------------------------------|--------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| Date: | TSN: | TSO: | Work performed: | Licence no |
| OTHER MAIN Removed engin | TENANCE: e carburetors, P/N: 89 | 912UL2-01, S/N: 95 64LP, S/N: 1144, AC 92530 & 892535, disas | 581147, ENG TT: 342.7, ENG TSO: NEW TT: 342.7, HOBBS: 342.7 sembled, cleaned, installed new carb repair kits, P/N: CV#4 2.72, rea: | Seembled and reinstalled on aircraft IAW |
| Rotax Maintena Maintenance M Chad Barta A&P 502705446 | anual for Rotax Engin | c Engine Type 912 Serie te Type 912 Series, Ref | es, Ref. # MML-912, (P/N: 899196, Rev. 1, dated July 01, 2021), Chap # MMH-912, (P/N: 899195, Rev. 0, Edition 2, dated September 01, 2 | ter 12-20-00, as applicable, & Rotax Heavy 2022), Chapter 73-00-10, as applicable. |
| ••••• | | | END | 1 |
| | | 1 | I | · |
| wo: MO | 1652 | | AeroMeph | Rotax Engine - page 1 of 1 |
| | | Aeromech · 67 | 99 N Glen Harbor Blvd · Glendale, AZ 85307 · 623877933 | 34 |
| N464LI TACH: | | | EW (TACH): | April 12, 2024 |
| - Gasket | Ring Rotax, Ir or. | nstalled (8) P/N | equired using manufacturers Rotax line MM 05-20 297-656 - Rotax Spark Plug, Installed (2) P/N 26 | |
| airworthy under wo | condition and is ork order: MO_1 | s approved for re 652. | rdance with a 100HR CONDITION INSPECTION a turn to service at this time. Details of work performe | and was determined to be in ed are on file with Aeromech |
| Colby Hi | nes A&P364998 | 30 IRMT 5264 | Cray a | |

| _ | Engine | hours: | Moule norformed | Signature & Licence no.: |
|----------|--------|--------|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| Date: | TSN: | TSO: | Work performed: | |
| 10/18/23 | 150.1 | | Performed 50 Hr oil change. | Emik |
| | , | | Replaced oil with 3/L's | 440 8699 |
| | | | Of Heroshell Sport plus 4 | , |
| | | | and new tempest oil Filter | |
| | | | Performed 50 Hr oil Change. Replaced of with 3/L's Of Heroshell sport plus 4 and new tempest oil Filter A/C is approved peturn to Service | |
| | | | service | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | • |
| | | | | |
| | | | | |

| _ | Engine hours: | | Signature & | | |
|-------|--------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-------------------|--------------|
| Date: | TSN: | TSO: | Work perfo | rmed: | Licence no.: |
| | Make: Rotax | | Model:912UL | N#: N464LP | |
| | Ser#: G5811 | 52 Engi | ne Total Time: 192.5 | Hobbs: 192.5 | |
| | - | | Aircraft | Total Time: 192.5 | |
| | AMM-128-0 Manufacture AO2) dated (checked and and newoil f 1;78,2;78,3; needed. Run | 0-60-001, cha ers engine sup 01/14/21 and I lubed all con filter. Replac R 78,4;78 over 8 n up, leak and | -811-00-60-7202 Revendix D. Cleaned, s Aeroshell sport plus Comp. check: d all hose clamps as | ; | |
| | | _ | e has been inspected IA found to be in an airwor | | on |
| | | | | Date: 12/04/23 | |
| | MA | 5863 | | | |
| | TE | EK Aircraft servic | e 942 Union Branch Road, Cor | apeake NC 27926 | |
| | | | | | |
| | | | | | |

| _ | Engine | hours: | Warten and arm a de | Signature & | ١. |
|-----------|--------|--------|-----------------------------------------------------------------------------------------------------------------------|--------------|---------------------------|
| Date: | TSN: | TSO: | Work performed: | Licence no.: | |
| 1AV623 | 26.8 | | Performed 25h oil change. Replaced oil w/ 3L's of Aeroshell sout plus 4 and new Tempest oil film IN: AA825706. A/C is | re | |
| | | | oil w/ 32.5 of Aeroshell some | 4277440 | |
| | | | plus 4 and new Tempest oil | | |
| | | | File PN: AA825706. A/C is | | |
| | | | approved for return to service. | | |
| | | | 20 | | |
| | | | Changed oil w/ 3 L's of | 2 nix | |
| | | | Aeroshell sport plus 4 and new tempest oil filter. A/c is approved for return to | 440 8699 | |
| | | | new tempest oil Filter. A/C | | |
| | | | is approved for return to | | |
| 29 Aug 23 | 69.9 | | service. | | |
| J | | | | | 7 |
| | | | | | 1 |
| | | | | | 1 |
| | | | | | \dashv_{\blacktriangle} |

| | Make: Rotax | Model:912UL | N#: N464LP | Signature & Licence no.: |
|------|----------------------------------|------------------------------------|---------------------|--------------------------|
| ate: | Ser#: G581152 | Engine Total Time: 100.5 | Hobbs: 100.5 | Licence no.: |
| | | Aircraf | t Total Time: 100.5 | |
| | Inspected engine I | AW Manufacturers maintenance | manual, (Manual # | |
| | | 01, chapter 50-20 Rev AO9) dat | | |
| | | ine supplement , (Manual# EIM | | |
| | | 21 and referencing part 43 appo | | |
| | | all controls. Changed oil W/3Lts | | |
| | | oile filter. Replaced all plugs W/ | | |
| | ⁻ 1;78,2;77,3;78,4;78 | | | |
| | _ needed. Run up, le | | | |
| | "I certify that thi | | | |
| | inspection | | | |
| ` | | | | |
| | | Z MA | Date: 09/22/23 | |
| | 1 2 m | | | |
| | TEK Aircra | 「 | | |
| | | | | |
| | | | | |
| | - | | | |
| | | | | |
| | + | | | |

Engine installation record:

| | Aircraft: | | e: | Engine | hours: | Signature & |
|-----------|--------------|------------|------|--------|--------|--------------|
| Registr.: | type: | in: | out: | TSN | TSO | Licence no.: |
| | ASHA Trainer | 10.01.2023 | 1 | -00- | 1 | PIPISTREL |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Base record:

| Engine log book number: | | for piston engine |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------------------------|
| Type of engine: | Model: | Engine serial no.: 9581/52 |
| Manufacturer: BRP-Rotax GmbH & Co KG, 4623 Gunskirchen, Austria | | Year of manufacture: Lore |
| Data sheet: | | |
| Take off power:59, \(\)kW | perm. duration: | min at r.p.m. |
| Max. cont. power: 58 kW at 5,500 r.p.m. | | |
| Note: The above mentioned engine is considered to be operationally reliable if operated and maintained in accordance with the Civil Aircraft and Civil Aviation Equipment Order, current issue and the pertinent operational and maintenance instructions. | | |
| Remarks: | | |
| | | ROTAX. |

Date: 27.12. 2022

Signature: PIBISTREL