

# The Standard AIRCRAFT LOG

The subject aircraft was involved in an incident / accident on \_ rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: **0903177159US**.

Signed: Underwriters Salvage Company

Date: 12/11/2024 AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100

		TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Hours: TT	AF: 4504.7	Tach: 711.0
		-I-I-DA 00 4	140 <b>S/N</b> : 28-21409
ake and service No leaks found	ced brake d and syste	fluid. Operate	ed normally. James Stuger At P 2016060TA
	4654R per I and replace	4654R  per Moo I and replaced lower LN	4654R  per Model: PA-28- I and replaced lower LMLG strut-tul

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alteration</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
		Hours: T	TAF: 4485.4 /	/ Hobbs: 691.7
Make:		Mo	odel: PA-28-	-140 S/N: 28-21409
lubricate instrume Inspecte ELT pas 12, Ignit replacin and cleas Services certify the	ed as needed. ent operation. ed and functio ssed all tests. ion Switch, by g both oil cool aned left brake d and bled bra nat this AIRCR	Recharge Replaced nally teste ELT battel functional ler hoses ver caliper. Fakes. Satis	ed aircraft bat induction air d ELT in accory ry expiration I I check per A with new parts Replaced O-rii factorily teste been inspecte	at battery, all controls, and serviced and attery. Inspected cockpit belts, lights, and ar filter element with new Brackett p/n BA 3. cordance with 14 CFR Part 91.207d(1-4) — May 27, 2026. Complied with AD 76-07-AD. Complied with AD 17-14-04 by its, p/n 63901-72, type C hoses. Removed ring, reassembled and reinstalled caliper. ed and checked for leaks - none found. I ted in accordance with an ANNUAL orthy condition END
	D. James Ster Stenger Aviati		ates	Sign: Super Lead Land Control Land Control Land Land Land Land Land Land Land Land

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	04/15/2024 N4654R	Hours: T	TAF: 4503.4	4 / Tach: 709.7
Make:		M	odel: PA-28	8-140 S/N: 28-21409
lubricat instrum Cleane Reset r none for alternat with AC 91.2076	ed tires, brake ed as needed ent operation. d sealant from ivet and replace tor boss mour CF-50. Inspect d(1-4) – FLT researce of the sealant from the sealant	es, electrices, electrices, electrices, Replaced rivet and ced tank sed right mant bracket and full passed all prition Switches	eal system ared aircraft be discrete induction a inner fuel take ealant with red in landing grand alternate inctionally test to the ELT had a sectionally test to the ELT had alternated inctionally test to the ELT had alternated including the entire includi	ce with 14 CFR Part 43 Appendix D. and battery, all controls, and serviced and coattery. Inspected cockpit belts, lights, and air filter element with new Brackett p/n BA 3. ank edges of right fuel tank using Polygone. new. Filled tank and checked for leaks, gear fairing bracket with new part. Replaced tor v-belt with new parts. Treated airframe ested ELT in accordance with 14 CFR Part battery expiration May 27, 2026. Complied tional check per AD. See AD Compliance

### RENNER AVIATION

3600 Carol Kennedy Dr. San Andreas, Ca. 95249

Date: 10-1-2021 N4654R Airframe Tach:660.41 AFTT:4454.11

#### Complied with the following inspections and airworthiness directives:

- 1. Annual/100 hour inspection per 14 CFR Part 43 Appendix D.
- 2. ELT annual inspection per 14 CFR, 91.207 (d) and ACK ICA. OK for service. (ELT battery next due 5/2026, RCPI and Audio Alert batteries due 3/2030).
- 3. Cabin fire extinguisher weight and visual inspection, OK for service.
- 4. AD2020-24-05 Wing spar inspection. By inspection per AD paragraph (g)(1)(i,ii.iii,iv)(2) and Piper SB 1304A parts I and III. No defects noted. Next due 10/1/2028.
- 5. AD2017-14-04 Oil cooler hoses. By visual per paragraph (h). No defects noted. Next due AFTT: 4554.11 Hoses due replacement 10/2022.
- 6. AD76-07-12 R1 Bendix ignition switch. By operational check per paragraph 1, (a-c). No defects noted. Next due 4554.11
- 7. Power flow exhaust ICA. Complied with per Power Flow Doc. PFS-14250-00 rev. I chapter 6.0. No defects noted. New exhaust gaskets installed and hardware torqued per Lycoming SSP1776-4.

#### Replaced the following items:

- Magnetic compass with new Airpath p/n C2300-L4, s/n AS-19619. "Compass requires swing and correction card prior to use for navigation."
- 2. ELT Dorn and Margolin and mount with new ACK ELT model E-04, s/n 36151, installation performed per ACK Installation and Operation Manual p/n E04M Rev. 1.10 dated 06/26/2020 and Advisory Circular 20-11A. Installed on same mount tray and same location as original ELT. Weight & balance and equipment list revised.
- 3. Oil pressure flex hose from engine to airframe p/n 624000-4-0080. Leak check ok.
- 4. Clevis pins and cotter pins for all four cowi latches.
- 5. Both fuel cap gaskets p/n T66815-00.
- 6. Aft stabilator trim cable with new p/n MC62701-047. Installation of cable performed per Piper PA-28 Cherokee service manual Ch. 5-21 thru 5-22 and rigged per ch. 5-23 as revised. Performed travel and operational checks, all ok.
- 7 Aft right roller bearing p/n 452-386 for co-pilots seat.
- 8. Clevis pins and cotter pins with new for entry door hinges.
- 9. Installed missing placards as required by POH items 1, 2, 3, 4, 6, and 7 as listed on pages 3.4 of POH.
- 10. Air filter element p/n BA-3

#### -CONTINUED ON NEXT PAGE-

#### -CONTINUED FROM PREVIOUS PAGE-

Performed the following repairs and/or service items:

1. Removed and installed both fuel tanks and installed Piper SK 765-106V inspection panel kit per Drawing No. 87589 rev. E to facilitate inspection of wing spars per AD2020-24-05. Replaced vent couplings on both fuel tanks and sender gasket p/n MC462-021 on left fuel tank also installed new fuel feed flex hoses for both tanks p/n's 350-6-0140, 350-6-0134 from ACS under order # 14820600 9/10/21. Leak and flow check of fuel system ok. Work performed per Piper PA28-140 Service Manual ch. 9-6,-7 as revised.

2. Installed missing rear bulkhead close out panel p/n 65494-000.

Repaired battery terminal adapter threads.

4. Repositioned fuel primer line at rear of engine to prevent chaffing.

5. Repaired right hand rear engine baffle and repositioned barrel tie strap for proper cylinder cooling.

Corrected throttle and mixture control cable support clamps in engine compartment.

7. Tightened support clamp hardware for shimmy damper.

8. Removed light surface rust from lower left engine mount frame and applied corrosion preventative paint.

9. Stop drilled two small cracks in right hand upper wing skin.

10. Corrected safeties on three aileron cable turn barrels, tensioned cables and checked travels per manufacturers specifications.

Corrected attach hardware for aft seat belts.

12. Tightened battery cable at solenoid attach.

! certify that this aircraft has been inspected in accordance with an Annual/100 Hour inspection and was determined to

be in an airworthy condition.

Renner Brewer A&	P/IA 3177530		

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alte</b> Entries must be endorsed with Name, Rating and Certificate Num Technician or Repair Facility. (See back pages for other specific	ber of	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			Airframe	RENNER AVIATION arol Kennedy Dr., San Andreas, Ca. 95249 Tach:599.24			Date:4-23-		RENNER AVIATION  3600 Carol Kennedy Dr. San Andreas. Ca. 95249  54R Airframe Tach:626.54
2. I	QK1R429K unde Removed Rapco s/n A74396. Rep p/n's RA-D9-18-	stalled amn er W.O. 20. vacuum pu laced Garlo 1, RAB3-5 c ok. "FAA	neter p/n 440- 3336 dated 12 imp p/n 211C oc seal p/n ST -1, three vacu -P-8740-52 S	402, s/n 203336 after overhaul by Air Parts of Lock Haven CRS# 2/17/2020. Operational check ok. CC, s/n 114650 and installed new Rapco pump p/n RAP215CC, 'D-2217 and drive pad gasket p/n 61183, both instrument air filters rum hoses, cleaned out vacuum lines and regulator. Run, leak and Gafety warning given to aircraft owner".			1. Replaced The above	l left fuel tank described rep nner Brewer	ng Maintenance and/or Repairs k drain valve with new CCA-1550. pair or maintenance is certified airworthy and approved for return to service.  A&P/ IA 3177530
4. F 5. F c — a 6. F	Replaced field w Replaced primer cleaned all three and operation cho Removed Aviation	ire from alt line to #2 oprimer noz eck ok. on Instrume	ernator to no cylinder, inve zles. Primer r ent Mfg. Corp	ise filter circuit. Installed new alternator belt p/n S1597-1-37.5  rted flare Tee fitting and primer flex hose from engine mount to engine, and nozzles installed per Lycoming SSP1776-4. Primer system leak			Repairs / N	Date:	ONICS AVIONICS CRS#TH3R867L / GOLD WING AVIATION  : 04-30-2021 Logbook: Airframe Tail Number: N4645R  Tach: 631.03 Model: PA-28-140 Serial: 28-21399
— 7. I — 8. F	Sigma-Tek, Inc. of Adjusted vacuum Installed missing Replaced Wheler	regulator  AFT seat s  rotating b	o model 5000 to 5.5" hg at tops for fronteacon model	DB-20, p/n 23-501-06-9, s/n T36395J. Weight change negligible. Full power. Operational check ok. I seats. And replaced attach hardware for front seat lap belts.  WRML-12 with new Whelen LED beacon model OR36R1W, s/n 420128 c. Weight and balance and equipment list revised and 337 filed this date.			Remo	oved out of tolerance 01720-01545 s/n: 1, tatic system has 1,2 fy that the transpon part 43 appendix F.	200 ft min leak. TEST FAILED Customer will return on state out to reputation and found to comply with 14  ander test(s) required by 91.413 have been performed and found to comply with 14
The	e above describe	d repair or		is certified airworthy and approved for return to service.			FEDERAL	escribed on the abo AVIATION AGENC' TH3R867L RTS Na	Y.It is airworthy, and is AFFROYES TO STATE TO S

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Aiterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE 18. <u>2020</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Ratir Technician or Repair Facility. (See back pa	ng and Certificate Number of
	X	ENT	RY CC	NTINUED FROM PREVIOUS PAGE *	9/1/20		_			exam by
•AD 72 •AD 13	ent ADs not due th -08-06 'Landing G -02-13 'Stabilator	iis inspection ear Torque L Control Systi	: ink inspection' ( em' is due even	lue every 500 hours TIS of torque links, next due @ Tach:1034.1.  2000 hours TIS or 7 years, whichever occurs first. Next compliance is due @ Tach:			<u> </u>		Sky World avi	a tion, Mid lan
	5 or May 2025, wh -14-04 'Oil Cooler			is due every 100 hours TIS; next due @ Tach: 605.86. Oil hose replacement is due every					Airframe	page 1 of 1
8 years	or 1000 hours TIS ver comes first.	, whichever	occurs first; unt	I type "D" hoses are installed. Next replacement is due @ Tach: 1481.0 or Oct 2022,		N4654R			PIPER, PA-28-140, S/N: 28-21409	September 1, 2020
•	that I have Inspectery (PN: BP1020)		•	orframe, found it meets the requirements of 14 CRF Part 91.207(d). Installed new 022.		A pre puro observation	chase insp ons were n	ection was c nade.	carried out using the manufacturers 100hr check	list as a guide and the following
l certify condition		has been ins	ected in accord	lance with 100hr/Annual Inspection Checklist and determined to be in airworthy		1. Cor	npression	check C/O.	1) 72/80 2) 74/80 3) 74/80 4) 76/80.	the making have approach to
				_		2. A v	ery slight o tube.	il leak is ev	ident on the No:- 4 cylinder oil return tube whe	ere the rubber hose connects to
Eric Litt	A&P 1435253 IA		ver			3. A b	ore scope	he in good	was C/O and the following observations were m condition with normal coloration, No:- 1 cylinder	er darrei nas a sinali alea al lile
						H CIV	n'riark na	ritian naar t	the top of the hore which could be eviderice v	i iluiti suitace oxidation, 140 2
						cylir bore	nder barre e. No:- 3&	l has very n 4 cylinders l	ninor score marks at the seven O-clock position barrels were observed to be in good condition	with cross hatching still visible
						i on a	all cylinder	bores.		
					_	4. The	engine be	arer paint is	s in poor condition with light surface corrosion e	ke tube is welded to the shroud
						D. A Se	ection of a ears not to	oout 1/8 of a have been	an inch of the muffler shroud where the air intal welded fully.	We fathe to accord to the outload
							:		upper and lower main landing gear attachment taching hardware was carried out and no defec	noints including a non invasive
							•			
© 1992 ASA						Richard D	eary A & F	3042422 _		

DATE 19	RECORDING Tach Time	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Entries must be of Techniques or Re	endorsed with	Name, Rating an	d Certificate	Number of
AVI	STSIDE ed nose strut with		10601 Observa Manassas, VA 2 (703) 368-8100 NOSE STRUT SE	0110 N4	AND DESCRIPTIONS	LYCOMING Tach: 552.22 8-21409 TTAF: 434 with MIL-PRF-5606F		Feb 12, 2020
Henry :	Zamora A&P 406	50946 <i>NG</i>	VY Ubo	not A		PAGE		/_
				when on	MEX			
		N	The state of the s	,)				
1992 ASA								

d Alteration	Description of Inspections, Tests, Repairs and Alte Entries must be endorsed with Name, Rating and Certificate Num	TOTAL TIME IN	TODAYS FLIGHT	RECORDING TACH	DATE
pecific entrie	Technician or Repair Facility. (See back pages for other specific	SERVICE	rtium	TIME	19
pecific	Technician or Repair Facility. (See back pages for other specific	SERVICE		TIME	19



10601 Observation Road Manassas, VA 20110 (703) 368-8100

LYCOMING Airframe N4654R

Jul 01, 2020 O-320-E2A

Tach: 561.04

PIPER PA-28-140 SN28-21409 TTAF: 4354.74

Performed an Annual Inspection with reference to Piper® Service Manual inspection checklist and the scope and detail of 14 CFR 43 Appendix D. Inspected instruments for operation, condition, and mounting. Verified proper movement of flight controls. Push-pull tubes and rod ends were inspected for security, condition, and operation. Cables, turnbuckles, and pulleys were lubricated IAW servicing instructions. Performed test of all interior and exterior lights. Verified presence of all required placards. Checked cabin heat, ventilation systems, and controls for freedom of movement. Pressure tested exhaust system and inspected engine mounts. Installed new 'No-Blow' gasket (PN: 77611) on #1 exhaust stack. Leak check satisfactory. Installed new EGT probe (PN: 86255) on #3 exhaust stack and performed successful operation test, C/W PowerFlow\* ICA by inspecting and lubricating joints with high-temp anti-seize IAW PFS-14150-INSTALL Section 2.3 & Section 5.0. Next ICA compliance is due at next annual. Installed new Adel clamps (PN: MS21919-DG10) in place of dry-rotted/rusted clamps in engine bay where necessary. Installed new Adel clamps (PNs: MS21919WDG12, MS21919WDG10, MS21919WDG8, MS21919WDG13) where necessary in engine bay to eliminate items cable tied directly to engine mounts. Inspected landing gear system. Serviced NLG OLEO strut with N<sup>2</sup>. Inspected all tires, brakes, wheels, and repacked all bearings. Re-Riveted (PN: 06-00351) RH brake pad onto push plate. Serviced brake fluid reservoir with MIL-PRF-5606H. Fabricated a repair patch from .032" ALCLAD and installed with rivets (PN: MS20470AD4-3) over damaged area on bottom center bulkhead inside fuselage, aft of station #138, and aft of access panel. Removed corrosion with ScotchBrite® and applied Corrosion X\* where necessary on inside of fuselage, aft of station #138, and aft of access panel. Installed '4-Point' Harness as per owner's request IAW "B.A.S. INC. Installation Instructions". Performed test on inertia wheel and verified proper operation. C/W ICA for solid state fuel booster pump IAW Doc. CA35328-800E-MAINT by disassembling and cleaning filter element inside pump. Next ICA compliance is due at next annual. C/W Piper\* MSB 1342 'Stabilator Fitting Inspection' by record search verification that no Stabilator fittings were ordered and installed between April 17 and July 30, 2019, as outlined in step 1 of this SB. No further action is required. C/W Piper SNL #1280 'Rudder Pedal and Bar Assembly Inspection' by performing inspections outlined in paragraph 1; Sections a. & b. within this service letter. No further action is required.

Researched Airframe ADs through June 2020.

•C/W AD 76-07-12 on 25 June 2020 @ Tach: 561.04 'Bendix Ignition Switch' I/A/W Paragraph 1 (a)(b)(c)(d) of this AD, Due every 100 hours. \* ENTRY CONTINUED ON FOLLOWING PAGE \* Next Due Tach: 5247.8.

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	SkyWorld Avionics LLC CRS 9MIR 540-788-9300 Sky	World World
			I certify that this transponder has been	Serial No. 4311 8
			SA-Form-3	REV 1 June a 2018
3 1992 ۸54				



10601 Observation Road Manassas, VA 20110 (703) 368-8100 Airframe N46546 LYCOMING Tach: 539.67 O-320-E2A

A Jun 07, 2019

PIPER PA-28-140 SN28-21409 TTAF: 4333.37

Performed a Annual Inspection with reference to Piper Cherokee Service Manual inspection checklist and the scope and detail of 14 CFR 43 Appendix D. Inspected instruments for operation, condition and mounting. Verified proper movement of flight controls, inspected for security, condition, and operation of rod ends, cables, turnbuckles, pulleys, and lubricated IAW servicing instructions. Checked all lights interior and exterior, verified all required placards. Checked cabin heat, ventilation systems and controls for freedom of movement. Pressure tested exhaust system and inspected engine mounts. Inspected landing gear, all tires, brakes, wheels and repacked all wheel bearings. Installed serviceable brake reservoir P/N 63355-09. Serviced brake system with MIL-PRF-5606H. Removed main battery and battery box. Removed corrosion, cleaned and primed floor of fuselage. Refinished fuselage floor with black acid proof battery box paint. Reinstalled battery box and main battery. Installed a new FAA PMA Lamar Battery Master Solenoid P/N:STS-M12, S/N:80R67037 and a new Master Relay Diode Assembly P/N:62279-000 with reference to Lamar Installation Instructions Drawing No. ST80001 Rev. E. C/W ICA for STC SA02168AT Power Flow Systems Exhaust inspection per Section 2.3 and IAW Section 5.0. Installed missing heat shroud screw and installed required Placard in view of the pilot stating "The Power Flow Systems, Inc. tuned exhaust system installed on this aircraft may cause the aircraft to burn more fuel at certain power/mixture settings. It is the Pilot's responsibility to determine what, if any, change in fuel flow exists and to plan accordingly. Inspection due every 100 hour or annual inspection, next due June 2020. C/W ICA for STC SA02410AT Solid State Fuel Boost Pump by cleaning filter IAW PMA Products, Inc Fuel Boost Pump, Removal, Installation, and Instruction for Continued Airworthiness Document No.CA35328-800E-MAINT. Due every 100 hours or 12 months, next due June 2020 Researched ADs Through June 07, 2019 C/W AD 72-08-06 Landing Gear Torque Link inspection IAW procedure (a) through (d) of this AD. Inspection due every 500 hours TIS of torque

L/W AD 72-08-06 Landing Gear Torque Link inspection IAW procedure (a) through (d) of this AD. Inspection due every 556 Hours 15 of the San Hours 1039.67

C/W AD 76-07-12 Bendix Ignition Switch I/A/W Paragraph 1 (a)(b)(c)(d) of this AD, Due every 100 hours. Next Due Tach:639.67

The following ADs are recurring, but not due at this time.

AD 13-02-13 Stabilator Control System repetitive inspection due every 2000 hours TIS or 7 years which ever occurs first, next due at Tach: 2505.86 or May 2025 which ever occurs first

AD 17-14-04 Oil Cooler Hose Assemblies Inspection is due every 100 hours TIS of hoses, next due Tach:605.86. Oil Hoses were replaced OCT 17, 2014/Tach:481.0. Replacement of hoses is due at accumulates 8 years or 1,000 hours TIS, whichever occurs first, until Type D hoses are installed. Next due OCT 2022 or Tach. 1481.0/AFTT:4274.7

Advised owner/operator that the registration numbers on this aircraft are not in compliance with14 CFR part 45 and AC 45-2E.

I certify that I have Inspected the ELT system in this Airframe, found it meets the requirements of 14 CRF Part 91.207(d). ELT Battery next due March 2020

I certify that this Airframe has been inspected in accordance with 100hr/Annual Inspection Checklist and determined to be in airworthy condition.

David Carter A&P 3186493 IA

SkyWorld Avionics, LLC	5060 Airport Rd. Midland, VA 22728		
Feb <b>a</b> 4 2019	Work Order No. 11038		ions
N4654R S/N: 28-21409	Tach: 5119.6	Page 1 of 1	of
			ies.)
netailed the Annareo Stratus ESG	ADS-B Compliant Transponder Part No. 1530	010-000050. Serial No. 077073 in accordance	
	is ESG Installation Instructions, Document No.		
	AC 43.13-1B Chapters 11 and 12, and AC43.13		
	e with AV-801 Installation Instructions Docum		
	ler Antenna, Part No. in accordance with Docu		
	ver Part No. 153010-000062, Serial No. 3i000		
		Part No. 153010-000029, Serial No. 062605 in	
ccordance with Document No. 60	00840-000041 Rev 1 dated, 15 Dec. 2016.		
PAAA A	Supplement Doc No. 606596 00075 Dog 2.1	J-1, J 27 N 2010	
in FAA Approved Flight Manual	Supplement, Doc. No. 606586-00075 Rev 2.1, oc. No. 600890-000049 Rev. 2.2, dated 21 September 21	dated 27 Nov 2018, was entered the Aircraft	
Virgint Manual. A Phot's Guide, D	000025 Rev. 2.2, dated 20 February 2018 was s		
placed in the aircraft records.	700025 1001. 2.2. dated 20 1 oblidary 2010 Was 5	applied with the STC No. SA04112CFI and	
ideal in the another reside.			
Complete operational tests were p	erformed according to manufacturers' instruction	ons. The equipment performed satisfactory and	
lid not adversely affect existing c	omponents or systems in the aircraft as required	by FAR 23.1309. The installed ADS-B out	
ystem has been shown to meet th	e equipment requirements set forth in 14 CFR 9	91.227.	
	Constant Control of the control		
In electrical load analysis was pe	rformed and found that the continuous aircraft	load on the alternator does not exceed 80% of	
ated capacity. The new weight ar	d balance for the aircraft has been calculated as	s result of this alteration. A copy of the weight	
Aug. 2017 and compass correction	n card installed in aircraft	performed in accordance with AC 43.215 date 7	
14.6. 2017 and compass correction	. vara mountain antique,		
The work described above was in	spected in accordance with current federal aviat	tion regulations and automate are a	
paneals and is approved for retur	n to service.	non regulations and current manufacturers	
• •			
Joshua A Owens	Vain Fedory 4, 2019	Certificate: A&P 4178138	_

E	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Feb.	orld Aviation. 2019 4R S/N: 28-2			port Rd. Midland. VA 22728  der No. 11038  19.6  Page 1 of 1
ground baggage Pages 1 at this ti	with ring termic compartment -2. Verified come.	ing MIL-W inals. Term . All work   ontinuity, p	-22759/16 wir inated opposit AW AC43.13 polarity, tested	charger interface kit Model No. BM-AIK2 by connecting a 2-wire battery charger with 10A inline circuit protection fuse. Attached to battery relay and airframe e end with Anderson SB50 plug with protective cover and mounted in forward /1B and referenced 752-647 BM-AIK2 Installation Instructions, Rev 20161130, with charger and for proper aircraft electrical system operation. No defects noted  Certificate: A&P 4178138

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5/14/18			N4654R	Tach: 505.86 ACTT: 4327.27
Tested E Complie	ELT per FAF	8 91.207 6-07-12	Replaced by ignition	d ELT battery, pn BP-1020. Next replacement due March 2020 switch inspection. Next due at tach 605.85
airworth	that this airc	raft has	been inspe	ected in accordance with an annual inspection and was found
airworth	y at this time	eraft has	been inspe	ected in accordance with an annual inspection and was found  A&P2794644 1A
airworth	y at this time	eraft has		Removed & Replaced Battery with New Concord
airworth	y at this time	eraft has	At	Removed & Replaced Battery with New Concord Battery RG-35AXC S/N . Work IN ACCORDANCE WITH PIPER Service Instructions
1/2/19	537,19	eraft has	At	Removed & Replaced Battery with New Concord Battery RG-35AXC S/N . Work IN

DATE XO 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				(Cont) (4) Starter solenoid to Starter, (5) engine to airfra
				ground, as required by Piper Service Bulletin 836 A. These Casles were replaced with #I gauge Copper Casle
				assemblies which were manufactured by Bogert Aviation
				INC. for this gircraft in accordance with STC SA3531.  NM, drawing number INO6-DR. All Caste assemblies are
102 1.50				EN IPMA Shamped. ASP Contraction 3313011
1/2/19	537.19			Battery box replaced with a battery box in accordance with applicable Bogert Aviation Master
				Document List (MDL) as listed on AMIL SAUTSOLOE.
1/2/19	537.19			ENgine Primer Pump removed and Cleaned. New
				O-rings intelled and lubed. Work completed in
				accordance with Piper service Instructions.
		-		C 1992 ASA

RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			I certify that the transponder tests required by FAR 91.413 have been performed IAW FAR 43 appendix F.  Date 10/17/2014 WO 1490  Signature Wolf Color
-			FAA - PMA
			This tag certifies that Sky-Tec Model No. STS-S12  Serial No. S2S-171518
	TACH	TACH FLIGHT	TACH FLIGHT TIME IN

DATE 10-15	RECORDING Tach Time	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alteration</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)			
119/15	495.71		4317.12	REPLACED CONCORDE BATTERY 12635 PAXC SER* 40720295 T. Schul 223945			
				RG35 AXC SER* 40720295			
				T. Schul 273945			
				Flite Instruments and Avionics 2310 S. Airport Blvd Ste 11 Chordler A7 85286 CS # 6FIR926C 480-516-0308			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286 CS # 6FIR926C 480-516-0308    Reg.#   A/C Make   Model   S/N Tach/hobb			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286  Reg.# A/C Make Model S/N Tach/hobb  U46548 Pige Pa28-440 28-21409  Solution and office the required by \$ 91.413, have been performed			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286  Reg.# A/C Make Model S/N Tach/hobb    480-516-0308    Reg.# A/C Make Model S/N Tach/hobb     465416   Dice   Da26-140   28-21409     I certify that the Static and altimeter, required by § 91.413, have been performed and found to comply with 14 CFR part 43, appendix F.			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286 CS # 6FIR926C 480-516-0308    Reg.#   A/C Make   Model   S/N Tach/hobb			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286  Reg.# A/C Make Model S/N Tach/hobb    Complete   Com			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286  Reg.# A/C Make Model S/N Tach/hobb    Complete   Com			
				2310 S. Airport Blvd Ste 11 Chandler AZ 85286  Reg.# A/C Make Model S/N Tach/hobb    Complete   Com			

DATE 294 3	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/22/13	452.25			REPLACED STABILATER TRIM BEARINGS P/N 452-413, 6PS CHECK UK. APPROVED
				FOR RETURN TO SERVICE
				2794644 A8P
0/17/14	481.0			COMPLIED WITH AD 95-26-13 BY REPLACING
				OCTOBER 2012. NEXT INSPECTION DATE CTACK 581.0. COMPLIED WITH AD 76.07-12 BY DIS CHECK OF IGNIFION/STARTER SIJITH. NEXT DIVE
				AT FACH SOLO. TESTED ELT PER FAR OIL 207.
				REPLACED BRAKE PADS P/M 066-10500 REPLACED MOSE WHEEL BEARING CUPS P/M 13836 1 (ERSIEN THE STATE
© 1992 ASA			•	PACKED WHEEL BEARING

OATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
				HAS BEEN INSPECTED IN AZZERDANCE WITH AN
				ATTHUAL INSPECTION AND IS IN AIRWORTHY
				CONDITION AT THIS TIME.  ASP 279 (1644 1A
			T. J. 491	0, N4654R, Piper PA-28-140, SN 28-21409, 10-17-2014
			Removed I	Bendix King KT 76 Transponder P# 066-1034-00, S# 25123, and endix King KT76A transponder P# 066-1062-00, S# 127696. Units was AW manufactures installation instructions P# 066-05143-0007, Revision 1999. No significant change to the Aircraft weight and balance.  ALT 2744
				© 1992

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alte</b> Entries must be endorsed with Name, Rating and Certificate Nur Technician or Repair Facility. (See back pages for other specific	mharaf
Cleaned in instruction with All has been service.	d fuel system ument panel f D 95-26-13 oi en inspected ir	filters. Re for pilots y il cooler h n accordan	ose inspection	ument vacuum filter. Installed new washer, spacers and bushing in Installed new fuel sumps on left and right fuel tanks. Complied on, AD 76-07-12 ignition switch inspection. I certify this Aircraft innual inspection and is airworthy and approved for return to	
I certification requirements of the control of the certification of the	fy that the ATO	91.413 and street of the stree	nder was tes	ted (in aircraft) as d to comply with 14  CRS# XXZR035Y	

9/ 2013	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
5- 20	430.83			COMPILED WITH AD'S 95-26-13 OIL COSIER HOSE
				INSPECTION AND 76-07-12 IGNITION SWITCH INSPECTION
				FUNCTIONALLY CHECKED EIT IN ACCORDANCE WITH FAR
				91.207d . I certify this AIRCRAFT HAS Been
				INSPECTED IN ALLURDANCE WITH AN ANNUAL INSPECTION
				AND IS A ROBOTHLY AND APPROVED FUR RETURN TO SERVICE
				Affan 355691, APIA
/20	430.83			REPLACED ELT BATTERY # BP1020
				REPLACED BATTERY. CONCORDE RG. 35/4X T. Sulm 273946
				1.5ch 273945
				© 1992 ASA

DATE 19_09 2010	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/14/09	192.0		4024,21	KEPLACED ELT BATTERY
1.20.10	222.6		4054.81	INSTALLED NEW CORCORDE BATTERY
			1-	T. Shu 223945
14/10	261.7		408321	INSTALLED USED DOOR HOLLER
				PURCHASED FROM DAWSON SALVAGE Aviation Services 7. 6ths 223945
			Moore	Aviation Services 1. 6ch 223945

Moore Aviation Services 4702 Fighter Aces Dr. Mesa, AZ. 85215

N5654R Tach 269.53 9-2-2010

#### Airframe

Cleaned fuel system filters. Replaced instrument vacuum filter. Replaced steering knuckle clevis pin. Repaired baffle by oil cooler. Complied with AD 95-26-13 oil cooler hose inspection, AD 76-07-12 ignition switch inspection and AD 10-15-10 Control shaft inspection. I certify this Aircraft has been inspected in accordance with a 100 hour inspection and is airworthy and approved for return to service.

Michael Moore 504906069 IA

DATE 2010 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/2/10	299.33	==	4121.04	INSTALLED 2 NEW GOODYEAR
				FUGHT CUSTOM III 6:00X6
2011 —	<b>→</b>			TIRES T. Sulul 223945
1.7-10	533,54		4155.05	REPLACED ELECTRIC FAI PURP. PIN CA35328-9006
				5/N 7420. OP CHECK GOOD, NO JELLS.
				1 / 5 cy 906049 AP
6/8/11	367.2		1118011	
	201.1		9108,6	REPLACED ELT BATTERY BP1010 T. Schul 223945
10.17.11	389.7		4211.11	REPAIR CRIACKED R. WHEEL PANT 134
				FRACTURE FIBERGLASS 1100 W. MAIN, MIEST
				r. Schu 223945 480. 969. 9876
0/29/11	389.7	7.5	42(111	REPAINTED R. WHEEL PANT BY TOUCH UP PRO
	201.1		121111	DHAMOUT SILVER MA-056-50 480.570-9885 T. Salur 223945 01992ASA

DATE 19 <u>68</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)						
3.29.00				REPLACED ELT BATTER / BP1018						
	— Dimon	DA 20 1	10 001							
	Piper PA-28-140 S/N 28-21409 N4654R T.T. 3,956.60 Hours									
	corresponding operation operation weigh	oonding on of air	Amperage reraft's elems and avance uncha	/ fuse holders installed in the instrument ull type circuit breakers of the e rating in their place. Functionally check ectrical systems and avionic equipment. All ionic systems found to be OK. inged. Electrical Load unchanged.    Solution   Solution   Solution						

DATE 2008 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
p.Z0.08	,		3960.1	REPLACED LITHUM BATTERY IN
				BENDIX-KING SKYMAPTI GPS WURK DONE BY EXEC PULONIC
				CHANDLER AIRPORT
		l		Moore Aviation Services

4702 Fighter Aces Dr. Mesa, AZ. 85215

N5654R Hobbs 192.0 7-14-2009

Airframe

Installed new air filter. Cleaned fuel system filters. Installed new wheel pant mount bracket on left axel. Installed new brake pads on left and right main gear. Installed new bolts and bushings on nose gear scissor assy. Cleaned and greased wheel bearings. Swapped left and right main tires. See AD list for compliance. I certify this aircraft has been inspected in accordance with an annual inspection and is airworthy and approved for return to service.

Michael Moore 504906069 IA

DATE 18 2001	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Insta yoke retur Mich	ato service.  ael Moore 50	acement y l work do 4906069	A&P  Me  A Time in se	amber PCW-601-103. Installed new push to talk switches and new lance with piper service manual and is airworthy and approved for loore Aviation Services 702 Fighter Aces Dr. Mesa, AZ. 85215 3947.13		Re and che Ch che Fo	eplaced de d Installe eck opera ecked ope ecked ope ound to b	efective aud a Push-pation of auderation of e OK	/N 28-21409 N4654R T.T. 3,956.55 Hours  Indio panel wire contact. Removed Glass fuse oull type circuit breaker (2 Amp). Functionally dio panel, Found to be OK Functionally  GPS unit., Found to be OK. Functionally  XM music source into audio panel.  changed. Electrical Load unchanged.  5/9/2008  Date
- 07-02 has be	Bendix switch en inspected i	n. AD 69- n accorda	22-02 no lo	Cleaned fuel filter. Installed new wires on landing light. Installed alled new bushings in stabilator trim drum. Complied with AD 76-inger applies due to new yokes being installed. I certify this aircraft annual inspection and is airworthy and approved for return to					© 1992 AS/

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE 3837.2	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2-3-	ine sector by I (Bending I cer I cer I/A/h	ston Jon Jon Mages X Mag	16 d # P-10 ~ 337 - 100 10 Switch that t	Replaced ELT Bestery  Herizon instruments Enc." Fachometes  A) in place of original techometes  this close, clas requirements of FAR 91.257  (WADK9-22-82 (control wheel inspect)  extense at toch 3305.7 (IN ADTK-07-12  ) by ops check next doe at toch 3305.7  his arrord has been inspected  Inspection and force as postly  Golden APP 265013.7A
1992 ASA				

DATE 152006	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9-29	4.7		3840.9	TACH REMOVE FOR CALIBRATION DUC TO ENSINE
				STC. 4.0 HOURS ROCORDIO SINCE Z.3.06.
				4.7 Hours Recorded SINCE install of person
				TAIN INSTAILED DICUR EGT - CAT TOTT
				+ components See 337 TUIS DATE, AD 69-62.
				AND AD 71-67-12 NOT DIE TILL 39321
				act T in challe NRV ATTENATUR AND VEIL.
				T . LI SUS DIRILAGI HAS DECN INSTITUTE
				A CARILE WITH AN ANNUL INSPECTION
				as Grasso in FAR 43 AVVENTA O FINE
				D. O. Service MANJAL AND 13 PIE WOLFFE
				AND APPRINCE FIX Retula to Service
				, , , , , ,
				1 A Au
				50190 601697A
				© 1992 A

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, 1</b> Entries must be endorsed with Name Technician or Repair Facility. (See both 1975)	e, Rating and C	ertificate Number of
12/04	Remain	il wo	ORK DOL	LORANC E INSTALLED Z	ERS RECOI	WEDATING
	SYSTA	N FOR	VFRUS	E OULY. VPDATED E IGHT & BALAUCE	QUIPMEN JEC 35456	SGUE ST74 A&P
1.28.04	3132			NSTALLED NEW CONCORDE SET	alon B	SAXC
	1/7/2005		FALCO	N EXECUTIVE AVIATION, INC. 4766 E. FALCON DR.	W.O. #	SVC-5576
DATE REG MODEL SER#	N4654R PA28-140 28-21409		FAA APPROV	MESA, ARIZONA 85215 'ED REPAIR STATION NO. X0FR185J RFRAME LOG ENTRY	HOBBS AFTT	N/A

TE	RECORDING Tach Time	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
29-08	<u> </u>		D /	ed flexible hose material for main touk
del	3150.2		Keplais	est flexible hose moternal je est and vent lines on left and right
CIT	3748.2		fuel to	Replaced fuel sending unit gostst on LH
20			foorke	Research All Joseph Fire pump p.N.
1	tric for	1100	we mi	the front producte. Replaced original
201	4 900300	1800	- see	the "steves Aircrost" gascolater A.O.
100	3.00	Sep	rest	~337 this date of the with
V	100/er	10500	-11 6V 1	eNacing Total LACT 4748, & OS
1	J620	ANG	303 1	50 Placement 10 18 - 2-82 contol World
Los	45+ P1	WICH	thin	Lext due al Milliant Com requirement
-	MY EMI-	to be	005	check next as the this almost has
6ge	FARG	1.59	ELT	inspect) i certification and foundarional my
(B)	t this	back	I/A/w	100 h Wall 1 1550 13 IA 0 1992 ASA
	1.12	Time	1 400	11000

**TODAYS** TOTAL Description of Inspections, Tests, Repairs and Alterations Description of Inspections, Tests, Repairs and Alterations 2003 FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Entries must be endorsed with Name, Rating and Certificate Number of RECORDING TODAYS TOTAL SERVICE Technician or Repair Facility. (See back pages for other specific entries.) TIME IN Technician or Repair Facility. (See back pages for other specific entries.) FLIGHT TACH SERVICE 3650.3 Replaced left and right main tires and £12-03 305Z,3 inspection rext due at toch 3171.6. Replaced tubes. with new, serviced nose vacuum regulator fitter aves induction air fitter with start with had flied and nitrogen new. I certify that this air wast hos been inspection and formed A 7685013AP GOODY FAR FLIGHT CUSTOM TIT acountary at this time. AERO CLASS "LEAKGUARD" TUBES 9978650 B FA 3653,0 7.13.03 3055.0 INSTAILED CONCORDE SEALED BATTERY # RG.35 AXC Remared voltage regulator and installed new VRZORA regulator, ops check good 6-4-04 3099.1 3689.8 Installed 4ea new bushings in no se 12-26-03 3071.6 gene scissors and sea new scissors botts, Respoled all landing gear strits, Replaced ELT Lattery with new expires Novos chi Requirements of FAR 71.207 reinstalled after of the by Varga Enterprises w.o. #15461 ELT (respect) (MAD 69-22-82 (control wheel respect by respection 7-2-04 rext due at tach 3171.6 (/wAD76-07-18 Bendy magswitch) by ops check next due Deczassa (/wAD95-26-13 (oilline inspect) by AL HATTE 497685013AF

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
0/10	<b>30</b> .!!			, , , , and pages to this opposite criticolly
	ENT AIRCRAFT PAR LAND, WI MADE IN		Fall Control of the C	under Model Kluck KT7CA
	Air Filter		S/N	Meets or exceeds FAR Part
Change		Change		pendix E requirements this Date: 07-01-2002
3022	Hre	- A	_ Signed.	GOLF BRAVO FAA/CRS OG6R211J
	2002 350	3건Hrs.	- ONE	GOLF DRAYO FAA/CRS OG6R211J
,				
-19-0	2-		C/W AL	69-22-82 (outrolwheel yoke 100)
ach	4HO 302	26	by insp	ection rest due at tock 312216
CTT	36106		C/W AD	
		/	check	next due at tach 3122.6 c/w AD
9	5-26-13	(oil	line in	The state of the s
	ach 312	2,6	CIWA	\$ 96-09-10(011 pump goods) see engine
	100 for	- de	وكاندة	( with requirements of FAR 91.207
E	ATINSA	· Ref	lacel	instrument air fitter and vocan
	egulata	5 4.1.		placed induction oir Etterwith
- B	ockett.	EIHEC	053	. see form 337 dated 7-15-02,
K	esedo	Ol p	to Fac	the master Window July

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	m-ro see for skyter equiple and breake there	turb sta sta right right his	337 de stor	spection and found all the sois IA
12-2	63033 27-02 by		100	Lest and right brake colpers.  and renstalled DG after repair  exprises. All All 1847  497665013AF

DATE 2000 15	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Re</b> Entries must be endorsed with Name, Rating a Technician or Repair Facility. (See back pages	e, Rating and Certificate Number of			
11:15	Pertinent details of work		F, uel gasculator	FALCON EXECUTIVE AVIATION, INC.  4766 E. FALCON DR.  MESA, ARIZONA 85215  AA APPROVED REPAIR STATION NO. XOFR185J  T. Replaced both fuel tank drain values. Repaired cabin AUTHORIZED SIGNATURE  on this aircraft are on file at this agency under work ord	XOFR185J			
12/30	2930.4		3528,6	NSTALLED NEW THROTTLE VERNIER CONTROL MIX BOTH CHISLES TEFLON ( T. Shu 223945	TUILE C.	Eq.		
t ·				1. Shu 223945				

DATE 2001	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1-9.01	2930.6		3578.6	MODEL 300-3 FLIGHTTHANS # 113R583L
	2943.2		3541.2	INSTALLED NEW BARREL LOCK ON DOOR, INSTALLED NEW BRINGKET ALL PLIEN # BA-3 T. Sulm 223945
2/6/0	Ren Tusti A200 Ust 2967.1	7 4	ADF PS EX U & TE TEBA 3565,1	31, GEVAVE 200 & MKIZ POWER SUPPY G. PM GOOOM AUDIO PANEC, I COM STED SYSTEM. REVISED EQUIPMENT ANCE REPORT.  TO CSGUS 854565774 ALP
				∫ 1992 AS/

RECORDING Tach Time	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
2869.3		3457.3	INSTALLED NEW ELT BATTERY #BP1010
2869,3		3457.3	INSTALLED NEW BEACON LENS & G.E. 1940 BUB
2869.3		3457.3	INSTALLED BLACKETT AIR FILTER # BA-3
	2869.3 2869.3	7869.3 2869.3	TACH TIME       FLIGHT SERVICE         2869.3       3457.3         2869.3       3457.3

RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
28863		34743	ANNUAL MSP COMPLETED THIS DATE
14.25		) A	ANNUAL MSP COMPLETED THE DIVER MANUAL  ALL WORK DOWE 1/A/W SERVICE MANUAL  + FOR 43 Appendix 0' 9W AD 69-22-02
			LE LINCO ADE OF THE HUD CHELLER
			+ c/w through 2000-5 Replaced
			I have tilk + TUBE
			DATE 3-25-GO TACH 2886.3 HAS BEEN INSPECTED
			I CERTIFY THAT THIS A RECREATED HAS BEEN INSPECTION AND INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
			DETAILS OF THE REPAIRS ARE ON FILE UNDER WORK CRITER
			TOTAL TIME 3474.3
			S M O H
			Bear Morris 17452 109-411
2910		3498.6	INSTAILED NEW GILL BATTERY G.3
	TACH TIME	TACH TIME FLIGHT	TACH TIME FLIGHT TIME IN SERVICE  28863  3474.3

DATE 12000	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				N4654R PIPER PA28-140 11/4/99
				TACH: 2865.8 S/N 28-21409 —
				Removed MK12A panel unit and installed MX12 panel unit. All equipment installed IAW the manufacturer's manuals and AC43.13 as appropriate. A function test was performed and passed. All work completed as shown on work order 15673 dated 9-3-99. Weight change negligible. Aircraft ok for return to service.  Delbert Willeford, Jr. ROYAL AVIONICS SYSTEMS, INC. CRS HN3R559L 4610 Fighter Aces Dr. Mesa, AZ 8215
13/00	2869.3		3457.3	WETALLED 7 CI-121 ANTENNAS
700	2061.3		לווטףט	CON #16 # 9 12/11/10>. FONG NEW
			1	DO 160 CORN FAIL RADIOS & COKAN
			- 1 1	FLICHT TRAILS AUIONICS INSTALLED CASKS FLICHT TRAILS AUIONICS INSTALLED CASKS ENDS & CHECKED OUT AVIONICS & @1992AS ENDS & CHECKED OUT AVIONICS & @1992AS ENDS O. L'D FOR PETURN TO SOMULES.

DATE 19 <u>99</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3.15	2836.9		3424.9	N4564R Piper PA28-140 3/15/99  Hobbs: 28369 S/N 28-21409 W/O: 15484  Tested system in aircraft and found Mode "A" and "C" decoders out of tolerance. Removed KT76 and aligned unit to specs with King maintenance manual. Function test ok. Reinstalled and tested in aircraft. Found the encoder was out of alignment. Readjusted to specs. Final test ok. Tested system to 15,000 feet. Aircraft ok for return to service.  Del Willeford, Jr CRS HN3R559L.  For Royal Avionics Systems, Inc. 5000 E. Falcon Dr.  Mesa, AZ 85215  INSTALED NEW CONCORDS BATTAGY  PART # RG 35 XC SEAUSO " T. SUM 223945		(0550) Cl measures refinish. R	sn:28 necked .316 in einstall	t <b>ry:</b> -21409 N flap hand ., and bu ed flap h	N4654R N4654R Tach:2863.3 9/17/99 dle for AD96-10-03 compliance. Cable mounting hole shing was installed. (2752) Removed flap handle for andle with new AN23-11 clevis bolt. Reinstalled andle. Reinstalled flap return spring. Functionally 0# 3253 Neil J. Abrams A&P 529089900 Mill Chrams
5.29 © 1992 ASA	2846.3			TIME 223945  TIMEN 223945  INSTALLED NOW BRACKETT  AIR FILTER PART # BA.3  T. SULL 223948					

DATE 19 <u>97</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2-6-97	7ALH 2762.4		3350.4	INSPECTED AIR FRAME I/A/S AN ANNUAL
				INSTECTION I CERTIFY That this AMERIAME
				inspection and has been found To Be
				in Ainworthy Constion at this time chaves Air Through 12-697 foralle to the
				Senethen E. R. TE AHPSGS 12160I
12-22-97	TACH 2765, 1			REMOVED & REPLACED BATTERY:
				CONCORD CB-35. BATTERY SERVICED & LISTA
				PER PIPER SERVICE INSTRUCTIONS. Charle & Learn Att Cart 2030423
				2030423

DATE 19 <u>98</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. ( <i>See</i> back pages for other specific entries.)
9.1.98	2806.0		3394.0	_
				RATTS AIR SERVICE  8/31/98  Stripped and RepaintedFlight Controls Removed & Checked For Balance.  Diamond Silver  Med Silver  Red  RATTS AIR SERVICE  N4654R   N4654R  HT-10634  HT-10639  HT-10568  Red  TR-10095
				Black 571 010  Micheal Ira  A & P 2130010

DATE 19 <u>46</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)					Description of Inspections, Tests, Repairs and Alterations  Description of Inspections, Tests, Repairs and Certificate Number of
11-13-96	Co	NT	,	SERVICE MANUAL 100 HR INSP. REPORT	19 <u>97</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Ambient of Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility.</b> (See back pages for other specific entries.)
				(TABLE III-I) AND FIND , IT IN AIRWORTHY CONDITION. Chash F Josep 148 Cest 2030423	CONT				WITH PIPER SERVICE BULLETIN \$36 A. FAA FORM 337 SUBMITTED. Charle F Green
11-13-9	2705.0		3282.0						Ad P Cest: 2030425
	3,700.0			BEEN INSPECTED IN ACCORDANCE— WITH AN ANNUAL INSPECTION AND	12-6-97	344,4		TTAE 3350.4	REPLACED LEFT CONTROL YOKE UNIVERSAL  JOINT WITH PIPER PART 62834-00 IN ACCORDANCE  TOINT WITH PIPER PART 62834-00 IN ACCORDANCE
				THIS DATE. A PIRWORTHY CONDITION					WITH PIPER SERVICE NAMES, 12.
				JAMES RAYNOVIC James Kayner- AP 207366783 IA					INSPECT, 16-07-12 19/10/101
4-20-97	7 2722.8	,		REMOVED & REPLACED ALUMINUM BATTERY Cables WITH COPPER CABLES FROM AMERICAN AVIATION					PERFORMED MAINTENING 100 HR INSPECTION
© 1992 ASA				BROKERAGE & LEASING, YUKON, OKLA.; INSTALLED IN ACCORPANCE NITH STC-SA3851 SW: ALSO COMPLIES					REPORT (TABLE III
									AIR WORTHY CONDITIONS Charles Fifteen Att Cent 2030423 END

		•			200 000		***************************************		T. Boneire and Alterations
DATE	RECORDING	TODAYS	TOTAL	Description of Inspections, Tests, Repairs and Alterations	DATE 19_ <i>96</i>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
19 <u>95</u>	TACH TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		. ITAIE		SENAICE	
					7-18-96	2701,0			REBUILT LEFT + RIGHT MAIN LNOG, GEAR
				DATE 9-24-95 TACH TIME 2634.4					TOT PEPIDED DRING WIGOAVRING.
				TOTAL TIME 3222.4 TSMOH ENG. 889.4					PIPER SERVICE INSTRUCTIONS. PACKEDWHL BANGS.
				IN ACCORDANCE WITH AN ANNUAL INSPECTION AND					Charle 7 from A+P Cest 2030423
				TOUR TO BE IN AIRWURTHY CONDITION THIS DATE.					
				B. JACK BRADLEY A & P - IA 460341210	11-13-96	2707.0			STOP DRILLED 2 SMALL CRACKS IN LOWER INBOARD
10-25-95	26363			/ 100071210					LEFT FLAP. DRILLED 2 DEATH HOLES THE DET.
				CONCORD BATTERY CB 35 5/N 280 111. WORK					
				Procedurate WIIII TIPED CPA LA LA					
				Charly Foren AAP Cent 2030423					
4-9-96	2658,6								INSPECT. IN
				REPLACED LANDING LIGHT WITH QUARTZ  HALOGEN, GE Q 4509. WORK IN ALLOR DANCE WITH PIPER SERVET					CONTROL WHERE THE CED BATTERY,  OPERATION. SERVICED BATTERY,  I CERTIFY THAT I HAVE INSPECTED THIS  TO CERTIFY THAT I HAVE WITH PIPER
				The state of the s					I CERTIFY THAT I HIVE WITH PIPER  AIRCRAFT IN ACCORDANCE WITH PIPER  © 1992 ASA
© 1992 ASA		<u> </u>		Chash Fface A+P Cost 2030423					MIKCKAI

DATE 19 <u>95</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE 19_95	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5-5	2631.8								
-		1		S/N QS 123 test required by FAR Part 91-413					REINSTALLED ALL BATTERY CONNECTIONS.
				Signature Wolf 4423					I CERTIFY THAT I HAVE INSPECTED THIS
				Date C-S-OT A					AIRCRAFT IN ACCORPANCE WITH PIPER SERVICE
				Date 5.5-95 Acro Yest Sevu. CRS A78R X55J					MANUAL 100 HR INSP. REPORT (TABLE III-I
9-24	2634.4			PACKED WHEEL BELL					AND FIND IT IN AIRWORTHY CONDITION.
				CONTROLS AND MARIES DEARINGS, LUBED ALL					100 1 Tilpon Att Cert. 2030425
-					9-24-95				- 26244 TATAL TIME A/C= 3222.4
-				PART) CHECKED AND ADJUSTED ALLERON RIGGING					- CINCE MAJOR = 889. Y. INSPECTED
				ADJUSTED TENSION ADJUSTED AILERON RIGGING					A STARRANCE WITH PIPER INSPECTION
				ADJUSTED TENSION ON ALL FLIGHT CONTROLS					AD 70-16-05 N/A DE 10
				DUE 9-96, COMPLIED ELT, BATTERY					TIME OF NEW MUFFEER, FIRER
-				(CONTROL WHEEL MICHALL WIS 69-22-92					90487-00 ON 10-30-10 IACH
				CONTROL WHEEL VISUAL INSPECT. , 76-07-12 IGNIFOR					ICAC HOS (SEE ENGINE LOG BOOK TI)
1				CLEANED AND PAINTERY AND BOX,					AND COMPUED WITH THRU
© 1992 ASA				CLEAVED AND PAINTED AND REINSTALLED IN					BUSEUN 95-18. A/C 7637 RON
				AC. SERVICED BATTERY, CLEANED AND					SATISFACTORY. (OVER)

DATE 19_94	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)					
				reclinician of riepail racility. (See back pages for other specific entries.)	DATE	RECORDING TACH	TODAYS FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
7/26	2573,4		3/6/.4		19 94	TIME		SERVICE	Technician or Repair Facility. (See back pages for other specific entries.)
				VALUE FILTER, INSTALLED	_				6 -) 11 1 to me half perhaped FLT
				NEW 8 DAY CLOCK, Clarky Flow Ast ant	_				CONT.) Lubed torque links, Replaced ELT
				# 2030423.					Buttery NEXT DUE 9-96. ADs Complied
									11 10 22 27 can trad wheel WISDEL INSPEN
8/26	2580		3168.0	Replaced Landmalate & 1014					- 2 00 of Taggie links-VISVO , 16-01-12 19 111104
0/				Replaced Landing light. & repaired Rotating Bogcon, Checked OK. Charle F. Shaen					1 constrain / new Titl That I have
				AtP Cent # 2030423.					4 I while august In accordance will
				15 11 CDA " 2030423 , C					O Manual 100 hr Inspection
91,1	111000		2,02 6	2					report (Table III-I) and find it in
9/16	2595.9		3/83.9	Drained left fuel tank and removed tank torephice					report (1466 III-1) and fine the
				THE GOWN FING. Installed were all					amworthy condition. Charles to free
				The liper service instantione out II			-		A+P cost # 2030 423
				in the statutess steel spraye in the					TACH TIME
				and replaced flexable brake lines both sides in					
				accordance with firm ( mes both sides in					1 10 C P AL I AN BEEN INSELLIEU
				accordance with figer Service Instructions, Clacked					The suitti has property the suit of the suite of the suit
© 1992 ASA				and Jubed all control pivots and cables. (CONT.)					TO BE IN AIDMORINY CONDITION THE DATE
									B thich marker
									R LACK BRADLEY A & P - IA 460341210

## Aircraft Record General Information

		24.22	140
Manufacturer Piper		Model <i>PA</i> 28-	140
Serial 28-21409		Registration Number	N4654 R
Date of Manufacture $2-7-66$			
Engine(s) currently installed:			2A , L-15997-27A
Manufacturer LycomiNG		Model 0-320 - E	2A , L-1599 7-21A
Manufacturer LycomiNG HUB Model Sensenich M74	Serial KT	72 <i>53</i> Seri	ial
Blade Model	Serial	Serial	Serial
Blade Model	Serial	Serial	Serial

# AIRCRAFT LOG



PIPER AIRCRAFT CORP., LOCK HAVEN, PA.

				N 0		
Date Time in Air Passengers Hrs. Min. Carried			NATURE OF FLIGHT			
Year Mo. Da	У			44.0		
12-10	7-52 7	Acr	-236	25 11 2950.5 Smott. 618.2		
				AD 70-16-05 MUFFIER INSPECIE		
				AD 70-16-05 MUFFIER INSP C/W		
-				Complied with 50 hr. Insp.		
				Tach/Hr. Meter 2362.5		
				A/CTT/Eng. TSMOH 2950.5		
				Date 12-10-52 W.O.# 8602		
		-		Mmily		
-	-			AERO MECHANICS INC. R/S SX3R857L		
				MATERIAL STATE OF THE STATE OF		
Total Forwa	ard					
Place o	f Last Airpla	ne Ove	rhaul			

Date of Last Overhaul

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

MC

	-		7 17	T .	00	
IR	CK	AI	1	L	ս ս	

REMARKS	SIGNATURE
9-27-93 The 2503 lever are believed are wheel Beausing and wheel Beausing and wheel Beausing and Well-22-02, 7 warmend bottery	Red ends control rings greece maingene 0-16-05, 10-05
And Time This Develor Has B	eeth
All Applicable Airworthiness Requirements  Total Time 3090 Tac Time 2500  SMOH 75 Date 9-27-93 W.O.#2  S. G. Schwartz IA 502586008	
25 35 Marging 111 20 20 110	10000

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date Year 92	Time in A	Min.	Passengers Carried	NATURE OF FLIGHT				
Year Da				Topics.				
5 20	KT96 TEST RECHAS BEE FAA APP	UIRED L PERE MILE I	HE TRANSPO S/N 25 BY FAR PART IRMED. IGH AVIONIC IEPAIR STA.	1 CERTIFY THAT THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY.  PAR. PART 91.411 HAVE BEEN  PERFORMED. THE ALTIMETER				
	DATE _		A A S	SIGNATURE ROLLMAND CRUMLEY  DATE 5-20-92  1-7-92 REMOVED LOANER  IR SPEED REINSTAUES OVERHAUSED  IRSPEED S/N 9824 CHECKED PITOT-  TRATIC SYSTEM FOR LEAKS, CHECKED  TATIC SYSTEM FOR LEAKS, CHECKED  TATIC SYSTEM FOR LEAKS, CHECKED  OK. JEMMESLIMMA APP 503478905				

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938 nunishable by Civil Penalty.

AT CI

AIRCRAFT LOG REPLACE ELT BATTERY BY: SIGNATURE IARKS Celleranks contral attach points Replaced set Battery replaced defront scool hose, Repair carbbeart shrow I Certify Asl Of This Date And Time This Kanfrand Has Been I.A.W. A Annue Inspection and Meets All Applicable Airworthiness Requirements Total Time 2911

NOTION Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C	AIRCRAFT LOG
Date Time in Air Passengers Carried NATURE OF FLIGHT	REMARKS
1-29-92 Tach. 2179.2 ACTT 2762.2 AD 70-16-05  Muffley Gusp. C/W Dwe  total 2229 2 Service Pwith  7 Ot Affoshel 15/50.  Complied with 50 hr. Insp.  Tach/Hr. Meter 2174.2  A/CTT/Eng. TSMOH 2762.2  Date 1-29-92 W.O.# 2339  AERO MECHANICS INC. R/S SX3R857L	3-11-92 Task 2204.2 Koran Appllo 300 Install & Clarated Firm 337 Filed Enstalled Exhlygens AP 25-6251 Aug Star Graham Exhlated Exhlygens AP 25-6251 4-25-92 50 W. insp. Tach 2231.0 TT 2829.0 C/W AD 69-22-02 par (a) (b) I insp Control whool's for crashs GWAD 70-16-05 per (c) insp muffer C/W AD 672-24-02 Linstall missing pleycard on par (a) insp Regains Ifuful Pyper S/m Wolf 3661
Total Forward	FAA REP ON # ZW3RO29M 2m 3Ro29m
Place of Last Airplane Overhaul  Date of Last Overhaul  NOTICE: Making false entries in this back is a violation of the Civil Account o	SED AIRPORT 290 SHRINE RD. # 5

N C	AIRCRAFT LOG
Date Time in Air Passengers Carried NATURE OF FLIGHT	REMARKS
Septens OR whed control surface Attach points, whed pulleges greesed gear, who I want majoren enterprise for up Edown Stops en from accustive instantial new airfilter instantial new good later secul and new downstop in formed as tomer that Escent racho down to transmitt order spinater attach angles Se Schuses TASCHSSEASS.  AD C/W 69-22-02  [ Certify As Of This Date	1-3-91 REMOURD THIS DATE GARWIN INC.  USI, PIN 22-204-02- A SIN 1424 FOR  REPAIR & RECENTIFICATION AS PER  CLOTOMARK REGURST.  LONGAN INC.  C.R.S. NHZDOJIL  MISSOULA, MT. 59602
Total Forward  And Time This for fame Has Been  177 Carlton Drive  178 Carlton Drive  177 Carlton Drive  178 Carlton Drive  177 Carlton Drive  178 Carlton Drive  177 Carlton Drive  178	
Place of Last Airplane Overhaul  Date of Last Overhaul  Date of Last Overhaul  Output Date of Last Overhaul	NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Pena

N.C	AIRCRAIT BOG	
Date Time in Air Passengers NATURE OF FLIGHT	REMARKS	SIGNATURE
Total Forward  Hrs. Min. Carried  Hrs. Min. Carried  10. Day  5-9-90 HAC 1973- C/W AD 15-69-22-03-06  AD 1: O Reversing at 20073. 2 AD 72-08-06  AD 1: O Reversing At 2005-2 C/W AD 69-22-02 parce, bid  RECOCCURRING AT 2005 hrs. 3. G. Schwarzst ta soasse, 008  7-7-90 Maintenance Performed Wheel control Attach points  Lelevanha and accounts pullys, garred gene, senurced  Latteny water chil control cables and Attachments, replaced  LATTENSORY AND LONG AT 4100  Total Forward  Total Forward	I Certify As Of This Date  And Time This Angual Has Been  I.A.W. A Angual Inspection and Meets  All Applicable Airworthiness Requirements,  Total Time 2641. Tac Time 2053  SMOH Date 1-90 W.0.#19450  S. G. Schwartz IA 502586008  S. G. Schwartz IA 502586008	
- Ai-l Overhoul		

, .				DOS PHÁNDRIA NC
Date Date	Time in Ai	min.	Passengers Carried	NATURE OF FLIGHT
Year Day				
1-25-90	the	190	3.º u	shall repaired & Caleprated DET.
	- S.G	. S	Dury	\$ IA 503586008 -
2-5-90	ensta	0	vew t	oltree Reg per manua SESchufet IASOJS86008
			- /	
2-10-90	install	ne	ev right	tank fuel quage St Schneif IASO 2586008
			•	7 7 0
740	Rise		a par	
-				
Total Forward				The Control of the Co
Place of La	st Airnlane	Over	haul	

AI	R C	R	A	F	T	L	0	G
----	-----	---	---	---	---	---	---	---

REMARKS	SIGNATURE
3-78-90 REPUACED FAULTY AIR SPEED AND INDICATORS  I CERTIFY THAT THE ALTIN PRESSURE ACTITUDE REPORTING SYSTEMS STATIC SYSTEM TEST REQUIRED BY FEAR 91.3UB HAS BEEN PERKORMED AND APPENDIXE OF PART 43. THE ALTIMETESTED TO 20,000 FEET.	TETTER, RUTOMATIC EM AND THE AR 91.171 AND COMPURS WITH

					AIRCRAFT LOG	
Year Mo. Day	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT	-	REMARKS	SIGNATURE
Ave from 43.	me unpinspe. App Doffaes. Oneo Braine po el Bearings on ustrage or recocurring	Mainter da Clean Hursel G. Remon 1939 Ehr	other Time 2427.8 on this Date and time this much taspect per Piper Manual P/10753-586  NET performed ReplaceD 1 main time, ReplaceD  Ed and grease main Androst canding gene, Greased  auge exactic, 1 new one on order addiced  a cleaned instatud e/H wing tank. C.i.w. ADS.  5, 69-22-62 no crabes recovering 19378 has  his time therefore under a samual inspector pelicable Directory Regulpments. W.O. 19413 on  Ehward the Sossificos and		Tac 1930.?  1-4-90 Replaced R/H main fice, I intown I lempred was gear wheel pant, le flair and calibration, siplaced rose tra title, SG. Schward IA Sassbard  1-17-90 Removed this date Dome for her	roke pad more EGT for with serviciable
Total Forward		hl		*	CRS3167 P	nies
	ast Overhaul				Missoul	

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

		1.4	N C
Date	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT
Year Mo. Day			
static s FAR 91.1 Altimete Signatur	y that the asystem tests. 71 have been tested to be a system of the syst	required perform	d by
6-29-		ted no	se gens + shimmy danger. Tightered danger mounts. Tach 1801.5 May R. Atings IA 2179824
Total Forward			
Date of La	ast Overhaul		a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG	
INSTALLED THIS DATE NARLO AR-850  BLIND ENCODER AND KING KT-70 XPONDER  THESE ONITS WERE INSTALLED AS PER  MAN UFACTORES SPECIFICATIONS AND  PERTINENT PARTS OF ACUS:13 PARTS  I AND Z. THE AIRCRAFT PAPERS HAVE  BEEN AMENDED AND CORRECTED SEE  AEROTRONICS SUPPLEMENT THIS DATE, 7/7/84  YOUNG AEROTRONIC TI	I certify that the trainspection required by performed and found to Appendix F.UNIT K. Signed AEROTRONICS, INC. III
I certify that the automatic pressure altitude reporting system tests have been performed as per 91.36b and has been found to comply with Appendix E, Part 43 Paragraph C. DATE 77/804  SIGNATURE  NOTICE:—Making laise entries in this book is a violation of the Civil Aeronautics Act of 1938,	to comply with FAR 43,  7 - 76  DATE 7 - 5 - 89  LIC.R.S. 3167B

			N C	1	AIBCRAFT	LOG	A By Comment
Date	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT	中的			SIGNATURE
Year Mo. Day	868	CO TO B SECURE OF	eviation inc.		REMARKS	14 1/2	
	-	HISSOULA	GUNTY AIRPORT				Male Land
		225 HWY	10 WEST BOX 16	+	MINUTERAN AVIATION INC.	1.4	
	1.5	MISSOU	A MT 59801 0. 0. 0 3681 1. C/W AD68-22-02 ON	1	MISSOULA COUNTY AIRPORT	The state of	
-				,	5225 HWY 10 WEST BOX 16		10 220) DATES 7/30/75
-	The second secon		2 1/2 1084/27/2000		MISSOULA, MT 59801 / 1/25 / 1/25	c/w A0	69-22-02 DATES 7/30/75
-	inspected in	accordance	will a Avacure pie Firm, Repurces. Due		1 and	our Contra	ELT BATTERY Que
-	inspection an	d was det	ermined to be in an air- Agarin @ 2050. 1 Us	3	certify that this aircraft er-engine has been	Rysacs 61	120
-	worthy condi-				inspected in accordance with a Amount	6	
-		0.16	of of		inspection and was determined to be in an ar-		
	Signature	Sarlos	1 Pany	Q1	worthy condition.		and the second second
	Title CRS	A15-1	3 Tachometer 1550. /				
					Signature Alaflet Bloog		
Total Forward	TT 7138.	The second secon	A. D. Notes See Ligring		Title CR5 1105-13 Tachometer 1598.	)	
							n maralty
Date of La	ast Overhaul	this book is	a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		TT 2186.7 A. D. Notes See Listing	Civil Aeronautics	Act of 1938, punishable by Civil Penalty.

" MILLIANT HERE ....

			404 F4 k R D F L J — N C		AIRCRAFT LOG	
Date	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT			SIGNATURE
Year Mo. Day					REMARKS	1
	2/27/85 14	99.4 HE.	INSTALLED PRITERSON AVIATION LAIC.	(	Whish Box Sorwand 5-30-85 Wille	Geraen
	KiT AFP	9-28	OPERATION OF AIRPLANE ON		The speaked by	10 mg 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	AUTOMOTIV	F. GAS	DEINIE. SEE, STC 4 PERM 337 BATED		MINUTEMAN AVIATION INC.	all which and
	7/27/85	FOR DE	TAILS Stubel A. Mangel 1885-005.13		MISSOULA COUNTY AIRPORT	serviced + Justice
			. 0		5225 HWY 10 WEST BOX 16	new Cerake lineng
-					Pate 9/12/83 11550 11A 11759801 2099	1-15-87 Thory Conderse
3-	27-85	TAC:	1509 TESTED TO ALT,7 VDB 15,000'			720-7
			Check perfermed in Accirpance		I cortify that this aircraft or make has been	
			171 AND FOUND TO COMPLY		inspected in accordance with a ANNUAL	
-	Withow	he T	CLCVANCES OF PART 43 APPENDIXE		inspection and was determined to be in an air-	
-			Walter UX Rieme IA 1631993	p.	worthy condition.	
IBR ck.	3-27-85 6	enalo	337/340 1		1', 1 1 A	
			338/340 Darry Challerser	ķ.	Signature Mulan M. Wanny	
Place of I	ast Airplane Over		1911 Jac Charles Charles		Title Cos nos-13 Tachander 1532.2	AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I
	ast Overhaul		l l		The same of the sa	be Civil Penalty
			a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		NOTITE 2110. 2 A D Notes Sur Light Aeronauties	Act of 1938. punishable by Com

N C	AIRCRAFT LOG
Date Time in Air Hrs. Min. Passengers Carried NATURE OF FLIGHT  Year	REMARKS
MAINTENANCE RELEASE: Sentelled in A/c used  Date: 10/5/83 Tack Time Nanco UGR-2 Glile	Date 6-6-84 W. O. Date 3-1-85 Bonare 338/340 MR 12 339/340
THE RADIO IDENTIFIED ABOVE WAS REPAIRED & Slope ALSTERNAL SIE	certify that this aircraft or engine has been Abrry Cudersen
REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE, PERTINENT DETAILS	inspected in accordance with a ANN JAL
OF THIS REPAIR ARE ON FILE AT THIS AGENCY.	inspection and was determined to be in an air worthy condition.
FAA REPAIR S ATION DOS 16  SAWTOOTH AVIONICS	Signature Walter WY Riemer
RAVALLI COUNTY AIRFORT	Title Do5-13 Tachometer/485
Total Forward	A. D. Notes (1)
Place of Last Airplane Overhaul  Date of Last Overhaul	2-1-85 Benaue 337°/340° Herry Cudlesen MK1Z 338/340°
NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.	NOTICE:—Making take entries in this book is a violation of the Civil Aeronauties Act of 1938, punishable by Civil Penalty.

/					AIRCRAFT BOX
Date	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT		REMARKS
Year Mo. Day					
Year			Date 3/8/8 2 W. O. Date  I certify that this aircraft or engine has been Inspected in accordance with a Annuar Inspection and was determined to be in an airc worthy condition.  Signature Accordance M Elderby Title Des 13 Tachometer 1409.6		Date 4-19-83 W. O. Date # 1854  I certify that this aircraft or engine has been inspected in accordance with a Annual inspection and was determined to be in an airworthy condition.  Signature Thorlas M. Chalge.
		100	П 1997 A. D. Notes C/a To D	N M	145.5
		Te	Soc Backollog	f.	Title 105-13 Tachometer IN Back of Log
Total Forward					TT 2041 A. D. Notes See SHeet IN BACK OF
Date of L	ast Overhaul		at the Chall Separately Set of 1000 municipality by Chall Devotes		NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.
NOTICE:-N	laking false entries in	this book is	a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		NOTICE: - Making false entries in this book is a violation of the Civil Aeronautic

AIRCRAFT LOG N C ..... Time in Air Date NATURE OF FLIGHT SIGNATURE Carried Hrs. Min. REMARKS Year ..... Day Kephaced. Vac Pomp. Teaching that this owners in here been town and discerdance with a Humile determined to be in airworthy condition Green macon Rendina Total Forward Place of Last Airplane Overhaul NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Ct-Il Pens NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date Time in Air Carried NATURE OF FLIGHT Hrs. Min. REMARKS Day SIGNATURE BAHERY HACK +IMY 1693:00 Total Forward Place of Last Airplane Overhaul .....

N C	AIRCRAFT LOG
Date Time in Air Passengers Carried MATURE OF FLIGHT LE FT. Brake Pucle	REMARKS
1 Mo.//pay the this diverage has been inspected in BiRera FT 15 found	Certify that this aircraft has been inspected in Chacked Ad 70-16-5
determined to be in airworthy condition. Ad. Note 20-26-4 c/av-	determined to be in airworthy condition.
Dato 1-16-7 Gotal time or Toth Reading/314.97 + Die Pentrount INSP	Date 6-16-73 Total time or Tach Reading/409'-
Ad Note 20-16-5 INSpettledMosshen for cracks	Signed Milliam C Mark A. &P. / Your C. Signed Nove 10 EL1.
Herris that this wire thinks is commissioned was the R 17 400 86 if if	determined to be in dirworthy condition.
determined to be in an worthy condition. By 20-24-4 checked Bakanes take.	Date 2/6-7/Total time or Tach Reading /4/2
Date 23 ) 2 Total time or Tach Roading/395, - Ad 70-16-5 Checked Mars Charles	Etranspender Removed
Place of Last Airplane Overhaul	5/20/75 COWAVE MODEL 10 10
Place of Last Airplane Overhaul	NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

					N C		
	Date	Time in Air Hrs. Min.		Passengers Carried	. NATURE OF FLIGHT		
Year Mo.	Day				the state of the s		
					I certify that the altimeter and static		
					a fam tests required by FAR Pot 91.1		
		N and a second			78 arrye been penolimed. The air meter		
1					wen tested to 16,000		
				signature Al Delhites 1A 15 97025			
			э	100	Date May 11, 1970		
4					Noland - Decoto Flying Service		
			100				
					Yakima, Washington		
		*			FAA Approved Repair Station 4255		
-	11	£115	TAI	led t	leated Pitor Static Systyn By Piper		
DW	NE	69046	+	Gene	re ALPHA 200 transcriver + ANT.		
ew 1	MP	w wit	12	94,9	New EMPTY WT C9 87.5		
	Forward	New U.	sef	vi. ho	ed Normal, 393, 9		
Pla	ce of L	ast Airplan	e Over	haul	Utility 593, 9		
Dat	te of La	ast Overhau	1		a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		

AIRCRAFT LOG	
REMARKS	SIGNATURE
determined to be in airworthy condition. A.D. note fift management of the second state of the second state of the second	
LNSTAUED NEW TIRE + TUBE RICH	IT WHEEL
TACH READING 1292:00 8/11/70 Ken	net Genders )

ATRO	
the second secon	SIGNATURE
DWINDER O / //	x0 112-12-6 C/W
2-3-69 +ACH -//10 1163134 Ad No	xe 47-12-4 C/W-
A CA TACH TANK DOWN INSTRUCTION AL MAX	. 69-22-2 C/W
tects y fact this directall has a and was	Wheel
accordance wit a Ochna inspectation of actual n s.p.	Controll to Cl 11 16: de
determined to e in airworthy condition. A.D. All Checked	First TANKS Cheffell
	V Doors & Checkey
compliance on his inspection	PS. FJERCER CULLERAN
Date/2-3 6 Total time or Tach Roading 1/62 All Co	ntrolls for for
	- Conviced Datt Ham
Signed William & Make A&P 1) 4000 more no	LINE LE LEFTUREL
The suggestion	as been Inspected in accordance
Leckid All Wheel Bearing Inglies the aircraft h	as been inspected in accordance
Tcertify that this and the	inspection and was determined
As he in Airworthy conditi	on. See chronological listing in
to be in the for AD Note (	empliance on this inspection.
pack of 102 to the	tel time or 12024
	ottal little of
- 19-4-69 T	ach Reading 1
Date	talaner
7/00	dare techner
Signed: Theory	- Fochner, A & E #640140 W/176
Theodor	e Fechner, A & E #640140 w/IA
	by Civil Penalty.
No. u aeronauti	es Act of 1938, punishable by

SIGNATURE REMARKS INSPECTED AIRFRAME, CONTROL CABLES, TIRES, BRAKES. OILED & GREASED ALL POINTS PER CHART, DRAINED CARBURETOR. DRAINED FUEL STRAINER & CLEANED, CHECKED NAV. LIGHTS & RADIO AND BATTERY, REPLACED NOSE GEAR RUBBER BUMPER P/W 13114-60 WITH NEW PART. ENGINE RUN UP THROUGH ENTIRE RANGE. AIRFRAME TOTAL TIME 1076.21 HRS. ENGINE TOTALTIME 1076,21 HRS. LCERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A PORIODIC INSPECTION + WAS DETERMINED TO BE IN AIRWORTHY CONDITION. DATE 11-24-68 and faither IA 678120 7-12-69- Lech reading 1115,37 Intelled new L+ (R Hand - Etabel - Prince - painted 14 1307608 the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

			N C	AIRCRAFT LOG	MIDE
Date Year	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT	REMARKS	SIGNATURE
Year Day  10 16  12 7			WOR CHECK WITHIN 2° CAURBORN) CONSORCHAIN ( WOR CHECK WITHIN 2° CAURBORN) CONSORCHAIN ( WOR CHECK WITHIN 2° TACH TO 13 CFILLY 0729/68	4/19/67 chaspected airfrance, this control cottes, gressed not crodes drains and choos all full strainers choosed botters, cleaned enlars, air	
				ACCORDANCE WITH A PLACE INSPECTED IN ACCORDANCE WITH A PLACE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  Date 119-67. Airframe TT 197.37: Engine TT 197.37.	37
				ROBERT R. SELLS MUNICIPALITY AND RESERVED R. SELLS MUNICIPALITY	
Total Forward					*
Place of I Date of I	act Overhaul		and the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		es Act of 1938; punishable by Civil Penalty

			N C	AIRCRAFT LOG	
Date #ALT	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT		SIGNATURE
Year 1967 Mo. Day				REMARKS	11 24
9 11	100 hr	Tins	pection TACH 901.86. Replaced	DE 1 END HORY	T- 70/10/34
-0 //	all brak	elin	ings. Replaced hose Tire. Packed	4/20/67 /NST. 199 ALTIN	efek Komovie
	all whe	01 h	edrings Inspected feel Tanks.	Delfelh of Septile By De	f. fech of
	as wer	AD	67-16-2, Aircraft determinal	Duch Aulay & Ceptify ming	HO101/35305
73	To be	airwor	the Howard Schutte AXP (662241	septthe Compassion	UAIP 13530
	10	C// W	7	001	INIC AVIATION SERVICE
				& Static system have been tested seen	Piper Specialists
				tested per FAR 91,170.	THE WASHINGTON 98108
				Altimeter. SFAT	(10)
				Signature Ft.	
			ing.	Cert No IRIA Ce	
				Date 9 /20/67	
				- And the state of	
Total Forward					
Place of I	ast Airplane Over	rhaul			
	The state of the s				Civil Penalty.
NOTICE:-N	Taking false entries in	this book is	a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.	- whee	Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOC SIGNATURE REMARKS orque Civil Asymptotics Act of 1938, punishable by Civil Penalty. NOTICE. M.L.

AIRCRAFT LOG SIGNATURE REMARKS Crear seat Civil Assertation Act of 1938, nunishable by Civil Penalty. NOTICE:-Making fale

AIRCRAIL	
REMARKS	SIGNATURE
3/1/67 100 14. completed	for Piper
	na 000,
I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A Penadic INSPECTION	
CONDITION, 69 Dela are	
TOTAL TIME 610 AUTH. MECH. 1196983	
TOTAL TIME	

Acronautics Act of 1938, punishable by Civil Penalty.

	The second second
	SIGNATURE
REMARKS	and the second second
12-14-67 Completed Rudder	
- Train modification - 49149	
PiPER 1617 # 75-7 086	
A P 136320471	
Cahoules Sturmer	
2-2-67 - Installed Dipertional	
Indraytop - Model BCH-10	2 /
A&P 136320471	Merrile
- Talearist.	Parent
Ce	

			N C	
Date	Time in Air Hrs. Min.	Passengers Carried		AIRCRAFT LOG
Year	Hrs. Min.	Carried	NATURE OF FLIGHT	
Year				SIGNATURE
	TAPI	Facad	1100	REMARKS
-	TACH		he 100 hr. inspection prola	
	Oct. 1	7 1966	anient found and the	12-9-66 Santalled 119T-40MB in
		7		
			Calles checked, and totalinetime	figur model . PA-28-140
1			and release charles	4N 28-21409 -N 4654R.
			There are	THE DE ST TO TOST TO T
			000	200
-			R. S. Siedford	Then alocar & an ate weight 1288.8
			At7 165 9210	12 1 2 1 1 1 1 84 7
			0 1	Hew Intotal wellships, A. Dir
			6) 10 10 10	Use I Lated
-			Overhauled Our Sheet in	of the contract of the sale
			At 18 / 10-12 -15 NOT	400 ms orange of he willen
			The Marion	Conday stilling
			UN 202823	CHIEF INSPECTOR.
-				
I Samuel				Repair Station 4402
Total Forward			The second secon	Washington Aircraft
Place of La	st Airplane Overh	aul		
Date of Las	st Overhaul			
NOTICE:-Ma	king false entries in t	his book is a		

AIRCRAFT LOG SIGNATURE REMARKS

Mom

				N C	AIRCRAFT LOG		
Date	Time in Ai Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT		ALLO	SIGNATURE
Mo. Day						REMARKS	SKINATONE
4/1/66	93	5		Date: 4/1/66 . 100 Hr. Inspection	-		EVEN LA CONTRACTOR
-				completed. A.D. s the 66-5 New Apply to this	sen.	A) (	
-						Number 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	LOOP ANTENNA, \$
-				WORTH WO FRUIETT AUP 1508916		1000 CO TO TOURNENT LIST	FAA FORM 33/
				A Diest Nose steering nods lengther 2 turns on night, shorten 2 Turns on lest		ISSUED. NEW AC EMPTY WEIGHT	= 1279.6285,
				Charged Bottery workingth		Number 127/66- INSTALLED NARCO ADF-31, CABLE PER STD. EQUIPMENT LIST. 15SUED. NEW AC EMPTY WEIGHT E.W.C.G. = 84.84 ()SEFUL LOAD	870.4 LBS (NORMAL),
				4581508816		670.44BS (UTILITY).	
				CREST AFRO		O. III INO	LUTUIN,
				RT, 1, BOX 811		Repair Sta	tion 4402
-				KENT, WASH, 98031		Washington	Aireratt
-		-		UL, 2-5858		9/20/00/	
Total Forward							the state of the s
	act Airplana	Overh	aul		-		
Date of La	st Overhaul	Overn	aul				The state of the s
Date of La	st Overhaul			••••••••••••	8		

			N C		
Date	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT		
Year					
			nra-dinustrative seems and		
			The state of the s		
-			S HATTE INCORPORED THE AND OF AND AND TOWN		
		-	1. HAVE INSPECTED THIS AIRCRAFT AND FOUND		
			IT COMPLIES WITH THE REQUIREMENTS OF		
			FAR 21.183. CERTIFICATE OF AIRWORTHINESS		
			DATED 2-7-66 WAS ISSUED BY ME		
			Sonald Filther 2049		
Total Forward			DMIR_2049		

Place of Last Airplane Overhaul .....

Date of Last Overhaul

Instructions for the Use of Log Book 5. Before departure on journey, pilot is personally to ascertain that entries in log have been made are correct, and then sign 1. This log must always accompany the aircraft to which it Special data such as manufacturers notes, test data, recondicertificate to the effect. refers. 2. No pages shall be torn from Log Book. No erasures, and tioning, etc., should be affixed to stubs provided for that purall entries to be made in ink. pose in the back of this book. 3. Original entries shall be made and signed by manufacturer CAA-18-1 Repair and Alteration forms listed on last page. This log book shall be available and produced, on demand of or seller. All other entries shall be made by Pilot, Chief Mechanic, or other competent person authorized to do so. 4. On journey, the pilot is responsible for carriage of Log Book anyone so authorized. and entries or omissions therein. Failure to do so will be con-PIPER AIRCRAFT CORP.—LOCK HAVEN, PA., U. S. A. sidered a serious neglect of duty. ming. Model Q-320-E2/7 Serial No. 1.15

Date of Manufacture .....

ich. Hub Design No. 1740. M.S. Hub Serial K. 7.

Seating Capacity (including pilot) ... Wt. Empty ... Wt. Empty ... Wt. Empty ... Wt. 2/50.

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Description of Aircraft

Make of Propeller

Address