

Make: GE Honda Aero Engines	Reg. No.: N14QB
Model: HF120-H1A	Date: December 15, 2022
Serial No.: 883326	W/O No.: 49579
Hours: 586.8 Cycles: 433	Page: 1 Hobbs:



Right Engine Maintenance Record

Description of Work Accomplished.

Inspections:

- *Complied with 600 Hour Detailed Inspection of the Inner Surface of the Fan Case. (72-00-00-200-804)
- *Complied with 600 Hour Detailed Inspection of the Mechanical Fuel Shutoff System. (73-00-00-200-801)
- *Complied with 600 Hour Maintenance and Inspection Program IAW Service Bulletin 71-0000 R00.

Airworthiness Directives/Service Bulletins:

- *Complied with Service letter SL-420-74-001 – Igniter Plug S/N's UNLL9761 (I/B), UNLL9760 (O/B) Inspection. Ok for continued service.
- Replacement due on or before 1186.8 ETT.**

AD's checked through BI-Weekly: 2022-25

Approval for Return to Service

The article identified above was repaired and inspected in accordance with current FAA regulations and is approved for return to service. Pertinent details of the repair are on file at this agency under this work order.

Authorized Signature:

Daniel S. Marinelli, Inspector

HONDA JET SOUTHEAST

FAA Certificated Repair Station WD4R618M

5360 NW 20th Terrace Fort Lauderdale, Florida 33309

Phone 954 491 3170 Fax 954 491 1612



1821 Firebrush Ln
Oviedo, FL 32765
(386) 385-8436

Logbook Entry

Registration #: N14QB
Work Order#: WO_247
Page: 1 of 1
Date: September 06, 2022

Type	Make/Model	SN	Hours	Ldgs / Cys
Engine Right	GE Honda HF-120	883326	524.6	392.0

Performed Engine Gas Cleaning Path with Water IAW GE EMM Task 72-00-00-100-802 and Honda AMM 72-00-00-100-802.

The above work has been performed in accordance with Federal Aviation Regulations and or the manufactures service manual. Details of work performed are on file with Turbine Aircraft Logistics, LLC under work order: WO_247.

Date: September 06,
2022

Signature: _____


Carson Lee (A&P/IA) 3011419



1821 Firebrush Ln
Oviedo, FL 32765
(386) 385-8436

Logbook Entry


Registration #: N14QB
Work Order#: WO_210
Page: 1 of 1
Date: June 03, 2022

Type	Make/Model	SN	Hours	Ldgs / Cys
Engine Right	GE Honda HF-120	883326	472.2	463.0

Serviced the engine to the full mark with 16oz of Mobile II turbine oil.

The above work has been performed in accordance with Federal Aviation Regulations and or the manufactures service manual. Details of work performed are on file with Turbine Aircraft Logistics, LLC under work order: WO_210.

Date: June 03, 2022

Signature: 

Carson Lee (A&P/IA) 3011419

HONDAHonda Aircraft Company, LLC
6420 Ballinger Road
Greensboro, NC 27410

Log Book Entry

Tail #: N14QB

WP#: WP300835

Page: 1 of 1

Revision IR 1/1/13 RSF-100

Release AC End Item: HF120

Position: Right

Type	Model	SN	Hours	Min	Ldgs / Cys
Engine	HF120	883326	30	18	21

The work identified below has been accomplished in accordance with the following referenced data or as otherwise noted:

AMM Ref.: HA-420

LMM Ref.: HF120

Sequence	Action Taken
Parts	Qty PN Description CD Serial

72501 Inspected RH engine chip detector and found a small sliver of magnetic shaving. This type of contamination is considered serviceable per table 801 of HF120 LMM 79-00-00. Cleaned chip detector and reinstalled. All work done in accordance with HF120 LMM 79-00-00. Leak check good.

The maintenance listed above was performed in accordance with the current Federal Aviation Regulations and is approved for return to service with regards to the maintenance accomplished. Further details are on file at the Repair Station under the above work package.

Date: 11 / 19 / 2018

Signature: 

For FAA CRS 3HDR835B/EASA.145.6748