



eurocopter

an EADS Company



AIRCRAFT LOG BOOK



SN 0398

Date of Issue : 8/3/05 

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
73	Oil Cooler	37.038.23.000	849-M04	79	02.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
61	Tail Gear Box	L652A0101051	M2428	65	02.2005	
62	Mixing Lever Gear Unit	L671M7007101	05-0403	67	02.2005	
63	Actuator	418-00862-011	1028	67	12.2004	
64	Actuator	418-00862-011	1033	67	12.2004	
65	Main Rotor Actuator	L673M20A1005	00462	67	02.2005	
66	Longitudinal	L673M20A1008	00462	67	02.2005	
67	Lateral	L673M20A1011	00462	67	02.2005	
68	Collective	L673M20A1012	00462	67	02.2005	
69	Fenestron Servo Actuator	L673M40A1003	00531	67	02.2005	
70	Generator 200A	23081-057	P1104	71	02.2005	
71	Generator 200A	23081-057	P1110	71	02.2005	
72	Oil Cooler	37.038.23.000	842-L04	79	02.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
49	Main Rotor Blade	L621M1010056	2056	62	03.2005	
50	Main Rotor Blade	L621M1010056	2066	62	03.2005	
51	Main Rotor Blade	L621M1010056	2225	62	03.2005	
52	Main Rotor Blade	L621M1010056	2234	62	03.2005	
53	Swash Plate	L623M2005102	05-0202	62	02.2005	
54	Main Gear Box	4649010008	1300	63	02.2005	
55	Rotor Shaft	L623M1006102	FRMB5142	63	02.2005	
56	Tail Rotor Head	L642A0101052	M1414	64	02.2005	
57	Central Plate	L642A2024101	FR490	64	02.2005	
58	Shaft Long Assy	L651M2008101	05-1002	65	03.2005	
59	Shaft	L651M2010101	05-0475	65	03.2005	
60	Shaft	L651M2012101	05-0457	65	03.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
37	FCDM	C19252PC08	E0798	31	02.2005	
38	FCDM	C19252PC08	E0818	31	02.2005	5.2 / TROUBLESHOOTING PFD FAILURES MKB
39	Smart Multifunction Display	C19267VG11	1654	31	02.2005	
40	Smart Multifunction Display	C19267VG11	1660	31	02.2005	3.8 / FAILED MKB
41	Instr Control Panel	C19269AA	E0571	31	02.2005	
42	Instr Control Panel	C19269AA	E0586	31	02.2005	
43	Temperatur Probe	C16196AB	1554	31	02.2005	
44	Temperatur Probe	C16196AB	1557	31	02.2005	
45	AHRU	420-00332-430	1945	34	03.2005	
46	AHRU	420-00332-430	1947	34	03.2005	
47	Removal Memory Module	420-01867-300	2152	34	03.2005	
48	Removal Memory Module	420-01867-300	2225	34	03.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
25	Canister	D240845-1	1340	28	01.2005	
26	Hydr. Valve Block. Res.	L290M20A1013	00873	29	02.2005	
27	Hydr. Valve Block. Res.	L290M20A1013	00890	29	02.2005	
28	Hydraulic Pump	L290M20A1014	00958	29	02.2005	
29	Hydraulic Pump	L290M20A1014	00987	29	02.2005	
30	Pressure Supply	L290M20A1015	00863	29	02.2005	
31	Pressure Supply	L290M20A1015	00880	29	02.2005	
32	VEMD	B19030GC08	3707	31	02.2005	
33	CAD	C19243BC08	1443	31	02.2005	
34	Rack Equipe 4 Module	C13077BA	442	31	02.2005	
35	Inclinometer	C19258AA	785	31	02.2005	
36	Reconfiguration Unit	C19270AA	E0272	31	02.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
13	ADU 3000	C17027AA01	1348	22	02.2005	
14	Battery 40Ah	33490409206	078204	24	03.2005	3.8 / LEAD ACID INSTALL
15	Full Option Master Box	4502-350-3	1476	24	02.2005	
16	Full Option Master Box	4503-350-3	1491	24	02.2005	
17	Basic Battery Box	4504-300-6	1437	24	02.2005	
18	Cartridge	130100	1330	28	01.2005	
19	Cartridge	130100	1338	28	01.2005	
20	Cartridge	130100	1339	28	01.2005	
21	Cartridge	130100	1340	28	01.2005	
22	Canister	D240845-1	1330	28	01.2005	
23	Canister	D240845-1	1338	28	01.2005	
24	Canister	D240845-1	1339	28	01.2005	

8.2 EQUIPMENT LOG CARD LIST

EC 135 P2

SN 0398

No.	PART NAME	PART NUMBER	SERIAL NUMBER	ATA 100	INSTALL. DATE (m.y)	REMOVED AT / REASON
1	AP Module	416-00297-006	669	22	02.2005	
2	AP Control	416-00298-010	507	22	02.2005	
3	Actuator	418-00876-250	1776	22	03.2005	
4	Actuator	418-00876-250	1826	22	03.2005	
5	Actuator	418-00876-800	1357	22	02.2005	
6	Actuator	418-00876-800	1872	22	02.2005	
7	Optical Fibre Gyro	438-00100-030	04/01542	22	02.2005	
8	Optical Fibre Gyro	438-00100-030	04/01545	22	02.2005	
9	Magnetometer	420-00339-000	1162	22	02.2005	
10	Magnetometer	420-00339-000	1186	22	02.2005	
11	P/R SAS Computer	416-00293-120	556	22	02.2005	
12	ADU 3000	C17027AA01	1347	22	02.2005	

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2 0398

Log Card Page



Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 18













Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SI	EC 135-036	Information concerning improvements to the Automatic Flight Control System AFCS	ECD	INFO 
SI	EC 135-039	Information concerning Operation of the Topping Pushbutton	ECD	INFO 
SI	EC 135-043	Information on the use of reinforced aft crosstubes	ECD	INFO 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 17




Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-85-011	Optional equipment - installation BKM-antenna on tail boom	ECD	N / A 
SI	EC 135-002	Selling of Overhauled and Maintained Main/Components	ECD	INFO 
SI	EC 135-003	JAA FORM 1 for Standard Parts	ECD	INFO 
SI	EC 135-004	JAA-Form 1 for helicopter spare parts	ECD	INFO 
SI	EC 135-005 R1	Customer service-contact names/adresses	ECD	INFO 
SI	EC 135-008	Short circuit hazard in electronic equipment	ECD	INFO 
SI	EC 135-009 R1	Identification of "Important parts"	ECD	INFO 
SI	EC 135-012	Available EC 135 document. and respective revision service	ECD	INFO 
SI	EC 135-013	Info: possibility of caution display comb. occurring on CDS	ECD	INFO 
SI	EC 135-016	Information on the Y2K problem for computer aided systems	ECD	INFO 
SI	EC 135-019 R1	Alteration of oil change intervals for main transmission	ECD	INFO 
SI	EC 135-024	Information and remarks concerning the possibility of inst.	ECD	INFO 
SI	EC 135-029	New issue of parts of the EC135 documentation	ECD	INFO 
SI	EC 135-030	Installation Bulletin from Allied Signal Aerospace	ECD	INFO 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 16

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-71-018 R2	Fuel Return Line - Installation of a Fuel Return Line	ECD	N / A 
SB	EC 135-71-022	Variant-Modification from EC135 T1 with Arrius 2B1 to EC135 P2 with PW206B2	ECD	N / A 
SB	EC 135-71-023 R1	Helicopter Model Conversion from EC 135 T1 to EC 135 T2	ECD	N / A 
SB	EC 135-71-025 R2	OEI Training Mode - Activation of OEI Training Mode Switch	ECD	N / A 
SB	EC 135-71-026	Installation of Heat Protection		
SB	EC 135-71-027	Attachment of Placard at Fuel Filler Neck	ECD	N / A 
SB	EC 135-77-001	Replacement of Dual Torque Indicator and N2 Triple RPM Indicator	ECD	N / A 
SB	EC 135-79-003	Engine Fuzz Burner System	ECD	N / A 
SB	EC 135-79-004	Modification of the Cover for the Protective Screen of the Fan mounted on the Main Transm.	ECD	N / A 
SB	EC 135-80-001	Replacement of Switch Unit	ECD	N / A 
SB	EC 135-85-001	Modification of the fixed provisions	ECD	N / A 
SB	EC 135-85-003	Modification of Cable-Cut Pushbutton	ECD	N / A 
SB	EC 135-85-004	Shortening of the Upper Deflector	ECD	N / A 
SB	EC 135-85-009	Cargo-Hook - Modification of Keeper	ECD	N / A 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 15

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-67-004	Installation of a Cover Assy at the Collective Lever	ECD	N / A ECD D-92
SB	EC 135-67-008	Replacement of Bellcranks with Bearings of lesser Starting Friction	ECD	N / A ECD D-92
SB	EC 135-67-010	Modification of Collective Short-Circuit Plug	ECD	N / A ECD D-92
SB	EC 135-71-001	Replacement of ARRIUS 2B with ARRIUS 2B1 Engines	ECD	N / A ECD D-92
SB	EC 135-71-002	Replacement of P&W Engines with P&W "Low-smoke" Engine Version	ECD	N / A ECD D-92
SB	EC 135-71-004 R1	Replacement of the Drain Lines	ECD	N / A ECD D-92
SB	EC 135-71-005	Reinforcement of Inlet Channels, Stiffener and Forward Firewalls	ECD	N / A ECD D-92
SB	EC 135-71-006	Replacement of the "Plate Assy"	ECD	N / A ECD D-92
SB	EC 135-71-007	Replacement of the Rotor Mast Seal	ECD	N / A ECD D-92
SB	EC 135-71-008 R1	Modification of the T1 Turbomeca Arrius Engines from version 2B1 to version 2B1A	ECD	N / A ECD D-92
SB	EC 135-71-010	Retrofitting of Art Engine Mounts	ECD	N / A ECD D-92
SB	EC 135-71-011	Connection of the Drain Hoses to the Drain Bottle	ECD	N / A ECD D-92
SB	EC 135-71-015	Mod. of T1 Engines from ARRIUS 2B1 to 2B1A_1 or from ARRIUS 2B1A to 2B1A_1	ECD	N / A ECD D-92
SB	EC 135-71-017 R1	Variant-Modification from EC135P1 with PW206B to EC135P2 with PW206B2	ECD	N / A ECD D-92

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 14

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-62-009	Replacement of Discharger Adapters	ECD	N / A ECD D-92
SB	EC 135-62-012 R1	Improvement of the cardan bearing system	ECD	N / A ECD D-92
SB	EC 135-62-015	Introduction of Improved Erosion Prot. And Reidentification of	ECD	N / A ECD D-92
SB	EC 135-62-016	Sealing of end face Wall	ECD	N / A ECD D-92
SB	EC 135-62-017	Introduction of a Sand Erosion Protection on the Blade Tip		
SB	EC 135-62-019	Installation of ventilation element	ECD	N / A ECD D-92
SB	EC 135-63-001 R1	Modification of the Rotor Brake System	ECD	N / A ECD D-92
SB	EC 135-63-004	Retrofitting of Oil Pressure Transducer	ECD	N / A ECD D-92
SB	EC 135-63-005	Main Rotor Drive - Main Transmission - Increase of the Tightening Torque on the Hub-Shaft N.	ECD	N / A ECD D-92
SB	EC 135-63-006	Main Transmission - Replacement of Spacer Tube Assy and Hub-Shaft Roller Bearing	ECD	N / A ECD D-92
SB	EC 135-63-007 R1	Incorporation of Inspection Covers in the Ceiling Panelling	ECD	N / A ECD D-92
SB	EC 135-64-002 R1	Retrofit of Tail Rotor from L642A0101051 into L642A0101052	ECD	N / A ECD D-92
SB	EC 135-67-001 R1	Modification of Pedal Cover on the Copilots Side	ECD	N / A ECD D-92
SB	EC 135-67-002 R2	Modification of Locking Device at the Cyclic Stick (Pilot)	ECD	N / A ECD D-92

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 13

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-34-011	Replacement Standby Compass MC.700-4NVG with Standby Compass 1007KCA1	ECD	N / A ECD D-92
SB	EC 135-34-012	Installation of an Iridium Antenna on the tail boom	ECD	N / A ECD D-92
SB	EC 135-34-013	Activation of Caution Display on Annunciater Control Unit	ECD	N / A ECD D-92
SB	EC 135-34-014	NMS - Modification of Wiring for Resetting the Flight Data in the AMS2000	ECD	N / A ECD D-92
SB	EC 135-52-001	Modification of the Main Tank Covers and Sealing of the Fuel Sensors	ECD	N / A ECD D-92
SB	EC 135-53-006	Replacement of Stator	ECD	N / A ECD D-92
SB	EC 135-53-007	Installation of Covers	ECD	N / A ECD D-92
SB	EC 135-53-011	Precautionary measures against cracking and repair of already affected areas	ECD	N / A ECD D-92
SB	EC 135-53-012	Replacement of the Mounting Brackets for the Radar Altimeter	ECD	N / A ECD D-92
SB	EC 135-53-013 R1	Mod. of Cross Beam by means of Cutout Recesses for Terminal Blocks 120VV / 220VV	ECD	N / A ECD D-92
SB	EC 135-62-001 R1	Inspection of Rectangular Ball Bearing	ECD	N / A ECD D-92
SB	EC 135-62-003 R1	Inspection of Main Rotor Blades in Pitch Control Cuff Area	ECD	N / A ECD D-92
SB	EC 135-62-007	Improvement of Mast Moment System (EURO-5)	ECD	15.Mrc.2005 ECD D-70
SB	EC 135-62-008	Inspection and possible Modification of the Lead-Lag Dampers	ECD	N / A ECD D-92

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 12







Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-31-010 R1	Improvement of Data Transfer for Data Line ARINC 429	ECD	N / A ECD D-92
SB	EC 135-31-012	Modification of CVFDR Erase Function	ECD	N / A ECD D-92
SB	EC 135-31-013	Indication and Recording Systems - CDS - Replacement of the CDS by an Improved Version	ECD	N / A ECD D-92
SB LTA/AD	EC 135-31A-002 R2 2001-306/3	Replacement of the primary Flight Displays(PFD) and/or replacement of the NDs	ECD	N / A ECD D-92
SB	EC 135-32-005	Modifications on HC before initial Inst. of the Version II det. parts of the emery floats	ECD	N / A ECD D-92
SB	EC 135-32-006	Installation of a new version II of the detachable part of the emergency float system	ECD	N / A ECD D-92
SB	EC 135-32-008	Retrofit of snowskids	ECD	N / A ECD D-92
SB	EC 135-32-009 R01	Replacement of Switch Lock on Collective Lever	ECD	N / A ECD D-92
SB	EC 135-33-003	Lights- Anti Collision Light (NVG)	ECD	N / A ECD D-92
SB	EC 135-34-002	Replacement of the Static Ports	ECD	N / A ECD D-92
SB	EC 135-34-003 R1	Replacement of Radar Altimeter KRA 405 by KRA 405B	ECD	N / A ECD D-92
SB	EC 135-34-004 R1	Mod. and Lengthening of the Transmitter Wire for the Radar Altimeter KRA 405B	ECD	N / A ECD D-92
SB	EC 135-34-006	Navigation - Tactical Radio - Deactivation "ELMER RT651/N-A"	ECD	N / A ECD D-92
SB	EC 135-34-010	Electrical Connection of Integrated Vibrator		

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 11











Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-28-006 R1	Replacement of "Globe" Type Fuel Pump with the "Test Fuchs" Type Fuel Pump	ECD	N / A 
SB	EC 135-28-007	Modification of the Fuel Tank System to 710 liters of capacity	ECD	N / A 
SB	EC 135-28-008	Inspection for correct Installation of Drain Line Outlet Tube	ECD	N / A 
SB	EC 135-28-009	Modification of Dual Connector of Venting System when Auxiliary Tank	ECD	N / A 
SB	EC 135-28-012	Conversion of Fuel Quantity Ind. from Analog. Ind. to Digital Ind. on the CPDS	ECD	N / A 
SB	EC 135-28-013	Fuelsystem External Fuel tank Activation of Digital Fuel level Indication on CPDS	ECD	N / A 
SB	EC 135-29-001	Improvement of Hydraulic Drain Lines	ECD	N / A 
SB	EC 135-29-002	Installation of additional attachment points	ECD	N / A 
SB	EC 135-29-006	Missing Identification Sleeve on Switch Lever HYD TEST	ECD	N / A 
SB	EC 135-31-001	Replacement of Cockpit display system CDS	ECD	N / A 
SB	EC 135-31-006 R2	Replacement of the CDS by an Improved Version	ECD	N / A 
SB	EC 135-31-007 R1	CPDS Upgrade of Software Version V2001A to V2002	ECD	N / A 
SB	EC 135-31-008	Modification of Cockpit Display System	ECD	N / A 
SB	EC 135-31-009 R1	CPDS Upgrade of Software Version to V2003	ECD	N / A 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 10

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
SB	EC 135-11-014	Attachement of a placard for "Hellas-System" on the I-Panel	ECD	N / A 
SB	EC 135-11-015	Replacement of the Placard on the Auxiliary Fuel Tank	ECD	N / A 
SB	EC 135-21-001	Replacement of Circuit Breaker 12HB	ECD	N / A 
SB	EC 135-22-002	Pitch and Roll Stability Augmentation System - Replacement of the P/R SAS Computer	ECD	N / A 
SB	EC 135-22-003	Replacement of Autopilot Computer Module	ECD	N / A 
SB	EC 135-22-004	Replacement of Autopilot Computer Module APM 2000	ECD	N / A 
SB	EC 135-22-005	Automatic flight control system AFCS - Improvement of the temp. stability of the AFCS	ECD	N / A 
SB	EC 135-22-008	Retrofitting of a Relais	ECD	N / A 
SB	EC 135-22-009	Pitch and Roll Stability Augmentation System	ECD	N / A 
SB	EC 135-23-001	Communication ATC Retrofit of NMC-CMA300 SW007 and or higher	ECD	N / A 
SB	EC 135-23-002 R 1	ATC - Replacement of secondary radar answering unit (MST 67A) (only published in German)	ECD	N / A 
SB	EC 135-24-008	Capping and stowing of wires at Module TB5 in order to ensure selection of the corr. Engine	ECD	N / A 
SB	EC 135-25-003	Retrofit of emergency locator transmitter C406-N HM		
SB	EC 135-28-003	Modification of Venting System	ECD	N / A 










6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

9

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASI	EC 135-A052	Information concerning a crack in the hoist boom adapter of the ext. mounted hoist	ECD	INFO 
ASI	EC 135-A053	Information concerning use of rivets for repairs to the helicopter structure	ECD	INFO 
ASI	EC 135-A054 R1	"Flight Report" page displayed on CPDS	ECD	INFO 
ASI	EC 135-A057	SIL 4502/3-350-0-24-001,4502/3-300/350-24-003,4502/3-300/350-24-004 and SB 4502/3-350-24	ECD	INFO 
ASI	EC 135-A060	Note concerning operation of external mounted hoist	ECD	INFO 
ASI	EC 135-A061	Quick-release rope suspension device - Service Letter 27-SL-E01-01-04 issued by BUCHER	ECD	INFO 
ASI	EC 135-A062	Notes regarding installation of the tail rotor	ECD	INFO 
ASI	EC 135-A063	EMS- Lifepak 12 Defibrillator/Monitor - Medical Device Notification of the Medtronic Company	ECD	INFO 
SB	EC 135-11-003 R2	Adaptation of placards in connection with an increased perm. gross mass up to 2835 kg	ECD	N / A 
SB	EC 135-11-005	Information label for operation of radar altimeter KRA 405	ECD	N / A 
SB	EC 135-11-006	Attachement of a placard on the CAD	ECD	N / A 
SB	EC 135-11-007	Fitting of a Placard on Helicopters with Reinforced Aft Cross Tubes	ECD	06.Apr.2005 
SB	EC 135-11-010	Replacement of a Placard at the Filler Neck of the Main Tank and Auxiliary Fuel Tank	ECD	N / A 
SB	EC 135-11-011	Installation of "Alternate Static System Correction" Table	ECD	N / A 










6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

8

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASI	EC 135-A025	Service Info Letter from Schroth Safety Products GmbH	ECD	INFO 
ASI	EC 135-A026	Service Bulletin from Wulfsberg Electronics Division	ECD	INFO 
ASI	EC 135-A027	Operation instructions for the reeling device, produced by the TOST company...	ECD	INFO 
ASI	EC 135-A031	Display error on Displaysystem SMD45H	ECD	INFO 
ASI	EC 135-A033	Instr.of the use of the safety-belt system for securing the operator of an external m.hoist	ECD	INFO 
ASI	EC 135-A037	Service Information Letter from THALES Company	ECD	INFO 
ASI	EC 135-A038	Service Bulletin No. 012-0705-103 from Honeywell	ECD	INFO 
ASI	EC 135-A041	Occurrence of CAT A caution indication during CAT A mode	ECD	INFO 
ASI	EC 135-A044	Service Information Letter from THALES Company	ECD	INFO 
ASI	EC 135-A045	Service Information Letter from Wulfberg Electronics Company	ECD	INFO 
ASI	EC 135-A046	Service Information Letter from Sagem Company	ECD	INFO 
ASI	EC 135-A047	Service Bulletin No. "C12847-31-001" from Thales	ECD	INFO 
ASI	EC 135-A050	Securing of the detachable sunshade	ECD	INFO 
ASI	EC 135-A051	Service Bulletin No. "WSB AT-434-6" from the Wulfsberg company	ECD	INFO 












6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

7

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-85A-010	Inspection of Wire Harness 39VB	ECD	N / A 
ASB	EC 135-85A-012	Crack on Adapter of Boom Assy, Goodrich Service Bulletin 44301-500-02	ECD	N / A 
ASI	EC 135-A002	Replacement of the Primary Flight Displays (PFD) and/or NDs	ECD	INFO 
ASI	EC 135-A006	Search and Landing Light, P/N L344 M3814 051	ECD	INFO 
ASI	EC 135-A007	Modification of the KGS-Inverter SPC-10(HD)	ECD	INFO 
ASI	EC 135-A010	Notes concerning emergency procedures for engine operation	ECD	INFO 
ASI	EC 135-A011	Procedure for eliminating pilot induced oscillations	ECD	INFO 
ASI	EC 135-A014	Info: Contact between tail rotorshaft/fuselage struct. parts	ECD	INFO 
ASI	EC 135-A015	Informations concerning the FCDS	ECD	INFO 
ASI	EC 135-A017	Information on Y2K compatibility for computer-aided systems	ECD	INFO 
ASI	EC 135-A018 R1	Information concerning P&W ASB No. 28184R01 and SB 28186	ECD	INFO 
ASI	EC 135-A021	Information concerning the discovery of cracks in areas of..	ECD	INFO 
ASI	EC 135-A022	Information in connection with cracks found on the adapters	ECD	INFO 
ASI	EC 135-A023	Information in connection with cracks found on the brackets	ECD	INFO 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

6

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-71A-009	Retrofit of the Air Wall Attachement and Replacement of the Air Wall	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-71A-016 2001-304 R1	Synchronization Procedure for Fuel Control Comp. for sustaining the Autom. Engine Control	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-71A-019 2001-304/2	EC135 T1-Software TU19C on EECU	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-71A-020 2001-304/2 R1	Software Improvement TU45C on FADEC without Increase of OEI Power	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-71A-021 2001-304/2	Description of a more detailed Starting Proc. in order to avoid possible Start-up Overspeed	ECD	N / A ECD D-92
ASB LTA	EC 135-71A-024 2002-333	Synchronization procedure for FC Components for sustaining the Automatic Engine Control	ECD	N / A ECD D-92
ASB	EC 135-76A-001	Emergency Engine Controls - Functional Test and, if necessary, Replacement of Gearboxes	ECD	N / A ECD D-92
ASB	EC 135-77A-002	Replacement of Triple RPM Indicator	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-79A-001 1998-109	Replacement of shaft with spline	ECD	N / A ECD D-92
ASB	EC 135-79A-002	Application of Sealing to the Screen of the Fan	ECD	N / A ECD D-92
ASB	EC 135-85A-002	Replacement of Junction Box	ECD	N / A ECD D-92
ASB	EC 135-85A-005	Insp. of Locking plate, Insp. of Cable Cutter System, Mod. or Repl. of Junction Box	ECD	N / A ECD D-92
ASB	EC 135-85A-006	Replacement of Blind Rivets i.a.w. Goodrich Service Bulletin 44301-500-01	ECD	N / A ECD D-92
ASB	EC 135-85A-007	Issue of an Alert Service Bulletin of the CUMULUS Company	ECD	N / A ECD D-92

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 5

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-62A-014	More detailed Preflight Check	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-63A-002 R4 2001-107	Visual Inspection or Crack Inspection on Torque Struts and on Emergency Stop	ECD	N / A ECD D-92
ASB	EC 135-63A-003	Inspection of Rotor Brake Disk	ECD	N / A ECD D-92
ASB	EC 135-64A-001	Reidentification of Tail Rotor	ECD	N / A ECD D-92
ASB	EC 135-65A-001 R1	Inspection of Rubber Sleeves	ECD	N / A ECD D-92
ASB	EC 135-65A-002 R1	Replacement of Tail rotor drive shaft	ECD	N / A ECD D-92
ASB	EC 135-65A-003	Repl. and Change of Insertion Direction of the att. Hardware at bearing location 1 on TRDS	ECD	N / A ECD D-92
ASB	EC 135-67A-003 R3	Inspection and Repair or Modifications of Tail Rotor Controls	ECD	N / A ECD D-92
ASB	EC 135-67A-005	Inspection of the mounted position of the SEMA actuator installed on the SAS control rod	ECD	N / A ECD D-92
ASB	EC 135-67A-006	Inspection of Lateral Control Lever for safe locking	ECD	N / A ECD D-92
ASB LTA	EC 135-67A-007 2002-396/2	Check of the Serial Number of and, if necessary, Replacement of the Main Rotor Actuator	ECD	N / A ECD D-92
ASB	EC 135-67A-009	Remove Tail Rotor Pedals and Inspect Pedal Bearings		
ASB	EC 135-67A-011	Insp. of attachment hardware and connecting parts between ball bearing control and yaw act.		
ASB	EC 135-71A-003	Modification of Air Wall, Center Sheet and Console	ECD	N / A ECD D-92

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

4

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-53A-003 R2	Inspec. of Roller Bearing to Bearing Support attaching Hardware	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-53A-004 98-389/033/7	Replacement of bearing supports	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-53A-005 1998-033/7 R3	Measur of Vibr. on TRDS and Repl. of Roller Bearing Att. Hardware at BearingLocations	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-53A-008 1999-102/2 R2	Acc. of an insp. of the att. hardware at bearing location 1 of the tail rotor drive shaft	ECD	N / A ECD D-92
ASB	EC 135-53A-009	Repl. of the att. hardware at bearing location1 of the tail rotor drive shaft with mod part	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-53A-010 1999-199/3 R2	Crack insp. on the Connecting Frame Flange and mod. of the bearing att. at bearing loc.1	ECD	N / A ECD D-92
ASB	EC 135-53A-015	Transmission Deck - Visible inspetion of XY-fittings for cracks		
ASB	EC 135-56A-001	Introduction of an Inspection for the Window Pane of the Sliding Door and Improvemnet of Jet.	ECD	N / A ECD D-92
ASB	EC 135-62A-002	Improvement of Ring	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-62A-004 1999-185/4 R3	Crack inspection at the Main Rotor Hub-Shaft	ECD	N / A ECD D-92
ASB LTA/AD	EC 135-62A-005 1999-264 R1	Inspect screw connection of bearing support for correct fit, Replacement of screw connection	ECD	N / A ECD D-92
ASB	EC 135-62A-010	Application of a slippage mark at the hexagonal head bolt and, if necessary, replacem. of..	ECD	N / A ECD D-92
ASB	EC 135-62A-011	Replacement of the shims	ECD	N / A ECD D-92
ASB	EC 135-62A-013	Crack inspection on the attchment plate for the rotor hub cap	ECD	N / A ECD D-92









6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

3

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-28A-011	Main Tank - Installation of an additional cover onto Auxillary Fuel Tank Connection	ECD	N / A 
ASB	EC 135-29A-003	Tailboom Fixing of "Additional Hydraulic Shielding Hose"	ECD	N / A 
ASB	EC 135-29A-005	Inspection on Return Line and Modification of Wiring Bundle Attachment	ECD	N / A 
ASB	EC 135-31A-003	Replacement of the Primary Flight Displays and/or replacement of the NDs	ECD	N / A 
ASB	EC 135-32A-001	Replacement of Float Assembly Attachment Bolt	ECD	N / A 
ASB	EC 135-32A-007	Emergency Flotation System - Replacement of Cylinder Supports and of Electrical Cable	ECD	N / A 
ASB	EC 135-32A-010	Assembly of new removable Parts of the EFS Version II	ECD	N / A 
ASB	EC 135-33A-001	Introduction of an inspection and life limit i.a.w. "Safety and SB SL 0899-01A"	ECD	N / A 
ASB	EC 135-33A-002	Safety and SB SL0198-01, SL0898-01, SL0898-02, SL0600-01 issued by Hughes Spectrolab	ECD	N / A 
ASB	EC 135-34A-007	Magnetic Sensors - Modification of Platform for Magnetic Sensors	ECD	N / A 
ASB	EC 135-34A-009	Reroute Pitot-Static Supply to the Copilot Side	ECD	N / A 
ASB	EC 135-52A-003	Doors and Service Covers - Sliding Doors - Visual Inspection for Cracks in the Upper Arm	ECD	15.Mrc.2005 
ASB LTA/AD	EC 135-53A-001 97-249 R3	Inspection of the Stator	ECD	N / A 
ASB LTA/AD	EC 135-53A-002 1998-033/7 R2	Inspection of bearing supports	ECD	N / A 










6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page

2








Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-24A-002	Replacement of High Power Consumer-Fuses	ECD	N / A 
ASB	EC 135-24A-003	Installation of Ground Reference Wire	ECD	N / A 
ASB	EC 135-24A-004	Inspection of free space around electrical wiring and modification	ECD	N / A 
ASB	EC 135-24A-005	Generator Power lines -Inspection and, if necessary, Mod. of the Routing of Power Lines	ECD	N / A 
ASB	EC 135-24A-006	Inspection and, if necessary Replacement of Contact Receptacles	ECD	N / A 
ASB	EC 135-24A-007 R1	Restriction in the reset procedures for gen. Caution: GEN DISCON and bus con. BUSTIE OPN	ECD	N / A 
ASB	EC 135-24A-009	Replacement of Relay M320D4N with Relay M500D4N	ECD	N / A 
ASB	EC 135-25A-001	Retrofit Seat Tracks Fenders for Pilots and Copilots Seat Tracks	ECD	N / A 
ASB	EC 135-25A-002	Stiffening of the Equipment Plate	ECD	N / A 
ASB	EC 135-26A-001	INSP: For Interchanged Electrical Connection Syst. I and II	ECD	N / A 
ASB	EC 135-28A-001	Removal or Replacement of a Sealing Ring on the Fuel Pumps	ECD	N / A 
ASB	EC 135-28A-002	Identification and, if necessary, Replacement of Fuel Sensors	ECD	N / A 
ASB	EC 135-28A-004	Installation of an additional grounding strip	ECD	N / A 
ASB	EC 135-28A-010	Establishing of an additional Ground Connection	ECD	N / A 

6. MODIFICATION AND SERVICE BULLETINS CHECKING

EC 135 P2

0398

Log Card Page 1

Type	Modification-/ Bulletin No. AD / LTA	Titel	Performing unit or contractor	Date of embodiment and inspection stamp
ASB	EC 135-04A-001	Reduction and Introduction of Life Limits because of increased MTOW	ECD	N / A 
ASB	EC 135-04A-004	Introduction of Life Limits for Tail Rotor Drive Shafts	ECD	N / A 
ASB	EC 135-04A-005	Change of the Life Limit of the Input Flange of the Tail Rotor Gearbox	ECD	N / A 
ASB	EC 135-11A-001	Replacement of Placard Fuel Cap	ECD	N / A 
ASB	EC 135-11A-002	Replacement of permissible gross mass and airspeed limit placards	ECD	N / A 
ASB	EC 135-11A-004	Installation of an additional placard for operation of the Directional Gyro	ECD	N / A 
ASB	EC 135-11A-008	Attachement of a placard at the fuel filler neck	ECD	N / A 
ASB	EC 135-11A-009	Replacement of placard at the fuel filler neck	ECD	N / A 
ASB LTA/AD	EC 135-21A-002 2000-270 R1	Installation of an Isolation Mat in the area of the Spring Resistor	ECD	N / A 
ASB	EC 135-21A-003	Inspection and, if necessary, replacement of bleed air shut-off valve	ECD	N / A 
ASB	EC 135-22A-001 R1	Instructions in the case of Defects in the Pitch and Roll Stability Augmentation System	ECD	N / A 
ASB	EC 135-22A-006	Reconfiguration of the FCDM - Modification of the Connections on Modules TB421/3	ECD	N / A 
ASB	EC 135-22A-007 R1	Inspection of Electrical Wiring for Correctness of Connections to Modules TB 104, 105, 106	ECD	N / A 
ASB	EC 135-24A-001 R2	Improvement of the Electrical Master Box	ECD	N / A 

7. SUCCESSIVE STATUS, MAINTENANCE AND OVERHAUL OPERATIONS

[illegible]

6. MODIFICATION AND SERVICE BULLETIN CHECKING							AIRCRAFT LOG CARD				Log Card No: 1
No.	Type of modification			Performing unit or contractor	Date of embodiment and inspection stamp		1. MATERIAL IDENTIFICATION				
1	Service Bulletins see Log Card Chapter 6			ECD	07.04.2005		Name HELICOPTER NATO Nomenclature ECD Part number EC135 P2 Manufacturer's P/N NATO Code CO 418 Delivery config. Version Serial number 0398 Amendments Supplier EUROCOPTER DEUTSCHLAND GmbH Typ				
							2. CONTRACT OR ORDER				
							Reference Date Issuing agency Kit No. Contrator Address				
							3. GUARANTEE				
							Material	Date of delivery	Guaranteed storage period	Service date	Guarantee operation period
							4. SPECIAL INFORMATIONS				
5. OPERATIONS							Monitoring of life limited components * YES ☐ NO ☒ No. of sheet : Appendix to table 4 YES ☐ NO ☒ No. of sheet : Transfer sheet YES ☐ NO ☒ No. of sheet : Remarks: Key's : Cabine door : A0091 Cargo door : A0091 Tank lock : A0091 * see Aircraft Log Book Chapter 7.2				
Contractor	Date	Aircraft Version and S/N	Support	Partial	Total	Certification	Operating limit (TBO) Life limit (TCI): ATA 100 Ch 53				
ECD	04/05	03:50	---	---	03:50	Manufacturing					
						Depreservation					
						Period.Overhaul					
						Fitting					