

Transport Canada Aviation Transports Canada Aviation

TP3911E

## AIRCRAFT TECHNICAL LOGS

Section 4. PROPELLER

**Second Edition** 

January 1987

Canada

The subject aircraft was involved in an incident / accident on 10/9/2024 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 3807548885US.

Signed: Underwriters Salvage Company

Date: 2/25/2025 AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100

## PROPELLER SERVICE AND

DATE	TIME RUN		TOTAL TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS,	
DATE	HRS. MIN. HRS. MIN.				MPLETE	
ROU(	-	Precision	Aircraft Mai	ntenance – !	-5011 Sabre Ln., Denton, TX, 76207 – 940.367.5988 – 409.767.1158	
_	16 P 110	cision			N6352T	
Engine	Make: Lyco	ming		Propeller	er Make: Sensenich AF Make: Piper Date: 01APR2023 -	
	Model: 0-3		-50000	Propeller	er Model: 76EM8S5-0-60 AF Model: PA-28-180 TACH: 3793.4 er S/N: 39175K AF S/N: 283669	
	S/N: L-1027 TT: 1.1	6-36A			er S/N: 39175K AF S/N: 283669 er TT: 357.28 AFTT: 3793.4 -	
	TTSOH: 1.1			Tropener		
				100	PROPELLER	
	This propell	er was ir	nspected IAV	N an annual	ıl/100HR inspection per FAR 43 appendix (d).	
	This proper	C1 1705 II	поресто			
L CERT	TEV THIS A	IRCRA	FT HAS E	BEEN REP	PAIRED AND INSPECTED IN ACCORDANCE WITH AN ANNUAL/100HR	
INCDE	CINA MOITS	THE C	LIRRENT F	EDFRAL A	AVIATION REGULATIONS AND WAS DETERMINED TO BE IN ARWORTHY	
COND	ITION WITH	RESPE	CT TO TH	E WORK P	PERFORMED AND IS APPROVED FOR RETURN TO SERVICE.	
			4	1	the trans	2.7
Wesley	Pearce AP 272	29740 IA	100			
			1250		Wife and the Control of the Control	9
		-All	(A)	(		
\	vo: N6352T 0	5-06-202	24		Propeller · page 1 of 1	
		1 25.3	Sept.		WINTENANCE	
		Sillian.	Sarasota A	vionics · 140	10 Airport Ave E · Venice, FL 34285 · 941-800-2135	
	N6352T				76EM8S5-0-60, S/N: 39175K May 15, 2024	
-	ETT: 93.5 PTSO: 82.0			OP TT: 449 F: 3875.5		
—   P	erform an an	nual/10	00 hour in	spection IA	AW Piper AMM, and Sensenich Propeller MM. Remove spinner	
B	enair crack in	n spinn	er with epo	oxy resin a	dition and security. All work done IAW Piper and Sensenich MM, and paint to match. Dress propeller blades. Reinstall spinner and	
l ri	n aircraft for	operat	tional and	leak check	k. Checked AD's thru current bi-weekly and all applicable are in eller has been inspected in accordance with an annual inspection	
a	nd was found	to be i	in an airwo	orthy condit	lition at this time.	
N	ith respect to	o the w	ork perforr	ned, this p	propeller is approved for return to service.	
				Marc	1110	
s	cott hyde A&I	P, IA 41	93028	1 sew		
	ir.				_	
-	A.				·	
wo	: N6352T 05-0	06-2024			SARASOTA Engine - page 1 of 1	
					A VIONICS  B. MAINTENANCE	
		Sa	rasota Avio	nics · 140 A	Airport Ave E · Venice, FL 34285 · 941-800-2135	
	6352T		LYCON	AING, 0-36	360-A4A, S/N: RL-33636-36E May 17, 2024	
TA	ACH: 3865.8	496		<b>-</b> .		
Ins	pected engine exed all rotation	e and i	nstallation	. Test run Dynamically	In for operational check. R & R spinner to inspect propeller.  Illy balanced engine and propeller combination to a final balance and puts. Balanced in accordance and puts. Balanced in accordance and puts.	
01.	of it o weldt	ils were	OI habbe	tile try write	eel with AN4 bolts, washers, and nuts. Balanced in accordance locument AW-9511-2.	
- 1						
sco	tt hyde Airfra	me and	l Powerpla	nt 4193028	28 Seef / ge	
L THIS PAG						

SINCE MFG.

David Townes Cox IA 2679578

PREVIOUS SUMMARY

TOTAL

SINCE MFG.

## PROPELLER LOG

1.	Make		140	SENSENICH
2.	Model -			76EM855-0-60
3.	Specification No.			PHEA
4.	Date of Manufacture			1994 2007
5.	Hub Serial No.			29703K 39175 K
6.	Blade	es		
in	(a)	Design No.		
	(b) Blade Serial Nos.			
		(i)		
		(ii)		
		(iii)		
		(iv)		
		(v)		
(c) Pitch Se			ing	1
		(i)	Basic	60"
		(ii)	High	
		(iii)	Low	
		(iv)	Reverse	

