

The Standard

1900-1901

1901

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS


BRUNGARD AVIATION LLC

3323 Airport Rd. Boulder, CO 80301 (303) 440-4791

Date:	6/27/2023	Reg:	N983PB	TSNEW	374.00	Tach:	376.60
Make:	Sensenich	Model:	2AOR5-F	Serial:			

1) Removed spinner. Inspected for cracks and excess wear. Inspected hub for cracks, leaks, looseness. Inspected blades for grease seals, nicks, cracks.

I certify that this PROPELLER has been inspected in accordance with 14CFR Part 43 Appendix D, Annual inspection guidelines and was determined to be in airworthy condition.



Ken Ellis A&P/IA 264847469

Year: <u>2024</u>	Total Time in Service	Description	Completed annual inspection per scope and detail of
Date: <u>11/7</u>	<u>375.8</u>		FAR 43 APP. D. I certify that this <u>Propeller</u>
Next Inspection Due:	Time Since Overhaul		has been inspected in accordance with annual
<u>475.8</u>	<u>375.8</u>	Mech. Cert. # or Repair Sta	inspection and was determined to be in airworthy condition <u>Enrique Ibarra Jr.</u>
			Number: <u>A&P 3996877 IA</u>

Propeller Record General Information

Propeller Manufacturer Sensenich

Model 2A0R5-F

Type _____

Hub Series # _____

Blade # _____

Date of Manufacture _____

Make/Model

Aircraft Installed On:

Van's RV-12;S

Serial #

12077