

PRATT & WHITNEY PW535E
SN: PCE-DG0338
TSN: 2308.8
CSN: 1307
TSO: N/A
CSO: N/A
W/O: 58241



ENGINE ENTRY

POSITION #1
EMB 505
N16DF
HOBBS: N/A
TTAF: 2308.8
LANDINGS: 1307
22/AUG/2022

Accomplished the following inspections in accordance with PW535E M/M or other approved / acceptable data

- 800 Hour/12 Month Engine Inspection.
- Task 71-00-00-760-823 Clearing of the TLD (Time Limited Dispatch)
- Task 72-00-02-810-801 Check Electronic Engine Control (EEC) Fault Isolation
- Task 72-60-01-212-801 Inspection of Engine Hydraulic Pump Driveshaft Splines
- Task 73-10-05-212-801 Detailed Visual Inspection of Fuel Filter Element
- Task 77-20-02-750-801 Operational Check T6 Temperature Indicating System
- Complied with SB PW500-72-30555 Inspection of Hydraulic Pump Drive Gearshaft Splines
- Complied with SB PW500-72-30560 Rev 1 Inspection/Repair of Electronic Engine Control. Found service bulletin not applicable by serial number not installed. No further action required.

I certify that this engine has been inspected in accordance with approved Pratt & Whitney inspection programs, as required by 14 CFR §91.409 (f) (3), and is determined to be in an airworthy condition and is approved for return to service with regards to the maintenance performed. Pertinent details are on file at this repair station under the above work order. A copy of this work order has been provided to the operator.

Signature



West Star Aviation
796 Heritage Way
Grand Junction, CO 81506 (970) 243-7500

FAA Certified Repair Station
WTXR173J

PRATT & WHITNEY PW535E
SN: PCE-DG0339
TSN: 2308.8
CSN: 1307
TSO: N/A
CSO: N/A
W/O: 58241



ENGINE ENTRY

POSITION #2
EMB 505
N16DF
HOBBS: N/A
TTAF: 2308.8
LANDINGS: 1307
22/AUG/2022

Accomplished the following inspections in accordance with PW535E M/M or other approved / acceptable data

- 800 Hour/12 Month Engine Inspection.
- Task 71-00-00-760-823 Clearing of the TLD (Time Limited Dispatch)
- Task 72-00-02-810-801 Check Electronic Engine Control (EEC) Fault Isolation
- Task 72-60-01-212-801 Inspection of Engine Hydraulic Pump Driveshaft Splines
- Task 73-10-05-212-801 Detailed Visual Inspection of Fuel Filter Element
- Task 77-20-02-750-801 Operational Check T6 Temperature Indicating System
- Complied with SB PW500-72-30555 Inspection of Hydraulic Pump Drive Gearshaft Splines
- Complied with SB PW500-72-30560 Rev 1 Inspection/Repair of Electronic Engine Control. Found service bulletin not applicable by serial number not installed. No further action required.

I certify that this engine has been inspected in accordance with approved Pratt & Whitney inspection programs, as required by 14 CFR §91.409 (f) (3), and is determined to be in an airworthy condition and is approved for return to service with regards to the maintenance performed. Pertinent details are on file at this repair station under the above work order. A copy of this work order has been provided to the operator.

Signature



West Star Aviation
796 Heritage Way
Grand Junction, CO 81506 (970) 243-7500

FAA Certified Repair Station
WTXR173J