

HONDAHonda Aircraft Company, LLC
6420 Ballinger Road
Greensboro, NC 27410

Log Book Entry

Tail #: N103JT
WP#: WP303009
Page: 1 of 1
Revision IR 1/1/13 RSF-100

Release AC End Item: HF120

Position: Right

Type	Model	SN	Hours	Min	Ldgs / Cys
Engine	HF120	883442	3536	48	2379

The work identified below has been accomplished in accordance with the following referenced data or as otherwise noted:

AMM Ref.: HA-420

LMM Ref.: HF120

Sequence	Action Taken			
Parts	Qty	PN	Description	CD Serial


- 72501** Performed required GHAE engine inspections per Special Inspection Workscope HF120-2024-001-ESN883445 up to Step 5, item b on RH side engine S/N 883442. Borescope inspection F.1.a, F.3.a, and F.3.b. was previously complied with by Banyan Air Services on WO 050/51448.
- 72503** Performed a long term preservation on the RH engine P/N HJ1-17201-120-004, S/N 883442 in accordance with GHAE HF120 LMM 72-00-00-620-011. Engine preserved on 11/15/2024, expires on 11/14/2025.

The maintenance and inspections listed above have been performed in accordance with the manufacturers recommendations and additional maintenance must be performed prior to Aircraft return to service. A list of discrepancies and unairworthy items has been provided for the aircraft owner or operator. Further details are on file at the Repair Station under the above work package.

Date:

11 / 18 / 2024

Signature:



For FAA CRS 3HDR835B/EASA 145.6748

HONDAHonda Aircraft Company, LLC
6420 Ballinger Road
Greensboro, NC 27410

Log Book Entry

Tail #: N103JT

WP#: WP303009

Page: 1 of 1

Revision IR 1/1/13 RSF-100

Release AC End Item: HF120

Position: Left

Type	Model	SN	Hours	Min	Ldgs / Cys
Engine	HF120	883445	3357	18	2243

The work identified below has been accomplished in accordance with the following referenced data or as otherwise noted:

AMM Ref.: HA-420

LMM Ref.: HF120

Sequence	Action Taken
Parts	Qty PN Description CD Serial

- 72001** Performed required GHAE engine inspections per Special Inspection Workscope HF120-2024-001-ESN883445 up to Step 5, item b on LH side engine S/N 883445. Borescope inspection F.1.a, F.3.a. and F.3.b. was previously complied with by Banyan Air Services on WO 050/51448.
- 72003** Performed a long term preservation on the LH engine P/N HJ1-17201-120-003, S/N 883445 in accordance with GHAE HF120 LMM 72-00-00-620-011. Engine preserved on 11/15/2024, expires on 11/14/2025.

The maintenance and inspections listed above have been performed in accordance with the manufacturers recommendations and additional maintenance must be performed prior to Aircraft return to service. A list of discrepancies and unairworthy items has been provided for the aircraft owner or operator. Further details are on file at the Repair Station under the above work package.

Date: 11/18/2024

Signature: 

For FAA CRS 3HDR835B/EASA 145.6748