# Propeller Log

N30853

Mt-Propeller

MTV-9-B

S/N 110647

The subject aircraft was involved in an incident / accident on <u>9/1/2024</u> rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: <u>8178283239US</u>.

Signed: Underwriters Salvage Company

Date: 12/2/2024
AIG Aerospace Adjustment Services Inc
3500 Lenox Road. Suite 1100

	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
				TOTAL brought forward from previous page	
	i.			Propeller Looker L. P.	
	N3085.	3		Propeller Logbook Entry	
	Date09	/05/2020			-
	Tach 2.	537.42			
	TTSN	1013.12			
	l:Inspect p	ropeller in accor	dance with FAR 43	Inspection  3, Appendix D (Annual Inspection) Using MT instructions  AD Compliance	
	1: Research	all AD notes	AD compliance she	AD Compliance	
	time)		to compliance she	AD Compliance sets in folder with these records (no new or recurring AD notes at this	
	l certify th	oetsch 34692781	ted this propeller in	accordance with an annual inspection and find in a land	
	4-1	3707278		n accordance with an annual inspection and find it to be in airworthy condition.	
		~			
	T -		1		
_	: [				
				Propeller Logbook Entry	
_	N30853			- Sand Littly	
	Date 06/10	0/2021			
_	Tach 2694				4
		.52			
_	TTRSN 11	70.22			
1	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee.		
_	TTRSN 11: 1: Remove prop	70.22	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	se. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	se. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	Se. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	Se. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	Se. BAP		
	TTRSN 11: 1: Remove prop	70.22 Deller for service	Se. BAP		
	TTRSN 11: 1: Remove prop	70.22 peller for service etrsch 3469278	ee. BAP		
	TTRSN 11: 1: Remove prop	70.22 peller for service etrsch 3469278	Se. BAP		
	TTRSN 11: 1: Remove prop	70.22 peller for service etrsch 3469278	Se. BAP	SUB- TOTALS this page	

Propeller Logbook Entry  Propeller Logbook  Propeller Logbooy  Propell		Pro	opeller Logbook Entry
Propeller Logbook Entry  Was 294.66 2 694.66  TISN 1370.76  TISPOH 0  Inspection  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Inspection  Inspection	N30853	200	
Inspection Using MT instructions AD Compliance Research all AD notes. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  Inspection Ins			
Inspection Institution Inspection Inspect and Ind Doutes Inspection Inspectio	Tach 2894.66 2	1694.66	
Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions  AD Compliance Research all AD notes. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  330853 Date 08/16/2024 Tach 2969.9 Hobbs 2543.9 TTSPOH 275.4 Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions  AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed I Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 Inspection and find it to be in airworthy condition.			
Propeller Logbook Entry  Propeller Logbook Entry  Wash 296.9  Ab Compliance  Research all AD notes. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Propeller Logbook Entry  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Lectrify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition. ames A. Goetsch 346927814  Propeller Logbook Entry  Wash 296.9  Install Propeller in accordance with FAR 43, Appendix D (Annual Inspection)  Inspection  Inspection  Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions  AD Compliance  Research all AD notes.  AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection  AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  Linstall Propeller Overhauled by Tiffin Aire, Inc under W/O 25404	TTSPOH 0		Increation
Research all AD notes. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 It certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Work performed  Propeller Logbook Entry  Was A. Goetsch 346927814  Propeller Logbook Entry  Was A. Goetsch 346927814  Propeller Logbook Entry  Was A. Goetsch 346927814  Inspection  Inspection  Inspection  Inspection  Inspection  Research all AD notes.  AD 07-26-13 (Blade Leading edge crosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection  AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 254044  Inspection and find it to be in airworthy condition	:Inspect propeller in acce	cordance with FAR 43, Appendix	D (Annual Inspection) Using MT instructions
## Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  ## Work performed  Propeller Logbook Entry  ## Work 2960.9 ## Work 2960.9 ## Work 2960.9 ## Work 2543.9 ## Work 254.9 ##			AD Compliance
Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  Work performed  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  Inspection  Inspection  Inspection  AD Compliance  AD O7-26-13 (Blade Leading edge crosion sheaths) propeller overhauled by Tiffin Aire under W/O #25404 eliminating repetitive inspection  AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.		. AD compliance sheets in folder	
Propeller Logbook Entry  Work performed  In certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.  Propeller Logbook Entry  N30853  Oute 08/16/2024  Fach 2969.9  Hobbs 2543.9  TSN 1645.9  TSPOH 275.4  Inspection  Inspecti		Land by TiMin Ains Incomedant	
Propeller Logbook Entry  N30853 Date 08/16/2024 Tuch 2969.9 Hobbs 2543.9 TTSN 1645.9 TTSPOH 275.4  Inspection	I certify that I have inspe	pected this propeller in accordance	e with an annual inspection and find it to be in airworthy condition.
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	lames A. Goetsch 346927	7814	
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	447		
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
Nate 08/16/2024 Fach 2969.9 Hobbs 2543.9 FTSN 1645.9 FTSPOH 275.4 Inspection Enspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
Pach 2969.9  Hobbs 2543.9  TTSN 1645.9  TTSPOH 275.4  Inspection  Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions  AD Compliance  Inspection  AD Compliance  Inspection  Ins		Pr	opeller Logbook Entry
Fach 2969.9  Hobbs 2543.9  FTSN 1645.9  FISPOH 275.4  Inspection	V30853		
Inspection Inspection Inspection Inspection Inspection Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 It certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	Date 08/16/2024	1	
Inspection Unspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Inspection Work performed Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404 Incertify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	Tach 2969.9		
Inspection Inspection Inspection Inspection Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions AD Compliance Research all AD notes. AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed Inspection  Work performed Inspection and find it to be in airworthy condition	Hobbs 2543.9		
Inspection  Inspection			
Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions  AD Compliance  Research all AD notes.  AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection  AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	ГТЅРОН 275.4		
Research all AD notes.  AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection (and compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	:Inspect propeller in acce	cordance with FAR 43, Appendix	Inspection  Expression (Annual Inspection) Using MT instructions
AD 07-26-13 (Blade Leading edge erosion sheaths) propeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection and compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
AD compliance sheets in folder with these records (no new or recurring AD notes at this time)  Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	: AD 07-26-13 (Blade L	Leading edge erosion sheaths) pro	opeller overhauled by Tiffin Aire under WO #25404 eliminating repetitive inspection
Work performed  Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition			
: Install Propeller Overhauled by Tiffin Aire, Inc under W/O 25404  I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition		in total with these records (no	
I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition	). Install Propeller Overh	nauled by Tiffin Aire Incumder V	Work performed N/O 25404
ames A. Goetsch 3469278IA	I certify that I have inspe	pected this propeller in accordance	e with an annual inspection and find it to be in airworthy condition.
	ames A. Goetsch 346927	78IA	d* Consider
	4-14	2	
	1		
	2		
			1
		-	
		-	
		-	
SUB- TOTALS this page			

TOTAL -- Carry forward to next page

#### Propeller Logbook Entry

N30853 Date 01/11/2017 Tach 1752.4 TTSN 228

Cessna McCauley propeller replaced with MTV-9-B S/N 110647 serviced by Tiffin Aire Inc. under W/O # 22844

Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Research all AD notes. AD compliance sheets in folder with these records. I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.

James A. Goetsch 3469278IA

#### Propeller Logbook Entry

N30853 Date 02/02/2018 Tach 2022.3 TTSN 497.9

#### Inspection

1:Inspect propeller in accordance with FAR 43, Appendix D (Annual Inspection) Using MT instructions

AD Compliance

1: Research all AD notes. AD compliance sheets in folder with these records (no new or recurring AD notes at this time)

I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.

James A. Goetsch 3469278IA

Propeller Logbook Entry


N30853 Date 03/21/2019 Tach 2306.0 Hobbs 1789.0 TT 553.6

#### Inspection

- 1: Inspect Propeller in accordance with FAR 43, Appendix D (Annual Inspection) using MT manual as a guide
  - AD Compliance
- 1: Research all AD notes using (T-data)
- 2: No new or recurring AD notes at this time.

I certify that I have inspected this propeller in accordance with an annual inspection and find it to be in airworthy condition.

James A. Goetsch 3469278 AP-IA



AVIAT AIRCRAFT INC. HUSKY A-1C-180 S/N 3191

## mt-propeller

The Winner's Propeller

#### PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198 Juni 2005

### **MAINTENANCE & SERVICE HISTORY**

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
11/25	494.23	Snew	Remove D From	
2016	329.6	tach	Duist Husky AIC SN3191 N91WY	
			5N3191 N91WY	
			Not black when	
			Not blade where	
			Chinnel	Mullun
			,,	Jun luns 5267/5899
NOTE	Enter Complian	nce With All Applic	able FAA A.D. & Factory Service Bulle	tins On Pages 11 & 12

### MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
29.08.71	00:00	_	Manufactured	6419 H
11/30/12	164.53		Removed from N79WY	ASP 3207506 IP
, ,.			,	/
4/22/	3 164.53	SNEW	I Certify this Propeller	
, ,			F. Certify this Propeller has been inspected TAW	
			A Annual inspection and	
			WAS Determined	
			Airworthy this Date	11 1
			4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1	Jullins 5210715899 AZZ
				5710715899 AZR

### MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
***	297.43		I certify this propeller	, No. 10 10 10 10 10 10 10 10 10 10 10 10 10
9-1-14	Tach 132.9	. 8	has been inspected THE	
		1	A Annual inspection	
		1 2 2 2 26	And was Determined	
		- XX	Airworthy this Date	Alm Ollins
10-2-15	392.82	_	U	52671589974
	228.19	Tach	1 certify this propeller	
			has been inspected IAM	Mr Ollinge
			A Annual inspection and	1 32671589914
			WAS Defermined Alginon	thy this Date
NOTE:	Enter Compliar	nce With All Applic	cable FAA A.D. & Factory Service Bulle	

Owner Name	
Address	
Propeller Model MTV-9-13	
Blade Model	
Hub Serial No	A la
Blade Serial No.1 ACF-43286	Propeller Diameter: 198 cm ± 0,5 cm
2 ACF- 43287	Low Pitch: $\frac{7}{7}$ ° $\pm$ 0,2 ° TCI: $\frac{72}{7}$ Month
3 ACF-43288	High Pitch: $\frac{27}{2}$ ° $\pm$ $\frac{1}{2}$ ° TBO: $\frac{2400}{2400}$ Hrs.
4	Feathering:° ±°
5	Reverse: ° <u>+</u> °
6	at radius station: 74 cm

### INSTALLATION HISTORY

Date	Aircraft Model, Registration & Serial No., Tacho or Hobbs-Time
1-7-2611	Installed New propeller on New Aviat Aircraft Inc.  model A-1C-/8C serial number 3/39 in accordance with applicable technical information and Aviat Aircraft
	Inc. Production Certificate No. 704NM.  Albert G Humbert for Aviat Aircraft
7/27/2012	Installed Propeller on new AvioT Aircraft Inc. model A-1C-
. 7 ~ 5 / 2013	in accordance with applicable Technical Information and Aviot Aircraft Inc. Production Certificate No. 704NM.