

OWNER: FLEXJET
ADDRESS: 26180 CURTISS WRIGHT PKWY
 RICHMOND HEIGHTS OH 44143
PHONE: 972-720-2600
FAX: 216-797-8152

ANALYST: MICHAEL ERNST 216-797-8481 (DIRECT) 972-720-2600 (OFFICE) PLEASE RECORD CHANGES TO ADDRESS, LAST
EMAIL: MICHAEL.ERNST@FLEXJET.COM 216-261-3500 (OFFICE) ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO
 WWW.FLIGHTOPTIONS.COM CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; Disposition: LIFE LIMITED AND OVERHAUL ITEMS; For: Aircraft Only; Time Accrued/Remaining: CHECKED; Generate XLS File: CHECKED;

AIRCRAFT	SERIAL/REGNO: 20038/N517FX	MODEL: CH 300	MANUFACTURER: BOMBARDIER INCORPORATED			
DATES		LAST ACTUALS		CURRENT ACTUAL		
CERTIFICATION DATE: 19-MAR-2005		18585.42 A/C HRS	as of 03-MAR-2025	_____ A/C HRS	as of ____/____/_____	
INSERVICE DATE: 19-MAR-2005		11348 AFL	as of 03-MAR-2025	_____ AFL	as of ____/____/_____	
MANUFACTURER DATE: 19-MAR-2005		17077.13 APH	as of 17-JUL-2025	_____ APH	as of ____/____/_____	

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
CHAPTER 26		FIRE PROTECTION								
26-21-05-101*	APU NO. 2 FIRE EXTINGUISHER CONTAINER (A115) APU DIACHARGE (PN 446518-1) CARTRIDGE									
	446518-1	MOS	120				31-AUG-2019	31-MAR-2027		425 d
	02283	HRS/MSC					13546.22			
LIFE LIMIT	REF:	AFL					8262			
	Manufacture Date: 01-MAR-2017									
26-21-05-101*	LEFT INBOARD NO. 1 FIRE EXTINGUISHER CONTAINER (A112) RH ENGINE DISCHARGE (PN 446518-1) CARTRIDGE									
	446518-1	MOS	120	N:0			02-MAR-2024	31-JUL-2031		2008 d
	AGB4967	HRS/MSC		N:0			17702.12			
LIFE LIMIT	REF:	AFL		N:0			10835			
	Manufacture Date: 01-JUL-2021									
+ 26-21-05-101*	LEFT OUTBOARD NO. 1 FIRE EXTINGUISHER CONTAINER (A111) LH ENGINE DISCHARGE (PN 446518-1) CARTRIDGE									
	446518-1	MOS	120	N:0			02-MAR-2024	31-JUL-2031		2008 d
	AGB4946	HRS/MSC		N:0			17702.12			
LIFE LIMIT	REF:	AFL		N:0			10835			
	Manufacture Date: 01-JUL-2021									
+ 26-21-05-101*	RIGHT INBOARD NO. 2 FIRE EXTINGUISHER CONTAINER (A113) LH ENGINE DISCHARGE (PN 446518-1) CARTRIDGE									
	446518-1	MOS	120				31-AUG-2019	31-MAR-2027		425 d
	02258	HRS/MSC					13546.22			
LIFE LIMIT	REF:	AFL					8262			
	Manufacture Date: 01-MAR-2017									
26-21-05-101*	RIGHT OUTBOARD NO. 2 FIRE EXTINGUISHER CONTAINER (A114) RH ENGINE DISCHARGE (PN 446518-1) CARTRIDGE									
	446518-1	MOS	120				31-AUG-2019	31-MAR-2027		425 d
	02265	HRS/MSC					13546.22			
LIFE LIMIT	REF:	AFL					8262			
	Manufacture Date: 01-MAR-2017									
CHAPTER 27		FLIGHT CONTROLS								
27-41-05-103*	HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA), PART NO. C47100-004/-005 [RII] (DOCUMENT P/N, S/N OF PRIMARY/SECONDARY MOTOR AND BRAKE ASSY WHEN REMOVING AND REPLACING) ACTUATOR									
	C47100-004	MOS					18-DEC-2019			
	0637A	HRS/MSC		N:3015.5			13796.72			
LIFE LIMIT	REF:	AFL	15000	N:1917			8421	21504		10156

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
27-52-13-101*	[RII] DISCARD THE BOLT OF THE LEFT FLAP INBOARD ACTUATOR (WING STATION (WS)122 LEFT) PART NO. 1005756020 SERIALIZED. REFER TO ADVISORY WIRE AW300-57-0167 AND QAB 2015-007 WHEN COMPLYING WITH INSPECTION. QAB CAN BE FOUND ON THE ONESKY PORTAL.									
	1005756020-001	MOS		N:0			25-JUN-2017			
	STR1811	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			7496	14996		3648
27-52-13-101*	[RII] DISCARD THE BOLT OF THE RIGHT FLAP INBOARD ACTUATOR (WING STATION (WS)122 RIGHT) PART NO. 1005756020. REFER TO ADVISORY WIRE AW300-57-0167 AND QAB 2015-007 WHEN COMPLYING WITH INSPECTION. QAB CAN BE FOUND ON THE ONESKY PORTAL.									
	1005756020-001	MOS		N:0			25-JUN-2017			
	STR1803	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			7496	14996		3648
27-52-15-101*	[RII] DISCARD THE BOLT OF THE LEFT FLAP OUTBOARD ACTUATOR (WING STATION (WS) 202 LEFT) PART NO. 1005756020. REFER TO ADVISORY WIRE AW300-57-0167 AND QAB 2015-007 WHEN COMPLYING WITH INSPECTION. QAB CAN BE FOUND ON THE ONESKY PORTAL.									
	1005756020-003	MOS		N:0			25-JUN-2017			
	STR1983	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			7496	14996		3648
27-52-15-101*	[RII] DISCARD THE BOLT OF THE RIGHT FLAP OUTBOARD ACTUATOR (WING STATION (WS) 202 RIGHT) PART NO. 1005756020. REFER TO ADVISORY WIRE AW300-57-0167 AND QAB 2015-007 WHEN COMPLYING WITH INSPECTION. QAB CAN BE FOUND ON THE ONESKY PORTAL.									
	1005756020-003	MOS		N:0			25-JUN-2017			
	STR1989	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			7496	14996		3648
27-52-35-101*	DISCARD THE FPU ECOLOGY (PART NO. 1754A0000-01) BOTTLE									
	1754A0000-01	MOS	60				23-JUL-2021	31-DEC-2025		-30d
	02340	HRS/MSC		N:0			15120.52			
LIFE LIMIT	REF:	AFL		N:0			9226			
	Manufacture Date: 01-DEC-2020									
275229-0201	[RII] LEFT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0202	[RII] RIGHT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0203	[RII] LEFT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0204	[RII] RIGHT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0205	[RII] LEFT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0206	[RII] RIGHT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0207	[RII] LEFT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0208	[RII] RIGHT INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			05-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0209	[RII] LEFT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0210	[RII] RIGHT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0211	[RII] LEFT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0212	[RII] RIGHT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0213	[RII] LEFT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0214	[RII] RIGHT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0215	[RII] LEFT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0216	[RII] RIGHT MID FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-001	MOS		N:0			06-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0401	[RII] LEFT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0402	[RII] RIGHT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0403	[RII] LEFT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0404	[RII] RIGHT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0405	[RII] LEFT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0406	[RII] RIGHT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0407	[RII] LEFT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0408	[RII] RIGHT OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751353-003	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0501	[RII] LEFT INBOARD FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-001	MOS		N:0			29-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0502	[RII] RIGHT INBOARD FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-001 SN-UNKNOWN	MOS HRS/MSC					29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0503	[RII] LEFT INBOARD FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-001 SN-UNKNOWN	MOS HRS/MSC					29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0504	[RII] RIGHT INBOARD FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-001 NSN	MOS HRS/MSC		N:0			29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0601	[RII] LEFT INBOARD FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003 SN-UNKNOWN	MOS HRS/MSC		N:0			29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0602	[RII] RIGHT INBOARD FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003 SN-UNKNOWN	MOS HRS/MSC		N:0			29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0603	[RII] LEFT INBOARD FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003 SN-UNKNOWN	MOS HRS/MSC		N:0			29-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0604	[RII] RIGHT INBOARD FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0605	[RII] LEFT OUTBOARD FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0606	[RII] RIGHT OUTBOARD FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0607	[RII] LEFT OUTBOARD FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0608	[RII] RIGHT OUTBOARD FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0609	[RII] LEFT OUTBOARD FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0610	[RII] RIGHT OUTBOARD FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648
275229-0611	[RII] LEFT OUTBOARD FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648
275229-0612	[RII] RIGHT OUTBOARD FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-003	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648
275229-0701	[RII] LEFT MID FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-007	MOS		N:0			25-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648
275229-0702	[RII] RIGHT MID FLAP FWD INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-007	MOS		N:0			26-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648
275229-0703	[RII] LEFT MID FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-007	MOS		N:0			25-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496		14996	3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
275229-0704	[RII] RIGHT MID FLAP FWD OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-007	MOS		N:0			26-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0801	[RII] LEFT MID FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-005	MOS		N:0			25-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0802	[RII] RIGHT MID FLAP AFT INBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-005	MOS		N:0			26-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0803	[RII] LEFT MID FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-005	MOS		N:0			25-JUN-2017			
	NA	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
275229-0804	[RII] RIGHT MID FLAP AFT OTBD (CARRIAGE SIDE ROLLER) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	1005751354-005	MOS		N:0			26-JUN-2017			
	NSN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
CHAPTER 29	HYDRAULIC POWER									
29-21-13-101*	HYD 50 CU. IN. (THE AUXILIARY HYDRAULIC SYSTEM ACCUMULATOR, PART NO. 900095-1) (*SN SUFFIX MUST CONTAIN E TO BE ALLOWABLE TO INSTALL, REF 2018-20-16) ACCUMULATOR									
	900095-1	MOS					24-JUN-2011			
	60199-1521ENA	HRS/MSC		N:0			6759.8			
LIFE LIMIT	REF:	AFL	15000	N:0			4056	19056		7708
CHAPTER 32	LANDING GEAR									

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
32-11-01-101*	LEFT MAIN LANDING GEAR PINTLE PIN ASSEMBLY 40118-103 SPP0106	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-01-101*	RIGHT MAIN LANDING GEAR PINTLE PIN ASSEMBLY 40118-3 SPP0106	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-01-102*	LEFT MAIN LANDING GEAR MAIN FITTING 40140-101 SPP0047	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-01-102*	RIGHT MAIN LANDING GEAR MAIN FITTING 40140-2 SPP0043	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-05-101*	LEFT [RII] MAIN LANDING GEAR SHOCK STRUT PISTON 40415-1 SPP0093	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-05-101*	RIGHT [RII] MAIN LANDING GEAR SHOCK STRUT PISTON 40415-1 SPP0081	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-05-102*	LEFT [RII] MAIN LANDING GEAR SHOCK STRUT CYLINDER ASSEMBLY 40405-1 SPP0085	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
32-11-05-102*	RIGHT [RII] MAIN LANDING GEAR SHOCK STRUT CYLINDER ASSEMBLY 40405-1 SPP0086	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-05-103*	LEFT [RII] MAIN LANDING GEAR SHOCK STRUT UPPER PIN 40124-1 CPS-0150	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-05-103*	RIGHT [RII] MAIN LANDING GEAR SHOCK STRUT UPPER PIN 40124-1 CPS-0151	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-05-104*	LEFT [RII] MAIN LANDING GEAR SHOCK STRUT LOWER PIN 40124-1 CPS-0148	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-05-104*	RIGHT [RII] MAIN LANDING GEAR SHOCK STRUT LOWER PIN 40124-1 CPS-0157	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-09-101*	LEFT [RII] MAIN LANDING GEAR PIVOT PIN 40111-1 SPP0080	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652
32-11-09-101*	RIGHT [RII] MAIN LANDING GEAR PIVOT PIN 40111-1 SPP0081	MOS HRS/MSC		N:14814.22			29-APR-2021 14814.22			
LIFE LIMIT	REF:	AFL	15000	N:9021			9021	15000		3652

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
32-11-09-102*	LEFT [RII] MAIN LANDING GEAR TRAILING ARM ASSEMBLY 40142-1 SPP0079	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-09-102*	RIGHT [RII] MAIN LANDING GEAR TRAILING ARM ASSEMBLY 40142-1 SPP0083	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-101*	LEFT MLG SIDE BRACE ACTUATOR ROD-END ASSEMBLY 19400-1 388	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-101*	RIGHT MLG SIDE BRACE ACTUATOR ROD-END ASSEMBLY 19400-1 484	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-102*	LEFT MLG SIDE BRACE TO AIRCRAFT UPPER PIN 40241-101 EXC-105	MOS HRS/MSC AFL	15000				19-MAR-2005 0 0		15000	3652
LIFE LIMIT	REF:									
32-11-17-102*	RIGHT MLG SIDE BRACE TO AIRCRAFT UPPER PIN 40241-101 EXC-109	MOS HRS/MSC AFL	15000				19-MAR-2005 0 0		15000	3652
LIFE LIMIT	REF:									
32-11-17-103*	LEFT [RII] MLG SIDE BRACE ACTUATOR CYLINDER ASSEMBLY 40302-2 82	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
32-11-17-103*	RIGHT [RII] MLG SIDE BRACE ACTUATOR CYLINDER ASSEMBLY 40302-1 1049	MOS HRS/MSC AFL	15000	N:0 N:0 N:0			29-APR-2021 14814.22 9021		24021	12673
LIFE LIMIT	REF:									
32-11-17-104*	LEFT MLG SIDE BRACE ACTUATOR PISTON ASSEMBLY 40303-1 42	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-104*	RIGHT MLG SIDE BRACE ACTUATOR PISTON ASSEMBLY 40303-1 600	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-105*	LEFT MLG SIDE BRACE LOWER PIN TO MAIN FITTING ASSEMBLY 40245-1 SPP0053	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-17-105*	RIGHT MLG SIDE BRACE LOWER PIN TO MAIN FITTING ASSEMBLY 40245-2 SPP0040	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-25-101*	LEFT MAIN LANDING GEAR AXLE 40112-1 SPP0082	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									
32-11-25-101*	RIGHT MAIN LANDING GEAR AXLE 40112-1 SPP0083	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
LIFE LIMIT	REF:									

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
32-21-01-102*	NOSE DISCARD THE AXLE OF THE NOSE LANDING GEAR, PART NO. 40642-1, SERIALIZED (NHA PART NO. 40642-101) AXLE 40642-101 07/MD201379 REF:	MOS HRS/MSC AFL	15000	N:14814.22 N:9021			29-APR-2021 14814.22 9021		15000	3652
32-22-00-103*	NLG DOOR HINGE FITTING PINS, PART NO. NAS6304, NON-SERIALIZED DISCARD NAS6304U18D/U16D SN-UNKNOWN REF:	MOS HRS/MSC AFL	7500	N:0			28-JUN-2017 12256.92 7496		14996	3648
32-43-37-101*	THE BRAKE ACCUMULATOR, PART NO. 33-147500 (*SN SUFFIX MUST CONTAIN E TO BE ALLOWABLE TO INSTALL, REF 2018-20-16 & SB 100-32-21 FOR AFFECTED SERIAL NUMBERS) [RII] DISCARD 33-147500 60218-2497NAE REF:	MOS HRS/MSC AFL	15200	R:0 N:2044.9 R:0 N:1010 R:0			04-MAY-2019 13490.62 8233		22423	11075
32-44-05-101*	DISCARD THE EMERGENCY/PARKING BRAKE ACCUMULATOR, PART NO. 33-155500 (*SN SUFFIX MUST CONTAIN E TO BE ALLOWABLE TO INSTALL, REF 2018-20-16 & SB 100-32-21 FOR AFFECTED SERIAL NUMBERS) [RII] DISCARD 33-155500 60219-2374NAE REF:	MOS HRS/MSC AFL APH	8300	N:2531.3 N:1613			07-APR-2020 14034.92 8549		15236	3888
CHAPTER 34		NAVIGATION								
34-11-00-101 LT*	LEFT A137 - PITOT-STATIC - DO NOT EXTEND [RII] PROBE 0856WC3 291552 REF:	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			02-JUN-2015 10519.42 6391		20119.42	1534
34-11-00-101 RT*	RIGHT A138 - PITOT-STATIC (34-11-00-101) [RII] PROBE 0856WC2 307824 REF:	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			21-NOV-2020 14516.52 8857		24116.52	5531.1
CHAPTER 35		OXYGEN								

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
35-11-01-101*	FORWARD OXYGEN STORAGE CYLINDER (77 CU. FT.) P/N 898-MT0C77 OR 806371-121 [BOTTLE CHANGE RII] CYLINDER									
	806371-121	MOS	180				03-AUG-2021	30-APR-2036		3743 d
	ALT281-50163	HRS/MSC					15120.52			
LIFE LIMIT	REF:	AFL					9226			
	Manufacture Date: 01-APR-2021									
35-11-05-101*	AFT OXYGEN STORAGE CYLINDER (115 CU. FT.) P/N 898-MT0C15 OR 806371-111 [BOTTLE CHANGE RII] CYLINDER									
	806371-111	MOS	180				05-FEB-2025	31-OCT-2034		3196 d
	ALT282-43193	HRS/MSC		O:0			18526.52			
LIFE LIMIT	REF:	AFL		O:0			11313			
	Manufacture Date: 31-OCT-2019									
CHAPTER 36	PNEUMATIC									
36-11-49-101*	UROSEAL CONNECTOR PART NO. GG468-4054-3/-19 - (ALI - DO NOT EXTEND) REMOVE AND REPLACE									
	GG468-4054-19	MOS		N:0			06-JUN-2022			
	7071	HRS/MSC	8000	N:0			15898.22	23898.22		5312.8
LIFE LIMIT	REF:	AFL		N:0			9692			
CHAPTER 52	DOORS									
52-11-25-101*	DISCARD OF THE PASSENGER DOOR ACTUATOR CABLE, PART NO. 1005210091-008. [RII]									
	1005210091-007	MOS					06-JUN-2017			
	FR0440	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
CHAPTER 54	NACELLES/PYLONS									
54-51-00-107*	[RII] DISCARD THE LEFT LOWER REAR ENGINE MOUNT BOLT, PART NO. 1005451659, SERIALIZED									
	1005451659-003	MOS		N:0			01-AUG-2017			
	5256	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
54-51-00-107*	[RII] DISCARD THE LEFT UPPER REAR ENGINE MOUNT BOLT, PART NO. 1005451659, SERIALIZED									
	1005451659-003	MOS		N:0			01-AUG-2017			
	5257	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
54-51-00-107*	[RII] DISCARD THE RIGHT LOWER REAR ENGINE MOUNT BOLT, PART NO. 1005451659, SERIALIZED									
	1005451659-003	MOS		N:0			22-JUL-2017			
	5252	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
54-51-00-107*	[RII] DISCARD THE RIGHT UPPER REAR ENGINE MOUNT BOLT, PART NO. 1005451659, SERIALIZED									
	1005451659-003	MOS		N:0			22-JUL-2017			
	5254	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
54-51-00-108*	DISCARD THE LEFT LOWER FORWARD ENGINE-THRUST-LINK BOLT PART NO. 1005451657, SERIALIZED									
	1005451657-005	MOS		N:0			17-JUL-2017			
	4442	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
54-51-00-108*	DISCARD THE LEFT UPPER FORWARD ENGINE-THRUST-LINK BOLT PART NO. 1005451657, SERIALIZED									
	1005451657-005	MOS		N:0			17-JUL-2017			
	4443	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
54-51-00-108*	DISCARD THE RIGHT LOWER FORWARD ENGINE-THRUST-LINK BOLT PART NO. 1005451657, SERIALIZED									
	1005451657-005	MOS		N:0			17-JUL-2017			
	5180	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
54-51-00-108*	DISCARD THE RIGHT UPPER FORWARD ENGINE-THRUST-LINK BOLT PART NO. 1005451657, SERIALIZED									
	1005451657-005	MOS		N:0			17-JUL-2017			
	5181	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
54-51-00-109*	DISCARD THE LEFT AFT ENGINE-THRUST-LINK BOLT, PART NO. 1005451658, SERIALIZED									
	1005451658-005	MOS		N:0			17-JUL-2017			
	4228	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
54-51-00-109*	DISCARD THE RIGHT AFT ENGINE-THRUST-LINK BOLT, PART NO. 1005451658, SERIALIZED 1005451658-005	MOS		N:0			17-JUL-2017			
	4571	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
		APH								
CHAPTER 57		WINGS								
57-11-00-140*	THE TRUNNION TO REAR SPAR TENSION PINS, PART NO. MS21250-08012,08042,08044 NON-SERIALIZED DISCARD									
	MS21250-08012	MOS		N:0			20-JUL-2017			
	NSN	HRS/MSC		N:0			12256.92			
DISCARD	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-101*	DISCARD ATTACHMENT PINS OF THE FLAP INBOARD SUPPORT, PART NO. MS21250-03, NON-SERIALIZED									
		MOS					16-JUN-2017			
		HRS/MSC					12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648
57-51-00-102*	DISCARD ATTACHMENT PINS OF THE FLAP MID SUPPORT, PART NO. MS21250-03, NON-SERIALIZED									
		MOS					16-JUN-2017			
		HRS/MSC					12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648
57-51-00-103*	DISCARD ATTACHMENT PINS OF THE FLAP OUTBOARD SUPPORT, PART NO. B0206003AG6, NON-SERIALIZED									
		MOS					17-JUN-2017			
		HRS/MSC					12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648
57-51-00-104*	DISCARD INBOARD AND MID SUPPORT BOLTS OF THE FLAP, PART NO. NAS6710, NON-SERIALIZED									
		MOS					24-JUN-2017			
		HRS/MSC					12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648
57-51-00-105*	DISCARD OUTBOARD SUPPORT BOLT OF THE FLAP, PART NO. NAS6309, NON-SERIALIZED									
		MOS					24-JUN-2017			
		HRS/MSC					12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
57-51-00-113*	DISCARD BOLTS OF THE INBOARD FORWARD FITTING OF THE FLAP, PART NO. MS21250H05, NON-SERIALIZED - AIRWORTHINESS LIMITATION - DO NOT EXTEND	MOS					08-JUN-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500				12256.92 7496	14996		3648
57-51-00-114*	DISCARD BOLTS OF THE MID FORWARD FITTING OF THE FLAP, PART NO. MS21250H05, NON-SERIALIZED - AIRWORTHINESS LIMITATION - DO NOT EXTEND	MOS					08-JUN-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500				12256.92 7496	14996		3648
57-51-00-115*	DISCARD BOLTS OF THE OUTBOARD FORWARD FITTING OF THE FLAP, PART NO. MS21250H04, NON-SERIALIZED - AIRWORTHINESS LIMITATION - DO NOT EXTEND	MOS					08-JUN-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500				12256.92 7496	14996		3648
57-51-00-116*	NO. 1 DISCARD THE CENTER SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751391-001/-005/-009 AND PART NO. 1005751391N500101- ALI - DO NOT EXTEND DISCARD	MOS					27-JUN-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500	N:0 N:111.9 N:67			12256.92 7496	14929		3581
57-51-00-116*	NO. 2 DISCARD THE CENTER SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751391-001/-005/-009 AND PART NO. 1005751391N500101- ALI - DO NOT EXTEND DISCARD	MOS					27-JUN-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500	R:0 N:111.9 R:0 N:67 R:0			12256.92 7496	14929		3581
57-51-00-117*	NO. 1 DISCARD THE OUTBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751392-001/-005/-011/-015 AND PART NO. 1005751392N500101 - AIRWORTHINESS LIMITATION - DO NOT EXTEND [RII] ASSEMBLY	MOS					27-JUL-2017			
LIFE LIMIT	REF:	HRS/MS AFL	7500	N:111.9 N:67			12256.92 7496	14929		3581

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
57-51-00-117*	NO. 2 DISCARD THE OUTBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751392-001/-005/-011/-015 AND PART NO. 1005751392N500101 - AIRWORTHINESS LIMITATION - DO NOT EXTEND [RII] ASSEMBLY									
	1005751392N500101	MOS					24-JUL-2017			
	83580-11	HRS/MSC		N:111.9			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:67			7496	14929		3581
57-51-00-118*	NO. 1 DISCARD THE INBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751390-001/-007/-011 AND PART NO. 1005751390N500101 - ALI - DO NOT EXTEND [RII] DISCARD									
	1005751390N500101	MOS					24-JUL-2017			
	82667-03	HRS/MSC		N:111.9			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:67			7496	14929		3581
57-51-00-118*	NO. 2 DISCARD THE INBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP, PART NO. 1005751390-001/-007/-011 AND PART NO. 1005751390N500101- ALI - DO NOT EXTEND [RII] DISCARD									
	1005751390N500101	MOS					24-JUL-2017			
	81895-R	HRS/MSC		N:111.9			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:67			7496	14929		3581
57-51-00-119*	NO. 1 FLAP ATTACHMENT BEARING OF THE OUTBOARD FORWARD FITTING, PART NO. HTY10-303 - ALI - DO NOT EXTEND DISCARD									
	HTY10-303	MOS		N:0			16-MAY-2023			
	NSN	HRS/MSC		N:0			17015.32			
LIFE LIMIT	REF:	AFL	5500	N:0			10396	15896		4548
57-51-00-119*	NO. 2 FLAP ATTACHMENT BEARING OF THE OUTBOARD FORWARD FITTING, PART NO. HTY10-303 - (ALI - DO NOT EXTEND) DISCARD									
	HTY10-303	MOS		N:0			15-MAY-2023			
	NSN	HRS/MSC		N:0			17015.32			
LIFE LIMIT	REF:	AFL	5500	N:0			10396	15896		4548
57-51-00-120*	NO. 1 FLAP ATTACHMENT BEARING OF THE CENTER FORWARD FITTING LH WS 121.50, PART NO. HTY12-303 (ALI - DO NOT EXTEND), DISCARD									
	HTY12-303	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
57-51-00-120*	NO. 2 FLAP ATTACHMENT BEARING OF THE CENTER FORWARD FITTING RH WS 121.50, PART NO. HTY12-303 (ALI - DO NOT EXTEND) DISCARD									
	HTY12-303	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-121*	NO. 1 FLAP ATTACHMENT BEARING OF THE INBOARD FORWARD FITTING, PART NO. HTY12-303 (ALI - DO NOT EXTEND) DISCARD									
	HTY12-303	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-121*	NO. 2 FLAP ATTACHMENT BEARING OF THE INBOARD FORWARD FITTING, PART NO. HTY12-303 (ALI - DO NOT EXTEND) DISCARD									
	HTY12-303	MOS		N:0			08-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-122*	[RII] LEFT FLAP OUTBOARD AFT LINK UPPER. DISCARD THE LINK ASSEMBLY BOLT NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED.									
	B0201076-5D27	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-122*	[RII] LEFT LOWER FLAP OUTBOARD AFT LINK LOWER. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED.									
	B0201060-5-30	MOS		N:0			28-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-00-122*	[RII] RIGHT FLAP OUTBOARD AFT LINK UPPER. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED.									
	B0201076-5D27	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
57-51-00-122*	[RII] RIGHT LOWER FLAP OUTBOARD AFT LINK LOWER. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED.									
	B0201060-5-30	MOS		N:0			28-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
57-51-03-101*	[RII] DISCARD THE LEFT INBOARD SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751419, SERIALIZED OR PART NO. K1000070195 NON-SERIALIZED									
	1005751419-005	MOS		N:0			04-JAN-2022			
	STR1257	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952
57-51-03-101*	[RII] DISCARD THE RIGHT INBOARD SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751419, SERIALIZED OR PART NO. K1000070195, NON-SERIALIZED									
	1005751419-005	MOS		N:0			04-JAN-2022			
	STR1251	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952
57-51-03-102*	[RII] DISCARD THE LEFT MID SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751429, SERIALIZED OR PART NO. K1000070195, NON-SERIALIZED									
	1005751429-005	MOS		N:0			06-JAN-2022			
	STR1315	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952
57-51-03-102*	[RII] DISCARD THE RIGHT MID SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751429, SERIALIZED OR PART NO. K1000070195, NON-SERIALIZED									
	1005751429-005	MOS		N:0			06-JAN-2022			
	STR1320	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952
57-51-03-103*	[RII] DISCARD THE LEFT OUTBOARD SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751439, SERIALIZED OR PART NO. K1000070195, NON-SERIALIZED									
	1005751439-005	MOS		N:0			04-JAN-2022			
	STR1215	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
57-51-03-103*	[RII] DISCARD THE RIGHT OUTBOARD SUPPORT SPIGOT OF THE FLAP, PART NO. 1005751439, SERIALIZED OR PART NO. K1000070195, NON-SERIALIZED									
	1005751439-005	MOS		N:0			04-JAN-2022			
	STR1283	HRS/MSC		N:0			15519.12			
LIFE LIMIT	REF:	AFL	4832	N:0			9468	14300		2952
575100-0501	[RII] LEFT INBOARD FLAP AFT LINK UPPER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6706DU29	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0502	[RII] RIGHT INBOARD FLAP AFT LINK UPPER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6706DU29	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0503	[RII] LEFT MID FLAP AFT LINK UPPER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6706DU29	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0504	[RII] RIGHT MID FLAP AFT LINK UPPER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6706DU29	MOS		N:0			30-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
575100-0601	[RII] LEFT INBOARD FLAP AFT LINK LOWER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6606D32	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0602	[RII] RIGHT INBOARD FLAP AFT LINK LOWER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6606D32	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0603	[RII] LEFT MID FLAP AFT LINK LOWER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6606D32	MOS		N:0			27-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0604	[RII] RIGHT MID FLAP AFT LINK LOWER BOLT. DISCARD THE LINK ASSEMBLY BOLTS NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6206 NON-SERIALIZED, NAS6706 NON-SERIALIZED, NAS6606 NON-SERIALIZED, 1005751393 SERIALIZED, B0201076-5 NON-SERIALIZED, AND B0201060-5 NON-SERIALIZED. (TLMC TASK 57-51-00-122*)									
	NAS6606D32	MOS		N:0			27-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0701	[RII] LEFT INBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6309C52DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
575100-0702	[RII] RIGHT INBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6309C52DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0703	[RII] LEFT MID FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6309C52DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0704	[RII] RIGHT MID FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6309C52DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0801	[RII] LEFT OUTBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6310C48DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
575100-0802	[RII] RIGHT OUTBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT. DISCARD OF THE ROLLER CARRIAGE BOLT. NOTE: THIS TASK IS APPLICABLE TO PART NUMBERS: NAS6309 NON-SERIALIZED, NAS6310 NON-SERIALIZED, 1005751360 NON-SERIALIZED, AND 1005751361 NON-SERIALIZED. TLMC TASK 27-52-29-105*									
	NAS6310C48DH	MOS		N:0			29-JUN-2017			
	SN-UNKNOWN	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
CHAPTER 71		POWER PLANT								
71-21-00-103*	LEFT NO. 1 [RII] DISCARD THE YOKE BOLT OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E014, SERIALIZED DISCARD									
	WBA7121E014-107	MOS		N:0			01-AUG-2017			
	5468	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
71-21-00-103*	RIGHT NO. 1 [RII] DISCARD THE YOKE BOLT OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E014, SERIALIZED DISCARD									
	WBA7121E014-107	MOS		N:0			22-JUL-2017			
	5467	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-104*	LEFT NO. 2 [RII] DISCARD YOKE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED DISCARD									
	WBA7121E015-111	MOS		N:0			01-AUG-2017			
	10411	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-104*	LEFT NO. 3 [RII] DISCARD YOKE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED DISCARD									
	WBA7121E015-111	MOS		N:0			01-AUG-2017			
	10410	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-104*	RIGHT NO. 2 [RII] DISCARD YOKE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED DISCARD									
	WBA7121E015-111	MOS		N:0			07-AUG-2017			
	10406	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-104*	RIGHT NO. 3 [RII] DISCARD YOKE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED DISCARD									
	WBA7121E015-111	MOS		N:0			07-AUG-2017			
	10407	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-105*	LEFT NO. 4 [RII] DISCARD THE YOKE BOLT OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E016, SERIALIZED DISCARD									
	WBA7121E016-107	MOS		N:0			01-AUG-2017			
	6173	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
71-21-00-105*	RIGHT NO. 4 [RII] DISCARD THE YOKE BOLT OF THE ENGINE MOUNT FITTING, PART NO. WBA7121E016, SERIALIZED DISCARD									
	WBA7121E016-107	MOS		N:0			07-AUG-2017			
	10538	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-106*	LEFT LOWER [RII] AFT DISCARD THE BOLTS OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED BOLT									
	WBA7122E014-103	MOS		N:0			01-AUG-2017			
	10739	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-106*	LEFT UPPER [RII] AFT DISCARD THE BOLTS OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED BOLT									
	WBA7122E014-103	MOS		N:0			01-AUG-2017			
	10734	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-106*	RIGHT LOWER [RII] AFT DISCARD THE BOLTS OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED BOLT									
	WBA7122E014-103	MOS		N:0			22-JUL-2017			
	10733	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-106*	RIGHT UPPER [RII] AFT DISCARD THE BOLTS OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED BOLT									
	WBA7122E014-103	MOS		N:0			22-JUL-2017			
	10736	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-107*	[RII] DISCARD LEFT LOWER FORWARD ENGINE MOUNT FS724L BOLT, PART NO. 1005451660, SERIALIZED									
	1005451660-003	MOS		N:0			26-JUL-2017			
	5261	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-107*	[RII] DISCARD LEFT UPPER FORWARD ENGINE MOUNT FS724L BOLT, PART NO. 1005451660, SERIALIZED									
	1005451660-003	MOS		N:0			25-JUL-2017			
	5256	HRS/MSC		N:0			12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648

Life Limited / Overhauled Parts Status Report

CH 300 S/N 20038 (N517FX): 18585.42 HRS, 11348 AFL as of 03-Mar-2025

Owner: FLEXJET

Report Date: 30-JAN-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE	MAX LIMIT	TIME REMAINING
71-21-00-107*	[RII] DISCARD RIGHT LOWER FORWARD ENGINE MOUNT FS724R BOLT, PART NO. 1005451660, SERIALIZED 1005451660-003	MOS		N:0			21-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-107*	[RII] DISCARD RIGHT UPPER FORWARD ENGINE MOUNT FS724R BOLT, PART NO. 1005451660, SERIALIZED 1005451660-003	MOS		N:0			21-JUN-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500	N:0			7496	14996		3648
71-21-00-108*	DISCARD NO. 1 [RII] ENGINE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. NAS6707HU7, NON-SERIALIZED	MOS					01-AUG-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648
71-21-00-108*	DISCARD NO. 2 [RII] ENGINE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. NAS6707HU7, NON-SERIALIZED	MOS					22-JUL-2017 12256.92			
LIFE LIMIT	REF:	AFL	7500				7496	14996		3648