

RUS SR20, N506SR, SN 1692

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-534F-1RF

PROPELLER S/N FP4830B

LOGBOOK # _____

The subject aircraft was involved in an incident /
accident on 12/30/2025 rendering it a Constructive
Total Loss as not repairable within its insured value. For
further details refer to insurance claim: 0818091678US.

Signed: *Underwriters Salvage Company*

Date: 2/25/2026

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

Date	Prop TSN	Inspection Details	Notes/Actions
		<p>Central Planes Aviation, Inc. Sauk Centre, MN 56378 (320) 352-3013</p> <p>Date: 08/02/2017 Reg. #: N506SR Tach: 2152.1 Total Time: 2152.1 Make: Hartzell Model: PHC-C3YF-1RF S/N: FP4830B TSMOH: 107.1</p> <p>1. Dressed blades and inspected hub for attachment and leaks, check ok. 2. I certify this propeller has been inspected in accordance with an annual inspection and determined airworthy at this time. Thomas J Wenker 3136772IA</p> <p><i>Thomas J Wenker</i></p>	
		<p>Central Planes Aviation Sauk Centre, MN 56378 (320) 352-3013</p> <p>Date: 11/01/2018 Reg. #: N506SR Tach: 2155.9 2740 Hobbs Total Time: 2155.9 Make: Hartzell Model: PHC-C3YK-1RF S/N: FP4830B TSMOH: 110.9</p> <p>1. Dressed blades and inspected hub for leaks and attachment. 2. I certify this propeller has been inspected in accordance with an annual inspection and determined airworthy at this time. Thomas J Wenker 3136772IA</p> <p><i>Thomas J Wenker</i></p>	

Ultimate Aircraft Services LLC

Date: 12/12/2019 Tach: 2251.7 TTP: 2251.7 Hobbs: 857.3 SMOH: 206.7

Annual inspection carried out on propeller. Prop bales dressed. All work carried out IAW FAR 43 Appendix D found safe to return to service

Justin Spence A&P 3798898 IA

Justin Spence



Ultimate Aircraft Services LLC

December 17, 2020 Wingnuts Aviation, LLC.
Tach: 2,312.30 4428 Airport Road
Prop SMOH: 289.7 Springfield, TN 37172

N506SR
PHC-J3YF-1RF/F7392-1
FP4830B

1. Complied with an Annual Inspection in accordance with our Checklist encompassing the scope and detail of 14CFR (FAR) 43 appendix D with reference to Cirrus SR20 Maintenance Manual and all applicable ICA's.
2. Researched AD's through bi-weekly 2020-25 and found to be in compliance.
3. Engine run up completed, all systems satisfactory.

I certify this prop has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Kyle LaMontagne
Kyle LaMontagne AP 3889107 IA

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---

RexAir Service Center - 304 Citation Point -- Naples, FL 34104 -- Ph. 239-649-8822

Date: 09-20-2013 N506SR SR20-GTS S/N: 1692 Tach: 2022.6 Hobbs: 2569.1 AFTT: 2022.6
 Hartzell Propeller: PHC-J3YF-IRF S/N: FP4830B PTSN: 2022.6 PTSOH: 0.0
 Maintenance: Propeller WO # 3057
 Installed overhauled propeller s/n FP4830B and overhauled prop governor s/n 060464.

Ryan Salyer *[Signature]* **A&P 3636791**

			Central Planes Aviation, Inc. Sauk Centre, MN 56378 (320) 352-3013	
		Date: Oct 9, 2014	Reg. #: N506SR Tach: 2082.9 Total Time: 2082.9	
		Make: Hartzell Model: PHC-J3YF-IRF S/N: FP4830B	TSMOH: 60.3	
		1. Greased hub per installing 3 pumps of Aeroshell #6 at ea blade. 2. Dressed blades and inspected hub for leaks and proper installation. 3. I certify this propeller has been inspected in accordance with an annual inspection and determined airworthy at this time. Thomas J Wenker 31367721A <i>Thomas J Wenker</i>		

			Central Planes Aviation, Inc. Sauk Centre, MN 56378 (320) 352-3013	
		Date: 11/17/15	Reg. #: N506SR Tach: 2117.4 Total Time: 2117.4	
		Make: Hartzell Model: PHC-J3YF-IRF S/N: FP4830B	TSMOH: 94.8	
		1. Dressed blades and inspected hub for leaks and attachment. 2. I certify this propeller has been inspected in accordance with an annual inspection and determined airworthy at this time. Thomas J Wenker 31367721A <i>Thomas J Wenker</i>		
		Quality Aviation, Inc. 3401 W. Trunk Hwy 21 Faribault, MN 55021 1-866-865-1777		
		N506SR Prop Log entry. Date: 07/07/16 Aircraft Flight Hobbs: 2139.8 Hobbs: 2716.4 Complied with a Annual inspection in accordance with 14 CFR 43, Appendix D using the Cirrus SR20 service manual as a guide. I certify that this Prop has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.		
		Gerald L. Serres A&P IA 3496061	<i>Gerald L. Serres</i>	

2012 Annual, TNSP

NAPLES AIR CENTER, INC.

CRS X04R655M

230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N506SR DATE: 12/23/11 WO: 11960 HOBBS: 1725.8 TTOH: 540.0

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ADS WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2011-25.

Robert L. House
FOR NAPLES AIR CENTER CRS X04R655M.
ROBERT L. HOUSE

NAPLES AIR CENTER, INC.

CRS X04R655M

230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N506SR DATE: 04/10/12 WO: 12095 HOBBS: 1824.9 TSOH: 639.1

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ADS WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2012-07.

Robert L. House
FOR NAPLES AIR CENTER CRS X04R655M.
ROBERT L. HOUSE

NAPLES AIR CENTER, INC.

CRS X04R655M

230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N506SR DATE: 8/6/12 WO: 12190 HOBBS: 1924.2 TSOH: 1924.2

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ADS WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2012-15.

Robert L. House
FOR NAPLES AIR CENTER CRS X04R655M.
ROBERT L. HOUSE

RexAir Service Center - 304 Citation Point -- Naples, FL 34104 -- Ph. 239-649-8822

Date: 08-08-2013 N506SR SR20-GTS S/N: 1692 Tach: 2022.6 Hobbs: 2569.1 AFTT: 2022.6

Hartzell Propeller: PHC-J3YF-1RF S/N: FP4830B PTSN: 2022.6

Maintenance: Propeller WO # 3057

Removed propeller for overhaul.

Ryan Salyer *Ryan Salyer* A&P 3636791



Aircraft Propeller Works, Inc.



Date: 8/21/2013
Model No: PHC-J3YF-1RF / F7392-1
Serial No: FP4830B
APW#: APW5468

This Hartzell Propeller overhauled in accordance with Hartzell manuals 202A, 113B and 133C. Blade serial numbers (1) K40454 (2) K40453 (3) K40451. Complied with SB-61-118F Rev.1, SB-61-136 Rev.1 and SL-61-217. No AD's apply to this propeller at this time. Approved for return to service. TTSN: 2022.6 TSO:00.0

Arthur J Michaud

Arthur J Michaud
Authorized Signature

FAA Repair Station # T4ZR741Y

Date	
	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 10/01/09 WO: 11421 HOBBS: 1185.8 TSOH: 0.0</p> <p>PROPELLER LOG REINSTALLED THIS PROPELLER AFTER OVERHAUL BY PROP WORKS, INC. TORQUED PROP BOLTS TO 65 FT LBS. INSTALLED SPINNER AND COWLING. RUN UP AND LEAK CHECKED GOOD. <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>
	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 10/26/09 WO: 11421 HOBBS: 1230.9 TSOH: 45.1</p> <p>PROPELLER LOG THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2009-21. <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>
	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 02/05/10 WO: 11477 HOBBS: 1329.2 TSOH: 143.4</p> <p>PROPELLER LOG THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2010-03 <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>


<i>2010 Annual Inspection</i>	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 06/09/10 WO: 11566 HOBBS: 1427.8 TSOH: 242.0</p> <p>PROPELLER LOG THIS PROPELLER HAS BEE INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITON. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2010-11. <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>
	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 02/16/11 WO: 11698 HOBBS: 1526.6 TSOH: 340.8</p> <p>PROPELLER LOG THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2011-03. <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>
<i>2011 Annual Ins</i>	<p>NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 06/29/11 WO: 11862 HOBBS: 1627.5 TSOH: 441.7</p> <p>PROPELLER LOG THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2011-12. <i>Robert L. House</i> ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.</p>

2000 Annual Report

NOTES: FLIGHT HOURS USED

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p align="center">NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 05/02/08 WO: 10854 HOBBS: 583.6 TTSN: 583.6</p> <p align="center">PROPELLER LOG</p> <p>I CERTIFY THAT THIS PROPELLER HAS BEEN SERVICED AND INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2008-08. PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER 10854.</p> <p align="center"><i>Robert L. House</i> FOR NAPLES AIR CENTER CRS X04R655M. ROBERT L. HOUSE</p>
			<p align="center">NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 09/26/08 WO: 110957 FLT HOBBS: 538.7 TTSN: 538.7</p> <p align="center">PROPELLER LOG</p> <p>THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2008-19.</p> <p align="center"><i>Robert L. House</i> FOR NAPLES AIR CENTER CRS X04R655M. ROBERT L. HOUSE</p>


			<p align="center">NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 12/09/08 WO: 11085 HOBBS: 636.2 TTSN: 636.2</p> <p align="center">PROPELLER LOG</p> <p>THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2008-24.</p> <p align="center"><i>Robert L. House</i> FOR NAPLES AIR CENTER CRS X04R655M. ROBERT L. HOUSE</p>
			<p align="center">NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 02/11/09 WO: 11177 737.9 HOBBS: 737.9 TTSN: 737.9</p> <p align="center">PROPELLER LOG</p> <p>THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2009-03. REMOVED PROPELLER AND REPLACED FWD CRANKSHAFT SEAL REINSTALLED PROPELLER.</p> <p align="center"><i>Robert L. House</i> FOR NAPLES AIR CENTER CRS X04R655M. ROBERT L. HOUSE</p>
			<p align="center">NAPLES AIR CENTER, INC. CRS X04R655M 230 AVIATION DRIVE SOUTH NAPLES, FLORIDA 34104 AIRCRAFT: N506SR DATE: 04/02/09 WO: 11231 HOBBS: 834.2 TTSN: 834.2</p> <p align="center">PROPELLER LOG</p> <p>THIS PROPELLER HAS BEEN INSPECTED IAW A 100 HR. INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2009-06.</p> <p align="center"><i>Robert L. House</i> FOR NAPLES AIR CENTER CRS X04R655M. ROBERT L. HOUSE</p>

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
RexAir Service Center – 304 Citation Point – Naples, FL 34104 -- Ph. 239-649-8822				
Date: 06/12/2007 N506SR SR20-GTS S/N: 1692 Tach: 291.2 Hobbs: 387 AFTT: 291.2 Hartzell Propeller: PHC-J3YF-IRF S/N: FP4830B TSN: 291.2				
Maintenance Performed: 100 HOUR INSPECTION- PROPELLER WO# 52 1327				
<ul style="list-style-type: none"> - 100 Hour Inspection completed this date in accordance with the manufactures recommended inspection check list. - Checked Ads though issue 2007-06 - Performed engine operational checks; prop satisfactory. 				
I certify that this propeller has been inspected IAW a 100 Hour Inspection as per Hartzell inspection checklist, and was determined to be in airworthy condition, and is approved for return to service.				
Howard Axtell  AP574242696IA				

NAPLES AIR CENTER, INC.
CRS X04R655M
230 AVIATION DRIVE SOUTH
NAPLES, FLORIDA 34104
AIRCRAFT: N506SR DATE: 10/01/07 WO: 10738 HOBBS: 464.3 TTSN: 464.3

PROPELLER LOG

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2007-19. PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER 10738.


FOR NAPLES AIR CENTER CRS X04R655M.
ROBERT L. HOUSE

Prop Works, Inc.

Aircraft Propeller Specialists

Date: 01/07/08
Model No: PHC-J3YF-1RF/F7392-1
Serial No: FP4830B

This Hartzell Propeller has been inspected and Flushed no metal found. Installed New seal kit, Angles checked. Propeller approved for return to service. Continue Time.


Peng Yann
Authorized Signature

FAA Repair Station # T4ZR741Y

Date	Propeller		A/C
	TSN	TSO	Hrs

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

RexAir Sales & Leasing, LLC – 200 Aviation Dr. N., Ste 1 – Naples, FL 34104 – Ph. 239-649-8822

Date: 11/29/2006 N506SR SR20-GTS S/N: 1692 Tach: 99.8 Hobbs: 131.2 AFTT: 99.8
 Hartzell Propeller: PHC-J3YF-IRF S/N: FP4830B TSN: 99.8

Maintenance Performed: **100 HOUR INSPECTION- PROPELLER WO#1239**

100 Hour Inspection completed this date in accordance with the manufactures recommended inspection check list.
 Checked Ads though issue 2006-24
 Performed engine operational run-up checks, prop satisfactory.

I certify that this propeller has been inspected IAW a 100 Hour Inspection as per Hartzell inspection checklist, and was determined to be in airworthy condition at this time, and is approved for return to service this date.

Daniel Spurr *Daniel Spurr* AP554250815IA



RexAir Service Center – 304 Citation Point – Naples, FL 34104 – Ph. 239-649-8822

Date: 02/13/2007 N506SR SR20-GTS S/N: 1692 Tach: 192.9 Hobbs: 259.4 AFTT: 192.9
 Hartzell Propeller: PHC-J3YF-IRF S/N: FP4830B TSN: 192.9

Maintenance Performed: **100 HOUR INSPECTION- PROPELLER WO#52**

- 100 Hour Inspection completed this date in accordance with the manufactures recommended inspection check list.
 - Checked Ads though issue 2007-04
 - Performed engine operational checks; prop satisfactory.

I certify that this propeller has been inspected IAW a 100 Hour Inspection as per Hartzell inspection checklist, and was determined to be in airworthy condition, and is approved for return to service.

Daniel Spurr *Daniel Spurr* AP554250815IA

PROPELLER MAINTENANCE RECORD

Position one

Propeller Model PHC-534E-1RF

Propeller S/N FP4830B

Blade Design F7392-1

Blade S/N's

No. 1 K40454

No. 2 K40453

No. 3 K40451

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cessna

Aircraft Model SR20

S/N 1692

Registration N506SR