ERICKSON AIR-CRANE

COMPONENT LOG CARD


NOMENCLATURE: Support Truss Assy- Aft Stabilizer	PART NO:	6420-66250-041	SERIAL NO:	EAC26093
NOME TO TOTAL	5.51000000000			

AIRCRAFT MODEL S- 64E/F	INSTALLED ON	INSTALL DATE	REMOVAL DATE	AIRCRAFT TOTAL TIME	COMPONENT TOTAL TIME	REASON FOR REMOVAL/COMMENTS
S64E	N243AC	9/10/2010		4271.2	NEW	
S64E	N243AC		3/29/2017	6303.5	2032.3	Transferred to N171AC
SHIF	NITIAL	OZApril 17	•	4019.7	2032.3	Remove @ ACTT 6707.4
S-64E	NITIAL	- L	09/29/20	5017.2	3059.8	REMAISO PER EAL REGUES
S64E	NIGHA	I AARIL 2022		19797.7	3059.8	REMOVE CACTT 21452.9
564E	NIGHAL		1 AUG 2025	20321.6	3588.7	DEPARTED AIRCRAFT
					1	
				_		
					1	
	_					
		1			•	

S-64E RETIREMENT TIME : 4720.0 hrs

S-84F RETIREMENT TIME : 4720.0 hrs.

PG 1 OF 2



COMPONENT MAINTENANCE RECORD

Oate	Work Order	T.T.	T.S.O	Description of Work Performed
04/07/09	N/A	NEW	N/A	Assy manufactured REF: Dwg 6420-66250, Rev. D under MO 81973.
				Remove assy from service at 4720.0 hrs TT for retirement.
Aug 2025	Na	3588.7	NA	TRUS DEPARTED AMPLIANT DIRING INCIDENT ON 22 July 2015 WAS UNABLE TO BE EXCOVERED. ATP 3550755
		_		WAS UNABLE TO BE EXCOVERED, A+P 3550755
	_			

PROPRIETARY INFORMATION

THIS DOCUMENT IS THE PROPERTY OF ERICKSON AIR CRANE AND MAY NOT BE USED BY ANYONE OTHER THAN ERICKSON AIR CRANE EMPLOYEES. THIS DOCUMENT MAY NOT BE COPIED, PRINTED OR REPRODUCED BY ANY MEANS, INCLUDING ELECTRONIC OR PHYSICAL METHODS WITHOUT EXPRESS WAITTEN PERMISSION FROM ERICKSON AIR CRANE.

ERICKSON AIR CRANE 1-800-866-6131

PG 2 OF 2



1. Approving Civil Aviation Authority/Country:	AUTHORIZED I	RELEASE	CERTIFICATE	3. Form Tra	acking Number:	
FAA/UNITED STATES		AIRWORTHINESS A		[
4. Organization Name and Address Erickson Incorporated d 3100 Willow Springs Roa	: ba Erickson Air-Crane Repair	r Station JYDR439F		5. Work Or Number:	der/Contract/Invoice	
6. Item: 7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11		
	TRUSS ASSY 8420-86250-041		1 EAC26093		REPAIRED	
A complete description of work perfor	Rev D. Total Time 3059.8 hrs. Remove at Total Timed is on file at the above referenced organization may apply to the article(s) described hereon. The ocks 11/12 was carried out in accordance with EAS 8.	under the work order and installer is responsible for	system tracking reference number indicated in ensuring complete compliance with any applica to that work, the component is considered read	able Airworthing	ess Directives. o service under EASA Part-	
	above were manufactured in conformity to: are in condition for safe operation. specified in Block 12.	Certifies the	at unless otherwise specified in block 12, the bed in Block 12 was accomplished in accord gulations, part 43 and in respect to that we	he work identi dance with Ti	tle 14, Code of	
13b. Authorized Signature:	13c. Approval/Authorization	No.: 14b. Authorized	14b. Authorized Signature:		14c. Approval/Certificate No.: JYDR439F	
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Kyp Virginia Lycett	ed or Printed):	14e. Da	28/Aug/2021	
	User	/Installer Respons	ibilities			
V .		utomatically constitute	nuthority to install the aircraft engine/prop	eller/article.		

FAA Form 8130-3 (02-14)

*Installer must cross-check eligibility with applicable technical data.

Scanned with

NSN: 0052-00-012-9005

CS CamScanner