Aircraft Model		Serial Nur	nber		
Reg #		Owner's	Name		
DATE TIN		IES MAY BE ON LINES IF REQUI		INSPECTOR'S SIGNATURE	LICENSE NUMBER
Replaced fuel car	Baker A  333 South Street, 386-83  Date: Registration: Make/ Model: Serial Number: Tach / Hobbs:  We transducer, p/n 102 O o-rings with new. With reference to the rek for return to service.  3232817IA	New Smyrna, FL 7-4073 03/07/24 N934PC A36 E-3448 2640.6 2-389012-11 with ser	viceable unit. Model 36 Maintenan	ce manual.	
JACK AIRCRAI ALL FLIGHT C O-RINGS -DC LIMITS, CHEC L/H STROBE A TEST ELT NEW I CERTIFY THA	4, LUBE EMERGE CK STALL AND PITO AND MOLEX CONI BATTERY DATE	I ELECTRIC AND I SE ALL WHEEL B NCY WINDOW EX OT HEAT , SERVIC NECTOR , INSPEC 1~2026 HAS BEEN INSP E IN AIRWORTHY	EMERGENCY LAI EARINGS , CHEC KIT GASKETS DC- CE TIRES WITH AI CT BATTERY BOX PECTED IN ACCO CONDITION ON	NDING GEAR ACTUA K ALL LIGHTING , LI 4 , ALL CABLE TENS R , INSPECT BRAKE AND TERMINALS. IN RDANCE WITH AN A I THIS DATE 7-1-202	SIONS IN PADS , RE-PIN ISTALL AND
					53

Aircraft Model	Serial Number
Reg #	Owner's Name

DATE TIME	ENTRIES MAY BE ON MULTIPLE	INSPECTOR'S	LICENSE
Y M D HOURS	LINES IF REQUIRED	SIGNATURE	NUMBER

N934PC

**RAYTHEON AIRCRAFT COMPANY A36** 

s/n E-3448

Hobbs: 2624.4

WO# 52282

01/15/2024

Performed Garmin SB 23086 Rev A to update Garmin GI275 ADAHRS Indicator S/N: 5mz105062 and Garmin GI275 ADAHRS Indicator S/N: 5MZ202062 to SW version 3.01. Ops check OK.

John Galbreath

FAACRS# G43R643N

Avionics Installations, Inc

333 South Street, New Smyrna Beach, FL 32168

Tel: 386-492-7760

D	<b>Baker A</b> 333 South Street, 386-837	New Smyrna, FL
	Date:	01/22/24
ARC	Registration:	N934PC
ADS_	Make/ Model:	A36
CENTER	Serial Number:	E-3448
OF CELLENCE	Tach / Hobbs:	2624.6

- Removed all 6 cylinders and replaced with new Superior Millennium cylinders, p/n 6A52006-A1 with s/n's as follows:
  - 1.526000022799
  - 2. 526000022793
  - 3. 526000022798
  - 4. 526000022803
  - 5. 526000022802
  - 6. 526000022800
- Installed cylinders using all new gaskets.
- Replaced all piston pins with new, p/n 630046
- Replaced all spark plugs with new, p/n URHB32E
- Replaced crankshaft seal with new, p/n 641250
- Replaced all intake lifter with new, p/n 658088.
- Replaced all exhaust lifters with new, p/n 658077
- Replaced 1 CHT probe with new.
- Serviced engine with 10 quarts Aeroshell 100M and new Tempest AA48109-1 filter.
- Serviced engine with 16 data to the Textron Beechcraft Model 36 Maintenance manual and the Continental Aerospace Work performed with reference to the Textron Beechcraft Model 36 Maintenance manual and the Continental Aerospace M-0 Maintenance and Overhaul manual.
  - I approve this work for return to service.

Curtis Boulware A&P 3232817IA

Air	craf	t Mc	del _		Serial Number	
Re	g #_				Owner's Name	
Y	ATE M			IME DURS	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LINES IF REQUIRED SIGNATURE	LICENSE NUMBER
	JAC O/H CAI REF LIG	K AI H RT P O- PAIR HTII	RCR/ BRA RING R/H	AFT AND AKE CAL ASS AND I TIP TAN AND E	FT S/N E3448 ACTT 2590.6  REMOVE MAIN TIRES AND REPLACE 700X6 FLT CUSTOM II, LUBE GIVER AND INSTALL NEW BRAKE PADS #66-10500 AND TUBES #TR20, I LUBE DC4, CHECK BATTERY CONNECTIONS, TEST ELT NEXT BATTERY K LEAK, LUBE ALL FLIGHT CONTROLS, ALL CABLE TENSIONS IN LIMITS, STALL WARNING, CLEAN AND GREASE ALL WHEEL BEARINGS, PERMERGENCY EXTENSION, INSTALL NEW NUT PLATE FOR RT TIP TANK I AIR, CHECK EMERGENCY WINDOW EXIT.	NSTALL NEW GAS DUE 3/2024 , TS , CHECK ALL REORM GEAR
	I CE	ERTI	· FY TH DUNE	HAT THIS	S AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUIN AIRWORTHY CONDITION: ALL AD'S CHECKED THRU THIS DATE 6-1 T.# 31226781/A	AL INSPECTION -2023.
					Beneves No Repeaces TKS System Pinter u	3,54
	14				16 > Pln 908-01.	
	61		<del></del>		Chouses - Lear and Spection Pentanas	SATIST ACTIVE!
					Janes C. D. 100 4:1 356640121	
_						
		_				
	-					
-	-					51

Reg#			Owner's N	Name			
DATE Y M D	TIME HOURS		MAY BE ON I			CTOR'S	LICENS NUMBE
		PUNTA GORDA (PG Charlotte County Airp 17220 Airport Rd, Bldg Punta Gorda, Fl 339	ort .211	SARAS AVION & MAINTEN	OTA ICS ANCE	_	
	Remo	05/02/2022 N934PC 5 oved and replaced primar oved and replace nose gea	y EGT probe P/N 86	240 with new per Bee	ech MM. per Beech MM.		
	Aron	Gober AP3349462 —					
					1		1
BE ALL FL TENSION OT ELT AN PECT BA IGS , SER CABLE 1	LIGHT CONT , LUBE ALL I ND BATTERY TTERY BOX VICE TIRES A		N AND GREASE I , REPLACE 2 M IS , REPLACE HI GHTING,STROB	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT	ARINGS , O, K GENERATO AT TUBE , E , EMERGEN	/H RT BRA ORS RT W OC4 FUEL ( ICY WIND	KE CALIPER ING , CAP O- OW OPS.
BE ALL FL TENSION OT ELT AN SPECT BA IGS , SER L CABLE T ERTIFY TH D FOUNI	LIGHT CONT , LUBE ALL I ND BATTERY TTERY BOX VICE TIRES TENSIONS IN HAT THIS ALL D TO BE IN A	ROLS, JACK AIRCR L/G PIVOTS, CLEA EXP. DATE 3-2024 AND CONNECTION AIR, CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE  I , REPLACE 2 N  IS , REPLACE HI  GHTING,STROB  I INSPECTED IN	ALL WHEEL BE MISSING VORTED EATER INLET SO SES, PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO AT TUBE , E , EMERGEN WITH AN A	/H RT BRA ORS RT W OC4 FUEL ( ICY WIND(	KE CALIPER ING , CAP O- OW OPS. ISPECTION
BE ALL FL TENSION ST ELT AN SPECT BA NGS , SER L CABLE T ERTIFY TH D FOUNI	LIGHT CONT , LUBE ALL I ND BATTERY TTERY BOX VICE TIRES TENSIONS IN HAT THIS ALL D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA' NGS , SER L CABLE T ERTIFY TH D FOUNI	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA NGS , SER L CABLE T ERTIFY TH ID FOUND	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA' NGS , SER L CABLE T ERTIFY TH D FOUNI	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA NGS , SER L CABLE T ERTIFY TH ID FOUND	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS, JACK AIRCR L/G PIVOTS, CLEA EXP. DATE 3-2024 AND CONNECTION AIR, CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA NGS , SER L CABLE T ERTIFY TH	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA' NGS , SER L CABLE T ERTIFY TH D FOUNI	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022
BE ALL FL TENSION ST ELT AN SPECT BA' NGS , SER L CABLE T ERTIFY TH ID FOUND	LIGHT CONT  , LUBE ALL  ID BATTERY  TTERY BOX  VICE TIRES  TENSIONS IN  HAT THIS ALL  D TO BE IN A	ROLS , JACK AIRCR L/G PIVOTS , CLEA EXP. DATE 3-2024 AND CONNECTION AIR , CHECK ALL LIG I LIMITS. RFRAME HAS BEEN AIRWORTHY COND	N AND GREASE I, REPLACE 2 M IS, REPLACE HI GHTING,STROB I INSPECTED IN OITION . AD'S CI	ALL WHEEL BE MISSING VORTED EATER INLET SO ES,PITOT HEAT ACCORDANCE HECKED THROU	ARINGS , O, K GENERATO CAT TUBE , E C , EMERGEN WITH AN A IGH THIS DA	TH RT BRA ORS RT W OC4 FUEL ( ICY WIND NNUAL IN ATE 6-6-20	IKE CALIPER ING , CAP O- OW OPS. ISPECTION 022

Aircraft Model	Serial Numb	er	
Reg #	Owner's Na	ame	
DATE TIME Y M D HOURS	ENTRIES MAY BE ON MI LINES IF REQUIRE		
Sarasota Avionics P 27220 Airport Rd, E Punta Gorda, FL 33 Date: 03/3/2022 W Tail #: N934PC Bee	Bldg #211		ASOTA ————————————————————————————————————
King KEA 130A(PN: 04489-10 SN:5MZ1 comply with App E King KEA 130A(PN: 14 CFR 43, and calil (PN: 011-00455-60 CFR 43 and 14 CFR	GI 275 AI (PN:011-04489-20 S): 066-03064-005 SN:32357), and the loss of 14 CFR 43. The Automatic point is in compliance with 10 SN:84115299) was tested, instantic Pressure sy	altitude of 20,000 feet and woressure altitude reporting eq was tested and found to com 4 CFR 91.217. The transpond pected and found to comply was tested and found to comply was tested and inspected	ere found to uipment Bendix ply with App E of ler GTX 330ES vith App F of 14 d in accordance
I certify all work do with current regula	one to the aircraft and/or comp ations of the Federal Aviation A ith respect to the work perforn	aministration and was round	
Sarasota Avionics PGD 27220 Airport Rd, Bld Punta Gorda, FL 33982 Date: 03/22/2022 Wo Tail #: N934PC BEECH	g #211 2	SAR AVII 513.3	ASOTA ONICS ERNATIONAL
	ng for new installations; KI525. /060-0015-00/47955, KA51B/ SSURE INDICATOR/09007-014		
012/5/011-04489-2	g; GMU11/011-04349-01/56J03 20/5MZ202062, GTP59/011-00 330 and GI275 BATTERY/011- stallation Manual #190-02246-	04520 00/5147607383 in acc	ordance with
GSB15/011-04937-i accordance with ma 97108794, for repai PN: 8130 S/N 18068	00/63M063273 and DC-AC INVanufacturer's instructions as a rir. Unit repaired and reinstalled 84, for overhaul. Reinstalled satt and Balance updated to reflec	/ERTER (TI10)/MD26-28/A2 ninor installation. Removed C I into aircraft. Removed air sp ume unit into aircraft. Installe	2-11060 in INS 430W, S/N
l certify all work do	rent regulations of the Federal n to service with respect to the	onent identified above was do	one in was found 49
The state of the s	for Sarasota Avi	onics Inc. CRS SOQD632X	

Aircraft Model \_\_\_\_\_ Serial Number \_\_\_\_

	R	eg i	#					Owner's	Name				
	Y	DAT	ΙΕ Ι D		TIME OURS	ENT		Y BE ON IF REQU	MULTIPLI IRED	E ·	INSPECTO SIGNATU		LICENSE NUMBER
	0	6-2	1-20	21	N934PC	Tach 2490	.7 annual	inspection	on				
	b re ei	onti eari emo mer CER	rols, ings, ite b gene TIFY	Repi Insp atter cy ex	ace ANS ect brak y next D tension, AIRFRAI	e pads, All c ue 03-2024, Remove jac ME HAS BEE ORTHY CON	able tensi Grease a ks, Lube fi N INSPEC	ions withi Il landing uel cap o- TED IN AG VD NOTE	in limits, Re gear comp rings DC4, CCORDANC	and cotte move and onents , Visual ins E WITH A	er pin, Clean d replace EL swing gear spection of f NNNUAL INS	and grand grand perference of the contraction of th	form nguisher
	и	IEEK	(LY I	NUM	BER 202.	1-12 USING 122678 I/A	DEECHUM	MFT INSPI	ladas	IIDE	,		
	Ro	oy 5.	. Pla								BATTE PART N	ARTEX PRO RY PACK 0: 452-0 5.N.:3907	2 CAGE Code: 18560 DDUCTS C: ELT 110-4 130 REV. R 54-016
AFÉ	7	27	209	,	1934PC		3490 BATE		ادر (3)42				
), I C						REMOVED		-14 (se	\	Deston	1NSTALL		
					GILL Char		0	zo weh	<del></del>				
					ONAR	Sound	4,3	Ste	A'A D		Meek -	400	200
												_	
	_												
		_											
			_					<del></del>					
	_	_	-					······································					
			_							-			
	-												

Aircraft M	lodel			Serial Nu	ımber		
					Namo		
Reg #				Owners	Name		
							LICENSE
DATE	1	ME	ENT	RIES MAY BE ON	MULTIPLE	INSPECTOR'S	NUMBER
YMD		URS		LINES IF REQU	IRED	SIGNATURE	NOMBLIX
		Ì					
						NOT UPO	
	D	ATE 5-28-1	19	HOBBS 2264.0	TT 2264.0	N934PC	
<del>                                     </del>	- 1,	CEDTIEV 1	гиат тир /	AIRFRAME HAS BEEN	INSPECTED IN ACCO	RDANCE WITH AN	
	A	NNUAL IN	ISPECTION A	AND WAS DETERMIED	TO BE IN AN AIRWO	RTHY CONDITION.	
	_ []\	ISPECTED	IAW FAR 43	AND WAS DETERMIED  APPENDIX D. MAINT UEL CAP O-RINGS 2 EA	A P/N MS29513-338. R/	R INSTRUMENT AIR	
	– FI	LTERS 1 E	EA P/N D9-14	UEL CAP O-RINGS 2 EA 1-5, P/N 2J4-7. C/W FAR	91.207d, ELT INSP. BY	Y INSP. NEXT DUE 3-	
	20	)20. LAND	ING GEAR R	ETRACTION, EXTENS	FNT SEE AD COMPL	LIANCE RECORDS	
	- 0	PERATION	VAL AND LE	AK CHECK PERFORM	ED SA I PI ACTORII		
	_			165	MP366	154018	
	<del></del>			KURT <b>SCHI</b> MPF	AP 3661540 IA	-	
	_			SELECT AIRCR	AFT SERVICE	1	
	1		1				
	-	- 1	laa	11 -20 200	41 TT 2	367.6 N 934PC	
<u> </u>	DA	E 31	2120	Hobbs ask	1.6 1 1 4	301,4	
		1270	ا د م	- Anti Lallen	-6.04	JI AND MARKET	
<del></del>		712	- (	7	<u> </u>	308648164	
		WEW	له بدر له	pathod 646 a	. DOBOTIO	MIC CHECK G	
			H.	$\alpha \geqslant \alpha$	$\langle \sigma \rangle = A \langle a \rangle$	308648164	
		<u> </u>	Jame	m u, 15 D			
1   1						l	
	٦.	I Date (	20.20	HOBBS 2393	o TT 2393.9	N934PC	
	_						
		I CERTII	FY THAT	THIS AIRFRAME H	IAS BEEN INSPEC	CTED IN	
<del>                                      </del>		ACCORI	DANCE W	ITH AN ANNUAL	INSPECTION AND	AWEAR 43	
	1	IO DE II	N AN AIK	WOKIHI CONDII	THE AREASE	EOLLOWS: K/K	
1 1 1		FLIFT C	ADO DING	INTENANCE AND GS P/N MS29513-33	8 M83248/1-110,-	007. SERVICE	
<del>                                      </del>		SHIMM	Y DAMPE	GS P/N MS29513-33 NER. R/R PROP GC	V. ROD END P/N	S1106-3. INSTALL	
		TIZOLE	ACARD OF	N KI WING AND N	OSESTRO	- NOCE GEAN	
		03. IVI	MAIN GEA	AK BKANE LIMINO	2 LVIA 000 1000	CENIERATORS	
1		**** I I/V/		P/N 1137   K.C.=11833   A.		CANINU	
		PLUG. R	RETOROU	F NOSE GEAR LIF	T LEG PIVOT BOI	T. C/W FAR 91.200	
		ELT INS	SP. BY INS	P. NEXT DUE 5-20	21. C/W CAV AER	COSPACE ICW AND BERYL D SHANNON	
-  -			LEGI IV AA	30-09-40, AND 3D	+300-30-001.	AD CEALS, AND	
				CH DI KELLACIII	O I ODD Diring	240/1-11000/	
		ADILIO	SUALS F/I	N S (2) 330-4-0140,	M229313-130, 1110	DETRACTION,	
		EXTEN	SION AND	EAR DOOK KODS. FMFRGENCV EY	TENSION TEST P	ERFORMED ORDS.	47
		SATISF	ACTORY.	ALL ADS CURREN	NT, SEE AD COMI	ERFORMED PLIANCE RECORDS. TISFACTORY. END.	
		OPERA'	TIONAL A	ND LEAK CHECK	PERFORMED SA	TISFACTORY, END.	

SELECT AIRCRAFT SERVICE

ircraft Model	Serial Number	Serial Number					
eg #	Owner's Name	Owner's Name					
DATE TIME M D HOURS	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER				
wo: WO_125	FilightLogix · 4510 Airport Road · Cincinnati, OH 45226 · 513-321-12	Airframe ⋅ page 1 of	1				
and With respect to the wor	H and RH main landing gear tires. Lubricated by performed, this airframe is approved for retrottlogix under work order: WO 125.	d wheel bearings. Spin checks urn to service. Details of work	s k				
Greg Herrinanii Adi IA 40000	71000						
1 OG ID# 3393 31-Way-20	Sportys Drive Clermont County Airport Bai 19 WO# 10123 BEECH A36	tavia, OH 45103 VYTR380B	Pg 1 / 1				
Performed inspections requestions requestions requestions requestions. Altimeter Make: BK Encoder Make: BK Transponder Make: Garmin	Model: KEA 130A 5/N: 32357 to 35 Model: KEA 130A 5/N: 32357 to 35 Model: GTX 330ES S/N: 84115299.  For Cincinnati Avionics  For Cincinnati Avionics  Altitude Prim Reading En -1000 -1 0 1 500 1 1000 2 1500 2 2000 2 3000 2 4000 2 6000 3	Aviantes Altimeter Scale Correct N934PC 31- nary Standby Altitude Prima Fror Reading Error 0 X 10000 30 0 X 12000 20 0 X 14000 30 0 X 16000 20 0 X 18000 60 0 X 20000 60 0 X 22000 70	etion Card May-2019 TY Standby TE Fror X X X X X X X X				

Aircraft Model			Serial Numb	er		
Reg #			Owner's Na	ame		
	TIME OURS DATE 5		AY BE ON MI S IF REQUIRE OBBS 2069.0	D	INSPECTOR'S SIGNATURE N934PC	LICENSE NUMBER
	I CERTI WITH A AIRWO MAINTI CUSTOI AA2J4-7 BRAKE KNOB F LANDIN	FY THAT THIS AIRFE, ANNUAL INSPECTION INSPECTION INSPECTION INSPECTION IN ENANCE AND REPAIRMER SUPPLIED P/N 50, AAD9-14-5. SERVIOUS CALIPER O-RINGS 30/N 50-524513-5. C/W FOR GEAR RETRACTION ERFORMED SATISFANDS. OPERATIONAL A	ON AND WAS I ISPECTED IAW RS ARE AS FOI 05C66-5. R/R IN E SHIMMY DA EA P/N MS287 FAR 91.207d, EL DN, EXTENSIO	DETERMIED TO FOUR FAR 43 APPEND LLOWS: R/R NOS ISTURMENT AIR IMPER WITH MIL 175-222. R/R THRO IT INSP. BY INSP IN AND EMERGEN IN CK PERFORMED AP 3661540 IA	BE IN AN  BIX D.  E TIRE WITH  FILTERS 1 EA P/N  -5606. R/R LEFT  OTTLE CONTROL  NEXT DUE 5-2018.  NCY EXTENSION  EEE AD COMPLIANCE  SATISFACTORY.	
	WITH A AIRWO MAINT SEALS 77E, P/I 066-105 ELT IN EXTEN	IFY THAT THIS AIRF A ANNUAL INSPECTI ORTHY CONDITON. II ENANCE AND REPA 2 EA P/N MS28775-22 N 092-308-0. R/R LEFT 000. R/R ELT BATTER SP. BY INSP. NEXT D SION AND EMERGEN ACTORY. ALL ADS C TIONAL AND LEAK	NSPECTED IAVIRS ARE AS FO 2. R/R NOSE WE AND RIGHT NOSE WE Y P/N 452-0130 UE 5-2019. LAN NCY EXTENSION	V FAR 43 APPENIDLOWS: R/R RIG PHEEL ASSY. ANI MAIN GEAR BRAI . NEXT DUE 9-20 NDING GEAR RET ON TEST PERFOR AD COMPLIANC RMFD SATISFAC AP 3661540 IA	DIX D.  HT BRAKE CALIPER  D TUBE 1 EA P/N 40-  KE LININGS 8 EA P/N  20. C/W FAR 91.207d,  FRACTION,  MED	
						45
	1					1

Aircraft Model	Serial Number	
Reg #	Owner's Name	
DATE TIME M D HOURS		LICENSE NUMBER
Date: June 18, 2015  Completed inspectio with Beech Service I fuel vent tube gromn FAR91.207(d). AD20	y to	
Date: April 21,  Completed insy with Beech Ser drain valve, CC primary and statchecked IAW F dampener w/M SCAT tubing or	Certified Repair Station E5ZR316Y oad, Hangar 6 Cincinnati, Ohio 45226 513-871-9966 N934PC Beech A-36 S/N E-3448 2016 Hobbs:1992.8 AFTT:1992.8 Eng. TT:1992.8 Eng. TSO:214.7 Prop TT:1992.8  pection this date in accordance with FAR 43 Appendix D. Serviced and lubricated aircraft in accordance rivice Manual. Installed missing VG on right wing. Reinstalled overhead vent knob. Replaced right fuel 2A-3400. Replaced co-pilot yoke map light bulb, 1495. Induction air filter due 2275.6 AFTT. Replaced and by instrument air filters, AAD9-14-5 and AA2J4-7. Replaced ELT battery, due 9-2018. ELT ops FAR91.207(d). Serviced landing gear actuator. Serviced and charged battery. Serviced shimmy lil-5606. Replaced outer fuel cap o-rings, MS29513-338. Cleaned and painted battery box. Replaced in heater duct to rear spar. All ground checks performed satisfactory. I certify that this aircraft has been excordance with an annual inspection and has been determined to be in an airworthy condition.————————————————————————————————————	
CUSTOME	AND REPLACE TKS SYSTEM FILTER WITH NEW P/N 908-01 ER SUPPLIED FILTER. INSTALLED WITH NEW SEALS 2 EA P/N	
S1207-20. I END.	LEAK AND OPERATIONAL CHECK PERFORMED SATISFACTORY.  KURT SCHIMPF AP 3661540 IA  SELECT AIRCRAFT SERVICE	

eg #	OWI	ner's Name		
	DURS ENTRIES MAY BE		INSPECTOR'S SIGNATURE	LICENSE NUMBER
	Certified Repair Station E5ZR316Y irport Road, Hangar 6 Cincinnati, Ohio 45226 5:3-01-2013 Hobbs:1778.1 AFTT:1778.1 Eng. TS	13-871-9966 N934PC Bee		
gear ch genera Installe left and MS295 MS287	eted inspection this date in accordance with Beech A lecks. Tested ELT in accordance with FAR91.207(d) tors on right wing. Replaced landing light bulb, GE45 d new battery cooling duct, BE709-4-23-6. Installed right wheel brake cylinders, MS28775-222. Adjuste 13-010 & MS29513-338. Installed missing snaps in 975-223 & 224, serviced with MIL5606 and nitrogen. Induction filter, next due @ 2275.6 AFTT. All ground spected in accordance with an annual inspection an end-	. ELT battery due 10-2013. Instal 196. Serviced main struts with MI new heat muff inlet duct, 115167 d right inboard gear door travel. F gear wells for flap actuator covers Replaced induction air filter, P13; checks performed satisfactory. In d has been found to be in an airy	lled 2 missing vortex L5606 and nitrogen.  DXX121323. Resealed Replaced fuel cap o-rings, s. Resealed nose strut, 7627, per AD84-26-02 certify that this aircraft has	
Joseph	K. Schott Inspector			
	gnature		L .	
Date:	Certified Repair Station E5ZR316Y Airport Road, Hangar 6 Cincinnati, Ohio 45226  May 16, 2014 Tach: 1869.9 AFTT: 1869.9 Engoleted inspection this date in accordance with FAR 4.	513-871-9966 N934PC Be S/N E-3448 gine TT: 1869.9 Engine TSO: 9	eech A36 3 1.8 Prop TT: 1869.9	
with E	Beech Service Manual. Replaced aft door ajar light bood and replaced fuse in power supply wire. Replaced ELT battery, due 6-2016. Opsiched ELT battery due 6-2016. Opsiched ELT battery, due 6-2016. Opsiched ELT battery due 6-2016. Opsiched ELT	ulb, GE327. Reinstalled altimeter ced primary and standby instrum ecked ELT IAW FAR91.207(d). S door seal.All ground checks perfo	r light tray. Repaired pilot's nent air filters, AAD9-14-5 Serviced shimmy dampener, ormed satisfactory. I certify	
J. Set	y Wash	end		

	Owner's Name		
	IES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICE NUM
Signature	N934PC Beech A36 6-8-2012 Hobbs 17.		
4760 Airport Rd Hangar 6 Lunl Cincinnati, Ohio 45226 513-87 Certified Repair Station E5ZR3	11-9966 16Y W.O.# E5305		
wings, cabin, fuselage, landing g components. Performed normal a aircraft IAW Beech Maintenance	n accordance with Beech Inspection guid ear and empennage sections. Checked light and emergency gear checks. Serviced and Manual. Removed existing engine baff	ghts and electrical d lubricated les and installed	
details. All required equipment is IAW STC SA02723CH gross we details. Replaced ELT battery, du	V STC SA368CH, see FAA form 337 dates now installed for this aircraft to be eligible ight increase, see FAA form 337 dated to be 10-2013. One checked FLT LAW FAE	ted this date for ible to operate his date for	
AD11-25-51 starter adapter shaft installed. AD84-26-02 paper air i	AD10-11-04 Lifters, DNA lifter date n, DNA not installed. AD12-03-06 fuel so filter due 3-13 or 1827TT whichever occorry. I certify that this aircraft has been	ot installed. ervo, DNA not	
accordance with an annual inspec	tion and has been found to be in an airw	orthy condition	
	Joseph K. Schott		
- Suna			
	Certified Repair Station E5ZR316Y		
4760 Airport Road, Hangar 6, Cincinnati, Ohio 45226	513-871-9966	_	
Cincinnati, Ohio 45226  Date: February/18/2013 Model: Hobbs: 1778.1 Hours N934PC			
Cincinnati, Ohio 45226  Date: February/18/2013 Model: Hobbs: 1778.1 Hours N934PC  Removed engine and installed over	IO-550-B W.O. #E5561 erhauled engine s/n: 685951. End.		
Cincinnati, Ohio 45226  Date: February/18/2013 Model: Hobbs: 1778.1 Hours N934PC  Removed engine and installed over	IO-550-B W.O. #E5561 erhauled engine s/n: 685951. End.		

Aircraft Model	Serial Number	
Reg #	Owner's Name	
	TIME ENTRIES MAY BE ON MULTIPLE INSPECTOR IOURS LINES IF REQUIRED SIGNATUR	Selection of the Control of the Cont
	Aviation Services  4696 Airport Rd. Hangar 2 Lunken Airport Cinti, OH 45226 513-871-6222  N934PC Beech A36 E- 8-23-2011 Hobbs 1681.	Salard M
	Repaired broken wire to air conditioning compressor. Repaired air conditioning conde actuator to condenser mount bracket. Replaced inoperative #1 TKS pump, p/n 951ABI 124-28V. Removed pump s/n AST03D767, installed overhauled pump s/n AST02G53 FAA form 8130-3 for details.——end——end——end———end——————————————————	8 see
	N934PC Beech A36 s/n E-3448 3-29-2012 Hobbs 1711.9  4760 Airport Rd Hangar 6 Lunken Airport Cincinnati, Ohio 45226 513-871-9966 Certified Repair Station E5ZR316Y  W.O.# E5164	
	Removed existing wingtips and installed D'Shannon Products wingtip fuel tanks IAW SA02722CH, see FAA form 337 dated this date for more detailsend	STC
+++		

eg #		Owner's N	ame		
DATE TIME HOURS		MAY BE ON N NES IF REQUIR	The state of the s	INSPECTOR'S SIGNATURE	LICENS!
Avionics, Inc. Hangar #2, Lur Cincinnati, OH		Beech A S/N E3 WO# 2	448		
FAA Form 8 performed.	topilot disconnect	st 17, 2010 and V	P/N031-00428-000 VO#2388 for detail	s of work	
Jøseph K Sc	hott CRS DD1R		NOT UP C D		
OF CI	ion Sei NCINNAT Hangar 2 Lunken Airp jschott@i		N934PC Beech A 5-9-2011 Hobbs Eng. TT 1660.2 Prop. TT 1660.2	1660.2 AFTT	
wings, cabin, fusels components. Perform IAW Beech Mainte FAR91.207(d), bat notch. Replaced brateries. Replaced ca certify that this airce been found to be in	nge, landing gear and med normal and en en ance Manual. Repetery due 7-12. Top of the liners, 66-105. So bin air filter, 35-534 raft has been inspecan airworthy condi	d empennage sectionergency gear check laced TKS filter, 90 charged battery. Cle Serviced shimmy da 1470-19. All ground ted in accordance v	36 Maintenance Man ons. Checked lights a ks. Serviced and lubr 08-01. Ops checked E caned up cowl flap ha ampener. Adjusted rig d checks performed so with an annual inspec	nd electrical icated aircraft ELT IAW indle detent ght main gear up atisfactory. I	
	h 4 Ell	Joseph K	. Schott A&P272464	269IA	
AND REPLACED F	230 A NA IRCRAFT:N934PC I		OUTH 104 11978 HOBBS: 1674.		

FOR NAPLES AIR CENTER CRS X04R655M.

Avionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222

April 17, 2009 Hobbs 1468.4

Aircraft Model_	April 17, 2009 Hobbs 1468.4	
All Craft Woder_	Installed Insight GEM610 engine monitor, see FAA Form 337 dated	
Reg #	this date for more detailsend	
11cg #	Joseph K. Schott A&P272464269	

DATE M	D HOURS		MAY BE ON MU ES IF REQUIRE	ACCUMULATION OF THE PERSON OF	INSPECTOR'S SIGNATURE	LICENSE NUMBER
	Avionics, Inc. Hangar #2, Lunken A	)	S/N E-3448 N934PC			
	Removed pitch se servo S/N 6299. I order #1913 date  Zach Stringer R	d June 11, 2009	of for pertinent de			
				VI	1	
		angar 2 Lunken Air	port Cinti, OH 45226 nics@zoomtown.com			
	cabin, fuselage, land Performed normal a Replaced primary in charged battery and 0130, due 7-2012. C wing. Cleaned and landing light bulb, C Installed missing co- Cylinders, DNA not Hydraulic Lifters, D	ling gear and emp nd emergency gea strument air filter reinstalled. Servic ps checked ELT labed sticky left co E4596. Replaced pilot shoulder har installed. AD 200 NA, by date. AD	ennage sections. Cher checks. Serviced a s, AAD9-14-5 & AA ded landing gear trans [AW FAR 91.207(d) owl latch. Replaced to both main tires, Gorness D ring cover, 509-19-07 EQ3 cylind 2009-25-01 Shoulded Loggiffy that this air	ecked lights and el nd lubricated aircr A2J4-7. Removed, smission level. Re b. Replaced missing op beacon bulb, 34 odyear Flight Cust 500794-5. AD 2009 lers, DNA, not inser Harness Washer,	Talled A1) 2009-24-52	
	an annual hispection	Mh K Su	Jose Jose	ph K. Schott A&F		

Owner's Name		
ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSI NUMBEI
Avionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222		
1-21-2009 Hobbs 1460.4	-	
ower nose gear door rod end. Installed chafe tape on ear nose gear door due to chafing on belly skin. Servi chimmy damper with MIL-5606 hydraulic fluid.—————	left	
J. L. G. Schott A&P27246	64269 ——	
ing gear, fuselage and empennage sections. Lubricate Beech Service Manual. Checked lights and electrical normal and emergency gear checks. Replaced one mon left wing forward of aileron. Installed missing screw ew pilot's vent window seal. ELT ops checked in accored to be be been accored to be been accordance with an annual inspection and to be in an airworthy condition.	ed and serviced components. hissing vortex on compass card. rdance with FAR arged battery. d on tail strobe. tor rod end. 66-105. itches with new fy that this aircraft has been	
<mark>ir filter and instrument air filters were replaced @ 3-5-</mark> r 1827.7 TT.	08 1327.7TT.	_
cs, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 2009 N934PC Beech A36 E-3448		
	Avionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222 1-21-2009 Hobbs 1460.4  Fightened right upper nose gear door rod end. Tighter ower nose gear door due to chafing on belly skin. Service in the context of the conte	Avionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222 1-21-2009 Hobbs 1460.4  Fightened right upper nose gear door rod end. Tightened left ower nose gear door due to chafing on belly skin. Serviced shimmy damper with MIL-5606 hydraulic fluid.  eng.  Joseph K. Schott A&P272464269  Vionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222 April 17, 2009 Hobbs 1468.4 TTAF and engine inspection this date per Beech Inspection Guide. Inspected wings, ing gear, fuselage and empennage sections. Lubricated and serviced Beech Service Manual. Checked lights and electrical components. normal and emergency gear checks. Replaced one missing vortex on left wing forward of aileron. Installed missing screw on compass card. It will be sufficiently selected with a coordance with FAR est. To be checked in accordance with FAR est. To be considered and charged battery. It is from aft tall section. Tighten left top cowl flap actuator rod end. gight brake disc, 164-00205. Replaced all brake liners, 66-105. 108-13-17 circuit breaker switch. Replaced affected switches with new ches. All ground checks performed satisfactory. I certify that this aircraft is spected in accordance with an annual inspection and has been to be in an airworthy condition.  Joseph K. Schott A&P272464269IA  irr filter and instrument air filters were replaced @ 3-5-08 1327.7TT.  25. Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 2009 N934PC Beech A36 E-3448 shot inoperative air conditioning system. Found time delay

Aircraft Model	Serial Number	
Reg #		
DATE TIME / M D HOURS	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S LICENSE SIGNATURE NUMBER
Compan	6320 Wate Eagle Oakland Cou	0 Highland Road erford, Mi. 48327 unty International Airport
Date: 11-04-08 1433 Removed aircraft batter check good.	A&P SHOONS	G242 battery. Operational
COMPA		20 Highland Road sterford, Mi. 48327 ounty International Airport
Date: 11-20-08 Removed GPS data card expires 12/1	1437.3 Hobbs  rds from Garmin 530 and 430. Upda 3/08. Garmin 530 and 430 updated a	ated data information. Current and operates normal.

eg #	Serial NumberOwner's Name
	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENS
M D HOURS	LINES IF REQUIRED SIGNATURE NUMBER
COMPAN	6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport  N934PC
Date: 09-25-08 Removed GPS data cards data card expires 10/23/05	1424 Hobbs from Garmin 530 and 430. Updated data information. Current 8. Garmin 530 and 430 updated and operates normal.
COMPANI	6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport  N934PC

Aircraft Model	Serial Number
Reg #	Owner's Name
DATE TIME / M D HOURS	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENS LINES IF REQUIRED SIGNATURE NUMBER
COMPANI	6320 Highland Road Waterford, Mi. 48327  Eagle Oakland County International Airport  N934PC
Serviced all tires to proper evel. This Aircraft has been ins	aker toggle switches due replacement by 08/06/2009.  The pressures of
COMPANI	6320 Highland Road Waterford, Mi. 48327  Caple Oakland County International Airport
Date: 08-27-08 Removed GPS data cards	1418.3 Hobbs from Garmin 530 and 430. Updated data information. Current Garmin 530 and 430 updated and operates normal.  A&P 55077832

Aircraft Model	Serial Number		
Reg #	Owner's Name		
DATE TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### **N934PC**

Date: 07-03-08

1378.5 Hobbs

Removed GPS data cards from Garmin 530 and 430. Updated data information. Current data card expires 7/31/08 Garmin 530 and 430 updated and operates normal.

A&P

585227832



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### N934PC

Date: 07-31-08

1399.2 Hobbs

Removed GPS data cards from Garmin 530 and 430. Updated data information. Current

data card expires 8/28/08. Garmin 530 and 430 updated and operates normal. 2282 26655 A&P

] #	Owner's Name
	6320 Highland Road
	Waterford, Mi. 48327  Falle Oakland County International Airport
COMPA	Waterford, Mi. 48327  Caple Oakland County International Airport
	N934PC
	7 0 TT 1357.9 Hobbs
Date: 5-16-08 135	7.9 11
Replaced landing gear	it it it is a light water Replaced missing V.G. ca left wing.
good Serviced battery	Williams and is approved
good Serviced battery	Williams and is approved
good. Serviced battery This Aircraft has been for return to service as	inspected in accordance with a 50Hr. inspection and is approved of this date and time. Details are on file at this facility under world
good. Serviced battery This Aircraft has been for return to service as	Williams and is approved
good. Serviced battery This Aircraft has been for return to service as	inspected in accordance with a 50Hr. inspection and is approved of this date and time. Details are on file at this facility under world
good Serviced battery	inspected in accordance with a 50Hr. inspection and is approved of this date and time. Details are on file at this facility under world
good. Serviced battery This Aircraft has been for return to service as	inspected in accordance with a 50Hr. inspection and is approved of this date and time. Details are on file at this facility under world
good. Serviced battery This Aircraft has been for return to service as	inspected in accordance with a 50Hr. inspection and is approved of this date and time. Details are on file at this facility under world
good. Serviced battery This Aircraft has been for return to service as	inspected in accordance with a 50Hr. inspecti, n and is approved of this date and time. Details are on file at this facility under work  A&P 357334572
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti, n and is approved of this date and time. Details are on file at this facility under work  A&P 357374572  6320 Highland Road
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti, n and is approved of this date and time. Details are on file at this facility under work  A&P 357374572  6320 Highland Road
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti, n and is approved of this date and time. Details are on file at this facility under work  A&P 38733452  6320 Highland Road
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti. n and is approved of this date and time. Details are on file at this facility under work  A&P 37737437  6320 Highland Road Waterford, Mi. 48327  Oakland County International Airport
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti, n and is approved of this date and time. Details are on file at this facility under work  A&P 357374572  6320 Highland Road
good. Serviced battery This Aircraft has been for return to service as order #2027.	inspected in accordance with a 50Hr. inspecti. n and is approved of this date and time. Details are on file at this facility under work  A&P 37737437  6320 Highland Road Waterford, Mi. 48327  Oakland County International Airport

Aircraft Model	Serial Number
Reg #	Owner's Name

DATE	TIME	ENTRIES MAY BE ON MULTIPLE	INSPECTOR'S	LICENSE
Y M D	HOURS	LINES IF REQUIRED	SIGNATURE	NUMBER



6320 Highland Road Waterford, Mi. 48327 Oakland Cour. y International Airport

#### N934PC

Date: 04-10-08

1344.5 Hobbs

Removed GPS data cards from Garmin 530 and 430. Updated data information. Current data card expires 5/8/08. Garmin 530 and 430 updated and operates normal.

SB55-3826 Stabilizers- inspection of elevator and rudder hinges for manufacturing damage. C/W by visual inspection IAW Paragraph 3.A. No damage found this date and time. Aircraft released for continued use.

A&P



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### N934PC

Date: 05-08-08

1357.9 Hobbs

Removed GPS data cards from Garmin 530 and 430. Updated data information. Current data card expires 6/05/08. Garmin 530 and 430 updated and operates normal.

A&P

Aircraft Model	Serial Number
Reg #	Owner's Name
DATE TIME Y M D HOURS	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENSE LINES IF REQUIRED SIGNATURE NUMBER
Continue	6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport
+1	<u>N934PC</u>
Date: 03-12-08 Removed GPS da data card expires	1329.6 Hobbs ta cards from Garmin 530 and 430. Updated data information. Current 4/10/08. Garmin 530 and 430 updated and operates normal.  A&P 55933777
COMP	6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport
	N934PC
Date: 04-09-08 Removed standby vanew Tempest model Airborne service tette	1344.5 TT  1344.5 Hobbs  cuum pump Airborne model 216CW S/N 7AU 1970 at.d installed a  AA3216CW S/N 51889. Operational check good. Rep iced due to  ar number 72.  A&P  S8922787

Aircraft Model	Serial Number	
Reg#	Owner's Name	

 DATE
 TIME
 ENTRIES MAY BE ON MULTIPLE
 INSPECTOR'S
 LICENSE

 Y
 M
 D
 HOURS
 LINES IF REQUIRED
 SIGNATURE
 NUMBER



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### **N934PC**

Date: 02-13-08

1324.5 Hobbs

Removed GPS data cards from Garmin 530 and 430. Updated data information. Current data card expires 3/13/08. Garmin 530 and 430 updated and operates normal.

A&P 387227887



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

IN ACCORDANCE WITH

N934PC

FAR 91.207 (D) 1, 2, 3, 4. BATTERY EXPIRES 4/2010

Date: 3-05-08

1327.7 TT

1327.7 Hobbs

Replaced all instrument pressure system filters and standby system filters. Replaced engine air filter. Replaced ELT battery. Replaced right hand muffler. Serviced both main gear with 5606 and nitrogen.

AD2007-08-08 Main landing gear uplock rollers. N/A by aircraft serial number. This Aircraft has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order #2021

A&P 58927872 7A

30

Tadewinds  Aviation  The professional approach	E ON MULTI REQUIRED  Oakland  N934PC	6320 Hig Waterfor d County	INSPECTO SIGNATURE Thland Road d, Mi. 48327 International data informa operates normal	R'S LICEN RE NUME
Tradewinds  Aviation  "the professional approach"  ate: 11-21-07  emoved GPS data cards from Garmin State card expires 12/20/07. Garmin 530	Oakland N934PC	6320 Hig Waterfor d County	signatul ghland Road d, Mi. 48327 International	Airport
ate: 11-21-07 emoved GPS data cards from Garmin State card expires 12/20/07. Garmin 530	N934PC	Waterford County	d, Mi. 48327 International	Airport
ate: 11-21-07 emoved GPS data cards from Garmin state card expires 12/20/07. Garmin 530	520 1 420	0. Updated odated and	data informa operates norm	ntion. Current mal.
emoved GPS data cards from Garmin Sata card expires 12/20/07. Garmin 530	-20 1 120	D. Updated odated and	data informa operates norm	ation. Current mal.
Tradewinds  Aviation				
Tradewinds  Aviation				
Tradewinds			7	
"the professional approach"	Oakland	Waterfor	ghland Road d, Mi. 48327 Internationa	*
	N934PC			
ate: 01-15-08 emoved GPS data cards from Garmin state card expires 2/14/08. Garmin 530 and card expires 2/14/08.		). Updated lated and c ジャラシ	data informa operates norm	ation. Current nal.
Miffed to				
	_			

Aircraft Model	Serial Number
Reg #	Owner's Name
	MAY BE ON MULTIPLE INSPECTOR'S LICENSE SIGNATURE NUMBER
Tradewinds Aviation "the professional approach"	Waterford, Mi. 48327 Oakland County International Airport
limits. Replaced tail strobe cannon proceed in a for return to service as of this date a order #2004.	N 36-555048-3, Adjust A/C belt tension to within
Tradewinds Aviation  "the professional approach"	6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport
Date: 10-23-07 1304.8 Ho	N934PC obbs
Removed GPS data cards from Garmin 53	n 530 and 430. Updated data information. Current 30 and 430 updated and operates normal.  A&P 5892283

ircraft Model				
eg #	Own	er's Name		
DATE TIME	ENTRIES MAY BE LINES IF RE	ON MULTIPLE QUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Jille Avia	nal approach	Water	Highland Road rford, Mi. 48327 nty International Air	port
Date: 08-27-07 Removed GPS data card expires 09/2	1265.9Hobb rds from Garmin 5 7/07. Garmin 530		ated data information and operates normal.	. Current
Date: 09-26-07 Removed GPS data card data card expires 10/25/0	al approach No.	Waterfo Oakland County 934PC	Tighland Road pord, Mi. 48327 por International Airport data information. Out of the control of	
MBM				

Aircraft Model	Serial Number
Reg #	Owner's Name
	IES MAY BE ON MULTIPLE INSPECTOR'S LICENS LINES IF REQUIRED SIGNATURE NUMBE
Tradewind Aviation  "the professional approa	Waterford, Mi. 48327 Oakland County International Airport
	N934PC
Removed GPS data cards from G	1.2Hobbs Garmin 530 and 430. Updated data information. Current min 530 and 430 updated and operates normal.  A&P SFFDINGS
Tradewinds  VALA Aviation  *the professional approach	Waterford, Mi. 48327 Oakland County International Airport
his Aircraft has been inspected in	1253.2 Hobbs or belt and adjusted to proper tension. Serviced all tires accordance with a 50Hr. inspection and is approved and time. Details are on file at this facility under work
	1

	Serial Number	
Reg #		
DATE TIME Y M D HOURS		PECTOR'S LICENSE NATURE NUMBER
Avia Avia	winds 6320 Highland A Waterford, Mi. 4 Oakland County Interna N934PC	18327
Date: 6-22-07 1201 Serviced tires to proper Replaced vortex genera Replaced landing light Serviced battery with d Replaced flash tube on This Aircraft has been for return to service as order #1978.	ator on left wing	n and is approved facility under work
-		
Trade Avi	ewinds 6320 Highland Waterford, Mi. Oakland County Intervisional approach	48327
"the profess	6320 Highland Waterford, Mi. Oakland County International approach  N934PC  1203.9Hobbs cards from Garmin 530 and 430. Updated data //02/07. Garmin 530 and 430 updated and operations.	, 48327 national Airport

ircraft Model	
DATE TIME M D HOURS	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICEN LINES IF REQUIRED SIGNATURE NUMB
Tradev Aviat	Waterford, Mi. 48327 Oakland County International Airport
	N934PC
Removed GPS data cards data card expires 06/07/0	from Garmin 530 and 430. Updated data information. Current 7. Garmin 530 and 430 updated and operates normal.  A&P 5892772
Trade Avia	Waterford, Mi. 48327 Oakland County International Airport
"the profession	nai approach
"the profession	N934PC
Date: 06-05-07	
Date: 06-05-07	N934PC  1182Hobbs ds from Garmin 530 and 430. Updated data information. Current //07. Garmin 530 and 430 updated and operates normal.
Date: 06-05-07	N934PC  1182Hobbs ds from Garmin 530 and 430. Updated data information. Current //07. Garmin 530 and 430 updated and operates normal.
Date: 06-05-07	N934PC  1182Hobbs ds from Garmin 530 and 430. Updated data information. Current //07. Garmin 530 and 430 updated and operates normal.
Date: 06-05-07	N934PC  1182Hobbs ds from Garmin 530 and 430. Updated data information. Current //07. Garmin 530 and 430 updated and operates normal.

Aircraft Model	Serial Number
Reg #	Owner's Name

ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENSE TIME DATE **SIGNATURE NUMBER** LINES IF REQUIRED HOURS YMD



"the professional approach"

6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

N934PC

INSPECTED ELT IN ACCORDANCE WITH FAR 91.207 (D) 1, 2, 3, 4. BATTERY BRES \_\_\_\_\_3/08 EXPIRES \_\_\_\_

Date: 3-16-07

1156.4TT

1156.4Hobbs

Replaced instrument pressure system and standby system filters. Replaced landing gear motor brushes. Replaced all fuel and oil hoses forward of firewall(8). Replaced engine driven pressure pump. Removed left main gear, right main gear and nose gear assemblies from aircraft. Disassembled, cleaned and inspected all assemblies. Reassembled all gear assemblies using new o-rings, scraper rings and hardware. Installed all gear assemblies onto aircraft and serviced with hydraulic fluid 5606 and nitrogen. Cycled gear several onto airciait and so that serviced nose gear shimmy dampner. Replaced right main times. Operation normal. Serviced nose gear shimmy dampner. Replaced right main times. Operation normal A/C compressor belt tension to within limits. Replaced courtesy brake linings. Adjusted A/C compressor belt tension to within limits. Replaced courtesy brake пппgs. Aujusted 1. Replaced V.G. on right wing. Replaced engine air filter. light switch in cabin door jamb. Replaced V.G. on right wing. Replaced engine air filter. light switch in caoin do. 3 [17] 18 [18] 18 [18] 19 [1

serial number.

This Aircraft has been inspected in accordance with an ANNUAL inspection and is This Aircraft has been hispection and is approved for return to service as of this date and time. Details are on file at this facility

under work order #1986.

A&P 59247821 7A



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

N934PC

Date: 03-16-07
Removed GPS data cards from Garmin 530 and 430 updated and operator. Current Removed GPS data cards from Garmin 530 and 430 updated and operator. Removed GPS data cards in San and 430 updated and operates normal. A&P

ircraft Model	Serial Number
eg #	Owner's Name
DATE TIME E	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENS LINES IF REQUIRED SIGNATURE NUMBE
Tradew Aviat "the professional	Waterford, Mi. 48327 Oakland County International Airport
Date: 02-14-07 Removed GPS data cards data card expires 03/15/07	N934PC  1151.7Hobbs from Garmin 530 and 430. Updated data information. Current 7. Garmin 530 and 430 updated and operates normal.  A&P SS92078/2
COMPLIED WITH THE 5 YEAR WING DLTS WERE INSPECTED AND FOL RS# MQ5R050N UNDER WORK OR CCORDANCE WITH RAYTHEON BO IE WING BOLT TORQUE CHECK IS IE AIRCRAFT AND/OR COMPONE	C AN AUTHORIZED RAYTHEON AIRCRAFT SERVICE CENTER OGBOOK ENTRY/ MAINTENANCE RELEASE  N934PC S/N: E-3448 HOBBS: 1153.4  G BOLT INSPECTION & 12 MONTH WING BOLT LUBRICATION AS THE 8 JND SERVICEABLE BY H & S PROPELLER SHOP, WATERFORD, MI., FAA RDER 40062. INSTALLED BOLTS WITH NEW NUTS AND TORQUED IN ONANZA SERIES MAINTENANCE MANUAL CHAPTER 57-00-00. PAGE 9-12.  S DUE AT THE NEXT SCHEDULED INSPECTION.  INT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE S AND WAS FOUND AIRWORTHY AS AFFECTED BY THE WORK ALLS ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO  AERODYNAMICS, INC. BUER634C

Aircraft Model	Serial Number		
Reg #	Owner's Name		
DATE TIME ENTRI	ES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Date: 1-3-07 1147.9TT Replaced left main tire asseming this Aircraft has been inspect for return to service as of this order #1947.	Oakland Countroach  N934PC  1147.9Hobbs  bly.		
I det			
Tradewin Aviation "the professional appli	Oakland Count roach'	lighland Road ford, Mi. 48327 fy International Airp	oort
Date: 01-17-07 Removed GPS data cards from data card expires 02/15/07. G	N934PC  1150.1Hobbs	ed data information.  and operates normal.	Current

Aircraft Model	Serial Number	er		
Reg #	Owner's Nar	me		
DATE TIME   M D HOURS	ENTRIES MAY BE ON MU LINES IF REQUIREI		SPECTOR'S IGNATURE	LICENS NUMBE
Tradev Aviation	ion Oakla	6320 Highland Waterford, Mi and County Intern	. 48327	rt
	N934PC	2		
data card expires 12/21/	1129.7Hobbs s from Garmin 530 and 4 06. Garmin 530 and 430 A&F	updated and opera	ates normal.	urrent
		I		
Tradev Aviat "the professional	ion Oakla	6320 Highland Waterford, Mi. nd County Intern	48327	t
Date: 12-21-06 Removed GPS data cards data card expires 01/18/0	1143.3Hobbs	30. Updated data i	tes normal.	urrent

ircraft Model	Serial Number
eg #	Owner's Name
DATE TIME ENTRIE	S MAY BE ON MULTIPLE INSPECTOR'S LICENS INES IF REQUIRED SIGNATURE NUMBE
Tradewind Aviation "the professional approx	Oakland County International Airport
Date: 08-24-06 1106.3TT Replaced strobe assembly P/N 0 This Aircraft has been inspected for return to service as of this da order #1925.	1106.3Hobbs 1-0770024-15 with new. in accordance with a 50HR inspection and is approved te and time. Details are on file at this facility under work
Tradewin Aviation  *the professional approfessional	Oakland County International Airport
Date: 10-31-06 Removed GPS data cards from	1124.9Hobbs Garmin 530 and 430. Updated data information. Current Garmin 530 and 430 updated and operates normal.

Aircraft Model	Serial	Number		
Reg #	Own	er's Name		
	ENTRIES MAY BE LINES IF RE	QUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
	5/30/0			
— R&R Vaci — ops check	um pump	o & filter	·s,	
		, ,	od	
Signature Work Ord	William Scanl	30/06		
	Keyson Airways Corporation Certified Repair Station KNMR864			
+,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Trade			hland Road	
אואליווי Avia		the second secon	d, Mi. 48327 International Airpor	rt -
"the profession		84PC		
07.12.07	5 OTT 1055 O	W 11		
Serviced battery with d				
Replaced tail strobe ass This Aircraft has been in	nspected in accordan	ice with a 50Hr. in	spection and is appr	oved
for return to service as order #1911.	of this date and time.	Details are on fil	e at this facility unde	er work
35 hr		A&P_ <u>27398/</u>	3	

Aircraft Model	Serial Number
Reg #	Owner's Name
DATE TIME ENTR	IES MAY BE ON MULTIPLE INSPECTOR'S LICENSE LINES IF REQUIRED SIGNATURE NUMBER
Serviced shimmy dampner w	Oakland County International Airport  INSPECTED E L T  IN ACCORDANCE WITH  FAR 91.207  (D) 1, 2, 3, 4, BATTERY  927.1Hobbs  EXPIRES 3/08  Sure system and stand by system filters. Replaced engine air rainer gasket. Replaced ELT battery. Due again 03/2008.  ith 5606. Adjusted air conditioner compressor belt.
Tradewin Aviation "the professional appr	Oakland County International Airport —
Date: 05-10-06 982.7TT Replaced tail nav light. Serviced battery with distilled This Aircraft has been inspects for return to service as of this order #1894.	982.7Hobbs  water. d in accordance with a 50HR inspection and is approved late and time. Details are on file at this facility under work
	17

craft Model	Serial Number			
g #	Owner's Name			
ATE TIME M D HOURS	ENTRIES MAY BE ON MULTI LINES IF REQUIRED	IPLE	INSPECTOR'S SIGNATURE	LICEN: NUMB
الالالالالالالا	dewinds Viation Oaklan of the state of the s	Waterfor	ghland Road d, Mi. 48327 International Air	port
	<u>N934PC</u>			
Replaced left main t compressor belt and This Aircraft has been	70.3TT 870.3Hobbs ire assembly. Replaced left and adjusted tension to within limiten inspected in accordance with as of this date and time. Detail	its. Replace h a 50 Hr. i ls are on file	ed left strobe tube.	DDmo- 1
- יווי An	lewinds liation ssional approach  N934PC	Wate	0 Highland Road erford, Mi. 48327 ty International A	irport
	895 TT 895 Hobb ced courtesy light push button A&P_27	switch P/N	I 8410K1 with ne	w

Aircraft Model	Serial Number
Reg #	Owner's Name

**ENTRIES MAY BE ON MULTIPLE** 

LINES IF REQUIRED Tradewinds Aviation

"the professional approach"

INSPECTOR'S **SIGNATURE** 

LICENSE NUMBER

6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### N934PC

864.8Tach

Removed and replaced right main tire assembly. Removed and replaced A/C door open

light switch P/N BZ-7RWT822 with new P/N BZ-7RWT822.

A&P 2739813



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

"the professional approach"

#### N934PC

864.8Hobbs

Removed and Replaced Quad dimmer assembly P/N 102-384039-1 S/N 2448A with

repaired assembly P/N 102-384039-1 S/N 2550A. 1 A&P 2739813



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

## N934PC

870.3Hobbs

Removed and replaced nose gear tow pin P/N 70898-60-820029-1.

Aircraft Model	Serial Number		
Reg #	Owner's Name		
DATE TIME M D HOURS	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSI NUMBE
Avi	otion Wate	Highland Road rford, Mi. 48327 nty International Airpo	
Replaced vacuum sys strut with nitrogen. Se	23.4TT 823.4Hobbs  Internal and standby vacuum system into the erviced battery with distilled water. In inspected in accordance with a 50H soft this date and time. Details are of the erviced A&P 2.	R inspection and is apposed in the Receiver the Receiver the Receive the Recei	
red the following equipment:	A-36 A/C SN: E-3448 W.O. NO: 10285 KT76C Transponder	GA55 Antenna	
alled the following equipmen	t: GTX330 Transponder GDL69A WX received		
alled the following equipmen installation was performed i ifications and is approved f new aircraft empty weight is new center of gravity is new moment is: 211522.1	n accordance with manufacturers for return to service. 2658.41 lbs. 79.57 inches.		

Reg #	Owner's Name		
DATE TIME I	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Tradev Avial "the professional	Oakland Cour	Highland Road ford, Mi. 48327 nty International Airp	oort
Date: 06-20-05 771. Replaced nose gear tow this Aircraft has been in for return to service as of order #1823.	1TT 771.1Hobbs pin P/N 60-820029-1. Replace two aspected in accordance with a 50H f this date and time. Details are on A&P 27	n file at this facility ur	se gear. proved nder work
	_		1
Tradev Aviat	oakland Con	220 Highland Road aterford, Mi. 48327 anty International Air	port
Tradev Aviat	oakland Con	aterford, Mi. 48327	port
"the professional	Oakland Con  N934PC  72.8TT  772.8Tach	aterford, Mi. 48327	port
"the professional Date: 06-21-05	Oakland Con  N934PC  72.8TT  772.8Tach	aterford, Mi. 48327	port
"the professional Date: 06-21-05	Oakland Con  N934PC  72.8TT  772.8Tach	aterford, Mi. 48327	port
"the professional Date: 06-21-05	Oakland Con  N934PC  72.8TT  772.8Tach	aterford, Mi. 48327	port

Avia Avia	winds ation	6320 Highland Road Waterford, Mi. 48327	
	onal approach	nd County International Airport	
This Aircraft has been	s of this date and time. Details	n a 50HR inspection and is approved a sare on file at this facility under the P 22398/3	/ed wor
Trade Avia  "the profession	tion Oakland	6320 Highland Road Waterford, Mi. 48327 County International Airport INSPECTED E L T IN ACCORDANCE WITH FAR 91.207 (D) 1, 2, 3, 4, BATTERY	
Replaced all filters in ir intake filter. Adjusted a with 5606. Serviced not	ar conditioner belt to within in se strut with nitrogen.  Inspected in accordance with a service as of this date and times.	d standby system. Replaced engine imits. Serviced shimmy dampner an ANNUAL inspection and is e. Details are on file at this facility.	

Aircraft Model 4-36	Serial Number E-3948
Aircraft Model A-SG	Owner's Name
DATE TIME ENTRIES Y M D HOURS LIN	MAY BE ON MULTIPLE INSPECTOR'S LICENSE NES IF REQUIRED SIGNATURE NUMBER
Tradewinds Aviation  "the professional approach	Waterford, Mi. 48327 Oakland County International Airport
Installed STC SA09074SC vortex g drawing list JVE-500 revision 2 date revision 1 dated 12/21/95. Also STC landing gross weight by 100 lbs. wh	TSO 664.2Hobbs generator kit in accordance with JVE Inc. master ted 08/21/95 and installation manual JVE-0494 C09254SC states increase in maximum takeoff and hen equipped with vortex generators per JVE Inc. STC of Logbook. A&P 3977877
- ENTERED OUT OF C	sagar Advalagessgaris
3213 Arnold Ave. S.  3 January 2005 S/N: E-344	Make: Raytheon Model: A36  HOBBS: 609.7
the Manufactures instance file this date. The preceding work Raytheon Maintenance Manuals and Procedures Manuals. This aircraft IS APPROVED for file and procedures is installed a	Per STC# SA01136WI and in conformance with anual P/N: 10353-01 Rev. 3. FAA Form 337 on k was accomplished using the following:  AC43.13 1B-2A and/or AS&T Inc. Installation light into known icing conditions when the and operating properly. (That list may be found action 2 pages 3-9.)
in the TKS POH supplement, sec Updated the POH/AFM and Weig Lance O. R	ght and Balance.

Aircraft Model	Serial Number			
Reg #	Owner's Name	Owner's Name		
DATE TIME EN	TRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER	
Tradewir Aviatio  "the professional app  Date: 02-14-05 630.6  AD2005-01-19 N/A Garmin	Water Oakland County  N934PC  630.6Hobbs	Highland Road ford, Mi. 48327 y International Airport		
Tradewir Aviatio "the professional app	Materfor Oakland County Proach	ghland Road rd, Mi. 48327 International Airport		
This Aircraft has been inspec	647.3Hobbs  placed nose tire. Replaced all braited in accordance with a 50HR is date and time. Details are on file.  A&P_586	nspection and is appro- le at this facility under	eved Work	

Tradewii	NIES MAY BE ON MULTIPLE INSPECTOR'S LICENS  6320 Highland Road
Lagevill	Waterford, Mi. 48327
III Aviatio	
"the professional ap	N934PC
(77	551.6Hobbs
Date: 09-24-04 551.6TT	d standby vacuum system intake filters.
This Aircraft has been inspec	d standby vacuum system intake filters.  cted in accordance with a 50HR inspection and is approved s date and time. Details are on file at this facility under work
for return to service as of the order #1762.	A&P 381765553
Yeld T	The state of the s
Tradewil	6320 Highland Road Waterford, Mi. 48327
MI Aviatio	Oakland County International Airport
A STATE OF THE STA	proach N934PC
"the professional ap	
"the professional ap	
	593.6Hobbs sordance with a 50HR inspection and is approved
	593.6Hobbs  cted in accordance with a 50HR inspection and is approved a date and time. Details are on file at this facility under work
	593.6Hobbs  cted in accordance with a 50HR inspection and is approved a date and time. Details are on file at this facility under work  A&P 587717877

Aircraft Model	Serial Number		
Reg #	Owner's Name		
	S MAY BE ON MULTIPLE	INSPECTOR'S SIGNATURE	LICENSE . NUMBER
Tradewinds Aviation  "the professional approach"	6320 Highla Waterford, N. Oakland County Inte	Ti. 48327	
Date: 07-02-04 452.7TT 452 This Aircraft has been inspected in according for return to service as of this date and to order #1738.	1	his facility under work	
Tradewinds Aviation  "the professional approach"	6320 Highla Waterford, M Oakland County Intel N934PC	li. 48327	
Date: 08-09-04 500.3TT 500 Replaced landing light. This Aircraft has been inspected in according return to service as of this date and to order #1750.	0.3Hobbs  ordance with a 50HR inspectime. Details are on file at the second sec	his facility under work	

Aircraft Model	Serial Number	
Reg #_	Owner's Name	
	ENTRIES MAY BE ON MULTIPLE INSPECTOR	R'S LICENSE
DATE TIME Y M D HOURS	LINES IF REQUIRED SIGNATUR	RE NUMBER
Tradew Aviati	Waterford, Mi. 48327 Oakland County International Airp	port
Replaced ELT batt	8.2TT 398.2Hobbs ery, battery is now due replacement May 2006.	
7220172	A&P 381765953	
Frade Avia Avia the profession	tion Oakland County International Ai	T
all tires to proper pressu	.4TT 401.4Hobbs filter. Replaced all instrument pressure system filters a battery with distilled water. Replaced both main tires. Bled right brake assembly. Serviced brake reservoints. Bled right accordance with an ANNUAL inspection a enspected in accordance with an ANNUAL inspection are so of this date and time. Details are on file at the	

DATE TIME HOURS	LINI	MAY BE ON MU ES IF REQUIRED		INSPECTOR'S SIGNATURE	LI(
All All	dewinds viation essional approach	Oaklan	Waterford,	land Road Mi. 48327 ternational Airpor	t
Date: 03-10-04 Replaced landing li This Aircraft has be for return to service order #1704.	ight. een inspected in a	nd time. Detail	a 50 Hr. ins s are on file P5896	at this facility unde	roved er wor
AT CO III.	ewinds		6320 Highl Waterford,		
	iation ssional approach	Oakland N934PC	l County Int	ernational Airport	
Serviced all tires to	proper pressure.	390.4Hobbs ccordance with ad time. Details	a 50 Hr. insp are on file a	pection and is appro t this facility under	oved Work

Aircraft Model	A-36 934PC			
	ME ENTRIE URS L	S MAY BE ON MULTIF INES IF REQUIRED	PLE INSPECTOR'S SIGNATURE	
יווין	radewing Aviation the professional appro-	Oakland	6320 Highland Road Waterford, Mi. 48327 County International Ai	rport -
Serviced tire	t has been inspected service as of this da	I in accordance with a attention and time. Details	linings on L/main. 50 Hr. inspection and is are on file at this facility of the second	approved under work
	Tradewin Aviation the professional appli	Oaklan (	6320 Highland Road Waterford, Mi. 48327 d County International A	Airport
Date: 11-1 Replaced i Replaced I This Aircr for return order #168	aft has been inspect to service as of this	ed in accordance with date and time. Detail	nd standby system intake a 50 Hr. inspection and is are on file at this facility $\frac{589237832}{}$	filter. is approved y under work
	us. ····			

Aircraft Model	Serial Number	
Reg #	Owner's Name	

TIME DATE HOURS M D

**ENTRIES MAY BE ON MULTIPLE** LINES IF REQUIRED

**INSPECTOR'S SIGNATURE** 

LICENSE NUMBER



6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### N934PC

Date: 04-16-03

147.7TT

147.7Hobbs

Serviced battery, and brake reservoir.

This Aircraft has been inspected in accordance with a 50HR inspection and is approved for return to service as of this date and time. Details are on file at this facility under work



381765953 A&P



"the professional approach"

6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport

#### N934PC

Date: 05-16-03

173.4TT

173.4Hobbs

Replaced instrument pressure system and standby system intake filters and inline filters. Intake filters due again at 273 hobbs, inline filters due again at 673 hobbs or next annual. Replaced engine air intake filter. Serviced all tires to proper pressure.

This Aircraft has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility

INSPECTED E L T IN ACCORDANCE WITH Fog 91.207

(D) 1, 2, 3, 4, BATTERY

EXPIRES.

A&P 58922787) IA

Mischel

Aircraft Model $A-36$ Serial Number $E-3448$ Reg # Owner's Name
DATE TIME ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENSE SIGNATURE NUMBER
Tradewinds  Waterford, Mi. 48327  Oakland County International Airport  The professional approach  N934PC
Date: 10-01-02 98.1TT 98.1Hobbs  Serviced all tires to correct pressure. Serviced battery with distilled water.  Serviced all tires to correct pressure with a 50HR inspection and is approved. This Aircraft has been inspected in accordance with a 50HR inspection and is approved. This Aircraft has been inspected in accordance with a 50HR inspection and is approved. This Aircraft has been inspected in accordance with a 50HR inspection and is approved. This Aircraft has been inspected in accordance with a 50HR inspection and is approved order #1578.
Tradewinds  6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport  N934PC  143.6Tach
Date: 02-28-03 143.6TT 143.6Tach  Checked wing bolt torque in accordance with bonanza maintenance. All good.  A&P 58937872

	ENTRIES MAY		PLE	INSPECTOR'S	LICE
D HOURS	LINES IF	REQUIRED		SIGNATURE	NUM
Alterna	tive		( <u></u>		-
AVION	lics	1661 Airpo Waterford, MI 483		SA	
Alternative Aviation F.A.A. Repair Sta	on Services, Inc. ation OA5R086N		Date	7/31/02	-
Reg. NoN934	PC	Ser	. No. <u>E3448</u>		
WO No	14002	_ Hours_	NA		
Removed failed KI-					
exchange KI-525A I normal.	P/N 066-3046-07	S/N 92740. Teste	ed the system	operation	
	X	X	X X		
aircraft and/or compor	nent identified above	e was repaired and	inspected in ac		-
cordance with current	air regulations and	found airworthy for	return to serv	vice	
cordance with current	111-1	11.//			
CRS OA5R086N	When Do				-
	Mu D				
	Allu Do				
CRS OA5R086N					
	ive_	1661 Airport	Road		
CRS OA5R086N	VC Gervices, Inc		Road 7-1304 USA	9/12/02	
CRS OA5R086N	CS W Services, Inc. 1 OA5R086N	1661 Airport aterford, MI 4832	Road 7-1304 USA Date	9/12/02	
Alternative Aviation S FA A Repair Station N9341 Reg. No.	Services, Inc. 10A5R086N PC	1661 Airport laterford, MI 4832 Ser. I Hours	Road 7-1304 USA □ate_ NoE3448	9/12/02	
Alternative Aviation S FA A Repair Station N9341 Reg. No	Services, Inc. 1 OA5R086N PC 14075	1661 Airport laterford, MI 4832 Ser. I Hours	Road 7-1304 USA Date_ No	9/12/02	
Alternative Aviation S FA A Repair Station N934 Reg. No.  Removed failed pitch installed new exchange	Services, Inc. 1 OA5R086N PC 14075 servo, KS-270C ge KS-270C P/N	1661 Airport laterford, MI 4832 Sen. I Hours P/N 065-00178-2	Road 7-1304 USA Date_ No. E3448 NA	9/12/02	
Alternative Aviation S FA A Repair Station N934 Reg. No. WO No. Removed failed pitch	Services, Inc. 1 OA5R086N PC 14075 servo, KS-270C ge KS-270C P/N	1661 Airport laterford, MI 4832 Sen. I Hours P/N 065-00178-2	Road 7-1304 USA Date_ No. E3448 NA 	9/12/02	
CRS OA5R086N	Notervices, Inc. of OA5R086N PC  14075  Servo, KS-270C ge KS-270C P/N normal. X X	1661 Airport laterford, MI 4832 Sen. I Houns P/N 065-00178-2 065-00178-2500 X X	Road 7-1304 USA Date_ No. E3448 NA 	9/12/02 	
Alternative Aviation S FA A Repair Station  N9341  Reg. No.  Removed failed pitch installed new exchang AP system operation X	Notervices, Inc. of OA5R086N PC  14075  Servo, KS-270C ge KS-270C P/N normal.  X  X  ent identified above	1661 Airport laterford, MI 4832 Sen. I Hours P/N 065-00178-2 065-00178-2500 X X X was repaired and in	Road 7-1304 USA Date_ No. E3448 NA	9/12/02 	

	M934PC  IME ENTRIES  DURS LIN	Serial Number Owner's Name  MAY BE ON MULTIPLE NES IF REQUIRED		LICENSE NUMBER
	radewinds Aviation  Professional approach	Oakland Cour	Highland Road rford, Mi. 48327 nty International Airpo	rt
Serviced all t landing light	has been inspected in service as of this date	e. Serviced battery with ght mufflers/tail pipes. accordance with a 50F and time. Details are o	th distilled water. Replace Re	proved
			l	
ין ויין. י	radewinds Aviation the professional approace	Oakland C N934PC	6320 Highland Road Waterford, Mi. 48327 Jounty International Air	port
	l pressure switch at fir vitch instead of landing	awall on left side. All	eraft Hobbs now runs of	ff of oil
pressure sy				1

TEM!	PEST
Air Filter Cha	nge Reminder
Installed at:	Change at:
1588.0 Hrs.	Hrs.
5-6	-/0
AIA Aero	Accessories, Inc.



N934PC S/N E-3448