

GIV N978CC S/N: 1335

Work Order #: 13352409.2

Date	A/C HRS	A/C AFL	ENG 1 HRS	ENG 1 ENC	ENG 2 HRS	ENG 2 ENC	APU HRS	
15-Sep-24	5860.9	3001	9067.6	4222	5555.1	A0F7	4341	
13-3ер-24	3000.5	2001	9007.0	4222	2222.1	2857	4341	

THE FOLLOWING MAINTENANCE WAS ACCOMPLISHED:

	TASK NUMBER	DESCRIPTION				
1	121335	PREFLIGHT CHECK				
2	240108	STANDBY POWER SYSTEM - OPERATIONAL TEST				
3	256339	DEFIBRILLATOR-INSP				
4	262550	PORTABLE H2O FIRE EXTINGUISHER - DETAILED INSPECTION				
5	262631	PORTABLE FIRE EXTINGUISHER (RIGHT COCKPIT) - DETAILED INSPECTION				
6	262635	PORTABLE FIRE EXTINGUISHER (AFT LAVATORY) - DETAILED INSPECTION				
7	280008	MICROBIOLOGICAL CONTAMINATION TEST OF FUEL TANK - SPECIAL DETAILED INSPECTION				
8	291057	COMBINED / FLIGHT HYDRAULIC SYSTEM RESERVOIR - FILLING PROCEDURES				
9	320004	MAIN LANDING GEAR (LEFT) - LUBRICATION				
10	320005	MAIN LANDING GEAR (RIGHT) - LUBRICATION				
11	320006	NOSE GEAR - LUBRICATION				
12	324265	BRAKES (LEFT) - BLEEDING PROCEDURES (DUNLOP)				
13	324266	BRAKES (RIGHT) - BLEEDING PROCEDURES (DUNLOP)				
14	711066	UPPER COWL DOOR (RIGHT) - REMOVAL / INSTALLATION P/N Off: 1159P41210-8 S/N Off: 395481001 Reason Removed: B-PREMATURE FAILURE P/N On: 1159P41210-8 S/N On: 042735 Part Condition: Serviceable Part Times:				

I certify that the above maintenance was performed in accordance with current manufacturer's instructions and required technical data. Items requiring inspection were inspected per approved inspection program required under 14 CFR Part 91.409 (f) (3). The aircraft has been found to be in airworthy condition, with regard to the work performed and is approved for return to service. Further details of work performed are on file under the referenced work order.

TECHNICIAN JASON Władyka

Certificate #: A&P: 3132748