



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

The subject aircraft was involved in an incident /
accident on 10/4/2025 rendering it a Constructive Total
Loss as not repairable within its insured value. For
further details refer to insurance claim: 3411200695US.

Signed: ***Underwriters Salvage Company***

Date: **11/24/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100
Atlanta, GA 30326

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Oct 05 2023	00:00	/	Manufactured	6419 Klesse 4 <i>[Signature]</i>



DECEMBER 05, 2024 N11KH-N96WJ TACH: 81.0 PTSN:0.0

MT PROPELLER LOG

PROPELLER M/N MTV-9-B/198-52 S/N 231475 INSTALLED ON N96WJ, AVIAT A-1C-200, S/N 3397 AT THIS TIME IAW STC SA02870CH AND FLIGHT RESOURCE LLC INSTALLATION INSTRUCTIONS REV. C DATED 07/11/2016. POST-INSTALLATION OPERATIONAL AND LEAK CHECKS SATISFACTORY.

THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER W/O NO. 80789 DATE 12/05/2024

SIGNED *[Signature]*
MICHAEL BERNHARDT FOR WIPAIRE, INC. CRS RJWR390K PHONE 651.451.1205

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

REG: N96WJ
MAKE: MT-PROPELLER
MODEL: MTV-9-B/198-52
SERIAL: 231475
DATE: 6/5/2025



1313 COUNTY RD 134, BUFFALO, MN 55313
763-682-1516

TACH: 83.2
PTT: 2.2
PTSNEW: 2.2

Performed Annual Inspection IAW 14 CFR Part 43, Appendix D and Aviat Aircraft A-1C-200 Instructions for Continued Airworthiness. Removed spinner, visually inspected propeller, checked propeller bolts for proper torque and safety wire. See updated AD Compliance Report dated 6/3/2025. I certify that this engine has been inspected IAW an Annual Inspection and was found to be in airworthy condition.

[Signature]

DREW HAUCK A&P 3955636 IA

REG: N96WJ
MAKE: MT-PROPELLER
MODEL: MTV-9-B/198-52
SERIAL: 231475
DATE: 10/3/2025



1313 COUNTY RD 134, BUFFALO, MN 55313
763-682-1516

TACH: 84.7
PTT: 3.7

PROPELLER

Performed Annual Inspection IAW 14 CFR Part 43, Appendix D and Aviat Aircraft A-1C-200 Instructions for Continued Airworthiness. Removed spinner, visually inspected propeller, checked propeller bolts for proper torque and safety wire. Confirmed all AD's complied with to date. See updated AD Compliance Report dated 10/3/2025. I certify that this propeller has been inspected IAW an Annual Inspection and was found to be in airworthy condition

[Signature]

WILLIAM WINGERD A&P 4474593 IA

ires
tion
ers

Owner Name _____

Address _____

Propeller Model MTV-9-B

Blade Model 198-52

Hub Serial No. 231475

Blade Serial No. 1 A0G-100981

Propeller Diameter: 198 cm \pm 0.5 cm

2 A0G-100982

Low Pitch: 7 ° \pm 0.2 ° TCI: 72 Month

3 A0G-100983

High Pitch: 27 ° \pm 1 ° TBO: 2400 Hrs.

4 _____

Feathering: / ° \pm / °

5 _____

Reverse: / ° \pm / °

6 _____

at radius station: 74 cm