

OWNER: GEORGIA CROWN DISTRIBUTING CO.		OPERATOR: GEORGIA CROWN DISTRIBUTING CO.	
ADDRESS: LAGRANGE CALLAWAY AIRPORT LAGRANGE GA 30240		ADDRESS: LAGRANGE CALLAWAY AIRPORT LAGRANGE GA 30240	
OFFICE: 706-322-0086		OFFICE: 706-322-0086	
FAX: 706-322-9583		FAX: 706-322-9583	
ANALYST: ERIC FOSTER	1-866-581-2267 (OFFICE)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL: EFOSTER@CAMPSYSTEMS.COM	316-462-2442 (FAX)	631-980-4222 (EFAX-CARDS)	
	WWW.CAMPSYSTEMS.COM		

AIRCRAFT	SERIAL/REGNO: 45-496/N877W	MODEL: LEARJET 75	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 22-NOV-2014		LAST ACTUALS:	
		3288.3 A/C HRS	as of 01-APR-2022
		3291 AFL	as of 01-APR-2022
		1248 APH	as of 01-APR-2022
		3625 APS	as of 01-APR-2022
APU	SERIAL/PART: P-534/3800726-1	MODEL: RE100 (CIMMS)	MANUFACTURER: HONEYWELL
INSTALLED ON: 18-APR-2014		LAST ACTUALS:	
0 APU HRS 0 A/C HRS		1248 APU HRS	as of 01-APR-2022
0 APUS		3625 APUS	as of 01-APR-2022
ENGINE NO. 1	SERIAL/PART: P-137179/3062075-1	MODEL: TFE731-40BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 06-FEB-2018		LAST ACTUALS:	
1427.9 ENG. HRS 1461 A/C HRS		3255.2 ENG. HRS	as of 01-APR-2022
1360 ENC		3263 ENC	as of 01-APR-2022
ENGINE NO. 2	SERIAL/PART: P-137180/3062075-1	MODEL: TFE731-40BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 26-JUL-2017		LAST ACTUALS:	
1193.3 ENG. HRS 1242.7 A/C HRS		3238.9 ENG. HRS	as of 01-APR-2022
1157 ENC		3247 ENC	as of 01-APR-2022

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA GENERAL										
14CFR PART 47 ^U	PERFORM RECURRENT AIRCRAFT REGISTRATION									Service ATA:--
	MOS	22-Aug-20	36		31-Aug-23		262 d			
	HRS	2532.1								
	AFL	2481								
ATA 00 - INFORMATION										
CA75-160608	REVIEW LEARJET 75 EINSPECTOR REVISION 08JUN2016									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
	PROC. REF: RCF CA75									
CA75-161207	REVIEW LEARJET 75 EINSPECTOR REVISION 2016.12.07									Service ATA:00
	MOS/MSC	14-Dec-16	-					REQUIREMENT CHANGE FORMS		
	HRS	976.5								
	AFL	971								
	PROC. REF: RCF CA75									
CA75-170110	REVIEW LEARJET 75 EINSPECTOR REVISION 2017.01.10									Service ATA:00
	MOS/MSC	15-Feb-17	-					REQUIREMENT CHANGE FORMS		
	HRS	1048								
	AFL	1028								
	PROC. REF: RCF CA75									
CA75-181109	REVIEW LEARJET 75 EINSPECTOR REVISION 2018.11.09									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
	PROC. REF: RCF CA75									
CA75-190429	REVIEW LEARJET 75 EINSPECTOR REV 2019.04.29									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
	PROC. REF: RCF CA75									

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF EC04-180802										
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF EC04-180802										
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
0000001	12 MONTH SERVICING CHECKS									Package ATA:05
	MOS	15-Nov-21	12 (+14d/-14d)	Adj -2d	13-Nov-22	27-Nov-22	OVD			
	HRS	3074.4								
	AFL	3067								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:1
0000002	36 MONTH ZONAL INSPECTIONS									Package ATA:05
	MOS	13-Feb-20	36 (+14d/-14d)		13-Feb-23	27-Feb-23	63 d (+14)			
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:2
0000003	72 MONTH ZONAL INSPECTIONS									Package ATA:05
	MOS	13-Feb-20	72 (+14d/-14d)		13-Feb-26	27-Feb-26	1159 d (+14)			
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:3
0000004	108 MONTH ZONAL INSPECTIONS									Package ATA:05
	MOS	22-Nov-14	108 (+14d/-14d)		22-Nov-23	06-Dec-23	345 d (+14)			
	HRS	0								
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
0000005	600 HOUR / 36 MONTH INSPECTIONS									Package ATA:05
	MOS	07-Sep-21	36 (+14d/-14d)		07-Sep-24	21-Sep-24	635 d (+14)			
	HRS	2985.7	600 (+25/-25)	Adj -43.6	3542.1	3567.1	253.8 (+25)			
	AFL	2970								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:5
0000006	1,200 HOUR / 72 MONTH INSPECTIONS									Package ATA:05
	MOS	13-Feb-20	72 (+14d/-14d)		13-Feb-26	27-Feb-26	1159 d (+14)			
	HRS	2342.1	1200 (+25/-25)		3542.1	3567.1	253.8 (+25)			
	AFL	2277								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:6
0000007	2,400 HOUR / 108 MONTH INSPECTIONS									Package ATA:05
	MOS	13-Feb-20	108 (+14d/-14d)		13-Feb-29	27-Feb-29	2255 d (+14)			
	HRS	2342.1	2400 (+25/-25)		4742.1	4767.1	1453.8 (+25)			
	AFL	2277								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:7
0000008	4800 HOUR INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	4800		4800		1511.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:8
0000009	10000 HOUR INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	10000		10000		6711.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:9
0000010	RVSM INSPECTIONS									Package ATA:05
	MOS	13-Jan-22	24 (+14d/-14d)		13-Jan-24	27-Jan-24	397 d (+14)			
	HRS	3155.3								
	AFL	3154								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:10
0000011	2400 HOUR - 4800 HOUR INITIAL INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	T:4800		4800		1511.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:11

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
0000012	2400 HOUR - 10000 HOUR INITIAL INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:12
0000013	4800 HOUR - 10000 HOUR INITIAL INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:13
0000014	6000 HOUR - 10000 HOUR INITIAL INSPECTIONS									Package ATA:05
	MOS	22-Nov-14								
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: EMP PACKAGES, EMP PACKAGES										PKG:14
050001 ^U	RENEW INSURANCE									Service ATA:05
			12		18-Aug-22					
	MOS	18-Aug-21					OVD	CUSTOMER OPERATIONS REQUIREMENT		
	HRS	2931.7								
	AFL	2924								
050002 ^U	US CUSTOMS BORDER OVERFLIGHT PERMIT RENEW									Service ATA:05
			24		15-Feb-23					
	MOS	15-Feb-21					65 d	CUSTOMER OPERATIONS REQUIREMENT		
	HRS	2685.7								
	AFL	2670								
050003 ^U	US CUSTOMS DECAL RENEW									Service ATA:05
			12		11-Jan-23					
	MOS	11-Jan-22					30 d	CUSTOMER OPERATIONS REQUIREMENT		
	HRS	3149.6								
	AFL	3148								
050004 ^U	SMS IMPLEMENTATION RENEW									Service ATA:05
			12		28-Jun-22					
	MOS	28-Jun-21					OVD			
	HRS	2849.4								
	AFL	2847								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	18-Jan-22								
	HRS	3125.3	150 (+100)		(3275.3) 3308.4	3375.3	20.1 (+100)			
	ENC	3131								
PROC. REF: LMM 72-00-00										
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	18-Jan-22								
	HRS	3109	150 (+100)		(3259) 3308.4	3359	20.1 (+100)			
	ENC	3115								
PROC. REF: LMM 72-00-00										
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS/MSC	08-Feb-14	N/A							
	HRS	0								
	ENC	0								
PROC. REF: LMM 72-00-00										
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS/MSC	13-Feb-14	N/A							
	HRS	0								
	ENC	0								
PROC. REF: LMM 72-00-00										
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	27-Mar-22								
	HRS	3252.7	600 (+50/-100)		(3852.7) 3885.8	3902.7	597.5 (+50)			
	ENC	3259								
PROC. REF: LMM 72-00-00										
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	04-Jun-21								
	HRS	2799	600 (+50/-100)		(3399) 3448.4	3449	160.1 (+50)			
	ENC	2799								
PROC. REF: LMM 72-00-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	26-Oct-21								
	HRS	3019.1	800 (+50/-300)		(3819.1) 3852.2	3869.1	563.9 (+50)			
	ENC	3007								
PROC. REF: LMM 72-00-00										
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	04-Jun-21								
	HRS	2799	800 (+50/-300)		(3599) 3648.4	3649	360.1 (+50)			
	ENC	2799								
PROC. REF: LMM 72-00-00										
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	19-Feb-21								
	HRS	2658.1	1200 (+100/-200)		(3858.1) 3891.2	3958.1	602.9 (+100)			
	ENC	2646								
PROC. REF: LMM 72-00-00										
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	13-Feb-20								
	HRS	2292.7	1200 (+100/-200)		(3492.7) 3542.1	3592.7	253.8 (+100)			
	ENC	2233								
PROC. REF: LMM 72-00-00										
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	26-Oct-21								
	HRS	3019.1	1600 (+50/-100)		(4619.1) 4652.2	4669.1	1363.9 (+50)			
	ENC	3007								
PROC. REF: LMM 72-00-00										
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS									Package ATA:05
	MOS	04-Jun-21								
	HRS	2799	1600 (+50/-100)		(4399) 4448.4	4449	1160.1 (+50)			
	ENC	2799								
PROC. REF: LMM 72-00-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 11 - PLACARDS AND MARKINGS										
1130000 ^S		CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS.							Service	ATA:11
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 11-30-00										PKG:6
ATA 12 - SERVICING										
1210002 ^S		CHECK FLAP ACTUATORS - CHECK OIL LEVEL.							Service	ATA:12
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 12-21-03										PKG:5
1210003 ^S		LUBRICATE FLAP ACTUATOR BALLNUT							Service	ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-03										PKG:1
1210004 ^S		LUBRICATE FLAP FLEXIBLE DRIVE SHAFTS - HAND LUBRICATE.							Service	ATA:12
	MOS	22-Nov-14								
	HRS	0	4800 ^S (+25/-25)							
	AFL	0								
PROC. REF: AMM 12-21-03										PKG:8
1210005 ^S		LUBRICATE NOSE LANDING GEAR TRUNNION PIN							Service	ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210006 ^S		LUBRICATE NOSE LANDING GEAR ACTUATOR ATTACH FITTING							Service	ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210009 ^S		LUBRICATE NOSE GEAR DOOR HINGE							Service	ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
1210011 ^S		LUBRICATE MAIN LANDING GEAR ACTUATOR JOINTS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210012 ^S		LUBRICATE MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210013 ^S		LUBRICATE MAIN LANDING GEAR TORQUE LINKS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210014 ^S		LUBRICATE MAIN LANDING GEAR DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210016 ^S		LUBRICATE PASSENGER/CREW DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210017 ^S		LUBRICATE PASSENGER/CREW DOOR PINS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210018 ^S		LUBRICATE PASSENGER/CREW DOOR TENSION BOLTS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
1210019 ^S		LUBRICATE EMERGENCY EXIT DOOR LATCHING MECHANISM								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210020 ^S		LUBRICATE EMERGENCY EXIT DOOR PINS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210021 ^S		LUBRICATE BAGGAGE COMPARTMENT DOOR LATCH PINS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210022 ^S		LUBRICATE BAGGAGE COMPARTMENT DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210023 ^S		LUBRICATE OXYGEN SYSTEM SERVICING DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210024 ^S		LUBRICATE TOILET SERVICING DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210025 ^S		LUBRICATE PRESSURE REFUELING STATION DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
1210026 ^S		LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210027 ^S		LUBRICATE TAILCONE ACCESS DOOR PINS								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210028 ^S		LUBRICATE TAILCONE ACCESS DOOR HINGE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-02										PKG:1
1210029 ^S		LUBRICATE MAIN LANDING GEAR TRUNNION PIN								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210060 ^S		MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE								Service ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
1210061 ^S		NOSE GEAR SHOCK STRUT - SERVICE								Service ATA:12
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 12-10-02										PKG:5
1210062 ^S		MAIN GEAR SHOCK STRUT - SERVICE								Service ATA:12
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 12-10-03										PKG:5

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
1221037 ^S		LUBRICATE ROLLING SURFACES OF MAIN AND NOSE FLAP ROLLER TRACKS							Service	ATA:12
	MOS/MSC	15-Nov-21	N/A ^S							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-03										PKG:1
1221042 ^S		LUBRICATE HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS							Service	ATA:12
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 12-21-03										PKG:5
1227000 ^S		LUBRICATE EMERGENCY PARK BRAKE HANDLE SHAFT							Service	ATA:12
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-27-00										PKG:1
ATA 21 - AIR CONDITIONING										
212001		LH CHECK VALVE							Component	ATA:21
PN:6621000000-043	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3290	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03										
212002		RH CHECK VALVE							Component	ATA:21
PN:6621000000-043	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3291	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-03										
212009		LEFT PLENUM ASSEMBLY CHECK VALVE							Component	ATA:21
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212009	RIGHT PLENUM ASSEMBLY CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-09										
2130000 ^S	INSPECT PRIMARY AND SECONDARY OUTFLOW VALVES								Service	ATA:21
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 21-30-01, AMM 21-30-02										PKG:6
2130001 ^S	REPLACE OUTFLOW VALVE AIR FILTER								Service	ATA:21
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 21-30-04										PKG:7
2130002 ^S	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:21
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 21-30-00										PKG:6
213001	LH EMERGENCY PRESSURIZATION VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1430	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-01										
213002	RH EMERGENCY PRESSURIZATION VALVE								Component	ATA:21
PN:3291224-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1433	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-01										
213003	CABIN PRESSURE CONTROLLER								Component	ATA:21
PN:6621300000-027	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:64-K0198	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
213031	PRIMARY OUTFLOW VALVE ASSY									Component ATA:21
PN:6621300000-019	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:73-A0681	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-01										
213032	SECONDARY OUTFLOW VALVE ASSY									Component ATA:21
PN:6621300000-021	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:81-C0413	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-02										
213055	ABSOLUTE BAROMETRIC PRESSURE SWITCH									Component ATA:21
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
213056	ABSOLUTE BAROMETRIC PRESSURE (OPTION) SWITCH									Component ATA:21
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
213110	CABIN PRESSURE CHECK VALVE									Component ATA:21
PN:130158-3-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:113-A1834	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-30-07										
2140001	TEST/CLEAN LEFT OZONE CONVERTER									Service ATA:21
PN:53A405-4	MOS	22-Nov-14								
SN:1770/3495	HRS	0	3600 (+25/-25)		3600	3625	311.7 (+25)			
	AFL	0								
PROC. REF: AMM 21-20-12										
2140001	TEST/CLEAN RIGHT OZONE CONVERTER									Service ATA:21
PN:53A405-4	MOS	22-Nov-14								
SN:17812/3507	HRS	0	3600 (+25/-25)		3600	3625	311.7 (+25)			
	AFL	0								
PROC. REF: AMM 21-20-12										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
2140002	LEFT OZONE CONVERTER								Component	ATA:21
PN:53A405-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1770/3495	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-12										
2140002	RIGHT OZONE CONVERTER								Component	ATA:21
PN:53A405-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:17812/3507	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-20-12										
2141001 ^S	VISUAL INSPECTION WATER SEPARATOR COALESCER BAG . CLEAN IF NECESSARY.								Service	ATA:21
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 21-50-03										PKG:1
2145000 ^S	VISUAL INSPECTION ECS PLENUM ASSEMBLY CHECK VALVES . VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.								Service	ATA:21
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 21-20-09										PKG:7
215001	ENVIRONMENTAL CONTROL UNIT								Component	ATA:21
PN:6621000000-089	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:793	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-01										
215003	WATER SEPARATOR ASSY								Component	ATA:21
PN:6621000000-031	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:756	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-50-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
2150054	PERFORM COMPRESSOR DRIVE MOTOR WEAR INSPECTION ON BRUSHES									Service ATA:21
PN:PN	MOS/MSC	04-Nov-15	-					NOT INSTALLED		
SN:NOT INSTALLED	HRS	442								
	AFL	439								
PROC. REF: GENERIC NO REF										
2150055	OVERHAUL COMPRESSOR DRIVE MOTOR									Service ATA:21
PN:PN	MOS/MSC	04-Nov-15	-					NOT INSTALLED		
SN:NOT INSTALLED	HRS	442								
	AFL	439								
PROC. REF: GENERIC NO REF										
2150056 ^S	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST									Service ATA:21
	MOS/MSC	07-Sep-21	N/A ^S							
	HRS	2985.7								
	AFL	2970								
PROC. REF: GENERIC NO REF										PKG:5
2150057 ^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST									Service ATA:21
	MOS/MSC	19-May-17	N/A ^S							
	HRS	1174								
	AFL	1140								
PROC. REF: GENERIC NO REF										PKG:6
2150059 ^S	CHECK AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK.									Service ATA:21
	MOS/MSC	19-May-17	N/A ^S							
	HRS	1174								
	AFL	1140								
PROC. REF: GENERIC NO REF										PKG:6
215102	COMPRESSOR DRIVE MOTOR									Component ATA:21
PN:PN	MOS/MSC	04-Nov-15	O/C							
SN:NOT INSTALLED	HRS	442								
	AFL	439								
PROC. REF: GENERIC NO REF										
2160008 ^S	INSPECT TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS.									Service ATA:21
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 21-60-11										PKG:5

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
216001	TEMPERATURE, ECS CONTROLLER									Component ATA:21
PN:6621000000-081	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1151830-01053	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-10										
216013	LH / CABIN TEMPERATURE CONTROL VALVE									Component ATA:21
PN:6621000000-047	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04, AMM 21-60-05										
216014	RH / COCKPIT TEMPERATURE CONTROL VALVE									Component ATA:21
PN:6621000000-047	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1433	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-04, AMM 21-60-05										
216025	TEMP SELECTOR									Component ATA:21
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-01										
216081	COCKPIT TEMPERATURE DUCT SENSOR									Component ATA:21
PN:6600423-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:627962-25970	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-07										
216084	CABIN TEMPERATURE DUCT SENSOR									Component ATA:21
PN:6600423-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:627962-25971	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-60-06										
ATA 22 - AUTO FLIGHT										
221002	ELEVATOR GSA 9000 SERVO ACTUATOR									Component ATA:22
PN:011-02213-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2JL005401	HRS	0		TSN 0						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-02										
2210030 ^S			TENSION CHECK PITCH SERVO CABLES							Service ATA:22
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 22-10-03										
PKG:6										
2210031 ^S			TENSION CHECK ROLL SERVO CABLES							Service ATA:22
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 22-10-05										
PKG:6										
2210032 ^S			TENSION CHECK YAW SERVO CABLES							Service ATA:22
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 22-10-07										
PKG:6										
2210034 ^S			** AUTOPILOT AUTOTRIM FUNCTION AND MISTRIM ANNUNCIATION - PERFORM FUNCTIONAL TEST							Service ATA:22
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 22-10-00										
PKG:5										
2210036 ^S			** RUDDER BOOST - PERFORM THE FLAP POSITION FAIL CONTROL COMPARISON MONITOR CHECK							Service ATA:22
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 22-50-00										
PKG:6										
2210037			** AUTOPILOT PITCH SERVO GEARBOX - REPLACE							Component ATA:22
PN:011-02214-10	MOS	22-Nov-14	240 (+14d/-14d)	TSN 0	22-Nov-34	06-Dec-34	4363 d (+14)	CMR**		
SN:2Q7005342	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
2210038	** AUTOPILOT ROLL SERVO GEARBOX - REPLACE									Component ATA:22
PN:011-02214-10	MOS	22-Nov-14	240 (+14d/-14d)	TSN 0	22-Nov-34	06-Dec-34	4363 d (+14)	CMR**		
SN:2Q7005349	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-05										
2210039	** AUTOPILOT YAW SERVO GEARBOX - REPLACE									Component ATA:22
PN:011-02214-11	MOS	22-Nov-14	240 (+14d/-14d)	TSN 0	22-Nov-34	06-Dec-34	4363 d (+14)	CMR**		
SN:2Q8005043	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-07										
221004	AILERON GSA 9000 SERVO ACTUATOR									Component ATA:22
PN:011-02213-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2JL005395	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-04										
221006	RUDDER GSA 9000 SERVO ACTUATOR									Component ATA:22
PN:011-02213-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2JL005400	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-06										
221008	PRIMARY AUTOPILOT TRIM, GTA 82 ADAPTER									Component ATA:22
PN:011-00960-20	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1A2000558	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-08										
221009	SECONDARY AUTOPILOT TRIM, GTA 82 ADAPTER									Component ATA:22
PN:011-00960-20	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1A2000585	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-08										
221040	GMC 7250 CONTROLLER									Component ATA:22
PN:011-02544-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:26E015062	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
221061	YAW (SM-205) SERVO ASSY									Component ATA:22
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-10-06										
ATA 23 - COMMUNICATIONS										
230001	UNILINK UL-701 TRANSCEIVER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
230002	CONFIGURATION (OPTION) MODULE									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
230003	CONFIGURATION MODULE									Component ATA:23
PN:P14126	MOS/MSC	22-Apr-15	O/C	TSN 0						
SN:1412614752	HRS	192.1		TSN 0						
	AFL	193		TSN 0						
PROC. REF: GENERIC NO REF										
230004	CONFIGURATION (ACID #) MODULE									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
230005	SWIFT BROADBAND CONFIGURATION MODULE SBU MODULE									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
230006	SWIFT BROADBAND CONFIGURATION MODULE SBU (SOFTWARE OPT) MODULE									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
2310000 ^S		** EMER COM SWITCH - PERFORM OPERATIONAL CHECK							Service	ATA:23
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 23-10-00										PKG:7
231001		GMA 36 (LH) AUDIO PANEL							Component	ATA:23
PN:011-01793-00	MOS/MSC	28-Oct-20	O/C							
SN:1HF006145	HRS	2598.8		TSN 2598.8						
	AFL	2555		TSN 2555						
PROC. REF: GENERIC NO REF										
231002		GMA 36 (RH) AUDIO PANEL							Component	ATA:23
PN:011-01793-00	MOS/MSC	28-Oct-20	O/C							
SN:1HF005517	HRS	2598.8		TSN 2598.8						
	AFL	2555		TSN 2555						
PROC. REF: GENERIC NO REF										
231003		CLEARANCE DELIVERY SYSTEM ASSEMBLY SWITCH PANEL							Component	ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231011		NO. 2 KPA 1052 (OPTION) POWER AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231012		NO. 1 KPA 1052 (OPTION) POWER AMPLIFIER							Component	ATA:23
PN:064-01072-0101	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:KPA1052-6739	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231030		KRX 1053 NO 1 (OPTION) HF RECEIVER							Component	ATA:23
PN:064-01073-0102	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:KRX1053-6984	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231031	KRX 1053 NO 2 (OPTION) HF RECEIVER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-01										
231032	VHF COMM (OPTION) ANTENNA ASSY									Component ATA:23
PN:VF10-347	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:6325	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-10-02										
231033	UPPER VHF ANTENNA ASSY									Component ATA:23
PN:DMC60-17-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:17484	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-02										
231034	LOWER VHF ANTENNA ASSY									Component ATA:23
PN:DMC60-17-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:17481	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-02										
231035	AFT AIR TO GROUND ANTENNA									Component ATA:23
PN:P12949	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:453394	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231036	FWD AIR TO GROUND ANTENNA									Component ATA:23
PN:P12949	MOS/MSC	09-Sep-15	O/C	TSN 0						
SN:479353	HRS	385.6		TSN 0						
	AFL	373		TSN 0						
PROC. REF: GENERIC NO REF										
231037	FWD WIFI ANTENNA									Component ATA:23
PN:P16917-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1691710376	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231038	MID WIFI ANTENNA									Component ATA:23
PN:P16917-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1691710356	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231039	AFT WIFI ANTENNA									Component ATA:23
PN:P16917-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1691710355	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231040	UCS 5000 SERVER									Component ATA:23
PN:P17000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1.7E+12	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
2312003 ^S	PERFORM VISUAL INSPECTION HF ANTENNA - CHECK FOR PROPER TENSION OF HF ANTENNA WIRE.									Service ATA:23
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 23-12-06										PKG:6
231202	KAC 1052 NO 1 (OPTION) ANTENNA COUPLER									Component ATA:23
PN:064-01074-0101	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:KAC 1052-6624	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-02										
231203	KAC 1052 NO 2 (OPTION) ANTENNA COUPLER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-02										
231300	AIR TO GROUND (ATG 5000) TRANSCEIVER									Component ATA:23
PN:P15864-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1586412226	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
231301	IRIDIUM TRANSCEIVER									Component ATA:23
PN:011-02268-01	MOS/MSC	11-Jan-22	O/C							
SN:2HU005106	HRS	3154								
	AFL	3153								
PROC. REF: AMM 23-13-01										
231303	VHF DATALINK RADIO, GDR 66 UNIT									Component ATA:23
PN:011-02303-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:222005159	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231330	FWD IRIDIUM ANTENNA									Component ATA:23
PN:C1490-1	MOS/MSC	31-Jan-22	O/C	TSN 0						
SN:674922	HRS	3183.8		TSN 0						
	AFL	3188		TSN 0						
PROC. REF: AMM 23-13-02										
231331	AFT IRIDIUM ANTENNA									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-13-02										
231501	LH AIRCELL CORDED SMART PHONE									Component ATA:23
PN:P17783-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:178310629	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
231502	RH AIRCELL CORDED SMART PHONE									Component ATA:23
PN:P17783-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1778310628	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
233005	AUDIO POWER AMPLIFIER									Component ATA:23
PN:APA3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:206	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233006	PASSENGER ADDRESS AMPLIFIER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-02										
233101	LH NO.1 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233102	LH NO.2 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233103	LH NO.3 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233104	LH NO.4 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233105	LH NO.5 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233106	LH NO.6 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233107	LH NO.7 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233108	LH NO.8 CABIN WINDOW PANEL (LAV)									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233109	RH NO.1 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233110	RH NO.2 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233111	RH NO.3 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233112	RH NO.4 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233113	RH NO.5 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233114	RH NO.6 CABIN (EMERGENCY EXIT DOOR) WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233115	RH NO.7 CABIN WINDOW PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233116	RH NO.8 CABIN WINDOW PANEL (LAV)									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
233117	SPEAKER KIT PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01										
233118	SPEAKER KIT PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01										
233119	SPEAKER KIT PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01										
233120	SPEAKER KIT PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
233121	SPEAKER KIT PANEL									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-30-01										
2360020	FUNCTIONAL TEST AIRCRAFT STATIC DISCHARGERS									Service ATA:23
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0								
PROC. REF: AMM 23-60-00										
236004	2 CHANNEL SATELLITE DIGITAL AUDIO RECEIVER									Component ATA:23
PN:XMR200-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:802000620	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
236005	2 CHANNEL SATELLITE DIGITAL AUDIO (ID# CHANNEL 1) RECEIVER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
236006	2 CHANNEL SATELLITE DIGITAL AUDIO (ID# CHANNEL 2) RECEIVER									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
236007	2-CHANNEL (OPTION) XM-RADIO INSTALLATION KIT									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
236010	XM WEATHER RADIO DATA PORT									Component ATA:23
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
2370000 ^S		FUNCTIONAL TEST COCKPIT VOICE RECORDER							Service	ATA:23
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 23-70-00										PKG:6
237001		COCKPIT VOICE (120 MIN) RECORDER							Component	ATA:23
PN:2100-1025-22	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:959734	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-01										
237005		MULTI AXIS INERTIA SWITCH							Component	ATA:23
PN:3LO-453/8	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:108682	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-05										
237019		SURFACE MOUNT, BLK MICROPHONE							Component	ATA:23
PN:S056-1048-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:993701	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
237031		CVR PREAMPLIFIER							Component	ATA:23
PN:S160-0030-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:899278	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-70-03										
239001 ^U		FCC PERMIT RENEW							Service	ATA:23
			120		09-Dec-24 ^M					
	MOS						728 d	CUSTOMER OPERATIONS REQUIREMENT		
	HRS									
	AFL									

ATA 24 - ELECTRICAL POWER

2420000		** LEFT ALTERNATOR - PERFORM BEARING REPLACEMENT							Service	ATA:24
PN:90278-2	MOS	28-Apr-21						CMR**		
SN:1028	HRS	2806	1200 (+25/-25)		4006	4031	717.7 (+25)			
	AFL	2792								
PROC. REF: AMM 24-20-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
2420000	** RIGHT ALTERNATOR - PERFORM BEARING REPLACEMENT									Service ATA:24
PN:90278-2	MOS	03-Aug-20						CMR**		
SN:1338	HRS	2493.2	1200 (+25/-25)	TAC 66.6	3626.6	3651.6	338.3 (+25)			
	AFL	2453		TAC 63						
PROC. REF: AMM 24-20-01										
242001	LH AC 5 KVA ALTERNATOR									Component ATA:24
PN:90278-2	MOS/MSC	28-Apr-21	O/C	TSO 0						
SN:1028	HRS	2806		TSO 0						
	AFL	2792		TSO 0						
PROC. REF: AMM 24-20-01										
242002	RH AC 5 KVA ALTERNATOR									Component ATA:24
PN:90278-2	MOS/MSC	03-Aug-20	O/C							
SN:1338	HRS	2493.2		TSO 66.6						
	AFL	2453		TSO 96						
PROC. REF: AMM 24-20-01										
242050	RC 25 AMP CIRCUIT AFT (OPTION) BREAKER									Component ATA:24
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242052	NO. 1 REMOTE CONTROL CIRCUIT BREAKER									Component ATA:24
PN:SM600BA35N1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:99192	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242054	NO. 2 REMOTE CONTROL CIRCUIT BREAKER									Component ATA:24
PN:SM600BA5N1	MOS/MSC	12-Oct-21	O/C	TSN 0						
SN:120966	HRS	3025.8		TSN 0						
	AFL	3012		TSN 0						
PROC. REF: GENERIC NO REF										
242055	RC 5 AMP REMOTE CIRCUITCB5035 (OPTION) BREAKER									Component ATA:24
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
242056	RC 35 AMP REMOTE CIRCUIT CB5036 (OPTION) BREAKER								Component	ATA:24
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242082	STATIC 1200 VA 115 VAC 60H INVERTER								Component	ATA:24
PN:PN	MOS/MSC	22-Nov-14	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
242083	STATIC 1200 VA 230 60H (OPTION) INVERTER								Component	ATA:24
PN:PN	MOS/MSC	22-Nov-14	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
2430003	OVERHAUL LH STARTER/GENERATOR								Service	ATA:24
PN:23280-075	MOS	13-Feb-20								
SN:P1291/CB	HRS	2342.1	1200 (+25/-25)		3542.1	3567.1	253.8 (+25)			
	AFL	2277								
PROC. REF: GENERIC NO REF										
2430003	OVERHAUL RH STARTER/GENERATOR								Service	ATA:24
PN:23280-075	MOS	13-Feb-20								
SN:P1267/CB	HRS	2342.1	1200 (+25/-25)		3542.1	3567.1	253.8 (+25)			
	AFL	2277								
PROC. REF: GENERIC NO REF										
243001	LH STARTER/GENERATOR								Component	ATA:24
PN:23280-075	MOS/MSC	13-Feb-20	O/C	TSO 0						
SN:P1291/CB	HRS	2342.1		TSO 0						
	AFL	2277		TSO 0						
PROC. REF: AMM 24-30-01										
243002	RH STARTER/GENERATOR								Component	ATA:24
PN:23280-075	MOS/MSC	13-Feb-20	O/C	TSO 0						
SN:P1267/CB	HRS	2342.1		TSO 0						
	AFL	2277		TSO 0						
PROC. REF: AMM 24-30-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243003	APU STARTER/GENERATOR								Component	ATA:24
PN:6608458-010	MOS/MSC	29-Nov-16	O/C	TSO 0						
SN:P1174	HRS	945.8		TSO 0						
	AFL	946		TSO 0						
PROC. REF: AMM 49-40-01										
243019	UPPER STARTING TURBINE LEAD ACID BATTERY								Component	ATA:24
PN:RG-380E/40L	MOS	17-Feb-21	48 (+1m/-1m)	TSN 0	17-Feb-25	17-Mar-25	798 d (+28)	LIFE LIMIT		
SN:41110654	HRS	2685.7		TSN 0						
	AFL	2670		TSN 0						
PROC. REF: AMM 24-31-06, CMM 24-30-71										
243020	LOWER STARTING TURBINE LEAD ACID BATTERY								Component	ATA:24
PN:RG-380E/40L	MOS	10-Jun-19	48 (+1m/-1m)	TSN 0	10-Jun-23	10-Jul-23	180 d (+30)	LIFE LIMIT		
SN:40943379	HRS	2080.7		TSN 0						
	AFL	1998		TSN 0						
PROC. REF: AMM 24-31-06, CMM 24-30-71										
2431003 ^S	** BATTERY TEMPERATURE CONTROL AND INDICATION - PERFORM INSPECTION CHECK								Service	ATA:24
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 24-31-01										PKG:7
2431066	CAPACITY CHECK EMERGENCY BATTERY								Service	ATA:24
PN:100-2692-02	DAYS	29-Mar-21	550 (+55/-55)		30-Sep-22	24-Nov-22	OVD			
SN:21048W0001	HRS	2736.2	4000 (+400/-400)		6736.2	7136.2	3447.9 (+400)			
	AFL	2722								
PROC. REF: CMM 24-30-17										
2431067	EMERGENCY BATTERY								Component	ATA:24
PN:100-2692-02	MOS/MSC	29-Mar-21	O/C	TSN 0						
SN:21048W0001	HRS	2736.2		TSN 0						
	AFL	2722		TSN 0						
PROC. REF: AMM 24-32-01										
2431068	CAPACITY CHECK LOWER STARTING TURBINE LEAD ACID BATTERY								Service	ATA:24
PN:RG-380E/40L	MOS	20-Jan-22	6 (+1m/-1m)		20-Jul-22	20-Aug-22	OVD			
SN:40943379	HRS	3164.4								
	AFL	3163								
PROC. REF: AMM 24-31-06, CMM 24-30-71										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
2431068	CAPACITY CHECK UPPER STARTING TURBINE LEAD ACID BATTERY									Service ATA:24
PN:RG-380E/40L	MOS	15-Feb-22	6 (+1m/-1m)	Adj 2d	17-Aug-22		17-Sep-22	OVD		
SN:41110654	HRS	3221.3								
	AFL	3211								
PROC. REF: AMM 24-31-06, CMM 24-30-71										
244001	IN-SEAT (COCKPIT) (OPTION) INVERTER POWER SUPPLY									Component ATA:24
PN:1215-20	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1755	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
244002	IN-SEAT (FWD CABIN) INVERTER POWER SUPPLY									Component ATA:24
PN:1215-20	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1492	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
244003	IN-SEAT (AFT CABIN) INVERTER POWER SUPPLY									Component ATA:24
PN:1215-20	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1756	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
244004	AUXILIARY CABIN OUTLET INVERTER (OPTION) POWER SUPPLY									Component ATA:24
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
2450001 ^S	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST									Service ATA:24
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 24-00-00										
										PKG:5
2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK									Service ATA:24
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 24-00-00										
										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
2450023 ^S	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK									Service ATA:24
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 24-00-00										PKG:5
2460001 ^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK.									Service ATA:24
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 24-60-00										PKG:6
246001	23B001 (LH FWD) POWER DISTRIBUTION PANEL									Component ATA:24
PN:650GC02Y03	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:680	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-02										
246002	23B001 (RH FWD) POWER DISTRIBUTION PANEL									Component ATA:24
PN:655GC02Y03	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:688	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-02										
246003	AFT POWER DISTRIBUTION (LH AFT) PANEL									Component ATA:24
PN:660GC02Y07	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:772	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-60-03										
246004	AFT POWER DISTRIBUTION (RH AFT) PANEL									Component ATA:24
PN:665GC02Y07	MOS/MSC	01-Apr-18	O/C							
SN:330	HRS	1520.3								
	AFL	1442								
PROC. REF: AMM 24-60-03										
ATA 25 - EQUIPMENT/FURNISHINGS										
2510001 ^S	VISUAL INSPECTION CREW SEATS AND SEAT BELTS									Service ATA:25
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 25-10-50										PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
2510003	HYDROSTATIC TEST CABIN FIRE EXTINGUISHER									Service ATA:25
PN:C352TS	MOS	22-Nov-14	144 (+14d/-14d)		22-Nov-26	06-Dec-26	1441 d (+14)			
SN:Y-547559	HRS	0								
	AFL	0								
PROC. REF: AMM 26-23-00										
2510003	HYDROSTATIC TEST COPILOT FIRE EXTINGUISHER									Service ATA:25
PN:A344T	MOS	22-Nov-14	144 (+14d/-14d)		22-Nov-26	06-Dec-26	1441 d (+14)			
SN:Y-688538	HRS	0								
	AFL	0								
PROC. REF: AMM 26-23-00										
2510003	HYDROSTATIC TEST PILOT FIRE EXTINGUISHER									Service ATA:25
PN:A344T	MOS	22-Nov-14	144 (+14d/-14d)		22-Nov-26	06-Dec-26	1441 d (+14)			
SN:Y-214884	HRS	0								
	AFL	0								
PROC. REF: AMM 26-23-00										
251001	LH FLT DECK SIDEWALL PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-05										
251002	RH FLT DECK SIDEWALL PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-05										
251003	LH FLT DECK SIDEWALL PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-05										
251004	RH FLT DECK SIDEWALL PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251005	COVER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-40										
251007	FLT-DECK (LH) LWR SIDEWALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-10										
251008	FLT-DECK (RH) LWR SIDEWALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-10										
251009	PEDESTAL COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-03										
251011	LH FLT DECK									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251012	RH FLT DECK									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251013	LH FLT DECK TOP CAP									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251014	RH FLT DECK TOP CAP									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251101	LH FLT DECK WINDOW TRIM									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251102	RH FLT DECK WINDOW TRIM									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251201	FLT DECK CENTER POST									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-40										
251202	ENTRYWAY HEADLINER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-01										
251203	CABIN DOOR-UPPER PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251204	CABIN DOOR-UPPER COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251205	LIGHT HOUSING									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251206	BRKT-LIGHT HOUSING									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251207	CABIN HEADLINER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-01										
251303	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251304	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251305	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251306	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251307	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251308	OXYGEN LID COVER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251401	LH CABIN WINDOW PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
251403	RH FWD CABIN WINDOW PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
251405	RH AFT CABIN WINDOW PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
251407	LH FWD WINDOW CLOSEOUT PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
251409	ESC HATCH WINDOW PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251410	ESC HATCH ESCUTCHEON ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
251421	LH CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251422	LH CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251423	LH CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251424	LH CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251426	CABIN DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251427	CABIN DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251428	CABIN DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251429	CABIN DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251513	CABIN (LH) FWD CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251515	CABIN (LH) AFT CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251517	CABIN (RH) FWD CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251519	CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251520	CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251521	CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251522	CONVENIENCE PANEL POD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251523	CABIN (RH) AFT CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-05										
251531	CABIN TABLE (LEATHER) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251532	CABIN TABLE (VENEER) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251533	CABIN TABLE (VENEER) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251534	CABIN TABLE (VENEER) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251535	CABIN TABLE (VENEER W/INLAY) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251536	MID CABIN LH AIRCELL, USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251537	MID CABIN LH WIRELESS AIRCELL, USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251538	MID CABIN RH AIRCELL, 4.3-USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251539	MID CABIN RH WIRELESS AIRCELL, 4.3-USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251540	LH MID CABIN, BOX, USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251541	RH MID CABIN, BOX, 4.3 -HDMI (FWD) - USB (AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251542	LH FWD USB SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251543	RH FWD/LH AFT, USB SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251544	MID CABIN LH, USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251545	MID CABIN RH, 4.3-USB (FWD/AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251546	ESC HATCH SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251547	RH AFT SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251548	CABIN TABLE (VENEER) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251549	LH FWD USB-HDMI SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251550	RH FWD/LH AFT, HDMI SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251551	MID CABIN LH, HDMI (FWD) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251552	MID CABIN RH, 4.3-HDMI (FWD) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251553	MID CABIN LH, HDMI (AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251554	MID CABIN LH AIRCELL, HDMI (FWD) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251555	MID CABIN LH AIRCELL, HDMI (AFT) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251556	MID CABIN LH WIRELESS AIRCELL, HDMI (FWD) SIDELEDGE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251557	MID CABIN LH WIRELESS AIRCELL, HDMI (AFT) SIDELEDGE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251558	MID CABIN RH AIRCELL, 4.3 HDMI (FWD) SIDELEDGE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251559	MID CABIN RH WIRELESS AIRCELL, 4.3 HDMI (FWD) SIDELEDGE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251560	ESC HATCH (LEATHER) TABLE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251561	ESC HATCH (VENEER) TABLE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251562	ESC HATCH (VENEER W/INLAY) TABLE ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251601	COVER DOOR MECHANISM									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251602	ANGLE									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251603	BUMPER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251604	BUMPER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251611	IPOD DOCKING HARNESS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251612	IPOD AUTHENTICATION DONGLE									Component ATA:25
PN:IDS1116-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:136	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251613	AFT 12" LCD BULKHEAD MONITOR-									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251613	FWD 12" LCD BULKHEAD MONITOR-									Component ATA:25
PN:LCD1209-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:90	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251614	#1 15" LCD BULKHEAD MONITOR-									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251615	LOWER LH FWD LEARJET, 28 VDC RECT. EXIT SIGN									Component ATA:25
PN:LJ60-ELES-02	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:149493-14-2	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251615	RH AFT LEARJET, 28 VDC RECT. EXIT SIGN									Component ATA:25
PN:LJ60-ELES-02	MOS/MSC	30-Dec-15	O/C	TSN 0						
SN:164239-22-2	HRS	520.3		TSN 0						
	AFL	513		TSN 0						
PROC. REF: GENERIC NO REF										
251615	UPPER LH FWD LEARJET, 28 VDC RECT. EXIT SIGN									Component ATA:25
PN:LJ60-ELES-02	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:149193-14-6	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251616	BEZEL FOR MSP3009 1 BUTTON									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251617	BEZEL FOR MSP3009 5 BUTTON									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251618	BEZEL FOR SCW1010-001-000 RH SCROLL WHEEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251619	BEZEL FOR SCW1010-002-000 LH SCROLL WHEEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251631	MEMBRANE (DOOR/LIGHT) SWITCH PANEL									Component ATA:25
PN:MSP3009-101-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:75	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251632	MEMBRANE (LAVATORY) SWITCH PANEL									Component ATA:25
PN:MSP3009-501-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:64	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251633	CORE MODULE TWO (LH FWD) PCU									Component ATA:25
PN:PCS3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:426	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251634	CORE MODULE TWO (RH FWD) PCU									Component ATA:25
PN:PCS3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:431	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251635	CORE MODULE TWO (LH AFT) PCU									Component ATA:25
PN:PCS3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:432	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251636	CORE MODULE TWO (RH AFT) PCU									Component ATA:25
PN:PCS3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:433	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251637	4.3" PASSENGER CONTROL UNIT									Component ATA:25
PN:PSM2410-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251638	4.3" PASSENGER CONTROL UNIT									Component ATA:25
PN:PSM2410-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251639	4.3" PASSENGER CONTROL UNIT									Component ATA:25
PN:PSM2410-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:404	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251640	REMOTE MAINTENANCE UNIT									Component ATA:25
PN:RMU3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:106	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251651	LH SCROLL WHEEL									Component ATA:25
PN:SCW1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:300	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251652	LH SCROLL WHEEL									Component ATA:25
PN:SCW1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:290	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251653	LH SCROLL WHEEL									Component ATA:25
PN:SCW1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:301	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251654	LH SCROLL WHEEL									Component ATA:25
PN:SCW1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:303	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251655	RH SCROLL WHEEL									Component ATA:25
PN:SCW1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:291	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251656	RH SCROLL WHEEL									Component ATA:25
PN:SCW1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:289	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251657	RH SCROLL WHEEL									Component ATA:25
PN:SCW1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:290	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251658	RH SCROLL WHEEL									Component ATA:25
PN:SCW1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:292	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251901	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:405	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251902	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:403	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251903	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:404	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251904	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:399	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251905	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:397	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251906	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:398	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251907	HEADPHONE-USB JACK									Component ATA:25
PN:ADT1810-001-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:400	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251908	HEADPHONE-USB-HDMI JACK									Component ATA:25
PN:ADT1810-003-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:123	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
251909	ETHERNET-USB JACK									Component ATA:25
PN:ADT1810-005-000	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:146	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
2520000 ^S	VISUAL INSPECTION PASSENGER SEAT AND SEAT BELTS									Service ATA:25
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF										
										PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252003	ASHTRAY ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252004	ASHTRAY ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252005	FLT DECK CUP HOLDER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252006	FLT DECK CUP HOLDER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252007	FLT DECK CUP HOLDER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252008	FLT DECK CUP HOLDER									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252011	(POS 1) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140603-110	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252012	(POS 2) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-113	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252013	(POS 3) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-109	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252014	(POS 4) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-116	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252015	(POS 5) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-111	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252016	(POS 6) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-114	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252017	(POS 7) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-112	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252018	(POS 8) PASSENGER SEAT ASSY									Component ATA:25
PN:4525204033-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:140630-115	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-45										
252090	AC OUTLET UNIT WITH WHITE (LAV) LED									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252091	AC OUTLET UNIT WITH WHITE (LH FWD) LED									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252092	AC OUTLET UNIT WITH WHITE (RH FWD) LED									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252093	AC OUTLET UNIT WITH WHITE (LH AFT) LED									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252094	AC OUTLET UNIT WITH WHITE (RH AFT) LED									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252101	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252102	RH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252103	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252104	RH WINDOW SHADE ASSY									Component ATA:25
PN:GA4525204019-06	MOS/MSC	18-Mar-16	O/C	TSN 0						
SN:UNKNOWN	HRS	633.1		TSN 0						
	AFL	616		TSN 0						
PROC. REF: AMM 25-20-15										
252105	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252106	RH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252107	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252108	RH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252109	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252110	RH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252111	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252112	RH WINDOW SHADE ASSY									Component ATA:25
PN:ATG57F001-A301	MOS/MSC	04-Jan-22	O/C	TSN 86						
SN:10180-106	HRS	3144.3		TSN 3144.3, TSR 0						
	AFL	3142		TSN 3142, TSR 0						
PROC. REF: AMM 25-20-15										
252113	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252114	RH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										
252115	LH WINDOW SHADE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-20-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252116	ESC HATCH WINDOW SHADE ASSY								Component	ATA:25
PN:ATG57F002-A301	MOS/MSC	30-Nov-21	O/C	TSN 84						
SN:10180-501	HRS	3099		TSN 3099						
	AFL	3093		TSN 3093						
PROC. REF: AMM 25-20-15										
252210	BLU-RAY DISC PLAYER								Component	ATA:25
PN:BDP3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:128	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252215	SEAT DISPLAY CONNECTION BRACKET								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252216	SEAT DISPLAY CONNECTION BRACKET								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252217	SEAT DISPLAY CONNECTION BRACKET								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252221	LH 7" SEAT TOUCH DISPLAY								Component	ATA:25
PN:DIS1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:206	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252222	RH 7" SEAT TOUCH DISPLAY									Component ATA:25
PN:DIS1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:197	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252223	LH 7" SEAT TOUCH DISPLAY									Component ATA:25
PN:DIS1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:207	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252224	RH 7" SEAT TOUCH DISPLAY									Component ATA:25
PN:DIS1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:199	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252225	LH 7" SEAT TOUCH DISPLAY									Component ATA:25
PN:DIS1010-002-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:211	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252226	RH 7" SEAT TOUCH DISPLAY									Component ATA:25
PN:DIS1010-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:200	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252303	LH FWD HDMI (M70) SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252341	AFT ETHERNET DECODER UNIT									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252341	FWD ETHERNET DECODER UNIT									Component ATA:25
PN:EDU3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:398	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252342	FWD ETHERNET ENCODER UNIT									Component ATA:25
PN:EEU0910-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:272	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252343	ETHERNET INTERFACE UNIT									Component ATA:25
PN:EIU3009-001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:298	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252401	LH FLT DECK HEADLINER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252402	RH FLT DECK HEADLINER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252601	EXT RANGE O2 CLOSE OUT ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252701	LAV FLOOR CLOSEOUT ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252703	FLOOR CLOSEOUT PANEL									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252801	LH LAV CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-15										
252802	RH LAV CONVENIENCE PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-15										
252803	LAV DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-15										
252804	LAV DOWNWASH LIGHT LENS									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-15										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
252901	LH AFT WALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252903	RH AFT WALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252905	CENTER AFT WALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
252907	UPPER AFT WALL PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253042	WAVEJET MICROWAVE OVEN									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253101	FWD STORAGE (LH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253105	FWD STORAGE (LH) (W/GALLEY REST) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253203	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253207	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253209	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253211	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253213	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253215	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253217	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253219	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253221	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253223	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253225	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253227	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253229	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253231	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253233	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253235	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253237	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253239	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253241	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253243	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253245	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253247	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253249	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253251	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253253	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253255	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253257	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253259	FWD GALLEY (RH) CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253261	FWD GALLEY (RH) CABINET ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253263	FWD GALLEY (RH) CABINET ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-30-05										
253301	TABLE STORAGE (LEATHER) CABINET ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253303	TABLE STORAGE (VENEER) CABINET ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253305	TABLE STORAGE (VENEER W/INLAY) CABINET ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
253701	LH LAV WINDOW PANEL ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-20										
253702	RH LAV WINDOW PANEL ASSY								Component	ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-20										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
253801	TOILET SHROUD ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-35										
253901	LH LAV SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-26										
253913	RH LAV SIDELEDGE ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-26										
253915	LH LAV DADO PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-25										
253917	RH FWD LAV DADO PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-25										
253919	RH AFT LAV DADO PANEL ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-25										
254001	LAV HEADLINER ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-10										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
254002	LAV VANITY ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-40										
254003	LAV W/O SINK VANITY ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-40										
254004	LAV VANITY ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-40										
254007	LH AFT PARTITION ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-01										
254009	RH AFT PARTITION ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-01										
254011	LH AFT (W/MONITOR) PARTITION ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-40-01										
254101	LAV									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
254111	LAV SHELF ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
254112	FIRST AID KIT CABINET ASSY									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
255001	PILOT CONTROL WHEEL LIGHTED CHART HOLDER									Component ATA:25
PN:10-62EH-W01C	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:164	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
255002	CO-PILOT CONTROL WHEEL LIGHTED CHART HOLDER									Component ATA:25
PN:10-62EH-W01C	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:163	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
2560000	CLEAN CVR BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY.									Service ATA:25
	MOS	08-Dec-20	24 (+14d/-14d)	Adj -16d	22-Nov-22	06-Dec-22	OVD			
	HRS	2621.9								
	AFL	2592								
PROC. REF: AMM 25-61-01										
2560000	CLEAN FDR BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY.									Service ATA:25
	MOS/MSC	16-Nov-16	N/A	Adj 6d				N/A EQUIPMENT NOT INSTALLED		
	HRS	922.3								
	AFL	930								
PROC. REF: AMM 25-61-01										
256001	PILOT SEAT ASSY									Component ATA:25
PN:0820-0-L-1P00P1131	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:331	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-50										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256002	CO-PILOT SEAT ASSY									Component ATA:25
PN:0820-0-R-1P00P1131	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:343	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-10-50										
256004 ^U	REPLACE CREW COCKPIT FLASHLIGHT BATTERIES									Service ATA:25
	MOS	14-Mar-22	6 (+30d/-30d)		14-Sep-22	14-Oct-22	OVD	CUSTOMER CODE		
	HRS	3269.1								
	AFL	3262								
256061	PILOT LIFE VEST									Component ATA:25
PN:63600-501	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5268685	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256062	CO-PILOT LIFE VEST									Component ATA:25
PN:63600-501	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5268689	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256063	NO. 1 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278671	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256064	NO. 2 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278676	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256065	NO. 3 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278678	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256066	NO. 4 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278678	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256067	NO. 5 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278673	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256068	NO. 6 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278664	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256069	NO. 7 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d			
SN:L5278664	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256070	NO. 8 LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278672	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256071	LAV LIFE VEST									Component ATA:25
PN:63600-101	MOS	21-Sep-21	120	TSN 0	21-Sep-31		3205 d	OVERHAUL		
SN:L5278675	HRS	2999.3		TSN 0						
	AFL	2984		TSN 0						
PROC. REF: AMM 25-60-01										
256076	FIRST AID KIT									Component ATA:25
PN:AAMK RX	MOS/MSC	14-Sep-21	DUE		30-Sep-22 ^M		OVD	VENDOR RECOMMENDATION		
SN:070120001	HRS	2985.7								
	AFL	2970								
Expiry Date: : 30-Sep-22 PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
2561001 ^{U S}			INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERIES. PERFORM FUNCTIONAL TEST OF ELT SYSTEM IN ACCORDANCE WITH FAR 91.207 (IF INSTALLED)						Service	ATA:25
	MOS	15-Nov-21	12 ^S							
	HRS	3074.4								
	AFL	3067								
										PKG:1
2561002			INSPECT CO-PILOT LIFE VEST						Service	ATA:25
PN:63600-501	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5268689	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002			INSPECT LAV LIFE VEST						Service	ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278675	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002			INSPECT NO. 1 LIFE VEST						Service	ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278671	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002			INSPECT NO. 2 LIFE VEST						Service	ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278676	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002			INSPECT NO. 3 LIFE VEST						Service	ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278678	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002			INSPECT NO. 4 LIFE VEST						Service	ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278678	HRS									
	AFL									
PROC. REF: AMM 25-60-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
2561002	INSPECT NO. 5 LIFE VEST									Service ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278673	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002	INSPECT NO. 6 LIFE VEST									Service ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278664	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002	INSPECT NO. 7 LIFE VEST									Service ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278664	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002	INSPECT NO. 8 LIFE VEST									Service ATA:25
PN:63600-101	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5278672	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
2561002	INSPECT PILOT LIFE VEST									Service ATA:25
PN:63600-501	MOS	21-Sep-21	12		21-Sep-22		OVD			
SN:L5268685	HRS									
	AFL									
PROC. REF: AMM 25-60-01										
256101	CVR ACCOUSTIC UNDERWATER BEACON									Component ATA:25
PN:DK120	MOS/MSC	08-Dec-20	O/C	TSN 0						
SN:NT54558	HRS	2621.9		TSN 0						
	AFL	2592		TSN 0						
PROC. REF: AMM 25-61-01										
256101	FDR ACCOUSTIC UNDERWATER BEACON									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-61-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256109	C406-N ELT									Component ATA:25
PN:453-5060	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:15148	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-01										
256109A	FUNCTIONAL CHECK C406-N ELT									Service ATA:25
PN:453-5060	MOS/MSC	22-Nov-14	N/A							
SN:15148	HRS	0								
	AFL	0								
PROC. REF: AMM 25-62-01, FAR 91.207										
256109B	INSPECT C406-N ELT									Service ATA:25
PN:453-5060	MOS	15-Nov-21	12		15-Nov-22		OVD			
SN:15148	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF, FAR 91.207										
256115	ELT 406 ANTENNA BLADE									Component ATA:25
PN:110-340	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:451158	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-03										
256201	ELT BATTERY									Component ATA:25
PN:452-0133	MOS/MSC	04-Sep-19	DUE	TSN 0	04-Sep-24 ^M		632 d			
SN:382125-023	HRS	2192.2		TSN 0						
	AFL	2111		TSN 0						
PROC. REF: GENERIC NO REF, FAR 91.207										
2566001	REPLACE CVR ULB BATTERY.									Service ATA:25
	MOS	08-Dec-20	72 (+14d/-14d)	Adj -16d	22-Nov-26	06-Dec-26	1441 d (+14)			
	HRS	2621.9								
	AFL	2592								
PROC. REF: AMM 25-61-01										
2566001	REPLACE FDR ULB BATTERY.									Service ATA:25
	MOS/MSC	22-Nov-14	N/A					N/A EQUIPMENT NOT INSTALLED		
	HRS	0								
	AFL	0								
PROC. REF: AMM 25-61-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
259001 ^U	FUNCTIONAL CHECK CABIN ENTERTAINMENT SYSTEM									Service ATA:25
	MOS	01-Apr-22	3		01-Jul-22		OVD	CUSTOMER CODE		
	HRS	3288.3								
	AFL	3291								
259002 ^U	FUNCTIONAL CHECK CABIN SEATS									Service ATA:25
	MOS	01-Apr-22	3		01-Jul-22		OVD	CUSTOMER CODE		
	HRS	3288.3								
	AFL	3291								
259003 ^U	FUNCTIONAL CHECK LAVATORY TO INCLUDE TOILET AND FAUCET									Service ATA:25
	MOS	01-Apr-22	3		01-Jul-22		OVD	CUSTOMER CODE		
	HRS	3288.3								
	AFL	3291								
259072	DEFIBRILLATOR (AED)									Component ATA:25
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
259072A ^U	DEFIBRILLATOR (AED) BATTERY									Component ATA:25
PN:PAD-PAK-07	MOS/MSC	31-Jul-18	O/C		01-Oct-22 ^M		OVD	CUSTOMER CODE		
SN:DS143-107	HRS	1684.8								
	AFL	1599								
ATA 26 - FIRE PROTECTION										
2610001	VISUAL INSPECTION LEFT ENGINE HOT SECTION FIRE DETECTOR ELEMENT									Service ATA:26
	MOS	06-Feb-18								
	HRS	1461	3500 (+100/-100)		4961	5061	1672.7 (+100)			
	AFL	1388								
PROC. REF: GENERIC NO REF										
2610001	VISUAL INSPECTION RIGHT ENGINE HOT SECTION FIRE DETECTOR ELEMENT									Service ATA:26
	MOS	26-Jul-17								
	HRS	1242.7	3500 (+100/-100)		4742.7	4842.7	1454.4 (+100)			
	AFL	1201								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
261057	FIRE DETECT CONTROL (NO 1) UNIT									Component ATA:26
PN:877-01032	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1344-424	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01										
261058	FIRE DETECT CONTROL (NO 2) UNIT									Component ATA:26
PN:877-01032	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1419-431	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01										
261069	ANTI-ICE LEAK DETECT (LH BLEED AIR) UNIT									Component ATA:26
PN:6626100000-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3045	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-12-01										
261070	ANTI-ICE LEAK DETECT (RH BLEED AIR) UNIT									Component ATA:26
PN:6626100000-003	MOS/MSC	20-Jul-15	O/C							
SN:3044	HRS	293.9		TSN 293.9						
	AFL	300		TSN 300						
PROC. REF: AMM 26-12-01										
261071	ANTI-ICE LEAK DETECT UNIT									Component ATA:26
PN:6626100000-003	MOS/MSC	03-Aug-15	O/C							
SN:2941	HRS	293.9		TSN 293.9						
	AFL	300		TSN 300						
PROC. REF: AMM 26-12-01										
261075	FIRE/OVERHEAT DETECTOR									Component ATA:26
PN:10-1093	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:13-0472	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-13-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
2620000 ^S		** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST								Service ATA:26
	MOS	22-Nov-14						CMR**		
	HRS	0	4800 ^S (+25/-25)							
	AFL	0								
PROC. REF: AMM 26-21-00										PKG:8
2620001 ^S		** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK								Service ATA:26
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 26-21-00										PKG:7
2620006	HYDROSTATIC TEST NO. 1									Service ATA:26
PN:33100021-1	MOS	01-May-19	60 (+14d/-14d)		01-May-24	15-May-24	506 d (+14)			
SN:69989B1	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
2620006	HYDROSTATIC TEST NO. 2									Service ATA:26
PN:33100021-1	MOS	01-May-19	60 (+14d/-14d)		01-May-24	15-May-24	506 d (+14)			
SN:67824B1	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
2620007	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB									Component ATA:26
PN:30903856	MOS	13-May-19	120 (+14d/-14d)	TSN 1	13-Apr-29	27-Apr-29	2314 d (+14)	SERVICE LIFE LIMIT		
SN:4079WJ	HRS	2056.8		TSN 0						
	AFL	1961		TSN 0						
PROC. REF: AMM 26-21-02										
2620007	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB									Component ATA:26
PN:30903859	MOS	13-May-19	120 (+14d/-14d)	TSN 1	13-Apr-29	27-Apr-29	2314 d (+14)	SERVICE LIFE LIMIT		
SN:4317WK	HRS	2056.8		TSN 0						
	AFL	1961		TSN 0						
PROC. REF: AMM 26-21-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
2620007	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB								Component	ATA:26
PN:30903856	MOS	13-May-19	120 (+14d/-14d)	TSN 1	13-Apr-29	27-Apr-29	2314 d (+14)	SERVICE LIFE LIMIT		
SN:1671RD	HRS	2056.8		TSN 0						
	AFL	1961		TSN 0						
PROC. REF: AMM 26-21-02										
2620007	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB								Component	ATA:26
PN:30903859	MOS	13-May-19	120 (+14d/-14d)	TSN 1	13-Apr-29	27-Apr-29	2314 d (+14)	SERVICE LIFE LIMIT		
SN:4319WK	HRS	2056.8		TSN 0						
	AFL	1961		TSN 0						
PROC. REF: AMM 26-21-02										
2620009 ^S	INSPECT CABIN FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.								Service	ATA:26
PN:C352TS	MOS	15-Nov-21	12 ^S (+14d/-14d)							
SN:Y-547559	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 26-23-00										PKG:1
2620009 ^S	INSPECT COPILOT FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.								Service	ATA:26
PN:A344T	MOS	15-Nov-21	12 ^S (+14d/-14d)							
SN:Y-688538	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 26-23-00										PKG:1
2620009 ^S	INSPECT PILOT FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.								Service	ATA:26
PN:A344T	MOS	15-Nov-21	12 ^S (+14d/-14d)							
SN:Y-214884	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 26-23-00										PKG:1
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33100021-1	MOS/MSC	13-May-19	O/C	TSN 67, TSO 0						
SN:69989B1	HRS	2056.8		TSO 0						
	AFL	1961		TSO 0						
PROC. REF: AMM 26-21-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:33100021-1	MOS/MSC	13-May-19	O/C	TSN 81, TSO 0						
SN:67824B1	HRS	2056.8	TSO 0							
	AFL	1961	TSO 0							
PROC. REF: AMM 26-21-01										
2620021 ^S	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION								Service	ATA:26
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF										
2620021 ^S	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION								Service	ATA:26
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF										
2620046 ^S	VISUAL INSPECTION NO. 1 ENGINE FIRE EXTINGUISHER DISCHARGE LINES								Service	ATA:26
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										
2620046 ^S	VISUAL INSPECTION NO. 2 ENGINE FIRE EXTINGUISHER DISCHARGE LINES								Service	ATA:26
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										
262040	WARNING HORN								Component	ATA:26
PN:430-M1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:865	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 26-13-02										
262041	PILOT FIRE EXTINGUISHER								Component	ATA:26
PN:A344T	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:Y-214884	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
262042	COPILOT FIRE EXTINGUISHER								Component	ATA:26
PN:A344T	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:Y-688538	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
262051	CABIN FIRE EXTINGUISHER								Component	ATA:26
PN:C352TS	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:Y-547559	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-22-01										
262075	APU FIRE EXTINGUISHER CONTAINER								Component	ATA:26
PN:51600-2	MOS/MSC	29-Mar-21	O/C	TSO 0						
SN:0328	HRS	2736.2		TSO 0						
	AFL	2722		TSO 0						
PROC. REF: AMM 26-22-01										
ATA 27 - FLIGHT CONTROLS										
2700000 ^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700001 ^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700002 ^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
2700003 ^S		VISUAL INSPECTION AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING.							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700004 ^S		VISUAL INSPECTION RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES.							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700005 ^S		VISUAL INSPECTION ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES.							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700006 ^S		VISUAL INSPECTION RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION.							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-00-00										PKG:6
2700007 ^S		* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8
2700008 ^S		* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
2700009 ^S		* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8
2700010 ^S		* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (AFT FUSELAGE).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8
2700012 ^S		* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (AFT FUSELAGE).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8
2700014 ^S		* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (WING).							Service	ATA:27
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: AMM 27-00-00										PKG:8
2710003 ^S		TENSION CHECK AILERON CONTROL SYSTEM CABLES (LOCATED IN WING)							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-10-00										PKG:6
2710004 ^S		TENSION CHECK AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE)							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-10-00										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271045	LH INBOARD AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103077-013	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J38415	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271046	RH INBOARD AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103076-017	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J45200	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271051	LH OUTBOARD UPPER AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103078-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J46335	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271052	RH OUTBOARD UPPER AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103078-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J46335	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271053	LH OUTBOARD LOWER AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103079-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J45420	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										
271054	RH OUTBOARD LOWER AILERON CONTROL CABLE ASSY								Component	ATA:27
PN:4527103079-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:J45420	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
2711001 ^S		** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-10-04										PKG:5
2712000 ^S		** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK							Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-60-09										PKG:5
2720003 ^S		TENSION CHECK RUDDER CONTROL CABLES							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-20-00										PKG:6
2720004 ^S		VISUAL INSPECTION RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS . CHECK DURING FULL TRAVEL OF RUDDER.							Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:6
2720030		VISUAL INSPECTION RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION.							Service	ATA:27
	MOS	13-Feb-20	72 (+14d/-14d)		13-Feb-26	27-Feb-26	1159 d (+14)			
	HRS	2342.1								
	AFL	2277								
PROC. REF: AMM 27-20-01										
272021		RUDDER TRIM TAB ACTUATOR ASSY							Component	ATA:27
PN:6627108000-003	MOS/MS	22-Nov-14	O/C	TSN 0						
SN:710	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272022	AILERON TRIM TAB ACTUATOR ASSY								Component	ATA:27
PN:6627108000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:715	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-09										
272031	LH LINEAR-RUDDER PEDAL ADJUST ACTUATOR								Component	ATA:27
PN:6627208001-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1501	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
272032	RH LINEAR-RUDDER PEDAL ADJUST ACTUATOR								Component	ATA:27
PN:6627208001-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1503	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-05										
2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-20-00										
										PKG:5
2730003 ^S	TENSION CHECK ELEVATOR CONTROL CABLES								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-30-00										
										PKG:6
273003	LH ELEVATOR CONTROL SYS PUSHROD								Component	ATA:27
PN:6627300101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:22707207-0021	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273004	RH ELEVATOR CONTROL SYS PUSHROD									Component ATA:27
PN:6627300101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2207207-0022	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273005	LH ELEVATOR CONTROL SYS PUSHROD									Component ATA:27
PN:6627300101-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2197177-0072	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273006	RH ELEVATOR CONTROL SYS PUSHROD									Component ATA:27
PN:6627300101-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2197177-0073	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
273063	LH ACTUATOR STICK SHAKER									Component ATA:27
PN:0050R	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2723	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										
273064	RH ACTUATOR STICK SHAKER									Component ATA:27
PN:0050R	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2728	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03										
273075	LH ANGLE OF ATTACK TRANSMITTER									Component ATA:27
PN:6627308500-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:156228-03	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273076	RH ANGLE OF ATTACK TRANSMITTER								Component	ATA:27
PN:6627308500-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:157146A-02	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01										
2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR								Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-30-14										PKG:5
2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-30-00										PKG:5
273101	LH STATIC (A20)(A21) INVERTER								Component	ATA:27
PN:SC3(A)	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:846	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-05										
273102	RH STATIC (A20)(A21) INVERTER								Component	ATA:27
PN:SC3(A)	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:845	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-05										
273201	ELEVATOR DISCONNECT CURRENT LIMITER								Component	ATA:27
PN:EM2154-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:845	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-13										
273220	ELEVATOR AFT DISCONNECT ACTUATOR								Component	ATA:27
PN:6627300103-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:686	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-09										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
273420	ELEVATOR OVERRIDE ACTUATOR ASSY								Component	ATA:27
PN:778D100-11	MOS/MSC	13-Feb-20	O/C							
SN:1016	HRS	2342.1								
	AFL	2277								
PROC. REF: AMM 27-30-14										
2740003 ^S	** SECONDARY PITCH TRIM SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-40-00, AMM 27-40-02										PKG:6
2740004 ^S	** PRIMARY PITCH TRIM SYSTEM - PERFORM FUNCTIONAL TEST								Service	ATA:27
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 27-40-00, AMM 27-40-02										PKG:6
2740032	HORIZONTAL STABILIZER ACTUATOR ASSY * HORIZONTAL STABILIZER ACTUATOR (6627401000-009) - PERFORM INSPECTION								Service	ATA:27
PN:6627401000-009	MOS	13-Feb-20						CMR*		
SN:B0364	HRS	2342.1	1200		3542.1		253.8			
	AFL	2277								
PROC. REF: AMM 27-40-02										
2740033	HORIZONTAL STABILIZER ACTUATOR ASSY * HORIZONTAL STABILIZER ACTUATOR (6627401000-009) - PERFORM DETAILED STRUCTURAL INSPECTION								Service	ATA:27
PN:6627401000-009	MOS	13-Feb-20						CMR*		
SN:B0364	HRS	2342.1	2400		4742.1		1453.8			
	AFL	2277								
PROC. REF: AMM 27-40-02										
274011	HORIZONTAL STABILIZER ACTUATOR ASSY								Component	ATA:27
PN:6627401000-009	MOS/MSC	13-Feb-20	O/C	TSO 0						
SN:B0364	HRS	2342.1		TSN 6301.8, TSO 0						
	AFL	2277		TSO 0						
PROC. REF: AMM 27-40-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
274051	HORIZ STAB ACTUATOR CONTROL BOX ASSY									Component ATA:27
PN:6627401000-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:705	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-03										
275001	FLAP CONTROL (J7) MODULE									Component ATA:27
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-02										
275020	LH OUTBD FLAP DRIVE ACTUATOR									Component ATA:27
PN:6627503000-033	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2364	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06										
275021	LH INBD FLAP DRIVE ACTUATOR									Component ATA:27
PN:6627503000-031	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2363	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06										
275022	RH FLAP DRIVE, INBD ACTUATOR									Component ATA:27
PN:6627503000-031	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2366	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06										
275023	RH FLAP DRIVE, OTBD ACTUATOR									Component ATA:27
PN:6627503000-033	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2346	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-06										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275057	FPU, FLAP POWER UNIT								Component	ATA:27
PN:6627503000-029	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1590	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-08										
275058	FLAP CONTROL UNIT FCU								Component	ATA:27
PN:C144486-3-003	MOS/MSC	08-Jan-18	O/C							
SN:1572	HRS	1447.7								
	AFL	1369								
PROC. REF: AMM 27-50-05										
275069	FLAP POSITION INDICATION UNIT								Component	ATA:27
PN:C145159-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1775	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-07										
275081	LH ROTARY VAR DIFF TRANSFORMER								Component	ATA:27
PN:6627503000-019	MOS/MSC	11-Mar-15	O/C	TSN 0						
SN:A1444	HRS	142.4		TSN 0						
	AFL	138		TSN 0						
PROC. REF: AMM 27-50-03										
275082	RH ROTARY VAR DIFF TRANSFORMER								Component	ATA:27
PN:6627503000-019	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A1456	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-03										
2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK								Service	ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-60-04										
										PKG:5

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
2760002 ^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK									Service ATA:27
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 27-60-00										PKG:5
276001	RH SPOILERON ACTUATOR ASSY									Component ATA:27
PN:6627602001-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:AAA511P455	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-04										
276002	LH SPOILERON ACTUATOR ASSY									Component ATA:27
PN:6627602001-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:AAA493P455	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-04										
2760021	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE									Service ATA:27
	MOS	28-Sep-21								
	HRS	3012.7	1200 (+25/-25)	Adj -40	4172.7	4197.7	884.4 (+25)			
	AFL	2997								
PROC. REF: GENERIC NO REF										
2760021	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE									Service ATA:27
	MOS	28-Sep-21								
	HRS	3012.7	1200 (+25/-25)	Adj -40	4172.7	4197.7	884.4 (+25)			
	AFL	2997								
PROC. REF: GENERIC NO REF										
2760021	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE									Service ATA:27
	MOS	28-Sep-21								
	HRS	3012.7	1200 (+25/-25)	Adj -40	4172.7	4197.7	884.4 (+25)			
	AFL	2997								
PROC. REF: GENERIC NO REF										
2760021	RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE									Service ATA:27
	MOS	28-Sep-21								
	HRS	3012.7	1200 (+25/-25)	Adj -40	4172.7	4197.7	884.4 (+25)			
	AFL	2997								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276013	SPOILER SHUT-OFF VALVE ASSY									Component ATA:27
PN:6627602002-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:0392TK	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-07										
276031	LH ROTARY VAR DIFF, SPOILER TRANSFORMER									Component ATA:27
PN:3A2-249A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A1355	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-05										
276032	RH ROTARY VAR DIFF, SPOILER TRANSFORMER									Component ATA:27
PN:3A2-249A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A1328	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-05										
276073	SPOILERON COMPUTER									Component ATA:27
PN:6627608500-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1027	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-02										
276076	ROTARY VAR DIFF CTL WHEEL TRANSFORMER									Component ATA:27
PN:3G4-211A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:0697/1413	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-06										
ATA 28 - FUEL										
281001	LH BAY 1 FWD EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140335	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281002	RH BAY 1 EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140343	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281003	LH BAY 2 FWD EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140318	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281004	RH BAY 2 FWD EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140339	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281005	LH BAY 3 EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:9140452	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281006	RH BAY 3 EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140338	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281007	LH BAY 2 AFT EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140334	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281008	RH BAY 2 AFT EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140340	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281009	LH BAY 9 EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:8140271	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281010	RH BAY 9 EJECTOR SCAVENGE PUMP									Component ATA:28
PN:6628200302-001V0685	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16140336	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-01										
281051	LH MOTIVE FLOW CHECK VALVE									Component ATA:28
PN:6628200106-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:18146241	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
281052	RH MOTIVE FLOW CHECK VALVE									Component ATA:28
PN:6628200106-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:19145129	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-05										
281102	FUSELAGE FUEL CELL BAG TANK									Component ATA:28
PN:6628120103-007	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:T002194	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-10-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281521	LH CHECK, FUEL TRANSFER VALVE									Component ATA:28
PN:7628200104-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:8145873	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										
281522	RH CHECK, FUEL TRANSFER VALVE									Component ATA:28
PN:7628200104-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:8145876	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03										
2820000 ^S	INSPECT LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.									Service ATA:28
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:6
282011	SHUTOFF, REFUEL VALVE									Component ATA:28
PN:6628200102-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:15146821	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-10										
282031	CHECK, FUEL SUPPLY (LH) NO 1 VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:49135135	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282032	CHECK, FUEL SUPPLY (LH) NO 2 VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3145099	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282033	CHECK, FUEL SUPPLY (RH) NO 1 VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:49133146	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282034	CHECK, FUEL SUPPLY (RH) NO 2 VALVE									Component ATA:28
PN:7628200101-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:49135149	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-03										
282037	SHUTOFF, FUEL SUPPLY (LH NO 1) VALVE ASSY									Component ATA:28
PN:6628200101-003	MOS/MSC	31-Jan-22	O/C	TSO 0						
SN:2143	HRS	3183.8		TSO 0						
	AFL	3188		TSO 0						
PROC. REF: AMM 28-20-06										
282038	SHUTOFF, FUEL SUPPLY (LH NO 2) VALVE ASSY									Component ATA:28
PN:6628200101-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2190	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06										
282039	SHUTOFF, FUEL SUPPLY (CTR) VALVE ASSY									Component ATA:28
PN:6628200101-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2435	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06										
282040	RH SHUTOFF, FUEL SUPPLY VALVE ASSY									Component ATA:28
PN:6628200101-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2461	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-06										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282041	CONTROL, REFUELING PANEL ASSY									Component ATA:28
PN:4528408000V5-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:13101175BA	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-14										
282063	1/4" PRE CHECK VALVE									Component ATA:28
PN:HTE940032-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:13140868	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-12										
282064	PILOT VALVE									Component ATA:28
PN:61087-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:699	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-11										
282075	LH MAIN EJECTOR PUMP									Component ATA:28
PN:6628200301-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:14140862	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-01										
282076	RH MAIN EJECTOR PUMP									Component ATA:28
PN:6628200301-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:14140876	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-01										
282087	LH STANDBY PUMP ASSY									Component ATA:28
PN:6628200303-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:5BK34	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282088	RH STANDBY PUMP ASSY								Component	ATA:28
PN:6628200303-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:5BK35	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-02										
282815	SHUTOFF, APU FUEL VALVE								Component	ATA:28
PN:7086048-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1115028101159C	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-20-04										
2840003 ^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS								Service	ATA:28
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 28-40-00										PKG:6
284001	LH FUEL (C1) PROBE ASSY								Component	ATA:28
PN:6628408000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33252	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284002	LH FUEL (C2) PROBE ASSY								Component	ATA:28
PN:6628408000-027	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN32919	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284003	LH FUEL (C3) PROBE ASSY								Component	ATA:28
PN:6628408000-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33245	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284004	LH FUEL (C4) PROBE ASSY									Component ATA:28
PN:6628408000-007	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33258	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284005	LH FUEL (C5) PROBE ASSY									Component ATA:28
PN:6628408000-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33327	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284006	LH FUEL (C15) PROBE ASSY									Component ATA:28
PN:6628408000-021	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33377	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284008	RH FUEL (C8) PROBE ASSY									Component ATA:28
PN:6628408000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33255	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284009	RH FUEL (C9) PROBE ASSY									Component ATA:28
PN:6628408000-027	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN32925	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284010	RH FUEL (C10) PROBE ASSY									Component ATA:28
PN:6628408000-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33245	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284011	RH FUEL (C11) PROBE ASSY									Component ATA:28
PN:6628408000-007	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33585	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284012	RH FUEL (C12) PROBE ASSY									Component ATA:28
PN:6628408000-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33531	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284013	RH FUEL (C17) PROBE ASSY									Component ATA:28
PN:6628408000-021	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33466	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284014	RH FUEL (C13) PROBE ASSY									Component ATA:28
PN:6628408000-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33577	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284015	LH FUEL (C14) PROBE ASSY									Component ATA:28
PN:6628408000-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33574	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284016	RH FUEL (C16) PROBE ASSY									Component ATA:28
PN:6628408000-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33580	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284017	LH FUEL (C6) PROBE ASSY								Component	ATA:28
PN:6628408000-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MN33579	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284033	FUSELAGE FUEL (C7) PROBE ASSY								Component	ATA:28
PN:6628408000-019	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:DTR 2963	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-40-05										
284104	FUEL QUANTITY SIGNAL CONDITIONER								Component	ATA:28
PN:6628408000-023	MOS/MSC	05-Feb-16	O/C	TSR 4						
SN:0797	HRS			TSR 0						
	AFL			TSR 0						
PROC. REF: AMM 28-40-04										
ATA 29 - HYDRAULIC POWER										
2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS								Service	ATA:29
	MOS	13-Feb-20								
	HRS	2342.1	2400 (+25/-25)		4742.1	4767.1	1453.8 (+25)			
	AFL	2277								
PROC. REF: AMM 29-20-02										
2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS								Service	ATA:29
	MOS	14-Mar-22								
	HRS	3269.1	300 (+25/-25)	Adj -27	3542.1	3567.1	253.8 (+25)			
	AFL	3262								
PROC. REF: AMM 29-10-03										
291002	HYDRAULIC MAIN FILTER (A74) MANIFOLD								Component	ATA:29
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
2910026 ^S		FUNCTIONAL TEST RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE							Service	ATA:29
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
						PROC. REF: AMM 29-10-06			PKG:6	
291033		RESERVOIR PRESSURIZATION CONTROL MODULE							Component	ATA:29
PN:6629001002-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:14-040366	HRS	0		TSN 0						
	AFL	0		TSN 0						
						PROC. REF: AMM 29-10-06				
291034		HYD RESERVOIR FLUID LEVEL SENSOR							Component	ATA:29
PN:3L14F-17	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:941	HRS	0		TSN 0						
	AFL	0		TSN 0						
						PROC. REF: AMM 29-30-02				
291045		LH ENGINE DRIVEN HYDRAULIC PUMP ASSY							Component	ATA:29
PN:6629101000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MX780308A	HRS	0		TSN 0						
	AFL	0		TSN 0						
						PROC. REF: AMM 29-10-01				
291046		RH ENGINE DRIVEN HYDRAULIC PUMP ASSY							Component	ATA:29
PN:6629101000-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:MX780309A	HRS	0		TSN 0						
	AFL	0		TSN 0						
						PROC. REF: AMM 29-10-01				
291057		MAIN HYD PRESSURE ACCUMULATOR							Component	ATA:29
PN:88746-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:666	HRS	0		TSN 0						
	AFL	0		TSN 0						
						PROC. REF: AMM 29-10-04				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291069	THERMAL SHUTOFF VALVE								Component	ATA:29
PN:7629101001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:983	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-10-07										
292011	AUXILIARY HYDRAULIC PUMP ASSY								Component	ATA:29
PN:6629201000-013	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:K0729	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-20-01										
292012 ^U	AUXILIARY HYDRAULIC PUMP MOTOR								Component	ATA:29
PN:6629201000-011	MOS/MSC	22-Mar-18	O/C	TSO 0						
SN:113A	HRS	1512		TSO 0						
	AFL	1433		TSO 0						
293001	CONTROL BOX ASSY								Component	ATA:29
PN:4529308000-013	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:595903	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-01										
293011	HYDRAULIC PRESSURE TRANSDUCER								Component	ATA:29
PN:APTE-196-1000-4000A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:8126-7-184	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04										
293012	HYDRAULIC PRESSURE TRANSDUCER								Component	ATA:29
PN:APTE-196-1000-4000A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:8158-7-94	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-30-04										
ATA 30 - ICE AND RAIN PROTECTION										
3010000 ^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK								Service	ATA:30
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 30-10-00										PKG:5
3010006 ^S	** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION									Service ATA:30
	MOS	13-Feb-20	36 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	600 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 30-10-07										PKG:5
301006	VERTICAL STABILIZER ANTI ICE PANEL									Component ATA:30
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
301063	LEFT (L13) ANTI-ICE PRESSURE REGULATING AND SHUTOFF VALVE									Component ATA:30
PN:6621000000-087	MOS/MSC	16-Mar-20	O/C							
SN:585	HRS	2391.2								
	AFL	2308								
PROC. REF: AMM 30-10-01										
301064	RIGHT (L12) ANTI-ICE PRESSURE REGULATING AND SHUTOFF VALVE									Component ATA:30
PN:6621000000-087	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1527	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										
301065	LEFT (L17) NACELLE ANTI-ICE PRESSURE REGULATING AND SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										
301066	RIGHT (L42) NACELLE ANTI-ICE PRESSURE REGULATING AND SHUTOFF VALVE									Component ATA:30
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
3020000 ^S	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST									Service ATA:30
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 30-20-00										PKG:6
3020005	LEFT	* ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	01-Nov-21						CMR*		
	HRS	3063.2	250		3313.2		24.9			
	AFL	3051								
PROC. REF: GENERIC NO REF										
3020005	RIGHT	* ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	01-Nov-21						CMR*		
	HRS	3063.2	250		3313.2		24.9			
	AFL	3051								
PROC. REF: GENERIC NO REF										
3020006	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS								Service	ATA:30
	MOS/MSC	22-Nov-14	N/A					NOT APPLICABLE		
	HRS	0								
	AFL	0								
PROC. REF: AMM 30-20-00										
3020006	RIGHT	ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BOREScope INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	22-Nov-14	N/A					NOT APPLICABLE		
	HRS	0								
	AFL	0								
PROC. REF: AMM 30-20-00										
3030000 ^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK									Service ATA:30
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 30-30-00										PKG:7

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
3040000 ^S	** WINDSHIELD ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM								Service	ATA:30
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 30-40-00										PKG:5
304021	WINDSHIELD ANTI-ICE CONTROLLER								Component	ATA:30
PN:90825-9	MOS/MSC	08-Jun-20	O/C	TSO 0						
SN:405	HRS	2435.2		TSO 0						
	AFL	2372		TSO 0						
PROC. REF: AMM 30-40-01										
308005	ICE DETECTOR PROBE								Component	ATA:30
PN:0871HN2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:651	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-80-01										
ATA 31 - INDICATING/RECORDING SYSTEMS										
3100002 ^S	** ELECTRONIC FLIGHT INSTRUMENT SYSTEM - PERFORM OPERATIONAL CHECK								Service	ATA:31
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 31-60-00										PKG:7
313001	FLIGHT DATA RECORDER								Component	ATA:31
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-30-01										
313003	TRIAXIAL ACCELEROMETER								Component	ATA:31
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
313019	FDR INERTIA SWITCH									Component ATA:31
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-30-02										
314011	DATA CONCENTRATION, GSD 41 (#1) UNIT									Component ATA:31
PN:011-01457-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16906170	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03										
314012	DATA CONCENTRATION, GSD 41 (#2) UNIT									Component ATA:31
PN:011-01457-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:16906169	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03										
314023	LH INTEGRATED AV, NAV/COM GIA 63W UNIT									Component ATA:31
PN:011-01105-40	MOS/MSC	10-Mar-15	O/C							
SN:2DC001259	HRS	142.4		TSN 142.4						
	AFL	138		TSN 138						
PROC. REF: AMM 31-41-01										
314024	RH INTEGRATED AV, NAV/COM GIA 63W UNIT									Component ATA:31
PN:011-01105-40	MOS/MSC	20-Mar-15	O/C							
SN:2DC000559	HRS	148								
	AFL	143								
PROC. REF: AMM 31-41-01										
314051	I/O, ENGINE AND AIRFRAME, GEA71 (PILOT) UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	01-Sep-16	O/C							
SN:46718891	HRS	851.9		TSN 851.9						
	AFL	862		TSN 862						
PROC. REF: AMM 31-41-02										
314052	I/O, ENGINE AND AIRFRAME, GEA71 (CENTER RH) UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:46718889	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
314053	I/O, ENGINE AND AIRFRAME, GEA71 (CENTER LH) UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:46718888	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-02										
314054	I/O, ENGINE AND AIRFRAME, GEA71 (CO-PILOT) UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	01-Sep-16	O/C							
SN:46718892	HRS	851.9		TSN 851.9						
	AFL	862		TSN 862						
PROC. REF: AMM 31-41-02										
3151002 ^S	** AURAL WARNING - PERFORM INSPECTION CHECK									Service ATA:31
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 31-51-00										PKG:5
3151003 ^S	** TAKEOFF CONFIGURATION WARNING - PERFORM INSPECTION CHECK									Service ATA:31
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 31-51-00										PKG:5
316001	(PILOT) GDU 1400W COLOR W SCR N LDSCAPE DISPLAY									Component ATA:31
PN:011-01910-30	MOS/MSC	06-Dec-16	O/C							
SN:1F1300305	HRS	959.3								
	AFL	961								
PROC. REF: AMM 31-60-01										
316002	CO-PILOT GDU 1400W COLOR W SCR N LDSCAPE DISPLAY									Component ATA:31
PN:011-01910-30	MOS/MSC	18-Apr-17	O/C							
SN:1F1300344	HRS	1118.2		TSR 0						
	AFL	1077		TSR 0						
PROC. REF: AMM 31-60-01										
316003	(MFD) GDU 1400W COLOR W SCR N LDSCAPE DISPLAY									Component ATA:31
PN:011-01910-30	MOS/MSC	24-Feb-17	O/C							
SN:1F1305054	HRS	1074.3								
	AFL	1046								
PROC. REF: AMM 31-60-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
316005	LH TOUCHSCREEN, GTC 570 CONTROLLER									Component ATA:31
PN:011-01924-10	MOS/MSC	01-Aug-16	O/C							
SN:1MB501723	HRS	820.9		TSN 820.9						
	AFL	830		TSN 830						
PROC. REF: AMM 31-60-02										
316006	RH TOUCHSCREEN, GTC 570 CONTROLLER									Component ATA:31
PN:011-01924-10	MOS/MSC	07-Aug-16	O/C							
SN:1MB501712	HRS	820.9		TSN 820.9						
	AFL	830		TSN 830						
PROC. REF: AMM 31-60-02										
316007	LH BACKUP, GCU 275 CONTROLLER									Component ATA:31
PN:011-01983-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1U7105564	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-03										
316008	RH BACKUP, GCU 275 CONTROLLER									Component ATA:31
PN:011-01983-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1U7105570	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-60-03										
316091	AFIS DATA TRANSFER (OPTION) UNIT									Component ATA:31
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 32 - LANDING GEAR										
321001	LH MLG GEAR INSTALLATION									Component ATA:32
PN:4532101000V102-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3210015 ^S	CORROSION INSPECTION NOSE LANDING GEAR AND WHEEL WELL									Service ATA:32
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF										PKG:1
321002	RH MLG GEAR INSTALLATION									Component ATA:32
PN:4532101000V10 2-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321011	LH MLG SHOCK STRUT CYLINDER ASSY									Component ATA:32
PN:200-0201-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:H0852	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										
321012	RH MLG SHOCK STRUT CYLINDER ASSY									Component ATA:32
PN:200-0201-006	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:H0845	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										
321073	LH DISPLACEMENT MLG ACTUATOR TUBE									Component ATA:32
PN:200-0305-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:H1833	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321074	RH DISPLACEMENT MLG ACTUATOR TUBE									Component ATA:32
PN:200-0305-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:H1849	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
321085	LH FWD MLG TRUNNION ASSY									Component ATA:32
PN:4532103011- 011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:CMI 368	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321086	RH FWD MLG TRUNNION ASSY									Component ATA:32
PN:4532103011-012	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:CMI 364	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										
321087	LH AFT MLG TRUNNION ASSY									Component ATA:32
PN:4532103021-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:CMI 349	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										
321088	RH AFT MLG TRUNNION ASSY									Component ATA:32
PN:4532103021-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:CMI 487	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-10-01										
321301	LH OUTBD MLG DOOR ASSY									Component ATA:32
PN:4552803003-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										
321302	LH INBD MLG DOOR ASSY									Component ATA:32
PN:4552803004-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										
321303	RH INBD MLG DOOR ASSY									Component ATA:32
PN:4552803004-006	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321304	RH OUTBD MLG DOOR ASSY									Component ATA:32
PN:4552803003-004	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-80-01										
3220003	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW									Service ATA:32
	MOS	25-Jun-21								
	HRS	2849	600 (+25/-25)		3449	3474	160.7 (+25)			
	AFL	2844								
PROC. REF: GENERIC NO REF										
3220007	LEFT * MAIN LANDING GEAR AXLE - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (P/N 200-0203-001)									Service ATA:32
	MOS	29-Nov-18	48		29-Nov-22		OVD	CMR*		
	HRS	1850.3								
	AFL	1764								
PROC. REF: AMM 32-10-01										
3220007	RIGHT * MAIN LANDING GEAR AXLE - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (P/N 200-0203-001)									Service ATA:32
	MOS	29-Nov-18	48		29-Nov-22		OVD	CMR*		
	HRS	1850.3								
	AFL	1764								
PROC. REF: AMM 32-10-01										
3220009	* NOSE LANDING GEAR STRUT ASSEMBLY - REPLACE (CMR*)									Component ATA:32
PN:2342100-037	MOS	25-Jun-21		TSN 52				LIFE LIMIT		
SN:075	HRS	2849		TSN 1803.8						
	AFL	2844	20000	TSN 1817	21027		17736			
PROC. REF: AMM 32-20-01										
322001	NOSE GEAR STEERING AND STRUT ASSY									Component ATA:32
PN:2342003-112	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:42	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-20-01										
3220010	* NOSE LANDING GEAR ACTUATOR ASSEMBLY - REPLACE (CMR*)									Component ATA:32
PN:6632201000-005	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:TASV876	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		16709			
PROC. REF: AMM 32-32-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220011	* NOSE LANDING GEAR ACTUATOR UPPER PIN - REPLACE (CMR*)									Component ATA:32
PN:4532302043-007	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:891	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		16709			
PROC. REF: AMM 32-32-01										
3220012	LEFT * MAIN LANDING GEAR STRUT ASSEMBLY - REPLACE (CMR*)									Component ATA:32
PN:200-0200-013	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H1808	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220012	RIGHT * MAIN LANDING GEAR STRUT ASSEMBLY - REPLACE (CMR*)									Component ATA:32
PN:200-0200-014	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H1801	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220013	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR, EXCLUDING THE END CAP - REPLACE (CMR*)									Component ATA:32
PN:200-0300-005	MOS	13-Feb-20		TSN 63				LIFE LIMIT		
SN:H0709	HRS	2342.1		TSN 2342.1						
	AFL	2277	17000	TSN 2277	17000		13709			
PROC. REF: AMM 32-31-01										
3220013	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR, EXCLUDING THE END CAP - REPLACE (CMR*)									Component ATA:32
PN:200-0300-006	MOS	13-Feb-20		TSN 63				LIFE LIMIT		
SN:H1709	HRS	2342.1		TSN 2342.1						
	AFL	2277	17000	TSN 2277	17000		13709			
PROC. REF: AMM 32-31-01										
3220014	LEFT UPPER * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0325-101	MOS	22-Nov-14	96	TSN 0	22-Nov-22		OVD	LIFE LIMIT		
SN:H3181	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										
3220014	RIGHT UPPER * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0325-101	MOS	22-Nov-14	96	TSN 0	22-Nov-22		OVD	LIFE LIMIT		
SN:H3180	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220016	INSPECT NOSE LANDING GEAR STRUT ASSEMBLY - PERFORM SPECIAL DETAILED INSPECTION.									Service ATA:32
	MOS	25-Jun-21								
	HRS	2849								
	AFL	2844	10000 (+25/-25)		12844	12869	9553 (+25)			
PROC. REF: GENERIC NO REF										
3220017	VISUAL INSPECTION NOSE LANDING GEAR TRUNNION AXLE									Service ATA:32
	MOS	25-Jun-21								
	HRS	2849								
	AFL	2844	10000 (+25/-25)		12844	12869	9553 (+25)			
PROC. REF: GENERIC NO REF										
3220018	NDT INSPECT LMLG SPECIAL DETAILED INSPECTION ON SHOCK STRUT									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	6600 (+25/-25)		6600	6625	3309 (+25)			
PROC. REF: GENERIC NO REF										
3220018	NDT INSPECT RMLG SPECIAL DETAILED INSPECTION ON SHOCK STRUT									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	6600 (+25/-25)		6600	6625	3309 (+25)			
PROC. REF: GENERIC NO REF										
3220019	NDT INSPECT NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	22-Nov-14								
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: NDT PART 7 / 32-30-02										
322002	NOSE GEAR CYLINDER ASSY									Component ATA:32
PN:2342102-003	MOS/MSC	25-Jun-21	O/C	TSN 0						
SN:6419S25	HRS	2849		TSN 0						
	AFL	2844		TSN 0						
PROC. REF: AMM 32-20-01										
3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION									Service ATA:32
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	T:10000		10000		6709			
PROC. REF: NDT PART 6 / 32-11-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220022	NDT INSPECT LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: NDT PART 7 / 32-10-07, NDT PART 7 / 32-10-08										
3220022	NDT INSPECT LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: NDT PART 7 / 32-10-07, NDT PART 7 / 32-10-08										
3220022	NDT INSPECT RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: NDT PART 7 / 32-10-07, NDT PART 7 / 32-10-08										
3220022	NDT INSPECT RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: NDT PART 7 / 32-10-07, NDT PART 7 / 32-10-08										
3220023	LEFT AFT * MAIN LANDING GEAR TRUNNION PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0213-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C1385	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220023	LEFT FORWARD * MAIN LANDING GEAR TRUNNION PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0212-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C1414	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220023	RIGHT AFT * MAIN LANDING GEAR TRUNNION PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0213-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C1375	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220023	RIGHT FORWARD * MAIN LANDING GEAR TRUNNION PIN - REPLACE (CMR*)								Component	ATA:32
PN:200-0212-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C1605	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220024	LEFT LOWER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:32
PN:200-0217-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:CPS01C3565	HRS	1823.5								
	AFL	1738								
PROC. REF: NDT PART 7 / 32-30-01, NDT PART 7 / 32-10-02										
3220024	LEFT UPPER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:32
PN:200-0325-101	MOS	09-Nov-18	48		09-Nov-22		OVD	CMR*		
SN:H3181	HRS	1823.5								
	AFL	1738								
PROC. REF: NDT PART 7 / 32-30-01, NDT PART 7 / 32-10-02										
3220024	RIGHT LOWER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:32
PN:200-0217-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:CPS01C3552	HRS	1823.5								
	AFL	1738								
PROC. REF: NDT PART 7 / 32-30-01, NDT PART 7 / 32-10-02										
3220024	RIGHT UPPER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:32
PN:200-0325-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:H3180	HRS	1823.5								
	AFL	1738								
PROC. REF: NDT PART 7 / 32-30-01, NDT PART 7 / 32-10-02										
3220028	LEFT * NOSE LANDING GEAR TRUNNION PIN - REPLACE (CMR*)								Component	ATA:32
PN:2342108-003	MOS	25-Jun-21		TSN 0				LIFE LIMIT		
SN:MTI-949	HRS	2849		TSN 0						
	AFL	2844	20000	TSN 0	22844		19553			
PROC. REF: AMM 32-20-01										
3220028	RIGHT * NOSE LANDING GEAR TRUNNION PIN - REPLACE (CMR*)								Component	ATA:32
PN:2342108-003	MOS	25-Jun-21		TSN 0				LIFE LIMIT		
SN:MTI 946	HRS	2849		TSN 0						
	AFL	2844	20000	TSN 0	22844		19553			
PROC. REF: AMM 32-20-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220029	* NOSE LANDING GEAR TRUNNION AXLE - REPLACE (CMR*)									Component ATA:32
PN:2342110-003	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:1235	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		16709			
PROC. REF: AMM 32-20-01										
322003	NOSE LANDING GEAR PISTON									Component ATA:32
PN:2342104-003	MOS/MSC	25-Jun-21	O/C							
SN:N200	HRS	2849		TSR 0						
	AFL	2844		TSR 0						
PROC. REF: AMM 32-32-01										
3220035	LEFT * MAIN LANDING GEAR SHOCK STRUT PISTON - REPLACE (CMR*)									Component ATA:32
PN:200-0202-003	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H2169	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220035	RIGHT * MAIN LANDING GEAR SHOCK STRUT PISTON - REPLACE (CMR*)									Component ATA:32
PN:200-0202-003	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H2157	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220036	LEFT * MAIN LANDING GEAR AXLE BEAM - REPLACE (CMR*)									Component ATA:32
PN:200-0203-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H1599	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220036	RIGHT * MAIN LANDING GEAR AXLE BEAM - REPLACE (CMR*)									Component ATA:32
PN:200-0203-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H1572	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220037	LEFT * MAIN LANDING GEAR SHOCK STRUT LINK - REPLACE (CMR*)									Component ATA:32
PN:200-0204-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:PRE31C-1849	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220037	RIGHT * MAIN LANDING GEAR SHOCK STRUT LINK - REPLACE (CMR*)									Component ATA:32
PN:200-0204-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:PRE13C-1816	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220038	LEFT LOWER * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0217-101	MOS	22-Nov-14	96	TSN 0	22-Nov-22		OVD	LIFE LIMIT		
SN:CPS01C3565	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										
3220038	RIGHT LOWER * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0217-101	MOS	22-Nov-14	96	TSN 0	22-Nov-22		OVD	LIFE LIMIT		
SN:CPS01C3552	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										
322004	NOSE GEAR STEERING AND STRUT INSTL BRACKET									Component ATA:32
PN:2342111-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:R711	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-20-01										
322005	NOSE LANDING GEAR FORK									Component ATA:32
PN:2342116-004	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:R1025	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
3220101	LEFT AFT * MAIN LANDING GEAR LINK PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0214-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-3183	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220101	LEFT FORWARD * MAIN LANDING GEAR LINK PIN - REPLACE (CMR*)									Component ATA:32
PN:200-0214-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-3184	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220101	RIGHT AFT * MAIN LANDING GEAR LINK PIN - REPLACE (CMR*)								Component	ATA:32
PN:200-0214-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-3165	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220101	RIGHT FORWARD * MAIN LANDING GEAR LINK PIN - REPLACE (CMR*)								Component	ATA:32
PN:200-0214-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-3166	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220102	LEFT * MAIN LANDING GEAR PISTON PIN - REPLACE (CMR*)								Component	ATA:32
PN:200-0215-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-1591	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220102	RIGHT * MAIN LANDING GEAR PISTON PIN - REPLACE (CMR*)								Component	ATA:32
PN:200-0215-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CPS01C-1581	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220103	LEFT * MAIN LANDING GEAR ACTUATOR PISTON - REPLACE (CMR*)								Component	ATA:32
PN:200-0301-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:PRE31C-2417	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220103	RIGHT * MAIN LANDING GEAR ACTUATOR PISTON - REPLACE (CMR*)								Component	ATA:32
PN:200-0301-103	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:PRE13C-2373	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220104	LEFT * MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE (CMR*)								Component	ATA:32
PN:200-0302-101	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:PRE13C-1817	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220104	RIGHT * MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE (CMR*)									Component ATA:32
PN:200-0302-101	MOS	22-Nov-14		TSN 0				CMR*		
SN:PRE13C-1872	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220105	LEFT * MAIN LANDING GEAR ACTUATOR END CAP - REPLACE (CMR*)									Component ATA:32
PN:200-0072-001	MOS/MSC	13-Feb-20	N/A							
SN:PRE13C-0509	HRS	2342.1								
	AFL	2277		TSN 0						
PROC. REF: AMM 32-31-01										
3220105	RIGHT * MAIN LANDING GEAR ACTUATOR END CAP - REPLACE (CMR*)									Component ATA:32
PN:200-0072-101	MOS/MSC	13-Feb-20	N/A							
SN:PRE13C-0508	HRS	2342.1								
	AFL	2277		TSN 0						
PROC. REF: AMM 32-31-01										
3220106	LEFT * MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE (CMR*)									Component ATA:32
PN:200-0304-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H2213	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220106	RIGHT * MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE (CMR*)									Component ATA:32
PN:200-0304-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:H2189	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220109	VISUAL INSPECTION NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.									Service ATA:32
	MOS	22-Nov-14								
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: GENERIC NO REF										
3220111	VISUAL INSPECTION LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.									Service ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220111	VISUAL INSPECTION RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.								Service	ATA:32
	MOS	22-Nov-14	96 (+14d/-14d)		22-Nov-22	06-Dec-22	OVD			
	HRS	0								
	AFL	0	10000 (+25/-25)		10000	10025	6709 (+25)			
PROC. REF: GENERIC NO REF										
3220116	LEFT * MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE (CMR*)								Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220116	RIGHT * MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE (CMR*)								Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	10000	TSN 0	10000		6709			
PROC. REF: AMM 32-10-01										
3220126	LEFT * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING - REPLACE (CMR*)								Component	ATA:32
PN:4532103041-013	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:31813/4-0S	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		16709			
PROC. REF: AMM 32-31-01										
3220126	RIGHT * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING - REPLACE (CMR*)								Component	ATA:32
PN:4532103041-014	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:31812/S-08	HRS	0		TSN 0						
	AFL	0	20000	TSN 0	20000		16709			
PROC. REF: AMM 32-31-01										
3220135	LEFT LOWER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:32
PN:200-0217-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:CPS01C3565	HRS	1823.5								
	AFL	1738								
PROC. REF: GENERIC NO REF										
3220135	LEFT UPPER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION								Service	ATA:32
PN:200-0325-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:H3181	HRS	1823.5								
	AFL	1738								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220135	RIGHT LOWER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION									Service ATA:32
PN:200-0217-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:CPS01C3552	HRS	1823.5								
	AFL	1738								
PROC. REF: GENERIC NO REF										
3220135	RIGHT UPPER * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION									Service ATA:32
PN:200-0325-101	MOS	13-Nov-18	48		13-Nov-22		OVD	CMR*		
SN:H3180	HRS	1823.5								
	AFL	1738								
PROC. REF: GENERIC NO REF										
3220139	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103201-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 3083	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220139	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103201-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 3095	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220139	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103201-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 3104	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220139	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103201-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 3100	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220140	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103202-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 1636	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220140	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103202-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 1448	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220141	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103203-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 1198	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220141	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN (CMR*)									Component ATA:32
PN:4532103203-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:CMI 1448	HRS	0		TSN 0						
	AFL	0	5000	TSN 0	5000		1709			
PROC. REF: AMM 57-10-05										
3220146	LEFT * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE.									Service ATA:32
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	T:4800		4800		1509			
PROC. REF: NDT PART 4 / 32-10-01										
3220146	RIGHT * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE.									Service ATA:32
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	T:4800		4800		1509			
PROC. REF: NDT PART 4 / 32-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3220148 ^S		CORROSION INSPECTION MAIN LANDING GEAR AND WHEEL WELLS							Service	ATA:32
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: GENERIC NO REF										PKG:1
3220149		LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE (P/N 200-0300-005, -006) (CMR*)							Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220149		RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE (P/N 200-0300-005, -006) (CMR*)							Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	17000	TSN 0	17000		13709			
PROC. REF: AMM 32-31-01										
3220150		LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (P/N 200-0300-005, -006) (EASA ONLY) (CMR*)							Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	13700	TSN 0	13700		10409			
PROC. REF: AMM 32-31-01										
3220150		RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (P/N 200-0300-005, -006) (EASA ONLY) (CMR*)							Component	ATA:32
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	13700	TSN 0	13700		10409			
PROC. REF: AMM 32-31-01										
322095		LH NOSE GEAR DOOR ASSY							Component	ATA:32
PN:4552800001-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:666	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-81-01										
322096		RH NOSE GEAR DOOR ASSY							Component	ATA:32
PN:4552800002-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:665	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-81-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322098	AXLE								Component	ATA:32
PN:2342117-002	MOS/MSC	25-Jun-21	O/C							
SN:R816	HRS	2849								
	AFL	2844								
PROC. REF: GENERIC NO REF										
322121	NLG UPLOCK								Component	ATA:32
PN:2269H000-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1711	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-32-02										
3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST								Service	ATA:32
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 32-33-00										PKG:5
323001	LEFT MLG SIDE BRACE ACTUATOR ASSY								Component	ATA:32
PN:4532101000V82-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										
323002	RIGHT MLG SIDE BRACE ACTUATOR ASSY								Component	ATA:32
PN:4532101000V82-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01										
323037	MLG (LH) INBOARD DOOR UPLOCK								Component	ATA:32
PN:6632303004-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2406	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323038	MLG (RH) INBOARD DOOR UPLOCK									Component ATA:32
PN:6632303004-006	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2403	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-02										
3231024	* LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS - REPLACE									Service ATA:32
PN:6632303003-003	MOS	13-Feb-20						LIFE LIMIT		
SN:1323	HRS	2342.1	2400		4742.1		1453.8			
	AFL	2277								
PROC. REF: AMM 32-31-02										
3231024	* RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS - REPLACE									Service ATA:32
PN:6632303003-003	MOS	13-Feb-20						LIFE LIMIT		
SN:1307	HRS	2342.1	2400		4742.1		1453.8			
	AFL	2277								
PROC. REF: AMM 32-31-02										
323220	LH DOWN AND LOCK SWITCH									Component ATA:32
PN:604HE162	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2054	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-02										
323221	RH DOWN AND LOCK SWITCH									Component ATA:32
PN:604HE162	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2077	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-60-02										
323735	CONTROL, MANIFOLD, LANDING GEAR VALVE									Component ATA:32
PN:6632302001-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1689	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-30-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
3240004 ^S		** EMERGENCY/PARKING BRAKE POSITION INDICATING SWITCH - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 32-42-01										PKG:5
3240005 ^S		** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 32-41-09										PKG:6
3240006 ^S		** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 32-41-04										PKG:6
3240007 ^S		** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 32-42-04										PKG:7
3240008 ^S		** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**		
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 32-42-02										PKG:5
3240009 ^S		** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	22-Nov-14						CMR**		
	HRS	0	4800 ^S (+25/-25)							
	AFL	0								
PROC. REF: AMM 32-41-08										PKG:8
324001	NO. 1 (LH OB) MLG WHEEL ASSY								Component	ATA:32
PN:3-1545-1	MOS/MSC	04-Jan-22	O/C	TSO 0						
SN:3809	HRS	3144.3		TSN 1779.7, TSO 0						
	AFL	3142		TSN 1742, TSO 0						
PROC. REF: AMM 32-40-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324002	NO. 2 (LH IB) MLG WHEEL ASSY									Component ATA:32
PN:3-1545-1	MOS/MSC	10-Feb-22	O/C							
SN:3819	HRS	3213.5			TSN 1365.8, TSO 0					
	AFL	3208			TSN 1256, TSO 0					
PROC. REF: AMM 32-40-02										
324003	NO. 3 (RH IB) MLG WHEEL ASSY									Component ATA:32
PN:3-1545-1	MOS/MSC	05-Feb-22	O/C		TSO 0					
SN:3186	HRS	3199.7			TSO 1642.9					
	AFL	3201			TSO 1627					
PROC. REF: AMM 32-40-02										
324004	NO. 4 (RH OB) MLG WHEEL ASSY									Component ATA:32
PN:3-1545-1	MOS/MSC	21-Mar-22	O/C		TSO 0					
SN:3810	HRS	3279.2			TSO 7755.5					
	AFL	3277			TSO 1895					
PROC. REF: AMM 32-40-02										
324005	NOSE GEAR WHEEL ASSY									Component ATA:32
PN:9544207-4	MOS/MSC	03-Mar-22	O/C		TSO 0					
SN:APR 14-11342	HRS	3234.8			TSN 1973.9, TSO 0					
	AFL	3229			TSN 1936, TSO 0					
PROC. REF: AMM 32-40-01										
324006	NO. 1 WHEEL TRANSDUCER									Component ATA:32
PN:140-13915	MOS/MSC	10-Mar-16	O/C							
SN:10572	HRS	621.2			TSN 621.2					
	AFL	604			TSN 604					
PROC. REF: AMM 32-50-04										
324007	NO. 2 WHEEL TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C		TSN 0					
SN:UNKNOWN	HRS	0			TSN 0					
	AFL	0			TSN 0					
PROC. REF: AMM 32-50-04										
324008	NO. 3 WHEEL TRANSDUCER									Component ATA:32
PN:140-13915	MOS/MSC	10-Mar-16	O/C							
SN:10594	HRS	621.2			TSN 621.2					
	AFL	604			TSN 604					
PROC. REF: AMM 32-50-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324009	NO. 4 WHEEL TRANSDUCER									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-04										
324021	NO. 1 (LH OB) MLG TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	04-Jan-22	O/C	TSN 0						
SN:12670781	HRS	3144.3		TSN 0						
	AFL	3142		TSN 0						
PROC. REF: AMM 32-40-02										
324022	NO. 2 (LH IB) MLG TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	10-Feb-22	O/C	TSN 0						
SN:12810569	HRS	3213.5		TSN 0						
	AFL	3208		TSN 0						
PROC. REF: AMM 32-40-02										
324023	NO. 3 (RH IB) MLG TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	05-Feb-22	O/C	TSN 0						
SN:91752549	HRS	3199.7		TSN 0						
	AFL	3201		TSN 0						
PROC. REF: AMM 32-40-02										
324024	NO. 4 (RH OB) MLG TIRE									Component ATA:32
PN:226K08-4	MOS/MSC	21-Mar-22	O/C	TSN 0						
SN:12850573	HRS	3279.2		TSN 0						
	AFL	3277		TSN 0						
PROC. REF: AMM 32-40-02										
324025	NOSE GEAR TIRE									Component ATA:32
PN:031-613-8	MOS/MSC	03-Mar-22	O/C	TSN 0						
SN:0303T00258	HRS	3234.8		TSN 0						
	AFL	3229		TSN 0						
PROC. REF: AMM 32-40-01										
324061	LH ANTI-SKID VALVE									Component ATA:32
PN:39-787	MOS/MSC	05-Feb-16	O/C	TSO 2						
SN:1073	HRS			TSO 0						
	AFL			TSO 0						
PROC. REF: AMM 32-41-07										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324062	RH ANTI-SKID VALVE									Component ATA:32
PN:6632401001-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1507	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07										
324097	BCU, BRAKE CONTROL UNIT									Component ATA:32
PN:6632401001-027	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:808A	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-02										
324111	(LH OUTBD) MLG GEAR BRAKE ASSY									Component ATA:32
PN:6632401000-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2872	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324112	(LH INBD) MLG GEAR BRAKE ASSY									Component ATA:32
PN:6632401000-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2871	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324113	(RH INBD) MLG GEAR BRAKE ASSY									Component ATA:32
PN:6632401000-002	MOS/MSC	11-Dec-19	O/C	TSO 0						
SN:0574	HRS	2296		TSO 0						
	AFL	2221		TSO 0						
PROC. REF: AMM 32-41-01										
324114	(RH OUTBD) MLG GEAR BRAKE ASSY									Component ATA:32
PN:6632401000-002	MOS/MSC	11-Dec-19	O/C	TSO 0						
SN:0725	HRS	2296		TSO 0						
	AFL	2221		TSO 0						
PROC. REF: AMM 32-41-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324201	SHUTTLE, BRAKE (LH OTBD) VALVE									Component ATA:32
PN:7632401002-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2675	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324202	SHUTTLE, BRAKE (LH INBD) VALVE									Component ATA:32
PN:7632401002-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2671	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324203	SHUTTLE, BRAKE (RH INBD) VALVE									Component ATA:32
PN:7632401002-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2674	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324204	SHUTTLE, BRAKE (RH OTBD) VALVE									Component ATA:32
PN:7632401002-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2669	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-04										
324205	L/H MLG O/B BRAKE SWIVEL									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324206	R/H MLG I/B BRAKE SWIVEL									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324207	L/H MLG I/B BRAKE SWIVEL									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324208	R/H MLG O/B BRAKE SWIVEL									Component ATA:32
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01										
324805	BRAKE ACCUMULATOR ASSY									Component ATA:32
PN:4532403040-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:705	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-42-02										
324806	EMERGENCY PARKING BRAKE VALVE ASSY									Component ATA:32
PN:6632401002-027	MOS/MSC	24-Nov-14	O/C							
SN:160	HRS	11.3								
	AFL	12								
PROC. REF: AMM 32-42-01										
325011	NOSE WHEEL STEERING SERVO ACTUATOR									Component ATA:32
PN:JR5208C	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:C0692	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-02										
325021	NOSE WHEEL STEER GEARBOX									Component ATA:32
PN:2W3-201D	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:711	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-03										
325031	NOSE WHEEL STEERING COMPUTER									Component ATA:32
PN:498000-03-03	MOS/MSC	20-May-16	O/C							
SN:00731	HRS	717.2								
	AFL	705								
PROC. REF: AMM 32-50-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
325041	LH NWS TRANSDUCER									Component ATA:32
PN:3A1-279A	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A1378	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-50-04										
325042	RH NWS TRANSDUCER									Component ATA:32
PN:3A1-279A	MOS/MSC	08-Jun-16	O/C							
SN:A0254	HRS	759.1								
	AFL	745								
PROC. REF: AMM 32-50-04										
325054	LH ACTUATOR, INBD DOOR, MAIN LANDING GEAR ACTUATOR									Component ATA:32
PN:6632303003-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1323	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-02										
325055	RH ACTUATOR, INBD DOOR, MAIN LANDING GEAR ACTUATOR									Component ATA:32
PN:6632303003-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1307	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-02										
3260005 ^S	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISC ASSEMBLY									Service ATA:32
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-01										PKG:1
ATA 33 - LIGHTS										
330000	PULSE LIGHT 2401S CONTROL UNIT									Component ATA:33
PN:020P0015-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1766	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
3310000 ^S		OPERATIONAL CHECK FLIGHT COMPARTMENT LIGHTING							Service	ATA:33
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 33-10-00										PKG:6
331001		CENTER SWITCH PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331002		CO-PILOTS INBOARD SWITCH PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331003		FLIGHT CONTROL SWITCH PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331004		PILOTS CB DS85 OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331005		CO-PILOT SIDE CB PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331005-DS58		PRESSURIZATION PANEL OVERLAY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331006	PILOTS SW PANEL BLANK OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331007	ENGINE CONTROL DS65 PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331008	ELECTRICAL PANEL DS85 OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331009	OVERHEAD LIGHTING PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331010	CABIN POWER DS64 OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331011	DU REVERSION PANEL DS165 OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331012	ENVIROMENTAL CONTROL DS163 PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331013	FLIGHT CONTROL DS67 PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331014	COCKPIT LIGHTS PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331015	GEAR/HYD PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331016	APU CONTROL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331017	THROTTLE QUAD A72 OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331018	CO-PILOTS C/B DS84 OVERLAY									Component ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-10-05										
331020	DIMMER									Component ATA:33
PN:LT-48G	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2769	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
3320000 ^S		OPERATIONAL CHECK PASSENGER COMPARTMENT LIGHTING							Service	ATA:33
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 33-20-00										PKG:6
3340000 ^S		OPERATIONAL CHECK EXTERIOR LIGHTING SYSTEMS							Service	ATA:33
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 33-40-00										PKG:6
334001		LEFT LED WING TIP POSITION LIGHT ASSEMBLY							Component	ATA:33
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
334002		WHITE NAV LIGHT ASSY							Component	ATA:33
PN:01-0771011-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:575	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-02										
334332		(LWR) ANTI-COLLISION/STROBE LIGHT ASSY							Component	ATA:33
PN:GE16386-12-1	MOS/MSC	29-Jun-17	O/C							
SN:1444362	HRS	1219								
	AFL	1182								
PROC. REF: AMM 33-40-01										
334333		(UPR) ANTI-COLLISION/STROBE LIGHT ASSY							Component	ATA:33
PN:GE16386-12-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:2894771	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-40-01										
3350003 ^S		OPERATIONAL CHECK EMERGENCY LIGHTING SYSTEM							Service	ATA:33
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 33-50-00										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
340001-RVSM	CHECK RVSM HEIGHT MONITORING									Service ATA:34
	MOS	27-Apr-20	24		27-Apr-22		OVD			
	HRS	2400	1000		3400		111.7			
	AFL	2325								
PROC. REF: GENERIC NO REF, FAR AGHME										
340003 ^U	UPDATE GARMIN OBSTACLE, AIRPORT DIRECTORY, AND SAFE TAXI DATA DATABASES									Service ATA:34
	DAYS	22-Mar-22	56		17-May-22		OVD	CUSTOMER CODE		
	HRS	3280.8								
	AFL	3280								
340004 ^U	UPDATE TERMINAL CHART DATABASE									Service ATA:34
	DAYS	01-Apr-22	14		15-Apr-22		OVD	CUSTOMER CODE		
	HRS	3288.3								
	AFL	3291								
340005 ^U	UPDATE NAV DATABASE									Service ATA:34
	DAYS	22-Mar-22	30		21-Apr-22		OVD	CUSTOMER CODE		
	HRS	3280.8								
	AFL	3280								
341001	LH GDC7400 ELSP AIR DATA COMPUTER									Component ATA:34
PN:011-02337-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1U6100455	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-01										
341001A	TEST/INSPECT LH GDC7400 ELSP AIR DATA COMPUTER (91.411)									Service ATA:34
PN:011-02337-01	MOS	13-Jan-22	24		12-Jan-24 ^M		396 d			
SN:1U6100455	HRS									
	AFL									
PROC. REF: AMM 34-17-01, FAR 91.411										
341002	RH GDC7400 ELSP AIR DATA COMPUTER									Component ATA:34
PN:011-02337-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1U6100454	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341002A	TEST/INSPECT RH GDC7400 ELSP AIR DATA COMPUTER (91.411)									Service ATA:34
PN:011-02337-01	MOS	13-Jan-22	24		12-Jan-24 ^M		396 d			
SN:1U6100454	HRS									
	AFL									
PROC. REF: AMM 34-17-01, FAR 91.411										
341073	FWD RADIO ALTIMETER ANTENNA									Component ATA:34
PN:S67-2002-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:552-20307	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-14-02										
341074	AFT RADIO ALTIMETER ANTENNA									Component ATA:34
PN:S67-2002-4	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:552-20311	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-14-02										
3411000 ^S	VISUAL INSPECTION PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS									Service ATA:34
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 34-11-01										PKG:6
3411052 ^S	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF PRIMARY PITOT-STATIC PROBES									Service ATA:34
	MOS	13-Jan-22	24 ^S (+14d/-14d)							
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 34-11-01										PKG:10
3411053	LH PITOT-STATIC PROBE									Component ATA:34
PN:6634100000-001	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:283243	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01										
3411054	RH PITOT-STATIC PROBE									Component ATA:34
PN:6634100000-003	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:286688	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
3411060	FUNCTIONAL TEST AIR DATA SYSTEM									Service ATA:34
	MOS	13-Jan-22	24 (+14d/-14d)		13-Jan-24		397 d (+14)			
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 34-17-00, FAR 91.411										PKG:10
3411062 ^S	VISUAL INSPECTION PITOT-STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS.									Service ATA:34
	MOS	13-Jan-22	24 ^S (+14d/-14d)							
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 34-11-01										PKG:10
341110	STANDBY PITOT-STATIC PROBE									Component ATA:34
PN:6634100000-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:287306	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-11-01										
341110A	TEST/INSPECT PITOT/STATIC SYSTEM									Service ATA:34
	MOS	13-Jan-22	24		13-Jan-24		397 d			
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 34-11-00, AMM 34-11-01, FAR 91.411										
341401	ALT-4000 ALTIMETER									Component ATA:34
PN:822-0615-207	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:HND3Y	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-14-01										
341401A	TEST/INSPECT ALT-4000 ALTIMETER									Service ATA:34
PN:822-0615-207	MOS/MSC	06-Feb-18	A/R							
SN:HND3Y	HRS	1461								
	AFL	1388								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341901	TOTAL AIR TEMPERATURE SENSOR									Component ATA:34
PN:102AU1AG	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:B24599	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-17-02										
342103	STANDBY COMPASS WITH LIGHT ASSY									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
342103A	CALIBRATION CHECK STANDBY COMPASS WITH LIGHT ASSY (FAR 25.1327)									Service ATA:34
PN:PN	MOS/MSC	22-Nov-14	C/C							
SN:UNKNOWN	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
342401	ELECTRONIC STANDBY INSTRUMENT GH-3900 SYSTEM									Component ATA:34
PN:9200-34400-0201	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1329	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-24-01										
342401A	FUNCTIONAL TEST ELECTRONIC STANDBY INSTRUMENT GH-3900 SYSTEM (91.411)									Service ATA:34
PN:9200-34400-0201	MOS	13-Jan-22	24		12-Jan-24 ^M		396 d			
SN:1329	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 34-24-01, FAR 91.411										
342402	3100 MAGNETOMETER									Component ATA:34
PN:9200-21200-0102	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:80063	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-24-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342601	LH GMU 44 MAGNETOMETER									Component ATA:34
PN:011-00870-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1CM012781	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02										
342602	RH GMU 44 MAGNETOMETER									Component ATA:34
PN:011-00870-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1CM012770	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-26-02										
342605	LH GRS 7800 COMPUTER									Component ATA:34
PN:011-02278-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:25M000517	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
342606	RH GRS 7800 COMPUTER									Component ATA:34
PN:011-02278-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:25M000421	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
343005	MARKER BEACON ANTENNA									Component ATA:34
PN:DMN27-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:18435	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-30-01										
343030	ANTENNA (DIPLEXER) COUPLER									Component ATA:34
PN:DMH21-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:52143	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-03										
343031	ANTENNA (DIPLEXER) COUPLER									Component ATA:34
PN:DMH21-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:52142	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
344111	UPPER TCAS ANTENNA									Component ATA:34
PN:S72-1735-24	MOS/MSC	15-Oct-20	O/C	TSN 0						
SN:833-0582	HRS	2589.7		TSN 0						
	AFL	2542		TSN 0						
PROC. REF: AMM 34-43-02										
344112	LOWER TCAS ANTENNA									Component ATA:34
PN:S72-1735-24	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:833-0265	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-02										
344143	TCAS II, GTS 8000 PROCESSOR									Component ATA:34
PN:011-02571-00	MOS/MSC	11-Jul-18	O/C							
SN:28P006029	HRS	1657		TSR 0						
	AFL	1575		TSR 0						
PROC. REF: AMM 34-43-01										
344209	ANTENNA (LIGHTNING SENSOR OPTION) ANTENNA									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
344211	WEATHER RADAR ANTENNA									Component ATA:34
PN:117-00254-01	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:532	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-42-03										
344212	WEATHER, BASE, GWX 70 RADAR									Component ATA:34
PN:011-01768-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1DP005500	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345013	DUAL ADF, ANT-462B ANTENNA									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345037	ATC LOWER NO 2 ANTENNA									Component ATA:34
PN:DMN150-2-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:134858	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-02										
345038	ATC LOWER NO 1 ANTENNA									Component ATA:34
PN:DMN150-2-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:134554	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-02										
345049	DME NO 1 ANTENNA									Component ATA:34
PN:DMN150-2-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:134575	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-02										
345050	DME NO 2 ANTENNA									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-02										
345083	LH VOR/ILS ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:34370	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345084	RH VOR/ILS ANTENNA									Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:34369	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
345260	PHASING COUPLER									Component ATA:34
PN:DMN4-17-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:23917	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345501	DME (DME-4000) TRANSCEIVER									Component ATA:34
PN:822-1466-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:40HDPG	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-01										
345502	DME (DME-4000) TRANSCEIVER									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-55-01										
345601	LH GTX 3000 TRANSPONDER									Component ATA:34
PN:011-01997-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:20S000925	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-01										
345601A	TEST/INSPECT LH GTX 3000 TRANSPONDER									Service ATA:34
PN:011-01997-00	MOS	12-Jan-22	24		12-Jan-24		396 d			
SN:20S000925	HRS									
	AFL									
PROC. REF: AMM 34-56-01, FAR 91.413										
345602	RH GTX 3000 TRANSPONDER									Component ATA:34
PN:011-01997-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:20S000926	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-01										
345602A	TEST/INSPECT RH GTX 3000 TRANSPONDER									Service ATA:34
PN:011-01997-00	MOS	12-Jan-22	24		12-Jan-24		396 d			
SN:20S000926	HRS									
	AFL									
PROC. REF: AMM 34-56-01, FAR 91.413										
345605	ATC UPPER NO 1 ANTENNA									Component ATA:34
PN:DMN150-2-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:134857	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345606	ATC UPPER NO 2 ANTENNA									Component ATA:34
PN:DMN150-2-2	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:134867	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-56-02										
345701	ADF (#1) RECEIVER									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01										
345702	ADF (#2) RECEIVER									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01										
346090	DATA MANAGEMENT (OPTION) UNIT									Component ATA:34
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
347510	LH GPS WAASXM ANTENNA									Component ATA:34
PN:013-00245-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:11916	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-01										
347511	RH GPS WAASXM ANTENNA									Component ATA:34
PN:013-00245-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:11915	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-01										
ATA 35 - OXYGEN										
3500024	HYDROSTATIC TEST PORTABLE OXYGEN DOT 3AA1800 (OPTION) CYLINDER (IF INSTALLED).									Service ATA:35
PN:PN	MOS/MSC		-					N/A EQUIPMENT NOT INSTALLED		
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
350230	PRESSURE INDICATOR									Component ATA:35
PN:P24071-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:700	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-00-05										
3510002 ^S	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK									Service ATA:35
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 35-00-00										PKG:6
3510003 ^S	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST									Service ATA:35
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 35-20-00										PKG:6
3510008	CREWMEMBER PBE									Component ATA:35
PN:PN	MOS/MSC		-					NOT INSTALLED		
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
351001	PILOT CREW OXYGEN MASK									Component ATA:35
PN:MC10-15-166	MOS/MSC	13-Feb-20	O/C	TSN 63, TSO 0						
SN:SE80828	HRS	2342.1		TSN 2342.1, TSO 0						
	AFL	2277		TSN 2277, TSO 0						
PROC. REF: AMM 35-10-01										
3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK									Service ATA:35
	MOS	15-Oct-21						CMR**		
	HRS	3036.3	1500 (+25/-25)	Adj -36.3	4500	4525	1211.7 (+25)			
	AFL	3017								
PROC. REF: AMM 35-00-01										
3510014 ^S	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST									Service ATA:35
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 35-20-00										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
351002	CO-PILOT CREW OXYGEN MASK									Component ATA:35
PN:663500000-059	MOS/MSC	20-Jul-16	O/C	TSO 0						
SN:SE59756	HRS	813.3		TSO 0						
	AFL	819		TSO 0						
PROC. REF: AMM 35-10-01										
3510022	OVERHAUL OXYGEN CYLINDER REGULATOR									Service ATA:35
	MOS	09-Feb-17								
	HRS	1045.2	4800 (+25/-25)		5845.2	5870.2	2556.9 (+25)			
	AFL	1027								
PROC. REF: GENERIC NO REF										
3510024	OVERHAUL CO-PILOT CREW OXYGEN MASK									Service ATA:35
PN:663500000-059	MOS	20-Jul-16	72 (+14d/-14d)		20-Jul-22	03-Aug-22	OVD			
SN:SE59756	HRS	813.3								
	AFL	819								
PROC. REF: GENERIC NO REF										
3510024	OVERHAUL PILOT CREW OXYGEN MASK									Service ATA:35
PN:MC10-15-166	MOS	04-Feb-20	72 (+14d/-14d)		04-Feb-26	18-Feb-26	1150 d (+14)			
SN:SE80828	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
3510025	HYDROSTATIC TEST 40 CU FT, W/GAUGE CYLINDER (PER DOT 3HT-1850).									Service ATA:35
PN:663500000-139	MOS	29-Jan-20	36 (+14d/-14d)		29-Jan-23	12-Feb-23	48 d (+14)			
SN:ST296479	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
3510026 ^S	** OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE - PERFORM FUNCTIONAL TEST									Service ATA:35
	MOS	22-Nov-14						CMR**		
	HRS	0	4800 ^S (+25/-25)							
	AFL	0								
PROC. REF: AMM 35-00-00										
										PKG:8

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
3510029	40 CU FT, W/GAUGE CYLINDER									Component	ATA:35
PN:6635000000-139	MOS	13-Feb-20	288 (+14d/-14d)		20-Mar-38		03-Apr-38	5577 d (+14)	LIFE LIMIT		
SN:ST296479	HRS	2342.1									
	AFL	2277									
			Manufacture Date:: 20-Mar-14	PROC. REF: AMM 35-00-01							
352011	OXYGEN CONTROL VALVE									Component	ATA:35
PN:6635000000-025	MOS/MSC	22-Nov-14	O/C	TSN 0							
SN:723	HRS	0		TSN 0							
	AFL	0		TSN 0							
			PROC. REF: AMM 35-20-01								
353001	PORTABLE OXYGEN DOT 3AA1800 (OPTION) CYLINDER									Component	ATA:35
PN:PN	MOS/MSC		O/C								
SN:UNKNOWN	HRS										
	AFL										
			PROC. REF: GENERIC NO REF								
353005	INTERCOSTAL ASSY									Component	ATA:35
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0							
SN:UNKNOWN	HRS	0		TSN 0							
	AFL	0		TSN 0							
			PROC. REF: GENERIC NO REF								
ATA 36 - PNEUMATIC											
3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST									Service	ATA:36
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**			
	HRS	2985.7	600 ^S (+25/-25)								
	AFL	2970									
			PROC. REF: AMM 36-10-00							PKG:5	
3610001 ^S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST									Service	ATA:36
	MOS	07-Sep-21	36 ^S (+14d/-14d)					CMR**			
	HRS	2985.7	600 ^S (+25/-25)								
	AFL	2970									
			PROC. REF: AMM 36-20-01							PKG:5	

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
3610048	LEFT HP BLEED MANIFOLD ASSEMBLY - PERFORM VISUAL INSPECTION.									Service ATA:36
	MOS	22-Nov-14								
	HRS	0	3500 (+100/-100)		3500	3600	211.7 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										
3610048	RIGHT HP BLEED MANIFOLD ASSEMBLY - PERFORM VISUAL INSPECTION.									Service ATA:36
	MOS	22-Nov-14								
	HRS	0	3500 (+100/-100)		3500	3600	211.7 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										
361006	LH HIGH PRESSURE SWITCH									Component ATA:36
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
361006	RH HIGH PRESSURE SWITCH									Component ATA:36
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-06										
3610061 ^S	CLEAN HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER									Service ATA:36
	MOS	07-Sep-21	36 ^S (+14d/-14d)							
	HRS	2985.7	600 ^S (+25/-25)							
	AFL	2970								
PROC. REF: AMM 36-10-02										PKG:5
361031	ECS, DUAL CHANNEL CONTROLLER									Component ATA:36
PN:6636108500-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:42XTV2	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-01										
361040	CHECK VALVE									Component ATA:36
PN:4011-14	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:437	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361050	SHUTOFF, BLEED AIR VALVE									Component ATA:36
PN:3876322-1	MOS/MSC	20-Mar-15	O/C	TSO 0						
SN:0421	HRS	148		TSO 0						
	AFL	143								
PROC. REF: AMM 36-10-02, AMM 36-10-10										
361053	LH ECS SHUTOFF VALVE									Component ATA:36
PN:6621000000-061	MOS/MSC	13-Mar-17	O/C	TSR 6						
SN:1153	HRS	1098.7		TSR 0						
	AFL	1064		TSR 0						
PROC. REF: AMM 36-10-03										
361054	RH ECS SHUTOFF VALVE									Component ATA:36
PN:6621000000-061	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1419	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-03										
361055	LH SHUTOFF, BUTTERFLY, 2.0 DIA VALVE									Component ATA:36
PN:6621000000-092	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1521	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
361056	RH SHUTOFF, BUTTERFLY, 2.0 DIA VALVE									Component ATA:36
PN:6621000000-092	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1521	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
361215	LH HP MANIFOLD ASSY									Component ATA:36
PN:LJ01212-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:210714-001	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-07										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361216	RH HP MANIFOLD ASSY									Component ATA:36
PN:LJ01212-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:240714-001	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-07										
361301	CHECK - APU VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:4411	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-10-09										
361302	LH CHECK - SERVO AIR VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:4315	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-02										
361303	RH CHECK - SERVO AIR VALVE									Component ATA:36
PN:6608295-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:4281	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-02										
361501	PRESSURE SERVO AIR REGULATOR									Component ATA:36
PN:6600245-004	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1605	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-15-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 38 - WATER/WASTE										
381009	FWD HEATED DRAIN MAST									Component ATA:38
PN:116393-101	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3949	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 38-30-03, AMM 38-30-04										
381010	AFT HEATED DRAIN MAST									Component ATA:38
PN:116393-101	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:3947	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 38-30-03, AMM 38-30-04										
383001	TOILET ASSY									Component ATA:38
PN:6638303001-005	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:U4863	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 38-30-01										
383002	TIMER BOX ASSY									Component ATA:38
PN:7638303002-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:T7524	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 38-30-02										
383005	WATER TANK ASSY									Component ATA:38
PN:AR9062-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:4867	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
383006	AFT HOT LIQUID CONTAINER									Component ATA:38
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 45 - CENTRAL MAINT SYSTEM										
454502	WIFI DATA LINK								Component	ATA:45
PN:011-01746-00	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1EJ005511	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 45-45-02										
454503	L-BAND ANTENNA								Component	ATA:45
PN:S65-5366-715	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:784-1420	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 45-45-03										
ATA 46 - INFORMATION SYSTEMS										
462001	XM GRAPHICAL WEATHER RECEIVER								Component	ATA:46
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 46-20-01										
462002	GDL69A RECEIVER								Component	ATA:46
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 49 - AIRBORNE AUXILIARY POWER										
4900002 ^S	FUNCTIONAL TEST AUXILIARY POWER UNIT FIRE EXTINGUISHER CONTAINER WIRING								Service	ATA:49
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 26-22-00										PKG:6
4900003	OVERHAUL APU STARTER/GENERATOR (REPLACE BRUSHES)								Service	ATA:49
PN:6608458-010	MOS	29-Nov-16						OVERHAUL		
SN:P1174	HRS	945.8								
	AFL	946								
	APH	365.8	1200 (+25/-25)		1565.8	1590.8	317.8 (+25)			
PROC. REF: AMM 49-40-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
4900004	APU - ENGINE OIL FILTER								Component	ATA:49
PN:3609088-1	MOS	13-Mar-19		TSN 0						
SN:UNKNOWN	HRS	748	750	TSN 0	1498		250			
	APUS	2123		TSN 0						
PROC. REF: AMM 49-90-04										
4900005	APU - ENGINE FUEL FILTER								Component	ATA:49
PN:3882440-1	MOS	13-Mar-19		TSN 0						
SN:UNKNOWN	HRS	748	750	TSN 0	1498		250			
	APUS	2123		TSN 0						
PROC. REF: AMM 49-30-03										
4900006	VISUAL INSPECTION APU STARTER/GENERATOR GEAR BOX DRIVE SPLINES								Service	ATA:49
PN:6608458-010	MOS/MSC	29-Nov-16	C/C							
SN:P1174	HRS	945.8								
	AFL	946								
PROC. REF: GENERIC NO REF										
4900008	APU - INSPECT APU ENGINE CHIP DETECTOR FOR CONTAMINATION								Service	ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
PROC. REF: AMM 49-90-05										
4900009	APU - PERFORM APU ENGINE OIL CHANGE								Service	ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
4900011 ^S	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK.								Service	ATA:49
	MOS	13-Feb-20	72 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 49-40-01										PKG:6
4900014	HYDROSTATIC TEST APU FIRE EXTINGUISHER CONTAINER								Service	ATA:49
PN:51600-2	MOS	01-Mar-21	60 (+14d/-14d)		01-Mar-26	15-Mar-26	1175 d (+14)			
SN:0328	HRS									
	AFL									
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
4900015	APU FIRE EXTINGUISHER CONTAINER CARTRIDGE									Component ATA:49
PN:30600-22	MOS	29-Mar-21	144 (+14d/-14d)	TSN 0	29-Mar-33	12-Apr-33	3760 d (+14)	LIFE LIMIT		
SN:UNKNOWN	HRS	2736.2		TSN 0						
	AFL	2722		TSN 0						
PROC. REF: AMM 26-22-01										
4900018	APU - AUXILIARY POWER UNIT TURBINE ROTOR									Component ATA:49
PN:3842340-2	MOS	24-Jul-14		TSN 0				LIFE LIMIT		
SN:14-156101-03645	HRS	0		TSN 0						
	APUS	0	4000	TSN 0	4000		375			
PROC. REF: AMM 49-10-01										
4900020	APU - AUXILIARY POWER UNIT COMPRESSOR ROTOR									Component ATA:49
PN:3822523-003	MOS	24-Jul-14		TSN 0				LIFE LIMIT		
SN:13-162053-59700	HRS	0		TSN 0						
	APUS	0	12000	TSN 0	12000		8375			
PROC. REF: AMM 49-10-01										
490060	APU CONTROLLER									Component ATA:49
PN:2119560-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:64-N0117	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-60-04										
491000	APU - DOWNLOAD APU ECU (TIMES/CYCLES)									Service ATA:49
	MOS/MSC	24-Jul-14	A/R							
	HRS	0								
	APUS	0								
PROC. REF: AMM 49-60-04										
491011	APU MAINTENANCE CONTROL PANEL									Component ATA:49
PN:7088001-3	MOS/MSC	04-Aug-16	O/C	TSN 0						
SN:DC484	HRS	828.7		TSN 0						
	AFL	835		TSN 0						
PROC. REF: AMM 49-60-02										
491020	APU CTLR PANEL ASSY									Component ATA:49
PN:6011-1	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A00HB1	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
493011	APU - APU PRESSURIZING VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493021	APU - APU FILTER BYPASS VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493031	APU - APU PRESSURE RELIEF VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493041	APU - APU DIFFERENTIAL PRESSURE VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493051	APU - APU FUEL PUMP									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-04										
493061	APU - APU DIFFERENTIAL PRESSURE INDICATOR									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
493071	APU - APU ASSEMBLY, FUEL CONTROL									Component ATA:49
PN:3883900-1	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:1401900	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
494001	APU - (LOW VOLTAGE) IGNITION UNIT									Component ATA:49
PN:3888000-7	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:J13390521	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-04										
494011	APU - APU IGNITION EXCITER									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-04										
494021	APU - APU LOW VOLTAGE IGNITER PLUG									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-02										
494031	APU - APU IGNITION LEAD									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-40-03										
494060	APU - APU GROUND CONTROL UNIT CHANGE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
495001	APU - APU ISOLATION VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-50-01										
495001	LH TAILCONE FAN									Component ATA:49
PN:011809500	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:I 14111072	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-50-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
495002	ACCESS DOOR TAILCONE FAN									Component ATA:49
PN:011809500	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:I 14111069	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 49-50-01										
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER									Component ATA:49
PN:2119560-3	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:64-N0117	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-60-04										
496010	APU - APU FUEL LINE REPLACE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
496011	APU - APU FUEL SHUTOFF VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
496021	APU - APU FLOW DIVIDER VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-06										
496031	APU - APU FUEL SOLENOID VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-01										
496041	APU - APU - BLEED AIR SHUTOFF VALVE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
497001	APU - APU SPEED SENSOR									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-04										
497011	APU - APU EGT THERMOCOUPLE									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-07										
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP									Component ATA:49
PN:3881825-1	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:P-1981	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-03										
499037	APU - APU LOW OIL PRESSURE SENSOR									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-02										
499048	APU - INLET TEMP SENSOR									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-70-06										
499049	APU - APU OIL TEMPERATURE BULB									Component ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
499061	APU - APU OIL LEVEL SENSOR									Component ATA:49
PN:3876318-1	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:1316222101388	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-90-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
499071	APU - APU ULTIMATE RELIEF VALVE								Component	ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: GENERIC NO REF										
499081	APU - APU MANIFOLD AND PRIMARY ATOMIZER								Component	ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-05										
499082	APU - APU MANIFOLD AND SECONDARY ATOMIZER								Component	ATA:49
PN:PN	MOS/MSC	24-Jul-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
PROC. REF: AMM 49-30-05										
49APU1	APU								Component	ATA:49
PN:3800726-1	MOS/MSC		E/C							
SN:P-534	HRS									
WC#: 49.APU1	AFL									
PROC. REF: AMM 49-10-01										
5-19-00-O4900008	APU - INSPECT APU CHIP DETECTOR - FOR CONTAMINATION. (ZONE/ACCESS 310JL, 310RR IRN # O4900008)								Service	ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
PROC. REF: AMM 49-90-05										
5-19-00-P4900009	APU - CHANGE APU OIL. (ZONE/ACCESS 310JL, 310RR). (IRN # P4900009). (REFER TO 12-10-10.) NOTE: THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49).								Service	ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
PROC. REF: AMM 12-10-10										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
5-19-01-K4900005	APU - REPLACE APU ENGINE FUEL FILTER. IRN # K4900005									Service ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
PROC. REF: AMM 49-30-03										
5-19-01-T4900004	APU - REPLACE APU OIL FILTER. THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49 (ZONE/ACCESS 310JR, 310QR) (IRN # T4900004)									Service ATA:49
	MOS	13-Mar-19								
	HRS	748	750		1498		250			
	APUS	2123								
PROC. REF: AMM 49-90-04										
ATA 52 - DOORS										
5210003 ^S	VISUAL INSPECTION EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.									Service ATA:52
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:6
5210006 ^S	VISUAL INSPECTION UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS									Service ATA:52
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:6
5210008 ^S	PERFORM OPERATIONAL CHECK - EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM.									Service ATA:52
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 52-20-07										PKG:6
5210009 ^S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394).									Service ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
521001	UPPER PASSENGER/CREW DOOR ASSY								Component	ATA:52
PN:4552101000-005	MOS/MS	22-Nov-14	O/C	TSN 0						
SN:W643	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
5210010	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION								Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	T:9600		9600		6311.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5210011	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.								Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	T:9600		9600		6311.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5210012 ^S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS.								Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5210013 ^S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION								Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:14
5210014 ^S	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.								Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
5210015 ^S			* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:14
5210016 ^S			* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5210017			* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	22-Nov-14						CMR*		
	HRS	0	T:9600		9600		6311.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
521002	LOWER PASSENGER/CREW DOOR ASSY								Component	ATA:52
PN:4552100050V109-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:W627	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
5210053	CABIN DOOR HANDLE - REPLACE								Service	ATA:52
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 52-10-08, AMM 52-10-13										
5210055 ^S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE								Service	ATA:52
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 12-21-02										PKG:6

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
522001	EMERGENCY EXIT DOOR ASSY								Component	ATA:52
PN:4552200076-V44-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:L496	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01										
523001	TAILCONE BAGGAGE DOOR ASSY								Component	ATA:52
PN:12045-558V3-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:660	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-30-01										
5240004 ^S	INSPECT AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION								Service	ATA:52
	MOS	13-Jan-22	24 ^S (+14d/-14d)							
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 52-40-01										PKG:10
524001	TAILCONE ACCESS DOOR ASSY								Component	ATA:52
PN:4552405151-017	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:666	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-40-02										
ATA 53 - FUSELAGE										
530001	FUSELAGE ASSEMBLY								Component	ATA:53
PN:4553000010-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:L496	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
5310001 ^S	* LONGERON, INTERNAL (BETWEEN F.S. 384 AND F.S. 433) - PERFORM VISUAL INSPECTION								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5310002 ^S		* FLIGHT DECK LONGERON (F.S. 149 - F.S. 196) - PERFORM VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5310003 ^S		* AFT PRESSURE BULKHEAD SUPPORT POST (F.S. 457) - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-18										PKG:9
5310004 ^S		* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-21										PKG:13
5310005 ^S		* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:13
5310006 ^S		* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-07										PKG:9
5310007 ^S		* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5310017 ^S		* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (F.S. 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT F.S. 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5310018 ^S		* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (F.S. 457) - PERFORM VISUAL INSPECTION - INSPECT BOTH FRONT AND AFT OF FACING SHEETS.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5310023 ^S		VISUAL INSPECTION FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.							Service	ATA:53
	MOS	22-Nov-14								
	HRS	0	10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5310025 ^S		VISUAL INSPECTION AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH)- PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.							Service	ATA:53
	MOS	22-Nov-14								
	HRS	0	10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5310027 ^S		* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-17										PKG:9
5311002		* NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	10000		10000		6709			
PROC. REF: NDT PART 6 / 32-12-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5311004	* NOSE LANDING GEAR TRUNNION FITTINGS - PERFORM VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	10000		10000		6709			
PROC. REF: GENERIC NO REF										
5311005	* NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0								
	AFL	0	10000		10000		6709			
PROC. REF: NDT PART 6 / 32-12-05										
5313001 ^S	CHECK FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK.								Service	ATA:53
	MOS	13-Jan-22	24 ^S (+14d/-14d)							
	HRS	3155.3								
	AFL	3154								
PROC. REF: AMM 53-00-01										PKG:10
5314000 ^S	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-01										PKG:11
5320001 ^S	* FUSELAGE PRESSURE FLOOR STEP (F.S. 433 - F.S. 457) - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-20-01										PKG:9
5323021 ^S	* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION - INSPECT LONGERON BETWEEN F.S. 398 AND F.S. 486, STRINGER 13 LHS & RHS.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323022 ^S					* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION - INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER.				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5323023 ^S					* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:13
5323024 ^S					* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION.				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-12										PKG:13
5323025 ^S					* FORWARD/AFT WHEELBOX JOINT (F.S. 150) - PERFORM VISUAL INSPECTION - INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5323026 ^S					* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT.				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-02										PKG:11
5323027 ^S					* FUSELAGE FRAME AT F.S. 412 - PERFORM EDDY CURRENT INSPECTION.				Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-20										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323028 ^S			* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-16										PKG:13
5323029 ^S			* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (F.S. 398, F.S. 412, F.S. 432, F.S. 466) - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-15										PKG:13
5323032			* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	13-Jan-22	24		13-Jan-24		397 d	CMR*		
	HRS	3155.3	2400		5555.3		2267			
	AFL	3154								
PROC. REF: NDT PART 6 / 56-20-01										
5323033 ^S			* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-40-02										PKG:9
5323034 ^S			* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-03										PKG:9
5323037 ^S			* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-09										PKG:9
5323038 ^S			* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-22										PKG:14

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323047 ^S		* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-10-04										PKG:12
5323048 ^S		* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING).							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-05										PKG:14
5323049 ^S		* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-11										PKG:9
5323050 ^S		* AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-04										PKG:14
5323051 ^S		* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (F.S. 220 - F.S. 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH & RH AND STRINGER 2 RH AND STRINGER 18 RH.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-05										PKG:14
5323053 ^S		* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (F.S. 171 TO F.S. 204) - PERFORM VISUAL INSPECTION - INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT F.S. 171, F.S. 182, F.S. 196 AND F.S. 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAIL							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323055	* TIE-ROD ASSEMBLY (F.S. 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION - INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	9600		9600		6311.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5323057 ^S	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-06										PKG:12
5323058 ^S	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-13										PKG:13
5323059 ^S	* STRINGER TO FRAME JOINTS (F.S. 162 TO F.S. 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-05										PKG:9
5323068 ^S	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION - INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5323069 ^S	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-08										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323073 ^S		* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION - INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435).							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5323074 ^S		* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION - INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466).							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5323081		* TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - PERFORM FLUORESCENT PENETRANT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	9600		9600		6311.7			
	AFL	0								
PROC. REF: NDT PART 8 / 53-10-01										
5323092		* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14	96		22-Nov-22		OVD	CMR*		
	HRS	0	4800		4800		1511.7			
	AFL	0								
PROC. REF: NDT PART 6 / 56-20-01										
5323164 ^S		* FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-40-01										PKG:9
5323165 ^S		* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-10										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5323166	* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).								Service	ATA:53
	MOS	22-Nov-14	144		22-Nov-26		1441 d	CMR*		
	HRS	0	10000		10000		6711.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5323168	* LH AND RH LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION (P/N'S 4553130001-802 THRU 4553130001-809)								Service	ATA:53
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5323173	* SKIN CUT-OUT FOR IRIIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								Service	ATA:53
	MOS/MSC	22-Nov-14	N/A					CMR*		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5323174	* SKIN CUT-OUT FOR IRIIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								Service	ATA:53
	MOS/MSC	22-Nov-14	N/A					CMR*		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5323175	* SKIN CUT-OUT FOR IRIIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								Service	ATA:53
	MOS/MSC	22-Nov-14	N/A					CMR*		
	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
5331021 ^S	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION - INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.								Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
5331022 ^S		* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5331023 ^S		* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION - INSPECT AT REAR SPAR ATTACHMENT FASTENERS.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5331024 ^S		* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5331025 ^S		* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION - INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5331026 ^S		* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION - INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5350000 ^S		* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433.							Service	ATA:53
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
535001	RADOME ASSEMBLY								Component	ATA:53
PN:6634408000-005	MOS/MSC	07-Dec-21	O/C							
SN:0598	HRS	3100.6		TSR 0						
	AFL	3096		TSR 0						
PROC. REF: AMM 53-50-01										
535601	LH DELTA FIN ASSY								Component	ATA:53
PN:4555501000-017	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0400	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										
535602	RH DELTA FIN ASSY								Component	ATA:53
PN:4555501000-018	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0420	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 53-56-01										
5360001 ^S	VISUAL INSPECTION DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.								Service	ATA:53
	MOS	22-Nov-14								
	HRS	0	10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5360006 ^S	NDT INSPECT DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.								Service	ATA:53
	MOS	22-Nov-14								
	HRS	0	10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: NDT PART 8 / 53-10-02										PKG:9
ATA 54 - NACELLES/PYLONS										
5410002 ^S	VISUAL INSPECTION PYLONS - INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE.								Service	ATA:54
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 54-00-01										PKG:7

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
545001	LH FIREWALL ASSY									Component ATA:54
PN:457130000-017	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:101261	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 54-50-01										
5450011 ^S	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-10-03										PKG:13
5450012 ^S	* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-03										PKG:13
5450015 ^S	* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-05										PKG:13
5450016 ^S	* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-02										PKG:13
5450017 ^S	LEFT * FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 53-40-01										PKG:13
5450017 ^S	RIGHT * FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.									Service ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 53-40-01										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
5450018 ^S	LEFT * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 71-20-01										PKG:13
5450018 ^S	RIGHT * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 71-20-01										PKG:13
5450019 ^S	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION - INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:13
545002	RH FIREWALL ASSY								Component	ATA:54
PN:457130000-018	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:7230	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 54-50-01										
5450020 ^S	LEFT * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT - PERFORM LIQUID PENETRANT INSPECTION.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 54-30-01										PKG:13
5450020 ^S	RIGHT * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT - PERFORM LIQUID PENETRANT INSPECTION.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 54-30-01										PKG:13
5450021 ^S	LEFT * ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION.								Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 71-20-03										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
5450021 ^S			RIGHT * ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION.						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 71-20-03										PKG:13
5450022 ^S			LEFT * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 71-20-01										PKG:13
5450022 ^S			RIGHT * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 71-20-01										PKG:13
5450023 ^S			LEFT * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 54-30-02										PKG:13
5450023 ^S			RIGHT * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 54-30-02										PKG:13
5450024 ^S			* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 53-30-14										PKG:13
5450025 ^S			* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION.						Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-03										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
5450026 ^S		LEFT * ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-01										PKG:13
5450026 ^S		RIGHT * ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-01										PKG:13
5450029 ^S		* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.							Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:13
5450030 ^S		* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION							Service	ATA:54
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 54-50-04										PKG:13
5450054		VISUAL INSPECTION LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	22-Nov-14								
	HRS	0	7000 (+100/-100)		7000	7100	3711.7 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										
5450054		VISUAL INSPECTION RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	22-Nov-14								
	HRS	0	7000 (+100/-100)		7000	7100	3711.7 (+100)			
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510000 ^S		* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-01										PKG:8
5510002 ^S		VISUAL INSPECTION ELEVATOR HINGES ON HORIZONTAL STABILIZER - INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE.							Service	ATA:55
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:7
5510003 ^S		VISUAL INSPECTION VISUAL INSPECTION VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET)							Service	ATA:55
	MOS	13-Feb-20	72 ^S (+14d/-14d)							
	HRS	2342.1	1200 ^S (+25/-25)							
	AFL	2277								
PROC. REF: GENERIC NO REF										PKG:6
5510004 ^S		* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION - CONTROL SURFACE REMOVAL NOT REQUIRED.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5510005 ^S		* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-05										PKG:11
5510006 ^S		* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 2 / 55-30-01										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510007 ^S		* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-06										PKG:9
5510008 ^S		* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 55-30-02, NDT PART 7 / 55-30-03										PKG:9
5510009 ^S		* HORIZONTAL STABILIZER MID SPAR UPPER CAP B.L. 0.0 TO B.L. 4.0 - PERFORM X-RAY INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 2 / 55-10-03										PKG:12
5510010		* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800		4800		1511.7			
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-03										
5510011		* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 2 / 55-10-01										
5510014 ^S		* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510015 ^S		* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-02										PKG:11
5510016 ^S		* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-03										PKG:11
5510017 ^S		* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-05										PKG:12
5510018 ^S		* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-04										PKG:9
5510019 ^S		* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-20-02										PKG:9
5510020 ^S		* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-07										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510021 ^S		* HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM DETAILED VISUAL INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5510023 ^S		* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-01										PKG:8
5510024 ^S		* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-20-01										PKG:9
5510033 ^S		* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 27-40-01										PKG:8
5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION								Service	ATA:55
	MOS									
	HRS	EFF	4800 (+25/-25)		4800 *	4825	1511.7 (+25)			
	AFL									
PROC. REF: GENERIC NO REF										
551005	HORIZONTAL STABILIZER ASSY								Component	ATA:55
PN:4555101001V46-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0385	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-40-01										
5510069 ^S		* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-02										PKG:11

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510070 ^S		* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 2 / 55-10-02										PKG:9
5510073 ^S		* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-07										PKG:9
5510074 ^S		* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT REAR SPAR CAP AND FASTENERS.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5510075 ^S		* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT SPAR CAPS AND FASTENERS							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5510076 ^S		* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR CAP AND FASTENERS.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5510082 ^S		* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:4800 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-04										PKG:11

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5510091	* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION.								Service	ATA:55
	MOS	07-Sep-21						CMR*		
	HRS	2985.7	625		3610.7		322.4			
	AFL	2970								
PROC. REF: AMM 55-10-00										
5510092 ^S	* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION								Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-10-06										
5510093 ^S	VISUAL INSPECTION HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB. - CENTER SPAR TO BL 0.0 RIB. - CENTER SPAR SPLICE PLATE. - AFT SPAR SPLICE PLATE. - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT). - UPPER								Service	ATA:55
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 55-00-01										
5510094 ^S	BORESCOPE INSPECTION LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB# 6 AND MID SPAR.								Service	ATA:55
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 55-10-00										
5520001	* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 7 / 27-30-01										
5520003 ^S	* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION - INSPECT SPAR CAP AT FASTENER HOLES.								Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
5520004 ^S		* ELEVATOR RIB #1 CAP- PERFORM VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5520021 ^S		* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-07										PKG:9
5520022 ^S		* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION.							Service	ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 8 / 27-30-01, NDT PART 8 / 27-30-02										PKG:9
552031	LH ELEVATOR ASSEMBLY								Component	ATA:55
PN:4555201005-011	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0392	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-01										
552032	RH ELEVATOR ASSEMBLY								Component	ATA:55
PN:4555201005-012	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0392	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-30-01										
553000	TAILCONE/VERTICAL STABILIZER ASSY								Component	ATA:55
PN:4555301001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0382	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
553001	BULLET FAIRING SKIN ASSY INSTALLATION									Component ATA:55
PN:4555311001-043	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A382	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 55-30-01										
5530011	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION.									Service ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	T:9600		9600		6311.7			
	AFL	0								
PROC. REF: NDT PART 6 / 55-30-06										
5540000 ^S	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION - INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.									Service ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5540001 ^S	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS.									Service ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5540002	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION.									Service ATA:55
	MOS	22-Nov-14						CMR*		
	HRS	0	9600		9600		6311.7			
	AFL	0								
PROC. REF: NDT PART 8 / 55-30-02										
554005	RUDDER ASSEMBLY									Component ATA:55
PN:4555401000-025	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A0394	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-20-01										
ATA 56 - WINDOWS										
5600002 ^S	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST.									Service ATA:56
	MOS	15-Nov-21	12 ^S (+14d/-14d)					CMR**		
	HRS	3074.4								
	AFL	3067								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
PROC. REF: AMM 56-10-01										PKG:1
5600010 ^S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION.								Service	ATA:56
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:8
5600012	LEFT * WINDSHIELDS - PERFORM BOLT HOLE INSPECTION								Service	ATA:56
	MOS	22-Nov-14						CMR*		
	HRS	0	4800		4800		1511.7			
	AFL	0								
PROC. REF: AMM 56-10-01										
5600012	RIGHT * WINDSHIELDS - PERFORM BOLT HOLE INSPECTION								Service	ATA:56
	MOS	22-Nov-14						CMR*		
	HRS	0	4800		4800		1511.7			
	AFL	0								
PROC. REF: AMM 56-10-01										
561001	LH WINDSHIELD ASSY								Component	ATA:56
PN:6656100001-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1953	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-10-01										
561002	RH WINDSHIELD ASSY								Component	ATA:56
PN:6656100001-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1876	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-10-01										
561003	EMERGENCY EXIT WINDOW-CABIN								Component	ATA:56
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-20-06										
ATA 57 - WINGS										
5710001 ^S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 57-30-02										PKG:9,12
5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB# 7 AND 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6448		6448		3159.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710004	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTER LINE TO WS 33.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-02										
5710005 ^S	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION - INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5710006	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-06										
5710007 ^S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-12										
5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6730		6730		3441.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-30-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6730		6730		3441.7			
	AFL	0								
PROC. REF: NDT PART 2 / 57-10-02										
571001	WING ASSEMBLY									Component ATA:57
PN:4557000004-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-10-00										
5710010	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6943		6943		3654.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-30-01										
5710011	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 2 / 57-10-03										
5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB# 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6859		6859		3570.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710013	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7885		7885		4596.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710014	* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:9903		9903		6614.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-01										
5710015 ^S	* WING REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-20										PKG:13
5710016	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION - INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7312		7312		4023.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710017	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION - INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710018	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-09										
5710019 ^S	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION - INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710020 ^S		* WING BOX RIBS - PERFORM VISUAL INSPECTION - INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
5710021		* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTER-LINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-02										
5710022		* CENTER SECTION MID SPAR CENTER-LINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTER-LINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7974		7974		4685.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-08, NDT PART 6 / 57-10-10										
5710023		* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-03										
5710024 ^S		* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-06										PKG:13
5710025		* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 2 / 57-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710026	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:8242		8242		4953.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-30-03										
5710028	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7811		7811		4522.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-11										
5710029 ^S	* WING MID SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-07										PKG:9
5710030 ^S	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-05										PKG:9
5710031	* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-30-01										
5710032	* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-30-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710033 ^S	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-05										PKG:13
5710034	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6451		6451		3162.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-13										
5710035 ^S	* WING LOWER SKIN AT DRAIN HOLE - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-30-02										PKG:13
5710037	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:8780		8780		5491.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710039 ^S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14								
	HRS	0	T:10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-18										PKG:13
5710083 ^S	* FLAP BOX STRUCTURE - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-40-02										PKG:13

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710084 ^S		NDT INSPECT SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14								
	HRS	0		T:4800 ^S (+25/-25)						
	AFL	0								
PROC. REF: NDT PART 6 / 57-40-01										PKG:11
5710085 ^S		NDT INSPECT SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14								
	HRS	0		T:10000 ^S (+25/-25)						
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-16										PKG:13
5710086 ^S		NDT INSPECT SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:57
	MOS	22-Nov-14								
	HRS	0		T:10000 ^S (+25/-25)						
	AFL	0								
PROC. REF: NDT PART 7 / 27-10-01										PKG:13
5710121	* WING BOX MID SPAR, OUTBOARD OF RIB #8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:8107	8107		4818.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710122	* WING BOX REAR SPAR, OUTBOARD OF RIB #6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000	10000		6711.7			
	AFL	0								
PROC. REF: GENERIC NO REF										
5710123	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:7167	7167		3878.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710124 ^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	4800 ^S							
	AFL	0								
PROC. REF: NDT PART 4 / 27-10-01										PKG:8
5710137	* MID SPAR AT RIB #2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:8242		8242		4953.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-11A										
5710138	* MID SPAR AT RIB #3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:8242		8242		4953.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-11A										
5710139	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:6943		6943		3654.7			
	AFL	0								
PROC. REF: NDT PART 6 / 57-20-03										
5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7167		7167		3878.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-10-00										
5710176	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: NDT PART 4 / 57-30-05										
5710181 ^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION.									Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 57-30-01										PKG:12

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710182 ^S			* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION.						Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 8 / 57-10-01										PKG:12
5710183 ^S			* WING DRAG LINK CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION.						Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 7 / 57-10-01										PKG:12
5710184 ^S			* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION.						Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 8 / 57-10-02										PKG:13
5710185 ^S			* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION.						Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 7 / 57-10-03										PKG:13
5710186 ^S			* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION.						Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0		T:10000 ^S						
	AFL	0								
PROC. REF: NDT PART 7 / 57-10-02										PKG:13
5710190			* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.						Service	ATA:57
	MOS	22-Nov-14	96		22-Nov-22		OVD			
	HRS	0								
	AFL	0								
PROC. REF: AMM 57-10-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.								Service	ATA:57
	MOS	22-Nov-14	96		22-Nov-22		OVD			
	HRS	0								
	AFL	0								
PROC. REF: AMM 57-10-00										
5730014 ^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION								Service	ATA:57
	MOS	15-Nov-21	12 ^S (+14d/-14d)							
	HRS	3074.4								
	AFL	3067								
PROC. REF: AMM 12-21-03										PKG:1
573090	LH WINGLET ASSY								Component	ATA:57
PN:4557300201-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:W056	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01										
573092	RH WINGLET ASSY								Component	ATA:57
PN:4557300201-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:W056	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-30-01										
574001	WING TEMP (MT42) SENSOR								Component	ATA:57
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
574002	WING TEMP (MT43) SENSOR								Component	ATA:57
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574003	WING TEMP (MT44) SENSOR									Component ATA:57
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
574004	WING TEMP (MT45) SENSOR									Component ATA:57
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
574005	LH INBD LEADING EDGE ASSY									Component ATA:57
PN:4557400005-049	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574007	RH INBD LEADING EDGE ASSY									Component ATA:57
PN:4557400005-050	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574011	LH INBD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-051	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574013	RH INBD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-052	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574033	LH CTR LEADING EDGE ASSY									Component ATA:57
PN:4557400005-041	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574035	RH CTR LEADING EDGE ASSY									Component ATA:57
PN:4557400005-042	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574039	LH OUTBD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-043	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574041	RH OUTBD LEADING EDGE ACCESS SECTION									Component ATA:57
PN:4557400005-044	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574050	LH OTBD ACCESS LEADING EDGE ASSY									Component ATA:57
PN:4557400005-045	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										
574051	RH OTBD LEADING EDGE ASSY									Component ATA:57
PN:4557400005-046	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 57-40-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5750002 ^S		* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-15										PKG:12
5750003 ^S		* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-14										PKG:13
5750004 ^S		* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-21										PKG:9
5750005 ^S		* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:12
575001	LH FLAP ASSY								Component	ATA:57
PN:4557500006-009	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:R0618	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-01										
575002	RH FLAP ASSY								Component	ATA:57
PN:4557500006-010	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:S0645	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-50-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5750048 ^S		* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 57-71-01										PKG:9
5750049 ^S		* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 57-10-04										PKG:9
5750051		* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000		10000		6711.7			
	AFL	0								
PROC. REF: AMM 27-50-01										
5750052		* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:7200		7200		3911.7			
	AFL	0								
PROC. REF: AMM 27-50-01										
5750053 ^S		* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-17										PKG:9
5750068 ^S		* FLAP FRONT SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-26										PKG:13
5760000 ^S		* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION.							Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-25										PKG:9

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5760001 ^S		* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION.								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-19										PKG:9
5760002 ^S		* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION.								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-60-01										PKG:12
5760003 ^S		* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION.								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 2 / 57-60-01										PKG:13
5760004 ^S		* AILERON BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION (NAS6204-16H)								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 7 / 57-60-01										PKG:12
5760005 ^S		* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION.								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-24										PKG:9
5760006 ^S		* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION								Service ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: GENERIC NO REF										PKG:9
576001	LH AILERON ASSEMBLY									Component ATA:57
PN:4557600003-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:S0645	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
5760014 ^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14						CMR*		
	HRS	0	10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-23										PKG:9
576002	RH AILERON ASSEMBLY								Component	ATA:57
PN:4557600003-002	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:S0640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-10-02										
5770000 ^S	NDT INSPECT SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION.								Service	ATA:57
	MOS	22-Nov-14								
	HRS	0	T:10000 ^S (+25/-25)							
	AFL	0								
PROC. REF: NDT PART 6 / 57-10-22										PKG:13
577001	LH SPOILERON ASSY								Component	ATA:57
PN:4557700003-043	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:640	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-01										
577002	RH SPOILERON ASSY								Component	ATA:57
PN:4557700003-044	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:S0649	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-60-01										
ATA 71 - POWER PLANT										
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component	ATA:71
PN:3060757-3	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-150262-34903	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY									Component ATA:71
PN:3060757-3	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-150262-34905	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-00-02, LMM 72-00-02										
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.									Service ATA:71
	MOS	26-Oct-21								
	HRS	3019.1	850 ^S (-350)							
	ENC	3007								
PROC. REF: LMM 72-00-00										
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.									Service ATA:71
	MOS	07-Jun-21								
	HRS	2799.6	850 ^S (-350)							
	ENC	2800								
PROC. REF: LMM 72-00-00										
710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)									Service ATA:71
	MOS	26-Oct-21								
	HRS	3019.1	850 ^S (-350)							
	ENC	3007								
PROC. REF: LMM 72-00-00, LMM 72-00-00										
710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)									Service ATA:71
	MOS	07-Jun-21								
	HRS	2799.6	850 ^S (-350)							
	ENC	2800								
PROC. REF: LMM 72-00-00, LMM 72-00-00										
7110004	TEST LEFT ENGINE ENGINE INLETS - PERFORM TAP-TEST.									Service ATA:71
	MOS	22-Nov-14								
	HRS	0	3500 (+100/-100)		3500	3600	211.7 (+100)			
	AFL	0								
PROC. REF: AMM 71-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7110004	TEST RIGHT ENGINE ENGINE INLETS - PERFORM TAP-TEST.									Service ATA:71
	MOS	22-Nov-14								
	HRS	0	3500 (+100/-100)		3500	3600	211.7 (+100)			
	AFL	0								
PROC. REF: AMM 71-10-01										
711001	LH UPPER ENGINE COWL ASSY									Component ATA:71
PN:2652023-193	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:101322	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-02										
711002	RH UPPER ENGINE COWL ASSY									Component ATA:71
PN:2652023-194	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:821	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-02										
711003	LH LOWER ENGINE COWL ASSY									Component ATA:71
PN:4554300013-037	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1314	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-02										
711004	RH LOWER ENGINE COWL ASSY									Component ATA:71
PN:4554300013-039	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:846	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-02										
711101	LH FWD ENGINE MOUNT									Component ATA:71
PN:4571200011-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:CDF-1541	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
711102	RH FWD ENGINE MOUNT									Component ATA:71
PN:4571200011-003	MOS/MS	22-Nov-14	O/C	TSN 0						
SN:CDF-1544	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120001 ^S	LEFT * FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION.									Service ATA:71
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 71-10-01										
										PKG:13
7120001 ^S	RIGHT * FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION.									Service ATA:71
	MOS	22-Nov-14						CMR*		
	HRS	0	T:10000 ^S							
	AFL	0								
PROC. REF: NDT PART 6 / 71-10-01										
										PKG:13
7120004	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
	MOS	22-Nov-14								
	HRS	0	15000 (+25/-25)		15000	15025	11711.7 (+25)			
	AFL	0								
PROC. REF: AMM 71-20-00										
7120004	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120004	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	11711.7 (+25)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120004	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING									Component ATA:71
	MOS	22-Nov-14								
	HRS	0	15000 (+25/-25)		15000	15025	11711.7 (+25)			
	AFL	0								
PROC. REF: AMM 71-20-00										
7120006	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120006	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS	22-Nov-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0	3500 (+100/-100)	TSN 0	3500	3600	211.7 (+100)			
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712005	NO. 1 AFT ENGINE ISOLATOR									Component ATA:71
PN:LM-833-SA18	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK2190	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712006	NO. 2 AFT ENGINE ISOLATOR									Component ATA:71
PN:LM-833-SA18	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK2147	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120069	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120069	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120069	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
712007	NO. 1 FORWARD UPPER ENGINE ISOLATOR									Component ATA:71
PN:LM-833-45	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK7441	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS									Component ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS									Component ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A							
SN:UNKNOWN	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS									Component ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120070	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								Component	ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
7120070	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								Component	ATA:71
PN:PN	MOS/MSC	22-Nov-14	N/A							
SN:UNKNOWN	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120073	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service	ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
7120073	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS									Service ATA:71
	MOS/MSC	22-Nov-14	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
7120074	* NO. 1 AFT ENGINE MOUNT BOLT - REPLACE									Service ATA:71
	MOS/MSC	06-Feb-18	E/C					CMR*		
	HRS	1461								
	AFL	1388								
PROC. REF: AMM 71-20-00										
7120074	* NO. 2 AFT ENGINE MOUNT BOLT - REPLACE									Service ATA:71
	MOS/MSC	26-Jul-17	E/C					CMR*		
	HRS	1242.7								
	AFL	1201								
PROC. REF: AMM 71-20-00										
712008	NO. 2 FORWARD UPPER ENGINE ISOLATOR									Component ATA:71
PN:LM-833-45	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK7526	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712009	NO. 1 FORWARD LOWER ENGINE ISOLATOR									Component ATA:71
PN:LM-833-45	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK7518	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
712010	NO. 2 FORWARD LOWER ENGINE ISOLATOR									Component ATA:71
PN:LM-833-45	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:LK7530	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-20-00										
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE									Service ATA:71
	MOS	26-Oct-21								
	HRS	3019.1	850 ^S (-350)							
	ENC	3007								
PROC. REF: LMM 72-00-00										
										PKG:0

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
714010 ^S		NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE							Service	ATA:71
	MOS	07-Jun-21								
	HRS	2799.6	850 ^S (-350)							
	ENC	2800								
PROC. REF: LMM 72-00-00										PKG:0
715010 ^S		NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	26-Oct-21								
	HRS	3019.1	850 ^S (-350)							
	ENC	3007								
PROC. REF: LMM 72-00-00										PKG:0
715010 ^S		NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	07-Jun-21								
	HRS	2799.6	850 ^S (-350)							
	ENC	2800								
PROC. REF: LMM 72-00-00										PKG:0
716005	LH NACELLE INLET ASSY								Component	ATA:71
PN:2652000V25-001	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1262	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-01										
716006	RH NACELLE INLET ASSY								Component	ATA:71
PN:2652000V25-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:778	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-10-01										
71EN1	NO. 1 ENGINE								Component	ATA:71
PN:3062075-1	MOS/MSC	06-Feb-18	E/C							
SN:P-137179	HRS	1461		TSN 1427.9						
WC#: 71.EN1	AFL	1388								
PROC. REF: AMM 71-00-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71EN2	NO. 2 ENGINE									Component ATA:71
PN:3062075-1	MOS/MSC	26-Jul-17	E/C							
SN:P-137180	HRS	1242.7		TSN 1193.3						
WC#: 71.EN2	AFL	1201								
PROC. REF: AMM 71-00-01										
ATA 72 - ENGINE										
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	08-Feb-14								
	HRS	0	3500 (+100)		(3500) 3533.1	3600	244.8 (+100)			
	ENC	0								
PROC. REF: LMM 72-00-00										
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	13-Feb-14								
	HRS	0	3500 (+100)		(3500) 3549.4	3600	261.1 (+100)			
	ENC	0								
PROC. REF: LMM 72-00-00										
72-AS-720006 ^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	08-Feb-14								
	HRS	0	3500 ^S (+100/-100)							
	ENC	0								
PROC. REF: GENERIC NO REF										
72-AS-720006 ^S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	13-Feb-14								
	HRS	0	3500 ^S (+100/-100)							
	ENC	0								
PROC. REF: GENERIC NO REF										
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	08-Feb-14								
	HRS	0	7000 (+200)		(7000) 7033.1	7200	3744.8 (+200)			
	ENC	0								
PROC. REF: LMM 72-00-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	13-Feb-14								
	HRS	0	7000 (+200)		(7000) 7049.4	7200	3761.1 (+200)			
	ENC	0								
PROC. REF: LMM 72-00-00										
72-AS-720008 ^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	08-Feb-14								
	HRS	0	7000 ^S (+200/-200)							
	ENC	0								
PROC. REF: GENERIC NO REF, LMM 72-60-02										
72-AS-720008 ^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS									Service ATA:72
	MOS	13-Feb-14								
	HRS	0	7000 ^S (+200/-200)							
	ENC	0								
PROC. REF: GENERIC NO REF, LMM 72-60-02										
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)									Service ATA:72
	MOS/MSC	20-Feb-18	A/R							
	HRS	1451.6								
	ENC	1376								
PROC. REF: LMM 72-00-00										
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)									Service ATA:72
	MOS/MSC	04-Aug-17	A/R							
	HRS	1225								
	ENC	1175								
PROC. REF: LMM 72-00-00										
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)									Service ATA:72
	MOS/MSC	22-Nov-14	A/R							
	HRS	5.9								
	ENC	5								
PROC. REF: LMM 73-21-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)									Service ATA:72
	MOS/MSC	22-Nov-14	A/R							
	HRS	5.9								
	ENC	5								
PROC. REF: LMM 73-21-02										
720110	NO. 1 ENGINE - ACCESSORY GEARBOX									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02										
720110	NO. 2 ENGINE - ACCESSORY GEARBOX									Component ATA:72
PN:3060827-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:S-4238	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-02										
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3071383-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-150211-00270	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3071383-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-150211-00287	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY									Component ATA:72
PN:358750-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162111-13244	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY									Component ATA:72
PN:358750-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-162111-13306	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060150-3	MOS/MSC	22-Jan-18	O/C	TSN 0						
SN:15-169020-01531	HRS	1427.9		TSN 0						
	ENC	1360		TSN 0						
PROC. REF: LMM 72-30-01										
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060150-3	MOS/MSC	03-Jul-17	O/C	TSN 3						
SN:15-169020-02100	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: LMM 72-30-01										
723010 ^S	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH									Service ATA:72
	MOS	26-Oct-21								
	HRS	3019.1	1600 ^S (+50/-100)							
	ENC	3007								
PROC. REF: LMM 72-00-00										
										PKG:0

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723010 ^S	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH									Service ATA:72
	MOS	07-Jun-21								
	HRS	2799.6	1600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 72-00-00										PKG:0
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER									Component ATA:72
PN:3075639-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162397-08705	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER									Component ATA:72
PN:3075639-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-162397-08717	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060437-1	MOS/MSC	22-Jan-18	O/C	TSN 0						
SN:17-152826-65619	HRS	1427.9		TSN 0						
	ENC	1360		TSN 0						
PROC. REF: GENERIC NO REF										
723012	NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060437-1	MOS/MSC	03-Jul-17	O/C	TSN 3						
SN:17-152826-49175	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: GENERIC NO REF										
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER									Component ATA:72
PN:3075633-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162397-07435	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER									Component ATA:72
PN:3075633-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-162397-07434	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060436-1	MOS/MSC	22-Jan-18	O/C	TSN 0						
SN:17-152826-61491	HRS	1427.9		TSN 0						
	ENC	1360		TSN 0						
PROC. REF: GENERIC NO REF										
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060436-1	MOS/MSC	03-Jul-17	O/C	TSN 3						
SN:17-152826-48948	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: GENERIC NO REF										
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL									Component ATA:72
PN:3074108-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:12-169025-00245	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL									Component ATA:72
PN:3074108-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:12-169025-00239	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	A/R	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.500	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060625-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-01098	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12028		8737			
PROC. REF: LMM 72-50-04										
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060625-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-01094	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12044		8753			
PROC. REF: LMM 72-50-04										
725017	NO. 1 ENGINE - HPT SHROUD SLEEVE									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725017	NO. 2 ENGINE - HPT SHROUD SLEEVE									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-07										
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060611-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-00173	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12028		8737			
PROC. REF: LMM 72-50-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component	ATA:72
PN:3060611-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-00810	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12044		8753			
PROC. REF: LMM 72-50-04										
725021	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER								Component	ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725021	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER								Component	ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725022	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD								Component	ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725022	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD								Component	ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component	ATA:72
PN:3060671-2	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-00868	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12028		8737			
PROC. REF: LMM 72-50-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC									Component ATA:72
PN:3060671-2	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156103-00929	HRS	0		TSN 0						
	ENC	0	12000	TSN 0	(12000) 12044		8753			
PROC. REF: LMM 72-50-04										
725031	NO. 1 ENGINE - 3RD-STAGE LTP BLADES									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725031	NO. 2 ENGINE - 3RD-STAGE LTP BLADES									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:3060555-5	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156111-00067	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10028		6737			
PROC. REF: LMM 72-50-07										
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC									Component ATA:72
PN:3060555-5	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:12-156111-00365	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10044		6753			
PROC. REF: LMM 72-50-07										
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
725050	NO. 1 ENGINE - FAN DISC									Component ATA:72
PN:PN	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20028		16737			
PROC. REF: GENERIC NO REF										
725050	NO. 2 ENGINE - FAN DISC									Component ATA:72
PN:3060287-2	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162246-00720	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20044		16753			
PROC. REF: GENERIC NO REF										
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060372-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00712	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10028		6737			
PROC. REF: LMM 72-30-04										
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060372-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00698	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10044		6753			
PROC. REF: LMM 72-30-04										
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075839-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00273	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10028		6737			
PROC. REF: LMM 72-30-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075839-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00818	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10044		6753			
PROC. REF: LMM 72-30-04										
725071	NO. 1 ENGINE - COMBUSTION LINER									Component ATA:72
PN:3060766-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-03523	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725071	NO. 2 ENGINE - COMBUSTION LINER									Component ATA:72
PN:3060766-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-03522	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060374-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00675	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10028		6737			
PROC. REF: LMM 72-30-04										
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3060374-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162045-00656	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10044		6753			
PROC. REF: LMM 72-30-04										
725081	NO. 1 ENGINE - OUTER TRANSITION LINER									Component ATA:72
PN:3060573-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-02935	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725081	NO. 2 ENGINE - OUTER TRANSITION LINER									Component ATA:72
PN:3060573-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-02988	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-03										
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075326-5	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162053-54865	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20028		16737			
PROC. REF: LMM 72-30-04										
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC									Component ATA:72
PN:3075326-5	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162053-54870	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20044		16753			
PROC. REF: LMM 72-30-04										
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:3074744-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13P62787	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD									Component ATA:72
PN:3074744-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13P62792	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-10, LMM 72-30-10, LMM 72-30-10										
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER									Component ATA:72
PN:3060371-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-182449-09499	HRS	0		TSN 0						
	ENC	0	8000	TSN 0	(8000) 8028		4737			
PROC. REF: LMM 72-50-06										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER									Component ATA:72
PN:3060371-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-182449-09493	HRS	0		TSN 0						
	ENC	0	8000	TSN 0	(8000) 8044		4753			
PROC. REF: LMM 72-50-06										
725130	NO. 1 ENGINE - FAN SPINNER									Component ATA:72
PN:3060156-2	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-5060-00130	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20028		16737			
PROC. REF: LMM 72-70-01										
725130	NO. 2 ENGINE - FAN SPINNER									Component ATA:72
PN:3060156-2	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-5060-00131	HRS	0		TSN 0						
	ENC	0	20000	TSN 0	(20000) 20044		16753			
PROC. REF: LMM 72-70-01										
725140	NO. 1 ENGINE - FAN DRIVE SHAFT									Component ATA:72
PN:3060180-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:1216205002342	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725140	NO. 2 ENGINE - FAN DRIVE SHAFT									Component ATA:72
PN:3060180-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1216205002353	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725141	NO. 1 ENGINE - FAN ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725141	NO. 2 ENGINE - FAN ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0				CUSTOMER CODE		
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL									Component ATA:72
PN:3060698-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-162446-00052	HRS	0		TSN 0						
	ENC	0	7000	TSN 0	(7000) 7028		3737			
PROC. REF: LMM 72-70-03										
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL									Component ATA:72
PN:3060698-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:12-162053-47086	HRS	0		TSN 0						
	ENC	0	7000	TSN 0	(7000) 7044		3753			
PROC. REF: LMM 72-70-03										
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT									Component ATA:72
PN:3060366-3	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P64041	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT									Component ATA:72
PN:3060366-3	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64042	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE									Component ATA:72
PN:3060534-4	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-02955	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE									Component ATA:72
PN:3060534-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-02954	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-40-04, LMM 72-40-04										
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS	08-Feb-14		TSN 0				LIFE LIMIT		
SN:13-182449-09483	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10028		6737			
PROC. REF: GENERIC NO REF										
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE									Component ATA:72
PN:3060514-1	MOS	13-Feb-14		TSN 0				LIFE LIMIT		
SN:13-182449-08997	HRS	0		TSN 0						
	ENC	0	10000	TSN 0	(10000) 10044		6753			
PROC. REF: GENERIC NO REF										
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-8	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-02415	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									Component ATA:72
PN:3060694-8	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-02416	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-02250	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT									Component ATA:72
PN:3060693-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-03364	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-11	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-02264	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY									Component ATA:72
PN:3060666-11	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-02512	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-50-04										
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-1034-40066	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING									Component ATA:72
PN:3060502-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-1034-40068	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:3060599-3	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-1034-40495	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING									Component ATA:72
PN:3060599-3	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-1034-40494	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:3073765-12	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-3300-03415	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL									Component ATA:72
PN:3073765-12	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-3300-03420	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY									Component ATA:72
PN:3070093-16	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64285	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-60-03										
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF, LMM 72-00-00										
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF, LMM 72-00-00										
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727001	NO. 1 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:3060163-5	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P63991	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-04										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727001	NO. 2 ENGINE - BYPASS FAN STATOR									Component ATA:72
PN:3060163-5	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P63992	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-04										
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:3061300-8	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-181898-01048	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY									Component ATA:72
PN:3061300-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-181898-01017	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-70-05										
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.									Service ATA:72
	MOS	19-Feb-21								
	HRS	2658.1		1200 ^S (+100/-200)						
	ENC	2646								
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04										
PKG:0										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727010 ^S		NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	13-Feb-20								
	HRS	2292.7	1200 ^S (+100/-200)							
	ENC	2233								
PROC. REF: GENERIC NO REF, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04										PKG:0
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	22-Jan-18	O/C	TSN 0						
SN:17-152826-61799	HRS	1427.9		TSN 0						
	ENC	1360		TSN 0						
PROC. REF: GENERIC NO REF										
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY									Component ATA:72
PN:3060457-1	MOS/MSC	03-Jul-17	O/C	TSN 3						
SN:17-152826-47223	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: GENERIC NO REF										
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:3075657-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162397-03940	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER									Component ATA:72
PN:3075657-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-162397-03934	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:3061510-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162111-19834	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY									Component ATA:72
PN:3061510-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-162111-19837	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727105	NO. 1 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:3060277-4	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:1215611408533	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727105	NO. 2 ENGINE - HELICAL RING GEAR									Component ATA:72
PN:3060277-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1215611408534	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727107	NO. 1 ENGINE - SUN GEAR									Component ATA:72
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727107	NO. 2 ENGINE - SUN GEAR									Component ATA:72
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727203	NO. 1 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:3060212-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-162255-33023	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727203	NO. 2 ENGINE - NO. 3 BALL BEARING									Component ATA:72
PN:3060212-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:12-162255-27358	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-30-01										
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:3060121-8	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:1216224301181	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY									Component ATA:72
PN:3060121-8	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1216224301178	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-1	NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13P62074	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-1	NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64280	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-2	NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P64228	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-2	NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64281	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727210-3	NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P64229	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-3	NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64282	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P64230	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64283	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14P64231	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY									Component ATA:72
PN:3060129-7	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14P64284	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 72-72-03										
ATA 73 - ENGINE FUEL AND CONTROL										
730110	NO. 1 ENGINE - FUEL CONTROL UNIT									Component ATA:73
PN:3070800-47	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:20397	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
730110	NO. 2 ENGINE - FUEL CONTROL UNIT									Component ATA:73
PN:3070800-47	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:20398	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
730120 ^S	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT									Service ATA:73
	MOS	27-Mar-22								
	HRS	3252.7	600 ^S (+50/-100)							
	ENC	3259								
PROC. REF: LMM 73-21-02, LMM 73-21-02										
730120 ^S	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT									Service ATA:73
	MOS	07-Jun-21								
	HRS	2799.6	600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 73-21-02, LMM 73-21-02										
730130	NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY									Component ATA:73
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01										
730130	NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY									Component ATA:73
PN:3060760-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:3547	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01										
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY									Component ATA:73
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-21-02										
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY									Component ATA:73
PN:70060003-1	MOS/MSC	01-Jun-17	O/C							
SN:12-30003-00010	HRS	1186.9								
	ENC	1144								
PROC. REF: LMM 73-21-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-1	NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00636	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-01150	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-10	NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00637	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-01171	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-11	NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00646	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-01174	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-12	NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00647	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-12	NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-01177	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-2	NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00649	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-2	NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00018	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-3	NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00650	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-3	NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00019	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-4	NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00651	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00020	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-5	NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00652	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00021	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-6	NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00653	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00024	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731005-7	NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00654	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00026	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-8	NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00655	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00028	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-9	NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-163498-00656	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY									Component ATA:73
PN:3060540-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-163498-00063	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR									Component ATA:73
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR									Component ATA:73
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:3070685-11	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:18899	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE									Component ATA:73
PN:3070685-11	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:18894	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 73-20-01										
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:394476-2	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:3723	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE									Component ATA:73
PN:394476-2	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:3725	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732102	NO. 1 ENGINE - RELIEF VALVE									Component ATA:73
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732102	NO. 2 ENGINE - RELIEF VALVE									Component ATA:73
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	27-Mar-22								
	HRS	3252.7	600 ^S (+50/-100)							
	ENC	3259								
PROC. REF: LMM 72-00-00, LMM 73-21-04										PKG:0
732120 ^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE									Service ATA:73
	MOS	07-Jun-21								
	HRS	2799.6	600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 72-00-00, LMM 73-21-04										PKG:0
733013	FUEL FLOW, DUAL CONVERTER									Component ATA:73
PN:6673308500-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:14061343A	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-31-02										
733031	ELECTRICAL RESISTANCE (FUEL - LH) TEMPERATURE BULB									Component ATA:73
PN:MS28034-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:DP238	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-31-03										
733032	ELECTRICAL RESISTANCE (FUEL - RH) TEMPERATURE BULB									Component ATA:73
PN:MS28034-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:DN797	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-31-03										
ATA 74 - IGNITION										
740110	NO. 1 ENGINE - IGNITION UNIT									Component ATA:74
PN:3061186-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:J13460385	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
740110	NO. 2 ENGINE - IGNITION UNIT									Component ATA:74
PN:3061186-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:J13460387	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG									Component ATA:74
PN:3060722-12	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:S13320009	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG									Component ATA:74
PN:3074541-4	MOS/MSC	03-Jul-17	O/C	TSN 2						
SN:UNKNOWN	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: LMM 74-00-01										
740140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	26-Oct-21								
	HRS	3019.1	1600 ^S (+50/-100)							
	ENC	3007								
PROC. REF: LMM 74-00-01, LMM 74-00-01										PKG:0
740140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD									Service ATA:74
	MOS	07-Jun-21								
	HRS	2799.6	1600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 74-00-01, LMM 74-00-01										PKG:0
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG									Component ATA:74
PN:3060722-12	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:S13320009	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG									Component ATA:74
PN:3074541-4	MOS/MSC	03-Jul-17	O/C	TSN 2						
SN:UNKNOWN	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: LMM 74-00-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
740160 ^S		NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	26-Oct-21								
	HRS	3019.1	1600 ^S (+50/-100)							
	ENC	3007								
PROC. REF: LMM 74-00-01										PKG:0
740160 ^S		NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	07-Jun-21								
	HRS	2799.6	1600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 74-00-01										PKG:0
742011	NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD								Component	ATA:74
PN:3060722-11	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:S13360003	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
742011	NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD								Component	ATA:74
PN:3060722-11	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:S14020008	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
742012	NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD								Component	ATA:74
PN:3060722-12	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:S13320009	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 74-00-01										
742012	NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD								Component	ATA:74
PN:3060722-12	MOS/MSC	03-Jul-17	O/C	TSN 0						
SN:S16320065	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: LMM 74-00-01										
742020	NO. 1 ENGINE - IGNITION EXCITER								Component	ATA:74
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742020	NO. 2 ENGINE - IGNITION EXCITER								Component	ATA:74
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 75 - AIR										
754210	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								Component	ATA:75
PN:3070816-14	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:1316901724314	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										
754210	NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								Component	ATA:75
PN:3070816-14	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:136901724313	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01										
761310	NO. 1 ENGINE - SURGE BLEED VALVE								Component	ATA:75
PN:978812-7-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14832	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761310	NO. 2 ENGINE - SURGE BLEED VALVE								Component	ATA:75
PN:978812-7-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14833	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
ATA 76 - ENGINE CONTROLS										
7600001 ^S	FUNCTIONAL TEST THRUST LEVER CONTROL MODULE								Service	ATA:76
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 76-10-02										PKG:7

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761003	L/H THROTTLE CABLE									Component ATA:76
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761004	R/H THROTTLE CABLE									Component ATA:76
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-10-01										
761005	THRUST LEVER CONTROL MODULE									Component ATA:76
PN:69011-21	MOS/MSC	31-May-19	O/C							
SN:1148009	HRS	2067.7								
	AFL	1977								
PROC. REF: AMM 76-10-02										
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE									Component ATA:76
PN:109696-6-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14189	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE									Component ATA:76
PN:109696-6-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14190	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01										
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER									Component ATA:76
PN:2118882-8001	MOS/MSC	03-Dec-14	O/C							
SN:103-BP0061	HRS	29.7								
	ENC	37								
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER									Component ATA:76
PN:2118882-8001	MOS/MSC	03-Dec-14	O/C							
SN:98-BP0058	HRS	29.7								
	ENC	37								
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM									Service ATA:76
PN:2118882-8001	MOS	09-Mar-22						CUSTOMER CODE		
SN:103-BP0061	HRS	3222.5	50		(3272.5) 3305.6		17.3			
	ENC	3222								
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00										
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM									Service ATA:76
PN:2118882-8001	MOS	09-Mar-22						CUSTOMER CODE		
SN:98-BP0058	HRS	3206.2	50		(3256.2) 3305.6		17.3			
	ENC	3206								
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-02, LMM 72-00-00										
ATA 77 - ENGINE INDICATING										
770101	NO. 1 ENGINE - N1 MONOPOLE									Component ATA:77
PN:3060714-5	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14910300006	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
770101	NO. 2 ENGINE - N1 MONOPOLE									Component ATA:77
PN:3060714-5	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:14910300013	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
770110	NO. 1 ENGINE - N1 LEAD MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-02										
770110	NO. 2 ENGINE - N1 LEAD MONOPOLE									Component ATA:77
PN:3060718-4	MOS/MSC	12-Dec-14	O/C	TSN 1						
SN:14-150262-37555	HRS	51.6		TSN 0						
	ENC	54		TSN 0						
PROC. REF: LMM 77-10-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
771210	NO. 1 ENGINE - N1 COMPENSATOR									Component ATA:77
PN:3060735-4	MOS/MSC	11-Dec-14	O/C	TSO 0						
SN:981309700388	HRS	51.1		TSO 0						
	ENC	53		TSO 0						
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03										
771210	NO. 2 ENGINE - N1 COMPENSATOR									Component ATA:77
PN:3060735-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1316909400636	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03										
771220	NO. 1 ENGINE - N2 MONOPOLE									Component ATA:77
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										
771220	NO. 2 ENGINE - N2 MONOPOLE									Component ATA:77
PN:3070722-8	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13910300192	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05										
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY									Component ATA:77
PN:3060763-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:1316901740688	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY									Component ATA:77
PN:3060763-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1316901740684	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01										
774001	ENGINE VIBRATION SIGNAL CONDITIONER BOX									Component ATA:77
PN:241-241-000-501	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:AK58305	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
774010	TAILCONE/VERT STAB ASSY RELAY BOX									Component ATA:77
PN:4520008441-003	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:B0374	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-03										
7741000 ^S	FUNCTIONAL TEST ENGINE VIBRATION MONITORING SYSTEM									Service ATA:77
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 77-41-00										PKG:7
774103	GSC46 (PRIMARY) SIGNAL CONDITIONER									Component ATA:77
PN:013-00337-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:352	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-04										
774104	GSC46 (SECONDARY) SIGNAL CONDITIONER									Component ATA:77
PN:013-00337-10	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:353	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 77-41-04										
ATA 78 - EXHAUST										
7830007	CHECK THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST.									Service ATA:78
	MOS	13-Jan-22								
	HRS	3155.3								
	AFL	3154								
	APH	1194	1200 (+25/-25)	Adj 6	2400	2425	1152 (+25)			
PROC. REF: NDT PART 6 / 78-30-01										
783001	LEFT THRUST REVERSER ASSY									Component ATA:78
PN:6678300000-025	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A30040651	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783001A	LEFT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783002	RIGHT THRUST REVERSER ASSY									Component ATA:78
PN:6678300000-026	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:A30040651	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783002A	RIGHT INBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783003A	LEFT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
783004A	RIGHT OUTBOARD THRUST REVERSER ACTUATOR									Component ATA:78
PN:PN	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00										
7830078 ^S	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK									Service ATA:78
	MOS	13-Feb-20	108 ^S (+14d/-14d)					CMR**		
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: AMM 78-32-40										
										PKG:7

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
7830081 ^S		NDT INSPECT LEFT ENGINE THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:78
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: NDT PART 7 / 78-30-01										PKG:7
7830081 ^S		NDT INSPECT RIGHT ENGINE THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION.							Service	ATA:78
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: NDT PART 7 / 78-30-01										PKG:7
7830082 ^S		NDT INSPECT LEFT ENGINE THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES.							Service	ATA:78
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: NDT PART 6 / 78-30-02, NDT PART 6 / 78-30-03										PKG:7
7830082 ^S		NDT INSPECT RIGHT ENGINE THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES.							Service	ATA:78
	MOS	13-Feb-20	108 ^S (+14d/-14d)							
	HRS	2342.1	2400 ^S (+25/-25)							
	AFL	2277								
PROC. REF: NDT PART 6 / 78-30-02, NDT PART 6 / 78-30-03										PKG:7
783101	LEFT THRUST REVERSER ISOLATION VALVE								Component	ATA:78
PN:6678300000-023	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1441	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-30-02										
783102	RIGHT THRUST REVERSER ISOLATION VALVE								Component	ATA:78
PN:6678300000-023	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:1436	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 78-30-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783301	LEFT THRUST REVERSER CONTROL UNIT									Component ATA:78
PN:LJ7836706-3	MOS/MSC	29-Aug-17	O/C							
SN:887	HRS	1295.5		TSN 1280.9						
	AFL	1236		TSN 1223						
PROC. REF: AMM 78-33-10										
783302	RIGHT THRUST REVERSER CONTROL UNIT									Component ATA:78
PN:LJ7836706-3	MOS/MSC	29-Aug-17	O/C							
SN:848	HRS	1295.5		TSN 1280.9						
	AFL	1236		TSN 1223						
PROC. REF: AMM 78-33-10										
ATA 79 - OIL										
790110	NO. 1 ENGINE - OIL PUMP									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
790110	NO. 2 ENGINE - OIL PUMP									Component ATA:79
PN:3060785-3	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:1316225400153	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
790130 ^S	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)									Service ATA:79
	MOS	18-Jan-22								
	HRS	3125.3	150 ^S (+100)							
	ENC	3131								
PROC. REF: LMM 72-00-00										
790130 ^S	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)									Service ATA:79
	MOS	18-Jan-22								
	HRS	3109	150 ^S (+100)							
	ENC	3115								
PROC. REF: LMM 72-00-00										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
790140 ^S		NO. 1 ENGINE - PERFORM OIL CHANGE								Service ATA:79
	MOS	19-Feb-21								
	HRS	2658.1	1200 ^S (+100/-200)							
	ENC	2646								
PROC. REF: LMM 72-00-00										PKG:0
790140 ^S		NO. 2 ENGINE - PERFORM OIL CHANGE								Service ATA:79
	MOS	13-Feb-20								
	HRS	2292.7	1200 ^S (+100/-200)							
	ENC	2233								
PROC. REF: LMM 72-00-00										PKG:0
790150 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service ATA:79
	MOS	27-Mar-22								
	HRS	3252.7	600 ^S (+50/-100)							
	ENC	3259								
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0
790150 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK								Service ATA:79
	MOS	07-Jun-21								
	HRS	2799.6	600 ^S (+50/-100)							
	ENC	2800								
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0
790160 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service ATA:79
	MOS	18-Jan-22								
	HRS	3125.3	150 ^S (+100)							
	ENC	3131								
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0
790160 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION								Service ATA:79
	MOS	18-Jan-22								
	HRS	3109	150 ^S (+100)							
	ENC	3115								
PROC. REF: LMM 79-10-01, LMM 79-10-01										PKG:0
791001		NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR								Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-10-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-10-01										
792002	NO. 1 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02										
792002	NO. 2 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02										
792005	NO. 1 ENGINE - OIL TANK ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-10-02										
792005	NO. 2 ENGINE - OIL TANK ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-10-02										
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE									Component ATA:79
PN:3060769-1	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:13-182215-12202	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08										
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE									Component ATA:79
PN:3060769-1	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:13-182215-12199	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-08										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792011	NO. 1 ENGINE - FUEL/OIL VALVE									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792011	NO. 2 ENGINE - FUEL/OIL VALVE									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-03										
792020	NO. 1 ENGINE - OIL CHECK VALVE ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
792020	NO. 2 ENGINE - OIL CHECK VALVE ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY									Component ATA:79
PN:160552-4	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:2278	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY									Component ATA:79
PN:160552-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:2279	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY									Component ATA:79
PN:160554-5	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:3691	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY									Component ATA:79
PN:160554-5	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:3692	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY									Component ATA:79
PN:160554-6	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:3736	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY									Component ATA:79
PN:160554-6	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:3743	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-10										
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02										
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-02										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:158465-6	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:14058	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE									Component ATA:79
PN:3075818-1	MOS/MSC	03-Jul-17	O/C	TSN 0						
SN:17-152826-44949	HRS	1193.3		TSN 0						
	ENC	1157		TSN 0						
PROC. REF: LMM 79-30-01										
793011	ELECTRICAL RESISTANCE (OIL - LH) TEMPERATURE BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	22-Nov-14	O/C	TSN 0						
SN:DP243	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-30-03										
793012	ELECTRICAL RESISTANCE (OIL - RH) TEMPERATURE BULB									Component ATA:79
PN:MS28034-3	MOS/MSC	29-Dec-14	O/C	TSN 0						
SN:186756	HRS	63.8		TSN 0						
	AFL	68		TSN 0						
PROC. REF: AMM 79-30-03										
793064	NO. 1 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793064	NO. 2 ENGINE - TEMP BULB									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-30-01										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE									Component ATA:79
PN:3060782-2	MOS/MSC	22-Feb-20	O/C	TSN 0						
SN:213859	HRS	2313.2		TSN 0						
	ENC	2242		TSN 0						
PROC. REF: LMM 79-30-01										
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH									Service ATA:79
	MOS	19-Feb-21								
	HRS	2658.1	1200 ^S (+100/-200)							
	ENC	2646								
PROC. REF: LMM 79-30-01										PKG:0
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH									Service ATA:79
	MOS	13-Feb-20								
	HRS	2292.7	1200 ^S (+100/-200)							
	ENC	2233								
PROC. REF: LMM 79-30-01										PKG:0
793316	NO. 1 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793316	NO. 2 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY									Component ATA:79
PN:PN	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY									Component ATA:79
PN:3060709-4	MOS/MSC	08-Feb-14	O/C	TSN 0						
SN:3747	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-07										
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY									Component ATA:79
PN:3060709-4	MOS/MSC	13-Feb-14	O/C	TSN 0						
SN:3748	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: LMM 79-20-07										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 99 - OPTIONAL KITS										
9900023	GVI OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900023										
9900024	GVI HARD LANDING INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900024										
9900025	GVI SEVERE TURBULENCE AND/OR MANEUVERS INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900025										
9900026	UNSCHEDULED ENGINE CHANGE INSPECTION									Service ATA:99
	MOS/MSC	06-Feb-18	A/R							
	HRS	1461								
	AFL	1388								
PROC. REF: EMP 9900026										
9900027	DVI HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF).									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900027										
9900028	OP/CK THRUSTS REVERSER INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 78-30-00, EMP 9900028										
9900029	GVI OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AT HIGH SPEED).									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900029										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 99 - OPTIONAL KITS										
9900030	GVI LIGHTNING STRIKE INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900030										
9900031	GVI HIGH GROUND WIND GUST INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900031										
9900032	GVI HEAT DAMAGE INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900032										
9900033	F/C NACELLE HEAT FAIL MESSAGE INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900033										
9900034	DVI ELEVATOR DISCONNECT INSPECTION.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 55-20-00, EMP 9900034										
9900035	GVI WING FLAP SYSTEM OVERSPEED CHECK.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-50-00, EMP 9900035										
9900036	NDT INSPECT PRESSURE CABIN SKIN THICKNESS MEASUREMENTS.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 6 / 53-10-01, EMP 9900036										

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 99 - OPTIONAL KITS										
9900037	GVI VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: EMP 9900037										
9900038	GVI INSPECTION OF AIRCRAFT OPERATIONS IN SALT INFLUENCED ENVIRONMENTS.									Service ATA:99
	MOS/MSC	22-Nov-14	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 12-24-00, EMP 9900038										
9900052	FOREIGN OBJECT DAMAGE INSPECTION									Service ATA:99
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
9900053	ENGINE VIBRATION INDICATION INSPECTION									Service ATA:99
	MOS/MSC		A/R							
	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
9910000 ^S	GVI ENGINE ZONAL INSPECTION									Service ATA:99
	MOS	13-Feb-20	36 ^S (+14d/-14d)							
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910000										PKG:2
9910001 ^S	GVI EXTERIOR AIRCRAFT ZONAL INSPECTION.									Service ATA:99
	MOS	13-Feb-20	36 ^S (+14d/-14d)							
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910001										PKG:2
9910002 ^S	GVI LANDING GEAR ZONAL INSPECTION.									Service ATA:99
	MOS	13-Feb-20	36 ^S (+14d/-14d)							
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910002										PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task

Status Report

Model: LEARJET 75 Serial: 45-496 RegNo: N877W HRS: 3288.3 AFL: 3291 As Of: 01-Apr-2022

12-Dec-2022 10:34 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 99 - OPTIONAL KITS										
9910003 ^S		GVI AFT FUSELAGE ZONAL INSPECTION.							Service	ATA:99
	MOS	13-Feb-20	72 ^S	(+14d/-14d)						
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910003										PKG:3
9910004 ^S		GVI NOSE ZONAL INSPECTION.							Service	ATA:99
	MOS	13-Feb-20	72 ^S	(+14d/-14d)						
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910004										PKG:3
9910005 ^S		GVI WING ZONAL INSPECTION.							Service	ATA:99
	MOS	13-Feb-20	72 ^S	(+14d/-14d)						
	HRS	2342.1								
	AFL	2277								
PROC. REF: EMP 9910005										PKG:3
9910006 ^S		GVI COCKPIT ZONAL INSPECTION.							Service	ATA:99
	MOS	22-Nov-14	108 ^S	(+14d/-14d)						
	HRS	0								
	AFL	0								
PROC. REF: EMP 9910006										PKG:4
9910007 ^S		GVI FUSELAGE ZONAL INSPECTION.							Service	ATA:99
	MOS	22-Nov-14	108 ^S	(+14d/-14d)						
	HRS	0								
	AFL	0								
PROC. REF: EMP 9910007										PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task