

The Standard

1910

1910

YEAR: 2023 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/19	9-24.1		926.6	VANS SB 14-02-05, 14-01-31, 16-03-28 C/W NO CRACKS FOUND tTT <u>926.6</u> Date <u>10-18-2023</u> This <u>AIRCRAFT</u> has been inspected in accordance with an annual Condition inspection within the scope and detail of F.A.R. 43 D and any pertinent I.C.A. s and is found to be in a condition for safe flight at this time. Ray L. Ender A&P 3201529 IA <u>Ray L. Ender</u> Wheel bearings ✓ Brake pads ✓ Rod ends Lubed, Tailwheel serviced <u>ATP 1905214</u>

YEAR: 2023 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12/17	928.1		930.6	Mixture cable replaced 184112 ^{CT-Q} - 70.5 <u>ATP 1905214</u>
10/19/24	972.7		975.2	N42CS tTT <u>975.2</u> Date <u>10/19/2024</u> This <u>AIRCRAFT</u> has been inspected in accordance with an annual Condition inspection within the scope and detail of F.A.R. 43 D and any pertinent I.C.A. s and is found to be in a condition for safe flight at this time. Ray L. Ender A&P 3201529 IA <u>Ray L. Ender</u> 10-9-24 TTAF 975.2 Wheel Bearings ✓ Brake Pads ✓ Rod End Lubed Tailwheel serviced Port R seat belts replaced. ELT Battery replaced GS-46 # 05926

YEAR: 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11-21	791.6		793.8	TT <u>793.8</u> Date <u>11-1-2021</u> This AIRCRAFT has been inspected in within <u>SEE NOTE #1</u> scope and detail of F.A.R. 43D and any pertinent manufacture inspections for an annual condition inspection and is found to be in condition for safe <u>PREVIOUS PAGE</u> flight at this time. Ray L Ender A & P 3201529 <u>Ray L Ender</u> Inspection Authorization
11/13/21	791.6		793.8	Replacement Rudder installed, GROUND and Flight Checked, satisfactory and AIRWORTHY <u>ATP 1905214</u>

YEAR: 2022 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/11	804.5		806.7	Throttle cable replaced. <u>ATP 1905214</u>
10-26	861.9		864.1	TT <u>864.1</u> Date <u>10-26-2022</u> This AIRCRAFT has been inspected in accordance with an annual Condition inspection within the scope and detail of F.A.R. 43 D and any pertinent I.C.A. s and is found to be in a condition for safe flight at this time. Ray L. Ender A&P 3201529 IA <u>Ray L Ender</u> N 42CS
10-26	861.9		864.1	Van SB14-02-05, 14-01-31, 16-03-28 C/W NO CRACKS FOUND

YEAR: 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1/25	759.5		759.2	GA35 WAAS GPS ANTENNA Replaced ATP # 1905214
1/30	756.5		759.2	TIRES Replaced - Wilkeron Recaps ATP # 1905214
3/3	762.0		765.0	400W Battery replaced. Mcke AVIONICS FAR 91.413 TRANSPONDERS and ALTITUDE REPORTING SYSTEMS The required tests and inspections as marked were performed in accordance with current approved procedures, and the equipment and/or systems complied with all requirements.
4/23	765.6		768.6	✓ PT 43 APPX F. TXP #1 GTX 327 S/N 8371616 ON 4/23/21 PT 43 APPX F. TXP #2 N/A S/N N/A ON N/A ✓ PT 43 APPX E. C. INTEGRATED SYSTEM TEST ON 4/23/21 FOR DETAILS SEE WO NO. 27046 DATED 4/23/21 SIGNED Joe M. Lee CERT NO. 2711073

MCKEE AVIONICS INC., SAN MARCOS, TEXAS
CRS-EEKR429K

YEAR: 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/2	768.3		771.3	Removed Oddesey PC 680 Ship Battery and installed EarthX Ship Battery, Model ETX 900. Removed Hartzell Propeller and installed Hartzell Model HC-G2YR-1NWX/N7605W/2X Propeller, Hub Seral # B38385B, Blade #s: C8198, C8199. New weight and balance calculated. Empty weight 1150.5, CG 78.5. ATP 1905214
7/7	772.0		775.0	GARMIN 400W Refurbished by GARMIN + Installed ATP 1905214
11-1-21	791.6		793.8	VANSB 14-02-05, 14-01-31, 16-03-28 C/W NO CRACKS FOUND
11-1-21	791.6		793.8	NOTE #1 THIS AIRCRAFT WAS MISSING THE RUDDER AND A REPLACEMENT RUDDER MUST BE REPAIRED OR INSTALLED NEW IN ACCORDANCE W/ MANUFACTURERS INSTRUCTIONS AND ANGLE OF DEFLECTION SET BEFORE AIRCRAFT IS AIRWORTHY. LOGBOOK ENTRY REQUIRED Ray S. Bender ATP 32015291A CONTY

10/24/19 663.8

$$\frac{1}{25}$$

EARTH x Battery Removed, dead cell. ETK 20L AGM
Battery installed. *MA* ATP1905214

YEAR: 2017 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/3			514.2	Installed new PC925 Odyssey Battery MMP ATP # 1905214
2018				Installed Garmin
3/2			530.1	FAR 91.413 TRANSPONDERS and ALTITUDE REPORTING Systems The required tests and inspections as marked were performed in accordance with current approved procedures, and the equipment and/or systems complied with all requirements. ✓ PT43. APPX F. TXP #1 GTX327 SN 83716106 ON 3-2-18 — PT43. APPX F. TXP #2 N/A SN N/A ON N/A ✓ PT43. APPX E. C. INTEGRATED SYSTEM TEST ON 3-2-18 FOR DETAILS. SEE WO NO 26445 DATED 2-25-18 3-2-18-EM SIGNED Joe McKee CERT NO. 2711073 MCKEE AVIONICS INC., SAN MARCOS, TEXAS CRS-EEKR429K

YEAR: 2018 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3/2	530.1		530.1	GARMIN GTX 327 Transponder installed MMP ATP # 1905214
3/7			530.1	Installed uAvionix Echo UAT ADSB, IAW 91.225 + 91.227 MMP ATP # 1905214
3/23			533.3 530.1	Installed PMAG, Left mag replaced. MMP ATP-1905214
5/15			544.6	Tailwheel service - clean + lube MMP ATP-1905214
9/21			575.3	Tires Rotated, bearings serviced, brake pads checked MMP ATP-1905214
			584.8	Propellers Inspected. PMAG A & P 2230759

[illegible]

YEAR: 16 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10-01			437.9	I CERTIFY that this Aircraft has been inspected with the scope and detail of appendix D Part 43 and found in condition for safe flight Tim Moss ATP # 2746314
10-1			437.9	VAN SB 14-02-05 AND SB 16-03-28 complied with, no cracks found. VAN 14-01-31 complied with, no cracks found. VANS 12-05, 14 inspected + installed. [Signature] ATP # 1905214

YEAR: 2013 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
08-26	179.0		201.0	I certify that this AIRCRAFT has been inspected in accordance with the scope and detail of appendix D of Part 43 and found to be in condition for safe flight operation Tim Moss A/P 2746314
2014				
02/06			236.1	VANS S.B. 140131 complied with, no cracks found
02/06			236.1	VANS S.B. 140203 complied with, no cracks found ATP # 1905214
04/15			236.1	Exchanged propellers, no effect on weight & balance ATP # 1905214

YEAR: 2014 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
09-01			271.2	I certify that this AIRCRAFT has been inspected in accordance with the scope and detail of appendix D of Part 43 and found to be in condition for safe flight operation Tim Moss ATP 2746314
09-01			271.2	VANS S.B. 140131 complied with, no cracks found
09-01			271.2	VANS S.B. 140205 complied with, no cracks found ATP # 1905214

[illegible][illegible]

[illegible]

AVIONICS

Notes

Replaced

- KT76C BENDIX/KING TRANSPONDER P/N 066-01156-0101 S/N - X12881/with GTX 327
- ICOM-1C-A200 S/N T51017 COM-1
- ICOM-1C-A700 S/N T50816 COM-2
- GARMIN 150XL GPS P/N 011-00345-00 S/N 81703873 - Replaced with 400W
- AUDIO PANEL BENDIX/KING KA134 S/N 14640
- MARKER BEACON - BENDIX/KING - Removed
- AIR FILTER^H F33-2060
- OIL FILTER CH48109-1

Aircraft Record General Information

Manufacturer VANS AIRCRAFT Model VAN'S AIRCRAFT RV-8

Serial 80546 Registration Number N42CS

Date of Manufacture 7-2003

Engine(s) currently installed:

Manufacturer LYCOMING Model IMO360B1B Serial L-204-46

Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer HARTZELL ~~#6-600R-1A~~ Model HC-G24R-1BFP/E7427 ~~HC-G24R-1BFP/E7427~~

TUB Model ~~D-6529-1~~ Serial ~~NS1750B~~ Serial B38385B

Blade Model ~~(#1) J83219~~ Serial ~~#1-145242~~ Serial C8198 Serial _____

Blade Model ~~(#2) J83216~~ Serial ~~#2-142061~~ Serial C8199 Serial _____