



Costa Mesa, CA 92626

949-373-7424

FAA CRS BKER301L

INSPECTION / MAINTENANCE RECORD

MODEL: PW535E

WORK ORDER: 14476

SERIAL NUMBER: PCE-DG0339

REG. NUMBER: N16GF

The following Inspections / Maintenance was accomplished:

<u>Sqwk#</u>	<u>Task/MM</u>	<u>Description</u>
1.1	05-50-00	Inspected the nose cone, fan blades, fan case, and fan exit stators. Rotated N1 for unusual noise/vibration. No discrepancy or damage noted.
	72-00-00	Performed Right Engine Combustion liner borescope for damage and FOD.
	72-00-00	Performed Borescope Right Engine first stage turbine. No discrepancy noted.
	72-00-00	Borescope Inspection of the First-stage High-compressor Rotor. No discrepancy noted.
	73-11-01	Performed Right engine Fuel filter detailed inspection. No discrepancy noted.
	79-21-00	Performed Right engine Fuel filter detailed inspection. No discrepancy noted.
	79-35-00	Performed inspection of Right Engine Metal detector. No discrepancy noted.
	24-31-01	Removed and reinstalled Right Engine Starter Generator. Performed inspection and rotated N2 for unusual noise/ vibration. No discrepancy noted.

Engine Hours: 2396.4

Engine Cycles: 1359

I certify that this engine has been inspected in accordance with approved inspections program as required under 14CFR Part 91.409 (f)(3). All items required to be inspected were inspected and there are no known conditions that exist which would make the aircraft unairworthy. Further details of this inspection and related maintenance are on file at this Repair Station under the above Work Order No: 14476

March 2, 2023

Noel E. Madlangbayan Jr. (Signature of Authorized Representative)
CRS BKER301L