



PROPELLER LOGBOOK

The subject aircraft was involved in an incident / accident on 9/7/2025 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 3141260555US.

Signed: ***Underwriters Salvage Company***

Date: **11/3/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

FAA AIRWORTHINESS DIRECTIVES COMPLIANCE RECORD

N43601

HARTZELL HC-C2YK-1BF, SN: CH41954B

01 NOV 2024

TACH: 3627.89

SMOH: 141.02

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Edward J. Cervantes
Edward J. Cervantes, AP27492891A

		Signature: _____
Year: _____	Total Hours	Complied by the following: _____ _____ _____ _____ _____
Date: _____		
A.D. #		
Next Inspection Due:		

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
------	----------------------	---------------------	---------------------	---

N43601

HARTZELL HC-C2YK-1BF, SN: CH41954B

01 OCT 2023

TACH: 3611.17

SMOH: 124.30

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Edward J. Cervantes
Edward J. Cervantes, AP2749289IA

N43601

HARTZELL HC-C2YK-1BF, SN: CH41954B

01 NOV 2024

TACH: 3627.89

SMOH: 142.42

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Edward J. Cervantes
Edward J. Cervantes, AP2749289IA

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
June 17 2020		"0"	Propeller completely overhauled LAW. OITM 1138 Rev 1/16, 150M 133C Rev 79 SPM 2024 Service Manuals All A.D.'s, S/B's, S/L's complied with to date. Pertinent details of this overhaul are on file under W.O. 020-230 at the following repair facility:	
			Johnson Propeller Ent., Inc. 211 Aviation St. hgr 104 Shafter, CA 93263 661-399-2480 FAA CRS # J3PR491J	Juan Salais 382686

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12



12659 Osborne St., Pacoima, CA, 91331-2192
Phone # 818-899 7468

MAINT

Date	Total Propeller Time	
		N43601 Tach: 3486.36 06/25/2020 Installed propeller after overhaul by CRS J3PR491J, W/O 020-230. Functional check, normal.
		AP 2827603
		N43601 HARTZELL HC-C2YK-1BF, SN: CH41954B SMOH: 99.10 TACH: 3585.97 01 SEP 2022 I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.
		Edward J. Cervantes, AP2749289IA

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Piper PA-28-140

Owner Name CECELIA STRATFORD

Address 607 HAWKS BICK PL.

SIMI VALLEY CA 93065

Propeller Model HC-C2YK-1BF

Blade Model FC7666A-2

Hub Serial No. CH41954B

Blade Serial No. 1 E49247

2 E49261

3 ~~~~~

4 ~~~~~