

N 57679



The Standard

ENGINE LOG

ASA-SE-1

The subject aircraft was involved in an incident / accident on 9 / 9 / 23 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim:

6332268746 US

Signed Charley Stanton


Date 10 / 10 / 23

AIG Aerospace Adjustment Services, Inc.

3500 Lenox Road, Suite 1100

Atlanta, GA. 30326

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				<u>Airplane Repair Inc Gillespie Airport 1965 N Marshall Ave El Cajon CA 619-940-8310</u>
	20 May 23			SMOH 942.0 Lyc O-320-A2B N57679
	Tach 1844.8			TSN ukn s/n L-27339-27A Bellanca 7ECA
				-this engine has been installed per stc SA02979CH from HO Aircraft for details see Form 337
				-installed a B&C spin on oil filter adapter iaw stc SE00825W1 for details see Form 337
				-installed new engine rubber mounts J-6230-1 and hardware * * *
				-installed ovh carburetor 10-3678-32 sn A-10-9626
				-fabricated two aeroquip 303 oil cooler hoses
				-R&R of engine mount for sand blast and powder coat and new hardware
				-installed new BA8103-1 filter element
				-modified existing baffling to accommodate new engine
				-installed new single muffler exhaust system with new ducts
				I certify that this Engine has been inspected in accordance with an ANNUAL INSPECTION
				and was determined to be in airworthy condition and returned to service. All work
				accomplished iaw current FAA regulations and manufacturer's maintenance instructions
				Stefan A Uerguen A&P 2451974 IA
				

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				<u>Airplane Repair Inc Gillespie Airport 1965 N Marshall Ave El Cajon CA 619-940-8310</u>
	5 Jul 23			SMOH 964.6 Lyc O-320-A2B N57679
	Tach 1867.4			TSN ukn s/n L-27339-27A Bellanca 7ECA
				-changed oil and filter, no metal found in filter, serviced with Phillips 100AW
				-compressions 75, 77, 73r, 75 over 80
				-installed serviceable oil sump quick drain
				-retorqued engine bolts and valve cover screws
				This Engine is returned to service with respect of work being performed. All work
				accomplished iaw current FAA regulations and manufacturer's maintenance instructions
				Stefan A Uerguen A&P 2451974 IA
				

Engine Record General Information

Manufacturer Lycoming Model O-320-A213

Serial L-27339-127A Type Certificate _____

This engine is currently installed in aircraft: N57679

Minimum Octane Fuel _____ Oil Grade: Summer _____ Winter _____

Magneto Time _____ Point Setting _____ Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ hours