






1711 County
Road 130,
Pearland TX
77581

TOLL FREE:
800-580-7767

PROPELLER LOGBOOK

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS & MINOR ADJUSTMENTS

DATE	TACH TIME	
		
	REG: N144BY M/N: M20J S/N: 24-0034	DATE: 4/10/2025 TACH: 4456.95 HOBBBS: PROPTTSOH:0.0
	INSTALLED OVERHAULED AND THEN REPAIRED PROPELLER McCauley P/N B2D34C214-B/G-90DHB-16E S/N 060064 THEN COMPLETED 100HR INSPECTION ON THIS PROP IAW MOONEY AIRPLANE COMPANY, INC. 100-HR/ANNUAL MAINTENANCE INSPECTION GUIDE & FAR 43 APPENDIX D	
	1. PROPELLER WAS CLEANED, INSPECTED AND INSTALLED WITH NEW SEAL, PROP TORQUED AND SAFETYED.	
	I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN 100HR INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION	
	SIGNED <u></u> Luis Rosa A&P 3544884	
	I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION	
	SIGNED <u></u> David E. Blake A&P 3492152 I/A	

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model B2D34C214-B

Blade Design G-90DHB-16E

Diameter 82"

Hub Ser. No. 060064

Blade Ser. Nos. _____

No. 1 AAB26017

No. 2 AAB26013

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High 32.8 Low 13.9

Feather N/A Reverse N/A

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____