

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 001 RV 1	MOD OF RPM CONTROL SYSTEM INST ADDS A/C 4 & MATERIALS (A/C 0004, 0005, 0006)	N/A	
SB 002	ENGINE CONTROL SYSTEM MODIFICATION (A/C 0001 - 0008)	N/A	
SB 003	AZIMUTH ASSEMBLY REPLACEMENT (A/C 0001 - 0009)	N/A	
SB 004	AIRCRAFT ELECTRICAL SYSTEM MODIFICATION (A/C 0001 - 0008)	N/A	
SB 005 RV 1	COLLECTIVE LIMITER HYDRAULIC LINE CLAMP REPOSITIONING	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 006	COLLECTIVE STICK BOX ASSY ENG RPM SWITCH WASHER REPLACEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 007	ADD FRICTIONLESS TAPE TO PREVENT CHAFING OF HORIZONTAL STABILIZER CONTROL STRUT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 008	LANDING LIGHT ASSEMBLY MOUNT REPAIR	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 009	SWITCH PANEL ASSEMBLY MODIFICATION (A/C 0002, 0004 - 0011)	N/A	
SB 010	INSPECTION AND RECLAMPING OF WIRE BUNDLE	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 011	REPLACEMENT OF SLIP RING HOUSING SCREWS	-----	REFER TO ROTOR SHAFT ASSY SERVICE CARD
SB 012 RV 1	TRANSMISSION OIL TANK BREATHER VENT REPOSITIONING	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 013	ROTOR SHAFT HOUSING DRAIN INSTALLATION (OPTIONAL)		
SB 016 RV 1	TAIL STRIKE INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 017	COLLECTIVE COUNTERBALANCE INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 018 RV 2	ADDITION OF SHROUD TO FUEL CELL FORWARD VENT VALVE ASSY	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 019	COLLECTIVE CONTROL CRANK IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 020	PARTICLE SEPARATOR CENTER BODY SEAL INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 021	ROTOR BLADE TIP CAP RETENTION IMPROVEMENT	-----	REFER TO BLADE ASSY SERVICE CARD
SB 022 RV 1	FORWARD RELAY BOX ASSY MOUNT IMPROVEMENT	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 023	TROLLEY INSTALLATION	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 024	ROTOR SHAFT AND HOUSING BEARING IMPROVEMENT & GREASING PROVISIONS	-----	REFER TO ROTOR SHAFT ASSY SERVICE CARD
SB 025	TRANSMISSION MOUNT IMPROVEMENT	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 026	INSTALLATION OF H1943-7 TORQUE INDICATOR (A/C 0004 - 0014)	N/A	
SB 027	HOBBS SWITCH MOUNT BRACKET IMPROVEMENT	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 030 RV 2	ADDITION OF ANTI-CHAFE TAPE TO LANDING GEAR BOOM	-----	REFER TO MLG BOOM COMPONENT SERVICE CARD
SB 031	INCREASED STRENGTH FORWARD TIE DOWN FITTING	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 033 RV 1	ROTOR SHAFT AND HOUSING BEARING CHECK	-----	REFER TO ROTOR SHAFT ASSY SERVICE CARD
SB 034	COCKPIT DOOR HINGE IMPROVEMENT (GREASE FITTINGS) (OPTIONAL)	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 035 RV1	INSTALLATION OF H1900K-22 EGT INDICATOR	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 036	INSTALLATION OF H1973-2 HOWELL LOAD INDICATOR	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 038 RV 2	NOSE GEAR STATIC DISCHARGER INSTALLATION	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 039	INCORPORATION OF IMPROVED HSI MOUNTING CLAMP	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 040	REPLACEMENT OF LOAD, DUAL TACH, & TORQUE IND CLAMP SCREWS	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 041	INSTALLATION OF K983185 - 003 SIGNAL CONDITIONER	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 042 RV 2	INSTALLATION OF WEIGHT ON WHEELS SWITCH	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>
SB 043	HORIZONTAL STABILIZER DAMPER LEAK CHECK	11 DEC 18	P/C # 117NE / B. GRAY <i>BGM</i>

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 001 RV 1	MOD OF RPM CONTROL SYSTEM INST ADDS A/C 4 & MATERIALS (A/C 0004, 0005, 0006)	N/A	
SB 002	ENGINE CONTROL SYSTEM MODIFICATION (A/C 0001 - 0008)	N/A	
SB 003	AZIMUTH ASSEMBLY REPLACEMENT (A/C 0001 - 0009)	N/A	
SB 004	AIRCRAFT ELECTRICAL SYSTEM MODIFICATION (A/C 0001 - 0008)	N/A	
SB 005 RV 1	COLLECTIVE LIMITER HYDRAULIC LINE CLAMP REPOSITIONING	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 006	COLLECTIVE STICK BOX ASSY ENG RPM SWITCH WASHER REPLACEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 007	ADD FRICTIONLESS TAPE TO PREVENT CHAFING OF HORIZONTAL STABILIZER CONTROL STRUT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 008	LANDING LIGHT ASSEMBLY MOUNT REPAIR	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 009	SWITCH PANEL ASSEMBLY MODIFICATION (A/C 0002, 0004 - 0011)	N/A	
SB 010	INSPECTION AND RECLAMPING OF WIRE BUNDLE	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 011	REPLACEMENT OF SLIP RING HOUSING SCREWS	-----	REFER TO ROTOR SHAFT ASSY SERVICE CARD
SB 012 RV 1	TRANSMISSION OIL TANK BREATHER VENT REPOSITIONING	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 013	ROTOR SHAFT HOUSING DRAIN INSTALLATION (OPTIONAL)		
SB 016 RV 1	TAIL STRIKE INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 017	COLLECTIVE COUNTERBALANCE INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 018 RV 2	ADDITION OF SHROUD TO FUEL CELL FORWARD VENT VALVE ASSY	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 019	COLLECTIVE CONTROL CRANK IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 020	PARTICLE SEPARATOR CENTER BODY SEAL INSTALLATION IMPROVEMENT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 044 RV 1	BLEED AIR LINE REROUTING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 045	FUEL PUMP DISCHARGE FITTING IMPROVEMENT	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 046 RV 3	INSTALL PERSONNEL CARRYING DEVICE SYSTEM (OPTIONAL)		
SB 047	TRANSMISSION OIL TANK	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 048	DATA LOGGER SUPPORT BRACKET MODIFICATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 049	BATTERY WIRING HARNESS REROUTING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 050 RV 2	COCKPIT SOUND DAMPENING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 051 RV 1	ENGINE OIL SCAVENGE FILTER INSTALLATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 052 RV 1	ENGINE MOUNT UPGRADE	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 053 RV 1	RELOCATION OF EXTERNAL INSTRUMENT PANEL	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 054 RV 1	HORIZONTAL STABILIZER SERIALIZATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 055	INSTALLATION OF EGT INDICATOR ON EXTERNAL INST PANEL (K983197-001) (A/C 0004 - 0014)	N/A	
SB 056	MODIFIED GROUNDING TECHNIQUE FOR FUEL LINES (A/C 0004- 0019)	N/A	
SB 057	PREVENT ROTOR HARNESS CHAFING (A/C 0004 - 0014)	N/A	
SB 058	ADD LARGE O.D. WASHERS TO TERMINAL BOARD (A/C 0004 - 0014)	N/A	
SB 059	RELOCATE EXTERNAL INSTRUMENT PANEL TO R/H SIDE OF A/C (OPTIONAL)		
SB 060 RV 1	AFT PYLON FAIRING MOUNTING IMPROVEMENT	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 061	IMPROVED COLLECTIVE LIMITER	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 062	IMPROVED LATERAL TRIM STRUT ASSY (A/C 0004 - 0018)	N/A	

Service Bulletins A94-0047

[illegible]

Service Bulletins A94-0047

[illegible]









Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 044 RV 1	BLEED AIR LINE REROUTING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 045	FUEL PUMP DISCHARGE FITTING IMPROVEMENT	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 046 RV 3	INSTALL PERSONNEL CARRYING DEVICE SYSTEM (OPTIONAL)		
SB 047	TRANSMISSION OIL TANK	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 048	DATA LOGGER SUPPORT BRACKET MODIFICATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 049	BATTERY WIRING HARNESS REROUTING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 050 RV 2	COCKPIT SOUND DAMPENING	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 051 RV 1	ENGINE OIL SCAVENGE FILTER INSTALLATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 052 RV 1	ENGINE MOUNT UPGRADE	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 053 RV 1	RELOCATION OF EXTERNAL INSTRUMENT PANEL	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 054 RV 1	HORIZONTAL STABILIZER SERIALIZATION	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 055	INSTALLATION OF EGT INDICATOR ON EXTERNAL INST PANEL (K983197-001) (A/C 0004 - 0014)	N/A	
SB 056	MODIFIED GROUNDING TECHNIQUE FOR FUEL LINES (A/C 0004- 0019)	N/A	
SB 057	PREVENT ROTOR HARNESS CHAFING (A/C 0004 - 0014)	N/A	
SB 058	ADD LARGE O.D. WASHERS TO TERMINAL BOARD (A/C 0004 - 0014)	N/A	
SB 059	RELOCATE EXTERNAL INSTRUMENT PANEL TO R/H SIDE OF A/C (OPTIONAL)		
SB 060 RV 1	AFT PYLON FAIRING MOUNTING IMPROVEMENT	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 061	IMPROVED COLLECTIVE LIMITER	11 DEC 18	<i>BGM</i> P/C # 117NE / B. GRAY
SB 062	IMPROVED LATERAL TRIM STRUT ASSY (A/C 0004 - 0018)	N/A	

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 063	ONE TIME INSP DIRECTIONAL CONTROL SPRING STRUT ASSY ATTACHMENT BOLT	11 DEC 18	 P/C # 117NE / B. GRAY
SB 064	IMPROVED ENGINE DECK	11 DEC 18	 P/C # 117NE / B. GRAY
SB 065	REINFORCEMENT OF SKIN AFT OF CARGO DOOR	11 DEC 18	 P/C # 117NE / B. GRAY
SB 066 RV 1	C60 MULTI-HOOK CAROUSEL ELECTRICAL INSTALLATION	11 DEC 18	 P/C # 117NE / B. GRAY
SB 067 RV 1	BLADE UPGRADE - INSTALL IMPROVED IDLER CRANK ASSY CENTER BRG & CLEVIS	-----	REFER TO BLADE ASSY SERVICE CARD
SB 068 RV 1	AIRCRAFT LIMITS PLACARD REPLACEMENT. REPLACED BY SB 118	N/A	
SB 072	ONE TIME ROTOR SHAFT AND HOUSING INSP AND/OR REPLACEMENT	-----	REFER TO ROTOR SHAFT ASSY SERVICE CARD
SB 073 RV 1	TAKE - OFF/LANDING CHECK LIST PLACARD REPLACEMENT	11 DEC 18	 P/C # 117NE / B. GRAY
SB 074 RV 2	PROVISIONS FOR DUAL CARGO HOOK (OPTIONAL)		
SB 075 RV 4	ENGINE FUEL PRESSURE WARNING INSTALLATION	11 DEC 18	 P/C # 117NE / B. GRAY
SB 077	FORWARD ENGINE MOUNT ROD ASSY IMPROVEMENT	11 DEC 18	 P/C # 117NE / B. GRAY
SB 078	ONE TIME ENGINE CONTROL CRANK REPLACEMENT	11 DEC 18	 P/C # 117NE / B. GRAY
SB 079	ONE TIME TEETER PIN REPLACEMENT (K910005-007)	N/A	N/A BY PART NUMBER
SB 080	IMPROVED INBOARD FLAP CLEVIS ASSY	-----	REFER TO BLADE ASSY SERVICE CARD
SB 081	ONE TIME INSP OF TRANSMISSION CLUTCH	-----	REFER TO CLUTCH COMPONENT SERVICE CARD
SB 082 RV 1	TORQUE CHECK ENG OUTPUT ADAPTER BOLT & REPLACEMENT ENGINE OUTPUT ADAPTER (A/C 0004, 0007, 0011 - 0015, 0017, 0019 - 0021, 0024, 0025)	N/A	
SB 083 RV 2	ENGINE OUTPUT ADAPTER SERIALIZATION (A/C 0002, 0008, 0010, 0016, 0026 - 0030)	N/A	
SB 084	ONE TIME BLOWER DRIVE SHAFT BOLT REPLACEMENT	11 DEC 18	 P/C # 117NE / B. GRAY

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 086	INSTALLATION OF IMPROVED INBOARD FLAP CLEVIS ASSEMBLY	-----	REFER TO BLADE ASSY SERVICE CARD
SB 087 RV 1	ONE TIME REPLACEMENT OF TEETER PIN SEAL WASHER	11 DEC 18	<i>Beg</i> P/C # 117NE / B. GRAY
SB 088 RV 1	DAILY INSPECTION OF TRANSMISSION CLUTCH ASSY (K974110-003)	CANX	
SB 089 RV 1	50 HR INSPECTION OF TRANSMISSION CLUTCH ASSY	CANX	
SB 090	ONE TIME TRANSMISSION CLUTCH CONVERSION (K974110-005 & K974110-003 IN THE K974002-701) N/A THIS P/N	-----	REFER TO CLUTCH COMPONENT SERVICE CARD
SB 091	IMPROVED TRANSMISSION OIL VENT SYSTEM (OPTIONAL)		
SB 092	TRANSMISSION OIL SCAVENGE FILTER BRACKET INSTALLATION (A/C 0004 - 0008, 0010 - 0016, 0019)	N/A	
SB 093	TRANSMISSION OIL SCAVENGE FILTER INSTALLATION	11 DEC 18	<i>Beg</i> P/C # 117NE / B. GRAY
SB 094 RV 1	INSTALLATION OF MULTIFUNCTION AURAL WARNING SYS (OPTIONAL)		
SB 095	MAIN LANDING GEAR BOOM SERIALIZATION. (A/C 0002 - 0004, 0008 - 0010, 0016, 0019 - 0021, 0024 - 0027)	-----	REFER TO MLG BOOM COMPONENT SERVICE CARD
SB 096	NOSE LANDING GEAR SERIALIZATION. (A/C 0002 - 0004, 0008 - 0010, 0016 - 0019, 0021, 0024 - 0027)	-----	REFER TO NLG COMPONENT SERVICE CARD
SB 097	MAIN LANDING GEAR SERIALIZATION. (A/C 0002, 0004 - 0008, 0010 - 0016, 0019 - 0021, 0024 - 0027)	-----	REFER TO MLG CYL COMPONENT SERVICE CARD
SB 098	ONE TIME LAG PIN REPLACEMENT (K910006-103)	N/A	
SB 099	ONE TIME BLADE GRIP LINER MODIFICATION	-----	REFER TO BLADE ASSY SERVICE CARD
SB 100	CYCLIC STICK INSTALLATION IMPROVEMENT	11 DEC 18	<i>Beg</i> P/C # 117NE / B. GRAY
SB 102	INSTALLATION OF MULTI FUNCTION AURAL WARNING SYSTEM. (OPTIONAL)	CANX	

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 139 RV 2	RECURRING OUTBOARD FLAP BRACKET BOLT REPLACEMENT	-----	REFER TO BLADE ASSY SERVICE CARD
SB 140	INSPECTION OF TRANSMISSION / ROTOR SHAFT DRAIN SLOT	11 DEC 18	^{130m} P/C # 117NE / B. GRAY
SB 141	ONE TIME INSPECTION OUTBOARD FLAP BRACKET	-----	REFER TO BLADE ASSY SERVICE CARD
SB 142	ONE TIME INSPECTION OF AZIMUTH CAM CONTROL ASSY BOLTS	11 DEC 18	^{Bm} P/C # 117NE / B. GRAY
SB 143	HEATER VALVE CABLE MODIFICATION (A/C 0039, 0040, 0041)	N/A	
SB 144	ONE TIME INSPECTION OF TRANSMISSION MOUNT ANGLE RADIUS (NO DEFECT THIS AIRFRAME)	11 DEC 18	^{Bm} P/C # 117NE / B. GRAY
SB 145	ONE-TIME INSPECTION: UPPER TUNNEL CRANK ORIENTATION	18 JAN 19	^{Bm} VKR018J / B. Smelser
SB 146	REPLACEMENT OF ROTOR BRAKE MASTER CYLINDER	N/A	
SB 147	ONE-TIME INSPECTION WINDSHIELD INSPECTION	20 MAR 19	^{Bm} VKR018J / B. Smelser
SB 148	ONE-TIME INSPECTION ROTOR BLADE OUTBOARD FLAP BRACKET	-----	REFER TO BLADE ASSY SERVICE CARD
SB 149	TRANSMISSION BYLON SUPPORT ASSEMBLY - INSPECTION	-----	REFER TO XMSN ASSY SERVICE CARD
SB 150	Lube Shear Shaft Inspection	02/09/21	Ben ^W AP 3527089
SB 151 R1	Bonding of Tachometer Generator	verified 04/18/23	Ben ^W AP 3527089
SB 152	Cockpit Windshield Modification	NA	Ben ^{McCarb} AP 3527089
SB 153	External Mount Fittings	NA	Ben ^{McCarb} AP 3527089
SB 154	Aircraft Limitations Placard	verified 04/18/23	Ben ^{McCarb} AP 3527089
SB 155	H8000-001 EGT Indicator	NA	Ben ^W AP 3527089
SB 156 R1	Azimuth Drive Coupling Tab Boreprobe	NA	Ben ^W AP 3527089

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 103	ONE TIME 660 HR REPLACEMENT OF SPRAG ASSY (K974110-003) N/A THIS P/N	-----	REFER TO CLUTCH COMPONENT SERVICE CARD
SB 104	ONE TIME INSP STABILIZER CONTROL CRANK BACKUP STRUCTURE	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 105	ONE TIME INSP OF ROTOR BLADE U-CRANK STUD	-----	REFER TO BLADE ASSY SERVICE CARD
SB 106	ONE TIME INSP OF VERTICAL FIN STRUCTURE	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 107	VERTICAL FIN MODIFICATION	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 108	ONE TIME TRANSMISSION GEARBOX MOUNT & STRUT MOUNT INSP (A/C OVER 4000 HRS)		
SB 109 RV 2	RECURRENT ROTOR BLADE GRIP INSPECTION	-----	REFER TO BLADE ASSY SERVICE CARD
SB 110	ROTOR BLADE GRIP MAGNETIC PARTICLE INSPECTION	-----	REFER TO BLADE ASSY SERVICE CARD
SB 111 RV 1	ROTOR BLADE GRIP REPLACEMENT	-----	REFER TO BLADE ASSY SERVICE CARD
SB 112 RV 2	ONE TIME INSPECTION OF ROTOR BLADE GRIP BUSHINGS	-----	REFER TO BLADE ASSY SERVICE CARD
SB 114	ONE TIME TORQUE CHECK INBOARD AND OUTBOARD FLAP BRACKETS	-----	REFER TO BLADE ASSY SERVICE CARD
SB 115	ONE TIME INSPECTION OF TRANSMISSION CLUTCH (K974002-701) N/A THIS P/N	-----	REFER TO CLUTCH COMPONENT SERVICE CARD
SB 116	ONE TIME INSP OF OIL COOLER BLOWER DYNAMIC COMPONENTS (K977130-001)	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 117	IMPROVED ENGINE OUTPUT ADAPTOR	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 118	7000 LB MAX TAKEOFF / LANDING GROSS WEIGHT	11 DEC 18	<i>Bgm</i> P/C # 117NE / B. GRAY
SB 122	ADD DRAIN HOLE TO ROTOR BLADE TIP CAPS	-----	REFER TO BLADE ASSY SERVICE CARD

Service Bulletins

Aircraft Serial No. A94 - 0047

Service Bulletin #	Description	Date Complied With	Cert No./Signature
SB 123	ONE TIME INSPECTION OF DIAGONAL STRAP BOLT HOLES (ALL BLADES EXCEPT 400 SERIES)	-----	REFER TO BLADE ASSY SERVICE CARD
SB 124	REMOVAL OF LAG PIN SEAL (A/C 0028 - 0032)	N/A	
SB 125	K FLEX DRIVE SHAFT INSTALLATION (K974180-003)	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY
SB 126	CENTER WALKWAY INSTALLATION (K936112-003)	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY
SB 127 RV 1	NEW TRANSMISSION INSTALLATION (K974302-001) N/A THIS P/N	-----	REFER TO TRANSMISSION ASSY SERVICE CARD
SB 128	ONE TIME INSPECTION OF L-CRANK BOLTS	-----	REFER TO ROTOR HUB ASSY SERVICE CARD
SB 129	BLADE REPAINT TO FACILITATE INSPECTION	-----	REFER TO BLADE ASSY SERVICE CARD
SB 130	REPLACEMENT OF EGT PLACARD	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY
SB 131	ROTOR BLADE SERVICE LIFE REDUCTION	-----	REFER TO BLADE ASSY SERVICE CARD
SB 132	BLADE CHEEK PLATE	-----	REFER TO BLADE ASSY SERVICE CARD
SB 133 RV 3	CANCELED	N/A	
SB 134	TEETER PIN SLIDING BEARING INSP (K913005-009) (K910105-11) INSTALLED. N/A THIS PART NUMBER	N/A	
SB 135	INSPECTION AND REPLACEMENT OF CYCLIC STICK GRIP MOUNT SCREWS	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY
SB 136	INSPECTION AND MODIFICATION OF START / IGNITION, VENT FAN, PITOT / STATIC AND FUEL PUMP CIRCUITS	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY
SB 137	CARGO HOOK MANUAL RELEASE CABLE CLAMPING (OPTIONAL) REF SB 46		
SB 138	SERIALIZATION OF AIRFRAME TAIL BOOM	11 DEC 18	<i>B J</i> P/C # 117NE / B. GRAY