



The Standard

engine lo

ASA-35-1

### **Burlington Air Center**

703 Airport Rd. Burlington, WI, 53105 (262) 763-9500 Fax (262) 763-2910

N26981

8/7/24

Hobbs: 1371.4


oil. Washed engine, ran up, checked for leaks, found satisfactory at this time.

Inspections: Completed Annual Inspection this date IAW FAR Pt. 43 App. D.	
Compressions: 1) 74/80, 2) 69/80, 3) 70/80, 4) 68/80, M-O 46/80.	
All AD's checked:	
AD 98-01-06 Carburetor Venturi: C/W by inspection per (a)(1) & (2). No defects noted at this time. Next Due: 9/1/25 or 4068.6 AFTT.	
Repairs as listed: removed both Slick 4301 magnetos SN's) 02111387 (LH) & 02111386 (RH) and sent to Poplar Grove Airmotive for 500hr IRAN see WO# 107579 / FAA form 8130-3 dated 31-Jul-24 for details. Reinstalled repaired magnetos listed above and set	
timing per placards & markings,	

Tach: 576.7

I certify; this <u>Engine</u> has been inspected in accordance with an <u>Annual</u> Inspection, determined to be in airworthy condition with regard to the work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.

All routine maintenance completed: BA-4108 induction filter, oil changed, took SOAP sample see Blackstone report for details. Cut open oil filter and inspected for FOD, none found at this time. Installed new AA48103-2 filter, serviced with 7qts of Aeroshell 15w50



· Repair

SMOH: 1009.1

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspecti Entries must be endorsed wit Facility. (See back pages for	h Name, Rating and Certific other specific entries.)	ate Number of Technician or f	1	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE		endorsed with	Name, Rating	Repairs and Alterations g and Certificate Number of Techni ntries.)	-
20/20/24	454,2	i II		No leaks done by Just	40 etre 11 12 m 20 replac	25 Anyloga		6-6-24	549.3			CHANGES	OIL w	FILTER	AA48108-) + 15w-57	Se
			В	urlington Air ( 703 Airport Rd. Burlington, WI, (262) 763-9500 Fax (262) 763-	53105			_								
4/2	6/24	Hobbs: 1	278.9	N2698J	Tach: 504.0	SMOH: 936.4										
All Ope	npressions: 1) 7 AD's checked: 98-01-06 Carbui vairs as listed: A routine mainter	o/80, 2) 70/ retor Ventur djusted idle nance comp nspected for	i: C/W by insp mixture. leted: BA-410 r FOD, none for	this date IAW FAR Pt. 43 App. D. 4) 70/80.  section per (a)(1) & (2). No defects 18 induction filter, oil changed, too bund at this time. Installed new AA 6, found satisfactory at this time.	k SOAP sample see Blacksto	ne report for details. Cut	=									
l ce reg	rtify; this <u>Engine</u> ard to the work	e has been performed,	inspected in a and that the v	accordance with <u>a 100 Hour Inspe</u> work has been accomplished in acc	ordance with current Federa	airworthy condition with Aviation Regulations. AS743242										

YEAR:    RECORDING TACH TIME   TODAY'S FLIGHT   TOTAL TIME IN SERVICE     DATE   RECORDING TACH TIME IN SERVICE   TOTAL TIME IN SERVICE     Description of Inspections, Tests, Repairs and Alterations     Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair     Facility. (See back pages for other specific entries.)	YEAR:	RECORDING	,	OTAL ME IN	Description of Inspections,
Burlington Air Center 703 Airport Rd. Burlingtoπ, WI, 53105 (262) 763-9500 Fax (262) 763-2910	<del>-</del> -	1/16/24	Hobbs: 1		Burlington Air C 703 Airport Rd. Burlington, WI, 5: (262) 763-9500 Fax (262) 763-29
Repairs as listed: installed 8) new MS21045-4 nuts on carburetor and carburetor air box mounting studs, corrected safety wire on oil filter. Ran up, leak checked, systems found satisfactory at this time.  I certify that the work described above has been accomplished and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.		Compressions: All AD's checks AD 98-01-06 Co Repairs as liste All routine ma open oil filter a oil. Washed en	<u>2</u> 1) 68/80, 2) 70/ ed: Carburetor Venturi ed: set ignition tin intenance compl and inspected for igine, ran up, chec ingine has been i	i: C/W by ming per leted: BA FOD, no cked for lengths	ction this date IAW FAR Pt. 43 App. D. 1/80, 4) 70/80, M-O 46/80.  Inspection per (a)(1) &(2). No defects no placards and markings.  A-4108 induction filter, oil changed, took ne found at this time. Installed new AA44 leaks, found satisfactory at this time.  In accordance with a 100 Hour Inspect the work has been accomplished in accor

## Burlington Air Center

703 Airport Rd. Burlington, WI, 53105

(262) 763-9500 Fax (262) 763-2910

Description of Inspections, Tests, Repairs and Alterations

Tach: 405.3

Carburetor Venturi: C/W by inspection per (a)(1) &(2). No defects noted at this time. Next Due: 2/1/25 or 3897.2 AFTT.

naintenance completed: BA-4108 induction filter, oil changed, took SOAP sample see Blackstone report for details. Cut r and inspected for FOD, none found at this time. Installed new AA48108-2 filter, serviced with 6qts of Aeroshell 15w50

SMOH: 837.7

Engine has been inspected in accordance with a 100 Hour Inspection, determined to be in airworthy condition with


work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alte Entries must be endorsed with Name, Rating and Certificate Nu Facility. (See back pages for other specific entries.)	mber of Technician or Repair	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and</b> Entries must be endorsed with Name, Rating and Certificat Facility. (See back pages for other specific entries.)	
9/4/23	0254.2	Smoll	650.25	Promod Oil à replaced w/to quarts Aeroshell 15W- Replace & Oil Filter w/Fign EZ AA40108-2 Note	50 done by Jishh aks noted 4450138 Janel	16/25/2	356.0			Drained cil and replaced w 6 quarys Accesse 11 15 w Spin EZ AA 49108-Z, no lests Done by Jacob Oost	
<u>†</u>				Burlington Air Center 703 Airport Rd. Burlington, WI, 53105 (262) 763-9500 Fax (262) 763-2910	-		•			Burlington Air Center	
	10/23/23	Но	bbs: 1018.3	N2698J Tach: 304.8	SMOH: 700.8				_	703 Airport Rd. Burlington, WI, 53105 (262) 763-9500 Fax (262) 763-2910	
— — —	All AD's check Repairs as list All routine ma	s: 1) 62/80, ked. ked: gapped aintenance	2) 70/80, 3) 65 and installed 1 completed: oil	) new UREM40E spark plug in lower position on cyl #2. changed this date, took SOAP sample and sent for analysis, see Black	estone report for details.	up, lea	s as listed: inst k checked, syst	ems found s	atisfactory at		
<del>-</del>	Aeroshell 15w	<b>/50</b> oil. Was <u>Engine</u> has	hed down engi	DD, none found at this time. Installed new AA48108-2 filter and fill ne, ran up, checked for leaks, none noted at this time.  If in accordance with a 100 Hour Inspection, determined to be in all the work has been accomplished in accordance with current Federal.	irworthy condition with	l certif approv	y that the wor red for return to	k described o service.	above has be	en accomplished and inspected in accordance with current Fed	deral Aviation Regulations and is
	<del></del>			JI Sil	+37+3242 -			<del>  </del>	<del></del>		

	Wo: PS23159  Engine · page 1 of 2  Plane Safe Aircraft Maintenance, Inc. · 503 West Bluemound Rd · Waukesha · W Fates · page 547 4999	Repair DATE	WO, 1 525133
	N2698J Continental, O200A, S/N: 63545-6-A June 30, 2023 Hobbs: 886.8 Tach: 204.4 TTSN: 4613.31 TSMOH: 600.45  1. Completed 100Hr/ Annual Inspection IAW FAR 43 appendix D, using Cessna 150 inspection forms as a guide.  2. Performed run-up, checked compressions: #1 75, #2 70, #3 78, #4 76/80.  3. Checked magneto to engine timing.  4. Changed oil and filter. Drained oil, took oil sample, and sent out for analysis. Removed, cut open, and inspected oil filter. No contaminants found. Installed new filter, P/N: AA48108-2. Serviced oil tank with 6 QTS. of 20W50 X/C and 9.6oz of CamGuard. Performed leak check, no leaks found at this time.  5. Removed, cleaned, gapped, inspected, tested, and rotated spark plugs. Reinstalled with new M674 gaskets.  6. Cleaned, inspected and lubricated all engine controls.  7. Replaced missing #1 inner cylinder baffling spring with serviceable hardware.		Plane Safe Aircraft Maintenance, Inc. · 503 West Bluemound Rd · Waukesha, WI 53188 · 262-547-1800  13. Removed existing pull starter, cable, spring, and related components. Installed new Sky-Tec push button starter, P/N: C12ST2/S IAW STC: SE10076SC (engine) and STC: SA10077SC (airframe). Removed old starter shaft, cleaned mating surfaces, and installed starter. Installed new push-button switch in existing pull cable hole. Routed wiring and made necessary electrical connections. Sealed several holes in firewall. Performed operational and leak checks, all checks are satisfactory. Completed 337 forms for airframe and engine and mailed to FAA. Updated weight and balance placed in aircraft.  14. AD's checked through Bi-Weekly 2023-14.  15. C/W AD 98-01-06 by visual inspection of carburetor venturi. No discrepancies found. Next due: 6/2024.  I certify that this engine has been inspected IAW an Annual Inspection, is found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Plane Safe Aircraft Maintenance, Inc. under work order: PS23159.
*6 X/ X	<ol> <li>Installed missing hardware on #4 valve cover attaching to engine baffling.</li> <li>Cleaned engine.</li> <li>Removed and replaced worn oil filler neck gasket with new, P/N: RG-533355.</li> <li>Dressed out broken area of cooling fin on #2 cylinder near top spark plug.</li> <li>Removed and replaced worn carburetor heat scat tube with new, P/N: SCAT-8.</li> </ol>		Druanne Pierce Airframe & Powerplant A&P393886792 ALLAKAL ACCO

		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician Facility. (See back pages for other specific entries.)	or Repair	2022 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1 1 1	wo: PS2215	9		Engine - page 2	of 2	7/8/22	2947.64	SMOH:	1 1 1 1	Drained oil and replaced with 6 Gvorts Phillips XC 20W-50 0:1 and 8 oz of Cam Guard. Replaced Oil Filter With PIN: (H48108-1. Cut open and inspected Oil oil filter. No Contaminants found. Collected Oil Sample for analysis. Safety wired New Filter. Engine Test run, no leaks noted. Jacob Aden, Owner, 4020020
		F	Plane Sale Aircraf	t Maintenance, Inc 503 West Bluemound Rd - Waukesha, WI 53188 - 262-547-1800		9/14/22	24.4	SMOH:	420.45	Praired oil and replaced WI6 9th Phillips XC 20W-50 oil and 9 oz of Cantavard.
				et, Crush, Installed P/N MS35769-18 - Gasket.				1.24		Found. Engine test run No lacks noted . Safety wired new filter. Jacob Aben 4020020 (owner)
	gasi 7. C/W	kets. / AD 98-0	1-06 by vis	ed, inspected, tested, and rotated spark plugs. Reinstalled with new M6 ual inspection of carburetor venturi. No discrepancies found. Next de		115/22	71.9	SMOH:	467.95	Drained oil and replaced up a quarts of Phillips XC 20W-50 oil and 8 oz of CamGuard Replaced oil filter up I'N CH48108-1. Cut open and inspected old oil filter. No contaminants fund. Safety Wired new Filter. Engine tost run. No leaks maked Jacob Aden August 4020020
				thru 2022-12		1/23/2023	110.1	CM au.	515 15	praired oil and replaced w/ Phillips XC Zow-50 (6 quarts) oil and 8 oz of Cambra oil and 18 oz of Camb
	condition	and is ap	proved for	een inspected IAW an Annual Inspection, is found to be in an airworreturn to service. Details of work performed are on file with Plane Sar work order: PS22159.	fe		113.1	SINUK.	313.13	Replaced oil filter WI PN CH48108-1. Cut open and inspected old oil filter, NO Contaminants found. Safety Wired new Filter. Engine test rvn. No leaks Noted.
				rplant A&P95526492   A Collection   Collecti		1/20/2013	154.3	SMOH	555.35	Jacob Aden, Owner, 4020020 Drained oil and replaced w/ 6 avorts of Phillips XC 20W-50. Replaced oil filter w/ P/N AA49108-2. Cut open and inspected old oil filter. No contaminants found. Safety wired new filter. Engine Test Run No leaks noted. Jacob Aden, Owner, 4020020

1000		TODAY'S FLIGHT		TIME IN Entries must be endorsed with Name Pating and Corti	TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair	 RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				N4098J S/N 150-65698	wo: PS22	A-75	Plane Safe Aircra	Engine - page 1 of 2  Aircraft Maintenance, Inc 503 West Bluemound Rd - Waukesha, WI 53188 - 262-547-1800	
CH4 68/ run acc	48108-1 oi 80 2) 72/8 and sheck ordance w	filter, p 0 3) 70/8 for leak ith 100 f	lugs cleane 30 4) 72/80 s. I have i nour and a	Oil serviced with 6 qts Phillips XC 20W-50 oil, installed new Champion ed and gapped, magnetos timed to engine. Compression check: 1)  O. All Ad's to this date complied with. Engine was successfully ground inspected this engine and found it to be in airworthy condition in annual inspection.  Date: 5-20-21, Tach Time: 2859.4, SMOH: 285.8	1. Co as 2. Pe 3. Ch 4. Ch an	J 2908.92 completed a guide. erformed r necked managed oil d inspect	S 30 100Hr/ Ann un-up, check agneto to er I and filter. ed oil filter.	Continental, O200A, S/N: 63545-6-A  SINCE OVERHAUL:  anual Inspection IAW FAR 43 appendix D, using Cessna 150 inspection forms cked compressions: #1 69, #2 62, #3 70, #4 69/80.  Ingine timing, all checks are good.  Drained oil, took oil sample, and sent out for analysis. Removed, cut open, No contaminants found. Installed new filter, P/N: CH48108-1 and serviced 20W50 X/C and 8oz of CamGuard. Performed leak check, no leaks found at oved oil screen assembly. Found oil screen previously removed IAW STC and with new crush washers, P/N: MS35769-11 and MS35769-48. Performed leaks found at this time. Installed P/N MS35769-11 - Gasket, Crush, Installed	



	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: DATE	RECORDING TACH TIME	9/8/2018 TACH: 2814.4 ENG TT: 4274.8 TSMOH: 240.8 ian or Repair
1-1-17	Tach: 27	9392		Completed 100 hr/Annual inspection on this date. Compressions: #1 1/80, #206/80, #304/80, #401/80 cold RtR.d oil filter the cut old one open, no abnormal wear noted. Drained to re-filled with 6 gts Phillips XC 20W-50. Timed mags to 28° Atac.  Mag sullch FT okay. CWAD 98-01-06 by inspection. No other discrepencies noted at this time. I certify this			Engine: Continental O-200A, S/N: 63545-6-A. Completed 100hr/Annual inspection on this date. Compressions: #1 75/80, #2 66/80, #3 68/80, #4 71/80. Verified magneto timing at 28 degrees BTC. Cleaned, gapped, & rotated spark plugs. Installed new BA4108 air filter element. Drained and re-filled oil with 5 qts of Phillips XC 20W-50 oil. Installed new Champion CH48108-1 oil filter. Replaced damaged engine baffle seals. Installed new pull starter clutch P/N CAM1971890N, S/N 15-239-32, IAW CAM Installation & ICA Instructions CI-02-01 Revision E issued June 26 2003. Post maintenance run-up check revealed no leaks & normal operation. All AD's up to date at this time, see separate report.
				engine has been inspected IAUTAR 1/3 appendix 0 for a loo hr inspection x is determined to be in Airworthy  Condition.  Thomas Rybarrzyk  Marzzeykszza			I certify this engine & propeller have been inspected IAW a 100 hr/annual inspection, FAR Part 43 App D, and are found to be in airworthy condition on this date and approved for return to service.  Thomas Rybarczyk AP2739463IA

148. X 14 CFR 43 0 Deline

YEAR: 20/6 DATE	TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6-4-16	Elyine IT 4	235.50	. Tach :	775.1, Tsoff 223.73 Hobbs 443.3	3-18-1	Eigine	Tt 425	4.1 Tach	2793.7 TSOH 742.3 Hobbs: 461-9
<del></del>				This Engire was inspected I for the latest inspection guide from		J			Bulanced propeller to very good good range Idu Vibrex 2000 ops manual. Added 5:5 02 @ 11:10 + 3.4 02 @ 9:10.
; <u> </u>				(0581 + 100 series service Manual + FAR 43 gpy D. Compressions: #1 72/80, #2 7900, #3 63/80, #4 73/80. Cat + replaced oil filter,					2000 ops manual. Added 5,5 ez @ 11:10 + 3,4 oz @ 9:10.
				no absorbed wear detected. (honored a) + re-filled with 5 ots phillip XI					They but
·				200-50. Installed 8 rew Auto life UREMHOE spark places. Timed		ļ			Thomas Riparczy & ADZ73446 STA
				Mags to 28° BIDC. May switch FT day. (1w AD 98.01-06 by inspection. No other discrepencies noted at this time. I certify					
				this engine + propeller here been inspected in Itw an annual	_				
				inspection and are determined to be in Airworthy andition.	,				
							-		
				Thomas Riburreyk APZ 73446344					

... I source (il tiluzzi vivi

YEAR: 20// DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: 2015 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)  This Engine was inspected IAW the latest Inspection Guide from the Cessna
6/5	272121			Removed & Replaced Hudraulic units from	-				100 Series Maintenance Manual and F.A.R. 43 Appendix D. The following
				Cylinder #3 or Serviceable parts from					maintenance was performed: Performed compression test with the following results: # I 76/80 #2 58/80 #3 66/80 #4 72/80. Will re-check compressions at
				AIRCRAFT SPECIAlities release certificate					next oil change. Cleaned and gapped spark plugs. Timed magnetos to 28 degrees BTDC. Cut and replaced oil filter, no anomalies found. Changed oil
				dated 5/31/2011. HLDall 2054997 APP					and serviced with 5qts of Phillips 20W-50 X/C. Cleaned and inspected fuel sump screen, no debris noted, changed all o-rings & gaskets. Magneto
				Test flight Satisfactory.					switch functional check okay. Re-clocked propeller to correct position, and checked tracking. C/W AD98-01-06 by inspection. No other discrepancies
	17 Apr 2012	1 1		e= 2723.02 Total time= 4183.42 SMOH= 171.65					noted at this time.
				Contract of the Manager Contract of the Contra					I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN
	magneto tin	ning Ma	inneto swi	#2 72/80 #3 72/80 #4 72/80. Changed engine oil and filter. Checked itch functional check satisfactory. C/W 98-01-06 by Inspection and found story. AD notes checked through 04/17/12. Inspected and serviced I/A/W					ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
_	100 hr inspe	ection an	d found a	tory. AD notes checked through 04/17/12. Inspected and serviced I/A/W inworthy. Test run satisfactory.					DATE 5/9/2015 TOTAL TIME 4217.79 TACH TIME 2757.39 T.S.O.H. 206.02
-				1 205441 MgV			1		CONTROL TI MI INI
_	1 1	1			_				SIGNATURE / / / / / / / / / / / / / / / / / / /
-									Thomas B. Rybarczyk AP 2739463 IA

Other regulation are

901/196 CI IIIII PU E .-

YEAR: 2009 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Refacility. (See back pages for other specific entries.)	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9/7	9230?	Oil & Filter Change Phillips XC 201050 3230.7			Phillips XC 201050 3230.7 8/26	272025			Change oil i Filter Hobbs 3788 KCZOWSU
1 Nov 2	ا 009 Ta	l =ch time	: 2695.96	l Total time= 4155.36 SMOH= 7→3.59					Jalle 2688449
function carbura	al check sator venturi	itisfactor per AD 9	y. Installed 8-01-06 ar	80 #3 65/80 #4 67/80. Checked magneto timing. Magneto switch dinew carburator airfilter element Brackett P/N BA4108. Inspected did found satisfactory. Test run satisfactory. AD notes checked 00 hr inspection and found airworthy.	Co	rburator ven	check: #1 ck satisfa turi per A	1 70/80 #2 actory. Inst AD 98-01-0	36 Total time= 4180.76 SMOH= 168.99  2.76/80 #3.76/80 #4.74/80. Checked magneto timing. Magneto switch talled new carburator airfilter element Brackett P/N BA4108. Inspected 96 and found satisfactory. Test run satisfactory. AD notes checked N 100 hr inspection and found airworthy
				H. L. Daniel Jr. 2054497 IA					N/20-1 2054497 AHP -
									_

YEAR: 2007 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	VEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	-
<sup>2</sup> //	Compres and filter. Enterpris Recalcula	ssion che r. Remov ses Oil Fil lated Wei	eck: #1 75/8 ved AirWolf liter mount I eight and Ba	TAL TIME: 4092.33 SMOH: 80.56 30, #2 77/80, #3 76/80, #4 75/80. Checked magneto timing. Changed oil of remote oil filter previously installed at overhaual and installed F&M P/N T.A.FL I/A/W STC SE7559SW. See Form 337 dated 2/1/2007. Inspected carb venturi per AD 98-01-06 and found satisfactory. 2007-02. Inspected I/A/W 100 hr inspection and found airworthy.  H. L. Daniel Jr. 205/497 IA	9/25	Comp Disas case, functi BA-4 AD98	pression ssembled , new oil ; ion check 106 Rev 8-01-06 a	check: #1 ( d as require pump kit Po ked OK. Ch D, and nev and found s	Irs TOTAL TIME: 4111.27 Hrs SMOH: 99.50 Hrs 65/80, #2 60/80, #3 72/80, #4 74/80 red to remove accessory case. Reassembled with new P/N 653679A5 P/N SA22354-1 and all new gaskets and seals. Timed mags. Mag switch thanged oil and filter. Installed new Bracket air filter assembly, P/N rew element P/N BA-4108 per AD96-09-06. Inspected carb venturi per satisfactory. Test run satisfactory. AD notes checked 09/18/08.  The provided HTML in the provided H	

YEAR: 2004 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/1	C/W T #2 76/s inspec and tes	30, #3 78 ted filter	03-3 by la 8/80, #4 75 element. I tisfactory.	pping exhaust valves of #1 & #4 cylinders. Compression check: #1 74/80, 5/80. Checked magneto timing. Changed oil and filter, cut open filter and Rotated spark plugs. Inspected venturi to C/W AD 98-01-06 by inspection AD notes checked through 2004-20. Inspected I/A/W 100 hr inspection and H. L. Daniel Jr. 2054497 IA	11/2/05	Comp and fil	ression of	check: #1	TOTAL TIME: 4074.69 SMOH: 63.23  78/80, #2 78/80, #3 78/80, #4 77/80. Checked magneto timing. Changed oil to venturi per AD 98-01-06 and found satisfactory. AD notes checked through W 100 hr inspection and found airworthy. TEST RUN SATISFACTORY.  H. L. Daniel Jr. 2054497 IA

YEAR: 2003 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Refacility. (See back pages for other specific entries.)	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Engin		d per TC	M manual	X30010. Installed new TCM P/N 653012 crankshaft, 4 new TCM	8/23	7562.56			CHANGED OIL & FILTER (AFROSHELL OIL 100 STEARHT MINERAL OIL & CH48108) Delle 2688449
bodies certifie by Div Inc., V see F. no. 17 hoses mount Fabric	s, connecting the state of the	g rods, h ft Specia DK, see y see FAA 80-3. Ins set to 28 cts, meta new oil	nydraulic un lities Service yellow tags. A forms 813 stalled new B degrees a al lines and quick drain iffles and se	hydraulic units and new connecting rod bolts. Camshaft, valve lifter its (3) and balance of internal steel parts inspected/overhauled and es, Tulsa, OK. Crankcase machined and accessory case inspected Starter, alternator and vacuum pump overhauled by Accessories, 0-3. Carburetor overhauled by F&F Fuel Systems, Collinsville, OK, Slick magnetos model no. 4301 and new complete harness model and engine data plate restamped per TCM MSB94-8A. Replaced all electrical wiring forward of the firewall. Installed new rubber engine valve. Replaced Brackett air filter element P/N BA-4108. Eals. Engine test run/leak check satisfactory. AD notes checked to service.  H. L. Daniel Jr. 2064497 IA	- 8/18 - 9/23 -	25/3.5			REMOVED AND REPLACED ROCKER ARMS FOR OVERHAUL  DUE TO EXCESSIVE BUSHING WEAR. DUBRHAUL  WORK DONE BY AIRCRAFT SPECIALTIES SERVICES,  TOLSA, OK TEST RUN SATISFACTORY. APPROVED FOR  RETURN TO SCUICE. N. 12054497 APPROVED  Changed OIL & FILTER (PHILLIPS X-6 20~50  CH48108) DENTER (PHILLIPS X-6 20~50

Manufacturer CONTINENTAL		lodel0-200 A	
Serial 63545-6-A		louer	ertificate
This engine is currently installed in aircraft			
Minimum Octane Fuel	Oil Grade:	Summer	_ Winter
Magneto Time_Z8° BTDC	Point Setting_		_ Firing Order _
Spark Plug Gap			
Manufacturer recommended overhaul at		hours	

and the first of the first of the first

# ENGINE LOGBOOK

SEE LOGBOOK 3 for entries after July, 03

#### INSPECTION & MAINTENANCE RECORD

		INSPECTION & MAINTENANCE RECORD
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
96-94	2278.01	Install heft muffler with used sepinlable
	4 2 2	mufflex - Loub Controls - Replace Scott Horas
		tighten As NecesSARY - Repulace Air Filten
		CLEAN FUELSCREENS - ChEAN Dil SCREEN-
		SAFetyed And Checks For Leak's - Run
		UP OK Donald Shadler 511-50-8546
9-6-94	2275.01	ABOVE WORK Superises & In spected.
		Toutify this engine has been insperted INW
		a 100 lu, inspection and was determined to be in
		an arrivathy condition. Jethelyon Alp 523783139
7-22-95	5338.5	Change oil Phillips 20-30
5/18/02	3999.43.	TACH TIME = 2540.43 TOTAL TIME = 3999.43. TXXH=
		1348.4. CAMP CHECK: #1-72/80, #2-72/80, #3-76/80,
		#4-75/80. CHECKED MAG TIMING. CHANGED OIL (20W-
		50 XC) CLEANED + INSPECTOIL SCREEN. CHECKED
		PLIGS. TEST RUN SATISFACTORY, I CERTIFY THIS
		ENGINE WAS INSP. MAIN A 160 HR INSP. AND WAS
		FOUND AIRWARTHY AD NATES CHECED THRU 2002 -10.
		N/2 A1 2054997 1A

NSPECTION	8	MAINTENANCE	RECORD
-----------	---	-------------	--------

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
5/26/02		TACH TIME = 2542.0. REMOVED CARB, DISASSEMBLED
7-7		TO WISDERT WENTURY ADJUSTED FLOAT LEVEL, RE-
		ASSEMBLED AND REINSTALLED. TEST RUNOK ADJUST-
		EO IDEE MIXTURE. 8/D. DI 2054497 ASP
120/22		TACH TIME = 2543.1. REMOVED + REPLACED #3
19/02		CYL FOR O'HACK BY C+S INDUSTRIES, VIOLA, KS.
		SEE SERVICEABLE PART TAG DATED G/18/02 AND W/O
		DOLEA WISTAUED WITH NEW GASKETS SEACS AND
		DISTON PUNGS. TEST RUN OK APPROVED FOR RE-
		TURU TO SERVICE. Attainly 2059497 IA
		17

#### AIRWORTHINESS DIRECTIVE COMPLIANCE

A.D. NUMBER	ITEM AFFECTED	COMPLIANCE DATE/HRS./CYCLE	METHOD OF COMPLIANCE	TYPE A.D.	NEXT COMPLIANCE DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.
-------------	---------------	-------------------------------	----------------------	--------------	------------------------------------	--------------------------------------

Date: 03/01/99, Tach Time: 2498.6, Engine TT: 3957.6, TSOH: 1306.6

Drained Oil and Checked Screens, nothing significant found. Serviced with 6 qts of Phillips X-country 20W50 engine oil. Tighten Throttle Cable clamp near the Carburetor. Compression as follows: #1 80/72, #2 80/77, #3 80/77, #4 80/76. A complete summary of all applicable AD's and compliance is found in AD records accompanying maintenance records. A complete summary of all applicable AD's and compliance is found in AD records accompanying maintenance records. Operational check satisfactory.

I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

Signed

John E. Davolt

A&P512589803

Ni	2 Chang	e Phil	lips 20-50	Xe	6 045	11-15-94
	TACK	Time	2528.14		Day Shad	Dy 511-50-85 4
						U
				$\vdash$		

LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS	LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS								
NAME OF PART PART NUMBER SERIAL NUMBER DATE/ENG, HOURS AT INSTAL T.B.O. DATE/ENG, HOURS CERT. NO.	NAME OF PART	PART NUMBER	SERIAL NUMBER	INSTALLATION DATE/ENG. HOURS	TIME ON PART AT INSTAL	LIFE LIMIT OR T.B.O.	SCHED. REMOVAL DATE/ENG. HOURS		AGI
DATE: 10/01/95 TACH: 2351.94 TIS: 3810.94 TSMOH: 1159.94 .	- sel chi	Dona -	of 24	39,53 1. 511-	50-85	46	0 =50 X		
CLEANED AND ROTATED SPARK PLUGS. CLEANED GASCOLATOR AND CARB.  SCREENS. REPLACED AIR FILTER ELEMENT. CLEANED OIL SCREEN AND CHANGED  OIL. CHECKED MAGNETO TIMING. COMPRESSION CHECK OK. OPENED MUFFLER  SHROUD AND INSPECTED FOR CRACKS, LEAKS, AND SECURITY OF INST. LUBED  ALL CONTROLS.  — I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IMP A 100 HOUR  — INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY  — CONDITION.  Dec 17, 95 Tack Time 2363.6 Rejustabled 41/  Cylends, after North Completed By Bren August  Ruyup af Cles Complained 62.  Onil 26-1996 TACK  Onil 26-1996 TACK	Com scree Repa comp satist	en for metal no ired broken ba bliance is foun factory.	ck Results #1 othing signifi offling bracked in the AD ongine has be	80/78, #2 80 cant found. Fet on #4 cylin book accomp	ne TT: 392: 0/75, #3 80/ deset E-gap of der. A complanying the manacordance	77, #4 80/7. on RH magniete summan naintenance with an an  2 Oau  Davolt 12589803 IA	5. Changed of teto. Replaced by of all application records. Ope nual inspection.  Ref: 98	inlet air filter. able AD's and rational check n and was	<u> </u>

#### INSTALLATION

		INSTALLED			REMOVED					
DATE	TYPE	CRAFT SERIAL NO.	LOCATION	TOTAL TIME	DATE	TOTAL TIME	AGENCY AND CERTIFICATE NO.			
71293	TACH:	2217.2	Service	al en	sine u	/ 6 at.	Als cleaned			
			oil & fue	SCRE	ens. R.	placed				
			Compre	5.00	72, 747	172 7	ENSPERTED PROP.			
			Ad's dw	, I	CKTIFY	4 1 2 2 3	WGINE 14115 BEEN ENDY.			
			IAW. AC				AND WAS DETERMINED			
			To BE 11				DITION.			
				J. 11.	Ellen	/	3783139			
						/				
1-8-94	TACK	2253.7	Charge	0:1	with P	4.11.ps 2	C20.50 D. Shadler			
3/23/94	Tack	2261.8	Cleaner	P Val	ne &	reich	on 3 cylerales			
, , ,			Replan	ed ;	4 KC	leno	will			
			Obelse	Cert Ci	slevel	5.	ee tag,			
			Donks	R Fes	le,	DP ZZ	18929			
\$			11.	,						
			1							
						The state of the s				

			INST	ALLATIC	NC		
		INSTALLED					REMOVED
DATE	TYPE	SERIAL NO.	LOCATION	TOTAL TIME	, DATE	TOTAL TIME	AGENCY AND CERTIFICATE
7-'			ED 2 CON	IT OUI	INDEDC	, CLEANEI	_
						WITH AI	
			RESCENT				
			ALLED NE ST SEATS			REFACE	<u> </u>
			SI SEALS ST GUIDE				1
						217610	R18 _
			2/5	t	18+1-	217610	
	1 -						- 1.2
309	14 7	cerls 7	Trie 2	2780	R.	austo	the D
ena	les	1+3	burn	no te	11	2 h	to
1 9	Votal	FR	han	No.	tores	1-00	tite .
nle	PZ	120	140	27/9	397	1	
	1	1	AUI	4-61-6	75	1	
436	0 40		1 1	. 1 0.	2.01	11/100-	SowH
1100	4 22	DANGE	ENG O	1 11	room	50-8546	BUWII
18-95	00	18.01	- Day	MAdles	00.	0000	20-50
to	L Ch	lange 1	ing ow	Has Dil	ins	The state of the s	511.50.050

TACK 2301.18 (23.17) HAS OILCLES. Day Shadley 511-50-45146

#### **ENGINE DESCRIPTION**

MANUFACTURER CONT.	MODEL 0-200
SERIAL NUMBER 63545-6-A	DATE OF MANUFACTURE
RATED BHP/SHP/THRUST	RPMMANIFOLD PRESSURE
FUEL REQUIRED OCTANE/PERFORMANCE	ALTERNATE FUEL
PROPELLER SER. NO.	DATE INSTALLED
REGISTERED OWNER	- DATE INSTALLED
STREET & NO.	
CITY, STATE, ZIP	
DATE PURCHASED	DATE SOLD
REGISTERED OWNER	DATESOLD
STREET & NO	
CITY, STATE, ZIP	
DATE PURCHASED	DATE SOLD
	DATE SOLD
TBO HOURS	
	LAST OVERHAUL DATE/HOURS 3

## **ENGINE LOGBOOK**

Cont 0200A SN 63545-6-A McCauley 1A100

Logbook No. 2

From 5,19,93

To 5019 63

© 1988 by IAP, Inc.
All Rights Reserved
International Standard Book Number 0-89100-331-2
For sale by: IAP, Inc., A Hawks Industries Company
Mail to: P.O. Box 10000, Casper, WY 82602-1000
Ship to: 7383 6WN Road, Casper, WY 82604-1835
(800) 443-9250 + (307) 266-3838 + FAX: 307-472-5106

HBC1192 Printed in the USA





## ENGINE

AND PROPELLER LOG



SERIAL NO. 63545-6-A

N 26985

PROPELLER INSPECTION & REPAIRS	
INSPECTION REPAIRS	MEMORANDA
DATE INSPECTED BY CONDITION DATE REPAIRED BY REPAIRS MADE	
6-1-92 TACH: Replaced air healther element, replace	Date 11-30 &2 Oil Change - 5 gts Blillips 20-50 XC TACK READS 1159.61 R. younger. 2-12-35 " " 175.00 "
paints of condenses. PH Wage, Replace Ben. spark plugs, Change	
ail closued oil scroen, cleaned fuel scroens, Serviced oil system	1-1-93 Change oil with Phillips XC 20-50 TACK TIME 2192,89 D. Shadley
w/ Phillips XC. Compression aheck all 70's plus.	
I certify this engine has been inspected TAW as 100hr.	
inspection and has been determined to be in an airworthy	
Condition J. Phillips AP 523783139 AI	

DROBEL	LER INSPECTION	& REPAIRS	PROPELLER INSPECTION & REPAIRS							
FROFEL	LEK 11451 Letten	the state of the s		INSPECTI	ON			REPAIRS		
INSPECTION		REPAIRS	1117 - 1117		Y CONDITION	DATE	REPAIRED BY	REPAI	RS MADE	
DATE INSPECTED BY CONDITION DATE	REPAIRED BY	REPAIRS MADE		TALL	smoul		Dan inimit	SCIPAL SOUTH	ED WITH ACROSHER	
2/20/89 TACH 1493.2 X	7-7-	TER Clubos HSSY 8/18 1971890	40	2032-39	840.39					
3	P 15 KZ	1 Act 475564928	- 50 cm	T. CLAM	GADDED.	+ TESTE	D PLOGS. Com	CHEK #1 1/80 #	Z 174 6 #3 760 #4 90	
2/16 THA 18444 Smort 6			CLEA	WED START	BR SWA	TH CON	ACTS. ANDUAL	INSPECTION C/u	I THIS DATE.	
			IC	CRITEY YUR	THUS E	NETWE	HAS BEEN IN	PETED IAN I	AN RUNUAL	
GARTER STURES HESSY	P/N 1971850 1	200 11/2 walnty Restand	INS	PECTION	AND 4	AS DE	TERMINED -	O BE IN LO KA	RUDATHY CON DATED	
RH MAL TEMPLES. LE	495564925	-1		3	Greco	lef of	And Al	19554761A		
	LICERTIFY THAT THE	SALRERAME								
	190 FIR INSPECTION	TH AN ARNUAL								
	VILLERIVING DE	THAN ION PIGSTUGIA								
	2 Post of	D19554461A	1							

ENGINE LOG

	1			ENGINE TO		
DATE	DURATION		TIME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
19		HOURS	Ютнѕ			
M	nes	13.	198	8 TACH 1469 HRS		
	/	cen	Ti	of that this engine has been	aspected 1.4	w
	a	100	40	inspection and has been dele	ennel To be	
	10	OILL	von	744 Condition	1 60 0	
				Of JAjora	1795910	
1				gener and		
					1	
-	LT					
-						
			CAR	RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEX	KT PAGE	
			CAIL			

PROPELLER INSPECTION & REPAIRS

	INSPECTIO	N			REPAIRS
DATE	INSPECTED BY		DATE	REPAIRED BY	REPAIRS MADE
Feb. 1,	1989 TACI	4/651	1 Sme	4 459,1 Comp	ression #/ 7/80 \$2 7/80 #3 7/80 # 77/80
1				+ thy cyl., Adj. K	
Resaire	el P' leas	el RH MA	E. Repl	seed STARTER I	Brushis Deartify thet this
ingill	e has been				QIEOHR Despection and was
deter	mineel to	Be in	An Acres	cortly Condita	on Pol 5. Kel f. AH 495564928
-1	1 500		1		LOSDER
Kes.	1889	TACH	651.1	SMCH 459.1	I CERTIEY THAT THIS AIRFRAME
					ENGINE HAS BEEN INSPECTED
	-				IN ACCORDANCE WITH AN ANNUAL
					100 HR INSPECTION AND WAS
			-		DETERMINED TO BE IN AN
					AIRWORTHY CONDITION
		-			All leafed all
					A STOCK OF THE STO
	-				1/66047
- 46				2	

ENGINE LOG			ENGINE LOG								
DATE DURATION ACCUMULATED TOTAL TIME REPAIRS ADJUSTMENTS SIGNATURE 19 HOURS IOTHS	LICENSE NUMBER	DATE D	URATION	TOTAL TIME HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER				
10/3/8/2 /ms/4/2 MEW Daints Londenser Dist.  1000 DIC 1A15 NATE 8-18-86 WITH ASSESSED 10-14 86 TACK TIME 1305.65 OIL CHANGED WITH AEROSH 100 W OIL 1A15 NATE 8-18-86 WITH AEROSH 100 W OIL 1A15 NATE 8-18-86 WITH AEROSH 100-14 86 TACK TIME 1311:94  10-14 86 TACK TIME 1311:94  10-15-86 TACK TIME 1317:04  TOSTALL SITE SE 20316 E FOR USE AUTOMOTIVE FUEL WITH EAST ASSESSED TO THE STALL TO THE STALL TO THE SITE OF ASSESSED TO THE STALL TO THE STALL TO THE STALL TO THE STALL SITE OF ASSESSED TO THE STALL TO THE STALL THE STALL SITE OF ASSESSED TO THE STALL THE STALL THE STALL SITE OF ASSESSED TO THE STALL TH	46CC 224	3-25-36 8-2-50 FEB3 1948	rac.+	Changed (378.4)	extery that this pircraft has to accordance with a annual was developed to be in air all the so Ken Messen 12 H3076  OIC CHANGE - ALLERA FALLET - OVER CHANGE - SCHOOL OF CONTROLL  SPARKALINGS Cleaned & GAMPER - SL	worthy Condition	acid				
CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE				CAR	RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	EXT PAGE					

ENGINE LOG ENGINE LOG ACCUMULATED DATE ACCUMULATED DATE LICENSE LICENSE DURATION TOTAL TIME DURATION TOTAL TIME SIGNATURE SIGNATURE REPAIRS --- ADJUSTMENTS REPAIRS --- ADJUSTMENTS NUMBER NUMBER HOURS IOTHS HOURS TOTHS LLEAN OIL SEREEN AEROSHEL RESET Timing 1.6 Enn FUEL Proge To FIRE WALL I certify that this Acade The has the I certify that this EmainE inspection as required by FAR - 43 inspected in accordance with annually and has been for inspection as required by FAR - 43 COMPRESSION TEST and has been found anworthy. \_\_\_\_\_ CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

10-12-37 TACK READS 1158.0 XXIVER ENGINE LOG ENGINE LOG MOREZAND OWNER DATE ACCUMULATED ACCUMULATED DATE LICENSE LICENSE DURATION TOTAL TIME DURATION TOTAL TIME REPAIRS --- ADJUSTMENTS SIGNATURE SIGNATURE REPAIRS --- ADJUSTMENTS NUMBER 19 84 NUMBER HOURS IOTHS mene test 1192, Magor, Overhand, Engene Completed Chene all Steel Pots & Macon Set inteles & So that Valore Out. you bed segs 27 Enger age to Monday Skedictires Overthe Phillip XC 20 -50 cmt Complete with Boante 77-1303 Mas amendant, Jus 271927, One arithel with D 3. 33552 I certify that this engine or aircraft has been inspected in accordance with a Conne inspection and was determined to be in an airworthy condition. Bayman Starry CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

				ENGINE LOG						ENGINE LOG		
DATE DUR	RATION	TOTAL HOURS	TIME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	198Z	DURATION	ACCUMULATED TOTAL TIME HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
10-2- 10		2158		from Sayota Secrit	il clientis cit	4 6 1 80 Chairt		-87-	anica to	Lefen That This Engen I mappelled land 20 See in Con reothy Con 10-2-82 Charlo R. 1 J.A. 1702687	of an Other detects	
					101		1		CARI	RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE.		

ENGINE LOG ENGINE LOG DATE ACCUMULATED ACCUMULATED DATE LICENSE LICENSE DURATION TOTAL TIME SIGNATURE DURATION TOTAL TIME REPAIRS --- ADJUSTMENTS SIGNATURE REPAIRS --- ADJUSTMENTS NUMBER NUMBER HOURS IOTHS HOURS IOTHS CHANGED OIL P 210 8668 obter one HERO SHELL IN 50 WT. 10/0 @ 68/ 0 68/00 a 1/60 removed pluy cleaned 1-3-81 sel screen replaced with areasheld Checked exhausto system 2/18/81 2417 Rilly W Word 341350/1861 CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE MANUATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

			ENq.	T. T.	ENGINE LOG		
DATE 1976	DURATI	ON	ACCUMU	LATED TIME	REPAIRS ADJUSTMENTS	SIGNATURE	NUMBER
10-8			2140	00	Tack reads 681.0 T.S.M.O.H. 839.0	#3 and #4 cyl	5.
10 0			2110		removed due to leaking intake values	replaced in a	ex
					value auides in both cyls, replaced	both intake va	lues
					and one ex, value. Left mag replac	ed oil seal, both	Mags.
Lewis .	2				c/w A.D. 74-26-9 both inputse coupli	ng bushings rep	Jaced.
					Replaced alt. drive couplings, replace	d tack drive se	eql,
					Engine serviced with 5qts. Mobil 30w	white band mineral	oil,
		I		7-	ran on ground and test Flown .	0.1 '4	
					All and the North Control of the Con	Winters.	
					a CLYPAN. inspection and found to be airworthy."	1898473 I.A.	
						1 and a second	Shell
1-4-78			2158	00	Idell reddo la live		
		-			65 mineral oil used, Replaced bottom s	ark plugs, mag	11111111
					set at 24° to comply with A.D. 77-13-3, #2	cyl, pushrod tube	3 Malled
				-	and rocker box gasket replaced.	9.1	
					41 certify this CNGN C. has been inspected I.A.W 20	P1898473 I.A.	
					RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	TRACE	
				CAR	RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEX	TAGE	-

ENGINE LOG

DATE					CICNATURE	LICENS
19	DURATION	TOTAL THE CICNATURE			NUMBE	
5-3-79		217/	00	Tack reads 717.0 T.S M.O.H. 875,01	ars, Changed oi	1 and
			-	cleaned screen, Checked comp, and ma	q. timing, Replace	ed
				too spork place. Dressed prop and	painted tace,	
				11 portify this ENGINE has been inspected I to we have	Whenles	
				Art	1898473 IA.	-
					0 10 70 -1	2
				Note: AD 78-09-07 both mags were N	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	e at
				total time 1452 therefore impulse INSPE	all intere ALDIE	18 473
				engine ile of 2452,0 or before, to	THE PLANT OF THE PROPERTY OF T	
-21-79		2.190	00	THOU DEADS 73/ DEMOUED # / 6'#.	3 CYLS. DUE TO	
		2170,	00	LEAKING NAINES - GUIDES & VALUE SE	ATS CHECKIED GO	100.
				DECROUND HALVES ON BOTH CYLS.	INSTITUTED NEW	
				RINGS & GASKETS, MyKainier ASP	2104664	
				T.S.M.O.H. 889.0 HRS.		
					-	
				DEV. ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEX		

CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

E					241 ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (					ENGINE LOG DAVID HE	S DATE EDGES -OWNER	,
	W.			ENGINE LOG		LICENSE	DATE	4.00.00	ACCUMULATED			LICENSE
DATE	DURATIO	N ACCUMULA	TIME	REPAIRS ADJUSTMENTS	SIGNATURE	NUMBER	19 75	DURATION	HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	NUMBER
19 /		HOURS I	IOTHS	10 474 sil chance Pb6	004 Lot	-	9-20			Annual insp. time S.M.O.H. 747.0	hrs Tack rea	ds
2/2	18/74	Tack	6 T		80A 69t		140		2048 00		aking in valu	
3/3	0/24	Toch	Te	300 //	A 50					Replaced both value quides, replace		
5/14	1/24	Tack	Te	ne 53 to oil change 100	al Civily to	2710"	*			installed with vew rings scals + qu	skets, ckéd	and
5/3/	124	Tach	100		the a realing	The same				adjusted mag. timing. 6 gts. Phill 3	om oil used. E	ngine
Eng	fere &	ac 10:	en		- arrivale							-
200	peoli	9	Sa J	the live for rango to be	100					The BASING .	Winters	
CON	12/2	- 3	W X	Jan 1 569 1	Mr. Shely A	P2225060				1 Certify Unis Septem - Has been Inspected 1. A. W	P1898473 I.A.	
1/2	8/14	Phh	100	A Tara Jane			_			a and found to be airworthy."		
11/2	20/14	000	2	80A 586	V		12-2	75		Tack time 614 Changed oil , Shell	65W replaced	
11/2	1		8							starter, clutch + bushing & seal.	on Winters H&P 189	\$473
										,		1
							2-18	-76		Tack time 639 changed oil Shell a	5W and cleane	.d
		4 3 4				-	-			screen San Winters A & P 1898473.		
							6 E 11	~1			1 02 01	1
							5-11-	16		Tack 664 changed oil, Shell 50	Atplage	73
							-					10
			CARRY	Y ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEX	KTPAGE	-	-		CAI	RRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	ATPAGE	

ENGINE LOG ENGINE LOG DATE ACCUMULATED LICENSE ACCUMULATED LICENSE DURATION TOTAL TIME SIGNATURE REPAIRS --- ADJUSTMENTS SIGNATURE TOTAL TIME REPAIRS --- ADJUSTMENTS NUMBER DURATION NUMBER HOURS IOTHS A5 1 2228060 Charge 100 hr draguetin J866 100 Ded 66 100 A Alu #68 228060 imus 166 10014 and have determined it to be in alrearthy P66 sondition, Date: 2-1-1974 1146 Oil 613 Ann MHO Rock Flore 400 17 Malas CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE A 17640 CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

ENGINE LOG ENGINE LOG DATE ACCUMULATED DATE LICENSE LICENSE DURATION TOTAL TIME DURATION TOTAL TIME SIGNATURE SIGNATURE REPAIRS --- ADJUSTMENTS REPAIRS --- ADJUSTMENTS NUMBER NUMBER HOURS IOTHS HOURS IOTHS Time A curilly that this Age been inspected in accordance with 66 and have destructed it to be in serworthy (livina 1514: 187 Sim & De ha CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

				ENGINE LOG						ENGINE LOG	
DATE	DURATION	TOTAL HOURS	TIME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	DATE 19	DURATION	ACCUMULA TOTAL TIN	TED ME REPAIRS ADJUSTMENTS SIGNATURE DTHS	LI
3841	VT 70						9-3-1	20	1340	41 Total aircraft hours, Tach realing Latel	Z
-	lass be			100 HOUK Inspection completed	on this date.		1			1340,41 Dantify that this enged how been	
		1		I certify this . ENG! Mt has been inspected i	n accordance				ins	parted in accordance with an admial inspection	n
				with A/N	nd to be air-		4		and	was determined to be in airworthy qualities.	Ĭ
- 0.1	0-11			worthy on this date. All items listed on work	order and in-				T5,0	10 41 houses.	
22-	4 (4)			spection forms No. 15.5.7 All A D no						James a Creft	
	ASTRONO I		4	with to date. Eyrin M. A	unt h. AYPI	1819510				11 1143707	
				TACH 1340,41	10			,			
1				TSMO 41			10/	28/70	i	20 HOUR	
_	X						_/	1	Leoni	fy this ENGINE has been inspected in accord.  TAKINGED	-
									with A		
-									Worth	y on this date. All themselves and found to be air	
-							· —		month	of this date. All items listed on work order and in	
									pheceto	All A D notes complied	
1-									TAC	H 1440 Enrive I Start In At 1819510	
						_			150	on this date. All items listed on work order and in- on forms No. 12 7	
-									NENT	NOO HOUR DUE 1540	
			CARR	Y ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEX	TPAGE					CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE	

CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

LICENSE

NUMBER

		ENGINE LOG								
RATION	ACCUMULATED TOTAL TIME	DEPAIDS AD WATER		LICENSE	DATE		I ACCUMULATED	ENGINE LOG		
	HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	NUMBER	19 70	DURATION	ACCUMULATED TOTAL TIME HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE
		June -59-1970	accordance I to be air- I to be air- der and in- s complied  1/20466  / Complete  / Comple		8/	MOB I	L 40 DET	MARTOR OVERHAUL OF ENOUNE 40 NEW POTONS, NEW RINGS, NEW PISTON P GASKET SET, NEW MOTOR MOUNT, BU PARTS MACKAPFLICKED, ENGINE CLEAN REASSEMPLED WITH NEW STANDARD MAIL STANDARD ROD BEARINGS ENGINE ASS MANFACTURES SPECIFICATIONS, ENGINE K WITH RECOMMUNDATIONS, I CERTIFY ALRWORTHY ON THIS DATE STATUL TIME 1301 hm. TSPM O 2 hm WORN ORDER # 1556	MIROME CYLINDE VIN BUSHINGS, CO VISHINGS, PLL ST ED AND INSPECT VI BEARINGS BIND VINSUED ACCORDE VIN IN INSCCORDE THIS ENGINE	RS. WELL  NEW  NEW  NEW  NEW
							CAR	RY ACCUMULATED TOTAL TIME FORWARD TO TOR OF MEN		

				ENGINE LOG			ENGINE LOG							
DATE	DURATION	HOURS 10	мЕ Этнs	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	19 20	DURATION	ACCUMULATE TOTAL TIME HOURS IOTH	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER		
		2/19 70		Teerthy this England. has are aspected in with A. X. E. C. Harry. has are aspected in a with the forms No. 222 All A D room with the forms No. 222 All A D room with the father Mading 100/3 Hams father time on Engine. 100/3 Hams of the forms of the form						certify this Engine has been inspected on this a rith A/N (Coldan Inspection and found to be rothy on this date. All items listed on work order and spection forms No. 1/6 B. A. D. Dotes comparith to date.  The Engine 1/03 Idan.  Tatal time on Engine 1/03 have	lied 7/70466			
									CA	ARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT	PAGE			

ENGINE LOG

				LINGTINE EOG		
DATE	DURATION	ACCUMULATED TOTAL TIME HOURS IOTHS		REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
19 /9		HOURS	IOTHS			HOMBER
12	129/6	7 /	58	Stand inspection Completed	on this d	ate
,	,,,,,	- Oi	l'	hanged Mobil #30, screen	Checked Compas	sim
		tes	1	Shoris Pleaned and gouned (	toints and de	mung
		Chi	ehe	Cypaust System Theched	Visapelle Class	lest
		Car	lun	ating filly Cleaned Winterwatter	Let installed	
		0	Cer	telef this Engine has been	Inspected.	in
		æ	ble	Dance Ditte a 100 Han	nonetun a	no.
		*	au	all amostly on this date	· Dhit p & no	linay
		0		Tachimeter Reading 811:00 How	14pt/17046	614
				Total time 811:00 Hausi		
-				DV ACCUMULATED TOTAL TIME FORWARD TO TOR OF ME		

CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

ENGINE LOG

DATE ACCUMULATED LICENSE DURATION TOTAL TIME SIGNATURE REPAIRS --- ADJUSTMENTS NUMBER 19 70 HOURS IOTHS Alp Exoting MP 964. Hans Hauro BREER FINSP FORM NO 10/2

CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

				ENGINE LOG						ENGINE LOG		
DATE 19	DURATION	TOTA	MULATED LL TIME S IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	DATE 19 69	 TOTAL TI	IME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
			CARRY A	ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	Parents of the control of the contro	A TOPE				Chiefeed oil Changed screen  Chiefe and fuel lines Checked  Caningle for hum longerted de  With a looke importee Conk  in this Out  Tachantee Times 710.13 Idan	Clucked all al Certify accorded fund anno	
							-		CARR	Y ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	KT PAGE	

	ENGINE LOG						ENGINE LOG		
DATE DURATION ACCUMULATE TOTAL TIME HOURS INTH	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	DATE		ACCUMULATED TOTAL TIME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
19 (8 HOURS 10TH  Auly 10 3/34 / C  9/4/49 579 45	REPAIRS ADJUSTMENTS  COMP. CHECKED OTTO BTO TO THO THE CHECKED.  Plugs CHECKED + Timing CHECKED.  I CERTIFY + HIS ENGINE HAS BEEN INSP. IN ACCORD ANCE WITH A  100 HR. INSP. AND WAS FOUND IN  AN AIR WORTHY CONDITION  Oil Chanced this date and 5 gt.  E-80 put in  100 HR. INSP.  COMPRESSION CHECKED OTTO BY TO THE COMPRESSION CHECKED ENG.	Dwight C. Ata At 1 Odgar G. Charles	167 45 98	19	o circuit paired and Aviatic with the far a	TOTAL TIME HOURS IOTHS  TOTAL HOURS IOTHS  TOTAL HOURS IOTHS	Charles	SIGNATURE  Congression, in  R-88 synthemical so  might to the sound of	
CA	Timing CHECKEL. OI'L SCREEN CLEANE SERVICEL ESSO E-80 OIL-THIS ENGI HAS BEEN INSP. IN ACCORDANCE WITH A INSP. AND WAS FOUND I'N AN AIRWOME RRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	100 HR DAN CONDITION. AC	St C. Ston			TO TA	Maine Flying Service, Inc.  oved Repair Station #1375.  I T - 696.  RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	XT PAGE	

	DURATION TOTAL TIME HOURS NOTHS  318 32  352 39 Complied with Continental Service Bullet MARGES CFI  M67-6 pertaining to reader arm shaft  to lease cleareness.  362 87 Changed ail (F 80 Ease) cleaned exceen cleaneds gapet spans plugs  Veneger King				4	-						
DATE 19	DURATION	TOTAL TIM	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER	DATE 19 48	DURATION	ACCUMU TOTAL HOURS	TIME	ENGINE LOG  REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
6/1/67		318 32	2	MY 1403962 CFI		9 Mar				50 hr Eng Check Oil changed		
7/21/67		352 39	9 Complied with Continental Service Bu	Act						Screen eleaned theat shrowd replaced, new O'Rings installed		
_				Duagne King	A.P.1645328	1-				In Gascalator.	Anewer Dist	hautera
8/1/67		362 8	7 Changed oil (= 80 East) closed across		2	1700	ine.	518	,09	50 HR CHECK		741654649
1/			cleaned gapet sport plugs	Gregge King	ANP1645728					CHANGED OIL CLEANED SCREEN	८७७ भड	2/14/20
40cT67		415 13	Changed oil (E80) Screens clear	ne d		-	4 5	3	-	CEERNES OFFICE	Lurghe Cito	1674598
-	14	ut u	Spark plugs cleaned & gapped. I certi	Sy		_				2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -		12.34
										the second second second		
-			end was determined To be in air	VOVILLE						The second secon		
				Elmus Depta	AP1659699		64			AND 1200 AND 1200 AND 1	18	
the second		C	ARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF	NEXT PAGE					1 1	the state of the s	-	

TO TOP OF NEXT PAGE

			ENGINE LOG		
DATE	DURATION		REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE
1966		HOURS IOTHS			NUMBER
9-17			Clarge Pail with Engor E- 50, 53To D		
			1 ca 5.T.P. Clanes all sera a Q		
			showers cleaned pluga and exception		
			Comprehen Transing and route Charles		
			The state of the s		
			COMPRESSION SHIEN #2 COLTSCOTHIC	R	
		D.	TE 2-17-16 TIME ON AIRFRAME ENGRICE 30 80		
			TACH TIME 200.44		
			certify that this Anguera has been inspected in ac-		
		co	rdance with a formal inspection, and was determined		
		to	be in airworthy condition. All applicable AD Notes have		
		b	en complied with, and are listed chronologically in back of		
		10	g book along with a description of the method of compliance.	PHZZXON	
		CAR	RY ACCUMULATED TOTALINIMENEORWARD TO TOP OF NEX	TPAGE	

				ENGINE LOG		
DATE	DURATION.	ACCUMULATED TOTAL TIME HOURS IOTHS		REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
1966		HOURS	Ютнѕ			-
11/28		239	06	CIL CHANGE - WINTER OIL		-
5-1-67		273	315	r 100 de Unspectión		
				all some and expense Red		
				del santo and acreen or leplace Red		
				sport plans shruse an soreen.		
				chapetel in occardance with a		
				to be in arrivably condition.		
6-7-67						ATT1487504
-	TACH	312	57	Changed oil with East E-80 Set		
-				plans	She but D. Jenh A	491487564
M-				TIME: FORWARD TO TOP OF NEX	CT PAGE	

CARRY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NEXT PAGE

				ENGINE LOG			-			ENGINE LOG		
DATE 19 66	DURATION	CCUMU TOTAL OURS	TIME IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE	DATE 19 6	DURATION	ACCUMULATED TOTAL TIME HOURS IOTHS	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
4-24-66 4-27-66 5-1-66 5-8-66 5-15-66 5-21-66		28 34 46 56.	26 /2 12 61 95	Changed oil reggest doll spred.  RY ACCUMULATED TOTAL TIME FORWARD TO TOP OF NE	R CLARK M03962 C R CLARK M03962 C R CLARK M03962 C R CLARK M03962 C R CLARK M03962 C B CLAR	FF				DATE TIME ON AIRFRAME-ENGINE 99.60  I certify that this has been inspected in accordance with a secondarie in airworth; condition. All applicable AD Notes have been complied with, and are listed chronologically in back or log book along with a description of the method of compliance Rating & Number Rating & Number		
			Onit	TO TOP OF NE	ATTAGE		12.			THE FORWARD TO TOP OF NEX	TPAGE	

TOTAL TIME FORWARD TO TOP OF NEXT PAGE

ENGINE I	DESCRIPTION			ENGINE LOG		
Mfgr. Continental Place		Date	DURATION TOTAL TIME	REPAIRS ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
Type I- opposed Model	200-A Serial No. 6	3545-6-A 196			76 Edioardo	12000
Rated H. P. / Maximum H. P			15 15		TO OULLES	1337313
Rated R. P. M. 2750 Maximum R. P	o.M. 2750 Oil Pressure					
Bore Stroke	Displacement	Cu. In.				-
Compression Ratio Supercha.	rger Ratio Gear Ratio					735-
Propeller Mc Cauley Hub Design	gn / A 100 Hub Serial	No. 1-2/28				
Blade Design Blade Serial	Blade Serial Blade	e Serial				-
Maximum Hub H. P. Maximum	n Blade H.P.					
Pitch 50" Diameter	Leng	th				-
	7					-
					-	
Owner's Name						
Address	City St	ate			DE NEVE DAGE	
		4886	CARRY	ACCUMULATED TOTAL TIME FORWARD TO TOP C	OF NEXT PAGE	