

			EO STATUS REPORT			Complied Count / Preclusive : 415 / 1 Partially Complied Count / Preclusive : 9 / 0 Not Complied Count / Preclusive : 221 / 4 AMOC Count : 1		
A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
STCSA615EA Rev IR 02/19/1968	Installation of Whelen Anti-Collison Lights		Not Complied				As Required	
STC SR00811NY Rev IR 12/23/1997	Installation of TFM-550		Not Complied				As Required	
BT139-008 Rev A 10/09/2006	Overhead CB Panel Assy drawing P/N 3G2490A00233, replacement the Auto Trim breaker P/N MS3320-5 with MS3320-7-1/2.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-46-001 Rev IR 03/01/2005	Primus Epic, Flight Software 2.4.0		Complied - N/A N/A by A/C S/N, confirmed on 09/15/2015 rcs -- Era QC			07/13/2011	One-Time	
BT139-003 Rev A 08/01/2008	Variant 4th flat panel display P/N 3G4630F00111 installation of.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-004 Rev IR 04/18/2005	Upper deck insulating covers P/N 3G5306P07511 installation.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-017 Rev IR 09/23/2005	Ejector Ducts Retro Modification - drawing P/N 3G7800P00711		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-009 Rev A 11/10/2005	Pt.I: insp of the lt&rt brake pedal assy pilot & copilot 2 Pt.II: rework lt & rt brake pedal assy pilot & copilot		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-020 Rev C 08/05/2011	Inspect and Apply Life limit to Fin Assembly P/N 3G5351A00132,3G5351A00133,3G5351A00134		Complied BT139-020 is cancelled, the limits and inspection intervals contained in this BT, are now included in the latest revision of Airworthiness Limitation section of IEPT. --			HWO-001424-2011 20.3 FH 09/13/2011		One-Time
STCSR02054LA Rev IR 01/02/2006	Installation of an Emergency Medical System *		Not Complied					As Required
AD2006-04-04 Rev IR 03/24/2006	Meggit Model 602 smoke detector replacement		Complied This AD is not applicable by part number smoke detector installed --			HWO-011484-2020 5437 FH 06/08/2020		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-053 Rev IR 04/19/2006	NIC-200 (Network Interface Controller) P/N 7026542-1901.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-022 Rev C 10/21/2009	Emergency floats and life rafts P/N 3G9560F00111, installation of.		Complied - N/A Not applicabl by aircraft serial number. T. Ross AAC -- Era QC			-- 01/01/2011		
BT139-068 Rev IR 08/30/2006	External hoist installation P/N 3G2591F00111 (Breezeeastern P/N HS-20200-421-02) inspection of.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-027 Rev B 03/29/2019	*	Cargo hook kit P/N3G2592F00111 install.Video module interface kit P/N 3G9310F00212 install.Cargo hook video camera kit P/N 3G9770F00111 install.		Not Complied			As Required	
BT139-051 Rev A 03/29/2013		Weather Radar Primus 701 kit P/N 4G3441F00111 installation.		Not Complied			As Required	
BT139-025 Rev A 11/27/2018	Installation of the KTA 970 TCAS 1 System with application of the kit P/N 3G3450F00311		Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011		As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-070 Rev IR 09/22/2006	Primus EPIC Flight Software Release 3.6.0 Installation.		Complied - N/A Not applicable by software installed T. Ross, AAC -- Era QC			01/01/2011		
BT139-030 Rev A 10/09/2006	Weather Radar Primus 660 Kit P/N 3G3441F00112 installation.		Complied Performed security an attachment inspection. Verified the Primus 660 Wx Radar System installed from OEM. No known defects noted. Performed security an attachment inspection. Verified the Primus 66 --			HWO-001421-2011 20.3 FH 09/21/2011	As Required	
BT139-014 Rev B 10/09/2006	PRIMUS EPIC fight software release 3.3.0 installation.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-64-002 Rev B 10/09/2006	PtI Inspection of Slider Assy P/N 3G6430A00131 of the spider and Slider Assy P/N 3G6430A01931.PtII Replacement of the Slider Bushing P/N 3G6430V00251.		Complied - N/A N/A by A/C S/N, confirmed on 09/15/2015 rcs -- Era QC			07/13/2011	One-Time	
BT139-047 Rev A 10/09/2006	Fan MGB Cooling P/N 3G6320V03853,		Complied - N/A N/A BY PART S/N. T. ROSS AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-011 Rev C 10/09/2006	Fairing assy LH P/N 3G5306P02233 or P/N 3P5330A31131.		Complied - N/A N/A by A/C S/N, confirmed on 09/15/2015 rcs -- Era QC			07/13/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-031 Rev A 10/09/2006	* 	Kit external hoist (feet four way) P/N 3G2591F00111 installation of.	Not Complied				As Required	
BT139-013 Rev B 10/09/2006		W/D DC External Power P/N 3G2440W00101.	Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	
BT139-010 Rev A 10/09/2006		Replacement of the VNE Placard Illuminated P/N 3G1130L00152 with new VNE Placard Illuminated P/N 3G1130L00155.	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-049 Rev A 10/09/2006		Water Activated switch P/N 503-23.	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-016 Rev B 10/09/2006		Replacement of the pedal assy P/N 3E6721A00135 with new pedal assyP/N 3E6721A00136.	Complied - N/A Not applicable by aircraft S/N. T. Ross AAC -- Era QC			01/01/2011		
BT139-005 Rev A 10/09/2006		Operational Envelope Expansion Part I Replacement of the Sliding Ring Assy P/N 3G6220A00432. Part II Replacement of Main Brake Assy P/N 3G3240V00332.	Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-018 Rev C 11/07/2017	Middle section frame 5700 inspection.		Incorporated into aircraft build. JFONTENOT 08/16/2019 -- Era QC			Manually Updated -- 07/13/2011	One-Time	
BT139-059 Rev A 11/06/2006	PtI: Repl of defective pressure switches of the #1 hydraulic power system.PtII: Repl of defective pressure switches of the #2 hydraulic power system.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-045 Rev IR 11/07/2006	Alternative 27Ah Auxiliary Battery Installation Kit P/N 4G2430F00112.		Complied - N/A Not applicable by part number installed, R. Cohn, AAC -- Era QC			01/01/2011		
BT139-038 Rev G 08/29/2019	Kit Health and usage monitoring system installation.		Not Complied				As Required	
BT139-021 Rev B 12/04/2006	Auxiliary fuel tank Kit P/N 3G2800F00111, installation of.		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	
BT139-052 Rev IR 12/08/2006	Kit acrylic windshields P/N 3G5610F00211.		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number	Date					Next Due
BT139-029	Installation of snow skis & slump pad fixed provisions		Not Complied					
Rev A	*							
05/30/2008	Parent							
BT139-029 PART I	Installation of snow skis & slump pad fixed provisions		Not Complied					As Required
	*							
BT139-029 PART II	Installation of snow skis		Not Complied					As Required
	*							
BT139-029 PART III	Installation of slump pads		Not Complied					As Required
	*							
BT139-029 PART IV	Installation of navigation light support		Not Complied					As Required
	*							
BT139-028	Installation of Kit EGPWS (Enhanced Ground Proximity Warning System) P/N 3G3440F00211		Complied	Complied with, T. Ross, AAC -- Era QC			Manually Updated	As Required
Rev B								--
10/30/2014								07/13/2011

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
STC SR01949LA Rev IR 01/03/2007	Installation of Apical Industries, Inc. Liferaft Kit Parent		Complied					
STC SR01949LA	Installation of Apical Industries, Inc. Liferaft Kit		Complied Complied with sheet metal portion of this STC. Installing R/H and L/H step beef ups and floor modifications all in accordance w/ SR01949LA Completed installation of Apical Industries,Inc Liferaft ki --			HWO-001424-2011 20.3 FH 09/22/2011	As Required	
STC SR01949LA (PARA 6.18-6.23)	Apical Life Raft Kit, External Handle		Complied Complied with the instructions for STC SR01949LA Para. 6.18-6.23. Installation of external life raft handles. See employees comments. --			HWO-004455-2014 2395.5 FH 12/15/2014	As Required	
BT139-006 Rev IR 01/25/2007	New pitch & roll trim actuator P/N 3G2220V00137, yaw trim actuator P/N 3G2220V00136 and collective trim actuator P/N 3G2220V00234, installation of.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-069 Rev B 01/25/2007	Tailpipe assy LH P/N 3G7800L00131 and tailpipe assy RH P/N 3G7800L00231 inspection		Complied - N/A N/A by P/N T. Ross, AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-073 Rev IR 02/08/2007	Install Rappelling Kit P/N 4G2590F00111		Not Complied				As Required	

*

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number					Date	Next Due
BT139-054	Part I: Flight data recorder power supply modification. Part II: DC battery and external power starter modification.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev A							--	
02/13/2007							07/01/2011	
BT139-074	AW139 HUMS upload of the new On Board System Configuration file V 5.1.0 on HUMS DAU and install the AW139 Configured HUMS Ground Station v3.6.0.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev C							--	
11/19/2008							07/13/2011	
BT139-078	Rear fuselage longerons retro modification.		Incorporated into aircraft build. JFONTENOT 08/16/2019 -- Era QC				Manually Updated	One-Time
Rev IR							--	
02/22/2007							07/13/2011	
BT139-015	Rear fuselage and tailboom retro-modifications.		Incorporated at aircraft build. JFONTENOT 08/16/2019 -- Era QC				Manually Updated	One-Time
Rev IR							--	
02/22/2007							07/13/2011	
BT139-076	Kit baggage compartment anchor system P/N 3G2550F00113.		Complied Complied with , T. Ross, AAC -- Era QC				Manually Updated	As Required
Rev IR							--	
03/16/2007							07/13/2011	
BT139-012	P/N 1-8486-3 Smart Linear Actuator (Lateral). P/N 2-8486-3 Smart Linear Actuator (Tail Rotor). P/N 8486-3 Smart Linear Actuator (Longitudinal).		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev IR							--	
04/13/2007							07/13/2011	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-071 Rev IR 04/23/2007	DC generator Max Loading Placard P/N 3G1130L00551, installation of.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-080 Rev A 04/23/2007	Part I: Replacement of transponder top antenna coaxial cables. Part II: Replacement of Transponder P/N 7517400-885 Pre-Mod Y.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-086 Rev IR 04/23/2007	Circuit breakers engine igniter 1&2 (CB107 and CB108).		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011		One-Time
BT139-075 Rev IR 05/09/2007	Kit ICS Passenger Cabin (12/16 Pax) P/N 4G2350F00411. *		Not Complied					As Required
BT139-087 Rev A 10/23/2007	Dimensional check of cockpit door and windows installation.Cockpit door windows seal replacement. (Superseded by BT139-129)		Complied - N/A Superseded by BT139-129. T. Ross, AAC -- Era QC			-- 07/13/2011		One-Time
BT139-085 Rev IR 05/18/2007	Fire Extinguisher Bottle Assy P/N 3G2620V00131.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
STCSR02108LA Rev IR 06/06/2007	Installation of Apical Nose Landing Gear Doors IAW STC SR02108LA.		Complied Verified AMT installed Apical Nose Landing Gear Doors IAW STCSR02108LA. Verified AMT installed Apical Nose Landing Gear Doors IAW STCSR02108LA. --			HWO-001424-2011 20.3 FH 09/22/2011	As Required	
BT139-084 Rev IR 07/12/2007	Power C/A (B1A18) P/N 3G9B11A01804.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
STCSR02624NY Rev IR 07/27/2007	Installation of the Goodrich Hoist Kit.		Not Complied				As Required	
BT139- 060 Rev IR 08/01/2007	Tail Rotor Drive Shaft Assy N.2 and N.3		Complied - N/A N/A by P/N, G Jeffers -- Era QC			06/03/2014	One-Time	
BT139- 060 Rev IR 08/01/2007	3T6510A00339	TCA9112				06/03/2014	One-Time	
BT139- 060 Rev IR 08/01/2007	Tail Rotor Drive Shaft Assy N.2 and N.3		Complied - N/A N/A by P/N, G Jeffers -- Era QC			06/03/2014	One-Time	
BT139-058 Rev A 08/09/2007	NI-900 Network Interface Module Assembly (NIM) P/N 7517964-912 MOD AH		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 01/01/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance						TT	
Eff Date	Part Number	Serial Number					Date	Next Due
BT139-019	Replacement of the Pilot and CoPilot ICS Panel P/N 7511900-982 or P/N 7511900-98201 with the new Pilot and CoPilot ICS Panel P/N 7511900-98202		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev IR							--	
08/21/2007							07/13/2011	
BT139-082	Elastomeric Bearings P/N 3G6220V00154.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev IR							--	
08/21/2007							07/13/2011	
BT139-046	Installation of 4 Axis Autopilot Kit P/N 3G2210F00211		Complied - N/A Not applicable by aircraft serial number, R. Cohn, AAC -- Era QC					
Rev IR								
08/30/2007							01/01/2011	
BT139-057	Introduction of variant P/N 3G0206P00311 on TCCA registered aircraft.		Complied - N/A N/A BY REGION, T. ROSS, AAC -- Era QC					One-Time
Rev B							--	
05/20/2010							07/13/2011	
BT139-081	Y9/Y10 bellcrank assy retro modification P/N 3G6706P00611.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC					One-Time
Rev IR							--	
09/20/2007							07/13/2011	
BT139-096	Flir (Seaflir II) Structural and Electrical Provisions Installation of.		Complied - N/A Not applicable by aircraft serial number. T. Ross AAC -- Era QC					
Rev IR								
10/31/2007							10/25/2013	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2007-25-14 Rev IR 12/26/2007	Inspection of tail pipe assemblies for cracks		Complied - N/A Not applicable by part number installed, R. Cohn AAC Philadelphia -- Era QC			07/13/2011		
BT139-094 Rev IR 01/08/2008	Pilot Door External Handle Retro Modification P/N 3G5206P05511.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-101 Rev IR 01/31/2008	Vip cabin interfaces wiring diagram modification.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-107 Rev B 07/15/2010	Installation of belly strobe kit		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	
BT139-093 Rev IR 02/11/2008	Chart holder PLT/CPLT kit, installation of.		Not Complied -- Era QC			Manually Updated	As Required	
BT139-099 Rev IR 02/11/2008	Kit central display P/N 4G4630F00111		Complied - N/A Not applicable by aircraft serial number. T. Ross AAC -- Era QC			01/01/2011		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-111 Rev A 02/25/2008	2nd GPS wiring diagram modification.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-097 Rev A 07/21/2008	Tail gearbox fitting inspection.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-090 Rev A 06/20/2008	Primus Epic Flight Software Release 4.8.0		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-109 PT1 Rev B 10/06/2010	*	Comply with Modification of Engine Exhaust Pipe Fairings IAW BT139-109 PT1	Not Complied					As Required
BT139-109 PT2 Rev B 10/06/2010		Comply with Modification of Engine Exhaust Pipe Fairings IAW BT139-109 PT1	Not Complied					As Required
BT139-129 Rev A 07/14/2008	Cockpit doors windows replacement (Superseded BT139-087 Rev A)		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date	
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025	
EO Number	Subject					Complied On		Interval	
Rev #	Method of Compliance					TT			
Eff Date	Part Number	Serial Number						Date	Next Due
BT139-115	✱	MAST VIBRATION ABSORBER KIT P/N 4G1860F00113, INSTALLATION OF	Not Complied						As Required
Rev D									
04/09/2010									
BT139-131		Pedal assy P/N 3E6721A00137 check replacement.	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC						One-Time
Rev IR								--	
06/13/2008								07/13/2011	
BT139-126		Wire strike protection systems (WSPS) top cable cutter assy P/N 423-83001-1 rework.	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC						One-Time
Rev IR								--	
06/20/2008								07/13/2011	
BT139-134		Tail assy inspection.	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC						One-Time
Rev IR								--	
08/08/2008								07/13/2011	
AD2008-14-02		Inspect Fuselage Station 5700 for Cracks	Complied - N/A Not applicable by serial number installed -- Era QC						
Rev 1									
01/16/2015								01/20/2015	
BT139-048		Comply with MLG upgrade P/N 3G3210V00133(LH)and P/N 3G3210V00233(RH), replacement with the superseding P/N 3G3210V00135(LH) and P/N 3G3210V00235(RH)	Complied - N/A Not applicable by part number installed, R. Cohn, AAC -- Era QC						
Rev IR									
09/09/2008								01/01/2011	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-138 Rev IR 09/16/2008	Installation of 27Ah Auxiliary Battery		Complied Verified completion of the following task, INSPECTED AC, FOUND 27 AMP HOUR AUX BATTERY INSTALLATION TO BE PREVIOUSLY COMPLIED WITH PER BT139-138 with no defects noted. --			HWO-001432-2011 20.3 FH 09/08/2011	As Required	
BT139-118 Rev B 12/13/2008	Inspection of Passenger Door Installation and Installation of Reinforcement Door Stops		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011	One-Time	
BT139-043 Rev A 07/28/2011	Heated windshields kit P/N 3G5610F00611 installation.		Complied Complied with, R. Cohn, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	
BT139-095 Rev A 10/28/2008	Replacement of PCM2 Pressure Switch Connections		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011	One-Time	
BT139-079 Rev IR 10/20/2008	Installation of Tail Posistion Light Adapter		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011	One-Time	
BT139-110 Rev IR 10/24/2008	MLG Sponson rear fairing step area extension. *		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-147 Rev IR 11/07/2008	Enhanced GPWS Kit Installation		Complied - N/A Not applicable per helicopter s/n. see birth records. JFONTENOT 02/05/2020 -- Era QC			-- 07/13/2011		
BT139-136 Rev IR 12/01/2008	Circuit breaker CB27 replacement.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-098 Rev IR 12/02/2008	Inspection of Float Switches P/N 3G9560V01151 and Implementation of Design Change		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011		One-Time
BT139-140 Rev C 11/26/2010	Increase of Aircraft Maximum Take-off Weight (MTOW) up to 6800 KG		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011		As Required
BT139-120 Rev IR 02/04/2009	Passenger fixed footstep protection kit P/N 3G5260A20611, installation of.		Not Complied					As Required
BT139-125 Rev IR 02/20/2009	Replacement of NIM P/N 7517964-912 with Improved Version P/N 7517964-914		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-133 Rev A 03/17/2009	Replacement of GCU P/N 1152550-3 with Improved Version P/N 1152550-5		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011	One-Time	
BT139-167 Rev IR 02/20/2009	Life-Rafts Inflation System Valve Inspection.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011	One-Time	
BT139-128 PTII Rev IR 03/16/2009	FLOOR PANEL RETRO MODIFICATION P/N 3P5306P03011 OR P/N *		Not Complied				As Required	
AD2009-06-07 Rev IR 03/31/2009	Replacement of Cockpit Door Windows		Complied IAW BT 139-129 Aircraft S/N 41269 is not affected, no work required. --			HWO-001424-2011 20.3 FH 08/25/2011	One-Time	
BT139-166 Rev IR 04/06/2009	Inspection of MAU Units for Corrosion and Improvement of Corrosion Prevention.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-172 Rev IR 04/23/2009	Installation Procedure and Adjustment Procedure for Rotor Brake Rudder Stop		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-157 PT I,II,III Rev C 11/23/2020	Installation of Primus Epic Flight Software Release 5.6.0. IAW AW139 BT139-157 PT I,II,III		Complied - N/A Not applicable, aircraft delivered new with upgrade. -- Era QC			-- 01/01/2011		
BT139-173 Rev C 03/14/2018	Kit 4 Axis enhanced (with sar modes) P/N 4G2210F00111. *		Not Complied				As Required	
BT139-159 Rev B 09/06/2010	Tail boom retro-modification procedure * 3G5350A00135 A7/0083		Not Complied				As Required	
STCSH3319NM Rev IR 07/10/2009	Installation of Precise Pulselite Control Unit		Complied Performed security attachment inspection. Confirmed the technician Installed the Precise Pulselite system with control unit P/N- 3060-S, S/N-LSS02237. Performed a satisfactory continuity check, and o --			HWO-002838-2013 1310.6 FH 07/18/2013	As Required	
BT139-124 Rev IR 08/04/2009	Battery Cable Assembly Installation retromodification. Parent		Complied - N/A -- Era QC					
BT139-124 PART 1	Battery Cable Assembly Installation retromodification.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-124 PART 2	Battery Cable Assembly Installation retromodification.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-142 Rev IR 08/04/2009	Replace Fire Detection/Extinguishing Control Panel P/N 3G2600V00252		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/01/2011		One-Time
BT139-035 Rev D 03/18/2022	Elt Deployable Kit P/N 3G2560F00311, Installation Of.		Complied Performed security an attachment inspection. Verified the ADELTA System Kit PN: 3G2560F00311 installed from OEM. No known defects noted. --			HWO-001421-2011 20.3 FH 09/21/2011		As Required
BT139-177 Rev IR 08/07/2009	Perform detailed inspection of Electrical Harness for Chaffing IAW BT139-177		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-103 Rev A 03/17/2010	Quick Access Recorder PN 4G3130F00311 Installation		Complied - N/A Not applicable by aircraft serial number. T. Ross AAC -- Era QC			01/01/2011		
BT139-161 Rev A 03/01/2012	Installation of HIGH INTENSITY LANDING LIGHT VARIANT P/N 3G3306P01411 AND		Complied - N/A Not applicable by Aircraft serial number, see birth records. JFONTENOT 02/05/2020 -- Era QC			-- 07/13/2011		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-193 Rev IR 09/03/2009	Perform detailed inspection of tailboom IAW BT139-193		Complied - N/A N/A, superceded by BT139-195. T. Ross, AAC -- Era QC			-- 07/13/2011		One-Time
BT139-194 Rev IR 09/03/2009	Perform detailed inspection of tailboom IAW BT139-194		Complied - N/A N/A, superceded by BT139-195. T. Ross, AAC -- Era QC			-- 07/13/2011		One-Time
AD2009-15-14 Rev IR 09/09/2009	Determine whether the Fire extinguishing bottle for engines 1&2 have the proper outlet end on the receptacle/Connector IAW BT139-085.		Complied Complied with AD2009-15-1 and agusta BT 139-085 inspection of fire extinguisher bottles on S/N's 65071B1 & 65072B1 found receptacles to be installed correctly. --			HWO-001424-2011 20.3 FH 08/23/2011		One-Time
BT139-191 Rev IR 10/05/2009	Installation of Search Light C/A Extension Retromod *		Not Complied					As Required
BT139-178 Rev IR 10/19/2009	Relocation of heels BT7 battery.		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011		As Required
BT139-113 Rev IR 10/26/2009	Full cabin extension P/N 4G5340F00111, installation of. *		Not Complied					As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Part Number	Subject Serial Number	Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-195 Rev B 02/02/2010	Tail Assembly Inspection Parent		Complied - N/A -- Era QC					
BT139-195 PART II	Comply with BT139-195 Part II on Inspection of Tail Assy.		Complied - N/A N/A by P/N, BT139-200 incorporated at factory. -- Era QC			20.3 FH		
	3G5350A00135	A7/0083				10/17/2011		
BT139-195 PART III	Comply with BT139-195 Part III on Inspection of Tail Assy.		Complied - N/A N/A by P/N, BT139-200 incorporated at factory. -- Era QC			20.3 FH		
	3G5350A00135	A7/0083				10/17/2011		
BT139-181 Rev IR 11/11/2009	Packing position of conduit/firing cable for the left life-rafts.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-162 Rev IR 11/12/2009	Installation of No 2 ICS additional headsets in AW139 passengers cabin with the application of the ICS EMS variant cable assy P/N 3G9B02B03001.		Complied - N/A Not applicable by aircraft serial number. T. Ross AAC -- Era QC			01/01/2011		
BT139-174 Rev IR 11/20/2009	Hinged windows in crew doors, installation of.		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011		As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-112 Rev A 02/02/2010	Electrical Modifications on long nose Helicopters.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-200 Rev IR 02/02/2010	Tailboom reinforcement structural retro-modification.		Complied with by upgrade kit installed at factory. -- Era QC			Manually Updated 20.3 FH 10/17/2011	As Required	
139-31-10-01 Rev 2 03/19/2012	Install Hobbs Hour meter IAW applicable N-number Era drawings.		Complied Hobbs meter installed per ERA drawing E-139-B-31-20-02. (no defects noted) --			HWO-002851-2013 1310.6 FH 07/23/2013	As Required	
ERA-25-08-00 Rev IR 02/16/2010	Upgrade ELT as required using applicable Era Drawing(s)		Not Complied				As Required	
BT139-198 Rev B 04/04/2019	Modification of secondary avionics bay.		Complied - N/A Not applicable by aircraft serial number, R. Cohn, AAC -- Era QC			-- 01/01/2011		
BT139-187 Rev B 03/11/2010	To verify the correct tightening torque of the main rotor damper eye end IAW BT139-187.		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH 11/06/2020	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-187 Rev B 03/11/2010	To verify the correct tightening torque of the main rotor damper eye end IAW BT139-187. 3G6220V01353MCR6442		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH 08/03/2020	One-Time	
BT139-187 Rev B 03/11/2010	To verify the correct tightening torque of the main rotor damper eye end IAW BT139-187. 3G6220V01353MCR5223		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH 06/17/2020	One-Time	
BT139-089 Rev IR 02/19/2010	Retromodification of Frame sta 3900 and frame sta 5700 structural repair.		Not applicable, T. Ross, AAC -- Era QC			Manually Updated -- 01/01/2011	As Required	
BT139-187 Rev B 03/11/2010	To verify the correct tightening torque of the main rotor damper eye end IAW BT139-187. 3G6220V01353MCR5574		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH 04/29/2020	One-Time	
BT139-187 Rev B 03/11/2010	To verify the correct tightening torque of the main rotor damper eye end IAW BT139-187. 3G6220V01353MCR5012		Complied - N/A NA by PN, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC			09/28/2017	One-Time	
BT139-206 Rev IR 03/18/2010	Upgrade of the Front Panel on the Landing Gear control Panel P/N 3G3230V00632.		Complied - N/A Not applicable by aircraft S/N. T. Ross AAC -- Era QC			01/01/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance				Complied On TT Date	Interval Next Due
BT139-210 Rev IR 03/30/2010	Cabin double layer windows.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
BT139-183 Rev IR 03/30/2010	Emergency Exit Decals		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
139-25-10-02 Rev 1 02/16/2011	Installation of Single Pilot VFR Chart Holder IAW with instruction listed on Era Minor 139-25-10-02		Complied INSPECTED AC, FOUND THAT NO AVIONICS INSTALLATIONS ARE REQUIRED FOR THIS CHART HOLDER. INSPECTED AC, FOUND THAT NO OPERATIONAL CHECKS ARE REQUIRED FOR THIS CHART HOLDER. --				HWO-001431-2011 20.3 FH 09/06/2011	As Required
BT139-203 Rev A 03/02/2012	BATTERY PANEL REINFORCEMENT RETROMOD P/N 3G5306P26511		Complied - N/A Not applicable by ACFT S/N. see birth records. JFONTENOT 02/05/2020 -- Era QC				-- 07/13/2011	
BT 139-175 Rev B 02/10/2011	Starter-generator grounding check. Parent		Complied - N/A -- Era QC					
BT139-175 PTII	Starter-generator improvement		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-175 PTI	Starter-generator grounding check.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			02/10/2011		One-Time
BT139-146 Rev IR 04/28/2010	ECS modification		Complied - N/A N/A by S/n. -- Era QC					One-Time
BT139-145 Rev IR 04/28/2010	Intermediate Gearbox (IGB) fitting assembly modification		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-149 Rev IR 04/30/2010	EGPWS (Enhanced Ground Proximity Wsrning System) Aural warning inhibit cable.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011		One-Time
BT139-189 Rev IR 05/19/2010	Increase of the T/R pitch angle		Complied Complied -- Era QC			Manually Updated -- 07/13/2011		As Required
BT139-176 Rev IR 06/04/2010	Installation of tail rotor drive MGB adapter variant P/N: 3G6306P01011. 3G6320A00134 AW1054		SB has been applied at MGB build due to DOM. JFONTENOT 02/17/2021 -- Era QC			Manually Updated 378.4 FH 02/17/2021		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
STCSR02104SE Rev IR 06/07/2010	Install ASU NVG kit. *		Not Complied				As Required	
139-30-10-00 Rev 1 10/25/2010	Relocation of RH/LH Heated Windshield Inverter (P/N 3G3040V00651) IAW Era Drawing 13930-1-272		Complied Performed security an attachment inspection. Verified the technician Relocated windsheild heat converters IAW BT 139-043 and Era Drawing No. 1390-1-272. Ops checked good IAW BT 139-043.. No defects --			HWO-001421-2011 20.3 FH 09/21/2011	As Required	
BT139-163 Rev A 12/06/2011	Tail Rotor Blade Lightning Strip Improvement		Complied Completed BT 139-163. Removed old lightning strips p/n 3G6410A03052 (4EA) and installed new lightning strips on T/R blade p/n 3G6410A00152 (4EA) IAW 39-A-64-11-01-00A-710A-B. Tail rotor blade continu --			HWO-002824-2013 1310.6 FH 07/29/2013	One-Time	
139-34-10-01 Rev IR 07/20/2010	Removal of Skyconnect dialer and installation of MMU II		Complied - N/A MMUII installed on 139-34-12-00. JFONTENOT 03/11/2020 -- Era QC			5330.3 FH 03/11/2020		
139-25-10-03 Rev IR 07/21/2010	Fabrication and installation of map case referencing latest revision of Era drawing 13925-1-250		Complied Complied with fabrication and installation of map case as per Era dwg 13925-1-250 (-001) Rev. B --			HWO-001423-2011 20.3 FH 09/21/2011	As Required	
139-25-10-04 Rev IR 07/21/2010	Fabrication and installation of access panels at Sta. 5700 referencing Era Drawing 13925-973..		Complied Fabricated and installed nutplate retainer and access cover panel onto L/H and R/H aft cabin interior panel I.A.W. era drawing 13925-973 --			HWO-001423-2011 20.3 FH 08/23/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance				Complied On TT Date	Interval Next Due
139-53-10-00 Rev IR 07/21/2010	Fabrication and installation of external ICS jack scuff guard		Not Complied					As Required
	*							
BT139-205 Rev A 03/29/2011	Inspection of engine fuel supply line.		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
BT139-213 Rev A 12/01/2010	General visual insp of NLG act fitting		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
BT139-208 Rev B 02/04/2011	Diode Support Improvement		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
STCSR02138SE PARA 3.10 Rev O 01/09/2018	OEM Maintenance-Step Cable Replacement Kit		Not Complied					As Required
	*							
139-28-10-00 Rev IR 09/20/2010	Fuel crossfeed drain.		Complied Composite portion of fuel drain mod was complied with IAW Era Minor 139-28-10-00. Installed fuel crossfreed drain in reference with ERA drawings NO. 13928-1-265 REV A. Complied with Delegated Inspec -- Mayer, Timothy R.				HWO-001424-2011 20.3 FH 10/21/2011	As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-10-06 Rev IR 09/25/2010	Equipment rail fabrication and installation.		Not Complied				As Required	
	*							
BT139-226 Rev IR 09/27/2010	New SBAS (WAAS) capable GPS		Not Complied				As Required	
	*							
BT139-211 Rev A 12/09/2010	MGB bearing replacement		SB has been applied at MGB build due to DOM. JFONTENOT 02/17/2021 -- Era QC			Manually Updated -- 06/08/2020	One-Time	
	3G6320A00134 AW1054							
BT139-171 Rev B 02/04/2011	Overhead Circuit Breaker Panel Variant		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
139-53-10-01 Rev IR 10/01/2010	Fabricate and install gusset and doubler support system for Apical Life Rafts installation.		Not Complied				As Required	
	*							
139-71-10-02 Rev IR 10/18/2010	Engine Intake Screen Upgrade		Complied Replaced O.E.M. screen with upgraded screen I.A.W. era Dwg. No. 13971-1-164 --			HWO-001423-2011 20.3 FH 09/13/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-148 Rev A 05/11/2020	*	Install complete provisions for EMS (MEDEVAC) configuration.	Not Complied				As Required	
BT139-230 Rev IR 10/22/2010		Diode support retromodification	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-100 Rev IR 10/22/2010		Main rotor FIPS installation, replacement of the slip ring assy bolts	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
139-25-10-01 Rev 5 11/29/2012		Install Cargo net P/N CS-AW139-2	Complied Installed Cargo net P/N CS-AW139-2 to baggage compartment floor. -- Era QC			Manually Updated 20.3 FH 10/12/2011	As Required	
139-53-10-02 Rev IR 10/28/2010		Fuel filler scuff guard	Complied Complied with Sheetmetal portion of this E.O.Fuel filler scuff guard fabrication. Fuel filler scuff guard was installed IAW Era Minor 139-53-10-02. --			HWO-001422-2011 20.3 FH 09/07/2011	As Required	
BT139-232 Rev IR 10/29/2010		Re-marking of Pall Aerospace P/N on the engine air particle seperator.	Complied - N/A N/A by P/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-53-10-03 Rev IR 11/04/2010	Fabrication and installation of stringer doublers.		Complied installed fabricated doubler as per ERA dwg. no. 13953-1-304. all parts treated primed, and painted prior to installation. --			HWO-001423-2011 20.3 FH 08/23/2011	As Required	
139-53-10-04 Rev IR 11/12/2010	Doublers STA 5795, WL 2470		Complied Complied with sheetmetal portion of this E.O. Fabricating and installation of doublers at STA. 5795, WL 2470.REF. ERA DWG. # S-139-G-53-11-00. --			HWO-001423-2011 20.3 FH 08/29/2011	As Required	
139-53-10-07 Rev IR 11/15/2010	Sliding cowl scuff guards		Complied Complied with sheetmetal portion of this E.O. Fabrication and installation of sliding cowl rail scuff guard. REF. ERA DWG# 13925-1-161. --			HWO-001422-2011 20.3 FH 09/01/2011	As Required	
139-53-10-05 Rev IR 11/15/2010	Baggage comprtmnt scuff guards		Complied Verified fabrication and installation of baggage compartment scuff guards as per ERA dwg no. 13925-1-154. No defects noted. Verified fabrication and installation of baggage compartment scuff guards --			HWO-001423-2011 20.3 FH 08/30/2011	As Required	
139-53-10-09 Rev IR 11/15/2010	Engine door latch mod.		Complied Complied with Sheetmetal portion of this Engineering Order, engine latch mod. AB/AW139 as per. ERA DWG. #13953-1-159. --			HWO-001423-2011 20.3 FH 08/21/2011	As Required	
139-53-10-06 Rev IR 11/15/2010	Modification of overhead panel		Complied Verified modification of overhead ceiling panel I.A.W. Era Dwg. No. 13925-1-266. No defects noted. Verified modification of overhead ceiling panel I.A.W. Era Dwg. No. 13925-1-266. No defects note --			HWO-001423-2011 20.3 FH 09/22/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-10-08 Rev IR 11/15/2010	Headset brackets		Complied Complied with Sheetmetal portion of this E.O. Fabrication and installation of pilot and copilot headset brackets.REF ERA DWG#13925-1-256. --			HWO-001423-2011 20.3 FH 09/01/2011	As Required	
139-71-10-01 Rev IR 11/15/2010	Strengthen uppr eng cowl intakes		Complied Fabricated doublers and installed I.A.W. Era Dwg. No. 139-1-172 --			HWO-001423-2011 20.3 FH 09/13/2011	As Required	
139-53-10-08 Rev IR 11/15/2010	Baggage floor protective panels		Complied Complied with Sheetmetal portion of this Engineering Order. Installation of baggage compartment protection panels. Ref.D139-799-017 Floor Protector Kit. --			HWO-001423-2011 20.3 FH 09/16/2011	As Required	
139-25-10-09 Rev IR 11/17/2010	Installation of A/F mounted DK140		Complied Installed Under Water Acoustic Beacon PN: DK140 SN:ST425621. Tested beacon for functionality and correct operating voltage test's were within limits. All work was performed IAW ERA DWG NO. 1393 --			HWO-001423-2011 20.3 FH 08/29/2011	As Required	
BT139-231 Rev IR 11/18/2010	Spectrolab Nightsun gimbal nut		Complied - N/A N/A by P/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-236 Rev IR 11/24/2010	Upgrade of Main Rotor Pitch Link Assy P/N 3G6230A01032. 3G6230A01033 MCR1113		Complied - N/A N/A by P/N -- Era QC			06/12/2013		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number				Date		Next Due
BT139-212	*	REPLACEMENT OF HOIST PENDANT SUPPORT ASSY P/N 3G2591A05431		Not Complied				As Required
Rev IR								
11/24/2010								
BT139-236		Upgrade of Main Rotor Pitch Link Assy P/N 3G6230A01032.		Complied - N/A N/A by P/N -- Era QC				
Rev IR								
11/24/2010	3G6230A01033	MCR1131				06/12/2013		
BT139-236		Upgrade of Main Rotor Pitch Link Assy P/N 3G6230A01032.		Complied - N/A N/A by P/N -- Era QC				
Rev IR								
11/24/2010	3G6230A01033	MCR1130				06/12/2013		
BT139-236		Upgrade of Main Rotor Pitch Link Assy P/N 3G6230A01032.		Complied - N/A N/A by P/N -- Era QC				
Rev IR								
11/24/2010	3G6230A01033	MCR1117				06/12/2013		
BT139-236		Upgrade of Main Rotor Pitch Link Assy P/N 3G6230A01032.		Complied - N/A N/A by P/N -- Era QC				
Rev IR								
11/24/2010	3G6230A01033	MCR1122				06/12/2013		
139-25-11-00	*	SAR/EMS Interior Panel/Lighting Package		Not Complied				As Required
Rev 2								
02/27/2012								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-11-01 Rev 1 03/10/2011	SAR/EMS Avionics Rack Install		Not Complied				As Required	
	*							
139-23-11-00 Rev 1 03/10/2011	Relocation of L/H Cabin Audio Panel		Not Complied				As Required	
	*							
139-25-11-02 Rev 1 03/10/2011	Fischer Cabin Seat Install		Not Complied				As Required	
	*							
BT139-229 Rev IR 01/21/2011	Integrated Secondary Flight Display Software		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC			-- 07/13/2011	One-Time	
139-71-11-00 Rev IR 01/28/2011	Installation Engine Wash Kit		Not Complied				As Required	
	*							
139-71-10-00 Rev IR 01/28/2011	Upper eng cntr cowl improvement		Complied Fabricated and installed doublers I.A.W. Era Dwg. No. 13971-1-163 --			HWO-001423-2011 20.3 FH 09/13/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT 139-034 Rev D 02/08/2023	HF System Kit P/N 3G2310F00211 Parent		Not Complied					
BT139-034 PT I *	HF System Kit P/N 3G2310F00211		Not Complied				As Required	
BT139-034 PT II *	HF System Kit P/N 3G2310F00211		Not Complied				As Required	
BT139-034 PT III *	HF System Kit P/N 3G2310F00211		Not Complied				As Required	
BT139-234 Rev A 08/31/2022	DF935-11 Direction Finding System Kit P/N 4G3450F00711, Installation of		Not Complied				As Required	
139-53-11-00 Rev IR 02/11/2011	Baggage door hinges		Not Complied				One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-214 Rev A 11/26/2012	Replacement of Pre Mod ADI		Complied - N/A N/A by component S/N. T. Ross, AAC -- Era QC			-- 07/13/2011	One-Time	
BT139-247 Rev IR 03/01/2011	Conversion of battery to 20 cell.		Complied Complied with BT 139-247 Verified AMT Complied with BT 139-247. No defects noted. Contacted Delegated Inspector on type for completion of M-019, W&B, Flight Manual Supplement, and/or 337 complet --			CWO-007403-2011 1 FH 05/11/2011	As Required	
BT139-216 Rev IR 03/02/2011	Search and Rescue Weather Radar Primus 701		Not Complied				As Required	
BT 139-105 Rev A 12/07/2012	Improvement of aircraft waterproofing		Partially Complied					
BT139-105	Improvement of aircraft waterproofing		Not Complied				As Required	
BT139-105 PART I	Improved waterproofing		Complied - N/A -- Era QC					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Part Number	Subject Serial Number	Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-105 PART II	Improved waterproofing		Complied Applied two layers of 7781 hexcel fiberglass and 9309.3 resin allowing to cure overnight and sanding smooth so paint shop can return to original paint scheme IAW B.T. 139-105 REV. A --			HWO-011534-2020 5437 FH 07/09/2020	As Required	
BT139-105 PART III	Improved waterproofing		Complied c/w part 3 --			TL-092902-2014 2210.5 FH 07/20/2014	As Required	
BT139-105 PART IV	Improved waterproofing		Complied - N/A -- Era QC					
BT139-105 PART IX	Improved waterproofing		Complied - N/A -- Era QC					
BT139-105 PART V	Improved waterproofing		Complied - N/A -- Era QC					
BT139-105 PART VI	Improved waterproofing		Complied - N/A -- Era QC					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject	Method of Compliance					Complied On	Interval
Rev #							TT	
Eff Date	Part Number	Serial Number					Date	Next Due
BT139-105 PART VII	Improved waterproofing				Complied - N/A -- Era QC			
BT139-105 PART VIII	Improved waterproofing				Complied - N/A -- Era QC			
BT139-105 PART X	Improved waterproofing				Complied - N/A -- Era QC			
BT139-105 PART XI	Improved waterproofing				Complied - N/A -- Era QC			
BT139-105 PART XII	Improved waterproofing				Complied - N/A -- Era QC			
BT139-105 PART XIII	Improved waterproofing				Complied - N/A -- Era QC			

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance				Complied On TT Date	Interval Next Due
BT139-105 PART XIV *	Improved waterproofing (Tail attachment fitting seal improvement)		Not Complied					As Required
BT139-062 Rev IR 03/03/2011	Installation of a Rotor brake cable assembly variant		Not Complied					As Required
139-25-11-03 Rev IR 03/11/2011	Seat cushion support bracket improvement		Complied Complied with Sheetmetal portion of this E.O.Fabricating and installing seat cushion support brackets. REF.ERA DWG# 13925-1-256. Contacted Delegated Inspector on type for completion of M-019, W& --				HWO-001423-2011 20.3 FH 09/01/2011	As Required
139-67-11-00 Rev IR 03/18/2011	Servo fault indicator		Not Complied					As Required
BT139-209 PT II Rev IR 03/29/2011	Tail cable assy inst imprvmnt		Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC				-- 07/13/2011	One-Time
BT139-209 PT I Rev IR 03/29/2011	Tail cable assy inst imprvmnt		Complied na by sn --				TL-039869-2011 42 FH 11/03/2011	One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-151 Rev IR 03/31/2011	HUMS software update		Complied - N/A N/A by MGB P/N -- Era QC			11/22/2011	One-Time	
BT139-243 Rev IR 04/05/2011	MODIFICATION OF TAIL UNIT ASSEMBLY. *		Not Complied				As Required	
BT139-139 Rev IR 06/08/2011	PCM pressure indicator switches		Complied - N/A N/ A BY PCM S/N AT AGUSTA R.ENDERS -- Era QC			10/22/2013	One-Time	
BT139-139 Rev IR 06/08/2011	PCM pressure indicator switches		Complied - N/A N/A by S/N, T. Ross, AAC -- Era QC			-- 07/13/2011	One-Time	
139-34-11-00 Rev 1 11/21/2011	EGPWS Remote data port		Complied Relocation of the EGPWS data port not required. Ref. ERA DWG. # 139-34-13-00 EGPWS relocation on long nose AW139. No defaults noted. Fabricated EGPWS data port bracket. I.A.W. Era Dwg. No. 139-34-1 --			HWO-002817-2013 1310.6 FH 07/16/2013	As Required	
BT139-239 Rev IR 06/20/2011	Heating/forced ventilation jet pump		Complied Complied with, T. Ross, AAC -- Era QC			Manually Updated -- 07/13/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-152 Rev IR 06/23/2011	Verify end cone are structure. 3G5350A00135 A7/0083		Complied - N/A N/A by PN -- Era QC			20.3 FH 10/18/2011	One-Time	
SB139-240 Rev D 03/31/2021	Installation of Pilot/Copilot collective grip *		Not Complied				As Required	
139-71-11-01 Rev IR 07/09/2011	Engine cowlng improvement		Complied Angle and access panels previously complied with by Agusta. No paint required for EO 139-71-11-01. No other defects noted. Contacted Delegated Inspector for completion of EO 139-71-11-01. Engine cow --			HWO-001423-2011 20.3 FH 10/21/2011	As Required	
139-25-11-05 Rev IR 07/09/2011	Registration & AWC Card Holder		Complied Fabricated and installed certification card holder Aw139 as pre ERA DWG. No. 13925-1-305 Contacted Delegated Inspector on type for completion of M-019, W&B, Flight Manual Supplement, and/or 337 c --			HWO-001423-2011 20.3 FH 09/01/2011	As Required	
139-53-11-02 Rev IR 07/09/2011	Nose cowlng pin doublers *		Not Complied				As Required	
139-24-11-01 Rev IR 07/09/2011	Weight on wheels terminal strip.		Complied INSTALLED WEIGHT ON WHEELS TERMINAL STRIP AND PERFORMED SATISFACTORY OPERATIONAL CHECK REF ERA DWG E-139-B-32-60-00. Contacted Delegated Inspector on type for completion of M-019, W&B, Flight Man --			HWO-001421-2011 20.3 FH 09/21/2011	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
139-53-11-03 Rev 1 07/22/2011	Transponder coax clamp.	Complied Complied with sheetmetal portion of this E.O. installing clamp for transponder antenna coax. REF.ERA DWG# 13971-1-170 Option 2 Complied with this E.O. by installing clamp for transponder antenna coax --	HWO-001421-2011 20.3 FH 09/13/2011	As Required				
139-11-11-00 Rev IR 07/11/2011	Standard Placards	Complied Applied Decals IAW AW139 Paint Scheme Drawing 13900-1-257 and AW139 ICN-39-A-112100-G-00001-00166-A-02-1. Installed required Placards IAW Era Drawing S-139-G-11-00-01 Rev 4 --	HWO-002838-2013 1310.6 FH 08/01/2013	As Required				
139-53-11-01 Rev IR 07/11/2011	Cabin overhead modification.	Complied Fabricated parts and modified Cabin Overhead Panels IAW ERA DWG NO. S-139-A-33-20-01. Job complete. Contacted Delegated Inspector for completion of task for modification of overhead interior panel. --	HWO-001423-2011 20.3 FH 10/21/2011	As Required				
BT139-249 Rev IR 07/13/2011	Solder splices inspection	Complied - N/A N/A by aircraft S/N. T. Ross AAC -- Era QC	-- 07/13/2011	One-Time				
STCSR02138SE PARA 3.7 Rev IR 07/18/2011	D139-799-023 Anti-rotation Blocks	Complied Conformed aircraft to STCSR02138SE PARA 3.7. --	TL-047466-2012 375.7 FH 04/19/2012	As Required				
139-53-11-06 Rev IR 07/20/2011	Relocation of TCAS Antenna	Not Complied		One-Time				

*

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-23-11-01 Rev 1 09/09/2011	Install Cabin Briefing System		Complied Duplicate entry refer to HWO 1427 task # 139 DMP-100 INST AVI for system installation and operational check. Sheetmetal portion not required on this installation. contacted delegated inspector --			HWO-001421-2011 20.3 FH 09/21/2011	As Required	
139-67-11-01 Rev IR 09/13/2011	139 Collective hardware		Complied Performed RII Inspection, Verified AMT EO perviously Complied With. Correct HDWR already installed. No defects noted. Performed RII Inspection, Verified AMT EO perviously Complied With. Correct HDWR --			HWO-002824-2013 1310.6 FH 06/20/2013	As Required	
139-31-11-00 Rev IR 09/13/2011	Install QAR		Complied Complied with on HWO-001428-2011. JFONTENOT 03/04/2020 -- Era QC			Manually Updated 20.3 FH 09/09/2011	As Required	
BT139-233 Rev A 10/11/2011	Hydraulic system hose inspection and replacement in the upper deck area. Parent		Complied					
BT139-233(PTI)	Hydraulic system hose inspection and replacement in the upper deck area.		Complied complied with B.T. 139-233. contacted delegated inspector. --			HWO-001632-2011 20.3 FH 10/25/2011	One-Time	
BT139-233(PTII)	Hydraulic system hose inspection and replacement in the upper deck area.		Complied D/N/A BY S/N D/N/A BY S/N --			TL-044639-2012 302.3 FH 02/20/2012	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-235(PTII) Rev A 01/10/2012	Re-work IGB fitting. 3G5350A00135A7/0083		Complied B.T. 139-235 has previously been complied with. --			HWO-002854-2013 1310.6 FH 06/17/2013	One-Time	
BT139-269 Rev IR 09/30/2011	Operational check of NR.1 and NR.2 hydraulics systems.		Complied c/w all --			TL-040254-2011 59.8 FH 11/11/2011	One-Time	
139-24-11-00 Rev 2 03/16/2012	Installation of Shore Power		Complied INSTALLED SHORE POWER AND PERFORMED SATISFACTORY OPERATIONAL CHECK REF ERA DWG E-139-B-24-40-00. installed sheetmetal portion of shore power connector as per ERA dwg no. S-139-G-24-40-00 Contacted --			HWO-001421-2011 20.3 FH 09/21/2011	As Required	
STCSR02138SE PARA 3.8 Rev IR 10/05/2011	D139-799-025 Cargo Compartment Raingutter Kit		Complied Installed raingutter kit on L/H and R/H side Ref STC SR02138SE PARA 3.8 --			HWO-002817-2013 1310.6 FH 06/06/2013	As Required	
STCSR02138SE PARA 3.4 Rev IR 10/05/2011	D139-799-017 Cargo Floor Protector Kit		Complied Contacted Delegated Inspector on type for completion of M-019, W&B, Flight Manual Supplement, and/or 337 completion. Installed D139-799-017 Floor Protector Kit IAW STC SR2138SE --			HWO-001424-2011 20.3 FH 10/12/2011	One-Time	
STCSR02138SE PARA 3.2 Rev IR 10/05/2011	D139-799-013 Cargo Door FWD Opening Kit		Complied PERFORMED AVIONICS PORTION OF CARGO DOOR FWD OPENING KIT BY MODIFYING DOOR SWITCHES AND PERFORMING SATISFACTORY OPERATIONAL CHECK REF ERA DWG E-139-B-33-30-00 Complied with Sheetmetal portion of FWD --			HWO-001424-2011 20.3 FH 10/26/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
STCSR02138SE PARA 3.1 Rev IR 10/05/2011	D139-799-011/-012 Maintenance Step Kit		Complied Sheetmetal portion previously C/W. Sheetmetal portion previously C/W. Sheetmetal portion previously C/W. Sheetmetal portion previously C/W. --			TL-054933-2012 602.8 FH 08/29/2012	One-Time	
STCSR02138SE PARA 3.6 Rev IR 10/05/2011	D139-799-021 Trim Protector Kit		Not Complied				As Required	
STCSR02138SE PARA 3.3 Rev IR 10/05/2011	D139-799-015 Engine Wash Kit		Complied Located and installed sheet metal portion of Engine Wash Kit using Dart Installations Instruuctions IID-139-799 Section D139-799-015 Composite portion of STCSR02138SE was complied with IAW STCSR0213 --			HWO-001424-2011 20.3 FH 10/21/2011	One-Time	
139-33-11-00 Rev IR 10/12/2011	Install Whelen LED Paramethus lights		Complied Complied with instructions for installation of supplemental landing lights. Ref. Era Minor 139-33-11-00, and Era Dwg. # 139-33-11-00. No defaults noted. --			HWO-002838-2013 1310.6 FH 07/16/2013	As Required	
STC SR02614NY-D Rev IR 10/28/2011	Life Port Dual Litter Installation		Not Complied				As Required	
BT139-244 Rev IR 11/02/2011	MGB Rod Backup Structure Cruciform Fitting Retromodification P/N 3G5306P36711, Installation of.		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
139-33-11-02 Rev 1 02/14/2012	*	Steerable landing lights white/IR switch and NVG light control panel install	Not Complied				As Required	
AD2011-20-06 Rev IR 11/14/2011		Tailboom Panels-Inspection of damage to prevent failure of a Tailboom, IAW AD2011-20-06.	Complied	N/A by installation of Retro-modification P/N 3g5309p01812 --		TL-039777-2011 34.9 FH 11/01/2011	One-Time	
		3G5350A00135	A7/0083					
139-53-11-07 Rev IR 11/17/2011	*	Installation of aft winch man safety harness provisions.	Not Complied				As Required	
139-33-11-01 Rev IR 11/17/2011		Install lower anti-collision light	Not Complied				As Required	
AD2011-20-08 Rev IR 11/21/2011		Inspect the PS, SCIO, CIO, and MAU cabinet and all related connectors for corrosion. Modify #2 MAU I/A/W Technical Bulletin No. 139-166.	Complied	Not applicable by serial number --		TL-040308-2011 62.2 FH 11/13/2011	One-Time	
BT139-275 Rev IR 12/01/2011		Collective control inspection.	Complied	n/a by s/n --		TL-041053-2011 114.5 FH 12/01/2011	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-276 Rev IR 12/02/2011	Cyclic control system inspection		Complied N/A BY S/N --			TL-042238-2011 188.4 FH 12/28/2011	One-Time	
139-23-11-02 Rev IR 12/02/2011	Aft cabin ICS system		Not Complied				As Required	
139-25-11-06 Rev IR 12/02/2011	Install Medical Equipment Mount		Not Complied				As Required	
BT139-225 Rev A 01/17/2012	INSTALLATION OF MISSION BUS (NON ESS 2) VARIANT P/N 3G2406P02511		Not Complied				As Required	
BT139-278 Rev IR 12/14/2011	Simco SRM9000 Mobile Radios		Complied n/a by s/n --			TL-050299-2012 478.5 FH 06/11/2012	One-Time	
139-25-11-07 Rev IR 12/14/2011	Improve Med Bed Stops		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
BT139-227 Rev IR 12/20/2011	#2 AC generator duct	Complied N/A BY AIRCRAFT S/N --	TL-044278-2012 287.8 FH 02/12/2012	One-Time				
139-71-11-02 Rev IR 01/09/2012	Engine exhaust duct drain removal	Complied Manual Compliance	139-71-11-02 211.9 FH 01/09/2012	As Required				
BT139-273 Rev IR 01/09/2012	Update HUMS software.	Complied c/w software update --	TL-046310-2012 338.8 FH 03/27/2012	One-Time				
BT139-121 Rev IR 01/13/2012	Static inverter P/N: 1152572-1	Complied N/A BY P/N KIT. --	TL-047046-2012 355.2 FH 04/10/2012	One-Time				
BT139-257 Rev IR 01/20/2012	Breeze-Eastern Hoist bumper	Complied - N/A N/A, Breeze-Eastern hoist not installed. -- Era QC		One-Time				
BT139-263 Rev IR 01/20/2012	FIPS T/R slip ring.	Complied - N/A N/A, FIPS not installed -- Era QC		One-Time				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-254 Rev A 02/07/2012	Starter generator clamp insp.		Complied n/a by a/c s/n --			TL-043757-2012 272.4 FH 02/01/2012		One-Time
139-34-12-00 Rev IR 01/23/2012	Installation of Skyconnect.		Complied Previously complied with per Era Dwg: 139-34-12-00. --			HWO-002838-2013 1310.6 FH 07/03/2013		As Required
139-25-12-00 Rev IR 02/06/2012	Cargo net brackets		Complied INSTALLED RETAINERS --			TL-044775-2012 302.3 FH 02/23/2012		One-Time
BT139-248 Rev IR 02/10/2012	SUPERSEDED- Tail rotor bearing support inspection Parent		Complied					
BT139-248(PTI)	SUPERSEDED-Tail rotor bearing support inspection		Complied C/W ALL --			TL-064088-2013 1043.9 FH 02/25/2013		
BT139-248(PTII)	SUPERSEDED-Tail rotor bearing support inspection		Complied C/W BT139-248 part II. --			TL-052712-2012 568.8 FH 07/22/2012		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number				Date		Next Due
139-25-12-05	*	Install ORCA interconnecting straps IAW latest ERA drawing		Not Complied				As Required
Rev IR								
02/15/2012								
BT139-104	*	Installation of Integrated ECS Maintenance and service panel		Not Complied				As Required
Rev IR								
02/17/2012								
139-25-12-03	*	Install upgraded manual hoist cable cutter mounting bracket IAW latest ERA Drawing.		Not Complied				As Required
Rev IR								
02/20/2012								
139-25-12-01	*	Install Rescue basket housing		Not Complied				As Required
Rev IR								
02/20/2012								
139-23-12-00	*	Installation of SAR Sky Connect		Not Complied				As Required
Rev IR								
02/27/2012								
139-25-12-04	*	Install EMS pouches IAW latest ERA drawing.		Not Complied				As Required
Rev IR								
02/29/2012								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
139-23-13-01 Rev IR 07/01/2013	Install TFM-550 FM Radio IAW Installation and Operating Instructions and Era Drawing 139-23-13-01 in their latest revisions.		Complied	Conformed a/c to Era Minor 139-23-13-01, GJ -- Era QC			Manually Updated 2177.7 FH 06/18/2014	As Required
139-23-12-01 Rev IR 03/13/2012	Enable EMT audio panel to allow for xmit on Comm1 & Comm 2.		Not Complied					As Required
139-31-12-00 Rev IR 03/13/2012	Install Beacon Decoder		Not Complied					As Required
STC SA02212AK Rev IR 03/13/2012	Install Whelen Parametheus Lights		Not Complied					As Required
BT139-238 Rev A 04/06/2012	Control Rod Inspection.		Complied	C/W BT 139-238 steps 5,6 --			TL-061757-2013 922.8 FH 01/10/2013	One-Time
BT139-256 PART II Rev A 09/05/2012	Number 4 pump line installation.		Complied	C/W instructions contained in BT139-256 Part II. --			TL-061443-2013 911 FH 01/04/2013	One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-256 PART I Rev A 09/05/2012	Number 4 pump line installation.		Complied c/w part 1 --			TL-056339-2012 660.4 FH 09/25/2012	One-Time	
BT139-284 Rev F 11/23/2020	FDR and RIPS variants		Verified installation of components for BT139-284, 10/4/2013, G. Jeffers -- Era QC			Manually Updated 1535.4 FH 10/04/2013	As Required	
BT139-064 Rev A 07/20/2012	Cockpit HEELS		Complied c/w all --			TL-057539-2012 730.4 FH 10/17/2012	One-Time	
139-25-12-02 Rev IR 04/11/2012	Relocate lower hoist pendant IAW latest revision of ERA Drawing.		Not Complied				As Required	
139-31-12-01 Rev IR 04/12/2012	Install AVR8345 Digital Video Recorder		Not Complied				As Required	
BT139-267 Rev IR 04/18/2012	Instrument panel improved fixing supports, Installation of.		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-23-12-02 Rev IR 05/14/2012	Install Becker AR 3209 VHF Radio		Not Complied				As Required	
	*							
139-25-12-06 Rev IR 05/14/2012	Install hoist cable guard I/A/W latest revision of applicable Era drawing.		Not Complied				As Required	
	*							
BT139-207 Rev B 03/22/2013	Rear avionics cooling fans		Complied - N/A N/A by Aircraft S/N. -- Era QC			1171.9 FH 04/05/2013	One-Time	
139-21-12-00 Rev 1 08/22/2012	Modification of Cabin Air Conditioner/Overhead Panels and Lighting.		Not Complied				As Required	
	*							
139-52-12-00 Rev IR 06/14/2012	Replace Maintenance step cables with chain IAW with latest applicable Era drawing and EO.		Complied EO / ERA DWG No. 139-52-12-00 has been previously complied with. --			HWO-002824-2013 1310.6 FH 06/10/2013	As Required	
139-34-12-01 Rev IR 06/19/2012	AHRU Cooling Fan		Not Complied				As Required	
	*							

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-34-12-02 Rev IR 06/19/2012	Install 2nd GPS IAW Manufacture Installation and latest revision of applicable ERA Drawing. *		Not Complied				As Required	
AD2012-11-12 Rev IR 07/03/2012	Collective Control Tube Installation		Complied AD2012-11-12 IS Not applicable by aircraft serial number. --			TL-050746-2012 492.1 FH 06/19/2012	One-Time	
AD2012-12-10 Rev IR 07/30/2012	Replace GCU P/N 1152550-3 using either GCU P/N 1152550-4 or GCU P/N 1152550-5 and modify electrical connectors per Agusta Bulletin 139-133.		Complied Not applicable by part number installed --			TL-062839-2013 980.5 FH 01/31/2013	One-Time	
BT139-288 Rev IR 08/03/2012	Inspection of tail rotor duplex bearing. Parent		Complied - N/A -- Era QC					
BT139-288 PT I	Inspection of tail rotor duplex bearing.		Complied - N/A Due to termination by discard time of 3000 hrs -- Era QC			02/06/2015		
BT139-288 PT II	Replace tail rotor duplex bearing		Complied - N/A Due to termination by discard time of 3000 hrs -- Era QC			02/06/2015	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-288 PT III	TR Duplex Bearing Shelf Life		Installed on aircraft 08/13/22. DOM 04/2021 -- Era QC			Manually Updated	One-Time	
	3G6430V00153 21231					-- 08/13/2022		
BT139-261	T/R FIPS Installation Imprvmnt		Not Complied				As Required	
Rev IR	*							
08/28/2012								
BT139-170	Double Hoist Electrical Provisions		Complied N/A by SN --			TL-057647-2012	One-Time	
Rev IR						730.4 FH		
10/08/2012						10/19/2012		
STCSR09628RC	Installation of Sky Connect		Complied Skyconnect system installed per installation instructions in STC SR09628RC. --			HWO-002935-2013	As Required	
Rev IR						1310.6 FH		
01/16/2013						07/30/2013		
BT139-308	Visual Inspection of Control Sticks		Complied Visually inspected the collective and cyclic sticks installations I/A/W BT139-308 --			TL-057474-2012	One-Time	
Rev IR						730.4 FH		
10/16/2012						10/16/2012		
BT139-179	Single Hoist Electrical Provision Modification		Complied n/a by a/c s/n. 2/23/2013. -- Landry, Michelle R.			TL-064000-2013	One-Time	
Rev IR						1041.8 FH		
10/24/2012						02/23/2013		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-55-12-00 Rev IR 10/30/2012	Winglet attachment locations, repair and reinforcement of existing fastener locations to repair or prevent elongation. (RH and LH sides)		Complied --			HWO-005780-2016 3188.5 FH 02/11/2016	As Required	
STC SR03251NY Rev IR 06/06/2013	Replace the OEM ceiling with D139-816-011 Interior Ceiling Panel Kit		Complied Verified replacement of OEM ceiling with D139-816-011 Interior Ceiling Panel Kit, DART STC SR03251NY IAW installation manual IIN-D139-816 Rev C. No defects noted. Verified replacement of OEM ceilin --			HWO-003462-2014 1803.6 FH 01/08/2014	As Required	
BT139-292 Rev IR 11/09/2012	Modify the number 2 drain line installation following modification of BT139-256.		Complied c/w previously. 2/23/2013. -- Landry, Michelle R.			TL-064000-2013 1041.8 FH 02/23/2013	One-Time	
BT139-304 Rev IR 11/15/2012	Additional 2nd landing light kit Installation.		Not Complied				As Required	
BT139-114 Rev IR 12/07/2012	Accessibilty Improvement Parent		Partially Complied					
BT139-114 PART I 	Accessibility Improvement (Cabin overhead 3 piece modification for access to PDP area)		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-114 PART II *	Accessibility Improvement (Landing Gear Control Valve access)		Not Complied				As Required	
BT139-114 PART III *	Accessibility Improvement (Replacement of the titanium engine mounts with more heat resistant mounts)		Not Complied				As Required	
BT139-114 PART IV *	Accessibility Improvement (installation of access panels near STA 5700 for external inspection)		Not Complied				As Required	
BT139-114 PART IX *	Accessibility Improvement(Rework of ceiling panels to ease access to the PDP area without removal of cotrol rod covers)		Not Complied				As Required	
BT139-114 PART V	Accessibilty Improvement (Fuel Manifold Acces Panel installation)		Complied Complied with BT139-114 PART V Accessibility improvement fuel manifold. --			HWO-011409-2020 5437 FH 08/18/2020	As Required	
BT139-114 PART VI *	Accessibility Improvement (STA7200 and STA8150 Acces Panel installation)		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-114 PART VII *	Accessiblity Improvement (Access Panel installation to ease in Anti-collision light removal)		Not Complied				As Required	
BT139-114 PART VIII *	Accessibility Improvement (Provides a provision to unlock the cabin door from inside the cabin during flight)		Not Complied				As Required	
BT139-114 PART X *	Accessibility Improvement (Installation of LH and RH belly access panels for trim actuator maintenance practices)		Not Complied				As Required	
BT139-114 PART XI *	Accessibility Improvement (Rework of Collective fairing allowing easier access to NLG inspection panel)		Not Complied				As Required	
BT139-114 PART XII *	Accessibility Improvement (Installation of Retro Mod to allow access to landing light replacements from exterior)		Not Complied				As Required	
BT139-280 Rev IR 12/07/2012	Corrosion Protection Improvement Parent		Not Complied					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
BT139-280 PART I *	Corrosion Protection Improvement, (provides instructions on how to apply AV15 on the fuselage structure under the cabin floor and in the rear fuselage	Not Complied		As Required				
BT139-280 PART II *	Corrosion Protection Improvement, (provides instructions on how to install new covers P/N 3G5330A37131 and P/N 3G5330A37031 in sponson area.	Not Complied		As Required				
BT139-280 PART III *	Corrosion Protection Improvement, (provides instructions on how to apply sealant tape to cabin door steps and fuselage access panels)	Not Complied		As Required				
BT139-280 PART IV *	Corrosion Protection Improvement, (provides instructions on how to install new drain holes in fuselage under cabin floor and rear fuselage structure).	Not Complied		As Required				
BT139-280 PART V *	Corrosion Protection Improvement, (provides instructions on how to install sealing tape between tail rotor shaft cowlings and the tail structure).	Not Complied		As Required				
BT139-280 PART VI *	Corrosion Protection Improvement, (provides instructions on how to apply sealing tape on passenger cabin subfloor).	Not Complied		As Required				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-280 PART VII *	Corrosion Protection Improvement, (provides instructions on how to apply sealing tape to rear fuselage power section).		Not Complied				As Required	
BT139-306 Rev IR 12/12/2012	Nose Landing Gear, Inspection of arms pin installation.		Complied c/w BT 139-306 --			TL-062085-2013 944.2 FH 01/17/2013	One-Time	
AD2012-21-52 Rev IR 12/26/2012	Comply with AD2012-21-52. Inspection of pilot and copilot collective and cyclic control stick installation and attachment hardware.		Complied Complied with all IAW AD2012-21-52 --			TL-057830-2012 740.8 FH 10/23/2012	One-Time	
139-25-13-00 Rev IR 01/23/2013	Cabin Cargo Net Installation		Not Complied				As Required	
BT139-297 Rev A 02/28/2017	TRAKKA A800 Searchlight Kits P/N 4G3340F02411 AND P/N 4G3340F02412, Installation of.		Not Complied				As Required	
BT139-312 Rev IR 02/05/2013	HUMS Software Version Upgrade		Complied c/w BT 139-312 --			TL-066276-2013 1175.9 FH 04/08/2013	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-305 Rev IR 02/07/2013	Tail Rotor Bearing Support Bracket Inspection		Complied - N/A Superceded by BT139-296, GJ 5/14/14 -- Era QC			12/14/2013		
BT139-262 Rev IR 02/27/2013	Replacement of Rear Upper Deck Panel		Complied RII completed for installation of rear upper engine deck. The installation is satisfactory. RII completed for installation of rear upper engine deck. The installation is satisfactory. -- Thibodeaux, Lauren .			HWO-004749-2015 2494.3 FH 04/20/2015	As Required	
BT139-108 Rev IR 02/27/2013	Additional Lower Mooring Installation for AW139 Aircraft, IAW BT139-108.		Not Complied				As Required	
BT139-300 Rev IR 03/01/2013	Emergency Flotation System (EFS) Connections Modification IAW BT139-300.		Complied Complied with Emergency Flotation System (EFS) Connections Modification IAW BT139-300. Performed Successful Continuity check per BT 139-300. --			HWO-002838-2013 1310.6 FH 06/05/2013	One-Time	
BT139-302 Rev IR 03/01/2013	Pedal Set Assy Inspection and Reconfiguration.		Complied IAW BT139-302, only the R/H co-pilot pedal needed replacement. This action was done IAW AMP-39-A-67-21-01-00A-710A-B. --			HWO-002824-2013 1310.6 FH 06/13/2013	One-Time	
BT139-192 Rev IR 03/01/2013	Sliding Passenger Door Check and Adjustment IAW BT139-192.		Complied Installed L/H cabin door IAW A139 AMP-39-B-52-12-01-00A-720A-K. Performed inspection IAW BT139-192, all measurements exceed minimum. Installed R/H cabin door IAW A139 AMP-39-A-52-12-02-00A-720A-A. P --			HWO-002824-2013 1310.6 FH 07/23/2013	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-158 Rev A 09/28/2016	Sliding Passenger Door Assembly Improvement, IAW BT139-158. *		Not Complied				As Required	
BT139-294 Rev IR 03/20/2013	HEELS Cabin Doors/Windows Lights Inspection, IAW BT139-294.		Complied C/W BT 139-294 HEEL Lights Inspection. --			TL-079507-2013 1746.6 FH 11/26/2013	One-Time	
139-34-13-00 Rev IR 03/25/2013	EGPWS Computer Relocation *		Not Complied				As Required	
139-23-13-00 Rev IR 04/08/2013	AW139 cabin ICS removeable cover installation		Complied fabricated and installed a modified removable ICS cover --			TL-082875-2014 1871.3 FH 01/30/2014	One-Time	
BT139-324 Rev A 06/04/2013	MR and TR Full Ice Protection System (FIPS) cables, Inspection of.		Complied - N/A N/A, Aircraft does not have FIPS equipment installed, DZ 04/15/2013. -- Era QC			1199.6 FH 04/15/2013	One-Time	
BT139-327 Rev A 05/30/2013	Improved head sealing of the secondary fuel probe 3G2840V010513240		Complied Painted Clear Coat on Head Sealing Of the Secondary Fuel Probe IAW BT-139-327 Using Sherwin Williams Aerospace Coatings Preparation and Painting Instructions. -- Lindley, Elloria .			CWO-025999-2016 -- 10/06/2016	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-327 Rev A 05/30/2013	Improved head sealing of the secondary fuel probe 3G2840V010513312		Complied Complied IAW BT139-327 Complied IAW BT139-327 --			CWO-029321-2017 -- 11/27/2017	As Required	
BT139-325 PTI Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532HSC258804		Complied - N/A Not applicable by part number. LMartin -- Era QC			3605.9 FH 07/18/2021		
BT139-325 PTII Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532HSC228589		Complied - N/A No longer applicable, no further action required. M. Michaelis -- Era QC			2989.01 FH 01/14/2021	One-Time	
BT139-325 PTI Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532HSC228589		Complied - N/A No longer applicable, no further action required. M. Michaelis -- Era QC			2989.01 FH 01/14/2021		
BT139-325 PTII Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532HSC238989		Complied - N/A Not applicable by part number. LMartin -- Era QC			2992.2 FH 06/29/2021	One-Time	
BT139-325 PTII Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532HSC258804		Complied - N/A Not applicable by part number. LMartin -- Era QC			3605.9 FH 07/18/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-325 PTI Rev A 07/01/2013	Main Rotor Servoactuator Inspection and Repair 3G6730V00532 HSC238989		Complied - N/A Not applicable by part number. LMartin -- Era QC			2992.2 FH 06/29/2021		
139-25-13-01 Rev IR 06/17/2013	Installation of First Aid Kit and Fire Extinguisher Bracket		Complied Complied with installation of first aid kit and fire extinguisher brackets. Ref Eradrawing# 139-25-13-01. --			HWO-011678-2020 5437 FH 08/19/2020	As Required	
BT139-307 Rev IR 06/19/2013	Hydraulic System Flexible Hoses Replacement in the Upper Deck Area		Complied complied with Bt-307 complied with Bt-307 --			TL-077513-2013 1597.6 FH 10/18/2013	One-Time	
AD2013-10-01 (E)(1) Rev IR 06/20/2013	Spectrolab Nightsun XP Searchlight		Complied Inspected Aircraft N811TA No Spectrolab Nightsun XP Searchlight Installed at this time AD2013-10-01 does not apply at this time. --			HWO-002824-2013 1310.6 FH 06/19/2013	One-Time	
BT139-289 Rev IR 07/03/2013	Nose Landing Gear, Alternative Shimmy Damper Fluid 3G3220V00135 00468		Complied - N/A Not applicable by component serial number, 9/25/2013, G. JEFFERS -- Era QC			09/25/2013	One-Time	
AD2013-06-51 Rev IR 03/25/2013	Perform an inspection of the Rescue Hoist in accordance with Goodrich Alert Service Bulletin no. 44301-10-15 dated March 8, 2013.		Complied - N/A Not applicable as Rescue Hoist not installed on this aircraft. R Sullivan -- Era QC			03/25/2013	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance				Complied On TT Date	Interval Next Due
BT 139-320 Rev IR 07/16/2013	FIPS Tail Rotor Slip Ring Drive Installation Improvement		Complied - N/A N/A by Configuration,(Only FIPS), 8/20/13, G. Jeffers -- Era QC				08/20/2013	One-Time
BT139-313 Rev A 03/14/2018	Installation of Transponder (XPDR) with ADS-B OUT Parent		Partially Complied					
BT139-313 PART I *	Installation of XPDR with ADS-B Out		Not Complied					As Required
BT139-313 PART II	Insallation of the new basic XPDR module.		Complied Complied with BT139-313 PART II. No defects noted. --				HWO-004456-2014 2395.5 FH 12/15/2014	As Required
BT139-313 PART III *	Installation of the new 2nd XPDR module		Not Complied					As Required
BT139-313 PART IV *	Installation of the new 2nd XPDR module		Not Complied					As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-313 PART V *	Installation of the new 2nd XPDR module		Not Complied				As Required	
BT139-315 Rev B 02/27/2014	Primus Epic Flight Software Release 7.4 (Phase 7Version 1), Installation of.		Not Complied				As Required	
BT139-332 Rev IR 08/02/2013	Install MGB Sun Gear Oil Nozzles PN 3G6306P01511 3G6320A00134 AW1054		SB has been applied at MGB build due to DOM. JFONTENOT 02/17/2021 -- Era QC			Manually Updated -- 06/08/2020	As Required	
BT139-343 Rev IR 08/02/2013	Accessory Drive ECS Compressor Visual Inspection and Modification		Complied - N/A N/A by Configuration, (Only FIPS), 8/20/13, G. Jeffers -- Era QC			08/20/2013	One-Time	
BT139-344 Rev IR 08/02/2013	Increase of (MGB) Overhaul Interval from 5000 FH to 6000 FH 3G6320A00134 AW1054		Pre-requisite SBs have been applied at MGB build due to DOM. JFONTENOT 02/17/2021 -- Era QC			Manually Updated 378.4 FH 02/17/2021	As Required	
BT139-329 Rev A 11/05/2013	Cargo Hook Kit P/N 3G2592F00111, Longeron BL +/-275 Retromod.		Complied - N/A N/A by Cargo Hook Provision Not Installed, 9/6/2013, G. Jeffers -- Era QC			1424.8 FH 09/06/2013	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-341 Rev A 04/11/2018	Installation of Main Rotor Scissors P/N 3G6230A00733 Parent		Not Complied					
	SB139-341 MRH (POST-MOD)AW139 Main Rotor Head conversion from 3G6220A00132 to 3G6220A00134 3G6220A00132 R340		Not Complied				As Required	
	SB139-341 ROT SWASHPLATE AW139 Rotating Swashplate conversion from 3G6230A00332 to 3G6206P01331 3G6230A00332 BAX6255		Not Complied				As Required	
STCSR03265CH Rev IR 09/13/2013	Installation of Removable Medical Litter, IAW Spectrum Air Ambulance Conversion, STC SR03265CH		Complied Installed Removable Medical Litter, IAW Spectrum Air Ambulance Conversion, STC SR03265CH, to include RFMS, weight and balance updates and applicable placards that may be needed, along with the complet --			TL-127208-2016 3190.2 FH 03/16/2016	As Required	
139-25-13-03 Rev IR 09/20/2013	FLIR Assembly Installation(Agusta TCd Optional Install)		Not Complied				As Required	
STCSR02138SE PARA 3.9 Rev IR 10/04/2013	Hinged Fuel Cap Kit		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
BT139-339 Rev B 05/23/2014	FIPS ATRU Replacement Parent	Complied						
BT139-339 PART I	Replace ARTU with New Model	Complied N/A by Aircraft Configuration, 10/17/2013, G. Jeffers -- Era QC	Manually Updated 1592.5 FH 10/17/2013	One-Time				
139-34-13-01 Rev IR 10/10/2013	GPS 796 *	Not Complied		As Required				
139-67-13-00 Rev IR 10/10/2013	Engine Governor Switch Protector	Complied C/W install IAW ERA drawing #139-67-13-00 --	TL-078045-2013 1639 FH 10/29/2013	One-Time				
AD2013-15-01. Rev IR 10/16/2013	Deactivation of FIPS Parent	Complied						
AD2013-15-01	Deactivate FIPS	Complied Not applicable due to model number --	TL-077078-2013 1560.9 FH 10/10/2013	One-Time				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AMOCAD2013-15-01	Install Fire Detector in the ATRU using bay according AWPC-KIT-2610F001		Complied - N/A Not applicable by aircraft not FIPS configuration -- Era QC			2726.5 FH 08/07/2015	One-Time	
BT139-336 Rev A 01/16/2014	FIPS M/R Cables Replacement 3G6220A00132R340		Not Complied				As Required	
139-33-13-00 Rev IR 11/04/2013	Installation of Whelen Strobes		Complied c/w 139-33-13-00 --			TL-090757-2014 2177.7 FH 06/18/2014	As Required	
139-25-13-04 Rev IR 11/05/2013	SAR Cabin Box with FLIR		Not Complied				As Required	
BT139-331 Rev B 09/26/2014	M/R Servo Layshaft Play 3G6730V00532HSC258804		Complied - N/A Not applicable by part number. LMartin -- Era QC			3605.9 FH 07/18/2021	One-Time	
BT139-331 Rev B 09/26/2014	M/R Servo Layshaft Play 3G6730V00532HSC238989		Complied - N/A Not applicable by part number. LMartin -- Era QC			2992.2 FH 06/29/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-331 Rev B 09/26/2014	M/R Servo Layshaft Play 3G6730V00532HSC228589		Complied - N/A No longer applicable, no further action required. M. Michaelis -- Era QC			2989.01 FH 01/14/2021	One-Time	
AD 2013-22-16 Rev IR 12/13/2013	Replace Solder Splices in CoPilot Audio System		Complied Not applicable by aircraft serial number --			TL-078745-2013 1699.4 FH 11/12/2013	One-Time	
BT 139-310 Rev A 08/07/2014	Installation of Low Speed Landing Aural Warning Kit Parent		Partially Complied					
BT 139-310 PART I	Installation of Low Speed Landing Aural Warning		Complied Complied with BT139-310 Part 1 [1-6]. No defects noted --			HWO-004456-2014 2395.5 FH 12/15/2014	As Required	
BT 139-310 PART II	Installation of Low Speed Landing Aural Warning		Not Complied				As Required	
BT 139-310 PART III	Installation of Low Speed Landing Aural Warning		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2013-25-09 Rev IR 01/28/2014	Inspection of NLG pin for correct assy		Complied Complied with para (e) 1 Complied with para (e) 1 --			TL-082385-2014 1840.3 FH 01/20/2014	One-Time	
BT139-116 Rev A 03/28/2014	R/H Aft Float Mod		Complied Installed aft flot Retro modification kit IAW ERA Drawing 139-116. --			HWO-011534-2020 5437 FH 08/18/2020	One-Time	
139-25-14-00 Rev IR 02/14/2014	Upper Door Track Hoist Cable Scuff Guard		Not Complied				As Required	
139-51-14-00 Rev IR 02/17/2014	R/H Aft Float Modification		Complied Fabricated and installed doubler under R/H baggage compartment I.A.W. Era Dwg. No. 139-51-14-00. --			HWO-004704-2015 2494.3 FH 03/16/2015	One-Time	
139-53-14-00 Rev IR 02/17/2014	Fly Away Kit Shelf		Complied Installed fly away shelf kit IAW ERA Drawing # 139-53-14-00. --			HWO-004704-2015 2494.3 FH 04/20/2015	As Required	
BT139-367 Rev IR 02/19/2014	T/R Servo, Measurement of Layshaft Play		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			3126.9 FH 03/24/2021	One-Time	
	3G6730V00732	HSC213631						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-311 Rev B 06/04/2014	Subfloor Frame Retromod, (T/R Pedals) Parent		Complied					
BT139-311 PT I	Visual Insp of Subfloor Frame (T/R Pedals)		Complied - N/A NA by BT139-311 PT II C/W -- Era QC			2494.3 FH 04/27/2015	One-Time	
BT139-311 PT II	Retromodification to Subfloor Frame STA2105 (T/R Pedals)		Complied C/W on VP283, HWO-004733-2015, GJ -- Era QC			2494.3 FH 04/22/2015	One-Time	
BT139-357 Rev B 03/23/2020	Install of 2nd GPS Kit (Short Nose) Parent		Not Complied					
BT139-357 PT I	Install of 2ND GPS Kit (Short Nose)		Not Complied				As Required	
BT139-357 PT II	Install of 2ND GPS Kit (Short Nose)		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance						TT	
Eff Date	Part Number	Serial Number					Date	Next Due
BT139-357 PT III	Install of 2ND GPS Kit (Short Nose)		Not Complied					As Required
*								
BT139-400	Phase 7 Version 3		Partially Complied					
Rev IR	*							
02/24/2014	Parent							
BT139-400 PT I	Inatall PH 7 to AW139 with 4.8 Installed		Not Complied					As Required
*								
BT139-400 PT II	Install PH 7 to AW139 with 4.8 Installed		Not Complied					As Required
*								
BT139-400 PT III	Install PH 7 to AW139 with 5.6 Installed		Not Complied					As Required
*								
BT139-400 PT IV	Install PH 7 to AW139 with 6.2 Installed		Complied	Complied with BT139-400 PT IV. No defects noted. --			HWO-004456-2014	As Required
							2395.5 FH	
							12/16/2014	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-400 PT V	Install PH 7 to AW139 with 4.8, 5.6, or 6.2 Installed		Complied Complied with BT139-400 PT V. No defects noted. --			HWO-004456-2014 2395.5 FH 12/16/2014	As Required	
BT139-353 Rev IR 03/11/2014	L/H & R/H Pax Removable Handle Parent		Not Complied					
BT139-353 PT I	L/H PAX Handle Provisions		Not Complied				As Required	
BT139-353 PT II	R/H PAX Handle Provisions		Not Complied				As Required	
BT139-353 PT III	L/H PAX Handle Provisions		Not Complied				As Required	
BT139-353 PT IV	R/H PAX Handle Provisions		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-353 PT V *	L/H PAX Handle Install		Not Complied				As Required	
BT139-353 PT VI *	R/H PAX Handle Install		Not Complied				As Required	
BT139-368 Rev IR 03/19/2014	Insp/Replacement of Lower Scissor Bearing Parent		Complied - N/A -- Era QC					
BT139-368 PT1	Insp of MR Lower Scissor Half		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			-- 07/13/2022		
BT139-368 PT1	Insp of MR Lower Scissor Half		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			-- 08/19/2022		
BT139-368 PTII	Replace Lower Scissor Bearing		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			-- 07/13/2022	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-368 PTII	Replace Lower Scissor Bearing		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		One-Time
	3G6230A00932	AW6424				08/19/2022		
AD2014-07-51 Rev IR 08/20/2014	Lower Half Scissor Spherical Bearings Parent		Complied - N/A -- Era QC					
AD2014-07-51(E)(1-2)	Lower Half Scissor Spherical Bearings		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		
	3G6230A00932	AW6424				08/19/2022		
AD2014-07-51(E)(1-2)	Lower Half Scissor Spherical Bearings		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			--		
	3G6230A00932	AW6426				07/13/2022		
AD2014-07-51(E)(3-5)	Lower Half Scissor Spherical Bearings		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			--		One-Time
	3G6230A00932	AW6426				07/13/2022		
AD2014-07-51(E)(3-5)	Lower Half Scissor Spherical Bearings		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		One-Time
	3G6230A00932	AW6424				08/19/2022		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2014-03-01 Rev IR 04/07/2014	Rework/Replace Wire Strike Protection System		Complied - N/A Not applicable by Wire Strike Protection System not installed, Documentation in Aircraft Records Binder, Section- (Airframe Airworthiness Directives) G. Jeffers -- Era QC			03/05/2014	One-Time	
139-33-14-00 Rev IR 04/23/2014	Orion LED POS/Strobes *		Not Complied				As Required	
STCSR02138SE PARA 3.5 Rev IR 05/05/2014	Cabin Floor Protector Kit *		Not Complied				As Required	
BT139-296 Rev A 06/21/2016	T/R Shaft Reinforcement Parent		Complied					
BT139-296 PT I	Visual Insp of Bearing Support		Complied - N/A NA by BT139-296 PT II C/W -- Era QC			04/27/2015		
BT139-296 PT II	Reinforce Backup Structure T/R Bearing Support		Complied C/W on VP283, HWO-004733-2015, GJ -- Era QC			Manually Updated 2494.3 FH 04/22/2015	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-93-14-00 Rev IR 05/19/2014	VMU (Video Management Unit) Relocation		Not Complied				As Required	
	*							
BT139-061 Rev B 03/23/2020	Installation of 2nd GPS		Complied Installed by Agusta as optional equipment during aircraft build. R Sullivan Complied with on previous revision. JFONTENOT 03/25/2020 -- Era QC			Manually Updated 2125.2 FH 05/27/2014	As Required	
BT139-190 Rev IR 06/04/2014	(DAU) Mounting Wedges Rivet Inspection		Complied - N/A Not applicable by serial number, G Jeffers -- Era QC				One-Time	
	3G3130V00251	0000089				06/25/2014		
BT139-372 Rev A 10/07/2014	(FIPS) Tail Gearbox (TGB) Fairing		Complied - N/A NA by Not Installed, GJ -- Era QC			2169.2 FH 06/13/2014	One-Time	
139-05-14-00 Rev IR 06/14/2014	Installation of ID Decals		Complied c/w 139-05-14-00 --			TL-090757-2014 2177.7 FH 06/18/2014	As Required	
SB139-155 Rev C 06/20/2023	2ND ANTICOLLISION LIGHT KITS		Not Complied					
	*							
	Parent							

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance				Complied On TT Date	Interval Next Due
SB139-155 PT I *	2ND ANTICOLLISION LIGHT KITS		Not Complied					As Required
SB139-155 PT II *	2ND ANTICOLLISION LIGHT KITS		Not Complied					As Required
SB139-155 PT III *	2ND ANTICOLLISION LIGHT KITS		Not Complied					As Required
BT139-323 Rev IR 08/07/2014	Improvement of Wearher Radar Primus 701 Installation		Not Complied					As Required
139-67-14-00 Rev IR 09/01/2014	Main Rotor Servo Switch Silicone Grease Application		Complied C/W 139-67-14-00 -- Mulderick, Kyle E.				TL-231377-2022 7443.9 FH 09/09/2022	30 D 10/09/2022
BT139-392 RA Rev A 02/14/2017	MAIN ROTOR (MR) SCISSOR LEVER BEARING P/N 3G6230V00654 Parent		Complied - N/A -- Era QC					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev #	Subject		Method of Compliance			Complied On TT	Interval	
Eff Date	Part Number	Serial Number				Date	Next Due	
BT139-392 RA PTI	Daily visual inspection of MR scissor bearing		Complied - N/A Not applicable by part number. LMartin -- Era QC			--	One-Time	
	3G6230A00932	AW6426				07/13/2022		
BT139-392 RA PTI	Daily visual inspection of MR scissor bearing		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			--	One-Time	
	3G6230A00932	AW6424				08/19/2022		
BT139-392 RA PTII	Install Special nut and washer		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			--	One-Time	
	3G6230A00932	AW6424				08/19/2022		
BT139-392 RA PTII	Install Special nut and washer		Complied - N/A Not applicable by part number. LMartin -- Era QC			--	One-Time	
	3G6230A00932	AW6426				07/13/2022		
BT139-392 RA PTIII	Replace MR Scissor lever bearings P/N 3G6230V00654 with new MR Scissor lever bearings P/N 3G6230V00655		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			--	One-Time	
	3G6230A00932	AW6424				08/19/2022		
BT139-392 RA PTIII	Replace MR Scissor lever bearings P/N 3G6230V00654 with new MR Scissor lever bearings P/N 3G6230V00655		Complied - N/A Not applicable by part number. LMartinNot applicable by part number. LMartinNot applicable by part number. LMartinNot applicable by part number. LMartinNot applic -- Era QC			--	One-Time	
	3G6230A00932	AW6426				07/13/2022		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-370 Rev IR 10/02/2014	Right Engine Assy Fuel Inlet Hose		Complied RII inspection completed for installation of #2 engine fuel line. The installation is satisfactory. RII inspection completed for installation of #2 engine fuel line. The installation is satisfactory. --			HWO-004705-2015 2494.3 FH 04/22/2015		One-Time
139-25-14-01 Rev IR 11/06/2014	AW139 SAR Cabin Floor Drain		Not Complied					As Required
BT189-010 Rev IR 11/26/2014	Tail Rotor (TR) Shutoff Valve (SOV) P/N 3G2910V00231.		Complied - N/A Requirements of Supplier SB6306-01 Completed as described in BT139-391 and BT189-010. By ES, 10/21/2015 -- Era QC			10/21/2015		One-Time
BT139-391 Rev IR 11/26/2014	Tail Rotor (TR) Shut-Off Valve (SOV) P/N 3G2910V00231		Complied c/w iaw bt requirements. -- Landry, Michelle R.			TL-104849-2015 2091.4 FH 01/30/2015		One-Time
AD2014-24-02 Rev IR 12/15/2014	AD2014-24-02 Superseded by AD2017-23-08		Complied - N/A -- Era QC					
AD2014-24-02 (F)(1)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		
	3G6230A00932	AW6424				08/19/2022		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
AD2014-24-02 (F)(1)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			--		
	3G6230A00932	AW6426				07/13/2022		
AD2014-24-02 (F)(2)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		One-Time
	3G6230A00932	AW6424				08/19/2022		
AD2014-24-02 (F)(2)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			--		One-Time
	3G6230A00932	AW6426				07/13/2022		
AD2014-24-02 (F)(3)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Not applicable, superseded by AD2021-05-21. LMartin -- Era QC			--		One-Time
	3G6230A00932	AW6426				07/13/2022		
AD2014-24-02 (F)(3)	AD2014-24-02 is Superseded by AD2017-23-08		Complied - N/A Superseded by AD 2021-05-21. M. Michaelis -- Era QC			--		One-Time
	3G6230A00932	AW6424				08/19/2022		
BT139-410 Rev A 02/12/2016	MR Damper Spherical Bearing & Rod End Insp Parent		Complied - N/A -- Era QC					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-410 PT I	MR Damper Spherical Bearing Insp		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			1091.3 FH		
	3G6220V01353	MCR5223				06/17/2020		
BT139-410 PT I	MR Damper Spherical Bearing Insp		Complied - N/A Not applicable, superseded by BT139-450. LMartin -- Era QC			2580.5 FH		
	3G6220V01353	MCR5278				11/06/2020		
BT139-410 PT I	MR Damper Spherical Bearing Insp		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			4068.7 FH		
	3G6220V01353	MCR5574				04/29/2020		
BT139-410 PT I	MR Damper Spherical Bearing Insp		Complied - N/A Superseded by BT139-450 Rev C. No further action required. M. Michaelis -- Era QC			2227.5 FH		
	3G6220V01353	MCR6442				08/03/2020		
BT139-410 PT I	MR Damper Spherical Bearing Insp		Complied - N/A NA - superseded by BT 139-450, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC					
	3G6220V01353	MCR5012				09/28/2017		
BT139-410 PT II	MR Damper Rod End Insp		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			1091.3 FH		
	3G6220V01353	MCR5223				06/17/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-410 PT II	MR Damper Rod End Insp		Complied - N/A NA - superseded by BT 139-450, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC					
	3G6220V01353	MCR5012				09/28/2017		
BT139-410 PT II	MR Damper Rod End Insp		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			4068.7 FH		
	3G6220V01353	MCR5574				04/29/2020		
BT139-410 PT II	MR Damper Rod End Insp		Complied - N/A Not applicable, superseded by BT139-450. LMartin -- Era QC			2580.5 FH		
	3G6220V01353	MCR5278				11/06/2020		
BT139-410 PT II	MR Damper Rod End Insp		Complied - N/A Superseded by BT139-450 Rev C. No further action required. M. Michaelis -- Era QC			2227.5 FH		
	3G6220V01353	MCR6442				08/03/2020		
BT139-389 Rev A 07/15/2016	Gaskets Antenna Installation *		Not Complied					As Required
SB139-395 Rev A 03/20/2015	TCAS II Part 1 and Part II kit installation *		Not Complied					As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
MOD/139/25.6006 Rev 8 03/10/2023	Installation of Sea Tray		Not Complied				As Required	
	*							
BT139-363 Rev IR 02/23/2015	Pilots Footsteps Kit		Not Complied				As Required	
	*							
BT139-373 Rev A 06/17/2016	#1 ENG Fuel Hose/Fire Det Parent		Complied - N/A -- Era QC					
BT139-373 PT I	Visual Insp #1 ENG Fuel Hose/Fire DET		Complied - N/A NA by A/C S/N -- Era QC					
						03/09/2015		
BT139-373 PT II	ReWork #1 ENG Thermal Barrier		Complied - N/A NA by A/C S/N -- Era QC				One-Time	
						03/09/2015		
AD2015-02-21 Rev IR 03/17/2015	Replace Single-Braid Hydraulic Hoses		Complied AD2015-02-21 previously complied with. --			TL-116603-2015 2765.3 FH 08/19/2015	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
BT139-350 Rev IR 04/08/2015	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS Parent	Not Complied						
BT139-350 PT3 04/08/2015	IGB FITTING REPLACEMENT 3G5350A00135 A7/0083	Not Complied		As Required				
SB29-0006 Rev IR 04/15/2015	UTC change of configuration of Power Control Module from 3G2900V00651 to 3G2900V00652 3G2900V00651 1298	Not Complied		As Required				
SB29-0006 Rev IR 04/15/2015	UTC change of configuration of Power Control Module from 3G2900V00651 to 3G2900V00652 3G2900V00651 745	Not Complied		As Required				
BT139-218 Rev IR 04/23/2015	Double Hoist Electrical Provision Modification	Complied - N/A N/A by A/C Serial Number -- Era QC		One-Time				
BT139-219 Rev IR 04/23/2015	Single Hoist Electrical Provision Modification	Complied - N/A N/A by A/C Serial Number -- Era QC		One-Time				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-366 Rev A 04/14/2016	LH Coll Torque Tube Cover Parent		Complied					
BT139-366 PT I	Insp/Rework LH Coll TQ Tube Cover		Complied C/W BT 139-366 Pt. 1 C/W BT 139-366 Pt. 1 --			TL-115084-2015 2682.3 FH 07/25/2015	One-Time	
BT139-366 PT II	Modify Cable Assy LH Coll TQ Tube		Complied C/W BT139-366 PT II. --			TL-132863-2016 3211.4 FH 07/11/2016	One-Time	
BT139-402 Rev IR 06/09/2015	MR Damper Bolt (3G6220A01252) 3G6220A00132 R340		Complied - N/A Not applicable by Damper Bolt part number. LMartin -- Era QC			3695.5 FH 04/21/2021	One-Time	
139-23-15-00 Rev IR 06/10/2015	Spidertracks S3, AW139		Complied --			HWO-005836-2016 3188.5 FH 02/08/2016	As Required	
BT139-374 Rev IR 07/06/2015	Emergency Floats Control Panel 3G9560V00558 S09646205		Complied Complied with by Leonardo S.p.a. -- Era QC			Manually Updated -- 01/17/2018	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
MOD/139/25.6025 Rev 7 09/08/2023	Introduction of SAR Cabin Equipment Stowage *		Not Complied				As Required	
BT139-425 Rev IR 08/31/2015	Main Rotor Actuator Upgrade 3G6730V00532HSC238989		Complied Complied with per SB27-131 listed on log card. LMartin -- Era QC			Manually Updated 492 FH 08/12/2015	One-Time	
BT139-425 Rev IR 08/31/2015	Main Rotor Actuator Upgrade 3G6730V00532HSC258804		Complied Complied with part number upgrade SB27-131. LMartin -- Era QC			Manually Updated 2987.2 FH 02/15/2018	One-Time	
BT139-425 Rev IR 08/31/2015	Main Rotor Actuator Upgrade 3G6730V00532HSC228589		Complied Complied with by HS Wroclaw, modified to part number 652. No further action required. M. Michaelis -- Era QC			Manually Updated 2064.3 FH 05/26/2017	One-Time	
139-52-15-00 Rev IR 09/10/2015	AW139 Baggage Compartment Door Seal *		Not Complied				As Required	
BT139-427 Rev IR 10/21/2015	Power Control Module		Complied - N/A See UTC SB29-0006 for compliance, C. Hine -- Era QC			5437 FH 07/01/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-15-01 Rev IR 10/28/2015	AW139 SART Install in SAR aircraft only		Not Complied				As Required	
BT139-431 Rev IR 11/10/2015	Deployable ELT System Interface Unit replacement.		Complied removed and replaced system interface unit with serviceable SIU REF BT139-431 and AW139 AMP 25-64-02 --			TL-124270-2016 3179.2 FH 01/13/2016	One-Time	
BT139-414 Rev IR 12/16/2015	BRACKETS NOSE INSTALLATION.		Not Complied				As Required	
BT139-417 Rev IR 01/15/2016	NEW ELASTOMERIC TAIL ROTOR DAMPER Parent		Complied					
BT139-417 PTI	NEW ELASTOMERIC TAIL ROTOR DAMPER WITHOUT FIPS		Complied RII inspection completed for installation of new T/R elastomeric dampers. The installations are satisfactory. RII inspection completed for installation of new T/R elastomeric dampers. The installat --			HWO-011478-2020 5437 FH 08/05/2020	As Required	
BT139-424 Rev IR 01/22/2016	Install Primus Epic Flight Software Release 7.10 (PHASE 7 V4). Parent		Not Complied					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance						TT	
Eff Date	Part Number	Serial Number					Date	Next Due
BT139-424 PTI	*	Comply with prerequisites required for installation of Phase 7 V4.	Not Complied					As Required
BT139-424 PTII		Install HW3 displays for Phase 7 V4 upgrade	Not Complied					As Required
BT139-424 PTIII		Load Primus EPIC Flight Software release 7.10 (Phase 7 Version 4).	Not Complied					As Required
AD 2016-01-06		FIPS T/R Slip Ring Insp	Complied Not Applicable by A/C configuration. FIPS not installed. --				TL-169048-2018	One-Time
Rev IR							4116.1 FH	
01/28/2016							10/14/2018	
139-23-16-00	*	Installation of Antenna Gaskets	Not Complied					As Required
Rev IR								
02/03/2016								
BT139-446		MAIN ROTOR (MR) DAMPER INSPECTIONS	Complied - N/A -- Era QC					
Rev IR								
02/12/2016		Parent						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-446 PTI	Torque check of the damper body and the damper rod end		Complied - N/A Complied with by Chevron (AC2R685K). Currently superseded by BT139-450 Rev C. No further action required. M. Michaelis -- Era QC			769.2 FH	02/12/2016	
	3G6220V01353	MCR6442						
BT139-446 PTI	Torque check of the damper body and the damper rod end		Complied - N/A Complied with by Macaer Aviation at total time 229.0. M. Michaelis -- Era QC			229 FH	03/25/2016	
	3G6220V01353	MCR5223						
BT139-446 PTI	Torque check of the damper body and the damper rod end		Complied - N/A NA - superseded by BT 139-450, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC			09/28/2017		
	3G6220V01353	MCR5012						
BT139-446 PTI	Torque check of the damper body and the damper rod end		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			4068.7 FH	04/29/2020	
	3G6220V01353	MCR5574						
BT139-446 PTI	Torque check of the damper body and the damper rod end		Complied - N/A Not applicable, superseded by BT139-450. LMartin -- Era QC			2580.5 FH	11/06/2020	
	3G6220V01353	MCR5278						
BT139-446 PTII	Visual inspection and dimension check MR Damper		Complied - N/A NA - superseded by BT 139-450, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC				One-Time	
	3G6220V01353	MCR5012				09/28/2017		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-446 PTII	Visual inspection and dimension check MR Damper		Complied - N/A Complied with by Macaer Aviation at total time 229.0. M. Michaelis -- Era QC			229 FH	One-Time	
	3G6220V01353	MCR5223				03/25/2016		
BT139-446 PTII	Visual inspection and dimension check MR Damper		Complied - N/A Not applicable, superseded by BT139-450. LMartin -- Era QC			2580.5 FH	One-Time	
	3G6220V01353	MCR5278				11/06/2020		
BT139-446 PTII	Visual inspection and dimension check MR Damper		Complied - N/A Complied with by Chevron (AC2R685K). Currently superseded by BT139-450 Rev C. No further action required. M. Michaelis -- Era QC			769.2 FH	One-Time	
	3G6220V01353	MCR6442				02/12/2016		
BT139-446 PTII	Visual inspection and dimension check MR Damper		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			4068.7 FH	One-Time	
	3G6220V01353	MCR5574				04/29/2020		
BT139-446 PTIII	Annex A MR Damper inspection		Complied - N/A Complied with by Macaer Aviation at total time 229.0. M. Michaelis -- Era QC			229 FH	One-Time	
	3G6220V01353	MCR5223				03/25/2016		
BT139-446 PTIII	Annex A MR Damper inspection		Complied - N/A Superseded by BT139-450 Rev C. M. Michaelis -- Era QC			4068.7 FH	One-Time	
	3G6220V01353	MCR5574				04/29/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-446 PTIII	Annex A MR Damper inspection		Complied - N/A Complied with by Chevron (AC2R685K). Currently superseded by BT139-450 Rev C. No further action required. M. Michaelis -- Era QC			769.2 FH	One-Time	
	3G6220V01353	MCR6442				02/12/2016		
BT139-446 PTIII	Annex A MR Damper inspection		Complied - N/A NA - superseded by BT 139-450, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC				One-Time	
	3G6220V01353	MCR5012				09/28/2017		
BT139-446 PTIII	Annex A MR Damper inspection		Complied - N/A Not applicable, superseded by BT139-450. LMartin -- Era QC			2580.5 FH	One-Time	
	3G6220V01353	MCR5278				11/06/2020		
BT139-434 Rev A 07/03/2017	Exhaust Tunnel Assy Mod		Not Complied				As Required	
139-34-16-01 Rev IR 02/22/2016	WX Radar Ant. Drive Mount Modification		Not Complied				As Required	
AD2016-01-15 Rev IR 02/25/2016	Pilot & Copilot T/R Pedal Support Frame Insp		Complied					
	Parent							

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2016-01-15 (E)(1-2)	Pilot & Copilot T/R Pedal Support Frame Insp		Complied - N/A Not applicable by BT139-311 PT II Complied with, G Jeffers -- Era QC			04/27/2015		
AD2016-01-15 (E)(3)	Pilot & Copilot T/R Pedal Support Frame Repair		Complied Previously complied with BT139-311 PT II, G Jeffers -- Era QC			Manually Updated 2494.3 FH 04/22/2015	One-Time	
BT139-418 Rev IR 03/11/2016	Rear Fuselage Structure Assy Improvement *		Not Complied				As Required	
BT139-397 Rev IR 04/07/2016	MLG Shock Absorber Screw Replacement 3G3210V00237 00567		Complied C/W BT139-397, MLG shock absorber screw replacement. --			TL-174544-2019 4415.6 FH 03/03/2019	One-Time	
BT139-397 Rev IR 04/07/2016	MLG Shock Absorber Screw Replacement 3G3210V00137 00575		Complied C/W BT139-397, MLG shock absorber screw replacement. --			TL-174544-2019 4415.6 FH 03/03/2019	One-Time	
BT139-450 Rev D 05/28/2019	MAIN ROTOR (MR) DAMPER INSPECTIONS Parent		Complied					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-450 PTI	Dye Penetrant inspection of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH	One-Time	
	3G6220V01353	MCR5223				06/17/2020		
BT139-450 PTI	Dye Penetrant inspection of MR Damper		Complied Complied with by Mecaer America. Part time since new: 2,544.7. -- Era QC			Manually Updated	One-Time	
	3G6220V01353	MCR5012				-- 01/30/2017		
BT139-450 PTI	Dye Penetrant inspection of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH	One-Time	
	3G6220V01353	MCR5574				04/29/2020		
BT139-450 PTI	Dye Penetrant inspection of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH	One-Time	
	3G6220V01353	MCR6442				08/03/2020		
BT139-450 PTI	Dye Penetrant inspection of MR Damper		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH	One-Time	
	3G6220V01353	MCR5278				11/06/2020		
BT139-450 PTIII	Detailed visual inspection for cracks on MR Damper		Complied c/w Detailed visual inspection for cracks on MR Damper IAW BT139-450 PTIII --			TL-167943-2018		
						4096.6 FH		
						09/19/2018		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
BT139-450 PTIV	Slippage Inspection both rod end and body bearings		Complied c/w Slippage Inspection both rod end and body bearings IAW BT139-450 PTIV --			TL-167943-2018 4096.6 FH 09/19/2018		
BT139-450 PTV	Visual inspection of MR Damper broached ring and piston slots 3G6220V01353 MCR5012		Complied - N/A NA by PN, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC			01/30/2017		
BT139-450 PTV	Visual inspection of MR Damper broached ring and piston slots 3G6220V01353 MCR6442		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH 08/03/2020		
BT139-450 PTV	Visual inspection of MR Damper broached ring and piston slots 3G6220V01353 MCR5278		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH 11/06/2020		
BT139-450 PTV	Visual inspection of MR Damper broached ring and piston slots 3G6220V01353 MCR5223		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH 06/17/2020		
BT139-450 PTV	Visual inspection of MR Damper broached ring and piston slots 3G6220V01353 MCR5574		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH 04/29/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-450 PTVI	Perform MR Damper bearing friction torque check		Complied - N/A Not applicable by part number JFONTENOT 03/15/2019 -- Era QC					
	3G6220V01353	MCR5012				03/14/2019		
BT139-450 PTVI	Perform MR Damper bearing friction torque check		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH		
	3G6220V01353	MCR6442				08/03/2020		
BT139-450 PTVI	Perform MR Damper bearing friction torque check		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH		
	3G6220V01353	MCR5574				04/29/2020		
BT139-450 PTVI	Perform MR Damper bearing friction torque check		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH		
	3G6220V01353	MCR5278				11/06/2020		
BT139-450 PTVI	Perform MR Damper bearing friction torque check		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH		
	3G6220V01353	MCR5223				06/17/2020		
BT139-450 PTVII	Detailed MR Damper inspection		Complied - N/A NA by PN, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC				One-Time	
	3G6220V01353	MCR5012				01/30/2017		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-450 PTVII	Detailed MR Damper inspection		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH	One-Time	
	3G6220V01353	MCR5278				11/06/2020		
BT139-450 PTVII	Detailed MR Damper inspection		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH	One-Time	
	3G6220V01353	MCR5574				04/29/2020		
BT139-450 PTVII	Detailed MR Damper inspection		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH	One-Time	
	3G6220V01353	MCR6442				08/03/2020		
BT139-450 PTVII	Detailed MR Damper inspection		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH	One-Time	
	3G6220V01353	MCR5223				06/17/2020		
BT139-450 PTVIII	Torque check of MR Damper		Complied - N/A NA by PN, no further action required. Part time since new: 2,544.7. M. Michaelis -- Era QC				One-Time	
	3G6220V01353	MCR5012				01/30/2017		
BT139-450 PTVIII	Torque check of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH	One-Time	
	3G6220V01353	MCR5223				06/17/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Part Number	Subject Serial Number	Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-450 PTVIII	Torque check of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH	One-Time	
	3G6220V01353	MCR6442				08/03/2020		
BT139-450 PTVIII	Torque check of MR Damper		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH	One-Time	
	3G6220V01353	MCR5574				04/29/2020		
BT139-450 PTVIII	Torque check of MR Damper		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH	One-Time	
	3G6220V01353	MCR5278				11/06/2020		
BT139-450 PTII	139 MR Damper Rod End verification of "Black Dot". If marking not present conduct Dye Penetrant inspection IAW BT139-450 PTII		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1091.3 FH		
	3G6220V01353	MCR5223				06/17/2020		
BT139-450 PTII	139 MR Damper Rod End verification of "Black Dot". If marking not present conduct Dye Penetrant inspection IAW BT139-450 PTII		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			2227.5 FH		
	3G6220V01353	MCR6442				08/03/2020		
BT139-450 PTII	139 MR Damper Rod End verification of "Black Dot". If marking not present conduct Dye Penetrant inspection IAW BT139-450 PTII		Complied - N/A Not applicable by part number. LMartin -- Era QC			2580.5 FH		
	3G6220V01353	MCR5278				11/06/2020		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-450 PTII	139 MR Damper Rod End verification of "Black Dot". If marking not present conduct Dye Penetrant inspection IAW BT139-450 PTII		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			4068.7 FH	04/29/2020	
	3G6220V01353	MCR5574						
BT139-450 PTII	139 MR Damper Rod End verification of "Black Dot". If marking not present conduct Dye Penetrant inspection IAW BT139-450 PTII		Complied - N/A Not applicable by part number JFONTENOT 03/15/2019 -- Era QC			01/08/2019		
	3G6220V01353	MCR5012						
BT139-419	TAIL STRUCTURE ASSY IMPROVEMENT		Partially Complied					
Rev IR	*							
04/21/2016	Parent							
BT139-419 PT II	TAIL STRUCTURE ASSY IMPROVEMENT		Complied - N/A Not Applicable by part number, C. HINE -- Era QC			7457.5 FH	09/14/2022	
	3G5350A00135	A7/0083						
BT139-419 PT III	TAIL STRUCTURE ASSY IMPROVEMENT		Not Complied				As Required	
	*							
	3G5350A00135	A7/0083						
BT139-419 PT I	TAIL STRUCTURE ASSY IMPROVEMENT		Not Complied				As Required	
	*							
	3G5350A00135	A7/0083						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-16-01 Rev IR 06/23/2016	SAR Cabin Overhead AC Screens *		Not Complied				As Required	
ASB139-452 Rev B 04/10/2018	MR Damper Inspection and Replacement Parent		Complied					
ASB139-452 PART I	Apply reduced torque to MR Damper Hub attachment nut		Complied pcw c/w RII, installation satisfactory -- Kaurich, Steven J.			TL-224296-2022 1091.3 FH 04/18/2022	One-Time	
	3G6220V01353	MCR5223						
ASB139-452 PART I	Apply reduced torque to MR Damper Hub attachment nut		Complied pcw c/w RII, installation satisfactory -- Kaurich, Steven J.			TL-224296-2022 2580.5 FH 04/18/2022	One-Time	
	3G6220V01353	MCR5278						
ASB139-452 PART I	Apply reduced torque to MR Damper Hub attachment nut		Complied pcw c/w RII, installation satisfactory -- Kaurich, Steven J.			TL-224296-2022 4068.7 FH 04/18/2022	One-Time	
	3G6220V01353	MCR5574						
ASB139-452 PART I	Apply reduced torque to MR Damper Hub attachment nut		Complied pcw c/w RII, installation satisfactory -- Kaurich, Steven J.			TL-224296-2022 4013.7 FH 04/18/2022	One-Time	
	3G6220V01353	MCR5012						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
ASB139-452 PART I	Apply reduced torque to MR Damper Hub attachment nut		Complied pcw c/w RII, installation satisfactory -- Kaurich, Steven J.			TL-224296-2022 2227.5 FH 04/18/2022	One-Time	
	3G6220V01353	MCR6442						
ASB139-452 PART II	Main Rotor Damper Replacement		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			1164 FH 11/06/2020	One-Time	
	M006-01H046-041	MCR00762RW						
ASB139-452 PART II	Main Rotor Damper Replacement		Complied - N/A Not applicable by Body End part number M006-01H046-041. LMartin -- Era QC			-- 04/29/2020	One-Time	
	M006-01H046-041	MCR05972						
ASB139-452 PART II	Main Rotor Damper Replacement		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			-- 06/17/2020	One-Time	
	M006-01H046-041	MCR07184						
ASB139-452 PART II	Main Rotor Damper Replacement		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			-- 08/03/2020	One-Time	
	M006-01H046-041	MCR07629						
ASB139-452 PART II	Main Rotor Damper Replacement		Complied - N/A Not applicable by Body End part number. LMartin -- Era QC			1469 FH 11/09/2020	One-Time	
	M006-01H046-041	MCR00435RW						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-452 Rev B 04/10/2018	Main Rotor Damper Body End Inspection		Complied C/W BT139-452 Part 1 INSTALLED Revision 19, Dated 07/01/2016 --			TL-132863-2016 3211.4 FH 07/11/2016	One-Time	
139-53-16-01 Rev IR 07/14/2016	STA. 1500 Doubler (Nose Avionics Compartment)		Not Complied				As Required	
STCSR03763NY Rev IR 07/19/2016	Intallation of SkyTrac ISAT-200A Airborne Position/Data Communicator (AW139)		Not Complied				As Required	
139-53-16-02 Rev IR 07/26/2016	AHRS Mount Modification		Not Complied				As Required	
139-23-16-01 Rev IR 08/09/2016	SAR Swimmer Station VOX		Not Complied				As Required	
STCSR03788NY Rev IR 08/10/2016	Install Dart Baggage Compartment Cargo Net		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-394 Rev IR 08/25/2016	AVCS Software Upgrade		Complied - N/A N/A by aircraft Serial Number. 09/01/2016 RCS -- Era QC			09/01/2016	One-Time	
SB139-237 Rev A 01/19/2018	INSTALLATION OF KIT STATIC DISCHARGE *		Not Complied					
SB139-237 PTI	INSTALLATION OF KIT STATIC DISCHARGE		Not Complied				As Required	
SB139-237 PTII	Replace Static Discharge Rope Assembly		Not Complied				As Required	
139-34-16-02 Rev IR 09/12/2016	AW139 Primus 660 WX Radar Ant. Drive Mount Mod.		Complied Completed Installation of AW139 Primus 660 WX Radar Ant. Drive Mount Mod. IAW 139-34-16-02. No defects noted. --			HWO-011409-2020 5437 FH 06/02/2020	As Required	
BT139-274 Rev IR 09/14/2016	Tail Gear Box Central Housing Dimension Check		Complied - N/A -- Era QC					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-274 PTII	Dimension Check of TGB Housings that have logged 7800 TSN		Complied - N/A Not applicable by Center Housing part number, no further action required. M. Michaelis -- Era QC			.01 FH	One-Time	
	3T6522A00246	BAX7340				08/06/2019		
BT139-274 PTI	Dimension Check of TGB housings that have not logged 7500 TSN		Complied - N/A Not applicable by Center Housing part number, no further action required. M. Michaelis -- Era QC			.01 FH	One-Time	
	3T6522A00246	BAX7340				08/06/2019		
BT139-303 Rev IR	MGB Input Modules Bearings Confirmation		Complied - N/A Not applicable by Input Module serial number. LMartin -- Era QC			--	One-Time	
09/20/2016	3K6320A00136	KHI-P42				06/09/2020		
BT139-303 Rev IR	MGB Input Modules Bearings Confirmation		Complied - N/A Not applicable by Input Module serial number. LMartin -- Era QC			--	One-Time	
09/20/2016	3K6320A00136	KHI-P44				06/09/2020		
BT139-454 Rev IR	*	KIT ICS 9000 CABIN STATION 4 P/N 4G2350F00911		Not Complied			As Required	
09/27/2016								
BT139-393 Rev IR	Sliding Passenger Door Assembly Improvement		Complied C/W BT139-393 C/W RII FOR BT139-393 FOUND SATISFACTORY C/W BT139-393 C/W RII FOR BT139-393 FOUND SATISFACTORY --			TL-174087-2019 4405.1 FH	One-Time	
09/28/2016						02/20/2019		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-78-16-00 Rev IR 09/30/2016	Engine Exhaust Ejector Special Washer & Inlet Repair		Not Complied				As Required	
	*							
BT139-422 Rev IR 10/07/2016	Emergency Medical Service (EMS) Medevac Provisions		Not Complied				As Required	
	*							
139-25-16-03 Rev IR 10/20/2016	SAR Cable Cutter Test Circuit AW139		Not Complied				As Required	
	*							
BT139-441 Rev A 03/21/2018	EGPWS Software Upgrade		Complied Complied with BT139-411 IAW SB965-1595-34-0034. Installed new label IAW SB965-1595-34-0034. --			TL-190765-2020 5271.3 FH 02/18/2020	One-Time	
BT139-063 Rev IR 11/07/2016	Modify fire panel connections IAW BT139-063		Complied - N/A Not applicable by aircraft serial number. R Sullivan -- Era QC			11/20/2018	One-Time	
BT139-466 Rev IR 12/06/2016	MAIN ROTOR (MR) SERVOACTUATOR DOWEL PINS		Complied - N/A Not applicable by serial number. LMartin -- Era QC			2992.2 FH 06/29/2021	One-Time	
	3G6730V00532	HSC238989						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-466 Rev IR 12/06/2016	MAIN ROTOR (MR) SERVOACTUATOR DOWEL PINS 3G6730V00532HSC258804		Complied Complied with per SB27-136 listed on log card.LMartin -- Era QC			Manually Updated 3605.9 FH 10/02/2019	One-Time	
BT139-466 Rev IR 12/06/2016	MAIN ROTOR (MR) SERVOACTUATOR DOWEL PINS 3G6730V00532HSC228589		Complied - N/A Not applicable by serial number, no further action required. M. Michaelis -- Era QC			2989.01 FH 01/14/2021	One-Time	
BT139-470 Rev IR 12/06/2016	Perform the detailed inspection for cracks of the tail structure assembly IAW BT139-470		Complied Inspection requirement tracked on current Era AW139 TLM Rev 08 139 TAIL ATTACH FITTING DI. 8350 L frequency never adopted. -- Era QC			Manually Updated 3211.4 FH 12/07/2016	One-Time	
BT139-440 Rev IR 12/13/2016	Primus Epic Wiring Parent		Complied					
BT139-440 PART I	Upgrade Primus Epic Wiring for Short Nose AB/AW139		Complied - N/A Part I N/A by aircraft serial number, only Part II is applicable to Long nose AW139s. RCS 12/14/2016 -- Era QC			12/14/2016	One-Time	
BT139-440 PART II	Upgrade Primus Epic Wiring for Long Nose AB/AW139		Complied C/W BT Pt II -- Castle, Deandre .			TL-174087-2019 4405.1 FH 02/18/2019	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance				Complied On TT Date	Interval Next Due
BT139-435 Rev IR 12/13/2016	Display Installation Update (Primus Epic)		Complied - N/A N/A by aircraft serial number not listed in Table 1. RCS 12/14/2016 -- Era QC				12/14/2016	One-Time
BT139-465 Rev A 01/25/2017	Inspect for and correct if necessary tail rotor driveshaft interference IAW BT139-465 Parent		Complied					
BT139-465 PART I	Inspect the tube shaft for evidence of scratches or indentations IAW BT139-465 PART I		Complied N/A by P/N N/A by P/N --				TL-167046-2018 4025.7 FH 08/29/2018	
BT139-465 PART II	Perform the retro-modification of the rear exhaust module and of the tunnel assembly IAW BT139-465 PART II		Complied N/A by aircraft s/n BT 465 PT II N/A BY A/C SERIAL NUMBER. 02-13-18 N/A by aircraft s/n --				TL-158550-2018 3503.8 FH 02/13/2018	One-Time
BT139-429 Rev IR 12/28/2016	WEIGHT EXTENSION TO 7000 KG *		Not Complied					
BT139-429 PT I	WEIGHT EXTENSION TO 7000 KG *		Not Complied					As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-429 PT II *	WEIGHT EXTENSION TO 7000 KG		Not Complied				As Required	
AD2016-26-01 Rev IR 01/31/2017	Perform hydraulic system tests IAW AD2016-26-01		Complied Performed hydraulic system tests IAW AD2016-26-01. No defects noted at this time. --			TL-145118-2017 3226.6 FH 04/20/2017	One-Time	
139-25-17-00 Rev IR 02/01/2017	Install "New Style" SART in all Era AW139 SAR aircraft.		Not Complied				As Required	
139-34-17-00 Rev IR 02/02/2017	Primus 660 WX Radar Spacer Modification		Complied Completion Installation of Primus 660 WX Radar Spacer Modification IAW 139-34-17-00. No defects noted. --			HWO-011409-2020 5437 FH 06/02/2020	As Required	
139-23-17-00 Rev IR 02/03/2017	ARINC 429 to RS232 Converter for Sky Connect		Not Complied				As Required	
SB139-442 Rev IR 03/22/2017	Deployable ELT Improvements		Complied Complied with SB139-442. --			TL-158768-2018 3518.3 FH 02/18/2018	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject		Method of Compliance				Complied On	Interval
Rev #							TT	
Eff Date	Part Number	Serial Number					Date	Next Due
SB139-215	Installation of HID Steerable Landing Lights		Not Complied					
Rev IR	*							
03/31/2017	Parent							
SB139-215 PT III	Replacement of Secondary L/H Landing Light and modification of Overhead CB Panel		Not Complied					As Required
	*							
SB139-215 PT IV	Replacement of Secondary R/H Landing Light		Not Complied					As Required
	*							
SB139-455	TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGSREPLACEMENT		Not Complied					
Rev A	*							
06/03/2021	Parent							
SB139-455 PTI	Replace Upper Deck Panel		Not Complied					As Required
	*							
ASB139-472	Main Rotor Slip Ring (FIPS) Inspection		Complied Not Applicable as FIPS kit not installed --				TL-146072-2017	One-Time
Rev IR							3230.1 FH	
05/09/2017							05/12/2017	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-468 Rev IR 05/15/2017	LEFT AND RIGHT FIRE DETECTION SYSTEM Parent		Complied					
SB139-468 PTI	Visual inspection of the Fire Detection Sensing Element for possible interference		Complied C/W SB 139-468 PT. I C/W SB 139-468 PT. I --			TL-150462-2017 3277.8 FH 08/11/2017		
SB139-468 PTII	Apply improved design for Retromod P/N 3G2610P00211.		Complied Completed RII, confirmed mechanic complied with BT139-468 IAW Leonardo Helicopters SB 139-468 PT I and PT II. No defects noted at this time. Completed RII, confirmed mechanic complied with BT139-468 --			HWO-008569-2017 3314.9 FH 11/30/2017	One-Time	
139-25-17-02 Rev IR 05/31/2017	Map Case with 28 Volt Power Bracket		Not Complied					As Required
139-25-17-01 Rev IR 05/31/2017	LifePort Med Bed Power		Not Complied					As Required
139-25-17-03 Rev IR 06/02/2017	Fabricate and install SAR Curtain Assembly		Not Complied					As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-17-04 Rev IR 07/27/2017	Install Cabin IV Rail Light SAR		Not Complied				As Required	
	*							
SB139-477 Rev IR 08/02/2017	R/H Shackle Tiedown Fittings Installation		Not Complied				As Required	
	*							
SB139-490 Rev IR 08/07/2017	MGB OIL COOLING FAN INSPECTION		Complied Complied with by PHI on Sept 4, 2017. No further action required. -- Era QC			Manually Updated -- 09/04/2017	One-Time	
	3G6320V03853 141600256							
SB139-457 Rev A 08/29/2019	Install Breeze-Eastern Single External Hoist		Not Complied				As Required	
	*							
PSEAW139/2017/583 Rev IR 10/06/2017	AW139 Tail Boom End Cone RH Panel Assy Replacement		Not Complied				As Required	
	*							
	3G5350A00135 A7/0083							
SB139-500 Rev IR 10/31/2017	Primus Epic Flight Software Release 7.12 and 7.14		Complied C/W upgrade to Primus Epic Flight Software Release 7.14 IAW SB139-500 instructions with no defects noted. Updated s/w decals IAW Era Minor 139-05-14-00 M-026 form with no defects noted. No 139-05-18- --			TL-168393-2018 4113.3 FH 09/30/2018	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
SB139-439 Rev A 09/16/2019	Install Four Axis Enhanced Flight Director Parent		Not Complied			*		
SB139-439 PART II	Install Four Axis Enhanced FD for newer models AW139s		Not Complied			*		As Required
SB139-515 Rev A 03/23/2020	Primus Epic Flight DSoftware Release 7.12 & 7.14 Upgrade Parent		Not Complied			*		
SB139-515 PART I	Software upgrade for older AB/AW139 with 4.8 Flight Software installed.		Not Complied			*		As Required
SB139-515 PART II	Software upgrade for newer AB/AW139 with 4.8 Flight Software installed.		Not Complied			*		As Required
SB139-515 PART III	Software upgrade for AB/AW139 with 5.6 Flight Software installed.		Not Complied			*		As Required

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number					Date	Next Due
SB139-515 PART IV	Software upgrade for older AB/AW139 with 6.2 or 6.5 Flight Software installed.			Not Complied			As Required	
*								
SB139-515 PART V	Software upgrade for AB/AW139 with 4.8, 5.6, 6.2, or 6.5 Flight Software installed.			Not Complied			As Required	
*								
SB139-515 PART VI	Software upgrade for older AB/AW139 with 4.8, 5.2, 5.6, 6.2, or 6.5 Flight Software installed.			Not Complied			As Required	
*								
SB139-453	LH/RH MLG Upgrade for 7000 KG IGW		Complied - N/A Not Applicable by part number MLG installed. R SullivanCurrent revision does not affect previous compliance. JFONTENOT 12/17/2019 -- Era QC			3679.4 FH		One-Time
Rev A								
05/22/2018	3G3210V00137	00575R					04/23/2018	
SB139-453	LH/RH MLG Upgrade for 7000 KG IGW		Complied - N/A Not Applicable by part number MLG installed. R SullivanCurrent revision does not affect previous compliance. JFONTENOT 12/17/2019 -- Era QC			3679.4 FH		One-Time
Rev A								
05/22/2018	3G3210V00237	00567R					04/23/2018	
STCSR00826DE	Install Sky Connect Tracker III		Not Complied					As Required
Rev IR	*							
03/26/2018								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Part Number	Subject Serial Number	Method of Compliance			Complied On TT Date	Interval Next Due	
AD2018-04-11 Rev IR 04/05/2018	AW139 TGB Central Housing Thickness Parent		Complied - N/A -- Era QC					
AD2018-04-11 (E) (1)	Dimension Check of TGB Housings that have logged 7500 TSN 3T6522A05147	TFA2574	Complied - N/A Not applicable by Center Housing Part Number, no further action required. M. Michaelis -- Era QC			.01 FH 08/06/2019	One-Time	
AD2018-04-11 (E) (2)	Dimension Check of TGB Housings that have logged 7800 TSN 3T6522A05147	TFA2574	Complied - N/A Not applicable by Center Housing Part Number, no further action required. M. Michaelis -- Era QC			.01 FH 08/06/2019	One-Time	
AD2018-04-11 (E) (3)	Do not install any TGB Central Housing unless inspection passed per BT139-274 3T6522A05147	TFA2574	Complied - N/A Not applicable by Center Housing Part Number, no further action required. M. Michaelis -- Era QC			.01 FH 08/06/2019	One-Time	
SB139-526 Rev IR 04/10/2018	MGB COOLING FAN Parent		Complied					
SB139-526 PART I	Detailed Inspection and Roughness Check 3G6320V03853	141600256	Complied Complied with by Safran Ventilation at overhaul. Part time since new: 3,993.96. -- Era QC			Manually Updated -- 06/20/2018		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-526 PART II	Remove MGB Oil Cooling Fan and return for Overhaul		Complied Complied with by overhaul JFONTENOT 02/11/2019 -- Era QC			Manually Updated		
	3G6320V03853 141600256					4169.46 FH		
						02/08/2019		
139-23-18-00	Relocate Tracker III Transceiver to Tail Boom		Not Complied					As Required
Rev IR	*							
04/17/2018								
SB139-530	REPLACEMENT OF AUTO FLIGHT TRIM ACTUATOR		Complied - N/A For compliance, see SAFRAN SB SED SB6262-22-07 compliance on currently installed Collective trim actuator p/n 3G2220V00234. JFONTENOT 05/07/2020 -- Era QC					One-Time
Rev IR						5437 FH		
06/13/2018						05/07/2020		
SED SB6262-22-07	Auto Flight Trim Actuator PN 3G2220V00234		Complied - N/A Not applicable by serial number JFONTENOT 05/16/2019 -- Era QC					One-Time
Rev IR								
06/13/2018	3G2220V00234 7191					05/16/2019		
SB139-534	STA 3120 FRAME INSPECTION		Complied - N/A STA 3120 FRAME INSPECTION IAW SB139-534 NA BY AC SN 22June 2018 -- Era QC					
Rev IR						3852.9 FH		
06/21/2018						06/22/2018		
SB139-513	Installation of Windshield washing system		Not Complied					As Required
Rev IR	*							
06/29/2018								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-62-18-00 Rev IR 07/03/2018	MR Upper Tension Link Fiberglass Plate Protection * 3G6220A00132R340		Not Complied				As Required	
SB139-489 Rev IR 07/24/2018	Installation of Kit Central Display Sirio Panel * Parent		Not Complied					
SB139-489 PT I * 	Installation of Kit Central Display Sirio Panel, structural and electrical provisions		Not Complied				As Required	
SB139-489 PT II * 	Installation of Kit Central Display Sirio Panel Equipment		Not Complied				As Required	
ASB139-533 Rev IR 08/30/2018	EFS AFT FLOAT ASSY INFLATION SYSTEM RESET PROCEDURE 3G9560V01532377		Complied Complied with per SB139-25-002. LMartin -- Era QC			Manually Updated 2315.4 FH 11/12/2018	One-Time	
ASB139-533 Rev IR 08/30/2018	EFS AFT FLOAT ASSY INFLATION SYSTEM RESET PROCEDURE 3G9560V01432216		Complied Complied with by Aerosekur on their Work Order 2018SI056/4801617476 on Oct 3, 2018. Part time since new: 9.55. M. Michaelis -- Era QC			Manually Updated -- 10/03/2018	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
SB139-498 Rev IR 09/06/2018	NLG SERVICING PLATE REPLACEMENT 3G3220V0013500468		Complied - N/A Not applicable by part number NLG installed. R Sullivan -- Era QC			09/18/2018		One-Time
SB139-528 Rev IR 11/06/2018	MAIN ROTOR SLIP RING CONNECTOR MODIFICATION		Complied N/A by A/C Configuration --			TL-170425-2018 4179.9 FH 11/16/2018		One-Time
SB139-499 Rev IR 12/17/2018	ROTORS ICE PROTECTION CABLES CONNECTORS		Complied n/a by p/n --			TL-171634-2018 4283.8 FH 12/16/2018		One-Time
ASB139-569 Rev B 07/25/2022	Set to as required, precluding AD 2021-18-11. Tail Rotor Slider Assy Detailed Inspection 3G6430A00131K15		Complied C/W T/R slider insp per AW139 MM 64, found satisfactory. -- Precluded - AD2021-18-11 - Inspection of the tail rotor Slider Assembly for corrosion.			TL-220977-2022 2442.3 FH 01/29/2022		As Required
SB139-375 Rev IR 01/29/2019	Auxiliary circuit-breaker panel modifications Parent		Complied					
SB139-375 PT I	AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS		Complied Inspected per SB139-375PT I. Found to have the correct nuts installed. --			HWO-011449-2020 5437 FH 08/11/2020		One-Time

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-375 PTII	AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS		Complied Verified there was no chafing with Aux wiring harness with previous routing. Completed installation of new routing for the Aux Circuit Breaker Panel. All work accomplished IAW the latest revision of S --			HWO-011449-2020 5437 FH 08/13/2020	One-Time	
SB139-375 PTIII	AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS		Complied Verified there was no interference of the Aux circuit breaker panel with the Alternate Static Port. All work accomplished IAW the latest revision of SB139-375 PT. III. No defects noted. --			HWO-011449-2020 5437 FH 08/13/2020	One-Time	
SB139-375 PTIV	AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS		Complied Installed 7 new screws P/N. MS51958-63B and Rubber cover P/N. 3G2490A00551 per BT139-375 PTIV. --			HWO-011449-2020 5437 FH 06/01/2020	One-Time	
ASB139-571 Rev IR 02/01/2019	DUPLEX BEARING P/N 3G6430V00153 RECALL 3G6430V00153 21231		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC -- 06/24/2022				One-Time	
SB139-531 Rev IR 02/14/2019	SDU SUPPORT IMPROVEMENT		Complied N/A by acft S/N and configuration. --			TL-180508-2019 4683.1 FH 07/20/2019	One-Time	
SB139-566 Rev IR 02/14/2019	EWP/CDU SOFTWARE UPGRADE		Complied N/A by aircraft serial number. --			TL-180399-2019 4673.1 FH 07/18/2019	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
139-71-19-00 Rev IR 03/27/2019	Installation of Wear Plates on AW139 Top Cowling Sliding Rails		Complied Inspected aircraft and found Installation of Wear Plates on AW139 Top Cowling Sliding Rails previously installed IAW ERA Minor 139-71-19-00. --			HWO-011409-2020 5437 FH 07/13/2020	As Required	
AD2019-05-03 Rev IR 03/28/2019	T/R Duplex Bearings (Remove from Service)		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			-- 06/24/2022	One-Time	
SB139-385 Rev IR 03/29/2019	INSTALLATION OF KIT VIDEO MODULE INTERFACE		Not Complied				As Required	
ELT REG RENEWAL Rev IR 04/25/2019	Renewal of ELT/ADELT Registration on the NOAA website.		Complied Complied with ELT registration renewal in NOAA website. -- Era QC			Manually Updated 7437.9 FH 09/09/2022	24 MO 09/09/2024	
PLB REG RENEWAL Rev IR 04/25/2019	Renewal of PLB Registration on the NOAA website.		Complied Complied with PLB registration renewal in NOAA website. R. Rowland 12/29/2022 -- Era QC			Manually Updated 1009 FH 12/29/2022	24 MO 12/29/2024	
PLB REG RENEWAL Rev IR 04/25/2019	Renewal of PLB Registration on the NOAA website.		Complied Complied with PLB registration renewal in NOAA website. R. Rowland 12/29/2022 -- Era QC			Manually Updated 1914.8 FH 12/29/2022	24 MO 12/29/2024	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
BT139-525 Rev A 11/21/2019	INSTALLATION OF INFLATION SERVICE CHARTS 3G9560V01432216		Complied Inspected float assy found service chart 304458B installed --			TL-194289-2020 98.55 FH 05/11/2020	One-Time	
BT139-593 Rev A 06/14/2019	Engine Mounting Rods Replacement		Complied n/a by p/n n/a by p/n see ERA FCD 000337 for details. 06-27-19 --			TL-179477-2019 4613.1 FH 06/28/2019	One-Time	
BT139-525 Rev A 11/21/2019	INSTALLATION OF INFLATION SERVICE CHARTS 3G9560V01532377		Complied Complied with per SB139-25-001 listed on log card. LMartin -- Era QC			Manually Updated 2315.4 FH 11/12/2018	One-Time	
139-23-19-00 Rev IR 06/18/2019	28VDC UTILITY CONNECTOR J158 AND CONNECTOR MOUNTING BRACKET INSTALLATION. *		Not Complied				As Required	
139-25-19-00 Rev IR 06/24/2019	Spectrum Aeromed Dual O2 Box installation *		Not Complied				As Required	
AD2019-12-06 Rev IR 07/30/2019	AW139 #1 Tail rotor driveshaft Parent		Complied					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2019-12-06 PTI	Inspect the #1 Tail rotor driveshaft		Complied - N/A na by ser. no. complied with on ERATL-181401-2019 -- Era QC			4728.6 FH 08/07/2019		
AD2019-12-06 PTII	Rear exhaust module and tunnel alter and re-identify		Complied N/A by A/C S/N --			TL-179877-2019 4637.6 FH 07/07/2019	One-Time	
AD2019-12-15 Rev IR 08/02/2019	139 MLG Shock Absorber Screw Replacement 3G3210V00137 00575R		Complied Complied with by previous accomplishment of BT139-397 JFONTENOT 07/02/2019 -- Era QC			Manually Updated 4626.8 FH 07/02/2019	One-Time	
AD2019-12-15 Rev IR 08/02/2019	139 MLG Shock Absorber Screw Replacement 3G3210V00237 00567R		Complied Complied with by previous accomplishment of BT139-397 JFONTENOT 07/02/2019 -- Era QC			Manually Updated 4626.8 FH 07/02/2019	One-Time	
139-25-19-01 Rev IR 08/06/2019	Rescue basket housing electrical outlets and breakers installation and static inverter installation *		Not Complied				As Required	
BT139-316 Rev IR 09/19/2019	ANCHOR NUTS IN FUEL TANK AREA		Complied N/A by A/C S/N N/A --			TL-183855-2019 4864.7 FH 09/25/2019	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance						TT	
Eff Date	Part Number	Serial Number					Date	Next Due
SB139-590		Installation of Kit DF	Not Complied					
Rev IR	*							
09/24/2019	Parent							
SB139-590 PT I		Perform the installation of DF complete provision P/N 4G3450A01011 or 4G3450A01012	Not Complied					
	*							
SB139-590 PT II		Perform DF Installation P/N 4G3450A0111	Not Complied					
	*							
139-23-19-01		AW139 Cabin ICS System Insatllation	Not Complied					
Rev IR	*							
11/01/2019								
139-34-19-00		AW139 EFB electrical provisions installation	Complied Completed AW139 EFB electrical installation IAW ERA drawing 139-34-19-00. No defects noted. --				HWO-011408-2020	As Required
Rev IR							5437 FH	
11/11/2019							08/17/2020	
SB139-475		INSTALLATION OF KIT ICS 9000 CABIN STATION 4	Not Complied					
Rev IR	*							
12/02/2019								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-594 Rev IR 12/17/2019	INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS Parent		Complied					
SB139-594 PT1	INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS		Complied C/W SB139-594 Pt. 1. Correct parts installed. C/W SB139-594 Pt. 1. Correct parts installed. --			TL-188005-2019 5096 FH 12/20/2019	One-Time	
SB139-594 PT2	INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS AND REPLACEMENT IF P/N NAS6612D56 BOLTS ARE INSTALLED		Complied N/A by installed part number. --			TL-189770-2020 5221 FH 01/27/2020	One-Time	
ASB139-610 Rev IR 12/17/2019	EMERGENCY FLOTATION SYSTEM, FLOAT SUPPLY HOSE INSPECTION OF		Complied N/A by p/n installed as per LCH inspection dept.12-18-19 --			TL-187888-2019 5089.3 FH 12/18/2019	One-Time	
ASB139-609 Rev A 04/13/2021	MGB BEARING LOCK-NUT REPLACEMENT 3G6320A00134 AW1054		Not Complied				One-Time 6000 FH	
ASB139-614 Rev IR 12/19/2019	FIRE EXTINGUISHER INSPECTION AND REPLACEMENT		Complied ASB is N/A by A/C Configuration. --			TL-188005-2019 5096 FH 12/20/2019	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-34-19-01 Rev IR 12/31/2019	AW139 EFB fixed provisions installation		Complied Verified installation of fixed provisions. The work is satisfactory. Verified installation of fixed provisions. The work is satisfactory. Contacted type inspector for completion of FAA form 337. --			HWO-011409-2020 5437 FH 08/11/2020	As Required	
MPN/2020/137 Rev IR 01/09/2020	AW139 Tail Boom End Cone LH Panel Assy Replacement		Not Complied				As Required	
SB139-524 Rev A 01/27/2022	DART LIFERAFT RESERVOIR ASSEMBLY ALIGNMENT LABEL POSITIONING		Complied N/A due to not installed --			TL-191179-2020 2028.5 FH 02/28/2020	One-Time	
SB139-612 Rev IR 02/19/2020	FAST ROPING DECAL REPLACEMENT		Complied Not applicable, fast rope kit not installed. --			TL-190828-2020 5279.5 FH 02/20/2020	One-Time	
SB139-037 Rev IR 02/27/2020	NLG ACTUATOR FITTING RETRO MODIFICATION		Complied N/A by aircraft S/N. --			TL-191377-2020 5311.1 FH 03/03/2020	One-Time	
139-25-20-00 Rev IR 03/16/2020	AW139 Upper Seat Cushions With Soft Back Fairings Installation.		Complied Installed AW139 Upper Seat Cushions With Soft Back Fairings as required IAW EO 139-25-20-00. Completed a M-005 and contacted the type inspector. --			HWO-011412-2020 5437 FH 07/15/2020	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-20-01 Rev IR 03/17/2020	AW139 Flight Crew Separation Curtain Installation		Complied Install Flight Crew Separation Curtain IAW Era Drawing#139-25-20-01 and attached M-026.03-29-2020 --			TL-192481-2020 5379.1 FH 03/29/2020	As Required	
SB139-595 Rev IR 03/26/2020	COCKPIT DOOR EMERGENCY RELEASE MECHANISM CHECK		Complied SB is NA by A/C configuration --			TL-192895-2020 5400 FH 04/09/2020	One-Time	
SB139-570 Rev IR 04/09/2020	*	FLOAT ASSY NEW GAUGE INSTALLATION	Not Complied				As Required	
		3G9560V01532 377						
SB139-570 Rev IR 04/09/2020		FLOAT ASSY NEW GAUGE INSTALLATION	Not Complied				As Required	
		3G9560V01052 781						
SB139-570 Rev IR 04/09/2020		FLOAT ASSY NEW GAUGE INSTALLATION	Not Complied				As Required	
		3G9560V01052 1357						
SB139-570 Rev IR 04/09/2020		FLOAT ASSY NEW GAUGE INSTALLATION	Not Complied				As Required	
		3G9560V01432 216						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-537 Rev IR 04/29/2020	DART EMERGENCY FLOTATION LIFE RAFT IMPROVEMENT		Complied SB139-537 is Not Applicable, 18 pax and 15 pax liferaft kits p/n 4G9560F00211 and 4G9560F00111 not installed. --			TL-193762-2020 5426.5 FH 04/29/2020	One-Time	
SB139-608 Rev IR 05/14/2020	INSPECTION OF BL 275 (LH/RH) AT STA 3500		Complied Does not apply to this S/N aircraft --			HWO-011463-2020 5437 FH 05/18/2020	One-Time	
139-71-20-00 Rev IR 06/02/2020	Engine cowling vent screen repair		Not Complied				As Required	
SB139-605 Rev A 03/09/2021	ELECTRICAL WHEEL BRAKE CABLE ASSY REPLACEMENT		Complied The SB is Not Applicable due to electrical powered parking brake module kit P/N 3G3240F00111 (SB139-137) not installed. Compliance recorded on Original issue of the SB, no further action required for --			HWO-011484-2020 5437 FH 06/08/2020	One-Time	
ASB139-637 Rev A 10/21/2020	HOIST CABLE CUTTER FRAME INSTALLATION		Complied - N/A Not applicable due to Goodrich hoist assy not installed at this time. JFONTENOT 10/26/2020 -- Era QC			5517.6 FH 10/26/2020	One-Time	
SB139-471 Rev IR 06/24/2020	SOFT COVER FAIRING AEROSEKUR LIFERAFT RETROMOD		Complied Not applicable, Aerosekur liferafts not installed --			HWO-011554-2020 5437 FH 07/06/2020	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-585 Rev IR 06/25/2020	(Aerazur) RIGHT AFT FLOAT INSPECTION AND BAGGAGE FLOOR PANELRETROMODIFICATION		Complied Not applicable, Aerazur floats kit P/N 3G9560F00212 not installed --			HWO-011554-2020 5437 FH 07/06/2020	One-Time	
STCSR04481AT Rev IR 07/20/2020	Installation of Luminator Aerospace LS400 Searchlight		Not Complied				As Required	
ASB139-633 Rev A 09/02/2020	RESTRICTION IN FORWARD FACING PASSENGER SEATS INSTALLATION		Complied Not applicable because of aircraft seat configuration. Compliance recorded on Initial Release of the service bulletin. JFONTENOT 09/04/2020 --			HWO-011656-2020 5437 FH 08/10/2020	One-Time	
ASB139-648 Rev A 02/15/2021	LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT		Complied Not applicable by life raft configuration. NO further action required. Compliance recorded on Original issue of service bulletin, no further action required. JFONTENOT 02/16/2021 --			HWO-011660-2020 5437 FH 08/12/2020	One-Time	
139-52-18-00 Rev IR 08/12/2020	Rotor Brake Access Door Removal		Not Complied				As Required	
139-25-20-02 Rev IR 08/13/2020	L/H & R/H Station 5700 Access Panels		Complied Complied with on VP-000532-2020, HWO-011409-2020, NST-186881-2020. JFONTENOT -- Era QC			Manually Updated 5437 FH 08/18/2020	As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2020-15-18 Rev IR 09/03/2020	Uncommanded deployment of the EFS due to improper accomplishment of the reset procedure of the SMA 3G9560V01532377		Complied For compliance see ASB139-533, C. Hine -- Era QC			Manually Updated 3159.7 FH 07/30/2020	One-Time	
AD2020-15-18 Rev IR 09/03/2020	Uncommanded deployment of the EFS due to improper accomplishment of the reset procedure of the SMA 3G9560V01432216		Complied For compliance see ASB139-533, C. Hine -- Era QC			Manually Updated 115.05 FH 07/30/2020	One-Time	
SB139-635 Rev IR 09/15/2020	TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS		Complied C/W TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS IAW SB139-635 --			TL-205003-2021 5723.3 FH 01/18/2021	One-Time	
STCSR01064DE Rev IR 09/22/2020	Installation of Axnes PNG Wireless Intercom Extension System		Not Complied				As Required	
AD2020-19-04 Rev IR 10/15/2020	MGB Input Module Replacement 3K6320A00136KHI-P44		Complied - N/A Not applicable by serial number. JFONTENOT 09/11/2020 -- Era QC			.1 FH 09/11/2020	One-Time	
AD2020-19-04 Rev IR 10/15/2020	MGB Input Module Replacement 3K6320A00136KHI-P42		Complied - N/A Not applicable by serial number. JFONTENOT 09/11/2020 -- Era QC			.1 FH 09/11/2020	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-512 Rev IR 10/21/2020	TAIL PLANE FITTING BUSHINGS INSPECTION 3G5351A01533 DEM00157		Complied - N/A Not applicable by part number. JFONTENOT 10/22/2020 -- Era QC			5506 FH 10/22/2020	One-Time	
SB139-512 Rev IR 10/21/2020	TAIL PLANE FITTING BUSHINGS INSPECTION 3G5351A01433 DEM00226		Complied - N/A Not applicable by part number. JFONTENOT 10/22/2020 -- Era QC			5506 FH 10/22/2020	One-Time	
SB139-634 Rev IR 10/21/2020	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER CONVERSION TO P/N 965-1595-036		Complied See SB 965-1595-34-0079 for compliance of SB SB139-634 -- Era QC			Manually Updated 7491.3 FH 12/14/2022	As Required	
SB139-655 Rev IR 11/05/2020	MGB INPUT MODULES MARKING 3K6320A00136 KHI-P42		Complied - N/A Not applicable by serial number. JFONTENOT 11/06/2020 -- Era QC			117.2 FH 11/06/2020	One-Time	
SB139-655 Rev IR 11/05/2020	MGB INPUT MODULES MARKING 3K6320A00136 KHI-P44		Complied - N/A Not applicable by serial number. JFONTENOT 11/06/2020 -- Era QC			117.2 FH 11/06/2020	One-Time	
SB139-629 Rev A 04/20/2021	FORWARD FLOATS COVERS UPGRADE		Complied N/A by PN, Not applicable due to Dart floats not installed, compliance recorded on initial release of bulletin, no further action required. JFONTENOT --			TL-203154-2020 5606.5 FH 12/05/2020	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
ASB139-654 Rev IR 12/02/2020	MAIN ROTOR SWASHPLATE BOOT INSPECTION Parent		Complied					
ASB139-654 PT1	MAIN ROTOR SWASHPLATE BOOT INSPECTION		Complied c/w insp --			TL-203154-2020 5606.5 FH 12/05/2020	One-Time	
ASB139-654 PT2	Set to as required for preclusion to AD2021-13-21 PTII. MAIN ROTOR SWASHPLATE BOOT INSPECTION		Complied -- Precluded - AD2021-13-21 PTII - Main Rotor Swashplate Boot Recurring Inspection			TL-231641-2022 7466 FH 09/15/2022	As Required	
ASB139-661 Rev B 05/09/2022	OVERHEAD PANEL INSPECTION Parent		Complied					
ASB139-661 PT2	OVERHEAD PANEL INSPECTION		Complied -- Precluded - AD2021-22-02 (G)(2) - Electrical Power Overhead Panel Inspection			TL-227173-2022 7202.1 FH 06/16/2022	As Required	
ASB139-661 PT1	OVERHEAD PANEL INSPECTION		Complied C/W OVERHEAD PANEL INSPECTION IAW ASB139-661 PT1 --			TL-206375-2021 5840 FH 02/22/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
ASB139-662 Rev IR 02/15/2021	LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT		Complied N/A by PN --			TL-206225-2021 5825.8 FH 02/18/2021	One-Time	
SB139-463 Rev IR 02/25/2021	INSTALLATION OF KIT CENTRAL DISPLAY		Complied - N/A SB not applicable per ACFT S/N effectivity -- Era QC			6646 FH 12/07/2021		
AD2021-04-01 Rev IR 03/26/2021	RESTRICTION IN FORWARD FACING PASSENGER SEATS INSTALLATION		Complied Not applicable by seat configuration -- Abousoud, Jad N.			TL-207545-2021 5939.8 FH 03/23/2021	One-Time	
AD2021-03-07 Rev IR 04/01/2021	ENGINE MOUNTING RODS REPLACEMENT		Complied N/A Previously complied with -- Comeaux, Christopher J.			TL-206663-2021 5870.3 FH 03/02/2021	One-Time	
139-33-21-00 Rev IR 04/21/2021	Cabin Task Lights, AW139 SAR		Not Complied				As Required	
AD2021-05-21 Rev IR 05/07/2021	Main Rotor Scissor Bearing		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			-- 08/19/2022	One-Time	
	3G6230A00932	AW6424						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2021-05-21 Rev IR 05/07/2021	Main Rotor Scissor Bearing 3G6230A00932 AW6426		Complied - N/A Not applicable by part number. LMartin -- Era QC			-- 07/13/2022	One-Time	
AD2021-07-13 Rev IR 05/11/2021	Superseded by AD2024-26-02 - Pacific Scientific Company rotary buckle assemblies(cracked buckle handles) ✱		Not Complied				One-Time	
SB139-674 Rev IR 06/16/2021	Aircraft Survivability Equipment (ASE) Retromod		Complied SB is N/A by A/C configuration. -- Mulderick, Kyle E.			TL-211354-2021 6189.3 FH 06/22/2021	One-Time	
AD2021-12-10 Rev IR 06/22/2021	Aerolite Stretcher Placards and Markings		Complied N/A stretcher not installed --			TL-210923-2021 6159.3 FH 06/12/2021	One-Time	
AD2021-13-21 PTII Rev IR 07/12/2021	Main Rotor Swashplate Boot Recurring Inspection		Complied c/w insp c/w insp -- Rahmaty, Mazyar .			TL-231641-2022 7466 FH 09/15/2022	50 FH 7516 FH	
AD2021-13-21 PTI Rev IR 07/12/2021	Main Rotor Swashplate Boot Inspection		Complied c/w imsp c/w imsp -- Rahmaty, Mazyar .			TL-211884-2021 6221.6 FH 07/04/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2021-13-01 Rev IR 08/03/2021	One-Time inspection of the main rotor (M/R) slip ring		Complied NA, M/R slip ring P/N 4G6220V00151 is not installed NA, M/R slip ring P/N 4G6220V00151 is not installed --			TL-211758-2021 6216 FH 07/01/2021	One-Time	
EASB139-679 AIRFRAME Rev IR 08/05/2021	Hoist Rated Load Check		Complied N/A Breeze Hoist not installed --			TL-213546-2021 6270.2 FH 08/09/2021	One-Time	
AD2021-15-09 Rev IR 08/27/2021	FLOAT CONTROL PANEL UPGRADE 3G9560V00558 S09646205		Complied - N/A Not applicable by part number. -- Era QC			285.5 FH 07/23/2021	One-Time	
SB139-660 Rev IR 09/27/2021	Primus Epic Flight Software release upgrade from Phase 7.12 & 7.14 to Phase 7.12.2 & 7.14.2		Not Complied				As Required	
SB139-671 Rev IR 10/11/2021	FIRE EXTINGUISHER REPLACEMENT		Complied N/A by part number --			TL-216411-2021 6472.5 FH 10/11/2021	One-Time	
AD2021-19-03 Rev IR 11/01/2021	Primus Epic System Software Update		Complied SB139-500 previously complied with. -- Mulderick, Kyle E.			TL-217340-2021 6516.8 FH 11/01/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2021-18-11 Rev IR 11/01/2021	Inspection of the tail rotor Slider Assembly for corrosion. 3G6430A00131K15		Complied C/W T/R slider insp per AW139 MM 64, found satisfactory. -- Rivera, Sergio .			TL-220977-2022 2442.3 FH 01/29/2022	One-Time	
ASB139-686 Rev IR 11/08/2021	Perform a detailed inspection of the TGB fitting. 3G5351A01152AVM-439		Complied No cracks noted. No cracks noted. No cracks noted. --			TL-217947-2021 5255.8 FH 11/14/2021	One-Time	
AD 2021-22-13 Rev IR 11/17/2021	Rated load check on Breeze Eastern hoist		Complied N/A Breeze hoist not installed. --			TL-217947-2021 6566.4 FH 11/14/2021	One-Time	
AD2021-22-07 Rev IR 11/18/2021	Umlaut Engineering (previously P3 Engineering) Hand Held fire extinguishers		Complied AD is N/A by extinguishers installed. AD is N/A by extinguishers installed. AD is N/A by extinguishers installed. -- Mulderick, Kyle E.			TL-218209-2021 6594.9 FH 11/20/2021	One-Time	
AD2021-20-12 Rev IR 11/22/2021	Emergency Flotation System (EFS) float compartment to inflate during maintenance of the EFS.		Complied AD is N/A by P/N installed on A/C. -- Mulderick, Kyle E.			TL-217340-2021 6516.8 FH 11/01/2021	One-Time	
SB139-696 Rev IR 12/09/2021	MAIN GEAR BOX REMARKING 3G6320A00134AW1054		Complied SB139-696 Not applicable by MGB S/N -- Era QC			Manually Updated 1218.5 FH 12/09/2021	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2021-22-02 Rev IR 01/03/2022	Electrical Power Overhead Panel Inspection Parent		Complied					
AD2021-22-02 (G)(1)	Electrical Power Overhead Panel Inspection		Complied Previously complied with IAW ASB139-661 -- Era QC			Manually Updated 6623.8 FH 11/30/2021	One-Time	
AD2021-22-02 (G)(2)	Electrical Power Overhead Panel Inspection		Complied Complied with overhead panel wiring inspection IAW AD2021-22-02 Para. G ref EASA AD2021-0044 Para. 2 -- Schwind, Michael J.			TL-227173-2022 7202.1 FH 06/16/2022	12 ME 06/30/2023	
AD2021-23-22 Rev IR 01/18/2022	Main Rotor Damper Inspection 3G6220V01353 MCR6442		Complied AD2021-23-22 N/A BY P/N -- Era QC			Manually Updated 2227.5 FH 01/24/2022	One-Time	
AD2021-23-22 Rev IR 01/18/2022	Main Rotor Damper Inspection 3G6220V01353 MCR5012		Complied AD2021-23-22 N/A BY P/N -- Era QC			Manually Updated 4013.7 FH 01/24/2022	One-Time	
AD2021-23-22 Rev IR 01/18/2022	Main Rotor Damper Inspection 3G6220V01353 MCR5278		Complied AD2021-23-22 N/A BY P/N -- Era QC			Manually Updated 2580.5 FH 01/24/2022	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2021-23-22 Rev IR 01/18/2022	Main Rotor Damper Inspection 3G6220V01353MCR5223		Complied AD2021-23-22 N/A BY P/N -- Era QC			Manually Updated 1091.3 FH 01/24/2022	One-Time	
AD2021-23-22 Rev IR 01/18/2022	Main Rotor Damper Inspection 3G6220V01353MCR5574		Complied AD2021-23-22 N/A BY P/N -- Era QC			Manually Updated 4068.7 FH 01/24/2022	One-Time	
SB139-539 Rev IR 01/26/2022	TRDL BEARING SUPPORT PANEL REINFORCEMENT Parent		Complied - N/A -- Era QC					
SB139-539 PT I	TRDL BEARING SUPPORT PANEL REINFORCEMENT 3T6510A00444TBF8713		Complied - N/A Not applicable by part number, no further action required. M. Michaelis -- Era QC			3036.6 FH 05/28/2022		
SB139-539 PT II	TRDL BEARING SUPPORT PANEL REINFORCEMENT 3G5350A00135A7/0083		Complied - N/A Not applicable by bearing P/N -- Era QC			6804.7 FH 01/28/2022	One-Time	
SB139-539 PT III	TRDL BEARING SUPPORT PANEL REINFORCEMENT 3G5350A00135A7/0083		Complied - N/A Not applicable by bearing P/N -- Era QC			6804.7 FH 01/27/2022	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2022-01-03 Rev IR 03/07/2022	Umlaut Engineering GmbH (Previously P3 Engineering GmbH) HAFEX (Halon-Free) Hand-Held Fire Extinguishers		Complied n/a by p/n of fire extinguisher installed n/a by p/n of fire extinguisher installed n/a by p/n of fire extinguisher installed -- Fucella, Justin T.			TL-222509-2022 6918 FH 03/07/2022	One-Time	
AD2022-02-12 Rev IR 03/17/2022	AMPI Time Limits Maintenance Checks		Complied c/w insp -- Rahmaty, Mazyar .			TL-221708-2022 6884.6 FH 02/16/2022	One-Time	
SB139-406 Rev A 03/18/2022	External Video Camera Kit Installation		Not Complied				As Required	
AD2022-07-01 Rev IR 05/09/2022	LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT		Complied N/A due to part number not installed -- Comeaux, Christopher J.			TL-223905-2022 7011.3 FH 04/08/2022	One-Time	
AD2022-05-10 AIRFRAME Rev IR 04/20/2022	Hoist Load Check Inspection		Complied n/a hoist not installed n/a hoist not installed n/a hoist not installed n/a hoist not installed n/a hoist not installed n/a hoist not installed -- Rahmaty, Mazyar .			TL-224165-2022 7033.2 FH 04/14/2022	One-Time	
139-25-22-00 Rev IR 05/17/2022	Zephyr Axelcut Installation		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number						Next Due
STCSR04718NY	Installation of RDR-7000 Weather Radar		Not Complied					As Required
Rev IR	*							
06/17/2022								
139-25-22-01	Installation of the Mission Console Kit		Not Complied					As Required
Rev IR	*							
07/18/2022								
EASB139-725	Tail Rotor Duplex Bearing Inspection and Replacement		Partially Complied					
Rev A	*							
08/09/2022	Parent							
EASB139-725 PT I & PT II	Tail Rotor Duplex Bearing Inspection and Replacment		Complied - N/A EASB139-725 PT I and PT II not applicable as company FCD covered all applicable replacements. No action required with Rev. A of this EASB. -- Era QC					--
	3G6430V00153	21231						07/25/2022
EASB139-725 PT III	Tail Rotor Duplex bearing inspection and replacement		Not Complied					5 FH
	*							
	3G6430V00153	21231						2405 FH
EASB139-725 PT IV	Tail Rotor Duplex bearing inspection and replacement		Not Complied					One-Time
	*							
	3G6430V00153	21231						2400 FH

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
ASB139-724 Rev B 09/29/2022	*	Tail Rotor Damper Bracket Inspection 3G6420A06131 AAB0131	Not Complied Precluded - AD2024-17-07 - Tail Rotor Damper Bracket Inspection				6 MO 11/19/2022	
ASB139-724 Rev B 09/29/2022		Tail Rotor Damper Bracket Inspection 3G6420A06131 AAB0120	Not Complied Precluded - AD2024-17-07 - Tail Rotor Damper Bracket Inspection				6 MO 11/19/2022	
AD2022-11-20 Rev IR 07/27/2022		Tail Rotor Gearbox fitting inspection 3G5351A01152 AVM-439	Complied See ASB139-686 for compliance information. M. Michaelis -- Era QC	Manually Updated 5909.1 FH 06/22/2022	One-Time			
ASB139-724 Rev B 09/29/2022	*	Tail Rotor Damper Bracket Inspection 3G6420A06131 AAB0118	Not Complied Precluded - AD2024-17-07 - Tail Rotor Damper Bracket Inspection				6 MO 11/19/2022	
ASB139-724 Rev B 09/29/2022		Tail Rotor Damper Bracket Inspection 3G6420A06131 AAB0121	Not Complied Precluded - AD2024-17-07 - Tail Rotor Damper Bracket Inspection				6 MO 11/19/2022	
139-23-22-00 Rev IR 09/16/2022		Convert NAT FM System to TiL FM System	Not Complied	As Required				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
139-33-22-00 Rev IR 09/20/2022	Logo Lights, AW139		Not Complied					As Required
PSE/TQ/2022/82336 Rev IR 09/30/2022	FCD-000471-2022 corrective actions (DC supply cable routing / collective torque tube C3)		Not Complied					As Required
SB139-672 Rev IR 10/03/2022	Visual Inspection and Modification of Number 4 Hydraulic Pump Line		Not Complied					
SB139-672 PT I	Visual inspection of Number 4 Hydraulic Pump Line		Not Complied					One-Time 04/01/2023
SB139-672 PT II	Modification of Number 4 Hydraulic Pump Line		Not Complied					One-Time 10/03/2023
EASB139-731 Rev IR 10/11/2022	FORWARD CABIN ROOF CEILING HARNESS INSPECTION		Not Complied					

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number	Method of Compliance	Complied On TT Date	Interval Next Due				
EASB139-731 PT I * 	FORWARD CABIN ROOF CEILING HARNESS INSPECTION	Not Complied		One-Time 7501.3 FH				
EASB139-731 PT II * 	FORWARD CABIN ROOF CEILING HARNESS INSPECTION	Not Complied		One-Time 7516.3 FH				
SB139-728 Rev IR 10/11/2022 *	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS Parent	Not Complied						
SB139-728 PT I * 	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS 3G6430V00153 21231	Not Complied		99 MO 12/11/2022				
SB139-728 PT II * 	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS 3G6430V00153 21231	Not Complied		100 FH 1250 FH				
SB139-728 PT III * 	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS 3G6430V00153 21231	Not Complied		300 FH 1250 FH				

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number						Next Due
139-25-22-02		Removal of FLIR Main Harness CEU to Turret due to ITAR	Not Complied					As Required
Rev IR	*							
11/15/2022								
AD2022-22-03		FORWARD CABIN ROOF CEILING HARNESS INSPECTION	Not Complied					
Rev IR	*							
11/17/2022		Parent						
AD2022-22-03 (G)(1)		FORWARD CABIN ROOF CEILING HARNESS INSPECTION	Not Complied					One-Time
	*							7501.3 FH
AD2022-22-03 (G)(2)		FORWARD CABIN ROOF CEILING HARNESS INSPECTION	Not Complied					One-Time
	*							7516.3 FH
139-25-22-03		Rescue Hoist Operator Panel Removal	Not Complied					As Required
Rev IR	*							
12/13/2022								
SB22-4		Replacement of Dart Pull Cables with S/N CH022456 to CH108632 or VT255863 to VT255868	Not Complied					One-Time
Rev IR	*							
01/01/2023								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-25-23-00 Rev IR 01/12/2023	* 645.1001	Installation of PLB in Dart Life Raft 07004	Not Complied				As Required	
139-25-23-00 Rev IR 01/12/2023	* 645.1002	Installation of PLB in Dart Life Raft 13003	Not Complied				As Required	
NSI-13233 Rev 5 10/23/2023	* 	Nova Systems Star Safire 380-HDc	Not Complied				As Required	
NSI-13237 Rev 6 10/24/2023	* 	Nova Systems ViDAR Installation	Not Complied				As Required	
AD2022-27-03 Rev IR 01/31/2023	* 3G6320A00134	AMOC MGB Lock Nut Replacement AW1054	Not Complied AMOC				One-Time 8054.3 FH	
SB139-733 Rev IR 02/02/2023	* 	Inspection of Sealant of Rigid Covers of Emergency Flotation System	Not Complied				One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
NSI-13238 Rev 4 09/06/2023	Nova Systems AIMS-FMS Integration		Not Complied					As Required
	*							
NSI-13664 Rev 8 11/15/2023	Nova Systems FlightCell DZMx Satcom Installation		Not Complied					As Required
	*							
NSI-13234 Rev 10 10/30/2023	Nova Systems Core Mission System Installation		Not Complied					As Required
	*							
NSI-13235 Rev 6 10/23/2023	Nova Systems Communications (Tactical Radio) Installation		Not Complied					As Required
	*							
139-25-23-01 Rev IR 03/14/2023	SAR Cabin Box Installation		Not Complied					As Required
	*							
AD2023-03-03 Rev IR 03/23/2023	Tail Rotor - Duplex Bearings - Inspection / Replacement		Partially Complied					
	*							
	Parent							

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
AD2023-03-03 PT I & PT II	Tail Rotor Duplex bearing inspection and replacement		Complied - N/A AD2023-03-03 PT I and PT II and EASB139-725 PT I and PT II not applicable as company FCD covered all applicable replacements. -- Era QC			127.2 FH		
	3G6430V00153	21231				03/02/2023		
AD2023-03-03 PT III	Tail Rotor Duplex bearing inspection and replacement		Not Complied				5 FH	
*	3G6430V00153	21231					2522.2 FH	
AD2023-03-03 PT IV	Tail Rotor Duplex bearing inspection and replacement		Not Complied				One-Time	
*	3G6430V00153	21231					2400 FH	
EASB139-754	Main Rotor P/C Link Upper Rod End Assy Inspection		Not Complied					
Rev IR	*							
03/31/2023	Parent							
EASB139-754 PT I & PT III	Inspection and marking of All AW139 with Main Rotor P/C Link Upper Rod End Assy installed on aircraft		Not Complied				One-Time	
*								
ASB139-734	Life Raft Inflation System Replacement		Complied - N/A Verified ASB139-734 is not applicable by Life Raft Part Number. Dart system installed. -- Era QC				One-Time	
Rev A						5093.3 FH		
04/28/2023	645.1002	13003				04/13/2023		

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
ASB139-734 Rev A 04/28/2023	Life Raft Inflation System Replacement 645.100107004		Complied - N/A Verified ASB139-734 is not applicable by Life Raft Part Number. Dart system installed. -- Era QC			3091.4 FH 04/13/2023	One-Time	
SB139-714 Rev IR 06/12/2023	Life Raft Cables Retromod *		Not Complied				One-Time	
AD2023-11-07 Rev IR 06/22/2023	Radio Altimeters Flight Restrictions *		Not Complied				One-Time	
139-56-23-00 Rev IR 11/06/2023	Protective Tape for acrylic windscreen *		Not Complied				As Required	
139-33-24-00 Rev IR 01/12/2024	Additional 2nd landing light kit electrical provisions installation (Ref. BT139-304). *		Not Complied				As Required	
NSI-13236 Rev IR 01/29/2024	Nova Systems SDL-350 Installation *		Not Complied				As Required	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
139-23-24-00 Rev IR 01/30/2024	Installation of Cabin Audio Aural Warnings		Not Complied				As Required	
	*							
AD2024-01-11 Rev IR 02/15/2024	Pacific Scientific Company Rotary Buckle assemblies (buckles) installed		Not Complied				One-Time	
	*							
NSI-13233-SB-02 Rev 2 03/14/2024	Laser activation for FLIR 380HDc		Not Complied				One-Time	
	*							
139-53-24-01 Rev IR 03/18/2024	Installation of Lower Maintenance Step Support Scuff Pads		Not Complied				As Required	
	*							
139-53-24-00 Rev IR 03/18/2024	Installation of Maintenance Step Pull Tab		Not Complied				As Required	
	*							
ASB139-777 Rev IR 05/23/2024	Emergency Flotation Control Panel Replacement		Complied - N/A Verified ASB139-777 is not applicable by Part Number. Y. Nervesa -- Era QC			1530.4 FH 05/23/2024	One-Time	
	3G9560V00558	S09646205						

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date	
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025	
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance				Complied On TT Date	Interval Next Due	
SB139-778 Rev IR 06/12/2024	Tail Plane Rod Assy Installation Inspection 3G5510A02733MCR02024		Complied - N/A Verified SB139-778 is not applicable by Part Number. Y. Nervesa 06/17/2024 -- Era QC				2465.3 FH 06/17/2024	One-Time	
SB139-778 Rev IR 06/12/2024	Tail Plane Rod Assy Installation Inspection 3G5510A02733MCR1490		Complied - N/A Verified SB139-778 is not applicable by Part Number. Y. Nervesa 06/17/2024 -- Era QC				3587.5 FH 06/17/2024	One-Time	
SB139-616 Rev IR 06/19/2024	* Parent	Lower L/H Tail Longeron Inspection and Repair		Partially Complied					
SB139-616 PT II *	Repair of Tail Lower L/H Longeron 3G5350A00135A7/0083		Not Complied					One-Time 06/19/2025	
SB139-616 PT III *	Repair of Tail Lower L/H Longeron 3G5350A00135A7/0083		Complied - N/A Verified SB139-616 PT III is not applicable by Tail Boom P/N -- Era QC				7491.3 FH 06/24/2024	One-Time	
SB139-616 PT IV	Repair of Tail Lower L/H Longeron 3G5350A00135A7/0083		Complied - N/A Verified SB139-616 PT IV is not applicable by Tail Boom P/N -- Era QC				7491.3 FH 06/24/2024	One-Time	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date	Interval Next Due	
SB139-616 PT I	Inspection of the Tail Boom Longerons		Not Complied				One-Time	
	*							
	3G5350A00135 A7/0083						12/19/2024	
139-33-24-02	Sapphire S46 Search light Installation		Not Complied				As Required	
Rev IR	*							
06/19/2024								
SB139-775	Pedal Assy Rework and Switches Installation		Not Complied					
Rev IR	*							
10/29/2024	Parent							
SB139-775 PT I	Pilot Pedal Assy Rework and Switches Installation		Not Complied				One-Time	
	*							
SB139-775 PT II	Copilot Pedal Assy Rework and Switches Installation		Not Complied				One-Time	
	*							
AD2024-20-04	Pacific Scientific Company Rotary Buckle assemblies (buckles) installed		Not Complied				One-Time	
Rev IR	*							
11/12/2024							02/12/2025	

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject					Complied On		Interval
Rev #	Method of Compliance					TT		
Eff Date	Part Number	Serial Number						Next Due
AD2024-17-07	Tail Rotor Damper Bracket Inspection		Not Complied					6 MO
Rev IR	*							
11/12/2024	3G6420A06131	AAB0131						01/12/2025
AD2024-17-07	Tail Rotor Damper Bracket Inspection		Not Complied					6 MO
Rev IR	*							
11/12/2024	3G6420A06131	AAB0118						01/12/2025
AD2024-17-07	Tail Rotor Damper Bracket Inspection		Not Complied					6 MO
Rev IR	*							
11/12/2024	3G6420A06131	AAB0121						01/12/2025
AD2024-17-07	Tail Rotor Damper Bracket Inspection		Not Complied					6 MO
Rev IR	*							
11/12/2024	3G6420A06131	AAB0120						01/12/2025
EASB139-795	External Rescue Hoist Cable Assy Ball End Inspection		Not Complied					One-Time
Rev IR	*							
11/27/2024								
ASB139-805	Hoist Clutch Replacement		Not Complied					One-Time
Rev IR	*							
11/28/2024								
Generated On	06/09/2025	MM/DD/YYYY	13:21:33	HH24:MI:SS	Page 152 of 155			

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number	Subject						Complied On	Interval
Rev #	Method of Compliance						TT	
Eff Date	Part Number	Serial Number					Date	Next Due
SB139-761	Hydraulic Flight Control Lines Retromods		Not Complied					
Rev IR	*							
12/23/2024	Parent							
SB139-761 PT I	Upper Deck Hydraulic Flight Control Lines Retromods		Not Complied					
	*							
SB139-761 PT II	Tail Boom Hydraulic Flight Control Lines Retromods		Not Complied					
	*							
	3G5350A00135	A7/0083	12/23/2025					
SB139-794 PT III	CS26 Life Raft additional Decals installation-COMPANY REQUIREMENT FOR ALL AW139 AIRCRAFT.		Not Complied					
Rev IR	*							
01/23/2025								
AD2025-03-03	External Rescue Hoist Cable Assy Ball End Inspection		Not Complied					
Rev IR	*							
02/19/2025								
AD2024-26-02	Pacific Scientific Company rotary buckle assemblies(cracked buckle handles)		Not Complied					
Rev IR	*							
03/07/2025								

A/C Reg #	Model #	EO Applicability	Source Doc Type	Part #	Serial #	Total Hours	Total Flights	Report Date
N811TA	AW139	Aircraft & Component			41269	7491.3	8761	06/09/2025
EO Number Rev # Eff Date	Subject Part Number Serial Number		Method of Compliance			Complied On TT Date		Interval Next Due
ASB139-801 Rev IR 03/31/2025	Overhead Panel Wires Inspection Parent		Not Complied					
ASB139-801 PT I *	One time inspection of the overhead panel for presence of interference between cables and fixing hardware.		Not Complied					One-Time
ASB139-801 PT II *	Recurring inspection of the overhead panel for presence of interference between cables and fixing hardware.		Not Complied					
SB139-751 Rev IR 04/22/2025	N.4 Auxiliary Hydraulic Pump Bracket Angle Inspection		Not Complied					One-Time
AD2025-07-01 Rev IR 05/15/2025	Navigation-Digital Air Data Computer-Replacement HG1153CA03 11034072		Complied - N/A Verified AD2025-07-01 is not applicable by ADC Part Number -- Era QC			7487.8 FH 04/11/2025		One-Time
AD2025-07-01 Rev IR 05/15/2025	Navigation-Digital Air Data Computer-Replacement HG1153CA03 10014085		Complied - N/A Verified AD2025-07-01 is not applicable by ADC Part Number -- Era QC			8339 FH 04/11/2025		One-Time

