

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
5-28-2026				VISUALLY INSPECTED PROP, SPINNER AND BULHEADS - OK. CHECKED	
AT JAN	5450.91			DEICE OPERATION - OK	
TS NEW	371.24			A-P450966172 Sulebony	
				PEARSON AIRCRAFT SERVICES LLC	

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
2-15-2023				VISUALLY INSPECTED PROP, HUB & BULLHEAD - OK OVER OPERATION	
ATTACH	5301.87			CHECKED - REPLACED ONE WIRE HARNESS FROM BULLHEAD TO BLADE.	
TSNSW	222.20			OPERATION CHECKED NORMAL.	
				AP45096672 Eubank	
				TRIMBLE AIRCRAFT SERVICES LLC	
7-2-2024				INSPECTED PROP, HUB AND BULLHEAD VISUALLY - OK. CHECK OPERATION	
ATTACH	5365.34			OF PILE ROOTS - OK.	
TSNSW	285.67				
				AP45096672 Eubank	
				TRIMBLE AIRCRAFT SERVICES LLC	

+

—

—

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
2-15-2023	5301.87			VISUALLY INSPECTED PROP, HUB & BULLHEADS - OK. CHECK OPERATION CHECKED - REPLACED ONE WIRE HARNESS FROM BULLHEAD TO BLADE.	
TSNSW	222.20			OPERATION CHECKED NORMAL.	
				AP450966172 Eubank	
				TERRILL AIRCRAFT SERVICES LLC	
7-2-2024	5365.34			INSPECTED PROP, HUB AND BULLHEAD VISUALLY - OK. CHECK OPERATION OF PILE ROOTS - OK.	
TSNSW	285.67				
				AP450966172 Eubank	
				TERRILL AIRCRAFT SERVICES LLC	

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
4-13-2020				PROPP, SPINNER AND BULKHEAD VISUALLY INSPECTED - OK. DEICE OPERATIONAL - CHECKED	
HRM	1839.1	OK			
RTMCH	5159.45			AP 45056172 Ewelson	
TSMBW	79.78			TEMBU AIRCRAFT SERVICES LLC	
11-1-2021				VISUALLY INSPECTED PROPP, SPINNER AND BULKHEAD - CHECKED OK.	
HRM				CHECKED DEICE OPERATION - OK	
RTMCH	5227.93				
TSNEW	148.86			AP 45056172 Ewelson	
				TEMBU AIRCRAFT SERVICES LLC	


PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
4-14-2019	RTMCH 5117.2	17.2	PROP REMOVED AND TAKE TO BYAM	PROP REMOVED AND TAKE TO BYAM	PROPPELLER
				DUE TO DEEP ROCK DAMAGE ON ONE BLADE,	
				REINSTALLED AFTER REPAIR.	
				APPROVED BY	
				TERMINAL AIRCRAFT SERVICE INC	

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
5/24/18	6	0	3AF34C503-D S/N 180529	THIS PROPELLER WAS MANUFACTURED NEW AT McCauley Propeller Systems. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	
8-4-2018				THIS PROP INSTALLED ON PIPER PA34-200T	N2908X
R7044	5079.67			S/N 34-7970352 ON RIGHT ENGINE.	
HR AM	1771.0				
	0 SINCE NEW				
				MP450966172 Eureka	
				RENEW AIRCRAFT SERVICES LLC	