

Medical Air Operations											
Socata TBM Maintenance Requirements Report											
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70		FHM:	4,523.70	PREVIOUS HOBBS:	0	ETT Adjustment	-285.9
AIRCRAFT REG #		N228CH				DATE:	3/13/2025	Engine Total Time:	4,237.80	L/C Adjustment	-127
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798				Landing Cycles:	4,925		
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.	
	12	1	PROTECTION of EXTERNAL FITTINGS			1200 HRS	112.7	4636.4		3,436.40	
	12	2	PROTECTION of EXTERNAL MOVABLE PARTS, LUBE FLAP ROLLERS			12 MO	-6	8/24/2024		8/24/2023	
	27	5	SPOILER & AILERON CABLE TENSION			12 MO	-6	8/24/2024		8/24/2023	
	28	6	FUEL STRAINERS CLEANLINESS & CONDITION			48 MO	26	4/21/2027		4/21/2023	
	28	6	FUEL STRAINERS CLEANLINESS & CONDITION			1500 HRS	1341	5864.7		4,364.70	
	28	7	FUEL FLAPPER VALVES CHECK RUBBER CONDITION			48 MO	26	4/21/2027		4/21/2023	
	28	7	FUEL FLAPPER VALVES CHECK RUBBER CONDITION			1500 HRS	1341	5864.7		4,364.70	
	21	8	PRESSURIZATION HOSES REPLACEMENT			168 MO	139	10/3/2036	Inspected	10/3/2022	
	34	9	AIR DATA SYSTEM LINE REPLACEMENT			168 MO	139	10/3/2036	Inspected	10/3/2022	
	35	10	OXYGEN SYS. COMP. & LINES FOR CONDITION			12 MO	-6	8/24/2024		8/24/2023	
	53	11	PERFORM a FATIGUE & CORROSION INSPECTION (Subsequent)			96 MO	67	10/3/2030		10/3/2022	
	53	11	PERFORM a FATIGUE & CORROSION INSPECTION (Subsequent)			3000 HRS	2750.8	7274.5		4274.5	
	**	**	***** POWER PLANT *****								
	11	13	PLACARD & MARKING, AREA 100			12 MO	-6	8/24/2024		8/24/2023	
	21	14	HEA EXCHANGER/COOLING TURBINE PACKOVERHAUL			6000 HRS	4912.7	9436.4		3436.4	
	24	22	CONCORD LEAD ACID BATTERY CHECK			12 MO	-6	8/24/2024	new battery installed 8/24/2023	8/24/2023	
	24	22	CONCORD LEAD ACID BATTERY CHECK			600 HRS	478.4	5002.1	new battery installed	4402.1	
	24	23	STANDBY GENERATOR BELT REPLACE			1200 HRS	700	5223.7	Replaced at engine change	4,023.70	
	24	24	STANDBY GENERATOR BRUSH CHECK			600 HRS	193.5	4717.2	replaced brush block	4,117.20	
	24	25	STANDBY GENERATOR OVERHAUL			3000 HRS	810.7	5334.4		2,334.40	
	24	26	STARTER GENERATOR BRUSH CHECK			600 HRS	193.5	4717.2	Replaced brushes	4,117.20	
	24	27	STARTER GENERATOR BEARING REPLACEMENT			1200 HRS	203.6	4727.3		3,527.30	

Medical Air Operations											
Socata TBM Maintenance Requirements Report											
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70		FHM:	4,523.70	PREVIOUS HOBBS:	0	ETT Adjustment	-285.9
AIRCRAFT REG #		N228CH				DATE:	3/13/2025	Engine Total Time:	4,237.80	L/C Adjustment	-127
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798				Landing Cycles:	4,925		
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.	
	24	28	STARTER GENENRATOR OVERHAUL			2400 HRS	1403.6	5927.3		3,527.30	
	28	29	MECHANICAL PUMP OVERHAUL			120 MO	17	7/15/2026		7/15/2016	
	28	29	MECHANICAL PUMP OVERHAUL			3500 HRS	1797.1	6320.8	Installed new pump	2,820.80	
	32	30	ELECTRO-HYDRAULIC GENERATOR OVERHAUL			120 MO	27	5/30/2027		5/30/2017	
	32	30	ELECTRO-HYDRAULIC GENERATOR OVERHAUL			10000 LCYC	8136	13061		3,061	
	32	31	LANDING GEAR HYDRAULIC SYSTEM FLUID REPLACEMENT			36 MO	7	10/3/2025		10/3/2022	
	32	32	BRAKE RESERVOIR HYDRAULIC FLUID REPLACEMENT			36 MO	7	10/3/2025		10/3/2022	
	61	34	CHECK PROPELLER ASSMBLY HARTZELL DOC# 149			12 MO	-6	8/24/2024		8/24/2023	
	61	34	CHECK PROPELLER ASSMBLY HARTZELL DOC# 149			400 HRS	150.8	4674.5		4,274.50	
	61	35	PROPELLER LUBRICATION (REFER 61-10-01-301)			12 MO	-6	8/24/2024		8/24/2023	
	61	35	PROPELLER LUBRICATION (REFER 61-10-01-301)			400 HRS	54.4	4578.1		4,178.10	
	61	36	PROPELLER OVERHAUL HARTZELL (HC-SL-61-61Y) LATEST REVISION	HC-E4N-3	HH4419	72 MO	50	4/17/2029		4/17/2023	
	61	36	PROPELLER OVERHAUL HARTZELL (HC-SL-61-61Y) LATEST REVISION			4000 HRS	3841	8364.7		4,364.70	
	61	37	BETA RING & CARBON BLOCK CHECK			12 MO	-6	8/24/2024		8/24/2023	
	61	37	BETA RING & CARBON BLOCK CHECK			600 HRS	350.8	4874.5	replaced block 4274.5	4,274.50	
	61	38	PROP GOV. OVERHAUL MODEL # 8210-007(SB-33580-M)			3500 HRS	2777.6	7301.3	revised due to engine removals	3,801.30	
	61	39	L2 PROP OVERSPEED GOV. MODEL # 210632 (SB-33580-M)			3500 HRS	3250.8	7774.5		4,274.50	
	71	40	VIBRATION ISOLATOR REPLACEMENT			3500 HRS	2688.4	7212.1		3,712.10	
	72	42	ENG. H.S.I. (PWC SB 14603 LATEST REVISION)			1750 HRS	1027.6	5551.3	revised due to engine removals	3,801.30	
	72	43	ENGINE BORESCOPE			400 HRS	54.4	4578.1		4,178.10	
	72	44	ENGINE OVERHAUL			3500 HRS	2777.6	7301.3		3801.3	
	72	45	ENGINE COMP. & TURBINE WASH			100 HRS	81.7	4605.4		4,505.40	
	73	47	FUEL MANIFOLD ADAPTERS & NOZZLES LEAK TEST			400 HRS	54.4	4578.1	revised due to engine removals	4178.1	
	73	48	CLEAN FUEL PUMP INLET SCREEN			600 HRS	441	4964.7	revised due to engine removals	4,364.70	
	73	49	INSPECT FUEL PUMP OUTLET FILTER			600 HRS	441	4964.7	revised due to engine removals	4,364.70	

Medical Air Operations												
Socata TBM Maintenance Requirements Report												
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70		FHM:	4,523.70	PREVIOUS HOBBS:	0		ETT Adjustment	-285.9
AIRCRAFT REG #		N228CH				DATE:	3/13/2025	Engine Total Time:	4,237.80		L/C Adjustment	-127
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798				Landing Cycles:	4,925			
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.		
	73	50	REPLACE FUEL PUMP OUTLET FILTER			600 HRS	441	4964.7	revised due to engine removals	4,364.70		
	73	51	REPLACE P3 FILTER	WF336238		1000 HRS	277.6	4801.3	revised due to engine removals	3,801.30		
	73	51A	CLEAN P3 FILTER			100 HRS	81.7	4605.4		4,505.40		
	73	51B	INSPECT & CLEAN P3 FILTER DRAIN VALVE HOUSING			100 HRS	81.7	4605.4		4,505.40		
	74	52	IGNITION EXCITER CONDITION			400 HRS	381.7	4905.4		4,505.40		
	74	53	IGNITION CABLES ROUTING, ATTACH			400 HRS	381.7	4905.4		4,505.40		
	74	54	SPARK IGNITERS CLEANLINESS			400 HRS	381.7	4905.4		4,505.40		
	74	55	SPARK IGNITERS OPS CHECK			400 HRS	381.7	4905.4		4,505.40		
	79	56	CHANGE ENGINE OIL			400 HRS	54.4	4578.1		4,178.10		
	79	57	REPLACE OIL FILTER			1000 HRS	500	5023.7		4,023.70		
	79	58	ENGINE CHIP DETECTORS CONTINUITY CHECK			12 MO	-6	8/24/2024		8/24/2023		
	79	58	ENGINE CHIP DETECTORS CONTINUITY CHECK			600 HRS	478.4	5002.1		4,402.10		
	79	59	AGB INTERNAL SCAVENGE PUMP INLET SCREEN			1000 HRS	654.4	5178.1		4,178.10		
	79	60	ENGINE OIL COOLER OVERHAUL			2100 HRS	1721.1	6244.8		4,144.80		
	**		***** FUSELAGE *****									
	11	61	EXTERIOR PLACARDS & MARKINGS AREA 200			12 MO	-6	8/24/2024		8/24/2023		
	11	62	INTERIOR PLACARDS & MARKINGS AREA 200			12 MO	-6	8/24/2024		8/24/2023		
	21	64	CLEAN OUTFLOW VALVE CONTROLLER FILTER			1200 HRS	112.7	4636.4		3,436.40		
	21	65	CLEAN OUTFLOW VALVE SEAT			12 MO	-6	8/24/2024		8/24/2023		
	21	66	CLEAN SAFETY VALVE FILTER			1200 HRS	112.7	4636.4		3,436.40		
	21	67	CLEAN SAFETY VALVE SEAT			12 MO	-6	8/24/2024		8/24/2023		
	22	69	CHECK B35,B36, B37 SERVO-ACTUATORS CABLES FOR CONDITION			12 MO	-6	8/24/2024		8/24/2023		
	22	70	CHECK B35,B36, B37 SERVO-ACTUATORS CABLE TENSIONS			12 MO	-6	8/24/2024		8/24/2023		
	22	71	CHECK B35, B36,B37,& B38 SERVO ACTUATORS CLUTCH TORQUES			3000 HRS	2750.8	7274.5		4,274.50		
	26	76	CHECK FIRE EXTINGUISHER, FOR WEIGHT AND PRESSURE			12 MO	-6	8/24/2024		8/24/2023		
	26	77	REPLACE FIRE EXTINGUISHER	Artex C352	G-40530944	60 MO	18	8/24/2026	date on bottle:2021	8/24/2021		
	34	80	STANDBY COMPASS COMPENSATION			36 MO	-9	5/20/2024		5/20/2021		

Medical Air Operations											
Socata TBM Maintenance Requirements Report											
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70	FHM:	4,523.70	PREVIOUS HOBBS:	0	ETT Adjustment	-285.9	
AIRCRAFT REG #		N228CH			DATE:	3/13/2025	Engine Total Time:	4,237.80	L/C Adjustment	-127	
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798			Landing Cycles:	4,925			
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.	
	34	81	TRANSPONDER CONTROL OPERATIONAL TEST 91.413			24 MO	-9	6/2/2024		6/2/2022	
	34	83	IFR EQUIPMENT OPERATIONAL TEST 91.411 & 91.413			24 MO	-9	6/2/2024		6/2/2022	
	34	85	ENCODING ALTIMETER FAR 91.411 WITH RVSM			24 MO	-9	6/2/2024		6/2/2022	
	35	92	OVERHAUL CREW OXYGEN MASKS			72 MO	43	10/3/2028		10/3/2022	
	35	93	DESINFECT PASSENGER OXYGEN MASKS			12 MO	-6	8/24/2024		8/24/2023	
	53	95	UNDER FLOOR & EMERGENCY EXIT DRAIN INSPECTION			12 MO	-6	8/24/2024		8/24/2023	
	53	97	LARGE DOOR FRAME INSPECTION			3000 HRS	1587.5	6111.2		3111.2	
	**	**	FRONT CARGO COMPARTEMENT UP TO PRESSURIZED BULKHEAD								
	11	98	PLACARD & MARKING, AREA 210			12 MO	-6	8/24/2024		8/24/2023	
	21	99	CHECK REFRIGERANT CHARGE IN VAPOR CYCLE COOLING SYSTEM			12 MO	-6	8/24/2024		8/24/2023	
	28	100	REPLACE FUEL UNIT FILTER ELEMENT			600 HRS	441	4964.7		4,364.70	
	28	101	CHECK WELDON ELECTRIC PUMP BRUSHES			6000 HRS	1476.3	6000		0	
	30	102	WATER SEPERATOR FILTER			12 MO	-6	8/24/2024		8/24/2023	Ice & Rain 30-10-04-301
	**	**	***** STABILIZER *****								
	11	103	PLACARD & MARKING, AREA 300			12 MO	-6	8/24/2024		8/24/2023	
	25	107	ELT OPERATIONAL TEST			12 MO	-6	8/24/2024		8/24/2023	
	25	108	REPLACE ELT BATTERY					8/1/2024		7/17/2019	
	27	109	CHECK RUDDER CABLE TENSIONS			12 MO	-6	8/24/2024		8/24/2023	
	27	110	CHECK ELEVATOR TRIM TAB CABLE TENSIONS			12 MO	-6	8/24/2024		8/24/2023	
	55	111	SECOND HORIZONTAL STABILIZER FATIGUE & CORROSION INSPECTION			96 MO	67	10/3/2030		10/3/2022	
	55	111	SECOND HORIZONTAL STABILIZER FATIGUE & CORROSION INSPECTION			3000 HRS	2750.8	7274.5		4274.5	
	55	112	SUBSEQUENT VERTICAL STABILIZER FATIFUE & CORROSION INSPECTION			60 MO	31	10/3/2027		10/3/2022	
	55	112	SUBSEQUENT VERTICAL STABILIZER FATIFUE & CORROSION INSPECTION			3000 HRS	2750.8	7274.5		4274.5	
	55	113	FIXED HORIZONTAL STABILIZER ULTRASONIC & FIBERSCOPIC INSPECTION			1200 HRS	112.7	4636.4		3,436.40	

Medical Air Operations											
Socata TBM Maintenance Requirements Report											
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70	FHM:	4,523.70	PREVIOUS HOBBS:	0	ETT Adjustment	-285.9	
AIRCRAFT REG #		N228CH			DATE:	3/13/2025	Engine Total Time:	4,237.80	L/C Adjustment	-127	
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798			Landing Cycles:	4,925			
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.	
	55	114	FIN ULTRASONIC, FIBERSCOPIC & TAP INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	55	116	RUDDER FIBERSCOPIC & TAP TEST INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	55	117	SPRAY SICCATIVE OIL INSIDE RUDDER TORQUE SHAFT			1200 HRS	112.7	4636.4		3,436.40	
	55	118	ELEVATOR FIBERSCOPIC & TAP TEST INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	**	**	***** LEFT WING *****								
	11	119	PLACARDS & MARKINGS, 500			12 MO	-6	8/24/2024		8/24/2023	
	57	120	SECOND LEFT WING STRUCTURE FATIGUE & CORROSION INSPECTION			96 MO	67	10/3/2030		10/3/2022	
	57	120	SECOND LEFT WING STRUCTURE FATIGUE & CORROSION INSPECTION			3000 HRS	2750.8	7274.5		4274.5	
	57	121	LEFT FLAP FIBERSCOPIC & TAP INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	57	122	LEFT AILERON FIBERSCOPIC & TAP INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	**	**	***** RIGHT WING *****								
	11	123	PLACARDS & MARKINGS, 600			12 MO	-6	8/24/2024		8/24/2023	
	35	124	GASEOUS OXYGEN CYLINDER TIGHTNESS.....			12 MO	-6	8/24/2024		8/24/2023	
	35	125	OXYGEN CYLINDER DOT E8162-1850 HYDROSTATIC TEST			60 MO	24	3/8/2027		3/8/2022	
	35	126	REPLACE OXYGEN CYLINDER			180 MO	96	2/28/2033		2/28/2018	
	57	127	SECOND RIGHT WING STRUCTURE FATIGUE & CORROSION INSPECTION			96 MO	67	10/3/2030		10/3/2022	
	57	127	SECOND RIGHT WING STRUCTURE FATIGUE & CORROSION INSPECTION			3000 HRS	2750.8	7274.5		4274.5	
	57	128	RIGHT FLAP FIBERSCOPIC & TAP INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	57	129	RIGHT AILERON FIBERSCOPIC & TAP INSPECTION			1200 HRS	112.7	4636.4		3,436.40	
	**	**	***** LANDING GEAR *****								
	11	130	PLACARDS & MARKINGS, AREA 700			12 MO	-6	8/24/2024		8/24/2023	
	32	131	INSPECT LEFT, RIGHT & NOSE LANDING GEAR			12 MO	-6	8/24/2024		8/24/2023	
	32	132	LUBRICATE LEFT, RIGHT & NOSE LANDING GEAR AXLES			12 MO	-6	8/24/2024		8/24/2023	

Medical Air Operations														
Socata TBM Maintenance Requirements Report														
AIRCRAFT S/N:		356	TOTAL TIME:		4,523.70		FHM:	4,523.70	PREVIOUS HOBBS:		0	ETT Adjustment		-285.9
AIRCRAFT REG #		N228CH					DATE:	3/13/2025	Engine Total Time:		4,237.80	L/C Adjustment		-127
AIRCRAFT MFG. DATE			5/3/2006	Engine Cycles:		4,798				Landing Cycles:		4,925		
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS		REMAINING	DUE	REMARKS	LAST INSP.			
	32	133	OVERHAUL LEFT WHEEL ASSEMBLY			1000	LCYC	590	5515		4515			
	32	133	OVERHAUL RIGHT WHEEL ASSEMBLY			1000	LCYC	579	5504		4504			
	32	134	CHECK LEFT & RIGHT MAIN LANDING GEAR SHOCK-ABSORBER INFLATION PRESSURE			12	MO	-6	8/24/2024		8/24/2023			
	32	135	INSPECT LEFT & RIGHT MLG PLAY, CORROSION, TORQUE LINKS, OIL CHANGE			60	MO	31	10/3/2027		10/3/2022			
	32	136	PERFORM A DIMENSIONAL CHECK ON THE LEFT & RIGHT LANDING GEAR			120	MO	27	5/30/2027		5/30/2017			
	32	137	OVERHAUL LEFT & RIGHT MAIN LANDING GEAR			5000	LCYC	75	5000		0			
	32	138	LEFT MAIN LANDING GEAR ACTUATOR OVERHAUL			120	MO	91	10/3/2032		10/3/2022			
	32	138	LEFT MAIN LANDING GEAR ACTUATOR OVERHAUL			5000	LCYC	4657	9582		4,582			
	32	138	RIGHT MAIN LANDING GEAR ACTUATOR OVERHAUL			120	MO	91	10/3/2032		10/3/2022			
	32	138	RIGHT MAIN LANDING GEAR ACTUATOR OVERHAUL			5000	LCYC	4657	9582		4,582			
	32	139	OVERHAUL NOSE WHEEL ASSEMBLY			1000	LCYC	266	5191		4191			
	32	140	CHECK NOSE LANDING GEAR SHOCK-ABSORBER INFLATION PRESSURE			12	MO	-6	8/24/2024		8/24/2023			
	32	141	INSPECT NOSE LANDING GEAR FOR PLAY, CORROSION AND PERFORM DIMENSIONAL CHECK ON TORQUE LINKS			60	MO	31	10/3/2027		10/3/2022			
	32	142	CHANGE OIL IN NOSE LANDING GEAR SHOCK-ABSORBER			60	MO	31	10/3/2027		10/3/2022			
	32	143	DO A DIMENSIONAL CHECK ON ATTACHING BOLTS OF THE NOSE LANDING GEAR			120	MO	27	5/30/2027		5/30/2017			
	32	144	REPLACE NOSE LANDING GEAR ACTUATOR HINGE BOLT			84	MO	17	7/17/2026		7/17/2019			
	32	144	REPLACE NOSE LANDING GEAR ACTUATOR HINGE BOLT			5000	LCYC	75	5000		0			
	32	145	OVERHAUL NOSE LAND GEAR ASSEMBLY			5000	LCYC	75	5000	4029.6	0			
	32	146	NOSE LANDING GEAR ACTUATOR OVERHAUL			120	MO	-8	6/27/2024		6/27/2014			

Medical Air Operations													
Socata TBM Maintenance Requirements Report													
AIRCRAFT S/N:			356	TOTAL TIME:	4,523.70	FHM:	4,523.70	PREVIOUS HOBBS:	0		ETT Adjustment	-285.9	
AIRCRAFT REG #			N228CH			DATE:	3/13/2025	Engine Total Time:	4,237.80		L/C Adjustment	-127	
AIRCRAFT MFG. DATE			5/3/2006	Engine Cycles:	4,798			Landing Cycles:	4,925				
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.			
	32	146	NOSE LANDING GEAR ACTUATOR OVERHAUL			5000	LCYC	1918	6843		1,843		
	32	147	REPLACE SHIMMY DAMPER FLUID			36	MO	10/3/2025		10/3/2022			
		148	PERFORM A POST INSPECTION FLIGHT							10/3/2022			
	**	**	RVSM INSPECTION PROGRAM										
			RVSM SATIC PORTS HEIGHT & SLOPE CHECK 53-00-00-601			200	HRS	78.4	4602.1		4,402.10		
			RVSM ALTITUDE ALERTER SYSTEM 22-11-00-601			600	HRS	107.4	4631.1		4,031.10		
			RVSM 24 MONTH PITOT STATIC CHECK			24	MO	-9	6/2/2024		6/2/2022		
			RVSM 24 MONTH AIR DATA COMPUTER CHECK			24	MO	-9	6/2/2024		6/2/2022		
			RVSM 12 MONTH CHECK			12	MO	-6	8/24/2024		8/24/2023		
	**	**	REOCCURRING ADS & SERVICE BULLETINS										
			AD 2002-19-01 FLIGHT CONTROL INSPECTION			ASREQ				5/30/2017			
			AD 2007-03-17 C18 BIS & C19 FRAME INSPECTION SB70-129			12	MO	N/A	N/A		N/A		
			AD 2007-03-17 C18 BIS & C19 FRAME INSPECTION SB70-129			200	HRS	N/A	N/A		N/A		
			AD 2015-17-10 MAIN LANDING GEAR INSPECTION SB70-130						No further action required. Strut housings replaced.				
			SB70-118 FLAP ACTUATOR FREE PLAY CHECK			12	MO	-6	8/24/2024		8/24/2023		
			SB70-118 FLAP ACTUATOR FREE PLAY CHECK			400	HRS	150.8	4674.5		4,274.50		
			SB70-118 FLAP ACTUATOR LUBRICATION			12	MO	-6	8/24/2024		8/24/2023		
			SB70-118 FLAP ACTUATOR LUBRICATION			400	HRS	150.8	4674.5		4,274.50		
	**	**	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS										
			Aveo PosiStrobe Beacons			12	MO	-6	8/24/2024		8/24/2023		
			BOOM BEAM LANDING LIGHT INSPECTION (LSM-500-045)			12	MO	-6	8/24/2024		8/24/2023		
			BOOM BEAM LANDING LIGHT INSPECTION (LSM-500-045)			100	HRS	81.7	4605.4		4,505.40		
			GDL 69/69A SATELLITE RADIO SA01487SE			12	MO	-6	8/24/2024		8/24/2023		

Medical Air Operations												
Socata TBM Maintenance Requirements Report												
AIRCRAFT S/N:		356	TOTAL TIME:	4,523.70		FHM:	4,523.70	PREVIOUS HOBBS:	0		ETT Adjustment	-285.9
AIRCRAFT REG #		N228CH				DATE:	3/13/2025	Engine Total Time:	4,237.80		L/C Adjustment	-127
AIRCRAFT MFG. DATE		5/3/2006	Engine Cycles:	4,798				Landing Cycles:	4,925			
LINE	ATA	SP. CHK#	ITEM/REQUIREMENT	PART NUMBER	3654	LIMITS	REMAINING	DUE	REMARKS	LAST INSP.		
	**	**	ADDITIONAL INSPECTION ITEMS									
			INSPECT FLIGHT MANUAL			12	MO	-6	8/24/2024	8/24/2023		
			REVIEW AD COMPLIANCE / BI-WEEKLY LIST			12	MO	-6	8/24/2024	8/24/2023		
			AIRCRAFT REGISTRATION RENEWAL			36	MO	OVERDUE	3/31/2031	3/31/2028		
			Oceanic C406-1 ELT Registration Due: 5/30/2020	453-5002-(999	12937	24	MO	10	12/14/2025	12/14/2023		
	32		OVERHAUL LEFT BRAKE ASSEMBLY			1000	LCYC	-16	4909	3909		
	32		OVERHAUL RIGHT BRAKE ASSEMBLY			1000	LCYC	-16	4909	3909		
			Brake Pads Left			time in service (hrs)		18.3	NDT 6/14/19	4505.4		
			Brake Pads Right			time in service (hrs)		18.3	NDT 2/21/2020	4505.4		
			Brake Rotors Left			time in service (hrs)		345.6	NDT 6/14/19	4178.1		
			Brake Rotors Right			time in service (hrs)		345.6	NDT 5/31/19	4178.1		
			Left Main Tire			time in service (hrs)		56.0	S/N: 20840148	4467.7		
			Right Main Tire			time in service (hrs)		296.5	S/N: 10780012	4227.2		
			Nose Tire			time in service (hrs)		492.3	S/N: 714S00166	4031.4		
	77		SHADIN Download			20	HRS	16.60	4540.3	4520.3		