



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-F2YR-1F

PROPELLER S/N CM 1156A

LOGBOOK # 1

The subject aircraft was involved in an incident /
accident on 10/11/2024 rendering it a Constructive
Total Loss as not repairable within its insured value. For
further details refer to insurance claim: 8221485590US.

Signed: ***Underwriters Salvage Company***

Date: **1/20/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

A3 Aircraft Services
HANGER 37, 5075 AIRPORT RD
MIDLAND, VA 22728
Email: a3aircraftservices@gmail.com

PROPELLER

Hartzell


HC-F2YR-1F

S/N CM1156A

- Inspected propeller IAW with manufactures instructions: serviced propeller with Aeroshell 6 grease

I certify that this propeller was inspected on 16 Nov 21 in accordance with a condition inspection, scope and detail FAR 43 Appendix D, and was determined to be in a condition for safe operation.

Date: 16 Nov 21
Tach: 1991.7
Prop TTSNEW: 1991.7



James P. Scott, A&P 2757152

A3 Aircraft Services
HANGER 37, 5075 AIRPORT RD
MIDLAND, VA 22728
Email: a3aircraftservices@gmail.com

PROPELLER

Hartzell

HC-F2YR-1F

S/N CM1156A

- Inspected propeller IAW with manufactures instructions: serviced propeller with Aeroshell 6 grease

I certify that this propeller was inspected on 2 Dec 22 in accordance with a condition inspection, scope and detail FAR 43 Appendix D, and was determined to be in a condition for safe operation.

Date: 2 Dec 22
Tach: 2069.2
Prop TTSNEW: 2069.2



James P. Scott, A&P 2757152

A3 Aircraft Services
HANGER 37, 5075 AIRPORT RD
MIDLAND, VA 22728
Email: a3aircraftservices@gmail.com

PROPELLER

Hartzell


HC-F2YR-1F

S/N CM1156A

- Inspected propeller IAW with manufactures instructions: serviced propeller with Aeroshell 6 grease

I certify that this propeller was inspected on 1 Feb 24 in accordance with a condition inspection, scope and detail FAR 43 Appendix D, and was determined to be in a condition for safe operation.

Date: 1 Feb 24
Tach: 2111.1
Prop TTSN: 2111.1



James P. Scott, A&P 2757152

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
7/9/20		1349	INSPECTED PROP/HUB. RUN UP / OPS CHECK GOOD. ADS REFERRED TO I CORRECT THIS DATE.
			I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW THE SCOPE AND DETAIL OF FAR PART 43 APPENDIX D AND HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION AND APPROVED FOR RETURN TO SERVICE.
			<i>James P. Scott</i> AP2748502 HA
A3 Aircraft Services HANGER 37, 5075 AIRPORT RD MIDLAND, VA 22728 Email: a3aircraftservices@gmail.com ph & fax 540-788-1749			Date: 14 Oct 20 Tach: 1895.3 Prop TTSNEW: 1895.3
PROPELLER Hartzell HC-F2YR-1F S/N CM1156A - Inspected propeller IAW with manufactures instructions; serviced propeller with Aeroshell 6 grease - Removed and reinstalled propeller to facilitate alternator and air conditioner belt replacement; reinstalled with new o-ring; torqued/safetied bolts I certify that this propeller was inspected on 14 Oct 20 in accordance with a condition inspection, scope and detail FAR 43 Appendix D, and was determined to be in a condition for safe operation.			
			 James P. Scott, A&P 2757152

6/2/19

HARTZELL HC-C2YK-1FB

PROP SMOH: 1327.7



N952W

SN: CM1156A

INSPECTED PROP AND HUB. LUBRICATED HUB WITH AEROSHELL #6. RUN UP/OPS CHECK SATISFACTORY.
I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW FAR 43(D) AND HAS BEEN FOUND TO BE IN AN
AIRWORTHY CONDITION AND APPROVED FOR RETURN TO SERVICE.

Jennifer Schindeldecker

Jennifer Schindeldecker AP2748502IA

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
10/10/2016			N952W
	Hartzell HC-C2YK-1FB	S/N: CM 1156A	ENG TSMOH: 437 PROP TT: 1271
			Lubricated propeller hub with Aeroshell 6 grease, dressed out small nicks and abrasions.
			I certify this propeller has been inspected in the scope and detail of FAR part 43 appendix (d) and has been found to be in an airworthy condition and approved for return to service.
			
			Dan B Davis A&P 469786177
5/21/2018	TSMOH: 41.7		HARTZELL HC-C2YK-1FB SN CM 1156A
	TT: 1295.7		LUBRICATED AND INSPECTED PROP AND HUB.
			I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW FAR 43 APP.(D)
			AND HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION AND APPROVED
			FOR RETURN TO SERVICE.
			JENNIFER SCHINDELDECKER  AP 27485021A

SMOH SMOH
PROP ENG

12/14/09	834	0	LUBE INSPECT DW LIT (ENG OVERHAUL)
4/3/11	966	132	LUBE INSPECT DW LIT (+132 GAS)
9/20/12	1086	252	LUBE INSPECT DW LIT
6/4/13	1175	341	LUBE AND INSPECT DW LIT
5/16/14	1205	371	LUBE AND INSPECT DW LIT

8/1/2015

N952W

Hartzell HC-C2YK-1FB

SN: CM 1156A

ENG.
TSMOH: 409

TT: 1243

Lubricated propeller hub with Aeroshell 6 grease.

I certify this propeller has been inspected in the scope and detail of FAR part 43 appendix D and is found to be in an airworthy condition and approved for return to service.

Jennifer Schindeldecker

Jennifer Schindeldecker AP2748502IA

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
8/31/97	0.2			INITIAL RUN DWRif
11/28/97	1.7			H1 SPEED TAXI DWRif
11/29/97	1.8			SAFETY WIRE RE-TORQUE DWRif
7/5/98	60			LUBE & 100 HR INSP DWRif
1/2/99	142			" DWRif
1/11/00	291			" DWRif
3/4/01	418			" DWRif
12/2/04		370		" DWRif
4/4/05		406		" DWRif
4/24/06		461		" DWRif (1.5 on Eng)
3/24/07		556 ⁹⁵		" DWRif (95 on Eng)
12/24/07		636 ¹⁷⁵		" DWRif (175 on Eng)
11/26/08		744 ²⁸³		" DWRif (283 on Eng)

4/24/02 REPAIRED Prop (see attached)
 3/12/03 LUBE and ✓ DWRif