

Description of Inspections, Tests, Repairs and Alterations 20 25 TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or TIME SERVICE DATE Repair Facility. (See back pages for other specific entries.) 16MAR 1375 Changed Orland Cillier IAW PA-21-150 Manual Using (1) 48108 or 1 Alter and 6 ets Phillips XC 204-50 motor Oil and checked for leaks Andrew Jardetzky PPL# 3530913 Changed Oil & 6 Her IAWPA-22-150 manual using 11 48108 0:1 filer and 6fs Phill: 45XC 2PW &P motor Oil and clocked for leaks, Andrew Jordetzky PPLH 3530915

YEAR

RECORDING

TODAY'S

TOTAL

20 D/	N7156D Piper PA22-150 S/N: 22-5020 Lycoming 0-320 S/N: L-6280-27 Date: 1 Nov. 2024 A/C Tach: 104.2 Eng. TT: 2878.46 TSMOH: 659.06	YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
# 1 1 2 1 1 1 2 1 3 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4	Performed a 100 hour inspection on this engine using the Piper PA?2-150 Service Manual and Check Sheet. Removed the prop and removed the engine cowlings. Preformed a Compression test performed as follows, #1; 75, #2; 75, #3; 76 and #4; 76. Changed oil and filter using (1) 48108 oil filter and (7qts) Phillips 20W50XC motor oil. Opened filter and sump screen and inspected and no contamination was noted at this time. Checked the magneto timing and adjusted as needed to 25 degrees BTDC. Removed all spark plugs, cleaned, gapped and tested, re-installed with new cooper washers and torque. Installed a new air inlet filter using (1) BA4108 bracket filter. Checked the operation of all engine controls for full travel and smoothness. Replaced The oil pressure hose and the fuel hose. Cleaned, gapped and tested all the spark plugs, re-installed with new cooper washers and torque. Removed the Gascolator bowl for inspection and operation of fuel control valve, Removed the carb bowl drain plug, flushed the carb, re-installed and safety. Performed a ground run, all OP's test, all checked out good at this date and tach. Completed this inspection using the Piper PA22-150 Service Manual and Check sheet. Researched the AD listings using the TDATA program, All AD's are complied with to this date and tach. I certify that this engine has been inspected as per a 100 hour inspection using the Piper PA22-150 Service Manual and that this engine has been inspected and has been determined to be in airworthy condition at this date and tach.		l certify has bee PA22/I	Nov. 20	ming 0- 24 Tach Engine ha ined to be i be manual a	22-150 S/N: 22-5020 320 S/N: L-6280-27 :: 104.2 Eng. TT: 2878.46 TSMOH: 659.06 s been inspected In Accordance with an Annual Inspection and in airworthy condition. All work was performed as per the Piper and check sheef. All AD's are complied with to this date and tach. 22-150 S/N: 22-5020 30 S/N: L-6280-27 31 Septimized to the completion of the com

YEAR 20 DATE RECORDING TACH TIME IN SERVICE TODAY'S FLIGHT TIME IN SERVICE TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20 22 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
N7156D Piper PA22-150 S/N: 22-5020 Engine: Lycoming O-320 S/N: L-6280-27 Date: 19 April 2022 Tach: 21.6 Eng. TT: 2795.86 TSMOH: 576.46 I certify that this Engine has been inspected In Accordance with an Annual Inspection and has been determined to be in airworthy condition. All work was performed as per the Piper PA22-150 service manual and check sheet. All AD's are complied with to this date and tach.	175ep	68,3			Changed Dil and Islter IAW PA-22-150 Mannul using (1) 48108 pilliter and Egts Philips 20W80 X (Mator 9i) and checked for leaky. Inimate slot # Antore Jardetthy 3530915
Vaughn Dowell A&P/IA 3684662	. 19Feb.	23 103.2			Changed 0:1 and filter IAW PA-22-150 Manual using (1) Tempest 4 (108-2 foller and 6 gts Philips 20w-50X C Motoroil and checked for leaks, fll# 3570915 Andrew Jardetzky

YEAR 20 22 RECORDING TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or SERVICE DATE Repair Facility. (See back pages for other specific entries.) 2022 and acud

PA22-150 S/N: 22-5020 N7156D 0-320 S/N: L-6280-27 Lycoming Date: 19 April 2022 A/C Tach: 21.6 Eng. TT: 2795.86 TSMOH: 576.46 Performed a 100 hour inspection on this engine using the Piper PA22-150 Service Manual and Check Sheet. Removed the prop and removed the engine cowlings. Changed oil and filter using (1) 48108 oil filter and (7ats) Phillips 20W50XC motor oil. Opened filter and sump screen and inspected and no contamination was noted at this time. Compression test performed as follows, #1; 76, #2; 76, #3; 76 and #4; 76. Checked the magneto timing and adjusted as needed to 25 degrees BTDC. Removed all spark plugs, cleaned, gapped and tested, re-installed with new cooper washers and torque. Installed a new air inlet filter using (1) BA4108 bracket filter. Checked the operation of all engine controls for full travel and smoothness. Inspected the Gascolator and flush the carb. Replaced the alternator adjuster arm attach bolt, tighten and safety. Performed a ground run, all OP's test, all checked out good at this date and tach. Completed this inspection using the Piper PA22-150 Service Manual and Check sheet. Researched the AD listings using the TDATA program, All AD's are complied with to this date and tach. I certify that this engine has been inspected as per a 100 hour inspection using the Piper PA22-150 Service Manual and that this engine has been inspected and has been determined to be in airworthy condition at this date and tach. Stacy Blackburn 3318734A&P

Description of Inspections, Tests, Repairs and Alterations

RECORDING TODAY'S TOTAL


Engine Record General Information		
Manufacturer Ly Coming Serial L-6280-27	Model Type Ce	D-32D
This engine is currently installed in aircraft:		
Minimum Octane Fuel	Oil Grade: Summer	Winter
Magneto Time	Point Setting	Firing Order
Spark Plug Gap		
Manufacturer's Recommended Overhaul at		



N7156D

PIPER AIRCRAFT CORP.,

LOCK HAVEN, PA.



TOP-MAJOR (Cross out one) Eng. Serial No. Ship N C Date	
	REMARKS
N7156D Piper PA22-150 S/N: 22-5020	17Jan22 Dil Charge & withhetix 15w-20 Tach. 1,6
Engine: Lycoming 0-320 S/N: L-6280-27	- Autre 3 Satelles 3530715
Date: 13 April 2021 Tach: 2727.88	- Staring Staring
Eng. TT: 2727.88 TSMOH: 508.48	
I certify that this Engine has been inspected In Accordance with an Annual Inspection	
and has been determined to be in airworthy condition. All work was performed as per the	
Piper PA22-150 Maintenance Manual and Check Sheet. All AD's are complied with to	
this date and Tach.	
Janes a Vowel	
Vaughn Dowell A&P/IA 3684662	
Labor & Material Certified by	

.....

ANNUAL INSPECTION ENGINE

REGISTRATION: N7156D MODEL: Lycoming 0-320

SERIAL NO.: 22-5020 SERIAL NO.: L-6280-27 SMOH: 490.1

Engine Serial

This Annual Inspection completed on this date in accordance with FAR 43 Appendix D check list.

- Engine controls inspected for proper operation and lubed.
- Cleaned & gapped spark plugs. Compression checked @ #1 70 /80, #2 76 /80, #3 74 /80, #4 74 /80.
- Inspected Propeller. See Prop log.

"I do hereby certify that this ENGINE has been inspected IAW an Annual Inspection and was determined to

be in Airworthy Condition".

TOTAL TIME: 2709.5

CHECK

A&P# 1A 184010 Date 3-10-20

N7156D Piper PA22-150 S/N: 22-5020 Lycoming 0-320

S/N: L-6280-27

Date: 13 April 2021 A/C Tach: 2727.88 Eng. TT: 2727.88 TSMOH: 508.48

Performed a 100 hour inspection on this engine using the Piper PA22-150 Service Manual and Check Sheet. Changed oil and filter using (1) 48108 oil filter and (7qts) Phillips 20W50XC motor oil. Opened filter and finger screen and inspected and no contamination was noted at this time. Compression test performed as follows, #1; 74, #2; 78, #3; 76 And #4; 76. Checked and adjusted the magneto timing as needed to 25 degrees BTDC. Removed all spark plugs, cleaned, gapped and tested, re-installed with new cooper washers and torque. R&R the air inlet filter using (1) BA4108 bracket filter. Replaced all (8) push rod tubes with serviceable tubes, Replaced the (4) exhaust rocker arms with 74636 due to incorrect numbers, check and set the dry tappet clearances. Replaced the throttle cable with a new McFarlane cable P/N MC12693-04. Checked the operation of all controls for full travel and smoothness. Performed a ground run, all OP's test, all checked out good at this date and tach. Completed this inspection using the Piper PA22-150 Service Manual and Check sheet. Researched the AD listings using the TDATA program, All AD's are complied with to this date and tach. I certify that this engine has been inspected as per a 100 hour inspection using the Piper PA22-150 Service Manual and that this engine has been inspected and has been determined to be in airworthy condition at this date and tach.

Stacy Blackburn 3318734A&P

NOTICE. N.

ANNUAL INSPECTION ENGINE

REGISTRATION: N7156D MODEL: LYC O-320 TOTAL TIME: 2655.5

SERIAL NO.: 22-5020 SERIAL NO.: 1-6280-27 SMOH: 436.1

This Annual Inspection completed on this date in accordance with FAR 43 Appendix D check list.

- Changed oil and filter, refilled sump with 8 quarts Philips 10w50.
- Replaced Rocker box cover gaskets.
- Removed 8 spark plugs, replaced with new.
- Inspected engine controls for proper operation and lubed.
- Inspected Propeller. See Prop log.
- Ground ran the engine, leaked checked OK.

"I do hereby certify that this <u>ENGINE</u> has been inspected IAW an Annual Inspection and was determined to be in Airworthy Condition".

ANNUAL INSPECTION ENGINE

REGISTRATION: N7156D

SERIAL NO.: 22-5020 SERIAL NO.: L-6280-27

MODEL: Lycoming O-320 **TOTAL TIME: 2686.9**

Engine Serial

SMOH: 467.5

This Annual Inspection completed on this date in accordance with FAR 43 Appendix D check list.

- Removed oil screen, inspected, cleaned and replaced.
- 2. Changed oil and filter, refilled sump with 8 quarts Philips 10w50.
- Engine controls inspected for proper operation and lubed.
- 4. Cleaned & gapped spark plugs.
- Inspected Propeller. See Prop log.
- 6. Ground ran the engine, leaked checked, OK.

"I do hereby certify that this ENGINE has been inspected IAW an Annual Inspection and was determined to be in Airworthy Condition".

A&P#14 2184210 Date 3-2-2019

CHECK ENGINE CHECK REPORT Engine Serial	Engine Serial ENGINE CHECK REPORT CHECK
OPERATION PERFORMED Date Checked Date Date Checked Che	OPERA PERFOE DATE: 07/12/2016 Total Engine Time Fuel Systems, line and carburetor Lubrication system lines, strainers an TACH: 2626.9 1. Removed Left exhaust manifold, repaired crack on right side and replaced
Cooling system, cowling, Baffles, lines and fittings right and Profession Have seem in specific and rocker arms and Dound to Be in Ayrworthy Condition Ignition, wires, plugs, points and shielding Engine manifold and motor mount, bolts and nuts Propeller Condition & Alignment Oil changed answer Yes or No	2. Removed Muffler shroud and inspected as per AD 68-05-01 R1. 3. Replaced burned out EGT probe with new Westach EGT probe. 4. Drained oil and replaced with 8 quarts Philips 10w50. 5. Replaced oil filter with new Champion oil filter. 6. Removed all spark plugs, cleaned, gapped and replaced. 7. Checked compression: #1=80/80, #2=79/80, #3=80/80, #4=79/80. 8. Removed Brackett Air cleaner element and replaced with new. 9. Removed vacuum regulator and replaced with new. 10. Removed Prop and replaced after overhaul (see Prop log). 11. Replaced alternator belt with new Gates belt.
Certified by E License No. Address NOTICE:—Making false entries in this hands and the property of the Parally of the Parall	Certified by has been inspected in accordance E License No. with a Hourse inspection and was determined to be in an airworthy condition. NOTICE:—Making false entries in this beak is a widely

22-

Completed Annual inspection this date. Inspection in accordance with FAR 43 Appendix D check list. Compression check as follows; #1 78/80, #2 78/80, #3 78/80 and #4 74/80. Cleaned, gapped and rotated spark plugs. AD2009-26-12 ECI Cylinder Assemblies does not apply to serial numbers installed

at this time.

I certify that this engine and propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

James E. Crisman A&P3220001IA For

Poudre Aviation Inc. 633 Buss Ave. Greeley, CO 80631 970-378-8994

PEMARKS

DATE: 2/21/2011 TACH: 2401.8 TOTAL TIME: 2401.8 N#: 7156D MODEL: PA22-150 S/N: 22-5020 ENGINE MODEL: O-320 S/N: L-6280-27 TOTAL TIME: 2401.8 SMOH: 182.4

PROPELLER MODEL: 74DM6 S/N: K12352 TOTAL TIME: UNK SPOH-Completed Annual inspection this date. Inspection in accordance with FAR 43 Appendix D check list

Compression check as follows: #1 78/80, #2 78/80, #3 78/80 and #4 74/80. Changed oil and filter filled sump with 7 ats. Aeroshell 100W.

I certify that this engine and propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

James E. Crisman A&P3220001IA Poudre Aviation Inc. 633 Buss Ave. Greeley, CO 80631 970-378-8994

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

SIGNATURE

	erial				N C						
Date R. P. M.		Ground T Hrs.	ime Min.	Air Tim	ne Min.	Total Tir					
Year Mo. Day	Ground	Air									
Dec 14,00	2219.4	5 cen	Jurafer	res	neveel	ton	Rewor	k.		51	
- nos	talles	ori	cival c	ende	valor r	en y	04 ad ,0	est.		0	
1/0		-	Just	4	usta	2580	1349/A			15	
410/08	INSta	elede	OH Ch	bur	ator-si	e 8	130-3.		1		
Kun	up !	Leak	Chee	Kt	agusto	neu	tok.			10/	
			Gle	X	Luston	258	0319/11.				
1.								-		0	
2/11/07	2227		Oil Chan	apal.	Giter che	ech no	plenisher			Sa	
-/10			with min	eval	oil	CLIC	purisace		7	2008	
3/9/08	2258,	5	Oll Chang	e, fil	ter change	eved	lenished		5	-DE	
			with Ago	shell	15/50 8	2+5,			+	-	
					Jerey &	Ban	2231680 A	OP_			
										-	
	TOTAL TIME							-		_	
NOTICE:-M	aking false ent	ries in this h	ook is a violation	of the Ci-	vil Aeronautics Act	of 1938 pt	michable by Civil	Penalty.		NOTI	

ENGINE LOG REMARKS SIGNATURE orey & Ban A+P 2231680 ket BA 4108 Air filter replaced TACH= 2328.65 SMOH = 109.22 : I CONTIFY THAT THIS BUGINE WAS WEDECTED in Accordance with an Annual inspection AND Approved FOR PETURN TO SOLVICE. -Making false entries in this book is a violation of the Civil Agrangation Act of 1000

Eastern Slopes Aviation

DATE: December 13, 2007 TACH: 2219.43 TSMOH: 0.00

Engine Log

Removed engine from N7156D. Disassembled engine. Sent case to Crankcase Services for overhaul. Sent crankshaft, camshaft, all gears, shafts, lifter bodies and connecting rods and push rods to D&S Cam Corp for overhaul. Reassembled engine using all new crankshaft bearings, connecting rod bearings, new oil pump housing, shaft and gears. All new gaskets and seals installed. Disassembled magnetos and replaced points, capacitors and impulse coupling. Set Egap and timed to engine. Installed new ignition harness and all spark plugs. Installed overhauled carburetor. Flushed and pressure tested oil cooler. Inspected exhaust IAW AD 68-05-01. Replaced engine pressure hoses with new assemblies complying with AD 72-21-03. C/W AD 04-10-14C1 by installing new bolt and tab. Installed new rod bolts, nuts and camshaft gear bolts. Installed all new ECI Titan nickel cylinders and pistons. Installed new piston pins and plugs. Engine assembled. Serviced with 20-50 mineral oil. Installed Casper Labs oil filter

housing – see 337. Installed Reiff sump heater. Engine ground run and idle and idle mixture adjusted. All work done IAW Lycoming Direct Drive overhaul mapual. Also see attached

overhaul tags and parts list. I certify this engine has been returned to service at this time.-END-

N7156D

Eastern Slopes Aviation


DATE: December 13, 2007 TACH: 2219.43 SMOH: 0.00

N7156D Engine Log

Performed hot compression test: (1) 78 (2) 74 (3) 76 (4) 76. Lubed all controls, checked gascolator. Checked magneto timing. Inspected engine mount. I certify this engine has been inspected IAW FAR 43 Appendix D annual inspection and has been returned to service at this tim.-END-

Signed: Joel K. Lusky 2580319 IA

	Date	R. P. M.	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs.	Min.		REMARKS	(-
Y	ear Mo. Day	Ground Air						REMARKS	SIGNATURE
			Placerville Avia 3501 Airport Placerville, Ca S	Rd		Ē	-	16 May 07 Tach 2174,5 Ou Change and screen Cheaked Filled with 8 quants amshell 15-50	
	S.N. : L-6	YC 0-320 3280-27 .: N7156D			Tach: 2137.8 TTSOH: 950.8 Date: 11/02/06	-	- -	Jesoy S.Ban #4P 2231680	
	ANNUAL INSPECTION. Drained Oil and Filled Eng with 8 Qts Aero Shell 15/50. Removed Oil Screen for Insp, no metal or contaminets found. Oil Screened installed. Cleaned Spark Plugs. #1 70/80; #2 65/80; #3 70/80; #4 70/80. Dressed and Pianted Prop.								
	I Certfy t Determin	hat this Engine and ned to be in an Airw	Signed: Lay C	al 11	ection and was	s – – – – – – – – – – – – – – – – – – –			
_	NOTICE:_M	TOTAL TIME	s book is a violation of the Ci	vil Accomputies Act of 1938 p	unishable by Civil P	lanoltu	-	NOTICE.	The street of the street



Date R. P. M. Year Mo. Day Ground	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs. Min.				REMARKS	SIGNATURE	
REG.: N7156D MODEL: Piper PA22-150 S/N: 22-5020 W/O: 39701 Inspected engine and control (2) 72/80, 3) 70/80, 4) 78/80 engine oil with 8 quarts of A and checked for leaks; none I CERTIFY THAT THIS EN	Aurora Avia Aurora State A 14338 Stenbock Way NE Aurora, OR 97 (503) 678-51 ols for proper operation and I 0. Retimed magnetos and cleroshell W80. Replaced alte e found. ADs checked through GINE WAS INSPECTED IN A BE IN AIRWORTHY CONDITIONAL STATES AND	irport	spark plugs. Change th new. Ground ran e	2012.8 S/N W/C 825.8 Insp pair d I C engine me.	DEL: : : : : : : : : : : : : : : : : : :	ade backs. Checke Y THAT THIS PRO ON AND FOUND	Aurora Aviation Aurora State Airport 14338 Stenbock Way NE ~ PO Box 127 Aurora, OR 97002 (503) 678-5172 ner for nicks, dents, and scratches. Blender ed ADs through bi-weekly 2001-19; none du OPELLER WAS INSPECTED IN ACCORDA TO BE IN AIRWORTHY CONDITION. A&P 574302965 IA	ue at this time. ANCE WITH AN A	
TOTAL TIME		P 574302965 IA					s in this book is a violation of the Civil Aeronautics Act		

Engine Serial

Engine Serial		N C		ENGINE LOG
Date R. P. M.	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs. Min.	DAGINE EUG
Year	ir			REMARKS SIGNATURE
Mo. Day Ground Ai	PEMOUED ACC OIL PUMP GER IN ACC HOUSING INSTAUED SKY INSTAUED SOA A INSTAUED SLICKI COOLED PER 33 BY INSP. NO PIT PROFECIED HA ANNUAL INS TO BE IN AN	HOUSING & IN AS & HOUSING, DI IS PER SERVICE PRIEW WITH AID TEC STANTER PO TET AIRFUTER PO TENNATOR PER THAG KIT KY317, TO BEHIND "4 EY TO FOUND THIS E VE BEEN INSA PECTIONS AND U AIRWORTHY 10	TILLED 18 HOLE INSTRUCTION 96-09-10; PL STC SE OCOZERNY PLSTC SA 71 GL STC SA 334 SW RELOCATED OIL C, CHUAD 98-02-08 PLOCATED INWAN PETED INWAN PETED INWAN PETED INWAN PETED INWAN	REMARKS 3-18-00 TT 1934.06 CHANGED ENGINE OIL -ADDED ALEOSHELL 100W PLUS Quil G. While Comm. Pilot 1093154 CERTIFY THAT THIS (AIRCRAFT ENGINE) HAS BEEN INSPECTED IN ACCORDANCE WITH A COMP CKD 1/80 2/80 76/2 (ANWAL) INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A.D.'S INCORPORATED TO 81-WEEPLY SUPPS 311/00 OIL TYPE AGRO SHELL 100W SIGNED Location Location GORDON P. RICHARDSON
TOTAL TIME		A 317		A & P 1505021
NOTICE:—Making false entries in the	his book is a violation of the Civ	il Aeronautics Act of 1938, pu	inishable by Civil Penalty.	NOTICE: Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty
				NOTICE:—Making false entires in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Paralty

Piper N 7156D WAS	SAME S STATE
parchased Nov1,1982 by	
TERRY & Judy OEstreich	
Total time on ongine	
The second secon	
1916:00 hours , 729 hours	
Since MAJOR OVER haul	
SEE NEXT PAGE 7	

ENGINE LOG Engine Serial Date Ground Time Air Time Total Time R. P. M. Min. SIGNATURE REMARKS Year Mo. Day Ground Air TOTAL TIME NOTICE:-Making false entries in this book is a violation of the Civil Assessation And at 1828, purishable by Civil Penalty. NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Engine Serial	ENGINE LOG
Date R. P. M. Ground Time Hrs. Min. Hrs. Min. Time Hrs. Min. Hrs. Min.	REMARKS
Year	1973. SIGNATURE
# 1/17/72 Removed coul appeal and gaged plugs charlesd	May 6-1973 - 100 HR INSPECTION - Changed OIL Rotilled 10 w acroshell
Compression checked may and set finish thingel och,	CLEANED SCHOOLS - REPLACE All Push and HOUSING SEALS
Cheeked and cleaned all spreams, cheeked all ambroce	Rocker Cover GASKeTS = 4 New Exh, FLAKEE GASKETS.
for proper fravel Tack reads 1834	KODAIR exh PIPE DY WeldING Checked COMPLETE
I certify this Emsons, has	- exh system Replaced Three OIL live conte-
been inspecial That India	- SERVICE GENERTOR FINSTALL of NEW BOUSHOR - POFUNCH
	- AFT, SIde OF PROP INSTAlled used caph wast
condition. Total time 834 I certify this Rque has	5 hrovd. At 9# 122923 (James a With
koley M. Cren been inspected in accordance	
Robert M. Grier	6-6-73 I certify this & ugine has been inspected in
A&P 2001759 a 2.00 and lone.	of accordance with an annual of rejection and was
1 De Kurmon	187/200 A.I. #722923 Clarence W Witter
	- Comment will to
Wilber H. Thurman 1279960 I.A.	
NOTICE:—Making false entries in this book in the land of the land	

Engine Serial	ENGINE LOG	
Date R. P. M. Ground Time Hrs. Min. Hrs. Min. Total Time Hrs. Min. Year	REMARKS : 3 SIG	NATURE
Year Mo. Day Ground Air	7	
11-15-69 Engeri genen 100 he shed this dale. 3		
Spark plugs clience, cheber + gappel. mayfle, " " "	12-14-10 100 ku casa 1 200	noi A.
checked Starks remark + suiceschurch 987		44
question of moral dericale. Or gene		96
washed down and would chessed to so to	mitted Sport plays climed 10	40 to
for Jeveral populating	Gopped + Cheshel. Feel flow & & & o.	d d d
Thelke Jauren AP 12 14960 18 5 3	Chicked.	ne
The same of the sa		in 3
	1 P 1219960 50	A C C C
वं भू भू वि	P1219960 200	日本の中日
THE STATE OF THE S	- LAS	S C C C
म मिल्लिस स्ट्रा	7 17	1 th
9 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		1000
	7 00+	7 L
TOTAL TIME	7 H.D.B	इ त ह
NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, nunishable by Civil Penalty.	Nome	

TT, Engin 499 5 Mott	SIGNATURE
9/30/68 Tack 1687.04 Certify that The me	me has been
suspected in accordance with	unual lugaretic
all Junes cheep, Juel & oil. ne	w Rocke But quelt
installed muffer friesure se	bucked by Ellight
Flying Service Vernon Kas	to IA1381213
THE REAL PROPERTY OF THE PROPE	NEGATION OF THE PARTY OF THE PA
Haran Carlotte Control of the Contro	

Date		R. P. M.		Ground Time Hrs. Min.		Air Ti	ime Min.	Total Time Hrs. Min.	
ear Mo.	Day	Ground	Air						
		Mississip	pi Aircrat	t Co.	-				
	-	Fort Ma	dison, lov	/a Phone	372-16	9			
		I certify	that this a	ircraft has b	een ins	pected			
		in accord	ance with	a PEROI	o, c				
		inspectio	n and wa	s determine	d to be	in air-			
		worthy	condition.						
		Date 8	-10-66	Time 14	153	TACK T	IME		
			60	ego	2 2	1. ertil	1 - 00	2	
211		Mechani		auth	da	pha d	6030	~~	
		OOIL	WITH	AEROSH		TEANED	SCRI	EENS.	
,	NEO	+ ange	o flug	S, CHECK	ED C	mpres.	1	-TIMIN	60
0 1	KED	EXHA	UST 5X			FIERS 1		EAKS.	
	ACE			TO DIL	PRECE	URE GI	LUCE.		
A	LIE	DWITH	MONS	TE 64-	27-2	ONCAR	2B FL	ONTH FL	CA7
עודו	2,								
OTT		TOTAL TIM						unishable by Civil	

REMARKS	SIGNATURE
Mississippi Aircraft Co.	0.00
Fort Madison, lowa Phone 372-1699 I certify that this altern has been inspected	peroskell 40 W.
certify that the ENCE	AD.66-5-4 Previous
inspected inspected	C/W
in accordance with a Change	Service instruction
inspection and was determined to be in air-	1088B C/N/
worthy condition. 409 S.M.O.H	Dressed leading & toes
Dare 9-13-67 - 1591	of broke and helper hinter
- Ilmes	of for the state of the state o
mediante Jamel OR, mertel	
- and 200302	
and and a sea	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

REMARKS	SIGNATURE
Jan 39.66. Shame Qis. filled w/ texpo 80-A	
A bull po mulli exercity Repair Carb	
this blast table of RuBrown 48 P15 24689	
*	
- CAR OF TO LIBERT	Salar Sa
The state of the s	Mental Control
	WENT AND THE PROPERTY OF THE
WE SEE TO SHOULD BE WANTED TO LIKE HER THE TO SEE	Mark Control
- Commence & State of the or Market	というないなり またなながら
The same of the same of the same of	apartin More Compared
A THE REAL PROPERTY AND THE PROPERTY	the trial particular transfer in the
	. 3 464

Date R. P. M.		Ground Time Hrs. Min.		Air Time Hrs. Min.		Total Tim Hrs.	Min.		
Year	Day	Ground	Air						
12/0	4	Tach	time	1278 Krs	1.	-01 2 8			1 10 0
, ,		100 Ar	inspe	etion co	mpli	ted this d	ete, c	·lean = 9	of plugo
ch	ech	may	neto p	einto Et	min	, clean	oil	air der	beaut
mo	Re	comp	usion	e test,	chi	ck muy	fler	replicant	1 Pow
Cher	Rig	revers	to a co	tester 1	mes	car repli	Eng:	Caffe 14 A	ling PCW
A N	NITE	- G7-1		ierb len	y loc.	AD,60-	No 2	mag peer o	1
					1 34	-		I Coleman	1.
				and the latest terms of th	· .	evant	The Females	ال فينا فينا	2000
				17C.	Top line.	Printi		1 142	3/90
				100	P Tille	10000	19	nds /	1000
				1/2		Up	9 6		
				1111	1 200	OF STUDING			
-					1-1	112			
-		TOTAL TIM	/TE			ivil Aeronautics Ac			

REMARKS	SIGNATURE
at 26-65 tach 1348	
Checked compression, Installer	P H new sleep
Cleaned and reapped other for	ic, checked
engen for al lacks	sheeked longs
lungles elected Starter a	al generator
Screen cheeked man tim	all feltie and
Checkers and the auto Ott	and poents
Cherped hist mull med	de system.
I certify that this 2	
inspected as remired by a sold of the	
inspection and is airworthy	
Hand Per Jord 1487374 TA	
AGONAIR SERVICE	
MUNICIPAL AIRPORT	
NOTICE:—Making false entries in this band will idealing of the Civil Asymptotic	

REMARKS	SIGNATURE
6/21/64 task 124/	Cales Teach ada
I sin wald	Charles Margarette et
Alabertal 1017	And seed to be
of change 1000 Bree	
Agonais:	33448

10/3/63 Tach time 1187 Pup.	SIGNATURE
- complete alabout Romblet 141:1.	lete = new exhaust podiom
- aprile quider, all Valvi spin	was new means and paris
shaft, hydroulie lifter assi's o foolies.	new Obre to be an
1 mario es alnerator Dell	Was use no Because a cole le conti
Centification Tag attached), over find mag comply with & P Note 62-4-2-Long Lok kit, over	hour starter every
I manuallit all stell by to as her	attention later committee
lifter Fodies # 12877 + plunger cosys # 12876 install	d. Per further information
W.O. # 11766 on file at this station certify the	thisenamewas inspected
do regarred	by a Periodic inspection and invover in the server in the Server
ice. A. & P	Mechacker Perhal A207980
ELLIOIT	FLYING SERVICE, Inc.

5 10 1000 REMARKS SIGNATURE inspected as inspection and

NOTICE: Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

REMARKS	SIGNATURE
9/9/11 J. h 2. dr 1049	ha
-100 hr upip. Oping. as p	in siper
- form for continua	tion of
- Beplaced B mag points	Chand
- gapaly plugs. Change, sa	cerso
- Sucked couling beffeld &	Rrope.
- certify that this Engine We	is inspected
as required by a periodic	epaction and
is airworthy	0
A. & P. Mochanic Chef Park	21H237900
ELLIOTT FLYING 05	WA. Inc.

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

1-13-61 tack time 950	
- 100 hr Insp Completed for Continuouse of	stravorehness cert
made made to be flowers theeles down of state	1 houses element oil
+ card all screen cland & gazed sport solus	replaced muffler polar
Se 4 bracket on the vil localer replaced only heart allowed	people couling where medded
Let bracket on the vil coaler replaced on heat should replaced on a nates on land of the for Al nates a	comply in Near of A/C boy
Leady	
	AYP William R Shift #1455049
I certify that this	Wan ins
	igna was mepeoted
as required by a	erisdie Monaction and
is airworthy.	
A. & P. Mechanic C	11:01
Ar & T. Mounding Ch	ster tarbo /A-237900
ELLIOTT FI	
TAUR' W.	PORT, IOWA

REMARKS

SIGNATURE

3-4-1960 plus . Retimed & mag NOTICE:-Making followers in of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

7-13-59, TACH. TIME 751 HRS.	
- 100 HR. INSPECTION COMPLETED FOR	CONTINUANCE OF
DIRWORTHINESS CERT. DRAPNED OIL + CLA	ONED OFL & APR
SEREENS, CLEANED + CAPPED SPARK PLUG	CHECKED MAG DOLLITS
ESLARTER Y GEN. BEUSHES PERIODED 1. H	SIDE FRONT FULLENE
THEFRE TIGHTENER ALL ROCKER COVER SO	REAS CHECKED
ENGINE CONTROLS & MOUNTS, COMPLIED	WITH AD NOTE 59-9-10
as LISTED IN REAR OF LOG. WASHED DO	UNTRON UP. O.K.
I certify that this Engin	- was inspected
	· · · · · · · · · · · · · · · · · · ·
as required by a 100 /	e. mspection and
is airworthy Penidue FA-	x37900 Chet Pares
	Con Asp# 138601
	G SERVICE, Inc.
NOTICE:—Making false entals in this has it a violation of the Civil Agrangatics	RI, IOWA
Making foles and the title to the willeties of the Civil Assonauties	Act of 1938 nunishable by Civil Penalty

REMARKS	SIGNATURE
3-4-59 Stold time on tack (I certify that this aircraft has been inspected fly Will in accordance with a periodic inspection and AFP 12 was determined to be in airworthy condition	17:00 hr lad E Kimmel 63 490.
— O NO MA CHA WOLDAY ODINGEROSE	

-5-58 Total time on tack 407:00 I certify that this aircraft has been inspected fing qualled in accordance with a periodic inspection and was determined to be in airworthy condition a on recording certify that this aircraft has been inspected in accordance with a section and was determined to be in airworthy condition

REMARKS

SIGNATURE

1-1-57 Total lime on lack 12	2:00
I certify that this aircreft has been inspected	
in accordance with a remode inspection and	
was determined to be in airworthy condition by Will	of E Kenne At 126349
2-14-57 Holal Time on to-1 96	1.75
I certify that this aircraft has been inspected	
an accordance with a periodic inspection and Training	Villand & Kennel
was determined to be in airworthy condition	2-1-34 d 2
	63110.
2-3-58 Total Time on tack 36	8:06
Court's a language	0.00
an accordance with a francis inspection and Al- O	allal 5 X of
was determined to be in airworthy condition AP/	63490.
The state of the s	67-110.

Instructions for the Use of Log Book

1. This log must always accompany the engine to which it refers. 2. No pages shall be torn from Log Book. No erasures, and

all entries to be made in ink.

3. Original entries shall be made and signed by manufacturer or seller. All other entries shall be made by Pilot, Chief Mechanic, or other competent person authorized to do so.

4. On journey, the pilot is responsible for carriage of Log Book and entries or omissions therein. Failure to do so will be considered a serious neglect of duty.

5. Before departure on journey, pilot is personally to ascertain that entries in log have been made are correct, and then sign certificate to the effect. 6. Special data such as manufacturers notes, test data, recondi-

tioning, etc., should be affixed to stubs provided for that pur-

pose in the back of this book.

7. CAA-18-1 Repair and Alteration forms listed on last page. 8. This log book shall be available and produced, on demand of anyone so authorized.

PIPER AIRCRAFT CORP.-LOCK HAVEN, PA., U. S. A.

]	ENGINE LOG N. 7156 15
MANUFACTURER Name Aug Con	Manifold Pressure Normal Maximum Rotation of Propeller License No. License No. License No. License No. License No. License No. Aveca Maria No. Z. 6280-27 Maximum Rotation of Propeller Date
Model 0-320 10 274	H. P. 150 Serial No. 2 6280-27
Stroke 3.875 Bore 5.125	Manifold Pressure Normal Maximum
R.P.M. Normal	B.H.P. Normal
Gear Reduction Ratio	Rotation of Propeller . Clockwise
Certified Correct	Date
OWNER Name	violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.
NOTICE:—Making false entries in this book is a	violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.