



Status Report

PHENOM 300

S/N 50500167 N16DF

OWNER: SOLAIRUS AVIATION
ADDRESS: 201 1ST STREET
PETALUMA CA 94952-4290
OFFICE: 817-999-1950
FAX: 877-455-5997

OPERATOR: SOLAIRUS AVIATION
ADDRESS: 201 1ST STREET
PETALUMA CA 94952-4290
OFFICE: 817-999-1950
FAX: 877-455-5997

ANALYST: ANDREY KORSUKOV
EMAIL: AKORSUKOV@CAMPSYSTEMS.COM

514-636-2020 (OFFICE)
514-636-7866 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT	SERIAL/REGNO: 50500167/N16DF	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
-----------------	-------------------------------------	--------------------------	------------------------------

CERTIFICATION DATE: 01-AUG-2013

LAST ACTUALS:

2396.4	A/C HRS	as of 28-DEC-2022
1359	AFL	as of 28-DEC-2022

ENGINE NO. 1	SERIAL/PART: PCE-DG0338/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	----------------------	---

INSTALLED ON: 05-SEP-2013

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

2396.4	ENG. HRS	as of 28-DEC-2022
1359	ENC	as of 28-DEC-2022

ENGINE NO. 2	SERIAL/PART: PCE-DG0339/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	----------------------	---

INSTALLED ON: 17-SEP-2013

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

2396.4	ENG. HRS	as of 28-DEC-2022
1359	ENC	as of 28-DEC-2022



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA GENERAL										
Z210-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: AMM 05-41-00		PKG:87		
Z210-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service	ATA:--
	MOS	20-Aug-18	120 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
						PROC. REF: AMM 05-41-00		PKG:87		
Z220-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service	ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
						PROC. REF: AMM 05-41-00		PKG:84		
Z220-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: AMM 05-41-00		PKG:87		
Z230-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service	ATA:--
	MOS	20-Aug-18	120 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
						PROC. REF: AMM 05-42-00		PKG:87		
Z230-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: AMM 05-42-00		PKG:87		
Z240-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: AMM 05-42-00		PKG:87		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA GENERAL										
Z240-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION									Service ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-42-00										PKG:84
Z310-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION									Service ATA:--
	MOS	20-Aug-18	120 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-43-00										PKG:87
Z310-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION									Service ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-43-00										PKG:87
Z320-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION									Service ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-43-00										PKG:87
Z320-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION									Service ATA:--
	MOS	20-Aug-18	120 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-43-00										PKG:87
Z330-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER									Service ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-44-00										PKG:87
Z330-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER									Service ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-44-00										PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA GENERAL										
Z340-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service	ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-44-00							PKG:84			
Z340-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-44-00							PKG:87			
Z410-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-46-00							PKG:87			
Z410-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-46-00							PKG:87			
Z430-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service	ATA:--
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-46-00							PKG:87			
Z430-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service	ATA:--
	MOS	20-Aug-18	120 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-46-00							PKG:87			
Z500-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service	ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-45-00							PKG:84			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA GENERAL										
Z500-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS									Service ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-45-00										PKG:84
Z700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY									Service ATA:--
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-47-00										PKG:84
ATA 00 - INFORMATION										
E53E-160530	NO. 1 ENGINE - REVIEW PW535E MM REV 11.0									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF E53E										
E53E-160530	NO. 2 ENGINE - REVIEW PW535E MM REV 11.0									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
PROC. REF: RCF E53E										
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16									Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-160520										
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM									Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-160705										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-160705-1										
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-160822										
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-161022										
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-161122										
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-161122-1										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55-161202										
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18								Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55										
EM55-190218A	REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF EM55										
EM55-210514-ALS	REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
EM55-211103-SMR	REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021								Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
EM55-220505-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED MAY 05/2022 FOR EMBRAER PHENOM 300							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
EM55-220630-CAMP ADJUSTMENT		REVIEW EMBRAER EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED JUN 30, 2022							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF -										
EM55-220812-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-505 - PHENOM 300							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
EM55-221017-AWL		REVIEW EMB-505 - PHENOM 300 AMM - PART IV - AIRWORTHINESS LIMITATIONS (AWL) REV 1 DATED OCT 17/2022							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
EM55-221103-SMR		REVIEW EMB-505 - PHENOM 300 AMM - PART III - SCHEDULE MAINTENANCE REQUIREMENTS (SMR) REV 5 DATED NOV 03/2022							Service	ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
EM55-230201-CAMP ADJUSTMENT		REVIEW EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED FEB 01, 2023								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
EM55-230216-CAMP ADJUSTMENT		REVIEW CAMP ADJUSTMENT FORM DATED FEB 16/2023 FOR EMB-505 - PHENOM 300								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
PROC. REF: RCF 00										
ATA 01 - LIMITATIONS										
01-00-DOC-001 ^U		AIRCRAFT REGISTRATION RENEWAL								Service ATA:01
	MOS/MSC	27-Jun-18	DUE		30-Jun-24 (M)		438 d			
	HRS									
	AFL									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-30-01		800 FH MAINTENANCE PACKAGE								Package ATA:05
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)	Adj -.4	2921.5	2951.5	525.1 (+30)			
	AFL	1220								
PROC. REF: SMR 05-30-01										
PKG:1										
05-30-10		1600 FH MAINTENANCE PACKAGE								Package ATA:05
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)		2711.12	2741.12	314.7 (+30)			
	AFL	555								
PROC. REF: SMR 05-30-10										
PKG:10										
05-30-20		2400 FH MAINTENANCE PACKAGE								Package ATA:05
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)		4179.4	4209.4	1783 (+30)			
	AFL	1007								
PROC. REF: SMR 05-30-20										
PKG:20										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-30-40	3200 FH MAINTENANCE PACKAGE									Package ATA:05
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)		3200	3230	803.6 (+30)			
	AFL	0								
PROC. REF: SMR 05-30-40										PKG:40
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	18-Aug-18	60 (+1m/-1m)		18-Aug-23	18-Sep-23	121 d (+31)			
	HRS	1321.5	3200 (+30/-30)		4521.5	4551.5	2125.1 (+30)			
	AFL	673								
PROC. REF: SMR 05-30-42										PKG:42
05-30-50	5600 FH MAINTENANCE PACKAGE									Package ATA:05
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)		5600	5630	3203.6 (+30)			
	AFL	0								
PROC. REF: SMR 05-30-50										PKG:50
05-30-60	6400 FH MAINTENANCE PACKAGE									Package ATA:05
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: SMR 05-30-60										PKG:60
05-30-80	12 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	18-Aug-22	12 (+1m/-1m)	Adj 9d	27-Aug-23	27-Sep-23	130 d (+31)			
	HRS	2308.8								
	AFL	1307								
PROC. REF: SMR 05-30-80										PKG:80
05-30-81	24 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	27-Aug-21	24 (+1m/-1m)		27-Aug-23	27-Sep-23	130 d (+31)			
	HRS	1988.6								
	AFL	1157								
PROC. REF: SMR 05-30-81										PKG:81
05-30-82	36 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	21-Aug-22	36 (+1m/-1m)		21-Aug-25	21-Sep-25	855 d (+31)			
	HRS	2308.8								
	AFL	1307								
PROC. REF: SMR 05-30-82										PKG:82

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-30-83	48 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	27-Aug-21	48 (+1m/-1m)		27-Aug-25		27-Sep-25	861 d (+31)		
	HRS	1988.6								
	AFL	1157								
PROC. REF: SMR 05-30-83										PKG:83
05-30-84	60 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	20-Aug-18	60 (+1m/-1m)		20-Aug-23		20-Sep-23	123 d (+31)		
	HRS	1321.5								
	AFL	673								
PROC. REF: SMR 05-30-84										PKG:84
05-30-87	120 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	01-Aug-13	120 (+1m/-1m)		01-Aug-23		01-Sep-23	104 d (+31)		
	HRS	0								
	AFL	0								
PROC. REF: SMR 05-30-87										PKG:87
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE									Package ATA:05
	MOS	01-Aug-13	T:120 (+1m/-1m)		01-Aug-23		01-Sep-23	104 d (+31)		
	HRS	0								
	AFL	0								
PROC. REF: SMR 05-30-90										PKG:90
05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-805	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)									Service ATA:05
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-805	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)									Service ATA:05
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-810		NO. 1 ENGINE - ENGINE IMMERSION IN WATER							Service	ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-810		NO. 2 ENGINE - ENGINE IMMERSION IN WATER							Service	ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-811		NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service	ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-811		NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service	ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-812		NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service	ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-812		NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service	ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-813		NO. 1 ENGINE - LOSS OF OIL							Service	ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL									Service ATA:05
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL									Service ATA:05
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-823	NO. 1 ENGINE - FUEL CONTAMINATION									Service ATA:05
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-823	NO. 2 ENGINE - FUEL CONTAMINATION									Service ATA:05
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
05-50-00-210-824	NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE									Service ATA:05
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-210-824		NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE							Service	ATA:05
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 05-50-00										
051254		NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package	ATA:05
	MOS	19-Aug-22	12 (+30d)		19-Aug-23	18-Sep-23	122 d (+30)			
	HRS	2308.8	800 (+10%)		(3108.8) 3108.8	3188.8	712.4 (+80)			
	ENC	1307								
PROC. REF: MM 05-20-00										
PKG:1										
051254		NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package	ATA:05
	MOS	19-Aug-22	12 (+30d)		19-Aug-23	18-Sep-23	122 d (+30)			
	HRS	2308.8	800 (+10%)		(3108.8) 3108.8	3188.8	712.4 (+80)			
	ENC	1307								
PROC. REF: MM 05-20-00										
PKG:1										
H140-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service	ATA:05
	MOS		120 (+1m/-1m)							
	HRS									
	AFL									
PROC. REF: AMM 05-42-00										
PKG:87										
H242-001 ^S		INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service	ATA:05
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: AMM 05-42-00										
PKG:87										
H430-001 ^S		INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS							Service	ATA:05
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-46-00										
PKG:84										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
H700-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service	ATA:05
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-47-00										PKG:84
H700-002 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service	ATA:05
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-47-00										PKG:84
H700-003 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING							Service	ATA:05
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 05-47-00										PKG:84
ATA 21 - AIR CONDITIONING										
21-01-01		RH INSC ILLUM PANEL							Component	ATA:21
PN:441-44279-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1024	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-01-01, AMM 21-01-01										
21-20-01		AVIONICS BLOWER							Component	ATA:21
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-07, AMM 31-41-07										
21-20-02		AVIONICS/DISPLAY COOLING FAN							Component	ATA:21
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-02, AMM 31-61-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY									Component ATA:21
PN:1300250-9	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:619	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-21-01, AMM 21-21-01										
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY									Component ATA:21
PN:1300250-9	MOS/MSC	08-Jun-18	O/C							
SN:528	HRS	1295.7								
	AFL	654								
PROC. REF: AMM 21-21-01, AMM 21-21-01										
21-20-05	GROUND COOLING FAN									Component ATA:21
PN:1133660-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:312	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-05, AMM 21-23-05										
21-21-02-001 ^S	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE									Service ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-21-02										PKG:60
21-21-02-001 ^S	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE									Service ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-21-02										PKG:60
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR									Component ATA:21
PN:100000-77	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:27376	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-03, AMM 21-23-03										
21-23-03	RAM AIR VALVE									Component ATA:21
PN:505-18030-405	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000762122	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-23-03, AMM 21-23-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-23-03-002 ^S		OPERATIONAL CHECK OF RAM AIR VALVE							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-23-03							PKG:60			
21-23-03-003 ^S		OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION							Service	ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-23-03							PKG:1			
21-23-04-001 ^S		OPERATIONAL CHECK OF RAM AIR CHECK VALVES							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-23-04							PKG:60			
21-23-05-001 ^S		GENERAL VISUAL INSPECTION OF GROUND COOLING FAN							Service	ATA:21
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)							
	AFL	555								
PROC. REF: AMM 21-23-05							PKG:10			
21-24-01-001 ^S		OPERATIONAL CHECK OF IFE COOLING FAN							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-24-01							PKG:60			
21-31-00-002 ^S		OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE							Service	ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-31-00							PKG:1			
21-31-00-003 ^S		OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)							Service	ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-31-00							PKG:1			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-31-00-004 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-31-00							PKG:50			
21-31-00-005 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-31-00							PKG:50			
21-31-01		(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT							Component	ATA:21
PN:2119286-10	MOS/MSC	31-Jan-19	O/C							
SN:2119286-01081	HRS	1483.9		TSN 2660						
	AFL	788		TSN 2089						
PROC. REF: AMM 21-31-01, AMM 21-31-01										
21-31-01-001		RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU)							Service	ATA:21
PN:2119286-10	MOS	31-Jan-19								
SN:2119286-01081	HRS	1483.9	5600 (+30/-30)	TAC 2660	4823.9 (M)	4853.9	2427.5 (+30)			
	AFL	788								
PROC. REF: AMM 21-31-01										
21-31-02		OUTFLOW VALVE							Component	ATA:21
PN:103922-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:103922-00193	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-02, AMM 21-31-02										
21-31-02-001		RESTORATION (REPAIR) OF OUTFLOW VALVE							Service	ATA:21
PN:103922-1	MOS	01-Aug-13								
SN:103922-00193	HRS	0	7200 (+30/-30)		7200	7230	4803.6 (+30)			
	AFL	0								
PROC. REF: AMM 21-31-02										
21-31-03		NEGATIVE PRESSURE RELIEF (NPR) VALVE							Component	ATA:21
PN:130664-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34163-0518	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-03, AMM 21-31-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-31-03-001 ^S		OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-31-03										PKG:50
21-31-04		PRESSURE RELIEF (PRV) VALVE							Component	ATA:21
PN:103918-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:103918-00279	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-31-04, AMM 21-31-04										
21-31-04-001 ^S		FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE							Service	ATA:21
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-31-04										PKG:50
21-41-01		BHS SHUT-OFF VALVE							Component	ATA:21
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-41-01, AMM 21-41-01										
21-41-04		RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS							Component	ATA:21
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-41-04, AMM 21-41-04										
21-52-01		VCS COMPRESSOR DRIVE MODULE							Component	ATA:21
PN:1133130-5	MOS/MSC	14-Aug-20	O/C	TSN 29, TSO 1						
SN:2088	HRS	1832.6		TSO 0						
	AFL	1049		TSO 0						
PROC. REF: AMM 21-52-01, AMM 21-52-01										
21-52-01-002		DISCARD OF COMPRESSOR DRIVE MODULE BELT							Service	ATA:21
	MOS	13-Mar-20								
	HRS	1779.4	2000 (+30/-30)		3779.4	3809.4	1383 (+30)			
	AFL	1007								
PROC. REF: AMM 21-52-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-52-01-003 ^S		FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION								Service ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-52-01										PKG:1
21-52-01-004		RESTORATION (OVERHAUL) COMPRESSOR								Service ATA:21
PN:1133130-5	MOS	14-Aug-20								
SN:2088	HRS	1832.6	2000 (+30/-30)		3832.6	3862.6	1436.2 (+30)			
	AFL	1049								
PROC. REF: AMM 21-52-01										
21-52-02		CDM COMPRESSOR MODULE								Component ATA:21
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-01, AMM 21-52-01										
21-52-03		SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE								Component ATA:21
PN:1133860-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:338	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-03, AMM 21-52-03										
21-52-03-001 ^S		GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES								Service ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-52-03										PKG:1
21-52-04		FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER								Component ATA:21
PN:1133850-104	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:636	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04										
21-52-05		COMPRESSOR DRIVE MODULE BELT								Component ATA:21
PN:PN	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-52-06-001 ^S		SERVICING OF VCS REFRIGERANT FLUID							Service	ATA:21
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 12-17-00							PKG:80			
21-52-08		AIR CONDITION CONDENSER ASSEMBLY							Component	ATA:21
PN:1133760-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:289	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-08, AMM 21-52-08										
21-52-08-001 ^S		GENERAL VISUAL INSPECTION OF VCS CONDENSER							Service	ATA:21
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)							
	AFL	555								
PROC. REF: AMM 21-52-08							PKG:10			
21-52-09		AIR CONDITION MIX FLOW CONDENSER FAN							Component	ATA:21
PN:1133720-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:195	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-09, AMM 21-52-09										
21-52-10		AIR CONDITION BLEED AIR HEAT EXCHANGER							Component	ATA:21
PN:1320260-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:289	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-52-10, AMM 21-52-10										
21-61-00-001 ^S		OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM							Service	ATA:21
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 21-61-00							PKG:1			
21-61-01		ECS TEMPERATURE CONTROLLER							Component	ATA:21
PN:1300670-6	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00361	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-61-01, AMM 21-61-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH									Component ATA:21
PN:1300450-10	MOS/MSC	18-Nov-17	O/C	TSN 0						
SN:3500	HRS	1111.12		TSN 0						
	AFL	555		TSN 0						
PROC. REF: AMM 21-61-03, AMM 21-61-03										
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH									Component ATA:21
PN:1300450-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2192	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-61-03, AMM 21-61-03										
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH									Component ATA:21
PN:1300450-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2197	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-61-04, AMM 21-61-04										
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH									Component ATA:21
PN:1300450-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2194	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 21-61-05, AMM 21-61-05										
21-61-06-001 ^S	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR									Service ATA:21
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 21-61-06										PKG:60
ATA 22 - AUTO FLIGHT										
22-11-00	GMC 715 GUIDANCE PANEL									Component ATA:22
PN:011-01430-00	MOS/MSC	01-Nov-18	O/C	TSR 1						
SN:15900541	HRS	1402.8		TSR 0						
	AFL	732		TSR 0						
PROC. REF: AMM 22-11-01, AMM 22-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-11-00-001		FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO								Service ATA:22
	MOS	18-Aug-22	12 (+30d/-30d)	Adj 9d	27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 22-11-00										
22-11-00-001		FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO								Service ATA:22
	MOS	18-Aug-22	12 (+30d/-30d)	Adj 9d	27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 22-11-00										
22-11-00-001		FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO								Service ATA:22
	MOS	18-Aug-22	12 (+30d/-30d)	Adj 9d	27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 22-11-00										
22-11-00-001		FUNCTIONAL CHECK TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO								Service ATA:22
	MOS	18-Aug-22	12 (+30d/-30d)	Adj 9d	27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 22-11-00										
22-11-00-002 ^S		LUBRICATION OF SERVO ACTUATORS								Service ATA:22
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 22-11-00										PKG:80
22-11-00-003 ^S		DETAILED INSPECTION OF AUTOPILOT SERVO CABLE								Service ATA:22
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 22-11-00										PKG:42
22-11-01		TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO								Component ATA:22
PN:011-00877-21	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1A0005808	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-02, AMM 22-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-11-02		AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO							Component	ATA:22
PN:011-00878-20	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1A1008833	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-02, AMM 22-11-02										
22-11-02		ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO							Component	ATA:22
PN:011-00878-20	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1A1008839	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-02, AMM 22-11-02										
22-11-02		RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO							Component	ATA:22
PN:011-00878-20	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1A1008845	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-02, AMM 22-11-02										
22-11-03		AILERON GSM 86 AUTOPILOT SERVO MOUNT							Component	ATA:22
PN:011-01904-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1GK008884	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-03, AMM 22-11-03										
22-11-06		ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT							Component	ATA:22
PN:011-01904-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1GK008775	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-06, AMM 22-11-06										
22-11-09		RUDDER GSM 86 AUTOPILOT SERVO MOUNT							Component	ATA:22
PN:011-01904-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1GK008773	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-09, AMM 22-11-09										
22-11-12		TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT							Component	ATA:22
PN:011-01904-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1GK008777	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 22-11-12, AMM 22-11-12										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-10-01	VHF ANTENNA									Component ATA:23
PN:S65-8280-41	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:322-3343	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-02, AMM 23-12-02										
23-11-01	PS440 HF CONTROL DISPLAY UNIT									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-01, AMM 23-11-01										
23-11-02	REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-02, AMM 23-11-02										
23-11-03	KPA 1052 POWER AMPLIFIER									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-03, AMM 23-11-03										
23-11-04	HF ANTENNA COUPLER									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-11-04, AMM 23-11-04										
23-12-02	BOTTOM VHF 2 ANTENNA									Component ATA:23
PN:S65-8280-41	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:322-3341	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-12-02, AMM 23-12-02										
23-21-01	SELCAL CSD DECODER									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-21-01, AMM 23-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-50-01	LEFT GMA 1347D AUDIO PANEL									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-51-01, AMM 23-51-01										
23-50-02	COPILOT HEADSET									Component ATA:23
PN:026-55-999-0131	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00201935	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-13-07, AMM 44-13-07										
23-50-02	PILOT HEADSET									Component ATA:23
PN:026-55-999-0131	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00201927	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-13-07, AMM 44-13-07										
23-50-03	LH CONSOLE COCKPIT HAND MICROPHONE									Component ATA:23
PN:85-03-12369-04	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:318237	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
23-50-04	COCKPIT SPEAKER									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-51-02, AMM 23-51-02										
23-50-05	CDVR MICROPHONE									Component ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-07, AMM 31-31-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-51-00-001 ^S		OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE							Service	ATA:23
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 23-51-00										PKG:40
23-51-01		RIGHT GMA 1347D AUDIO PANEL							Component	ATA:23
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-51-01, AMM 23-51-01										
23-51-05		LEFT CONTROL PANEL							Component	ATA:23
PN:441-40943-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1030	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-51-05, AMM 23-51-05										
23-51-05		RIGHT CONTROL PANEL							Component	ATA:23
PN:441-40943-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1031	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-51-05, AMM 23-51-05										
23-61-00-001 ^S		FUNCTIONAL CHECK OF STATIC DISCHARGERS							Service	ATA:23
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 23-61-00										PKG:83
ATA 24 - ELECTRICAL POWER										
24-01-01		LEFT CONSOLE CONTROL PANEL							Component	ATA:24
PN:441-40929-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0520	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-01-01, AMM 24-01-01										
24-31-01		NO. 1 ENGINE STARTER/GENERATOR							Component	ATA:24
PN:400SG180Q-4	MOS/MSC	18-Aug-22	O/C	TSN 73, TSO 0						
SN:S00623XL	HRS	2308.8		TSO 0						
	AFL	1307		TSO 0						
PROC. REF: AMM 24-31-01, AMM 24-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-01	NO. 2 ENGINE STARTER/GENERATOR									Component ATA:24
PN:400SG180Q-4	MOS/MSC	18-Aug-22	O/C	TSO 13						
SN:S02202XL	HRS	2308.8		TSO 0						
	AFL	1307		TSO 0						
PROC. REF: AMM 24-31-01, AMM 24-31-01										
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017									Service ATA:24
PN:400SG180Q-4	MOS	18-Aug-22								
SN:S00623XL	HRS	2308.8	800 (+30/-30)	3108.8	3138.8	712.4 (+30)				
	AFL	1307								
PROC. REF: AMM 24-31-01										
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017									Service ATA:24
PN:400SG180Q-4	MOS	18-Aug-22								
SN:S02202XL	HRS	2308.8	800 (+30/-30)	3108.8	3138.8	712.4 (+30)				
	AFL	1307								
PROC. REF: AMM 24-31-01										
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)									Service ATA:24
PN:400SG180Q-4	MOS/MSC		N/A							
SN:S00623XL	HRS									
	AFL									
PROC. REF: AMM 24-31-01										
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)									Service ATA:24
PN:400SG180Q-4	MOS/MSC		N/A							
SN:S02202XL	HRS									
	AFL									
PROC. REF: AMM 24-31-01										
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT									Component ATA:24
PN:GCSG550-12B	MOS/MSC	18-Nov-17	O/C							
SN:60762	HRS	1111.12								
	AFL	555								
PROC. REF: AMM 24-31-02, AMM 24-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT									Component ATA:24
PN:GCSG550-12B	MOS/MSC	18-Nov-17	O/C							
SN:60800	HRS	1111.12								
	AFL	555								
PROC. REF: AMM 24-31-02, AMM 24-31-02										
24-31-07-001 ^S	RESTORATION (CLEANING) OF LH SHUNT GENERATOR									Service ATA:24
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 24-31-07										
										PKG:84
24-31-07-001 ^S	RESTORATION (CLEANING) OF RH SHUNT GENERATOR									Service ATA:24
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 24-31-07										
										PKG:84
24-36-01	AFT MAIN BATTERY									Component ATA:24
PN:RG-380E/44	MOS/MSC	20-Mar-21	H/T	TSN 4						
SN:70012681	HRS	1891.3		TSN 0						
	AFL	1087		TSN 0						
PROC. REF: AMM 24-36-01, AMM 24-36-01										
24-36-01	FORWARD MAIN BATTERY									Component ATA:24
PN:RG-390E	MOS/MSC	20-Mar-21	H/T	TSN 9						
SN:41092073	HRS	1891.3		TSN 0						
	AFL	1087		TSN 0						
PROC. REF: AMM 24-36-01, AMM 24-36-01										
24-36-01-003	DISCARD AFT MAIN BATTERY									Service ATA:24
PN:RG-380E/44	MOS/MSC	20-Mar-21	N/A							
SN:70012681	HRS	1891.3								
	AFL	1087								
PROC. REF: AMM 24-36-01										
24-36-01-003	DISCARD FORWARD MAIN BATTERY									Service ATA:24
PN:RG-390E	MOS/MSC	20-Mar-21	N/A							
SN:41092073	HRS	1891.3								
	AFL	1087								
PROC. REF: AMM 24-36-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015)									Service ATA:24
PN:RG-380E/44	MOS/MSC		N/A							
SN:70012681	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015)									Service ATA:24
PN:RG-390E	MOS/MSC		N/A							
SN:41092073	HRS									
	AFL									
PROC. REF: GENERIC NO REF										
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)									Service ATA:24
PN:RG-380E/44	MOS/MSC	20-Mar-21	N/A							
SN:70012681	HRS	1891.3								
	AFL	1087								
PROC. REF: GENERIC NO REF										
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)									Service ATA:24
PN:RG-390E	MOS/MSC	20-Mar-21	N/A							
SN:41092073	HRS	1891.3								
	AFL	1087								
PROC. REF: GENERIC NO REF										
24-36-02-001 ^S	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)									Service ATA:24
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 24-36-02										PKG:60
24-36-STC-003 ^U	DISCARD AFT MAIN BATTERY (CONCORDE BATTERY)									Service ATA:24
PN:RG-380E/44	MOS	20-Mar-21	48		20-Mar-25		701 d			
SN:70012681	HRS	1891.3								
	AFL	1087								
24-36-STC-003 ^U	DISCARD FORWARD MAIN BATTERY (CONCORDE BATTERY)									Service ATA:24
PN:RG-390E	MOS	20-Mar-21	48		20-Mar-25		701 d			
SN:41092073	HRS	1891.3								
	AFL	1087								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-36-STC-005 ^U		CAPACITY CHECK AFT MAIN BATTERY (CONCORDE BATTERY)							Service	ATA:24
PN:RG-380E/44	MOS	13-Sep-22	6 (+1m/-1m)		13-Mar-23	13-Apr-23	OVD			
SN:70012681	HRS	2348								
	AFL	1324								
24-36-STC-005 ^U		CAPACITY CHECK FORWARD MAIN BATTERY (CONCORDE BATTERY)							Service	ATA:24
PN:RG-390E	MOS	13-Sep-22	6 (+1m/-1m)		13-Mar-23	13-Apr-23	OVD			
SN:41092073	HRS	2348								
	AFL	1324								
24-54-05		28 VDC / 115 VAC STATIC INVERTER							Component	ATA:24
PN:AS-24-0026-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0558	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-54-05, AMM 24-54-05										
24-65-00		W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE							Component	ATA:24
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-65-02, AMM 24-65-02										
24-65-01		LEFT POWER DISTRIBUTION BOX							Component	ATA:24
PN: SX7EG20-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0236	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-65-01, AMM 24-65-01										
24-65-02		RIGHT POWER DISTRIBUTION BOX							Component	ATA:24
PN: SX7EG21-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0217	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-65-02, AMM 24-65-02										
24-65-04		NOSE POWER DISTRIBUTION BOX							Component	ATA:24
PN: SX7EG22-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0223	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 24-65-04, AMM 24-65-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-11-01	COPILOT SEAT									Component ATA:25
PN:1419-02BE	MOS/MSC	18-Nov-17	O/C	TSN 48						
SN:407-1419	HRS	1111.12		TSN 1111.12						
	AFL	555		TSN 555						
PROC. REF: AMM 25-11-01, AMM 25-11-01										
25-11-01	PILOT SEAT									Component ATA:25
PN:PN	MOS/MSC	18-Nov-17	O/C	TSN 48						
SN:UNKNOWN	HRS	1111.12		TSN 1111.12						
	AFL	555		TSN 555						
PROC. REF: AMM 25-11-01, AMM 25-11-01										
25-11-01-001 ^S	DETAILED INSPECTION COPILOT SEAT									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-11-01										PKG:20
25-11-01-001 ^S	DETAILED INSPECTION PILOT SEAT									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-11-01										PKG:20
25-11-01-002 ^S	DETAILED INSPECTION OF COCKPIT SEAT BELTS									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-11-01										PKG:20
25-21-01	PAX 1 - RH AFT FACE SEAT									Component ATA:25
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-01	PAX 2 - LH AFT FACE SEAT									Component ATA:25
PN:403174-1I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55138	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-21-01	PAX 3 - RH AFT FACE SEAT									Component ATA:25
PN:403174-2I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55140	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-01	PAX 6 - LH FWD FACE SEAT									Component ATA:25
PN:403174-3I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55141	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-01	PAX 7 - RH FWD FACE SEAT									Component ATA:25
PN:403174-4I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55142	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER SEATS									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-21-01										PKG:20
25-21-01-002 ^S	DETAILED INSPECTION OF PASSENGER SEAT BELTS									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-21-01										PKG:20
25-21-02	DIVAN									Component ATA:25
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-02, AMM 25-21-02										
25-21-02-001 ^S	DETAILED INSPECTION DIVAN									Service ATA:25
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-21-02										PKG:40

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-21-02-002 ^S		DETAILED INSPECTION DIVAN SEAT BELTS							Service	ATA:25
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-21-02										PKG:40
25-21-03		PAX 4 - LH FWD FACE SEAT							Component	ATA:25
PN:403174-1I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55137	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-03		PAX 5 - RH FWD FACE SEAT							Component	ATA:25
PN:403174-2I2DZ	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55139	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-21-01, AMM 25-21-01										
25-21-04		(DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY							Component	ATA:25
PN:PN	MOS/MSC	21-Oct-20	O/C	TSN 0						
SN:UNKNOWN	HRS	1859.4		TSN 0						
	AFL	1063		TSN 0						
PROC. REF: AMM 25-21-04, AMM 25-21-04										
25-21-04-001		RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY							Service	ATA:25
PN:PN	MOS	12-Oct-20	84		12-Oct-27		1637 d			
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 25-21-04, AMM 25-21-04										
25-21-04-002		DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER							Service	ATA:25
PN:PN	MOS	12-Oct-20	120		12-Oct-30		2733 d	LIFE LIMIT		
SN:UNKNOWN	HRS									
	AFL									
PROC. REF: AMM 25-21-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-21-04-003		DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG ASSEMBLY							Service	ATA:25
	MOS	27-Aug-21	48 (+1m/-1m)		27-Aug-25		27-Sep-25	861 d (+31)		
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 25-21-04										
25-21-04-004		OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY							Service	ATA:25
	MOS	27-Aug-21	48 (+1m/-1m)		27-Aug-25		27-Sep-25	861 d (+31)		
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 25-21-04										
25-21-10		AIRBAG CYLINDER INFLATOR, ACH COLD							Component	ATA:25
PN:PN	MOS/MSC	21-Oct-20	O/C	TSN 0						
SN:UNKNOWN	HRS	1859.4		TSN 0						
	AFL	1063		TSN 0						
PROC. REF: GENERIC NO REF										
25-21-11		DIVAN SEAT BELT AIRBAG ASSEMBLY							Component	ATA:25
PN:3DAB0426501	MOS/MSC	21-Oct-20	O/C	TSN 0						
SN:8010279036	HRS	1859.4		TSN 0						
	AFL	1063		TSN 0						
PROC. REF: AMM 25-21-04, AMM 25-21-04										
25-43-01-001 ^S		DETAILED VISUAL INSPECTION BELTED TOILET UNIT							Service	ATA:25
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-43-02										PKG:40
25-43-01-002 ^S		DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT							Service	ATA:25
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 25-43-02										PKG:40
25-60-01		EMERGENCY LOCATOR TRANSMITTER							Component	ATA:25
PN:S1821502-02	MOS/MSC	10-Aug-20	O/C	TSN 84						
SN:LX1100050560	HRS	1832.6		TSN 1832.6						
	AFL	1049		TSN 1049						
PROC. REF: AMM 25-61-01, AMM 25-61-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-03	ELT ANTENNA									Component ATA:25
PN:S65-8282-406	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:401-2280	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-61-03, AMM 25-61-03										
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY									Component ATA:25
PN:S1820506-01	MOS/MSC	21-Jul-19	H/T	TSN 0						
SN:18200498	HRS	1612.9		TSN 0						
	AFL	883		TSN 0						
PROC. REF: AMM 25-61-01, AMM 25-61-01										
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM									Service ATA:25
PN:S1821502-02	MOS	16-Aug-22	12		16-Aug-23		119 d			
SN:LX1100050560	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 25-61-00										
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER									Service ATA:25
PN:S1821502-02	MOS	16-Aug-22	12		16-Aug-23		119 d			
SN:LX1100050560	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 25-61-00										
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY									Service ATA:25
PN:S1820506-01	MOS/MSC	21-Jul-19	DUE		31-Mar-25 (M)		712 d	LIFE LIMIT		
SN:18200498	HRS	1612.9								
	AFL	883								
PROC. REF: AMM 25-61-04										
25-61-05	CS144-A ELT/NAV INTERFACE MODULE									Component ATA:25
PN:S1825502-02	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:TM0000016677	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-61-05, AMM 25-61-05										
25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACEMODULE									Service ATA:25
PN:S1825502-02	MOS	14-Nov-13	120		14-Nov-23		209 d			
SN:TM0000016677	HRS	0	16000		16000		13603.6			
	AFL	0								
PROC. REF: AMM 25-61-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-01	FIRST AID KIT									Component ATA:25
PN:019708-0005L	MOS/MSC	27-Jun-22	H/T	TSN 17						
SN:NSN	HRS	2256.4		TSN 374.9						
	AFL	1290		TSN 210						
PROC. REF: GENERIC NO REF										
25-62-01-001	VISUAL CHECK FIRST AID KIT									Service ATA:25
PN:019708-0005L	MOS/MSC	27-Jun-22	DUE		01-Dec-23 (M)		226 d			
SN:NSN	HRS	2256.4								
	AFL	1290								
PROC. REF: AMM 25-62-01										
25-62-02	COPILOT LIFE VEST									Component ATA:25
PN:66601-505	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2168218	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 1 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199755	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 2 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199756	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 3 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199762	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 4 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199765	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-02	NO. 5 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199766	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 6 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199767	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 7 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199771	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	NO. 8 PASSENGER LIFE VEST									Component ATA:25
PN:66601-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2199777	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02	PILOT LIFE VEST									Component ATA:25
PN:66601-505	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:L2168207	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 25-62-02, AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST									Service ATA:25
	MOS	01-May-13	120		01-May-23		12 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST									Service ATA:25
	MOS	01-Jul-13	120		01-Jul-23		73 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST									Service ATA:25
	MOS	01-May-13	120		01-May-23		12 d	OVERHAUL		
	HRS									
	AFL									
PROC. REF: AMM 25-62-02										
25-62-04-001 ^S	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER									Service ATA:25
	MOS	27-Aug-21	24 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 25-62-04										
PKG:81										
25-66-01	LIFE RAFT									Component ATA:25
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 26 - FIRE PROTECTION										
26-11-01	LEFT ENGINE FIRE DETECTOR									Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	23-Mar-17	O/C							
SN:50219	HRS	960.9								
	AFL	479								
PROC. REF: AMM 26-11-01, AMM 26-11-01										
26-11-01	RIGHT ENGINE FIRE DETECTOR									Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:47955	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-11-01, AMM 26-11-01										
26-11-01-001 ^S	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR									Service ATA:26
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)							
	AFL	555								
PROC. REF: AMM 26-11-01										
PKG:10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-11-01-001 ^S		DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR							Service	ATA:26
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)							
	AFL	555								
PROC. REF: AMM 26-11-01										PKG:10
26-11-01-002 ^S		OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR							Service	ATA:26
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 26-11-01										PKG:1
26-11-01-002 ^S		OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR							Service	ATA:26
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 26-11-01										PKG:1
26-15-01		MODEL 602 SMOKE DETECTOR							Component	ATA:26
PN:8930-223B60L014	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:22414	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-15-01, AMM 26-15-01										
26-21-01		ENGINE FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33000073-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:67512A1	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-21-03, AMM 26-21-03										
26-21-01-001		FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL							Service	ATA:26
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	2400 (+30/-30)		2400	2430	3.6 (+30)			
	AFL	0								
PROC. REF: AMM 26-21-00										
26-21-01A		FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL							Component	ATA:26
PN:441-44278-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1027	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-21-01, AMM 26-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-21-03-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE									Service ATA:26
PN:33000073-1	MOS	01-Jul-13	120		01-Jul-23		73 d	AIRWORTHINESS		
SN:67512A1	HRS									
	AFL									
PROC. REF: AMM 26-21-03										
26-21-05-001 ^S	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)									Service ATA:26
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 26-21-05										PKG:20
26-21-07	NO. 1 CARTRIDGE									Component ATA:26
PN:30903962-1	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:1982PB	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-21-07, AMM 26-21-07										
26-21-07	NO. 2 CARTRIDGE									Component ATA:26
PN:30903963-1	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:1151PB	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-21-07, AMM 26-21-07										
26-21-07-001	DISCARD NO. 1 CARTRIDGE									Service ATA:26
PN:30903962-1	MOS	01-Jul-13	120		01-Jul-23		73 d	LIFE LIMIT		
SN:1982PB	HRS									
	AFL									
			Manufacture Date:: 01-Jul-13	PROC. REF: AMM 26-21-07						
26-21-07-001	DISCARD NO. 2 CARTRIDGE									Service ATA:26
PN:30903963-1	MOS	01-Jul-13	120		01-Jul-23		73 d	LIFE LIMIT		
SN:1151PB	HRS									
	AFL									
PROC. REF: AMM 26-21-07										
26-21-09-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING									Service ATA:26
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 26-21-09										PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER									Component ATA:26
PN:RT-A1200	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:X-726569	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 26-24-01, AMM 26-24-01										
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER									Component ATA:26
PN:RT-A1200	MOS/MSC	21-Jul-19	H/T	TSN 1						
SN:Y-502206	HRS	1612.9		TSN 0						
	AFL	883		TSN 0						
PROC. REF: AMM 26-24-01, AMM 26-24-01										
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS	27-Jul-22	12		27-Jul-23		99 d			
SN:X-726569	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS	27-Jul-22	12		27-Jul-23		99 d			
SN:Y-502206	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS	01-Jan-13	144		01-Jan-25		623 d	LIFE LIMIT		
SN:X-726569	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS	21-Jul-19	144		01-May-31 (M)		2934 d	LIFE LIMIT		
SN:Y-502206	HRS	1612.9								
	AFL	883								
PROC. REF: AMM 26-24-01										
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS/MSC		N/A							
SN:X-726569	HRS									
	AFL									
PROC. REF: AMM 26-24-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS/MSC		N/A							
SN:Y-502206	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER									Service ATA:26
	MOS/MSC		N/A							
	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER									Service ATA:26
PN:RT-A1200	MOS/MSC		N/A							
SN:Y-502206	HRS									
	AFL									
PROC. REF: AMM 26-24-01										
ATA 27 - FLIGHT CONTROLS										
27-001	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR									Service ATA:27
PN:475100-1013	MOS/MSC		N/A							
SN:0263	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-001	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR									Service ATA:27
PN:475100-1013	MOS/MSC		N/A							
SN:0238	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-002	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-2013	MOS/MSC		N/A							
SN:0403	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-002	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-2013	MOS/MSC		N/A							
SN:0402	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-003	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-1013	MOS/MSC		N/A							
SN:0094	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-003	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-1013	MOS/MSC		N/A							
SN:1968	HRS									
	AFL									
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-004	ROLL TRIM ACTUATOR									Component ATA:27
PN:470500-1005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0215	HRS	0	12000	TSN 0	12000		9603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-14-02, AMM 27-14-02										
27-005	YAW TRIM ACTUATOR									Component ATA:27
PN:470600-1005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0206	HRS	0	12000	TSN 0	12000		9603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-24-02, AMM 27-24-02										
27-006	PITCH TRIM ACTUATOR									Component ATA:27
PN:467500-1003	MOS	27-Feb-21		TSR 1				LIFE LIMIT		
SN:0303	HRS	1886.3	35000	TSN 4708, TSR 0	32178.3		29781.9			
	AFL	1084		TSR 0						
PROC. REF: AMM 27-41-01, AMM 27-41-01										
27-007	LEFT SPOILER ACTUATOR									Component ATA:27
PN:456800-1003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0431	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02										
27-007	RIGHT SPOILER ACTUATOR									Component ATA:27
PN:456800-1003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0422	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-008		ELECTRO - RUDDER GUST LOCK ACTUATOR							Component	ATA:27
PN:SYLC-53058	MOS/MSC	20-Nov-14	O/C							
SN:1464	HRS	329.1								
	AFL	161								
PROC. REF: AMM 27-70-01, AMM 27-70-01										
27-009		RUDDER BOOSTER ACTUATOR							Component	ATA:27
PN:9125-3	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0199T	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-23-02, AMM 27-23-02										
27-01-01		LEFT CONTROL WHEEL							Component	ATA:27
PN:83912139	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00735	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-01-01, AMM 27-01-01										
27-01-01		RIGHT CONTROL WHEEL							Component	ATA:27
PN:83912141	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00684	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-01-01, AMM 27-01-01										
27-01-02		LH PEDAL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-01-02, AMM 27-01-02										
27-01-02		RH PEDAL ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-01-02, AMM 27-01-02										
27-01-03-001 ^S		LUBRICATION OF ROTARY BALL SPLINE							Service	ATA:27
	MOS	27-Aug-21	24 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										
										PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-010		LEFT TOGGLE LINK							Component	ATA:27
PN:456870-1001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0394	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-65-02, AMM 27-65-02										
27-010		RIGHT TOGGLE LINK							Component	ATA:27
PN:456870-1001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0397	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-65-02, AMM 27-65-02										
27-011		STICK PUSHER ACTUATOR							Component	ATA:27
PN:9124-1	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0217T	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-36-02, AMM 27-36-02										
27-012		POWER DRIVE UNIT							Component	ATA:27
PN:467700-1003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0232	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-07, AMM 27-51-07										
27-013		LEFT FLAP POSITION SENSOR UNIT							Component	ATA:27
PN:457310-1001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0463	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-03, AMM 27-53-03										
27-013		RIGHT FLAP POSITION SENSOR UNIT							Component	ATA:27
PN:457310-1001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:0444	HRS	0	35000	TSN 0	35000		32603.6			
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-03, AMM 27-53-03										
27-014		DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Service	ATA:27
PN:457360-1007	MOS/MSC	01-Aug-13	N/A							
SN:SSW0382	HRS	0								
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-014		DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS	01-Aug-13						LIFE LIMIT		
SN:SSW0774	HRS	0	35000		35000		32603.6			
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-014		DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1007	MOS/MSC		N/A							
SN:SSW1184	HRS									
	AFL									
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-014		DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT								Service ATA:27
PN:457360-1007	MOS/MSC	01-Aug-13	N/A							
SN:SSW0384	HRS	0								
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-014		DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS	01-Aug-13						LIFE LIMIT		
SN:SSW0777	HRS	0	35000		35000		32603.6			
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-014		DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS	01-Aug-13						LIFE LIMIT		
SN:SSW0824	HRS	0	35000		35000		32603.6			
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-015		DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT								Service ATA:27
PN:457360-1007	MOS	01-Aug-13						LIFE LIMIT		
SN:SSW0382	HRS	0	35000		35000		32603.6			
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-015		DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	N/A							
SN:SSW0774	HRS	0								
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-015		DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1007	MOS	13-Mar-20						LIFE LIMIT		
SN:SSW1184	HRS	1779.4	35000		36779.4		34383			
	AFL	1007								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-015		DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT								Service ATA:27
PN:457360-1007	MOS	01-Aug-13						LIFE LIMIT		
SN:SSW0384	HRS	0	35000		35000		32603.6			
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-015		DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	N/A							
SN:SSW0777	HRS	0								
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-015		DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Service ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	N/A							
SN:SSW0824	HRS	0								
	AFL	0								
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-016		DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR								Service ATA:27
PN:475100-1013	MOS	13-Mar-20						LIFE LIMIT		
SN:0263	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-016		DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR								Service ATA:27
PN:475100-1013	MOS	13-Mar-20						LIFE LIMIT		
SN:0238	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-017		DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR								Service ATA:27
PN:475000-2013	MOS	13-Mar-20						LIFE LIMIT		
SN:0403	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-2013	MOS	13-Mar-20						LIFE LIMIT		
SN:0402	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-1013	MOS	13-Mar-20						LIFE LIMIT		
SN:0094	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
PN:475000-1013	MOS	13-Mar-20						LIFE LIMIT		
SN:1968	HRS	1779.4	7200		8979.4		6583			
	AFL	1007								
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL									Component ATA:27
PN:462900-1017	MOS/MSC	14-Jan-21	O/C							
SN:0061	HRS	1881.5		TSN 1271.5						
	AFL	1080		TSN 643						
PROC. REF: AMM 27-03-01, AMM 27-03-01										
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL									Component ATA:27
PN:462900-1017	MOS/MSC	14-Jan-21	O/C							
SN:0113	HRS	1881.5		TSN 2560.6						
	AFL	1080		TSN 1501						
PROC. REF: AMM 27-03-01, AMM 27-03-01										
27-03-01-002 ^S	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-03-01										PKG:50
27-03-01-003 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-03-01										PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-03-01										
27-04-01	TRIM ACTUATOR CONTROLLER									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-04-01, AMM 27-04-01										
27-04-01-001 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-04-01										
										PKG:50
27-04-01-002 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-04-01										
										PKG:50
27-11-00	AILERON CABLES ASSY.									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-02, AMM 27-11-02										
27-11-00-001 ^S	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS									Service ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-11-00										
										PKG:42
27-11-01	LEFT AILERON									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-11-01, AMM 27-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-11-01	RIGHT AILERON									Component ATA:27
PN:505-14740-4001	MOS/MSC	14-Aug-20	O/C	TSN 84						
SN:0000773570	HRS	1832.6		TSN 1832.6						
	AFL	1049		TSN 1049						
PROC. REF: AMM 27-11-01, AMM 27-11-01										
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION									Service ATA:27
	MOS	14-Aug-20	60 (+1m/-1m)		14-Aug-25		14-Sep-25	848 d (+31)		
	HRS	1832.6	3200 (+30/-30)		5032.6		5062.6	2636.2 (+30)		
	AFL	1049								
PROC. REF: AMM 27-11-02										
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK									Service ATA:27
	MOS/MSC	01-Aug-13	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-11-02										
27-11-02-002 ^S	DETAILED INSPECTION OF AILERON CONTROL CABLES									Service ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-11-02										PKG:42
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6000 (+30/-30)		6000	6030	3603.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-14-03										
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-14-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-14-03	LEFT AILERON TAB									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-14-03, AMM 27-14-03										
27-21-00	RUDDER CABLES ASSY.									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-21-02, AMM 27-21-02										
27-21-00-001 ^S	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS									Service ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-21-00										PKG:42
27-21-01	RUDDER ASSEMBLY									Component ATA:27
PN:505-39084-405	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000761547	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-21-01, AMM 27-21-01										
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION									Service ATA:27
	MOS	14-Aug-20	60 (+1m/-1m)		14-Aug-25		14-Sep-25	848 d (+31)		
	HRS	1832.6	3200 (+30/-30)		5032.6		5062.6	2636.2 (+30)		
	AFL	1049								
PROC. REF: AMM 27-21-02										
27-21-02-001(INITIAL)	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK									Service ATA:27
	MOS/MSC	01-Aug-13	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-21-02										
27-21-02-002 ^S	DETAILED INSPECTION OF RUDDER CONTROL CABLES									Service ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-21-02										PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-23-00-001 ^S		OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM							Service	ATA:27
	MOS	20-Aug-18								
	HRS	1321.5	1600 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-23-00										PKG:10
27-24-02-001		FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH							Service	ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6000 (+30/-30)		6000	6030	3603.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-24-03										
27-24-02-002		DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM							Service	ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-24-02										
27-24-03		RUDDER TRIM TAB							Component	ATA:27
PN:505-10450-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000758803	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-24-03, AMM 27-24-03										
27-26-01		VENTRAL RUDDER							Component	ATA:27
PN:505-07540-417	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000765982	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-26-01, AMM 27-26-01										
27-31-00		ELEVATOR CABLES ASSY							Component	ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-02, AMM 27-31-02										
27-31-00-001 ^S		GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS							Service	ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-31-00										PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-31-01	LEFT ELEVATOR									Component ATA:27
PN:505-43071-4037	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000761545	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01, AMM 27-31-01										
27-31-01	RIGHT ELEVATOR									Component ATA:27
PN:505-43071-4038	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000761546	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-01, AMM 27-31-01										
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION									Service ATA:27
	MOS	14-Aug-20	60 (+1m/-1m)		14-Aug-25		14-Sep-25	848 d (+31)		
	HRS	1832.6	3200 (+30/-30)		5032.6		5062.6	2636.2 (+30)		
	AFL	1049								
PROC. REF: AMM 27-31-02										
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK									Service ATA:27
	MOS/MSC	01-Aug-13	-							
	HRS	0								
	AFL	0								
PROC. REF: AMM 27-31-02										
27-31-02-002 ^S	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES									Service ATA:27
	MOS	18-Aug-18	60 (+1m/-1m)							
	HRS	1321.5	3200 (+30/-30)							
	AFL	673								
PROC. REF: AMM 27-31-02										PKG:42
27-31-03	LEFT ELEVATOR TAB									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03, AMM 27-31-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-31-03	RIGHT ELEVATOR TAB									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-31-03, AMM 27-31-03										
27-31-03-001 ^S	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-31-03										
										PKG:50
27-31-03-002 ^S	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-31-03										
										PKG:50
27-36-03-001 ^S	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH									Service ATA:27
	MOS	21-Jul-19								
	HRS	1612.9	1600 (+30/-30)							
	AFL	883								
PROC. REF: AMM 27-36-03										
										PKG:10
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-41-01										
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6000 (+30/-30)		6000	6030	3603.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-40-00										
27-41-01-003 ^S	LUBRICATION OF PITCH TRIM ACTUATOR									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										
										PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-41-01										
27-41-01-005 ^S	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-18-00										PKG:83
27-41-01-006 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-41-01										PKG:50
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL									Component ATA:27
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 27-51-00										
27-51-01-001 ^S	LUBRICATION OF FLAP ACTUATORS BALL SCREWS									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										PKG:83
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-01-002	DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										
27-51-01-002	DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										
27-51-01-002	DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										
27-51-01-002	DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										
27-51-01-002	DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR									Service ATA:27
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	7200 (+30/-30)		8979.4	9009.4	6583 (+30)			
	AFL	1007								
PROC. REF: AMM 27-51-01										
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	7200 (+30/-30)		7200	7230	4803.6 (+30)			
	AFL	0								
PROC. REF: AMM 27-51-01										
27-51-01-005 ^S	SERVICING OF FLAP ACTUATOR GEAR BOXES									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-18-00										PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-01-900-801-01		LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Component	ATA:27
PN:475100-1013	MOS/MSC	13-Mar-20	H/T							
SN:0263	HRS	1779.4		TSN 1816.57						
	AFL	1007		TSN 2143						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-01-900-801-02		RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Component	ATA:27
PN:475100-1013	MOS/MSC	13-Mar-20	H/T							
SN:0238	HRS	1779.4		TSN 1768.25						
	AFL	1007		TSN 1504						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-01-900-801-03		LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Component	ATA:27
PN:475000-2013	MOS/MSC	13-Mar-20	H/T							
SN:0403	HRS	1779.4		TSN 18243						
	AFL	1007		TSN 1087						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-01-900-801-04		RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Component	ATA:27
PN:475000-2013	MOS/MSC	13-Mar-20	H/T							
SN:0402	HRS	1779.4		TSN 1824.5						
	AFL	1007		TSN 1087						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-01-900-801-05		LEFT NO. 1 INBOARD FLAP ACTUATOR							Component	ATA:27
PN:475000-1013	MOS/MSC	13-Mar-20	H/T							
SN:0094	HRS	1779.4		TSN 1777.6						
	AFL	1007		TSN 1733						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-01-900-801-06		RIGHT NO. 1 INBOARD FLAP ACTUATOR							Component	ATA:27
PN:475000-1013	MOS/MSC	13-Mar-20	H/T							
SN:1968	HRS	1779.4		TSN 728						
	AFL	1007		TSN 650						
PROC. REF: AMM 27-51-01, AMM 27-51-01										
27-51-05		LEFT INBOARD FLAP							Component	ATA:27
PN:505-14401-4001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000761080	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-05	LEFT OUTBOARD FLAP									Component ATA:27
PN:505-39079-4001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000766304	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05										
27-51-05	RIGHT INBOARD FLAP									Component ATA:27
PN:505-14401-4002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000760228	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05										
27-51-05	RIGHT OUTBOARD FLAP									Component ATA:27
PN:505-14401-4001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000763226	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05										
27-51-06-001 ^S	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										PKG:83
27-51-06-001 ^S	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										PKG:83
27-51-06-001 ^S	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT									Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00										PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-06-001 ^S		LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00							PKG:83			
27-51-06-001 ^S		LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00							PKG:83			
27-51-06-001 ^S		LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 12-21-00							PKG:83			
27-51-06-002 ^S		DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06							PKG:83			
27-51-06-002 ^S		DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06							PKG:83			
27-51-06-002 ^S		DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06							PKG:83			
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT							Service	ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06							PKG:83			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT								Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06						PKG:83				
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT								Service ATA:27
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 27-51-06						PKG:83				
27-51-06-900-801-01		RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Component ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:SSW0824	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-51-06-900-801-02		RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT								Component ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:SSW0777	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-51-06-900-801-03		LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT								Component ATA:27
PN:457360-1007	MOS/MSC	13-Mar-20	H/T	TSN 8						
SN:SSW1184	HRS	1779.4		TSN 0						
	AFL	1007		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-51-06-900-801-04		LEFT INBOARD FLAP FLEXIBLE 1 SHAFT								Component ATA:27
PN:457360-1005	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:SSW0774	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-51-06-900-801-05		LEFT CENTER FLAP FLEXIBLE 2 SHAFT								Component ATA:27
PN:457360-1007	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:SSW0382	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-51-06-900-801-06	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT									Component ATA:27
PN:457360-1007	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:SSW0384	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-51-06, AMM 27-51-06										
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER									Component ATA:27
PN:780501-9	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1456	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-53-01, AMM 27-53-01										
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS-INTERNAL									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 27-64-00										
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 27-64-00										
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL									Service ATA:27
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 7 27-64-00										
27-65-00-001 ^S	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM									Service ATA:27
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-60-00										PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-65-01-001 ^S		GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)							Service	ATA:27
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 27-65-00										PKG:60
27-66-01		NO. 1 CONTROL WHEEL POSITION SENSOR							Component	ATA:27
PN:456896-1001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:052563	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-66-01, AMM 27-66-01										
27-66-01		NO. 2 CONTROL WHEEL POSITION SENSOR							Component	ATA:27
PN:456896-1001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:077808	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-66-01, AMM 27-66-01										
27-66-02		LEFT SPOILER SURFACE POSITION SENSOR							Component	ATA:27
PN:456897-1001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:084747	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-66-02, AMM 27-66-02										
27-66-02		RIGHT SPOILER SURFACE POSITION SENSOR							Component	ATA:27
PN:456897-1001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:084749	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 27-66-02, AMM 27-66-02										
ATA 28 - FUEL										
28-11-00-001 ^S		FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS							Service	ATA:28
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 28-11-00										PKG:80
28-11-05		LEFT WING WATER DRAIN VALVE							Component	ATA:28
PN:L83A13-628	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H00385	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-05, AMM 28-11-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-11-05		RIGHT WING WATER DRAIN VALVE							Component	ATA:28
PN:L83A13-628	MOS/MSC	14-Jun-18	O/C	TSN 2						
SN:J76447	HRS	1300.6		TSN 0						
	AFL	657		TSN 0						
PROC. REF: AMM 28-11-05, AMM 28-11-05										
28-11-07		LEFT WING DUMP VALVE							Component	ATA:28
PN:V98A32-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F84410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-07, AMM 28-11-07										
28-11-07		RIGHT WING DUMP VALVE							Component	ATA:28
PN:V98A32-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F87621	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-11-07, AMM 28-11-07										
28-12-01-001 ^S		SPECIAL DETAILED INSPECTION OF FUEL VENT NACA							Service	ATA:28
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 28-12-01										PKG:1
28-12-03		LEFT FUEL TANK FLOAT VENT VALVE							Component	ATA:28
PN:L87-19-001P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F96031	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03, AMM 28-12-03										
28-12-03		RIGHT FUEL TANK FLOAT VENT VALVE							Component	ATA:28
PN:L87-19-001P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F96025	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-12-03, AMM 28-12-03										
28-12-03-001 ^S		OPERATIONAL CHECK LEFT FLOAT VENT VALVE							Service	ATA:28
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 28-12-03										PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-12-03-001 ^S		OPERATIONAL CHECK RIGHT FLOAT VENT VALVE								Service ATA:28
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 28-12-03										PKG:60
28-21-01		LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01, AMM 28-21-01										
28-21-01		RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01, AMM 28-21-01										
28-21-02		LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE								Component ATA:28
PN:P99C25-606P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H08480	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03, AMM 28-21-03										
28-21-02		RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE								Component ATA:28
PN:P99C25-606P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H08477	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03, AMM 28-21-03										
28-21-03		LEFT WING DC AUXILIARY BOOST PUMP CANISTER								Component ATA:28
PN:C93R25-606P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H05434	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03, AMM 28-21-03										
28-21-03		RIGHT WING DC AUXILIARY BOOST PUMP CANISTER								Component ATA:28
PN:C93R25-606P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H05433	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-03, AMM 28-21-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-05	LEFT WING JET PUMP FEED LINE									Component ATA:28
PN:T99A19-602	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F12779	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-05, AMM 28-21-05										
28-21-05	RIGHT WING JET PUMP FEED LINE									Component ATA:28
PN:T99A19-602	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F12777	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-05, AMM 28-21-05										
28-21-07	LEFT 0.75 SHUTOFF VALVE									Component ATA:28
PN:B97-15-601	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F94064	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-07, AMM 28-21-07										
28-21-07	RIGHT 0.75 SHUTOFF VALVE									Component ATA:28
PN:B97-15-601	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F94061	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-07, AMM 28-21-07										
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM									Service ATA:28
	MOS	28-Apr-22						AIRWORTHINESS		
	HRS	2203.6	800 (+30/-30)	Adj 9.3	3012.9	3042.9	616.5 (+30)			
	AFL	1261								
PROC. REF: AMM 28-21-07										
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM									Service ATA:28
	MOS	28-Apr-22						AIRWORTHINESS		
	HRS	2203.6	800 (+30/-30)	Adj 9.3	3012.9	3042.9	616.5 (+30)			
	AFL	1261								
PROC. REF: AMM 28-21-07										
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR									Component ATA:28
PN:D97C00-644P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:C701219	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-07, AMM 28-21-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-08	LEFT WING 28 VDC SOV ACTUATOR									Component ATA:28
PN:D97C00-644P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:C701218	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-07, AMM 28-21-07										
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR									Component ATA:28
PN:D97C00-644P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:C701557	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-07, AMM 28-21-07										
28-21-09	LEFT WING SCAVENGER JET PUMP									Component ATA:28
PN:T99A19-603	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H07414	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-09, AMM 28-21-09										
28-21-09	RIGHT WING SCAVENGER JET PUMP									Component ATA:28
PN:T99A19-603	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H07413	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-09, AMM 28-21-09										
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE									Component ATA:28
PN:B97H19-608P2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H06934	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-10, AMM 28-21-10										
28-21-10-001	OPERATIONAL CHECK OF FUEL XFEED VALVE									Service ATA:28
	MOS	01-Aug-13								
	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 28-21-10										
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE									Component ATA:28
PN:L96-13-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H07175	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-11, AMM 28-21-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE									Component ATA:28
PN:L96-13-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H07176	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-11, AMM 28-21-11										
28-21-13	INSC ILLUM PANEL									Component ATA:28
PN:441-42621-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1186	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-21-13, AMM 28-21-13										
28-23-01	REFUEL CONTROL PANEL									Component ATA:28
PN:742388-1-2	MOS/MSC	27-Aug-21	O/C							
SN:742388IN00305	HRS	1988.6								
	AFL	1157		TSO 2999						
PROC. REF: AMM 28-23-01, AMM 28-23-01										
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE									Component ATA:28
PN:L94E31-653P3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H06035	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-03, AMM 28-23-03										
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE									Component ATA:28
PN:L94E31-653P3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:H06038	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-03, AMM 28-23-03										
28-23-04-001 ^S	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER									Service ATA:28
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 28-23-05										PKG:40
28-23-07	LEFT HIGH LEVEL SENSOR									Component ATA:28
PN:722860-2-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0560	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-07, AMM 28-23-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-23-07	RIGHT HIGH LEVEL SENSOR									Component ATA:28
PN:722860-2-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0559	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-07, AMM 28-23-07										
28-23-09	FUEL PORT AND CAP									Component ATA:28
PN:K97-63-613	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:F58630	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-23-09, AMM 28-23-09										
28-41-01	NO. 1 LEFT PROBE									Component ATA:28
PN:765896-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765896IN00514	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 1 RIGHT PROBE									Component ATA:28
PN:765896-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765896IN00522	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 2 LEFT PROBE									Component ATA:28
PN:765873-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765873IN00534	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 2 RIGHT PROBE									Component ATA:28
PN:765873-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765873IN00533	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 3 LEFT PROBE									Component ATA:28
PN:765874-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765874IN00523	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-41-01	NO. 3 RIGHT PROBE									Component ATA:28
PN:765874-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765874IN00521	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 4 LEFT PROBE									Component ATA:28
PN:765875-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765875IN00523	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-01	NO. 4 RIGHT PROBE									Component ATA:28
PN:765875-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:765875IN00526	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01, AMM 28-41-01										
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT									Component ATA:28
PN:738742-1-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:738790IN00666	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-41-05, AMM 28-41-05										
28-43-01	TEMPERATURE SENSOR									Component ATA:28
PN:798840-1-0	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:03408	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 28-43-01, AMM 28-43-01										
28-43-01-001 ^S	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR									Service ATA:28
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 28-43-01										PKG:60
28-45-01	LEFT PRESSURE SWITCH									Component ATA:28
PN:D98C07-611	MOS/MSC	20-Mar-21	O/C	TSN 91						
SN:1109	HRS	1891.3		TSN 1891.3						
	AFL	1087		TSN 1087						
PROC. REF: AMM 28-45-01, AMM 28-45-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-45-01	RIGHT PRESSURE SWITCH									Component ATA:28
PN:D98C07-611	MOS/MSC	20-Mar-21	O/C	TSN 91						
SN:1038	HRS	1891.3		TSN 1891.3						
	AFL	1087		TSN 1087						
PROC. REF: AMM 28-45-01, AMM 28-45-01										
ATA 29 - HYDRAULIC POWER										
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR									Component ATA:29
PN:3032763-003	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:MX769411	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02										
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:3032249-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:MX769135	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02										
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP									Component ATA:29
PN:3032249-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:MX769518	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02										
29-12-02-001 ^S	VISUAL CHECK OF MANIFOLD/ RESERVOIR									Service ATA:29
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 29-12-02										PKG:80
29-12-02-002 ^S	OPERATIONAL CHECK LEFT EDP CHECK VALVE									Service ATA:29
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 29-10-00										PKG:50
29-12-02-002 ^S	OPERATIONAL CHECK RIGHT EDP CHECK VALVE									Service ATA:29
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 29-10-00										PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-15-03	HYDRAULIC ACCUMULATOR									Component ATA:29
PN:0860231003	MOS/MSC	20-Nov-14	O/C	TSN 12						
SN:60231-2659	HRS	329.1		TSN 329.1						
	AFL	161		TSN 161						
PROC. REF: AMM 29-15-03, AMM 29-15-03										
29-15-03-001 ^S	SERVICING OF HYDRAULIC ACCUMULATOR									Service ATA:29
PN:0860231003	MOS	18-Aug-22	12 (+1m/-1m)							
SN:60231-2659	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 12-13-00										PKG:80
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE									Component ATA:29
PN:3032428-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:AA410648	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-15-04, AMM 29-15-04										
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE									Component ATA:29
PN:3032428-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:AA410649	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-15-04, AMM 29-15-04										
29-15-04-001	OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE									Service ATA:29
PN:3032428-001	MOS	09-Nov-21	48 (+30d/-30d)	Adj 9d	18-Nov-25	18-Dec-25	944 d (+30)	AIRWORTHINESS		
SN:AA410648	HRS	2059.7	3200 (+30/-30)		5259.7	5289.7	2863.3 (+30)			
	AFL	1192								
PROC. REF: AMM 29-15-04										
29-15-04-001	OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE									Service ATA:29
PN:3032428-001	MOS	09-Nov-21	48 (+30d/-30d)	Adj 9d	18-Nov-25	18-Dec-25	944 d (+30)	AIRWORTHINESS		
SN:AA410649	HRS	2059.7	3200 (+30/-30)		5259.7	5289.7	2863.3 (+30)			
	AFL	1192								
PROC. REF: AMM 29-15-04										
29-15-05	PRIORITY VALVE									Component ATA:29
PN:2217-0001-401	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00191	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-15-05, AMM 29-15-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-31-02-001 ^S		FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE							Service	ATA:29
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 29-31-02										PKG:50
ATA 30 - ICE AND RAIN PROTECTION										
30-01-01		MD INSC ILLUM PANEL							Component	ATA:30
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-01-01, AMM 30-01-01										
30-12-00-001 ^S		OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-10-00										PKG:60
30-12-01-001 ^S		FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-12-01										PKG:60
30-12-02		LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component	ATA:30
PN:RYLB-53534-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0193	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-02, AMM 30-12-02										
30-12-02		RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component	ATA:30
PN:RYLB-53534-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0192	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-02, AMM 30-12-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-463	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-462	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-451	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-475	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-471	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8078-2-498	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-12-05-001 ^S		FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-12-05							PKG:60			
30-12-05-001 ^S		FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-12-05							PKG:60			
30-12-05-002 ^S		FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-12-05							PKG:60			
30-12-05-002 ^S		FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service	ATA:30
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-12-05							PKG:60			
30-21-01		LEFT ENGINE ANTI-ICE PRESUURE VALVE							Component	ATA:30
PN:10030295	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000365	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-01, AMM 30-21-01										
30-21-01		RIGHT ENGINE ANTI-ICE PRESUURE VALVE							Component	ATA:30
PN:10030295	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000362	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-01, AMM 30-21-01										
30-21-02		LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER							Component	ATA:30
PN:APTE-477F-1000-100G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8002-3-355	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-02, AMM 30-21-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER									Component ATA:30
PN:APTE-477F-1000-100G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:7858-4-487	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-21-02, AMM 30-21-02										
30-21-02-001	FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER									Service ATA:30
	MOS	01-Aug-13								
	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 30-21-02										
30-21-02-001	FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER									Service ATA:30
	MOS	01-Aug-13								
	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 30-21-02										
30-21-02-720-801-A	TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK								Service	ATA:30
	MOS/MSC	01-Aug-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	AFL	0								
PROC. REF: AMM 30-21-02										
30-21-03-001 ^S	BORESCOPE INSPECTION OF PICCOLO TUBE									Service ATA:30
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 30-21-03										PKG:50
30-21-04-001 ^S	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS									Service ATA:30
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 30-21-00										PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-31-00-002		OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING								Service ATA:30
	MOS	27-Aug-21	24 (+1m/-1m)		27-Aug-23		130 d (+31)			
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 30-30-00										PKG:81
30-41-01-002 ^S		DISCARD OF WINDSHIELD RAIN REPELLENT COATING								Service ATA:30
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 30-41-01										PKG:80
30-41-01-003 ^S		FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE								Service ATA:30
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 30-41-01										PKG:80
30-42-00-001 ^S		OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM								Service ATA:30
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 30-42-00										PKG:1
30-42-01		LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL								Component ATA:30
PN:EPM-112-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:02237	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-42-01, AMM 30-42-01										
30-42-01		RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL								Component ATA:30
PN:EPM-112-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:02281	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-42-01, AMM 30-42-01										
30-81-02		LEFT NOSE ICE DETECTOR								Component ATA:30
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 30-81-02, AMM 30-81-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-30-02		CVDR ACCELEROMETER							Component	ATA:31
PN:3001-01-111	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1212-DTN0632	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-05, AMM 31-31-05										
31-30-03		REAR CVDR IMPACT SWITCH							Component	ATA:31
PN:5930-4-000	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:6023	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-04, AMM 31-31-04										
31-31-00-002		OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER)							Service	ATA:31
	MOS	18-Aug-22	12 (+1m/-1m)	Adj 9d	27-Aug-23	27-Sep-23	130 d (+31)			
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 31-31-00										PKG:80
31-31-01		(CVR / CVDR) COCKPIT VOICE RECORDER							Component	ATA:31
PN:2100-3083-50	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000889039	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-01, AMM 31-31-01										
31-31-03		CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component	ATA:31
PN:DK120/90	MOS/MSC	21-Jul-19	H/T	TSN 1						
SN:AT130345	HRS	1612.9		TSN 0						
	AFL	883		TSN 0						
PROC. REF: AMM 31-31-03, AMM 31-31-03										
31-31-03-001		DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service	ATA:31
PN:DK120/90	MOS/MSC	21-Jul-19	DUE		01-Mar-26 (M)		1047 d	LIFE LIMIT		
SN:AT130345	HRS	1612.9								
	AFL	883								
PROC. REF: AMM 31-31-03										
31-31-09		CVDR CONTROL PANEL							Component	ATA:31
PN:441-42635-003	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0528	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-31-09, AMM 31-31-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-33-01	FDR - FLIGHT DATA RECORDER									Component ATA:31
PN:2100-2044-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000879288	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-33-01, AMM 31-33-01										
31-33-03	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON									Component ATA:31
PN:DK120	MOS/MSC	21-Jul-19	H/T	TSN 0						
SN:AT137022	HRS	1612.9		TSN 0						
	AFL	883		TSN 0						
PROC. REF: AMM 31-33-03, AMM 31-33-03										
31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED)									Service ATA:31
PN:DK120	MOS/MSC	21-Jul-19	DUE		28-May-26 (M)		1135 d	LIFE LIMIT		
SN:AT137022	HRS	1612.9								
	AFL	883								
PROC. REF: AMM 31-33-03										
31-33-04	FORWARD CVDR IMPACT SWITCH									Component ATA:31
PN:5930-4-000	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:6031	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-33-04, AMM 31-33-04										
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER									Component ATA:31
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-33-05, AMM 31-33-05										
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER									Component ATA:31
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-33-05, AMM 31-33-05										
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER									Service ATA:31
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 31-33-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER									Service ATA:31
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 31-33-05										
31-40-01	LH DCU UNIT									Component ATA:31
PN:011-01457-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:16905831	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-01, AMM 31-41-01										
31-40-01	RH DCU UNIT									Component ATA:31
PN:011-01457-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:16905833	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-01, AMM 31-41-01										
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT									Component ATA:31
PN:011-01105-40	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2DC000661	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05										
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT									Component ATA:31
PN:011-01105-40	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2DC000673	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05										
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL									Component ATA:31
PN:441-42627-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1192	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
31-42-00-001 ^S	OPERATIONAL CHECK OF HSDB SWITCH REVERSION									Service ATA:31
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 31-42-00										
										PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT									Component ATA:31
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03, AMM 31-41-03										
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:46716601	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03, AMM 31-41-03										
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:46716558	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03, AMM 31-41-03										
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT									Component ATA:31
PN:011-00831-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:46716613	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-41-03, AMM 31-41-03										
31-61-00-001 ^S	OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)									Service ATA:31
	MOS	16-Apr-21								
	HRS	1907.8	3200 (+30/-30)							
	AFL	1095								
PROC. REF: AMM 31-61-00										PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)									Service ATA:31
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 31-61-00										PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)									Service ATA:31
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 31-61-00										PKG:40

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-61-01	MFD (MULTI-FUNCTION FLIGHT DISPLAY)									Component ATA:31
PN:011-01910-10	MOS/MSC	16-Apr-21	O/C	TSR 12						
SN:1F1105348	HRS	1907.8		TSR 0						
	AFL	1095		TSR 0						
PROC. REF: AMM 31-61-01, AMM 31-61-01										
31-61-01	PFD 1 (PRIMARY FLIGHT DISPLAY)									Component ATA:31
PN:011-01910-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1F1100235	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-01, AMM 31-61-01										
31-61-01	PFD 2 (PRIMARY FLIGHT DISPLAY)									Component ATA:31
PN:011-01910-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1F1100285	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-01, AMM 31-61-01										
31-61-05	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY									Component ATA:31
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-05, AMM 31-61-05										
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL									Component ATA:31
PN:441-44282-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1060	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-06, AMM 31-61-06										
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL									Component ATA:31
PN:441-44282-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1061	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-06, AMM 31-61-06										
316104-0101	PAX NO.1 GTC570 TOUCHSCREEN CONTROLLER									Component ATA:31
PN:011-01924-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1MB501000	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 31-61-04, AMM 31-61-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
316104-0101	PAX NO.2 GTC570 TOUCHSCREEN CONTROLLER									Component ATA:31
PN:011-01924-10	MOS/MSC	18-Oct-19	O/C	TSR 15						
SN:1MB501004	HRS	1672.7		TSR 0						
	AFL	925		TSR 0						
PROC. REF: AMM 31-61-04, AMM 31-61-04										
ATA 32 - LANDING GEAR										
32-00-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS									Service ATA:32
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 32-00-20										PKG:1
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING									Component ATA:32
PN:2317-1201-503	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475208/001	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING									Component ATA:32
PN:2317-1201-504	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1480783/001	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-003	LEFT PINTLE PIN									Component ATA:32
PN:2317-1101-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1464072/009	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-003	RIGHT PINTLE PIN									Component ATA:32
PN:2317-1101-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473168/004	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-004		LEFT PINTLE PIN							Component	ATA:32
PN:2317-1102-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1472927/003	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-004		RIGHT PINTLE PIN							Component	ATA:32
PN:2317-1102-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1477519/004	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-005		LEFT MLG SHOCK STRUT (MF - AS) AXLE							Component	ATA:32
PN:2317-1103-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1466151/009	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-005		RIGHT MLG SHOCK STRUT (MF - AS) AXLE							Component	ATA:32
PN:2317-1103-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473550/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-006		LEFT MLG SHOCK STRUT (TR - AS) AXLE							Component	ATA:32
PN:2317-1107-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1471120/002	HRS	0		TSN 0						
	AFL	0	15300	TSN 0	15300		13941			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-006		RIGHT MLG SHOCK STRUT (TR - AS) AXLE							Component	ATA:32
PN:2317-1107-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473186/005	HRS	0		TSN 0						
	AFL	0	15300	TSN 0	15300		13941			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-007		LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component	ATA:32
PN:2317-1109-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475264/004	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-007		RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component	ATA:32
PN:2317-1109-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473158/003	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-008		LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component	ATA:32
PN:2317-1126-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475931/012	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-008		RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component	ATA:32
PN:2317-1126-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1467968/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-10-00		LEFT MAIN LANDING GEAR							Component	ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-00										
32-10-00		RIGHT MAIN LANDING GEAR							Component	ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-00										
32-10-01		LEFT MAIN LANDING GEAR LEG STRUT ASSY							Component	ATA:32
PN:2317-1100-405	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00172	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-10-01		RIGHT MAIN LANDING GEAR LEG STRUT ASSY							Component	ATA:32
PN:2317-1100-406	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00175	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-01, AMM 32-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY									Component ATA:32
PN:2317-1500-405	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00177	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY									Component ATA:32
PN:2317-1500-406	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00182	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE									Component ATA:32
PN:2317-1502-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1474859/001	HRS	0		TSN 0						
	AFL	0	15300	TSN 0	15300		13941			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE									Component ATA:32
PN:2317-1502-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1470313/004	HRS	0		TSN 0						
	AFL	0	15300	TSN 0	15300		13941			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE									Component ATA:32
PN:2317-1503-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475196/001	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE									Component ATA:32
PN:2317-1503-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1462718/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT									Component ATA:32
PN:2317-1509-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1470385/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-103		RIGHT MAIN LANDING GEAR TRAILING ARM BOLT							Component	ATA:32
PN:2317-1509-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1474295/003	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-104		LEFT MAIN LANDING GEAR TRAILING ARM							Component	ATA:32
PN:2317-1513-501	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1474258/001	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-105		RIGHT MAIN LANDING GEAR TRAILING ARM							Component	ATA:32
PN:2317-1513-502	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1476822/001	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-106		LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component	ATA:32
PN:2317-1505-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1476860/009	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-106		RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component	ATA:32
PN:2317-1505-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1476860/014	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-04, AMM 32-11-04										
32-11-00-001 ^S		GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR							Service	ATA:32
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 32-11-00										PKG:80
32-11-00-003		LUBRICATION OF MAIN LANDING GEAR							Service	ATA:32
	MOS	16-Aug-22	12 (+1m/-1m)	Adj 11d	27-Aug-23	27-Sep-23	130 d (+31)			
	HRS	2308.8								
	AFL	1307	650 (+30/-30)		1957	1987	598 (+30)			
PROC. REF: AMM 12-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-01-001		RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-11-01-002		RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-11-02-001		RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-11-02-002		RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-11-02-900-801-05		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								Component ATA:32
PN:2117-3001-003	MOS/MSC	18-Dec-15	H/T	TSN 0						
SN:1558048/016	HRS	625.9		TSN 0						
	AFL	328		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-06		LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								Component ATA:32
PN:2117-3001-003	MOS/MSC	18-Dec-15	H/T	TSN 0						
SN:1559185/008	HRS	625.9		TSN 0						
	AFL	328		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-07		LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER								Component ATA:32
PN:2117-3010-001	MOS/MSC		H/T	TSN 0						
SN:1462767/002	HRS			TSN 0						
	AFL	EFF		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER									Component ATA:32
PN:2117-3010-001	MOS/MSC		H/T	TSN 0						
SN:1472421/010	HRS			TSN 0						
	AFL	EFF		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN									Component ATA:32
PN:2117-3019-001	MOS/MSC		H/T	TSN 0						
SN:1475904/001	HRS			TSN 0						
	AFL	EFF		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN									Component ATA:32
PN:2117-3019-001	MOS/MSC		H/T	TSN 0						
SN:1453597/007	HRS			TSN 0						
	AFL	EFF		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE									Component ATA:32
PN:2117-3007-003	MOS/MSC	18-Dec-15	H/T	TSN 0						
SN:1569020/019	HRS	625.9		TSN 0						
	AFL	328		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE									Component ATA:32
PN:2117-3007-003	MOS/MSC	18-Dec-15	H/T	TSN 0						
SN:1569020/004	HRS	625.9		TSN 0						
	AFL	328		TSN 0						
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)									Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *	01-Sep-23	104 d (+31)	OVERHAUL		
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10641 (+30)			
PROC. REF: AMM 32-11-00										
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)									Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *	01-Sep-23	104 d (+31)	OVERHAUL		
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10641 (+30)			
PROC. REF: AMM 32-11-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-03-004	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER									Service ATA:32
	MOS	16-Aug-22	12 (+1m/-1m)	Adj 11d	27-Aug-23		27-Sep-23	130 d (+31)		
	HRS	2308.8								
	AFL	1307	650 (+30/-30)		1957	1987		598 (+30)		
PROC. REF: AMM 12-14-02										
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)									Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)									Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-11-00										
32-20-01	NOSE LANDING GEAR									Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-21-00										
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER									Component ATA:32
PN:2317-3000-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00385	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER									Component ATA:32
PN:2317-3000-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00397	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER									Component ATA:32
PN:2317-3011-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473257/003	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800			15441		
PROC. REF: AMM 32-11-03, AMM 32-11-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-201		RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER							Component	ATA:32
PN:2317-3011-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475238/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-202		LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component	ATA:32
PN:2317-3021-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1466140/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-202		RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component	ATA:32
PN:2317-3021-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473524/002	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-203		LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component	ATA:32
PN:2317-3001-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1479673/004	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-203		RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component	ATA:32
PN:2317-3001-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1479803/007	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-204		LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component	ATA:32
PN:2317-3004-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1463946/012	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										
32-204		RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component	ATA:32
PN:2317-3004-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473256/008	HRS	0		TSN 0						
	AFL	0	16800	TSN 0	16800		15441			
PROC. REF: AMM 32-11-03, AMM 32-11-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-21-00-001 ^S		GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR								Service ATA:32
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 32-21-00										PKG:80
32-21-00-003		LUBRICATION OF NOSE LANDING GEAR								Service ATA:32
	MOS	16-Aug-22	12 (+1m/-1m)	Adj 11d	27-Aug-23		27-Sep-23	130 d (+31)		
	HRS	2308.8								
	AFL	1307	650 (+30/-30)		1957		1987	598 (+30)		
PROC. REF: AMM 12-21-00										
32-21-01-001		RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *		12030	10641 (+30)		
PROC. REF: AMM 32-21-00										
32-21-02		NLG RETRACTION ACTUATOR								Component ATA:32
PN:2117-1000-401	MOS/MSC	14-Aug-20	O/C	TSR 5						
SN:00327	HRS	1832.6		TSN 1024, TSR 0						
	AFL	1049		TSN 751, TSR 0						
PROC. REF: AMM 32-21-02, AMM 32-21-02										
32-21-03		NLG DOWNLOCK ACTUATOR								Component ATA:32
PN:2117-2000-401	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00193	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-21-03, AMM 32-21-03										
32-21-04-001		RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *		12030	10641 (+30)		
PROC. REF: AMM 32-21-00										
32-21-05-001		RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *		12030	10641 (+30)		
PROC. REF: AMM 32-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-21-05-004		SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER								Service ATA:32
	MOS	16-Aug-22	12 (+1m/-1m)	Adj 11d	27-Aug-23		27-Sep-23	130 d (+31)		
	HRS	2308.8								
	AFL	1307	650 (+30/-30)		1957	1987		598 (+30)		
PROC. REF: AMM 12-14-03										
32-21-06-005 ^S		VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER								Service ATA:32
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 32-21-06										PKG:80
32-21-09-001		RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY								Service ATA:32
	MOS	EFF	120 (+1m/-1m)		01-Aug-23 *		01-Sep-23	104 d (+31)	OVERHAUL	
	HRS									
	AFL	EFF	12000 (+30/-30)		12000 *	12030		10641 (+30)		
PROC. REF: AMM 32-21-00										
32-23-03		NLG DOOR - TORQUE TUBE ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-300		LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR								Component ATA:32
PN:2117-3000-601	MOS/MSC	18-Dec-15	O/C							
SN:00329	HRS	625.9								
	AFL	328								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-300		RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR								Component ATA:32
PN:2117-3000-601	MOS/MSC	18-Dec-15	O/C							
SN:00370	HRS	625.9								
	AFL	328								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-301		LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER								Component ATA:32
PN:2117-3034-501	MOS			TSN 0				LIFE LIMIT		
SN:1470400/004	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *			10647		
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-301		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER							Component	ATA:32
PN:2117-3034-501	MOS			TSN 0				LIFE LIMIT		
SN:1482484/001	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-302		DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service	ATA:32
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-302		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service	ATA:32
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-303		DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service	ATA:32
PN:2117-3010-001	MOS	01-Aug-13						LIFE LIMIT		
SN:1462767/002	HRS	0								
	AFL	0	12000		12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-303		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service	ATA:32
PN:2117-3010-001	MOS	01-Aug-13						LIFE LIMIT		
SN:1472421/010	HRS	0								
	AFL	0	12000		12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-304		LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component	ATA:32
PN:2117-3008-901	MOS			TSN 0				LIFE LIMIT		
SN:70023/0003	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-304		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component	ATA:32
PN:2117-3008-901	MOS			TSN 0				LIFE LIMIT		
SN:71820/0021	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON									Component ATA:32
PN:2117-3009-007	MOS			TSN 0				LIFE LIMIT		
SN:1451017/014	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON									Component ATA:32
PN:2117-3009-007	MOS			TSN 0				LIFE LIMIT		
SN:1454669/018	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-306	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN									Service ATA:32
PN:2117-3019-001	MOS	01-Aug-13						LIFE LIMIT		
SN:1453597/007	HRS	0								
	AFL	0	12000		12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-306	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN									Service ATA:32
PN:2117-3019-001	MOS	01-Aug-13						LIFE LIMIT		
SN:1475904/001	HRS	0								
	AFL	0	12000		12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-307	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE									Service ATA:32
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-307	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE									Service ATA:32
	MOS/MSC	01-Aug-13	N/A							
	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP									Component ATA:32
PN:2117-3011-001	MOS			TSN 0				LIFE LIMIT		
SN:1446587/005	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-308		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP							Component	ATA:32
PN:2117-3011-001	MOS			TSN 0				LIFE LIMIT		
SN:1474293/006	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-309		LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component	ATA:32
PN:2117-3013-001	MOS			TSN 0				LIFE LIMIT		
SN:1465449/005	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-309		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component	ATA:32
PN:2117-3013-001	MOS			TSN 0				LIFE LIMIT		
SN:1475190/009	HRS			TSN 0						
	AFL	EFF	12000	TSN 0	12006 *		10647			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-31-01		LANDING GEAR CONTROL LEVER							Component	ATA:32
PN:827101-13	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0031	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-01, AMM 32-31-01										
32-31-04		CENTER FUSELAGE LANDING GEAR SELECTOR VALVE							Component	ATA:32
PN:7342-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0207T	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-04, AMM 32-31-04										
32-31-05		LH MLG UPLOCK BOX ASSY							Component	ATA:32
PN:2617-1000-401	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00367	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-05, AMM 32-31-05										
32-31-05		NLG UPLOCK BOX ASSY							Component	ATA:32
PN:2617-1000-401	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00370	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-05, AMM 32-31-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-31-05	RH MLG UPLOCK BOX ASSY									Component ATA:32
PN:2617-1000-402	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00184	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-31-05, AMM 32-31-05										
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT									Component ATA:32
PN:PN	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	12000	TSN 0	12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT									Component ATA:32
PN:PN	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	12000	TSN 0	12000		10641			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END									Component ATA:32
PN:MTMKS14ALGA 1	MOS			TSN 0				LIFE LIMIT		
SN:00191	HRS			TSN 0						
	AFL	EFF	10500	TSN 0	10506 *		9147			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END									Component ATA:32
PN:MTMKS14ALGA 1	MOS			TSN 0				LIFE LIMIT		
SN:00283	HRS			TSN 0						
	AFL	EFF	10500	TSN 0	10506 *		9147			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-312	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER									Service ATA:32
PN:2117-3010-001	MOS/MSC	01-Aug-13	N/A							
SN:1462767/002	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-312		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER								Service ATA:32
PN:2117-3010-001	MOS/MSC	01-Aug-13	N/A							
SN:1472421/010	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-313		LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT								Component ATA:32
PN:2117-3029-001	MOS	18-Dec-15		TSN 0				LIFE LIMIT		
SN:00530	HRS	625.9		TSN 0						
	AFL	328	28000	TSN 0	28328		26969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-313		RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT								Component ATA:32
PN:2117-3029-001	MOS	18-Dec-15		TSN 0				LIFE LIMIT		
SN:00529	HRS	625.9		TSN 0						
	AFL	328	28000	TSN 0	28328		26969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-314		DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN								Service ATA:32
PN:2117-3019-001	MOS/MSC	01-Aug-13	N/A							
SN:1453597/007	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-314		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN								Service ATA:32
PN:2117-3019-001	MOS/MSC	01-Aug-13	N/A							
SN:1475904/001	HRS	0								
	AFL	0								
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-315		DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE								Service ATA:32
PN:2117-3007-003	MOS	18-Dec-15						LIFE LIMIT		
SN:1569020/019	HRS	625.9								
	AFL	328	12000		12328		10969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-315		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE								Service ATA:32
PN:2117-3007-003	MOS	18-Dec-15						LIFE LIMIT		
SN:1569020/004	HRS	625.9								
	AFL	328	12000		12328		10969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-316		DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								Service ATA:32
PN:2117-3001-003	MOS	18-Dec-15						LIFE LIMIT		
SN:1559185/008	HRS	625.9								
	AFL	328	12000		12328		10969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-316		DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								Service ATA:32
PN:2117-3001-003	MOS	18-Dec-15						LIFE LIMIT		
SN:1558048/016	HRS	625.9								
	AFL	328	12000		12328		10969			
PROC. REF: AMM 32-11-02, AMM 32-11-02										
32-35-00-001		FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM								Service ATA:32
	MOS	27-Aug-21	24 (+30d/-30d)		27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	1988.6	1600 (+30/-30)		3588.6	3618.6	1192.2 (+30)			
	AFL	1157								
PROC. REF: AMM 32-35-00										
32-35-00-002		GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES								Service ATA:32
	MOS	27-Aug-21	24 (+30d/-30d)		27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS		
	HRS	1988.6	1600 (+30/-30)		3588.6	3618.6	1192.2 (+30)			
	AFL	1157								
PROC. REF: AMM 32-35-00										
32-35-02		CENTER FUSELAGE FREE FALL VALVE								Component ATA:32
PN:7343-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0201T	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-35-02, AMM 32-35-02										
32-400		NOSE LANDING GEAR SHOCK STRUT								Component ATA:32
PN:2317-5100-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00184	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-21-01, AMM 32-21-01										
32-401		NOSE LANDING GEAR SHOCK STRUT AXLE BOLT								Component ATA:32
PN:2310-1144-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:00052	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-01, AMM 32-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-402		NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT							Component	ATA:32
PN:PN	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-06, AMM 32-21-06										
32-403		LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component	ATA:32
PN:2317-5105-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1472948/003	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-01, AMM 32-21-01										
32-403		RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component	ATA:32
PN:2317-5105-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1472948/005	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-01, AMM 32-21-01										
32-404		NOSE LANDING GEAR SHOCK STRUT MAIN FITTING							Component	ATA:32
PN:2317-5301-503	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475193/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-11-01, AMM 32-11-01										
32-405		NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER							Component	ATA:32
PN:2117-4000-403	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:00190	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-06, AMM 32-21-06										
32-406		NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE							Component	ATA:32
PN:2317-5101-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1467733/007	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-01, AMM 32-21-01										
32-407		LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component	ATA:32
PN:2317-5201-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1472944/008	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-07, AMM 32-21-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-407		UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component	ATA:32
PN:2317-5201-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1472944/002	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-07, AMM 32-21-07										
32-408		NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN							Component	ATA:32
PN:2317-6003-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1468892/014	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-409		NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE							Component	ATA:32
PN:2310-1165-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1476853/002	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-07, AMM 32-21-07										
32-41-00		BRAKE CONTROL UNIT							Component	ATA:32
PN:DAP00100-07	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:288160267	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01, AMM 32-41-01										
32-41-00-001 ^S		FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM							Service	ATA:32
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 32-41-00										PKG:50
32-41-01		BRAKE CONTROL UNIT TRAY							Component	ATA:32
PN:DAP00134-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1021	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-01, AMM 32-41-01										
32-41-02		LH BRAKE PEDAL TRANSDUCER							Component	ATA:32
PN:Q3008	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:082658	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-02, AMM 32-41-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-41-02	RH BRAKE PEDAL TRANSDUCER									Component ATA:32
PN:Q3008	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:082660	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-02, AMM 32-41-02										
32-41-02-001 ^S	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER									Service ATA:32
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 32-41-02										
										PKG:60
32-41-02-001 ^S	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER									Service ATA:32
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 32-41-02										
										PKG:60
32-41-02-002 ^S	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER									Service ATA:32
	MOS	21-Jul-19								
	HRS	1612.9	1600 (+30/-30)							
	AFL	883								
PROC. REF: AMM 32-41-02										
										PKG:10
32-41-02-002 ^S	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER									Service ATA:32
	MOS	21-Jul-19								
	HRS	1612.9	1600 (+30/-30)							
	AFL	883								
PROC. REF: AMM 32-41-02										
										PKG:10
32-41-06	LH MLG WHEEL SPEED TRANSDUCER									Component ATA:32
PN:DAP00103-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:36MJ	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-06, AMM 32-41-06										
32-41-06	RH MLG WHEEL SPEED TRANSDUCER									Component ATA:32
PN:DAP00103-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:55MH	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-06, AMM 32-41-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-41-07	BRAKE CONTROL MODULE									Component ATA:32
PN:DAP00101-02	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:86MG	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-41-07, AMM 32-41-07										
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN									Component ATA:32
PN:57675-1	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:00562	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-07, AMM 32-21-07										
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT									Component ATA:32
PN:2310-1183-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1458779/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-07, AMM 32-21-07										
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK									Component ATA:32
PN:2317-5191-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475737/004	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03										
32-43-00-001 ^S	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM									Service ATA:32
	MOS	20-Mar-21								
	HRS	1891.3	5600 (+30/-30)							
	AFL	1087								
PROC. REF: AMM 32-43-00										PKG:50
32-43-01-001 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM									Service ATA:32
	MOS	18-Dec-15								
	HRS	625.9	5600 (+30/-30)							
	AFL	328								
PROC. REF: AMM 32-43-00										PKG:50
32-43-02	PRESSURE SWITCH									Component ATA:32
PN:DAP00108-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:117MB	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 29-12-03, AMM 29-12-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR									Component ATA:32
PN:DAP00106-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:198	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-43-04, AMM 32-43-04										
32-43-05	EMERGENCY/PARKING BRAKE VALVE									Component ATA:32
PN:DAP00107-01	MOS/MSC	12-Nov-20	O/C							
SN:92HJ	HRS	1871.6								
	AFL	1071								
PROC. REF: AMM 32-43-02										
32-43-06	PRESSURE TRANSDUCER									Component ATA:32
PN:DAP00109-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8049-6-10	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-43-06, AMM 32-43-06										
32-43-08	THERMAL RELIEF VALVE									Component ATA:32
PN:DAP00110-01	MOS/MSC	14-Jun-18	O/C	TSN 10						
SN:609	HRS	1300.6		TSN 0						
	AFL	657		TSN 0						
PROC. REF: AMM 32-43-08, AMM 32-43-08										
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE									Component ATA:32
PN:DAP00202-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:107	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-43-02, AMM 32-43-02										
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE									Component ATA:32
PN:2216-0001-401	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00491	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-43-11, AMM 32-43-11										
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE									Service ATA:32
	MOS	13-Mar-20						AIRWORTHINESS		
	HRS	1779.4	800 (+30/-30)		2579.4	2609.4	183 (+30)			
	AFL	1007								
PROC. REF: AMM 32-43-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-45-00	LH MAIN WHEEL AND TIRE ASSY									Component ATA:32
PN:505-19517-611	MOS/MSC	06-Oct-22	O/C	TSR 2						
SN:5003VJ	HRS	2353.4		TSR 0						
	AFL	1329		TSO 180, TSR 0						
PROC. REF: AMM 32-45-02, AMM 32-45-02										
32-45-00	NOSE WHEEL AND TIRE ASSY									Component ATA:32
PN:505-19601-607	MOS/MSC	24-Jan-22	O/C	TSO 0						
SN:5167QJ	HRS	2121.9		TSO 0						
	AFL	1220		TSO 0						
PROC. REF: AMM 32-45-02, AMM 32-45-02										
32-45-00	RH MAIN WHEEL AND TIRE ASSY									Component ATA:32
PN:505-19517-611	MOS/MSC	25-Jan-22	O/C	TSR 7						
SN:5107UF	HRS	2121.9		TSR 0						
	AFL	1220		TSO 163, TSR 0						
PROC. REF: AMM 32-45-02, AMM 32-45-02										
32-45-01	LEFT MAIN WHEEL									Component ATA:32
PN:DAP00098-02	MOS/MSC	06-Oct-22	O/C	TSR 2						
SN:5003VJ	HRS	2353.4		TSR 0						
	AFL	1329		TSO 180, TSR 0						
PROC. REF: AMM 32-45-01, AMM 32-45-01										
32-45-01	RIGHT MAIN WHEEL									Component ATA:32
PN:DAP00098-02	MOS/MSC	25-Jan-22	O/C	TSR 7						
SN:5107UF	HRS	2121.9		TSR 0						
	AFL	1220		TSO 163, TSR 0						
PROC. REF: AMM 32-45-01, AMM 32-45-01										
32-45-01-002 ^U	SPECIAL DETAIL INSPECTION LH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY									Service ATA:32
PN:505-19517-611	MOS/MSC	06-Oct-22	O/C							
SN:5003VJ	HRS	2353.4								
	AFL	1329								
32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY									Service ATA:32
PN:DAP00098-02	MOS/MSC	06-Oct-22	T/C							
SN:5003VJ	HRS	2353.4								
	AFL	1329	1500 (+30/-30)	TAC 180	2649	2679	1290 (+30)			
PROC. REF: AMM 32-45-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY									Service ATA:32
PN:DAP00098-02	MOS/MSC	25-Jan-22	T/C							
SN:5107UF	HRS	2121.9								
	AFL	1220	1500 (+30/-30)	TAC 163	2557	2587	1198 (+30)			
PROC. REF: AMM 32-45-00										
32-45-02	LEFT MAIN WHEEL TIRE									Component ATA:32
PN:258K63-2	MOS/MSC	06-Oct-22	O/C	TSN 0						
SN:20330556	HRS	2353.4		TSN 0						
	AFL	1329		TSN 0						
PROC. REF: AMM 32-45-02, AMM 32-45-02										
32-45-02	RIGHT MAIN WHEEL TIRE									Component ATA:32
PN:258K63-2	MOS/MSC	25-Jan-22	O/C	TSN 0						
SN:10071200	HRS	2121.9		TSN 0						
	AFL	1220		TSN 0						
PROC. REF: AMM 32-45-02, AMM 32-45-02										
32-45-03	LH MLG HUB CAP									Component ATA:32
PN:DAP00131-02	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:20MB	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-45-03, AMM 32-45-03										
32-45-03	RH MLG HUB CAP									Component ATA:32
PN:DAP00131-02	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:19MB	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-45-03, AMM 32-45-03										
32-45-11	NOSE WHEEL									Component ATA:32
PN:DAP00099-02	MOS/MSC	25-Jan-22	O/C	TSO 0						
SN:5167QJ	HRS	2121.9		TSO 0						
	AFL	1220		TSO 0						
PROC. REF: AMM 32-45-11, AMM 32-45-11										
32-45-11-002 ^U	SPECIAL DETAIL INSPECTION NOSE WHEEL AND TIRE ASSY (NDT) OF NOSE LANDING GEAR WHEEL ASSEMBLY									Service ATA:32
PN:505-19601-607	MOS/MSC	25-Jan-22	O/C							
SN:5167QJ	HRS	2121.9								
	AFL	1220								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY									Service ATA:32
PN:DAP00099-02	MOS/MSC	25-Jan-22	T/C							
SN:5167QJ	HRS	2121.9								
	AFL	1220	1500 (+30/-30)		2720	2750	1361 (+30)			
PROC. REF: AMM 32-45-00										
32-45-12	NOSE TIRE									Component ATA:32
PN:156E23-1	MOS/MSC	25-Jan-22	O/C	TSN 0						
SN:00740428	HRS	2121.9		TSN 0						
	AFL	1220		TSN 0						
PROC. REF: AMM 32-45-11, AMM 32-45-11										
32-45-21	LH MLG CARBON BRAKE ASSY									Component ATA:32
PN:DAP00097-04	MOS/MSC	18-Nov-17	O/C	TSR 0						
SN:5107ML	HRS	1111.12		TSR 0						
	AFL	555		TSR 0						
PROC. REF: AMM 32-45-21, AMM 32-45-21										
32-45-21	RH MLG CARBON BRAKE ASSY									Component ATA:32
PN:DAP00097-04	MOS/MSC	18-Nov-17	O/C							
SN:5002MF	HRS	1111.12								
	AFL	555								
PROC. REF: AMM 32-45-21, AMM 32-45-21										
32-500	NOSE LANDING GEAR SHOCK ABSORBER									Component ATA:32
PN:2317-5170-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00191	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK									Component ATA:32
PN:2317-5227-501	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1482475/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: GENERIC NO REF										
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING									Component ATA:32
PN:2317-5113-005	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1474301/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-503		NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER							Component	ATA:32
PN:2317-5237-501	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1483604/002	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: GENERIC NO REF										
32-600		NOSE LANDING GEAR DRAG BRACE							Component	ATA:32
PN:2317-6000-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00184	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-601		NOSE LANDING GEAR UPPER DRAG BRACE							Component	ATA:32
PN:2317-6114-501	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1473553/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-602		NOSE LANDING GEAR LOWER DRAG BRACE							Component	ATA:32
PN:2317-6201-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1468146/015	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-603		LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component	ATA:32
PN:2317-6001-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1468893/001	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-603		RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component	ATA:32
PN:2317-6001-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1468893/002	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										
32-604		NOSE LANDING GEAR DRAG BRACE PIN							Component	ATA:32
PN:2317-6003-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475910/005	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-09, AMM 32-21-09										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-61-01	LH WING PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34121	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34656	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 1 NLG PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34629	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34654	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH									Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 2 NLG PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34645	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH									Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH									Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH									Component ATA:32
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-61-01	RH WING PROXIMITY SWITCH									Component ATA:32
PN:80-057-01	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:34122	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
32-700	NOSE LANDING GEAR LOCKING STAY									Component ATA:32
PN:2317-6500-403	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00179	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 32-21-04, AMM 32-21-04										
32-701	NOSE LANDING GEAR UPPER LOCKING STAY									Component ATA:32
PN:2317-6521-003	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1474291/006	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-04, AMM 32-21-04										
32-702	NOSE LANDING GEAR LOWER LOCKING STAY									Component ATA:32
PN:2317-6531-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1475191/004	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-04, AMM 32-21-04										
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT									Component ATA:32
PN:2310-1734-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1468550/004	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-04, AMM 32-21-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT									Component ATA:32
PN:2310-1734-001	MOS	01-Aug-13		TSN 0				LIFE LIMIT		
SN:1471069/006	HRS	0		TSN 0						
	AFL	0	11200	TSN 0	11200		9841			
PROC. REF: AMM 32-21-04, AMM 32-21-04										
ATA 33 - LIGHTS										
33-01-01	OVERHEAD LIGHTS CONTROL PANEL									Component ATA:33
PN:441-44443-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1023	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-01-01, AMM 33-01-01										
33-12-01	COCKPIT DIMMER									Component ATA:33
PN:81-01760-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0571	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-12-01, AMM 33-12-01										
33-12-02	INSC ILLUM - TEST PANEL									Component ATA:33
PN:441-42631-003	MOS/MSC	20-Dec-18	O/C	TSN 2						
SN:1541	HRS	1411.6		TSN 0						
	AFL	742		TSN 0						
PROC. REF: AMM 33-12-02, AMM 33-12-02										
33-31-02	NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS									Component ATA:33
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
33-42-01	LH LWR FWD TAXI LIGHT ASSY									Component ATA:33
PN:81017-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000238	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-42-01, AMM 33-42-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-42-01		RH LWR FWD TAXI LIGHT ASSY							Component	ATA:33
PN:81017-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000228	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-42-01, AMM 33-42-01										
33-47-01		LEFT LANDING LIGHT ASSY							Component	ATA:33
PN:81017-5	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000223	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-47-01, AMM 33-47-01										
33-47-01		RIGHT LANDING LIGHT ASSY							Component	ATA:33
PN:81017-6	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000234	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-47-01, AMM 33-47-01										
33-48-00		LEFT NO. 1 NAVIGATION LIGHT							Component	ATA:33
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02										
33-48-00		LEFT NO. 2 NAVIGATION LIGHT							Component	ATA:33
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02										
33-48-00		RIGHT NO. 1 NAVIGATION LIGHT							Component	ATA:33
PN:84004-7	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000420	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02										
33-48-00		RIGHT NO. 2 NAVIGATION LIGHT							Component	ATA:33
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-48-00-001	DISCARD LEFT NO. 1 NAVIGATION LIGHT									Service ATA:33
PN:PN	MOS	01-Aug-13								
SN:UNKNOWN	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-48-00										
33-48-00-001	DISCARD LEFT NO. 2 NAVIGATION LIGHT									Service ATA:33
PN:PN	MOS	01-Aug-13								
SN:UNKNOWN	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-48-00										
33-48-00-001	DISCARD RIGHT NO. 1 NAVIGATION LIGHT									Service ATA:33
PN:84004-7	MOS	01-Aug-13								
SN:000420	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-48-00										
33-48-00-001	DISCARD RIGHT NO. 2 NAVIGATION LIGHT									Service ATA:33
PN:PN	MOS	01-Aug-13								
SN:UNKNOWN	HRS	0	12000 (+30/-30)		12000	12030	9603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-48-00										
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT									Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-48-00										PKG:20
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT									Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-48-00										PKG:20
33-48-00-002 ^S	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT									Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-48-00										PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-48-00-002 ^S		GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT								Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-48-00										PKG:20
33-49-00		NO. 1 STROBE LIGHT								Component ATA:33
PN:84036-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:000254	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02										
33-49-00		NO. 2 STROBE LIGHT								Component ATA:33
PN:84036-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00248	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02										
33-49-00-001		DISCARD NO. 1 STROBE LIGHT								Service ATA:33
PN:84036-3	MOS	01-Aug-13								
SN:000254	HRS	0	8000 (+30/-30)		8000	8030	5603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-49-00										
33-49-00-001		DISCARD NO. 2 STROBE LIGHT								Service ATA:33
PN:84036-4	MOS	01-Aug-13								
SN:00248	HRS	0	8000 (+30/-30)		8000	8030	5603.6 (+30)			
	AFL	0								
PROC. REF: AMM 33-49-00										
33-49-00-002 ^S		GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT								Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-49-00										PKG:20
33-49-00-002 ^S		GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT								Service ATA:33
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 33-49-00										PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-52-01	LH REAR EMERGENCY LIGHT BATTERY									Component ATA:33
PN:7450LS-00	MOS/MSC	06-Oct-22	O/C							
SN:005564	HRS	2353.4								
	AFL	1329								
PROC. REF: AMM 33-52-01, AMM 33-52-01										
33-52-01	RH FWD EMERGENCY LIGHT BATTERY									Component ATA:33
PN:7450LS-00	MOS/MSC	06-Oct-22	O/C							
SN:006135	HRS	2353.4								
	AFL	1329								
PROC. REF: AMM 33-52-01, AMM 33-52-01										
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY)									Service ATA:33
PN:7450LS-00	MOS	06-Oct-22	12		06-Oct-23		170 d			
SN:005564	HRS	2353.4								
	AFL	1329								
PROC. REF: AMM 33-52-01										
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY)									Service ATA:33
PN:7450LS-00	MOS	06-Oct-22	12		06-Oct-23		170 d			
SN:006135	HRS	2353.4								
	AFL	1329								
PROC. REF: AMM 33-52-01										
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY)									Service ATA:33
PN:7450LS-00	MOS/MSC		N/A							
SN:005564	HRS									
	AFL									
PROC. REF: AMM 33-52-01										
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY)									Service ATA:33
PN:7450LS-00	MOS/MSC		N/A							
SN:006135	HRS									
	AFL									
PROC. REF: AMM 33-52-01										
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY									Service ATA:33
PN:7450LS-00	MOS/MSC		N/A							
SN:005564	HRS									
	AFL									
PROC. REF: AMM 33-52-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY									Service ATA:33
PN:7450LS-00	MOS/MSC		N/A							
SN:006135	HRS									
	AFL									
PROC. REF: AMM 33-52-01										
33-52-05	SELF-ILLUMINATED UNIT									Component ATA:33
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 33-52-05, AMM 33-52-05										
33-52-17-001 ^S	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED)									Service ATA:33
	MOS	21-Jul-19								
	HRS	1612.9	1600 (+30/-30)							
	AFL	883								
PROC. REF: AMM 33-52-17										PKG:10
ATA 34 - NAVIGATION										
34-00-01 ^U	ACSS TRANSPONDER									Component ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
34-00-02	TRANSPONDER RF RELAY									Component ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
34-00-03	NO.1 IASP SMART PROBE									Component ATA:34
PN:2015L-4B	MOS/MSC	18-Dec-15	O/C							
SN:0229	HRS	625.9								
	AFL	328								
PROC. REF: AMM 34-15-07, AMM 34-15-07										
34-00-03	NO.2 IASP SMART PROBE									Component ATA:34
PN:2015L-4B	MOS/MSC	06-Dec-16	O/C							
SN:0550	HRS	862.2								
	AFL	431								
PROC. REF: AMM 34-15-07, AMM 34-15-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-00-04	SD CARD DATABASE									Component ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
34-10-01	RADIO ALTIMETER									Component ATA:34
PN:066-01153-0101	MOS/MSC	20-Mar-21	O/C							
SN:KRA405B-20222HRS		1891.3		TSO 159						
	AFL	1087		TSO 112						
PROC. REF: AMM 34-31-02, AMM 34-31-02										
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA									Component ATA:34
PN:S67-2002-45	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:553-5137	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02, AMM 34-31-02										
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA									Component ATA:34
PN:S67-2002-45	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:553-5138	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-31-02, AMM 34-31-02										
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT									Component ATA:34
PN:C16786DA01	MOS/MSC	27-Aug-21	O/C	TSN 96						
SN:C16786005129	HRS	1988.6		TSN 1988.6						
	AFL	1157		TSN 1157						
PROC. REF: AMM 34-11-01, AMM 34-11-01										
34-11-00-001	FUNCTIONAL CHECK OF (IESI) INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001)									Service ATA:34
PN:C16786DA01	MOS	27-Aug-21	24 (+1m/-1m)	27-Aug-23	27-Sep-23	130 d (+31)				
SN:C16786005129	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 34-11-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-02	PITOT/STATIC PROBE									Component ATA:34
PN:0856UT4	MOS/MSC	21-Jul-19	O/C	TSN 68						
SN:281580	HRS	1612.9		TSN 1612.9						
	AFL	883		TSN 883						
PROC. REF: AMM 34-11-02, AMM 34-11-02										
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)									Service ATA:34
PN:0856UT4	MOS	27-Aug-21	24 (+1m/-1m)		27-Aug-23		27-Sep-23	130 d (+31)		
SN:281580	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 34-11-02										
34-15-00-001 ^S	FUNCTIONAL CHECK OF AIR DATA SYSTEM									Service ATA:34
	MOS	27-Aug-21	24 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 34-15-00										PKG:81
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS									Service ATA:34
	MOS	21-Jul-19	60 (+1m/-1m)		21-Jul-24		21-Aug-24	459 d (+31)		
	HRS	1612.9								
	AFL	883								
PROC. REF: AMM 34-15-00										PKG:84
34-15-00-003	DETAILED INSPECTION OF IASP									Service ATA:34
	MOS	27-Aug-21	24 (+1m/-1m)		27-Aug-23		27-Sep-23	130 d (+31)		
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 34-15-07										PKG:81
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM									Component ATA:34
PN:011-00868-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:42022834	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-01, AMM 34-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM									Component ATA:34
PN:011-00868-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4203158	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-01, AMM 34-21-01										
34-20-02	LEFT MAGNETOMETER									Component ATA:34
PN:011-00870-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1CM009554	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-02, AMM 34-21-02										
34-20-02	RIGHT MAGNETOMETER									Component ATA:34
PN:011-00870-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1CM009801	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-21-02, AMM 34-21-02										
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER									Service ATA:34
PN:011-00870-10	MOS	21-Aug-22	36 (+1m/-1m)							
SN:1CM009554	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 34-21-02										PKG:82
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER									Service ATA:34
PN:011-00870-10	MOS	21-Aug-22	36 (+1m/-1m)							
SN:1CM009801	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 34-21-02										PKG:82
34-23-00	MAGNETIC COMPASS									Component ATA:34
PN:KCA0120W	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:BI1600712	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-23-01, AMM 34-23-01										
34-23-00-001 ^S	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS									Service ATA:34
PN:KCA0120W	MOS	21-Aug-22	36 (+1m/-1m)							
SN:BI1600712	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 34-23-00										PKG:82

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA									Component ATA:34
PN:S65-247170	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:173-3788	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-03, AMM 34-32-03										
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE									Component ATA:34
PN:S65-247170	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:173-3786	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-03, AMM 34-32-03										
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER									Component ATA:34
PN:011-00987-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:47766633	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-57-01, AMM 34-57-01										
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA									Component ATA:34
PN:013-00245-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:10866	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02										
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA									Component ATA:34
PN:013-00245-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:10865	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02										
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA									Component ATA:34
PN:011-01768-00	MOS/MSC	19-Jan-14	O/C	TSO 0						
SN:1DP000506	HRS	80.7		TSO 0						
	AFL	43		TSO 0						
PROC. REF: AMM 34-42-01, AMM 34-42-01										
34-40-04	TCAS II UNIT									Component ATA:34
PN:9003500-55905	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:TSE01813	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-01, AMM 34-43-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-40-05		TCAS II TOP ANTENNA							Component	ATA:34
PN:7514060-902	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:ANE72073	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-05, AMM 34-43-05										
34-43-02		LOWER TCAS L BAND ANTENNA							Component	ATA:34
PN:S65-5366-7L	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:261-112411	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-43-02, AMM 34-43-02										
34-50-02		BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA							Component	ATA:34
PN:S65-5366-7L	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:261-112408	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-52-02, AMM 34-52-02										
34-50-02		TOP XPDR L BAND ANTENNA							Component	ATA:34
PN:S65-5366-7L	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:261-112410	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-52-02, AMM 34-52-02										
34-50-03		KN 63 DISTANCE MEASURING UNIT							Component	ATA:34
PN:066-01070-0001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:36158	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-01, AMM 34-51-01										
34-50-05		PHASING COUPLER							Component	ATA:34
PN:SSPD-113-10	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:7545	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-01, AMM 34-32-01										
34-50-06		MARKER BEACON ANTENNA							Component	ATA:34
PN:S35-1000-2	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:102-9844	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-04, AMM 34-32-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-50-07		MARKER BEACON ANTENNA SPLITTER							Component	ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-05, AMM 34-32-05										
34-50-08		VOR/LOC/GS ANTENNA SPLITTER							Component	ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-02, AMM 34-32-02										
34-50-09		VOR/LOC/GS ANTENNA RF CABLE							Component	ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-32-02, AMM 34-32-02										
34-50-10		GSR 56 IRIDIUM UNIT							Component	ATA:34
PN:011-02268-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1NZ005508	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-01, AMM 23-15-01										
34-50-11		IRIDIUM SATCOM ANTENNA							Component	ATA:34
PN:S67-1575-109	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:11601	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-15-03, AMM 23-15-03										
34-50-12		GDL 59 DATALINK MANAGEMENT UNIT							Component	ATA:34
PN:011-01746-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1EJ005290	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-23-01, AMM 23-23-01										
34-50-13		WI-FI - DATALINK ANTENNA							Component	ATA:34
PN:S65-5366-71S	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:258-2489	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-50-14	ADF ANTENNA									Component ATA:34
PN:622-7383-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:3Y8CN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-02, AMM 34-53-02										
34-50-15	ADF UNIT									Component ATA:34
PN:622-7382-101	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4M10P	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-01, AMM 34-53-01										
34-51-02	NO. 1 DME L BAND ANTENNA									Component ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-51-02, AMM 34-51-02										
34-52-00	NO. 1 TRANSPONDER									Component ATA:34
PN:9006000-55000	MOS/MSC	16-Oct-19	O/C							
SN:NXE11625	HRS	1672.7								
	AFL	925								
PROC. REF: AMM 34-52-01, AMM 34-52-01										
34-52-00	NO. 2 TRANSPONDER									Component ATA:34
PN:9006000-55000	MOS/MSC	16-Oct-19	O/C							
SN:NXE11649	HRS	1672.7								
	AFL	925								
PROC. REF: AMM 34-52-01, AMM 34-52-01										
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM									Service ATA:34
PN:9006000-55000	MOS	16-Aug-21	24		16-Aug-23		119 d			
SN:NXE11625	HRS									
	AFL									
PROC. REF: AMM 34-52-00										
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM									Service ATA:34
PN:9006000-55000	MOS	16-Aug-21	24		16-Aug-23		119 d			
SN:NXE11649	HRS									
	AFL									
PROC. REF: AMM 34-52-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-52-04	LOWER COAXIAL UNIT									Component ATA:34
PN:D2-729B005	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:582214	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-52-04, AMM 34-52-04										
34-52-04	UPPER COAXIAL UNIT									Component ATA:34
PN:D2-729B005	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:582210	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-52-04, AMM 34-52-04										
34-53-01	ADF MOUNTING TRAY									Component ATA:34
PN:622-5212-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:469KK	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-53-01, AMM 34-53-01										
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL									Component ATA:34
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 34-61-03, AMM 34-61-03										
ATA 35 - OXYGEN										
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE									Service ATA:35
	MOS	16-Aug-22	36 (+30d/-30d)	Adj -26d	21-Jul-25	20-Aug-25	824 d (+30)	AIRWORTHINESS		
	HRS	2308.8	2400 (+30/-30)		4708.8	4738.8	2312.4 (+30)			
	AFL	1307								
PROC. REF: AMM 35-00-00										
35-01-00-001 ^S	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION									Service ATA:35
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 35-01-02										PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-01-02	OXYGEN CYLINDER TRANSDUCER									Component ATA:35
PN:4441125-000	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:7825-6-186	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-02, AMM 35-01-02										
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH									Component ATA:35
PN:P24151	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0241	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-05, AMM 35-01-05										
35-01-06	OXYGEN SYSTEM CONTROL PANEL									Component ATA:35
PN:441-40945-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0522	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-06, AMM 35-01-06										
35-01-07	COCKPIT SENSOR									Component ATA:35
PN:P24099	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0463	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-07, AMM 35-01-07										
35-01-08	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH									Component ATA:35
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
35-01-09	ALTITUDE COMPENSATING REGULATOR									Component ATA:35
PN:4421135-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00421	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-09, AMM 35-01-09										
35-01-10	LOW PRESSURE OXYGEN VALVE									Component ATA:35
PN:4421132-109	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00390	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-01-10, AMM 35-01-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
35-02-01		OXYGEN CYLINDER								Component	ATA:35
PN:4441122-077	MOS/MSC	08-Jun-18	H/T	TSN 59, TSR 4							
SN:569710103	HRS	1295.7		TSR 0							
	AFL	654		TSR 0							
PROC. REF: AMM 35-02-01, AMM 35-02-01											
35-02-01-001		FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR								Service	ATA:35
PN:4441122-077	MOS	28-Feb-18	60	28-Feb-23			OVD				
SN:569710103	HRS										
	AFL										
PROC. REF: AMM 35-02-01											
35-02-01-003		DISCARD OF OXYGEN CYLINDER								Service	ATA:35
PN:4441122-077	MOS	01-Jul-13	180	TAC 59	01-Aug-23		104 d	LIFE LIMIT			
SN:569710103	HRS										
	AFL										
Manufacture Date:: 01-May-13				PROC. REF: AMM 35-02-01							
35-02-05		OXYGEN PRESSURE REGULATOR								Component	ATA:35
PN:PN	MOS/MSC	08-Jun-18	O/C	TSR 4							
SN:UNKNOWN	HRS	1295.7		TSR 0							
	AFL	654		TSR 0							
PROC. REF: GENERIC NO REF											
35-11-00-001		OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX								Service	ATA:35
	MOS	16-Aug-22	12 (+30d/-30d)	Adj 11d	27-Aug-23	26-Sep-23	130 d (+30)	AIRWORTHINESS			
	HRS	2308.8	800 (+30/-30)	3108.8		3138.8	712.4 (+30)				
	AFL	1307									
PROC. REF: AMM 35-11-02											
35-11-01		COPILOT OXYGEN MASK STOWAGE BOX								Component	ATA:35
PN:1186F6-23	MOS/MSC	01-Aug-13	O/C	TSN 0							
SN:01036	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 35-11-01, AMM 35-11-01											
35-11-01		PILOT OXYGEN MASK STOWAGE BOX								Component	ATA:35
PN:1186F6-23	MOS/MSC	01-Aug-13	O/C	TSN 0							
SN:01037	HRS	0		TSN 0							
	AFL	0		TSN 0							
PROC. REF: AMM 35-11-01, AMM 35-11-01											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 35 - OXYGEN											
35-11-02		LEFT CREW OXYGEN MASK								Component	ATA:35
PN:174232-93	MOS/MSC	21-Jul-19	O/C	TSN 108, TSO 6							
SN:29094	HRS	1612.9	TSN 1321, TSO 0								
	AFL	883	TSN 1486, TSO 0								
PROC. REF: AMM 35-11-02, AMM 35-11-02											
35-11-02		RIGHT CREW OXYGEN MASK								Component	ATA:35
PN:174232-93	MOS/MSC	09-Nov-21	O/C								
SN:37554	HRS	2059.7									
	AFL	1192									
PROC. REF: AMM 35-11-02, AMM 35-11-02											
35-11-02-001		DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK								Service	ATA:35
PN:174232-93	MOS	27-Aug-21	24 (+1m/-1m)	27-Aug-23		27-Sep-23	130 d (+31)				
SN:29094	HRS	1988.6									
	AFL	1157									
PROC. REF: AMM 35-11-02											
35-11-02-001		DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK								Service	ATA:35
PN:174232-93	MOS	09-Nov-21	24 (+1m/-1m)	09-Nov-23		09-Dec-23	204 d (+30)				
SN:37554	HRS	2059.7									
	AFL	1192									
PROC. REF: AMM 35-11-02											
35-11-02-002		RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK								Service	ATA:35
PN:174232-93	MOS	21-Jul-19	72 (+1m/-1m)	TAC 6	21-Jan-25	21-Feb-25	643 d (+31)				
SN:29094	HRS	1612.9	3600 (+30/-30)	5212.9		5242.9	2816.5 (+30)				
	AFL	883									
PROC. REF: AMM 35-11-02											
35-11-02-002		RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK								Service	ATA:35
PN:174232-93	MOS	09-Nov-21	72 (+1m/-1m)	09-Nov-27		09-Dec-27	1665 d (+30)				
SN:37554	HRS	2059.7	3600 (+30/-30)	5659.7		5689.7	3263.3 (+30)				
	AFL	1192									
PROC. REF: AMM 35-11-02											
35-11-02-003		DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK								Service	ATA:35
PN:174232-93	MOS/MSC	N/A									
SN:29094	HRS										
	AFL										
PROC. REF: AMM 35-11-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK									Service ATA:35
PN:174232-93	MOS/MSC		N/A							
SN:37554	HRS									
	AFL									
PROC. REF: AMM 35-11-02										
35-11-04-001 ^S	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED)									Service ATA:35
	MOS	21-Aug-22	36 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 35-11-04										
PKG:82										
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE									Service ATA:35
	MOS	16-Aug-22	36 (+30d/-30d)	Adj -26d	21-Jul-25	20-Aug-25	824 d (+30)	AIRWORTHINESS		
	HRS	2308.8	2400 (+30/-30)		4708.8	4738.8	2312.4 (+30)			
	AFL	1307								
PROC. REF: AMM 35-21-00										
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE									Service ATA:35
	MOS	21-Aug-22	36 (+30d/-30d)	Adj -31d	21-Jul-25	20-Aug-25	824 d (+30)	AIRWORTHINESS		
	HRS	2308.8	2400 (+30/-30)		4708.8	4738.8	2312.4 (+30)			
	AFL	1307								
PROC. REF: AMM 35-21-00										
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:4411071-012	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4411071-012-00155	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:4411072-012	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4411072-012-00340	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:4411072-012	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4411072-012-00382	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:4411072-012	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4411072-012-00384	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER									Component ATA:35
PN:4411072-012	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:4411072-012-00408	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 35-21-01, AMM 35-21-01										
35-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS									Service ATA:35
	MOS	21-Aug-22	36 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 35-21-01										PKG:82
35-31-01	PBE - PROTECTIVE BREATHING EQUIPMENT									Component ATA:35
PN:MR-10022NEMB	MOS/MSC	01-Apr-13	H/T	TSN 0						
SN:E1300994	HRS			TSN 0						
	AFL			TSN 0						
PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-31-01-001	DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)									Service ATA:35
PN:MR-10022NEMB	MOS	01-Apr-13	126 (+1m/-1m)		01-Oct-23		01-Nov-23	165 d (+31)	LIFE LIMIT	
SN:E1300994	HRS									
	AFL									
PROC. REF: AMM 35-31-01										
ATA 36 - PNEUMATIC										
36-00-00-710-801-A	TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK									Service ATA:36
	MOS/MSC	01-Aug-13	A/R							
	HRS	0								
	AFL	0								
PROC. REF: AMM 36-00-00										
36-01-01	PNEUMATIC INSC ILLUM PANEL									Component ATA:36
PN:441-42633-002	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1192	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-01-01, AMM 36-01-01										
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE									Component ATA:36
PN:RYLB-53505-5	MOS/MSC	14-Jul-21	O/C							
SN:0340	HRS	1973.8								
	AFL	1142								
PROC. REF: AMM 36-11-01, AMM 36-11-01										
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE									Component ATA:36
PN:RYLB-53505-6	MOS/MSC	14-Jun-18	O/C							
SN:0389	HRS	1300.6		TSN 317						
	AFL	657		TSN 180						
PROC. REF: AMM 36-11-01, AMM 36-11-01										
36-11-01-001 ^S	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER									Service ATA:36
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-01										PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-11-01-002 ^S		OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION							Service	ATA:36
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 36-11-00										PKG:1
36-11-02-001 ^S		DETAILED INSPECTION OF BLEED LINE WATER DRAINS							Service	ATA:36
	MOS	27-Aug-21	24 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 36-11-02										PKG:81
36-11-03		AMS CONTROLLER							Component	ATA:36
PN:SYLZ-53632-205	MOS/MSC	18-Dec-15	O/C							
SN:0241	HRS	625.9								
	AFL	328								
PROC. REF: AMM 36-11-03, AMM 36-11-03										
36-11-04		NO. 1 ENGINE FAN AIR VALVE							Component	ATA:36
PN:RYLB-53527-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0381	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-04, AMM 36-11-04										
36-11-04		NO. 2 ENGINE FAN AIR VALVE							Component	ATA:36
PN:RYLB-53527-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0391	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-04, AMM 36-11-04										
36-11-04-001 ^S		RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER							Service	ATA:36
	MOS	01-Aug-13								
	HRS	0	2400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-04										PKG:20
36-11-05		LH INCONEL 625 BLEED PRE-COOLER							Component	ATA:36
PN:10965000-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:T0165	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-05, AMM 36-11-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-11-05	RH INCONEL 625 BLEED PRE-COOLER									Component ATA:36
PN:10964000-105	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:T0158	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-05, AMM 36-11-05										
36-11-06	CROSS BLEED VALVE									Component ATA:36
PN:RYLB-53506-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0207	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-06, AMM 36-11-06										
36-11-06-001 ^S	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION									Service ATA:36
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 36-11-06										PKG:1
36-11-06-002 ^S	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER									Service ATA:36
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-06										PKG:60
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER									Component ATA:36
PN:APTE-479F-1000-200G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8051-5-49	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-07, AMM 36-11-07										
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER									Component ATA:36
PN:APTE-479F-1000-200G	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8051-5-61	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-07, AMM 36-11-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR									Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:DTN3488	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-08, AMM 36-11-08										
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR									Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:DTN3497	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-08, AMM 36-11-08										
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR									Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:DTP6067	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-08, AMM 36-11-08										
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR									Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:DTP6070	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 36-11-08, AMM 36-11-08										
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR									Service ATA:36
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-08										PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR									Service ATA:36
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-08										PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR									Service ATA:36
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-08										PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-11-08-001 ^S		FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR							Service	ATA:36
	MOS	01-Aug-13								
	HRS	0	6400 (+30/-30)							
	AFL	0								
PROC. REF: AMM 36-11-08										PKG:60
36-21-01-001		OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS							Service	ATA:36
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	6400 (+30/-30)		6400	6430	4003.6 (+30)			
	AFL	0								
PROC. REF: AMM 36-21-01										
ATA 38 - WATER/WASTE										
38-33-00		TOILET ASSY							Component	ATA:38
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
38-33-07		WASTE DRAIN VALVE							Component	ATA:38
PN:0218-0032-1	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:183529	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 38-33-07, AMM 38-33-07										
38-33-12 ^U		LAVATORY PUMP							Component	ATA:38
PN:RCP5161-00	MOS/MSC	22-Feb-20	O/C	TSR 3						
SN:03140656	HRS	1769.3		TSR 0						
	AFL	998		TSR 0						
ATA 44 - CABIN SYSTEMS										
44-12-07		3-CHANNEL AUDIO AMPLIFIER							Component	ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-12-07, AMM 44-12-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 44 - CABIN SYSTEMS										
44-21-03	DC-DC CONVERTER									Component ATA:44
PN:35-192-00	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:191	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-03, AMM 44-21-03										
44-21-09	IFE INSC ILLUM PANEL									Component ATA:44
PN:441-44843-001	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1021	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-09, AMM 44-21-09										
44-21-11	XM RECEIVER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-23-21, AMM 44-23-21, AMM 44-21-11, AMM 44-21-11										
44-21-13	XM HEAD CONTROL									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-13, AMM 44-21-13										
44-21-15	AUDIO VOLUME CONTROLLER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-15, AMM 44-21-15										
44-21-17	IR RECEIVER WITH CONNECTOR									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-17, AMM 44-21-17										
44-21-19	IR REMOTE CONTOLLER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-17, AMM 44-21-17										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 44 - CABIN SYSTEMS										
44-21-21	WIRELESS AUDIO TRANSMITTER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-21, AMM 44-21-21										
44-21-23	NO. 1 WIRELESS HEADPHONE									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
44-21-23	NO. 2 WIRELESS HEADPHONE									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
44-21-25	HEADPHONE DISTRIBUTION AMPLIFIER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-25, AMM 44-21-25										
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-22-01, AMM 44-22-01										
44-22-03	NO. 1 10.4 INCH FOLD DOWN MONITOR-									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-22-03, AMM 44-22-03										
44-32-01	ATG5000 TRANSCEIVER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-32-01, AMM 44-32-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 44 - CABIN SYSTEMS										
44-32-03	AIRCELL CONFIGURATION MODULE									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-32-03, AMM 44-32-03										
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-32-05, AMM 44-32-05										
442127-0101	LH NO. 1 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										
442127-0102	RH NO. 2 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										
442127-0103	LH NO. 3 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										
442127-0104	RH NO. 4 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										
442127-0105	LH NO. 5 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 44 - CABIN SYSTEMS										
442127-0106	RH NO. 6 AUDIO CONTROL JACK									Component ATA:44
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11										
ATA 52 - DOORS										
52-00-00	KEY LOCK KIT									Component ATA:52
PN:505-09736-901	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:8MA000860CK	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
52-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE									Service ATA:52
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 52-10-00										PKG:84
52-10-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE									Service ATA:52
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 52-10-00										PKG:84
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL								Service ATA:52	
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-10-00										
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL								Service ATA:52	
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL								Service	ATA:52
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-10-00										
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL								Service	ATA:52
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-10-00										
52-10-20-001 ^S	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL								Service	ATA:52
	MOS	18-Aug-22	12 (+1m/-1m)							
	HRS	2308.8								
	AFL	1307								
PROC. REF: AMM 52-10-20										PKG:80
52-11-00-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM								Service	ATA:52
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 52-11-00										PKG:83
52-11-00-003 ^S	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH								Service	ATA:52
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 52-11-23										PKG:1
52-13-00	MAIN DOOR BALANCE ASSY. GEAR SECTOR								Component	ATA:52
PN:PN	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-13-01	MAIN DOOR BALANCE ASSY. PINION SHAFT								Component	ATA:52
PN:PN	MOS/MSC	01-Aug-13	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
52-13-21-001 ^S	DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED)								Service	ATA:52
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 52-13-21										PKG:50
52-13-22	MAIN DOOR BALANCING MECHANISM								Component	ATA:52
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22										
52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE								Service	ATA:52
PN:PN	MOS/MSC	18-Dec-15	O/C							
SN:UNKNOWN	HRS	625.9								
	AFL	328								
PROC. REF: AMM 52-13-22										
52-13-22-004 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES								Service	ATA:52
	MOS	01-Aug-13								
	HRS	0	3200 (+30/-30)							
	AFL	0								
PROC. REF: AMM 52-13-22										PKG:40
52-13-23-001 ^S	DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED)								Service	ATA:52
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 52-13-23										PKG:50
52-20-00	EMERGENCY DOOR								Component	ATA:52
PN:500-09700-439	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000768318	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-20-01-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service	ATA:52
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 52-20-00						PKG:87				
52-20-01-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service	ATA:52
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00						PKG:90				
52-20-01-01-901		GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL							Service	ATA:52
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-20-00										
52-20-01-01-902		DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL							Service	ATA:52
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 52-20-00										
52-20-20-001 ^S		INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM							Service	ATA:52
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 52-20-20						PKG:83				
52-20-21-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL							Service	ATA:52
	MOS	27-Aug-21	24 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 52-20-21						PKG:81				
52-31-20-001 ^S		GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM							Service	ATA:52
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 52-31-20						PKG:83				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-32-20-001 ^S		GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM							Service	ATA:52
	MOS	27-Aug-21	48 (+1m/-1m)							
	HRS	1988.6								
	AFL	1157								
PROC. REF: AMM 52-32-20							PKG:83			
52-71-20		LOWER PAX DOOR MICRO SWITCH ASSEMBLY							Component	ATA:52
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-71-20, AMM 52-71-20										
52-71-20		UPPER PAX DOOR MICRO SWITCH ASSEMBLY							Component	ATA:52
PN:PN	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 52-71-20, AMM 52-71-20										
ATA 53 - FUSELAGE										
53-00-00-001 ^S		GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS							Service	ATA:53
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 53-00-20							PKG:1			
53-05-00-001 ^S		DETAILED INSPECTION OF FUSELAGE DRAINS							Service	ATA:53
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: AMM 53-05-00							PKG:84			
53-10-00-001 ^S		INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-10-00							PKG:90			
53-10-00-002 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES							Service	ATA:53
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-10-00							PKG:87			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-00-003 ^S		INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE							Service	ATA:53
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-10-00										PKG:87
53-10-01-01-901		DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-01-01-902		DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-02-01-901		GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-02-01-902		DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-03-01-901		GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-10-00										PKG:90
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-10-00										
53-10-07-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE								Service	ATA:53
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 53-10-00										PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 5 53-10-00										
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 5 53-10-00										
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WEEL STRUCTURE.								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 5 53-10-00										
53-14-00	NOSE RADOME								Component	ATA:53
PN:5190-102-1	MOS/MSC	06-Dec-16	O/C	TSN 37						
SN:502	HRS	862.2		TSN 862.2						
	AFL	431		TSN 431						
PROC. REF: AMM 53-14-00, AMM 53-14-00										
53-20-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-20-00										PKG:90
53-20-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-20-00										PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 53-20-00										
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-20-00										PKG:90
53-20-05-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-20-00										PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-06-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE								Service	ATA:53
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 53-20-00										PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-20-06-002 ^S		INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service	ATA:53
	MOS	06-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 53-20-00										PKG:90
53-20-06-01-901		DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-06-01-902		DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:8750		8750		6353.6			
	AFL	0	T:7000		7000		5641			
PROC. REF: NDT PART 5 53-20-00										
53-20-07-01-901		DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-07-01-902		DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-08-002 ^S		INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE							Service	ATA:53
	MOS	07-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 53-20-00										PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-10-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-20-00										PKG:90
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-00-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: NDT PART 5 53-30-00		PKG:90		
53-30-00-002 ^S		INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: NDT PART 5 53-30-00		PKG:90		
53-30-01-01-901		GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
						PROC. REF: NDT PART 5 53-30-00				
53-30-01-01-902		DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
						PROC. REF: NDT PART 5 53-30-00				
53-30-02-002 ^S		INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
						PROC. REF: NDT PART 5 53-30-00		PKG:90		
53-30-02-01-901		DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:12500		12500		10103.6			
	AFL	0	T:10000		10000		8641			
						PROC. REF: NDT PART 5 53-30-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-30-00										PKG:90
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:10000		10000		7603.6			
	AFL	0	T:8000		8000		6641			
PROC. REF: NDT PART 5 53-30-00										
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:12500		12500		10103.6			
	AFL	0	T:10000		10000		8641			
PROC. REF: NDT PART 5 53-30-00										
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL								Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-07-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION								Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-30-00										PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-07-002 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-30-00						PKG:90				
53-30-07-01-901		GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-07-01-902		DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL							Service	ATA:53
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 53-30-00										
53-30-08-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service	ATA:53
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-30-00						PKG:87				
53-30-08-002 ^S		INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service	ATA:53
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 53-30-00						PKG:90				
ATA 54 - NACELLES/PYLONS										
54-00-00-001 ^S		GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS							Service	ATA:54
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 54-51-20						PKG:1				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-50-00-001 ^S		INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE							Service	ATA:54
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 54-50-00										PKG:90
54-50-00-002 ^S		INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX							Service	ATA:54
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00										PKG:90
54-50-01-01-901		GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL							Service	ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-50-00										
54-50-02-01-901		GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL							Service	ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-50-00										
54-50-03-001 ^S		EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.							Service	ATA:54
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 54-52-00										PKG:84
54-50-03-01-901		GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL							Service	ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-52-00										
54-50-03-01-902		DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL							Service	ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-52-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL									Service ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-52-00										
54-50-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES									Service ATA:54
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 54-55-00										PKG:87
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL									Service ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 6 54-55-00										
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL									Service ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 54-55-00										
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL									Service ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 5 54-55-00										
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL									Service ATA:54
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:15000		15000		12603.6			
	AFL	0	T:12000		12000		10641			
PROC. REF: NDT PART 5 54-55-00										
ATA 55 - STABILIZERS										
55-00-00-001 ^S	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS									Service ATA:55
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
	AFL	1220								
PROC. REF: AMM 55-00-20										PKG:1
55-10-00	HORIZONTAL STABILIZER (COMPLETION)								Component	ATA:55
PN:505-10700-413	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000767289	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
55-10-00-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS								Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-10-00										PKG:84
55-10-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING								Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-10-00										PKG:84
55-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS								Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-10-00										PKG:84
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-02-01-902		DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-10-00										PKG:87
55-10-03-002 ^S		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-10-00										PKG:84
55-10-03-01-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-03-01-902		DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-04-01-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-05-001 ^S		INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS							Service	ATA:55
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-10-00						PKG:90				
55-10-05-01-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-05-02-901		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-10-00										
55-10-05-02-902		SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-05-03-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-05-04-901		DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-10-00										
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-08-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS								Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-10-00										PKG:84
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-09-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT								Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-10-00										PKG:87
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-09-01-902		DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL								Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-10-10-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS								Service ATA:55
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-10-00										
PKG:90										
55-10-10-01-901		DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL								Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-10-00										
55-20-01-002 ^S		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX								Service ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00										
PKG:87										
55-20-01-01-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL								Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-20-00										
55-20-01-01-902		DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL								Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-20-00										
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-20-00										
55-20-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY									Service ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-20-00										PKG:87
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-20-00										
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 8 55-20-00										
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS									Service ATA:55
	MOS	27-Aug-21	60		27-Aug-26		1226 d	ALI		
	HRS	1988.6								
	AFL	1157								
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS									Service ATA:55
	MOS	27-Aug-21	60		27-Aug-26		1226 d	ALI		
	HRS	1988.6								
	AFL	1157								
PROC. REF: NDT PART 5 55-20-00										
55-22-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB									Service ATA:55
	MOS	01-Aug-13	T:120							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-22-00										PKG:90
55-30-00	VERTICAL STABILIZER									Component ATA:55
PN:505-10100-413	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:0000768317	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
55-30-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER									Service ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-30-00										PKG:84
55-30-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER									Service ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-30-00										PKG:90
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-30-00										
55-30-02-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER								Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-30-00										PKG:84
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 55-30-00										
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-03-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS								Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-30-00										PKG:87
55-30-03-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX								Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00										PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-03-01-901		DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-03-01-902		SPECIAL DETAILED INSPECTION (BOREScope) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-04-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING							Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-30-00										PKG:84
55-30-04-01-901		GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-30-05-002 ^S		INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER							Service	ATA:55
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 55-30-00										PKG:84
55-30-05-01-901		DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-30-06-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING							Service	ATA:55
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-30-00										PKG:90
55-30-06-01-901		DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-30-00										
55-40-01-002 ^S		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX							Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-40-00										PKG:87
55-40-01-01-901		SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-40-00										
55-40-01-01-902		DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL							Service	ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-40-00										
55-40-02-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS							Service	ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-40-00										PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-40-00										
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-40-00										
55-40-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY									Service ATA:55
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-40-00										PKG:87
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL									Service ATA:55
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 55-40-00										
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS									Service ATA:55
	MOS	27-Aug-21	60		27-Aug-26		1226 d	ALI		
	HRS	1988.6								
	AFL	1157								
PROC. REF: NDT PART 5 55-40-00										
55-40-04-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS									Service ATA:55
	MOS	27-Aug-21	60		27-Aug-26		1226 d	ALI		
	HRS	1988.6								
	AFL	1157								
PROC. REF: NDT PART 5 55-40-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-42-00-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB							Service	ATA:55
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 55-42-00										PKG:90
ATA 56 - WINDOWS										
56-10-00		LEFT GLASS, HEATED WINDSHIELD ASSY, (LH)							Component	ATA:56
PN:NP-195301-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:12355H0712	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-11-00, AMM 56-11-00										
56-10-00		RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH)							Component	ATA:56
PN:NP-195301-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:13101H2793	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-11-00, AMM 56-11-00										
56-10-01-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOW							Service	ATA:56
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 56-12-00										PKG:84
56-10-01-002		FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS							Service	ATA:56
	MOS	18-Nov-17								
	HRS	1111.12	1600 (+30/-30)	2711.12	2741.12	314.7 (+30)				
	AFL	555								
PROC. REF: AMM 56-10-00										
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE							Service	ATA:56
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 56-10-00										PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE							Service	ATA:56
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 56-10-00						PKG:90				
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE							Service	ATA:56
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 56-10-00						PKG:90				
56-10-03-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE							Service	ATA:56
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 56-10-00						PKG:90				
56-10-03-01-901		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL							Service	ATA:56
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 56-10-00										
56-12-00		LEFT ACRYLIC SIDE WINDOW							Component	ATA:56
PN:NP-195302-3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:13005H1825	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 56-12-00, AMM 56-12-00										
56-12-00		RIGHT ACRYLIC SIDE WINDOW							Component	ATA:56
PN:NP-195302-4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:13044H6499	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 56-12-00, AMM 56-12-00										
56-20-00		NO. 1 WINDOW TRANSPARENCY							Component	ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020948	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 56-20-00, AMM 56-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-20-00	NO. 10 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020992	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 11 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020992	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 2 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020950	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 3 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020956	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 4 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020961	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 5 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020962	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 6 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020985	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-20-00	NO. 7 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020986	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 8 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020990	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-00	NO. 9 WINDOW TRANSPARENCY									Component ATA:56
PN:14024	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2020991	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 56-20-00, AMM 56-20-00										
56-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS									Service ATA:56
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 56-20-00										PKG:84
ATA 57 - WINGS										
57-00-00-001 ^S	GENERAL VISUAL INSPECTION OF WINGLET POLYURETHANE FILMS									Service ATA:57
	MOS	25-Jan-22								
	HRS	2121.9	800 (+30/-30)							
	AFL	1220								
PROC. REF: AMM 57-35-21										PKG:1
57-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX									Service ATA:57
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-10-00										PKG:90
57-10-00-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN									Service ATA:57
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-10-00										PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-01-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS							Service	ATA:57
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-00-00										PKG:87
57-10-01-01-901		DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL							Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-02-002 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR							Service	ATA:57
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-10-00										PKG:90
57-10-02-01-901		DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL							Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-03-002 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR							Service	ATA:57
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-10-00										PKG:90
57-10-03-01-901		DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL							Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-04-002 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR							Service	ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-20-00										PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL									Service ATA:57
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-10-00										PKG:87
57-10-07-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL									Service ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-10-00										PKG:84
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-11-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE									Service ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-10-00										PKG:84
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-10-00										
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:12500		12500		10103.6			
	AFL	0	T:10000		10000		8641			
PROC. REF: NDT PART 5 57-10-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-50-01-001 ^S		EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS								Service ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-50-00										PKG:84
57-50-01-01-901		DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										
57-50-01-01-902		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:11250		11250		8853.6			
	AFL	0	T:9000		9000		7641			
PROC. REF: NDT PART 6 57-50-00										
57-50-01-02-901		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL								Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-50-00										
57-50-01-03-901		DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL								Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										
57-50-01-04-901		DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL								Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-50-00										
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										
57-50-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK								Service	ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-20-00										PKG:84
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-50-00										
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-50-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-50-00										
57-52-00-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP								Service	ATA:57
	MOS	01-Aug-13	T:120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-52-00										
										PKG:90
57-52-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP								Service	ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-52-00										
										PKG:84
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-52-00										
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-52-00										
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-52-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:11250		11250		8853.6			
	AFL	0	T:9000		9000		7641			
PROC. REF: NDT PART 6 57-52-00										
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-52-00										
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-52-00										
57-53-00-001 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE OUTBOARD FLAP									Service ATA:57
	MOS	01-Aug-13	120 (+1m/-1m)							
	HRS	0								
	AFL	0								
PROC. REF: NDT PART 5 57-53-00										PKG:87
57-53-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP									Service ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-53-00										PKG:84
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:11250		11250		8853.6			
	AFL	0	T:9000		9000		7641			
PROC. REF: NDT PART 6 57-53-00										
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-53-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 6 57-53-00										
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON								Service	ATA:57
	MOS	27-Aug-21	60		27-Aug-26		1226 d	ALI		
	HRS	1988.6								
	AFL	1157								
PROC. REF: NDT PART 5 57-60-00										
57-60-00-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON AND TAB								Service	ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-60-00										PKG:84
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-60-00										
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-60-00										
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL								Service	ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-60-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-60-00										
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL									Service ATA:57
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:17500		17500		15103.6			
	AFL	0	T:14000		14000		12641			
PROC. REF: NDT PART 5 57-60-00										
57-60-04-001 ^U	INTERNAL DETAILED VISUAL INSPECTION OF AILERON MASS-BALANCE WEIGHTS AND ATTACHMENTS									Service ATA:57
	MOS/MSC	14-Aug-20	O/C							
	HRS	1832.6								
	AFL	1049								
57-70-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS									Service ATA:57
	MOS	20-Aug-18	60 (+1m/-1m)							
	HRS	1321.5								
	AFL	673								
PROC. REF: NDT PART 5 57-70-00										PKG:84
ATA 70 - STANDARD PRACTICES - ENGINES										
700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION									Service ATA:70
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 70-00-00										
700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION									Service ATA:70
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 70-00-00										
ATA 71 - POWER PLANT										
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS									Service ATA:71
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
PROC. REF: MM 70-00-00										
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS									Service ATA:71
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 70-00-00										
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH									Service ATA:71
	DAYS/MSC	06-Apr-16	A/R							
	HRS	694.9								
	ENC	349								
PROC. REF: MM 71-00-00										
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH									Service ATA:71
	DAYS/MSC	06-Apr-16	A/R							
	HRS	694.9								
	ENC	373								
PROC. REF: MM 71-00-00										
71-00-00-160-806	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH									Service ATA:71
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-160-806	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH									Service ATA:71
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN									Service ATA:71
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-00-00-760-810		NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN							Service	ATA:71
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-814		NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service	ATA:71
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-814		NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service	ATA:71
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-817		NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA							Service	ATA:71
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-817		NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA							Service	ATA:71
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 71-00-00										
71-00-00-760-823		NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service	ATA:71
	MOS	18-Aug-22	12 (+30d)		18-Aug-23	17-Sep-23	121 d (+30)			
	HRS	2308.8	630 (+10%)		(2938.8) 2938.8	3001.8	542.4 (+63)			
	ENC	1307								
PROC. REF: MM 71-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-00-00-760-823		NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)								Service ATA:71
	MOS	18-Aug-22	12 (+30d)		18-Aug-23	17-Sep-23	121 d (+30)			
	HRS	2308.8	630 (+10%)		(2938.8) 2938.8	3001.8	542.4 (+63)			
	ENC	1307								
PROC. REF: MM 71-00-00										
71-11-00-001 ^S		GENERAL VISUAL INSPECTION OF UPPER MID COWL								Service ATA:71
	MOS	01-Aug-13								
	HRS	0	5600 (+30/-30)							
	AFL	0								
PROC. REF: AMM 71-11-00										PKG:50
71-20-00		LEFT AFT ENGINE MOUNT ISOLATOR								Component ATA:71
PN:LM-475-SA4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK0634	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-22-00, AMM 71-22-00										
71-20-00		LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR								Component ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK1191	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-21-00, AMM 71-21-00										
71-20-00		LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR								Component ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK1189	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-21-00, AMM 71-21-00										
71-20-00		RIGHT AFT ENGINE MOUNT ISOLATOR								Component ATA:71
PN:LM-475-SA4	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK0643	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-22-00, AMM 71-22-00										
71-20-00		RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR								Component ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK1186	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-21-00, AMM 71-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR									Component ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:LK1188	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 71-21-00, AMM 71-21-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA4	MOS/MSC	01-Aug-13	O/C							
SN:LK0634	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C							
SN:LK1191	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C							
SN:LK1189	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA4	MOS/MSC	01-Aug-13	O/C							
SN:LK0643	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C							
SN:LK1186	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS									Service ATA:71
PN:LM-475-SA3	MOS/MSC	01-Aug-13	O/C							
SN:LK1188	HRS	0								
	AFL	0								
PROC. REF: AMM 71-20-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-21-01-01-901		RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY							Service	ATA:71
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:7500		7500		5103.6			
	AFL	0	T:6000		6000		4641			
PROC. REF: AMM 71-20-00										
71-22-01-01-901		DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL							Service	ATA:71
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:4500		4500		2103.6			
	AFL	0	T:3600		3600		2241			
PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00										
71-22-01-01-902		RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY							Service	ATA:71
	MOS	01-Aug-13						AIRWORTHINESS		
	HRS	0	T:7500		7500		5103.6			
	AFL	0	T:6000		6000		4641			
PROC. REF: AMM 71-20-00										
71-31-00-001 ^S		DETAILED INSPECTION OF PYLON FIREWALL SEAL							Service	ATA:71
	MOS	13-Mar-20								
	HRS	1779.4	2400 (+30/-30)							
	AFL	1007								
PROC. REF: AMM 71-31-00										PKG:20
71-60-01		LEFT ENGINE AIR INLET							Component	ATA:71
PN:505-43420-403	MOS/MSC	06-Dec-16	O/C	TSN 0						
SN:CPI388	HRS	862.2		TSN 0						
	AFL	431		TSN 0						
PROC. REF: AMM 71-60-01, AMM 71-60-01										
71-60-01		RIGHT ENGINE AIR INLET							Component	ATA:71
PN:505-43430-403	MOS/MSC	06-Dec-16	O/C	TSN 0						
SN:CPI353	HRS	862.2		TSN 0						
	AFL	431		TSN 0						
PROC. REF: AMM 71-60-01, AMM 71-60-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71EN1	NO. 1 ENGINE									Component ATA:71
PN:A3072913-01	MOS/MSC	05-Sep-13	E/C							
SN:PCE-DG0338	HRS	0								
WC#: 71.EN1	AFL	0								
PROC. REF: AMM 71-00-00, AMM 71-00-00										
71EN2	NO. 2 ENGINE									Component ATA:71
PN:A3072913-01	MOS/MSC	17-Sep-13	E/C							
SN:PCE-DG0339	HRS	0								
WC#: 71.EN2	AFL	0								
PROC. REF: AMM 71-00-00, AMM 71-00-00										
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION									Service ATA:71
	MOS	19-Aug-22	12		19-Aug-23		122 d			
	HRS	2308.8	630		(2938.8) 2938.8		542.4			
	ENC	1307								
PROC. REF: MM 72-00-02										
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION									Service ATA:71
	MOS	19-Aug-22	12		19-Aug-23		122 d			
	HRS	2308.8	630		(2938.8) 2938.8		542.4			
	ENC	1307								
PROC. REF: MM 72-00-02										
ATA 72 - ENGINE										
72-00-00-000-802	NO. 1 ENGINE - DISCARD GAS GENERATOR CASE									Service ATA:72
PN:3076150-01	MOS									
SN:RWA06E387	HRS									
	ENC	EFF	8200		(8200) 8200 *		6841			
PROC. REF: GENERIC NO REF										
72-00-00-000-802	NO. 2 ENGINE - DISCARD GAS GENERATOR CASE									Service ATA:72
PN:3076150-01	MOS									
SN:RWA11E898	HRS									
	ENC	EFF	8200		(8200) 8200 *		6841			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00-212-801 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-801 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-802 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-802 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-803 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-803 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-804 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00-212-804 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-805 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-805 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-806 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-806 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-807 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-807 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00-212-808 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-808 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-809 ^S		NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-212-809 ^S		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service	ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-280-802		NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR							Service	ATA:72
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										
72-00-00-280-802		NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR							Service	ATA:72
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										
72-00-00-280-818		NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)							Service	ATA:72
	MOS	26-Jul-13	T:120 (+1m)		26-Jul-23	26-Aug-23	98 d (+31)			
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)									Service ATA:72
	MOS	28-Jul-13	T:120 (+1m)		28-Jul-23		28-Aug-23	100 d (+31)		
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										
72-00-00-280-820 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES									Service ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-280-820 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES									Service ATA:72
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL									Service ATA:72
	MOS/MSC	01-Aug-18	BF/F							
	HRS	1321.5								
	ENC	697								
PROC. REF: MM 72-00-00										
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL									Service ATA:72
	MOS/MSC	01-Aug-18	BF/F							
	HRS	1321.5								
	ENC	697								
PROC. REF: MM 72-00-00										
72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS									Service ATA:72
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										
72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS									Service ATA:72
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-01-810-822	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)									Service ATA:72
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-01										
72-00-01-810-822	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)									Service ATA:72
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-01										
72-00-51-030-002	NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER									Service ATA:72
	MOS	EFF						LIFE LIMIT		
	HRS	EFF	5000 (+100)		(5000) 5000 *	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 72-50-01, MM 72-50-01										
72-00-51-030-002	NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER									Service ATA:72
	MOS	EFF						LIFE LIMIT		
	HRS	EFF	5000 (+100)		(5000) 5000 *	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 72-50-01, MM 72-50-01										
72-60-01-212-801	NO. 1 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES									Service ATA:72
	MOS	19-Aug-22								
	HRS	2308.8	1200 (+100)		(3508.8) 3508.8	3608.8	1112.4 (+100)			
	ENC	1307								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-60-01-212-801	NO. 2 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES									Service ATA:72
	MOS	19-Aug-22								
	HRS	2308.8	1200 (+100)		(3508.8) 3508.8	3608.8	1112.4 (+100)			
	ENC	1307								
PROC. REF: GENERIC NO REF										
720010	NO. 1 ENGINE - OVERHAUL									Service ATA:72
	MOS	26-Jul-13								
	HRS	0	5000 (+100)		(5000) 5000	5100	2603.6 (+100)			
	ENC	0								
PROC. REF: GENERIC NO REF										
720010	NO. 2 ENGINE - OVERHAUL									Service ATA:72
	MOS	28-Jul-13								
	HRS	0	5000 (+100)		(5000) 5000	5100	2603.6 (+100)			
	ENC	0								
PROC. REF: GENERIC NO REF										
720060	NO. 1 ENGINE - HOT SECTION INSPECTION									Service ATA:72
	MOS	26-Jul-13								
	HRS	0	2500 (+50)		(2500) 2500	2550	103.6 (+50)			
	ENC	0								
PROC. REF: MM 72-00-00										
720060	NO. 2 ENGINE - HOT SECTION INSPECTION									Service ATA:72
	MOS	28-Jul-13								
	HRS	0	2500 (+50)		(2500) 2500	2550	103.6 (+50)			
	ENC	0								
PROC. REF: MM 72-00-00										
721010	NO. 1 ENGINE - GEARBOX									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
721010	NO. 2 ENGINE - GEARBOX									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722001	NO. 1 ENGINE - OIL PUMP									Component ATA:72
PN:3073477-02	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:EC01A004A019	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 79-20-02, MM 79-20-02										
722001	NO. 2 ENGINE - OIL PUMP									Component ATA:72
PN:3073477-02	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:EC01A004A018	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 79-20-02, MM 79-20-02										
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY									Component ATA:72
PN:3073356-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:PKAAA497643	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	30000	TSN 0			28641			
PROC. REF: GENERIC NO REF										
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY									Component ATA:72
PN:3073356-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:PKAAA497639	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	30000	TSN 0			28641			
PROC. REF: GENERIC NO REF										
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR									Component ATA:72
PN:3073311-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003AEWD	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	15000	TSN 0			13641			
PROC. REF: MM 72-30-01, MM 72-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723010		NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR							Component	ATA:72
PN:3073311-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A00387F5	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	15000	TSN 0			13641			
PROC. REF: MM 72-30-01, MM 72-30-01										
723020		NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR							Component	ATA:72
PN:3073292-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:TXA1D0221	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	15000	TSN 0			13641			
PROC. REF: GENERIC NO REF										
723020		NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR							Component	ATA:72
PN:3073292-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:TXA1D0220	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	15000	TSN 0			13641			
PROC. REF: GENERIC NO REF										
723030		NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component	ATA:72
PN:3072981-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003B74T	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
723030		NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component	ATA:72
PN:3072981-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A003BB01	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
723040		NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR							Component	ATA:72
PN:3056210-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:EAAD000C512	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR									Component ATA:72
PN:3056210-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:EAAD000C513	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY									Component ATA:72
PN:3075221-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:EDA01270U	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-30-02, MM 72-30-02										
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY									Component ATA:72
PN:3075221-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:EDA0128T	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-30-02, MM 72-30-02										
723060	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723060	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY									Component ATA:72
PN:3075850-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:A003C2N0	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY									Component ATA:72
PN:3075850-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:A003B9CN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY									Component ATA:72
PN:3076150-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:RWA06E387	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY									Component ATA:72
PN:3076150-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:RWA11E898	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER									Component ATA:72
PN:3073236-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:A003BP6L	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER									Component ATA:72
PN:3073236-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:A003BPDH	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3052673-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PKAAA499889	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3052673-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PKAAA499890	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER									Component ATA:72
PN:3052668-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AFD00M164	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER									Component ATA:72
PN:3052668-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:AFDOOM168	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER									Component ATA:72
PN:3072571-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UAC9230	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER									Component ATA:72
PN:3072571-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UAC9227	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER									Component ATA:72
PN:3072572-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UAC9175	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER									Component ATA:72
PN:3072572-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UAC9174	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING									Component ATA:72
PN:3052737-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:LPA000013844	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING									Component ATA:72
PN:3052737-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:LPAOOOO13848	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR									Component ATA:72
PN:3072574-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:EAAD000C347	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR									Component ATA:72
PN:3072574-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:EAAD000B894	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723160	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING									Component ATA:72
PN:3052670-02	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:FCN382421	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723160	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING									Component ATA:72
PN:3052670-02	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FCN387769	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3072280-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PKAAA498484	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3072280-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PKAAA498486	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING									Component ATA:72
PN:3052616-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:FCN291815	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING									Component ATA:72
PN:3052616-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FCN293014	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723190	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723190	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK									Component ATA:72
PN:3053812-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003BADC	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK									Component ATA:72
PN:3053812-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A003B4P7	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK									Component ATA:72
PN:3053743-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003BKNX	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK									Component ATA:72
PN:3053743-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A003BKP3	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
724001	NO. 1 ENGINE - INNER COMBUSTION LINER									Component ATA:72
PN:3075516-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:A003B2M4	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-40-01, MM 72-40-01										
724001	NO. 2 ENGINE - INNER COMBUSTION LINER									Component ATA:72
PN:3075516-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:A003B0FL	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-40-01, MM 72-40-01										
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER									Component ATA:72
PN:3075522-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:A003ATN2	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-40-01, MM 72-40-01										
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER									Component ATA:72
PN:3075522-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:A003B9CN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-40-01, MM 72-40-01										
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY									Component ATA:72
PN:3075468-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:ACM221857666	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY									Component ATA:72
PN:3075468-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:ACM221857589	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK									Component ATA:72
PN:3053331-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003ATM0	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	10000	TSN 0			8641			
PROC. REF: MM 72-50-01, MM 72-50-01										
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK									Component ATA:72
PN:3053331-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A003B7M1	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	10000	TSN 0			8641			
PROC. REF: MM 72-50-01, MM 72-50-01										
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER									Component ATA:72
PN:3052661-01	MOS	26-Jul-13		TSN 0				LIFE LIMIT		
SN:A003AXPO	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER									Component ATA:72
PN:3052661-01	MOS	28-Jul-13		TSN 0				LIFE LIMIT		
SN:A003B50F	HRS	0		TSN 0						
	ENC	0		TSN 0						
	ACCCYC	0	13500	TSN 0			12141			
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKH5679	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1159	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1206	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1215	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1217	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1226	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1245	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1260	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY2879	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6464	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6468	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1114	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6477	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6483	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6486	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6488	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6490	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6493	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6496	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6497	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA6498	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7026	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1116	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7030	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7032	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7044	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7045	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7052	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7058	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7060	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7066	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7069	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7071	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1125	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7072	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7075	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7083	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7085	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7087	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7088	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7094	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7098	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7104	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7105	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1131	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7106	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7256	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7257	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7803	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7804	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7810	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7816	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7822	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7823	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7824	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1142	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7842	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1147	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1152	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWKY1158	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7853	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7854	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7858	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7864	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7867	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7869	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7873	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7879	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA7884	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:HWLA8272	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKF7098	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5221	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5224	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5225	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5226	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5232	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5237	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5243	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5258	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5260	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5265	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5180	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5266	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5268	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5271	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5275	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5278	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5415	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5418	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5464	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5471	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5512	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5181	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5522	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5528	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5536	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5539	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5546	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5561	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5567	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5569	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5575	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5578	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5187	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5584	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5585	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5589	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5593	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5595	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5601	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5604	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5605	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5608	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5609	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5196	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5612	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5613	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5614	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5619	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5621	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5624	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5628	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5630	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5631	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5633	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5199	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5651	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5208	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5210	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5215	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5652	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5655	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5661	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5667	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5668	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5670	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5673	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5673	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5678	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE									Component ATA:72
PN:3077471-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:HWKH5694	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING									Component ATA:72
PN:3073355-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:FCN386251	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING									Component ATA:72
PN:3073355-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FCN386256	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY									Component ATA:72
PN:3076552-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:RWA10E895	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-50-03										
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY									Component ATA:72
PN:3076552-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:RWA13E199	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-50-03										
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER									Component ATA:72
PN:3073353-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:MDAA003A255	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER									Component ATA:72
PN:3073353-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:MDAA003A272	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING									Component ATA:72
PN:3052263CL01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PDAKDRTC01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING									Component ATA:72
PN:3052263CL01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PDAKBBEF01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING									Component ATA:72
PN:3052361CL01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PDAH9MCM01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING									Component ATA:72
PN:3052361CL01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PDAKE1KY01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY									Component ATA:72
PN:3073262CL02	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:BHHNEBN01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY									Component ATA:72
PN:3073262CL02	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:BHHDBYD01	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING									Component ATA:72
PN:3052549-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FCN388396	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:3073908-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AEB0166324	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:3073908-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AEB0166327	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:3073908-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AEB0166374	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:3073908-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AEB0166388	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726060	NO. 1 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726060	NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING									Component ATA:72
PN:3112368-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY									Component ATA:72
PN:3078183-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PKAAA515523	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY									Component ATA:72
PN:3078183-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PKAAA490510	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT									Component ATA:72
PN:3072279-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:RWA07E507	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT									Component ATA:72
PN:3072279-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:RWA07E508	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING									Component ATA:72
PN:3072235-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:FAA1301671	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING									Component ATA:72
PN:3072235-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FAA1301673	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING									Component ATA:72
PN:3052605-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:FAA1305087	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING									Component ATA:72
PN:3052605-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:FAA1305082	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING									Component ATA:72
PN:3052550-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:BB0168993	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726120	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING									Component ATA:72
PN:3052550-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:BB0169002	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3072282-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:PKAAA496491	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT									Component ATA:72
PN:3072282-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:PKAAA496492	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY									Component ATA:72
PN:3075013-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:KYAA011A983	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY									Component ATA:72
PN:3075013-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:KYAA011A986	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY									Component ATA:72
PN:3074835-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:KYAA011A963	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-70-01										
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY									Component ATA:72
PN:3074835-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:KYAA011A965	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 72-70-01										
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR									Component ATA:72
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR									Component ATA:72
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 73 - ENGINE FUEL AND CONTROL										
72-00-00-280-819 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1
72-00-00-280-819 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 72-00-00										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES									Service ATA:73
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES									Service ATA:73
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES									Service ATA:73
	MOS									
	HRS									
	ENC	EFF	9900		(9900) 9900 *		8541			
PROC. REF: MM 73-10-04										
73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES									Service ATA:73
	MOS									
	HRS									
	ENC	EFF	9900		(9900) 9900 *		8541			
PROC. REF: MM 73-10-04										
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT									Service ATA:73
	MOS	19-Aug-22	12 (+30d)		19-Aug-23	18-Sep-23	122 d (+30)			
	HRS	2308.8								
	ENC	1307								
PROC. REF: MM 73-10-05										
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT									Service ATA:73
	MOS	19-Aug-22	12 (+30d)		19-Aug-23	18-Sep-23	122 d (+30)			
	HRS	2308.8								
	ENC	1307								
PROC. REF: MM 73-10-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER									Service ATA:73
PN:3052624-01	MOS	25-Jan-22								
SN:UNKNOWN	HRS	2121.9	800 (+10%)	Adj -.4	(2921.5) 2921.5	3001.5	525.1 (+80)			
	ENC	1220								
PROC. REF: MM 73-10-05, MM 73-10-05										
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER									Service ATA:73
PN:3052624-01	MOS	25-Jan-22								
SN:UNKNOWN	HRS	2121.9	800 (+10%)	Adj -.4	(2921.5) 2921.5	3001.5	525.1 (+80)			
	ENC	1220								
PROC. REF: MM 73-10-05, MM 73-10-05										
73-10-07-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-10-07										PKG:1
73-10-07-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-10-07										PKG:1
73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT									Service ATA:73
PN:3071682-05	MOS									
SN:F80275	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 73-20-01										
73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT									Service ATA:73
PN:3071682-05	MOS									
SN:F80260	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 73-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-20-02-212-801 ^S		NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS								Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-20-02										PKG:1
73-20-02-212-801 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS								Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-20-02										PKG:1
73-20-10-212-801		NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS								Service ATA:73
PN:3073237-05	MOS									
SN:ADXBA000843	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-20-10-212-801		NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS								Service ATA:73
PN:3073237-05	MOS									
SN:ADXBA000839	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-20-20-212-801		NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES								Service ATA:73
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-20-20-212-801		NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES								Service ATA:73
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH									Service ATA:73
	MOS									
	HRS		5000 (+100)		(5000) 5000 (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH									Service ATA:73
	MOS									
	HRS		5000 (+100)		(5000) 5000 (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
73-21-01	LEFT FADEC									Component ATA:73
PN:3073593-08	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2013040023	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-21-01, AMM 73-21-01										
73-21-01	RIGHT FADEC									Component ATA:73
PN:3073593-08	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:2013060010	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 73-21-01, AMM 73-21-01										
73-30-02-212-801 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-30-02										PKG:1
73-30-02-212-801 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR									Service ATA:73
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 73-30-02										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER									Component ATA:73
PN:8TJ300AAB2	MOS/MSC	26-Dec-16	O/C	TSN 37						
SN:31130	HRS	872		TSN 872						
	AFL	436		TSN 436						
PROC. REF: AMM 73-33-01, AMM 73-33-01										
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER									Component ATA:73
PN:8TJ300AAB2	MOS/MSC	26-Dec-16	O/C	TSN 37						
SN:31132	HRS	872		TSN 872						
	AFL	436		TSN 436						
PROC. REF: AMM 73-33-01, AMM 73-33-01										
731002	NO. 1 ENGINE - FLOW DIVIDER									Component ATA:73
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731002	NO. 2 ENGINE - FLOW DIVIDER									Component ATA:73
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731005	NO. 1 ENGINE - FUEL FILTER									Component ATA:73
PN:3052624-01	MOS/MSC	25-Jan-22	O/C	TSN 6						
SN:UNKNOWN	HRS	2121.9		TSN 0						
	ENC	1220		TSN 0						
PROC. REF: MM 73-10-05										
731005	NO. 2 ENGINE - FUEL FILTER									Component ATA:73
PN:3052624-01	MOS/MSC	25-Jan-22	O/C	TSN 6						
SN:UNKNOWN	HRS	2121.9		TSN 0						
	ENC	1220		TSN 0						
PROC. REF: MM 73-10-05										
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19375	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19392	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19394	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19376	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19378	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19379	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19380	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19381	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19382	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19384	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:DEAAA19386	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19313	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19393	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19395	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19377	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19383	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19385	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19387	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19388	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19389	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19390	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY									Component ATA:73
PN:3057135-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:DEAAA19391	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT									Component ATA:73
PN:3073593-08	MOS/MSC	05-Aug-13	O/C	TSN 0						
SN:2013040023	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-03, MM 73-20-03										
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT									Component ATA:73
PN:3073593-08	MOS/MSC	05-Aug-13	O/C	TSN 0						
SN:2013060010	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-03, MM 73-20-03										
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU)									Component ATA:73
PN:3071682-05	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:F80275	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-01, MM 73-20-01										
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU)									Component ATA:73
PN:3071682-05	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:F80260	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-01, MM 73-20-01										
732005	NO. 1 ENGINE - N2 SPEED SENSOR									Component ATA:73
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732005	NO. 2 ENGINE - N2 SPEED SENSOR									Component ATA:73
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732006	NO. 1 ENGINE - N1 SPEED SENSOR									Component ATA:73
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732006	NO. 2 ENGINE - N1 SPEED SENSOR									Component ATA:73
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS									Component ATA:73
PN:3073237-05	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:ADXBA000843	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02										
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS									Component ATA:73
PN:3073237-05	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:ADXBA000839	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02										
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH									Component ATA:73
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH									Component ATA:73
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE									Component ATA:73
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07										
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE									Component ATA:73
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
733001	NO. 1 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR									Component ATA:73
PN:3073602-01	MOS/MSC	26-Dec-16	O/C	TSN 41						
SN:UNKNOWN	HRS	872		TSN 872						
	ENC	460		TSN 460						
PROC. REF: MM 73-30-02, MM 73-30-02										
733001	NO. 2 ENGINE - FUEL PRESSURE TRANSDUCER/SENSOR									Component ATA:73
PN:3073602-01	MOS/MSC	26-Dec-16	O/C	TSN 41						
SN:UNKNOWN	HRS	872		TSN 872						
	ENC	460		TSN 460						
PROC. REF: MM 73-30-02, MM 73-30-02										
ATA 74 - IGNITION										
74-00-01-750-801 ^S	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM									Service ATA:74
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-00-01										PKG:1
74-00-01-750-801 ^S	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM									Service ATA:74
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-00-01										PKG:1
74-10-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER									Service ATA:74
PN:31J2807-07	MOS	19-Aug-22	12 (+30d)							
SN:NNA13240229	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-10-01										PKG:1
74-10-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER									Service ATA:74
PN:31J2807-07	MOS	19-Aug-22	12 (+30d)							
SN:NNA13270141	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-10-01										PKG:1
74-20-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES									Service ATA:74
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-01										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
74-20-01-212-801 ^S		NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES							Service	ATA:74
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-01										PKG:1
74-20-02-210-801 ^S		NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR							Service	ATA:74
PN:3070508-01	MOS	19-Aug-22	12 (+30d)							
SN:N/A	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-02										PKG:1
74-20-02-210-801 ^S		NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR							Service	ATA:74
PN:3070508-01	MOS	19-Aug-22	12 (+30d)							
SN:NNA1810019	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-02										PKG:1
74-20-02-210-801 ^S		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR							Service	ATA:74
PN:3070508-01	MOS	19-Aug-22	12 (+30d)							
SN:NNA18180049	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-02										PKG:1
74-20-02-210-801 ^S		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR							Service	ATA:74
PN:3070508-01	MOS	19-Aug-22	12 (+30d)							
SN:NNA18180037	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 74-20-02										PKG:1
74-20-02-960-801		NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER							Service	ATA:74
PN:3070508-01	MOS/MSC	27-Aug-21	O/C							
SN:N/A	HRS	1988.6								
	ENC	1181								
PROC. REF: MM 74-20-02, MM 74-20-02										
74-20-02-960-801		NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER							Service	ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C							
SN:NNA1810019	HRS	1321.5								
	ENC	697								
PROC. REF: MM 74-20-02, MM 74-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
74-20-02-960-801		NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER								Service ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C							
SN:NNA18180049	HRS	1321.5								
	ENC	697								
PROC. REF: MM 74-20-02, MM 74-20-02										
74-20-02-960-801		NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER								Service ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C							
SN:NNA18180037	HRS	1321.5								
	ENC	697								
PROC. REF: MM 74-20-02, MM 74-20-02										
741001		NO. 1 ENGINE - EXCITER IGNITION								Component ATA:74
PN:31J2807-07	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:NNA13240229	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 74-10-01, MM 74-10-01										
741001		NO. 2 ENGINE - EXCITER IGNITION								Component ATA:74
PN:31J2807-07	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:NNA13270141	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 74-10-01, MM 74-10-01										
742000		NO. 1 ENGINE - 5 O'CLOCK IGNITER								Component ATA:74
PN:3070508-01	MOS/MSC	27-Aug-21	O/C	TSN 2						
SN:N/A	HRS	1988.6		TSN 0						
	ENC	1181		TSN 0						
PROC. REF: MM 74-20-02, MM 74-20-02										
742000		NO. 2 ENGINE - 5 O'CLOCK IGNITER								Component ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C	TSN 0						
SN:NNA18180049	HRS	1321.5		TSN 0						
	ENC	697		TSN 0						
PROC. REF: MM 74-20-02, MM 74-20-02										
742001		NO. 1 ENGINE - 7 O'CLOCK IGNITER								Component ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C	TSN 0						
SN:NNA1810019	HRS	1321.5		TSN 0						
	ENC	697		TSN 0						
PROC. REF: MM 74-20-02, MM 74-20-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER									Component ATA:74
PN:3070508-01	MOS/MSC	20-Aug-18	O/C	TSN 0						
SN:NNA18180037	HRS	1321.5		TSN 0						
	ENC	697		TSN 0						
PROC. REF: MM 74-20-02, MM 74-20-02										
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD									Component ATA:74
PN:3127408-02	MOS/MSC	15-Sep-16	O/C	TSN 0						
SN:NNA16280037	HRS	793.5		TSN 0						
	ENC			TSN 0						
PROC. REF: MM 74-20-01, MM 74-20-01										
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD									Component ATA:74
PN:3127408-01	MOS/MSC	15-Sep-16	O/C	TSN 0						
SN:NNA16300313	HRS	793.5		TSN 0						
	ENC			TSN 0						
PROC. REF: MM 74-20-01, MM 74-20-01										
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD									Component ATA:74
PN:3127408-01	MOS/MSC	15-Sep-16	O/C	TSN 0						
SN:NNA16300314	HRS	793.5		TSN 0						
	ENC			TSN 0						
PROC. REF: MM 74-20-01, MM 74-20-01										
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD									Component ATA:74
PN:3127408-02	MOS/MSC	15-Sep-16	O/C	TSN 0						
SN:NNA16280036	HRS	793.5		TSN 0						
	ENC			TSN 0						
PROC. REF: MM 74-20-01, MM 74-20-01										
ATA 75 - AIR										
75-30-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE									Service ATA:75
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 75-30-01										PKG:1
75-30-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE									Service ATA:75
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 75-30-01										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR									Service ATA:75
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 75-30-01										
75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR									Service ATA:75
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 75-30-01										
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE									Service ATA:75
PN:3053367-01	MOS									
SN:AHX0500205	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE									Service ATA:75
PN:3053367-01	MOS									
SN:AHX0500202	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE									Component ATA:75
PN:3075987-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:TR6663	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE									Component ATA:75
PN:3075987-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:TR6665	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01, MM 75-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER									Component ATA:75
PN:3071811-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:1627	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER									Component ATA:75
PN:3071811-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:1612	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-960-801	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES									Service ATA:75
	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-960-801	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES									Service ATA:75
	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-960-802	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE									Service ATA:75
PN:3075987-01	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
SN:TR6663	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01										
75-30-01-960-802	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE									Service ATA:75
PN:3075987-01	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
SN:TR6665	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-30-01-960-803		NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service	ATA:75
PN:3071811-01	MOS/MSC	26-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
SN:1627	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01										
75-30-01-960-803		NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service	ATA:75
PN:3071811-01	MOS/MSC	28-Jul-13	A/R					UNSCHEDULED MAINTENANCE CHECK		
SN:1612	HRS	0								
	ENC	0								
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01										
75-30-02-212-801		NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service	ATA:75
PN:3071811-01	MOS									
SN:1627	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
75-30-02-212-801		NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service	ATA:75
PN:3071811-01	MOS									
SN:1612	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
75-30-20-212-801		NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR							Service	ATA:75
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-30-20-212-801		NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR								Service ATA:75
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
750010		NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR								Component ATA:75
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-00-00										
750010		NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR								Component ATA:75
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-00-00										
753002		NO. 1 ENGINE - SERVO COMPUTER								Component ATA:75
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
753002		NO. 2 ENGINE - SERVO COMPUTER								Component ATA:75
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
753010		NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY								Component ATA:75
PN:3053367-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:AHX0500205	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01										
753010		NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY								Component ATA:75
PN:3053367-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:AHX0500202	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 75-30-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
753020	NO. 1 ENGINE - BOV TORQUE MOTOR									Component ATA:75
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
753020	NO. 2 ENGINE - BOV TORQUE MOTOR									Component ATA:75
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
ATA 76 - ENGINE CONTROLS										
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY									Component ATA:76
PN:6990010-11	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:1436	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 76-11-01, AMM 76-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM									Service ATA:77
	MOS	19-Aug-22	36 (+30d)	Adj -29d	21-Jul-25	20-Aug-25	824 d (+30)			
	HRS	2308.8	1600 (+100)		(3908.8) 3908.8	4008.8	1512.4 (+100)			
	ENC	1307								
PROC. REF: MM 77-20-02										
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM									Service ATA:77
	MOS	19-Aug-22	36 (+30d)	Adj -29d	21-Jul-25	20-Aug-25	824 d (+30)			
	HRS	2308.8	1600 (+100)		(3908.8) 3908.8	4008.8	1512.4 (+100)			
	ENC	1307								
PROC. REF: MM 77-20-02										
77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT									Service ATA:77
PN:3075878-01	MOS									
SN:13-667	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT									Service ATA:77
PN:3075878-01	MOS									
SN:13-010433	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
774001	NO. 1 ENGINE - DATA COLLECTION UNIT									Component ATA:77
PN:3075878-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:13-667	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-40-01, MM 77-40-01										
774001	NO. 2 ENGINE - DATA COLLECTION UNIT									Component ATA:77
PN:3075878-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:13-010433	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 77-40-01, MM 77-40-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)									Service ATA:79
PN:3052640-01	MOS									
SN:07953406	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)									Service ATA:79
PN:3052640-01	MOS									
SN:07937322	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER									Service ATA:79
	MOS	25-Jan-22								
	HRS	2121.9	5000 (+100)		(7121.9) 7121.9	7221.9	4725.5 (+100)			
	ENC	1220								
PROC. REF: MM 79-20-01										
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER									Service ATA:79
	MOS	25-Jan-22								
	HRS	2121.9	5000 (+100)		(7121.9) 7121.9	7221.9	4725.5 (+100)			
	ENC	1220								
PROC. REF: MM 79-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-20-01-960-801	NO. 1 ENGINE - DISCARD THE OIL FILTER									Service ATA:79
PN:3052590-01	MOS	25-Jan-22						DISCARD		
SN:NSN	HRS	2121.9	800 (+10%)		(2921.9) 2921.9	3001.9	525.5 (+80)			
	ENC	1220								
PROC. REF: MM 79-20-01, MM 79-20-01										
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER									Service ATA:79
PN:3052590-01	MOS	25-Jan-22						DISCARD		
SN:NSN	HRS	2121.9	800 (+10%)		(2921.9) 2921.9	3001.9	525.5 (+80)			
	ENC	1220								
PROC. REF: MM 79-20-01, MM 79-20-01										
79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP DETECTOR									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 79-30-01										
79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP DETECTOR									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: MM 79-30-01										
79-30-01-770-801 ^S	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR									Service ATA:79
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 79-30-01										PKG:1
79-30-01-770-801 ^S	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR									Service ATA:79
	MOS	19-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 79-30-01										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-30-02-210-801 ^S	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH									Service ATA:79
	MOS	21-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 79-30-02										PKG:1
79-30-02-210-801 ^S	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH									Service ATA:79
	MOS	21-Aug-22	12 (+30d)							
	HRS	2308.8	800 (+10%)							
	ENC	1307								
PROC. REF: MM 79-30-02										PKG:1
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS)									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										
79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS)									Service ATA:79
	MOS									
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	2603.6 (+100)			
	ENC									
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR									Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00371	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-31-05, AMM 79-31-05										
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR									Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	01-Aug-13	O/C	TSN 0						
SN:00372	HRS	0		TSN 0						
	AFL	0		TSN 0						
PROC. REF: AMM 79-31-05, AMM 79-31-05										
790000	NO. 1 ENGINE - OIL FILTER									Component ATA:79
PN:3052590-01	MOS/MSC	25-Jan-22	O/C	TSN 0						
SN:NSN	HRS	2121.9		TSN 0						
	ENC	1220		TSN 0						
PROC. REF: MM 79-20-01, MM 79-20-01										
790000	NO. 2 ENGINE - OIL FILTER									Component ATA:79
PN:3052590-01	MOS/MSC	25-Jan-22	O/C	TSN 0						
SN:NSN	HRS	2121.9		TSN 0						
	ENC	1220		TSN 0						
PROC. REF: MM 79-20-01, MM 79-20-01										
790020	NO. 1 ENGINE - CHANGE OIL									Service ATA:79
	MOS/MSC	26-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00, MM 72-00-00										
790020	NO. 2 ENGINE - CHANGE OIL									Service ATA:79
	MOS/MSC	28-Jul-13	A/R							
	HRS	0								
	ENC	0								
PROC. REF: MM 72-00-00, MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792010	NO. 1 ENGINE - TEMPERATURE SENSOR									Component ATA:79
PN:ATS-9-800	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:020612-1	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
792010	NO. 2 ENGINE - TEMPERATURE SENSOR									Component ATA:79
PN:ATS-9-800	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:020612-5	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER									Component ATA:79
PN:3052640-01	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:07953406	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-02, MM 73-10-02										
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER									Component ATA:79
PN:3052640-01	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:07937322	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-02, MM 73-10-02										
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR									Component ATA:79
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR									Component ATA:79
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793020	NO. 1 ENGINE - OIL TANK FILLER CAP									Component ATA:79
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500167 RegNo: N16DF HRS: 2396.4 AFL: 1359 As Of: 28-Dec-2022

19-Apr-2023 12:23 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793020	NO. 2 ENGINE - OIL TANK FILLER CAP									Component ATA:79
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)									Component ATA:79
PN:PN	MOS/MSC	26-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)									Component ATA:79
PN:PN	MOS/MSC	28-Jul-13	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task