

N 7086 W

Pacific Continental Engines Inc.

O-360-A3A

S/N L-6066-36

OVERHAULED 9-7-02 @ 1546.1 TACH.

VAN NUYS, CALIF. 91406

CERTIFIED STATION 4595

N 7086 W

ENGINE LOG BOOK

DATE	1/25/2023 N180LR Tach hours: 1895.1 ESMOH: 1895.1 ETT: 5140.1			
BRT.	- Changed oil and filter. Serviced with 6 quarts of XC20W-50 and AA48110-2 filter.			
FWD.	- Cylinder compression test (leakage) values: #1 78, #2 79, #3 60, #4 79 / 80			
	- Cleaned and tested spark plugs. Reinstalled and torqued with new gaskets.			
	- Replaced engine control mounting clamps.			
	- Replaced loose alternator mounting hardware with correct hardware.			
	- Replaced valve cover gasket on #2 cylinder.			
	- Replaced oil drain valve P/N CCB-37000.			
	- Removed engine driven fuel pump to repair broken cooling shroud. Shroud was repaired by welding. Fuel pump was reinstalled with new gasket.			
	- Replaced damaged RH mag leads with used set.			
	- Resurfaced cylinder exhaust flange on cylinder #3. Reinstalled aft exhaust with new exhaust gaskets.			
	- Removed vacuum pump and replaced adapter oil seal P/N 06A19956. Reinstalled vacuum pump with new gaskets.			
	- Removed both mags. Opened up and inspected. Replaced breaker points on RH mag with like-new set P/N TCM-0202. Set E-gap and reinstalled with new gaskets. Magnetos timed to engine at 25* BTDC.			
	- Replaced all rubber engine mounts P/N J-7402-24.			
	- Verified AD 98-02-08 Crankshaft failure not applicable to this engine by verifying PID stamped on crankshaft flange. No further action required.			
	- Performed ANNUAL INSPECTION and 100 hour INSPECTION of engine as defined by 14 CFR appendix D to part 43. Engine found to be airworthy at this time.			
	Justin T. Dix A&P 3347687 IA <i>Justin T. Dix</i>			
	:	:	:	
	:	:	:	
	:	:	:	
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

SECTION REFERENCE DATA

DATE	02/05/2023 N180LR Tach hours: 1911.3 Hobbs: 5225.8	
	- Flew aircraft from GSO to W78 and found that there was an intermittent variation in power of engine. All gauges normal, mag check normal, starting normal	
	- Upon investigation, found #2 cylinder to be missing one exhaust nut and the exhaust pipe flange to be slightly away from the cylinder - Replaced exhaust gaskets on #1 and #2 cylinders with new 77611 gaskets, replaced missing nut and installed new washers on #1 and #2 cylinder exhaust studs.	
	- Test ran engine and had very rough transition up to run up RPM and low EGT indication on #2 cylinder.	
	- Removed valve cover on #2 cylinder and found the valve spring on the intake valve to be broken. Installed serviceable valve spring and reassembled	
	- Installed new EGT probe on #2 cylinder PN 10-00830	
	- Performed test flight and returned plane to KGSO	
	Justin T. Dix A&P 3347687 IA <i>Justin T. Dix</i>	
	3/10/2023 N180LR Tach hours: 1994.7 ESMOH: 1994.7 ETT: 5239.7	
	- Changed oil and filter. Serviced with 7 quarts of XC20W-50 and AA48110-2 filter.	
	- Cylinder compression test (leakage) values: #1 75, #2 64, #3 63, #4 75/80	
	- Cleaned and tested spark plugs. Replaced three spark plugs with new UREM38E. Reinstalled and torqued with new gaskets.	
	- Removed #3 cylinder due to unservicable exhaust flange. Installed repaired Lycoming cylinder from Triad Aviation, P/N LW12425. Installed with new gasket set. Work was performed in reference to Lycoming Service Manual.	
	- Replaced #1 and #3 cylinder intake hose P/N 69603. Replaced #1 and #3 oil drainback tubing P/N STD1821.	
	- Replaced carb heat cable with new P/N MC63902-002.	
	- Replaced lower carb heat shroud P/N A63723-002.	
	- Performed ANNUAL INSPECTION and 100 hour INSPECTION of engine and propeller as defined by 14 CFR appendix D to part 43.	
	Engine and propeller found to be airworthy at this time.	
	Kenton Good A&P 3701376 IA <i>Kenton Good</i>	

Sept 1-2022

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	Tac: 1677.4	4942.2		Annual inspection using IAW Far part 43 Appx-D: inspection Form. Ckd oil filter & oil lts		
	ckd gasolator: per STC	SA 010226 SE		AP 98-02-08 inspected		
	Crankshaft Corrosion Due	- Sept 1-2027. Normal				
	Compression @ 70% @ 70% @ 70% @ 70%			Ckd Muffler CK Magnifying 25		
BTC.	Engine washed Down & Ran	- No Leaks -				
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:			

DATE 9-1-2022 T.T. IN SERVICE 4942.2

CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH FAR PART 43 AND DETERMINED TO BE IN AIRWORTHY CONDITION.

Ronald P. Hubert IA
20761

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DAT

11/04/2022 N180LR TACH: 1796.4 Hobbs: 5086.4

- Serviced spark plugs and installed new gaskets P/N 07-01798
- Changed oil and filter. Serviced with XC-20W50 7 quarts and AA48110-2 filter
- Replaced 07-03061 72059 Lycoming oil level gage gasket.
- Removed cowl, propeller, exhaust, starter, carburetor and oil sump. Replaced LW-13353 Lycoming Oil Sump Gasket.
- Reinstalled oil sump, carburetor, starter, exhaust system, propeller, cowl and test ran engine
- Performed 100 hour INSPECTION of engine and propeller as defined by 14 CFR appendix D to part 43. Engine and propeller found to be airworthy at this time.

Justin T. Dix A&P 3347687 IA *Justin T. Dix* 336-514-2724

1/25/2023 N180LR Tach hours: 1895.1 PSMOH: 1576.5

- Performed ANNUAL INSPECTION and 100 hour INSPECTION of propeller as defined by 14 CFR appendix D to part 43.

Propeller found to be airworthy at this time.

Justin T. Dix A&P 3347687 IA *Justin T. Dix*

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
2016						
BRT. FWD.	:	:	:			
T.T	4932.6	:	:	Drain Oil. Removed Filter Replaced		
TAC	1687.8	:	:	Zats Philips 20/50wt Re Place oil filter		
	:	:	:	Champion CH48110-1. Clean gasculator Per		
	:	:	:	STC. SA01026SE. Wash Engine down		
	:	:	:	Compression OK ① 17/80 ② 14/80 ③ 74/80 475/80		
	:	:	:	OK Standby Vacuum Per manufacture spec.		
	:	:	:	Cleaned 1 gap + Rotated Plugs		
	:	:	:	① AD 98-02-08 Crankshaft Corrosion		
	:	:	:	② AD 99-24-10 Vacuum pump Normal		
	:	:	:	DATE 11-15-2016		
	:	:	:	I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED	4932	
	:	:	:	IN ACCORDANCE WITH A 100hr INSPECTION AND		
	:	:	:	AS DET. MINED BY		
TOTALS	:	:	:	Ronald R. - [Signature]	2076281 ADP	
All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.						

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
	① AD 98 02 08 CW CRANK NORMAL
	②
	This is to certify that this Aircraft and Powerplant and Propeller have been inspected in accordance with a annual inspection and was found airworthy. Tac 1687.8 Total Time
	Aircraft 4932.6 Ad Check 1620 TT Eng 4932.6 TT Prop 611
	Time since eng owl 1687.8 Time Since Prop owl 1369.2
	Franklin C. Wilson IA 1589043 Irondale, Ohio 43932 330-532-2819
	Franklin C. Wilson 15 Nov 2016

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:	This is to certify that this Aircraft and Powerplant and Propeller have been inspected in accordance with a annual inspection and was found airworthy. Fac <u>1548.8</u> Total Time		
:	:	:	:	Aircraft <u>47938</u> Ad Check <u>14-17</u> TT Eng <u>4793.8</u> TT Prop <u>UNK</u>		
:	:	:	:	Time since eng ovl <u>1548.8</u> Time Since Prop ovl <u>1230.2</u>		
:	:	:	:	Franklin C. Wilson-IA 1589043 Irondale, Ohio 43932	390-532-2819	
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE 2015	Hobbs 4865.3	Tac 1606.4	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
9-18	100h inspection Compression CK ① $\frac{72}{80}$ ② $\frac{71}{80}$ ③ $\frac{74}{80}$ ④ $\frac{75}{80}$ Changed oil 6qt Philip ^{2015PWT} Filter. Cleaned fuel Pump + gasolator tank Saftey - washed engine down - CK mag timing - Engine Test Ran no Locks - CK Standby Vacuum - Per manufacture Spec. AD 76-07-12 - Test per Ad. AD 98-02-08 Crankshaft inspection Due 2016, AD 2005-12-06 - Impluso Coupling Due - Tax time 1726 - AD 99-24-10 - Standby VAC. CK AD 70-16-05 Muffler Normal. CK AD 95-26-13 CK Reflase Tax time 5365 Tac.		
DATE 10-2-2015	T.T. IN SERVICE 4865.3	I CERTIFY THAT THIS <u>Engine</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>100h</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. Aronold R. L. L. 2076281	
DATE 10-2-2015	T.T. IN SERVICE 4856.3	I CERTIFY THAT THIS <u>Engine</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. C. J. R. 178600/HZ	

TT 4791.3 Engoverland 1548.8

DATE TAC 1548.8 Engine TT 4791.3 MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

2014 Aug 16 - 100 hr inspection - Compression Test ① 74/40 ② 75/40 ③ 74/80 ④ 74/80
 Replaced Primer (FLEX) Clean & Rotated Plugs, Wash Engine Down. install
 New gasolator PLAC) Leak ok. Tighten Rubber intake tube
 CK mag timing Engine Test Ran & is in Satisfactory condition

AD-98-02-08 Crankshaft imp. Due 2016.

AD-99-24-10 Inspected. Standby VAC.

AD 96-12-07 Superseded by 2005-12-06. Impluse Coupling Due at TAC →
 Time 1726) mag switch Test Per AD 76-07-12

Ronald R. Burke

DATE 5/10/14 T.T. IN SERVICE 4791.3
 I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED
 IN ACCORDANCE WITH A 100 hr INSPECTION AND
 HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE Sept 1 2014 T.T. IN SERVICE 4791.3
 I CERTIFY THAT THIS Engine HAS BEEN INSPECTED
 IN ACCORDANCE WITH A 100 hr INSPECTION AND
 WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

~~6-29-2014 F~~

1.1 (6-29-2014)

TACK Time - 1547.75

HOBBS - 4801.1

DRAINED OIL

RePLACed with Phillips 20W50 6 Qnts

Replaced Filter Tempest AA48110-2

ground RAN engine No LEAK Found

END

A+R 2076281 Ronald R. Kukulak

TTeng 4755.9

DATE

Joe 1513.9

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

2013 Found No 4 cylinder Crack. Replaced with Millennium
 Sept 18 cylinder SL36006N-A20 366N-H13-4258 Kit contains
 New Parallel Cylinder. head, barrel, valves, valve seats,
 Valve Guides, Piston, rings & gasket kit. (Superior Air Parts)
 Installed a Tongue Per Lycoming &
 Put 7 qts 80wt Non detergent Oil - Ground Run
 for 10 min 1000 RPM - 10 min 1200 RPM - 10 min 1500 RPM -
 next 1600 RPM ck mag. & for Oil Leaks - No Leaks -
 Installed ^{using} Superior air parts - Overhaul Manual O-360 Series & Lycoming
 overhaul Manual - End

Oct 20 2013 Installed New Carb Heat seat hose
 Ronald R Nickels ATP 2076281

THIS AIRCRAFT HAS BEEN INSPECTED
 IN ACCORDANCE WITH A
 NOTIFICATION TO BE IN AIRWORTHY CONDITION.

Page 1

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
5/25/2011	:	:	:			
THCH	:	:	:			
4612.10	:	:	:			
Annual Inspection 1370.4 TS MOH 3907.8 ITEN changed Oil and Filter. Filled with Phillips 50W-50 HC. Cleaned and gapped spark plugs Comp #1 68/80, #2 69/80 #3 61/80, #4 60/80. Cleaned Injection Straps. C/W AD 1005- 12-06 bench impulse coupling by Inspector. No Defects Noted Due in 500 hours. Installed New Distributor Gear in Left Magneto. C/W AD 98-02-08 Cracks left Inspector by Due Perpetrant Inspection. No Defects Noted. Due in 5 years or Next Annual Inspection. AD 2047 21/12 by Head Cracks Does not apply due to No FCI Cylinders Assemblies Installed. C/W AD 99-24-10 Engine Flight						
TOTALS	:	:	:			

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

(cont.)

Page 2

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5/25/2011	4612.0 TAF Stanley Vacuum by inspection of Shuttle Valves Control Cable, and Saddle Fitting. No Defects Noted. Due next annual. I certify that this Engine has been inspected in accordance with an Annual Inspection and found to be Airworthy at this time. Richard C. Phil FA 3453613

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD. 10/1/09						
TACH READS 4434 hrs. Perform 100 hr. inspection. Compressor test: 1-45/80, 2-42/80, 3-48/80, 4-40/80. CHANGE OIL, FILTER, CLEAN SUCTION SCREEN, ADD PHILLIPS 20W-50 XC OIL. CLEAN & GAP SPARK PLUGS, REMOVE MAGNETS, RESET 'E' GAP AND CONTACT POINTS TO SPECIFICATIONS. REINSTALL MAGS WITH NEW CASKETS & TIME TO 75° BTDC. CLEAN FUEL SCREENS, DRAIN CARBURETOR & FLOW BOWL. REPLACE ALTERNATOR BELT AND INNOVATION AIR FILTER ELEMENT. INSTALL NEW RH EXHAUST CLAMP ON RH COLLECTOR PH 43735-00. TEST GROUND ROLL UP SATISFACTORY - END.						
				I certify that this ENGINE has been inspected		
				In accordance with 100 hr. inspection and		
				was determined to be in airworthy condition.		
				Date 10/1/09 W.O. #		
				Total Time 192.4 5 MOD		
				Signed [Signature] AR-220723		
TOTALS				All repairs, inspections, and alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS	
5-7-2010	TACH READS 4537 hrs. Perform 100 hour inspection. Drain oil, inspect distributor. Add Phillips 20W-50. Compressor test: 1-42/80, 2-44/80, 3-42/80, 4-40/80. Install new Harmon sparkplugs. Remove. Check magnet timing. Clean all fuel screens. Reval #3 rocker cover. Inspect exhaust system. Degrease engine and cowling. Ground run engine. Oh. & WD.	
	I certify that this ENGINE has been inspected	I certify that this ENGINE has been inspected
	In accordance with 100 hr. inspection and	In accordance with 100 hr. inspection and
	was determined to be in airworthy condition.	was determined to be in airworthy condition.
	Date 5-7-2010 W.O. #	Date 5-7-2010 W.O. #
	Total Time 4537	Total Time 129.5 5 MOD
	Signed [Signature]	Signed [Signature]
	A&P [Signature]	A&P [Signature]

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD. 4/30/2009				Jack reads 4332 perform 100 hr inspection IAW Farport		
43 appendix				compression test #1 70/80 #2 28/80 #3 72/80 #4 69/80 Replace #		
2 cylinder with Gibson aviation overhauled steel cylinder assigned travel #				61125 08-6 assembly includes serviceable piston pin, new ring seals and		
gaskets Drain oil and Replace filter, clean oil suction screen cut				oil filter and inspected for metal (none found) add Phillips 20W50 Type		
M for break-in: clean and gap spark plugs check mag timing, timing at 25°				clean fuel strainer and drain float bowl, Wash engine & ground run		
satisfactory. - End.						
I certify that this engine has been inspected						
In accordance with FAR Inspection and						
was determined to be in airworthy condition.						
Date 7/30/2009 W.O. #						
Total Time 1090.4						
Signed Joseph Reid						
A&P 3112998						
TOTALS						

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
7/14/2009	Jack reads 4363 C/W AD 95-26-13 Replaced oil cooler hoses with part # 124F001-8CR0460 Type (D) hoses from Precision Hose Technology, AD 95-26-13 next due on 7/14/2019 or at 5363 tach time (whichever occurs first). End
	Joseph Reid A&P 3112998
7/14/2009	Jack reads 4363 drained oil and added 8 qts of Phillips 20/50 XC cut oil filter and inspected for metal contamination (none found) ground run engine and noted no leaks.
	Joseph Reid A&P 3112998

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
11/07/2008				Performed: 100 hr inspection IAW Far part 43 appendix "D" Compression test: #1 ⁷¹ / ₈₀ #2 ⁷² / ₈₀ #3 ⁶⁸ / ₈₀ #4 ⁷⁸ / ₈₀ . Change oil and filter add Phillips xC 20W50 clean oil suction screen. Clean and gap spark plugs Replace points on left mag. Installed service capacitor. Checked point gap and laded cam on right mag. Set ignition timing at 25° B.T.C. Clean fuel screens and drain carb float bowl. Replaced exhaust clamp L/H side on muffler. Washed engine ground run satisfactory. End		
				In accordance with 100 hr inspection and was determined to be in airworthy condition.		
				Date 11/07/2008 W.O. #		
				Total Time 966.45 M.O.H		
				Signed Joseph Reid		
				A&P 3112998		
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
3/4/2009	Tach reads 4279 hrs Drained oil and replaced oil filter add Phillips xC 20W50 Cut and inspected oil filter for metal (none found) Ground ran engine and inspected for leaks. (None found). End Joseph L Reid a&P 3112998
4/4/09	TACH READS 4310 HRS. REMOVE AND REPLACE #3 CYLINDER ASSY WITH O'HAILED UNIT FROM GIBSON AVIATION CR3 AV2R704K. ASSY INCLUDES STEEL CYLINDER ASSY, SERVICEABLE PISTON, NEW RINGS, SEALS, GASSETS, PISTON PIN PLUGS, SERVICEABLE PISTON PIN. PHILLIPS 20W-50 TYPE IN OIL INSTALLED FOR BREAK-IN. POST MAINTENANCE RUN UP CHECK OK - END Curtis Smith AP-2220423

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
8/17						
STICK ON ENTRY REMOVED AND INSTALLED ON PROPER PAGE THIS DATE STICK ON ENTRY TO THIS PAGE MADE IN ERROR DATED 8-17-04 FOR CORRECT ENTRY Dink Run P4P15175001D						
TOTALS	:	:	:			

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
4/1/08	TACH READS 4005 HRS. PERFORM 100hr INSPECTION IN ACCORDANCE WITH APPENDIX D OF PART 43. COMPRESSION TEST 1-74/80, 2-78/80, 3-76/80, 4-76/80. CHANGE OIL, FILTER, ADD PHILLIPS 20W-50XC. CLEAN OIL Suction SCREEN, CLEAN CHAMP SPARK PLUGS CHECK MAGNETO TIMING. CHECK POINT GAPS LUBE POINTS. CLEAN ALL FUEL SCREENS, DRAIN CARBURETOR FLOOT BOWL. REPLACE EXHAUST STUD # 3 CYL EXHAUST PORT. INSTALL NEW EXHAUST TAIL PIPE ASSY. SILICONE LUBE STARTER BENCH. ENGINE WASHED DOWN GROUND RUN UP & BT'S FACTORY - END. I certify that this <u>ENGINE</u> has been inspected in accordance with <u>100hr</u> inspection and was determined to be in airworthy condition. Date <u>4/1/08</u> W.O. # <u> </u> Total Time <u>01.762.75</u> hours Signed <u>Chris Smith</u> A & P <u>2220413</u>

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT.	:	:	:			
FWD.	:	:	:			
1-30-01	10:00	3550	:	Drained oil, inspect filter, add		
	:	:	:	Quosnell 15W50 EVO		
	:	:	:	Ryan Smith		
	:	:	:	#445745086		
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
4-10-01	Work on 3597 Puffin 100 hour inspection. H0335.354.7 (omphom tool: #17/80 #27/80 #3.74/800 SMOH 354.7 #475/80. Drain oil, inspect filter, add Air H0335 3597 Quosnell 15W50. Clean fuel screens. Clean and app sparkplugs. Inspect muffler and flame. Retorque #3 exhaust flange fuel and right magenta. Replace indicator air filter - Retorque fuel filter at strainer assembly. I certify that this engine has been inspected In accordance with 100hr inspection and was determined to be in airworthy condition. Date 4-10-01 W.O.# Total Time 3597 Signed Ryan Smith A&P 445745086

DATE 2004	GROUND TIME	TIME	AL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
8/17/04	ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 N180LR Lycoming O-360-A3A 17 August 2004 Tach Time: 1682.4 Removed old alternator. Installed overhauled / exchange unit, P/N: 3656624, S/N: E070701. Unit installed using original hardware and new safeties. Reinstalled forward cowl and propeller. Propeller torqued to 65 ft/lb's and safetied. Ground run operational check of charging system satisfactory. END. <i>L. John Wells</i> L. John Wells A&P523116767 w/o 21060					
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:			

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
10-12-04	DRAINED ENGINE OIL AND REMOVED FILTER AND SUMP SCREEN FOR
TACH	INSPECTION. FILTER WAS CUT OPEN AND EXAMINATED FOR CONTAMINATION -
1690.01	NON FOUND. SUMP SCREEN WAS INSPECTED AND FOUND CLEAN. SCREEN WAS
	REASSEMBLED WITH NEW MS35769-21 COPPER CRUSH WASHER, TORQUED AND SAFETIED.
	INSTALLED A NEW CHAMPION CH48110-1 OIL FILTER AND TORQUED TO 17 FT LBS.
	SERVICED WITH 8 QTS Aero-shell 80 NON-DETERGENT OIL. ENGINE WAS RUN TO
	CHECK FOR OIL LEAKS AND NON SOUND. THIS INSTALLATION IS CONSIDERED
	DIAGNOSTIC AND AIRCRAFT/ENGINE IS APPROVED FOR RETURN TO SERVICE.
	RT RUN AT P 15115001A

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
12/6/03	TACH TIME: 1640:23			94.13 SMOH. DRAINED ENGINE OIL AND REMOVED OIL FILTER AND SUMP SCREEN FOR INSPECTION. CUT FILTER OPEN AND INSPECTED FOR CONTAMINATION - NON FOUND. INSPECTED SUMP SCREEN AND FOUND CLEAN. REINSTALLED WITH NEW CRANK WASHER P/N MS35769-21. INSTALLED NEW CHAMPION OIL FILTER P/N CH48110. TORQUED TO 16 FT.LBS. SERVICE ENGINE WITH 8 QTS AEROSHELL 15W50 ASHLBS DISPERGENT (DETERGENT) OIL. (THIS WAS TO REMOVE BREAKING NON DETERGENT OIL). REMOVED TACH CABLE AND INSTALLED NEW TACH CABLE DUE TO NON-USE TACH (CONNECTION PROBLEM). ENGINE STARTED RUN AND LEAK A MARK ON OIL ENGINE OIL FOR RETURN TO SERVICE. R. Russ A&P 15115001A		
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5-27-04	Tach 1661.97, 115.87 SMOH. Engine compartment was un-cowled for inspection following a flight to warm-up the engine and oil. Drained oil and removed filter and sump screen for inspection. Cut open filter and found no evidence of contamination. Same for the sump screen. Performed differential compression test on all cylinders. Results are as follows; #1-76/80, #3-77/80, #2-78/80, #4-77/80. Removed entire exhaust system for installation of a new left header due to frozen slip joint and a new muffler under warrantee(baffles loose). New Blo-Proof gaskets were installed. Installed a new Champion oil filter P/N CH48110 and torqued to 16 ft. lbs. Cleaned, gapped and installed spark plugs. Torqued to 30 ft. lbs. Serviced engine with 8 quarts of Aero-Shell 80 wt. non detergent oil. Verified timing set at 25 degrees BTDC. Installed new Bracket BA-104 inlet filter. Engine was inspected for discrepancies and none found. All AD's have been previously complied with and the only new AD is 2004-10-14, amendment 39-13644 and does not apply due to recent overhaul at which time a new crankshaft bolt and retainer was replaced. There are no other new AD's issued against this engine since the last AD list update. Existing AD list may be found in the aircraft records and is still in effect. Engine was test run and mag drop verified acceptable. This engine has been inspected in accordance with a 100 hour/Annual inspection and found to be in an airworthy condition and is approved for return to service.
	Richard T. Russ A&P 15115001A

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
10-15-02	TACH	1555.3	9.2 SMOH	DRAINED ENGINE OIL, REMOVED FILTER AND OIL SUMP SCREEN FOR EXAMINATION. FOUND NO CONTAMINATION IN THE SCREEN. CUT OPEN FILTER AND EXAMINED FOR CONTAMINATION AND NONE WAS FOUND. REINSTALLED OIL SUMP SCREEN WITH A NEW CRUSH WASHER AND INSTALLED A NEW CHAMPION OIL FILTER P/N CH48110 AND 7 QTS AEROSHELL 80 MINERAL OIL. CLEANED ENGINE AND CHECKED FOR OIL LEAKS AND FOUND NONE. THIS ENGINE IS CONSIDERED AIRWORTHY AND RETURNED TO SERVICE.		
				<i>[Signature]</i>		
				USE AD P15115001A		
TOTALS	:	:	:			
All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.						

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5-14-03	Tach 1584.73, 38.63 SMOH. Aircraft was flown for 30 minutes to heat oil and cylinders for inspection. Oil was drained and oil filter and sump screen* removed for inspection. Filter was cut open and inspected for contamination, no particles or contamination found. Checked compression on all cylinders and results are: # 1-75/80, # 3-79/80, #4-78/80, # 2-77/80. Installed new champion oil filter P/n Ch48110 and added 7 quarts Aeroshell 80 non detergent oil. Removed all spark plugs, cleaned, gapped and reinstalled. Torqued to 25 ft. lbs. Removed and replaced Brackett air Filter Element P/N BA 104. Checked ignition timing per engine spec 25 BTC. Inspected mag points and found satisfactory. Removed fuel sump, cleaned screen, and reinstalled sump bowl. Removed RH exhaust system for inspection of muffler. Found inner baffle deflector loose and unairworthy. Returned to Wall Colomoy under warrantee. Installed new Nicrocraft muffler P/N PIM 0002, Piper P/N 99482-02. Reinstalled exhaust system. A Standby Vacuum System was installed per STC. (see 337 dated 5-14-03 for details.) Engine was test run and determined to be airworthy in accordance with a 100 hour/Annual inspection and approved for return to service. THERE WERE NO NEW ADS ISSUED SINCE LAST ANNUAL AND ALL ADS HAVE BEEN COMPLIED WITH. REF AD LIST IN AIRCRAFT RECORDS.
	<i>[Signature]</i> Richard T Russ A&P 15115001A
	* COPPER GASKET P/N M335769-21

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
9-7-02; Tach Time 1546.1. Engine was removed for overhaul due to inability to find source of an oil leak. All of the engine was inspected by D & B Aircraft Engines, Inc. for wear and damage ref w/o 10721 dated 9-4-02. Engine was reassembled with a certified late model overhauled crankcase, and accessory housing. Three of the cylinders # 1, 2 & 4 were replaced with fresh overhauled chrome cylinders. # 3 had been previously replaced @ 1518 hours. All cylinders have new valve guides and new exhaust valves and keepers. All parts recommended by Lycoming service bulletin 240K (for replacement at overhaul) were replaced including new rod bolts and nuts. Camshaft and tappets were overhauled by Rock Aviation, Inc. ref. yellow tags & w/o 8351 dated 8-30-02. Engine was overhauled in accordance with Lycoming overhaul manual. Carburetor was overhauled by Mikes Aircraft Fuel Metering Service ref w/o 14483 dated 8-30-02 yellow tag. Installed a new AC fuel pump P/N 41271. Magneto's were reinstalled on engine and engine timed to 25 degrees before top dead center. Propeller was reinstalled and torqued to 65 ft. lbs. per the Piper Service Manual. For a list of all parts installed see ETA invoice # 9102002 dated 9-10-02. Engine was serviced with Aeroshell 50 straight mineral oil. Engine was test run, leak checked and found airworthy for continued service.						
<i>Richard T. Russ</i> Richard T. Russ A&P 15115001A				TACH 1546.1 O-SMOH	3243.1 WAF	
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
9/16/02	(4.5 SMOKY) TACH 1550.6 REMOVED EXISTING OIL TEMP SENDER ON REAR OF ENGINE AND INSTALLED A NEW CALIBRATED OIL TEMP SENDER. ENGINE WAS RUN AND CHECKED FOR OIL LEAKAGE. AIRCRAFT TEST FLOWN AND OIL TEMP STABILIZED @ 190°F. SENDING UNIT WAS INSTALLED WITH A NEW COPPER CRUSH WASHER AND TIGHTENED IN ACCORDANCE WITH THE LYCOMING O/H MANUAL. THIS INSTALLATION IS CONSIDERED AIRWORTHY AND AIRCRAFT APPROVED FOR RETURN TO SERVICE R.T. RUSH A/P 15115001A

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	Coit From previous page within 5% of the test unit and exactly accurate at 200°F with red line starting at 230°F (see test notes in POM. OIL PRESSURE GAGE WAS TESTED AND FOUND TOTALLY ACCURATE WITH TEST GAGES. OIL COOLER WAS REMOVED (P/N 455-165) AND A NEW OIL COOLER P/N 20002A S/N B8A-58220 INSTALLED. (REF PACIFIC OIL COOLER YELLOW TAG) DATED 5-17-02. ALL COMPONENTS WERE REINSTALLED, ENGINE WAS TEST RUN AND LEAK CHECKED - NO LEAKAGE FOUND. ALL WORK WAS PERFORMED IN ACCORDANCE WITH LYCOMING INSTRUCTIONS AND AIRWORTHY STANDARDS AND THIS AIRCRAFT IS CONSIDERED AIRWORTHY FOR CONTINUED SERVICE. Richard J. Russ ACP 15115001A					
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
8/14/02	TACH 1543.1 REMOVED NO 2 CYLINDER TO CHECK FOR CRACK IN Cyl due to oil leak. CYLINDER FOUND TO BE CRACKED. INSTALLED FRESH OVERHAULED CHRYSLER CYLINDER OVERHAULED BY D&B AIRCRAFT ENGINES (SEE REPAIR TAG) ALL WORK PERFORMED IN ACCORDANCE WITH THE LYCOMING OIL MANUAL AND STANDARD AIRCRAFT PRACTICES. ENGINE WAS TEST RUN AND FLOWN FOR 30 MINUTES TO VERIFY EVERYTHING OPERATING NORMALLY. THIS ENGINE IS AIRWORTHY AND OK FOR RETURN TO SERVICE. Richard J. Russ ACP 15115001A

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	6/1/02	TACH	:	Removed oil cooler AND REPLACED WITH FRESH O/H FROM PACIFIC OIL COOLER SERVICE P/N 20002A, S/N B89-58228 REF: YELLOW TAG #W/O 33113. REMOVED TEMP PROBE AND PERFORMED CALIBRATION CHECK by comparing to Temp INDICATION IN BOILING OIL USING A OUTSIDE THERMOMETER. REMOVED OIL FILTER HOUSING AND VERNATHERM to check VERNATHERM OPERATION AND SEAT. ALL COMPONENTS REINSTALLED IN ACCORDANCE WITH MAINTENANCE MANUAL(S). AIRCRAFT IS CONSIDERED AIRWORTHY AND APPROVED FOR RETURN TO SERVICE		
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
7-16-02	TACH 1526.65 PERFORMED DIFFERENTIAL COMPRESSION TEST TO CHECK RING SEATING ON NO 3 CYL. TEST RESULTS AS FOLLOWS 1-78/80, 3-75/80, 4-80/80, 2-75/80 R Russ A&P 15H5001A
7-17-02	TACH 1526.70 THE FOLLOWING WORK WAS ACCOMPLISHED TO TEST THE ENGINE OIL TEMP AND OIL PRESSURE SYSTEM WHICH INCLUDED GAGE CALIBRATION. REMOVED AND REPLACED OIL FILTER AND OIL FILTER HOUSING CONTAINING THE VERNATHERM. VERNATHERM SEAT WAS INSPECTED AND GROUND (ROGUT) PER SI 1316A. A NEW VERNATHERM WAS TESTED FOR OPERATION IN ACCORDANCE WITH LYCOMING TEST PROCEDURES. VERNATHERM P/N SL53E1900 REV B ASSY FULLY CLOSED @ 185°F. THE OIL TEMP SENDING UNIT WAS TESTED WITH A CALIBRATED THERMOMETER AND THE AIRCRAFT GAGE WAS FOUND TO BE

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	6-01-02					
	Tach time 1519.9, TTSMOH 1200.29: checked compression using a differential pressure testor with orifice cyl. # 1-76/80, #3-77/80, #2-75/80, #4-78/80. Drained oil and checked filter for contamination-none found. Removed exhaust system for inspection. Removed engine from mount to clean, paint & refurbish. Cleaned all 3 primer injectors and repaired two primer lines. Removed both magnetos for inspection. Replaced points on RH magneto. Removed all induction tubes and reinstalled with new intake gaskets P/N PA71973 and new induction hoses P/N 69603, removed crankshaft plug to inspect crankshaft in accordance with SB 505B and AD 96-09-10. Clean out slug and inspected for cracks, corrosion and dimension. No cracks or corrosion was found and inside diameter check with new specs. Installed a new STD-1211 plug in accordance with the Lycoming Service Manual. Installed 4 new oil return hoses P/N STD-1196. engine was reinstalled with 8 new lord mounts P/N J-7402-24 and new engine mount bolts & nuts. Muffler was replaced with a new assy. P/N 99482-02R and a new stainless heater shroud. Exhaust system was inspected and reinstalled with new blo-proof exhaust gaskets P/N 77611. Eight new Champion spark plugs model REM40E were installed and torqued to 30 ft. pounds. Both magnetos were reinstalled with new gaskets and time to 25 deg.					
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
	BFTDC. A new Champion oil filter P/N Ch48110 was installed and engine was serviced with 8 qts. 100 wt. Aeroshell non-detergent oil. A new bracket P/N 63695-000 was installed on the alternator mounting bracket to support the RH engine cooling baffle. All cooling baffles were removed and repaired as required using 2024-T3 aluminum. All of the baffle seals were replaced with new 1/8" silicon rubber seals. The carburetor heat aluminum duct was repaired and installed with new hardware. Removed carburetor heat box and overhauled with new grommets and bushings. Reinstalled and safetied. All the engine scat hoses were replaced with new. Propeller was reinstalled, torqued, and safetied.
	This engine has been inspected in accordance with an annual inspection and is considered airworthy and approved for return to service.
	<i>Richard T. Russ</i> Richard T. Russ A&P 1511500IA

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
12-6-01	Tach 1518.80	: SMOH 1199.2	Comp CK. #1 78/80 #2 76/80 #3 40/80 #4 78/80	Remove #3 cylinder due to low Comp. Replace Valve with new P/N SL 19001 A Replace Valve Guide with new P/N SL 74230 A Replace Rings with new P/N SL 5401-SC Ring Set. Install with new Gasket set P/N SL 12032-SC. ALL WORK IAW Lycoming Overhaul Manual. Changed Oil & Filter, Serviced Engine with 80ts W100 Mineral Aeroshell Oil. Cleaned, Gapped, & tested Spark Plugs. Cleaned and Inspected Engine Air Induction Filter. AID 96-09-10 Oil Pump Impellers - Cont. to Next Page →		
TOTALS	:	:	:			

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS	
12-6-01	Tach 1518.80	SMOH 1199.2 Cont. from Previous Page - Removed Accessory Housing, Visual Inspected Oil Pump Has Nitrided driving Impeller P/N LW-18109, Carbureted Impeller Shaft Assembly P/N LW-18110. Washed Engine & Cowling. Test Run Checked for Leaks None Noted @ this time. — — —
Date 12-6-01	total time 1199.2 SMOH	Date 12/6/01 TT 1199.2 SMOH
I certify this Engine has been inspected in accordance with a 100hr inspection and was determined to be in airworthy condition.	Signature <i>[Signature]</i> A&P No. 446423169	I certify this Engine has been inspected in accordance with an Annual inspection and found to be in airworthy condition
		Signature <i>[Signature]</i> IA 172113Z

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT.	:	:	:			
FWD.	:	:	:			
	:	:	:			
	:	:	:			
PRECISION AVIATION 5240 S. COLLINS SUITE 100, ARLINGTON, TX 76018 817/465-0908 Date: 11/30/00 Tach Time: 1514.55 REGISTRATION: N7086W S/N: 28-872 Drained oil. Removed oil filter. Added 8qts. of Aeroshell 100W oil. Installed new CH48110 oil filter. Removed left magneto, sent out to Select Aircraft Services for repair (see yellow tag). Reinstalled magneto after repair. Timed to 25degrees BTDC as per Piper Service Manual. <i>John Butler</i> JOHN BUTLER A&P 566868948						
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and address.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
21 Aug 00	Tach 1439.17 SMOH 1119.57 Comp. CK. #1 76/80 #2 74/80 #3 74/80 #4 72/80 Changed oil and filter. Serviced engine with 8qts. w/ Aeroshell. Cleaned gapped & tested spark plugs. Replaced "O" ring and lower gasket on dipstick tube. Replaced exhaust gaskets #'s 3 & 4 cylinders. Replaced cylinder head oil return hoses #'s 1 & 3 cylinders. Replaced scot tubing for defroster. Replaced carb. heat scot tubing. Cleaned engine, test ran, checked for leaks & operational limits. AD 96-12-07 Impulse couplings cw (hYs) and TCM MSB645. Next due 1939.17
21 Aug 00	Tach 1439.17 SMOH 1119.57 I certify this engine and propeller has been INSPECTED in accordance with an Annual Inspection & was determined to be in AIRWORTHY condition. <i>Mark Davis</i> A&P 44068004 IA

DATE 99	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	1262.8	Tach.	Annual Insp.			
8-10	OK.	CLEAN PLUGS & TEST.	DRESS & PAINT PRPG.		CHECK COMP (SEE BELOW) CHECK TIMING	
	DETAILS	LISTING IN AC RECORDS.	WASH DOWN ENGINE		CHECK AD SEE	
	CHECK OK :	:	:		& TEST RUN & LEAK	
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	COMPRESSION CHECK					
	#1 75/80	#2 76/80	#3 72/80			
	#4 78/80	#5 X/80	#6 X/80			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:			

Date: 8-10-99 Tach/Robbs: 1262.8

Total: SMOH: *Prop*

I certify that this engine/airframe has been inspected in accordance with a 100 hour/annual inspection and has been determined to be in airworthy condition.

Authorized Signature: *Jim Brown*

Certificate # AP4406295791A

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE 99	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
10-4	1293.7 Tach. (CHANGE OIL & FILTER. SERVICE ENG. WITH 8 QTS AS W 80 OIL & 48110 FILTER CHECK OLD FILTER FOR METAL, NONE FOUND. TEST RUN & LEAK CHECK OK. INSPECT EX JAW AD
	OK. DUE 50 HRS. <i>Jim Brown 440629579 A & P</i>
11/11/00	1356.15 Tach. Changed oil & Filter - Service Engine with 8 Quarts Acushell 80 W. Run engine & Test for leaks
	<i>Alvin G. Rucker</i>
	1721139 A & P

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
98						
BRT. FWD.	:	:	:			
10-3	1073.0	TACH.	REMOVE ALT. & REPAIR. REPAIR HEAT MUFF FOR CABIN HEAT. REPLACE EX PIPE RT SIDE (SEE TAB) REPLACE SPINNER. CHANGE OIL & FILTER. SERVICE WITH 7 QTS AS100 & 48110 FILTER. TEST RUN & LEAK CHECK OK.			
	:	:	:	J. Brown 440629579 A&P		
12-01	1124.1	TACH.	CHANGE OIL & FILTER. SERVICE W/ 9 QTS AS W80 OIL & 48110 FILTER. CUT FILTER & CHECK FOR METAL NONE FOUND. TEST RUN & LEAK CHECK OK. OK TO RETURN TO SERVICE.			
	:	:	:	J. Brown 440629579 IA		
TOTALS	:	:	:			

[illegible]

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	:	:	:			
20 JUNE 1997	TACH 996	ENGINE TOTAL TIME 3213.8	ENGINE TIME SINCE OVERHAUL 466.4 HR	PROPELLER TOTAL TIME - UNKNOWN	PROPELLER TIME SINCE OVERHAUL 168.5 HR	ANNUAL INSPECTION COMPLETED IAW FAR 43 APPENDIX D REQUIREMENTS. CHANGED OIL & REPLACED CH48110 FILTER. REFILLED 8 QTS. AERO SHELL 15W50. CLEANED/GAPPED/TESTED/ROTATED SPARKPLUGS. CHECKED MAG TIMING. DRESSED PROPELLER. AD 96-09-10 OIL PUMP IMPELLERS, PL/C/W @ 5/87 OVERHAUL. AD 96-09-10 SUPERSEDES AD 81-18-04 R2. I CERTIFY THAT THIS ENGINE & PROPELLER HAVE BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WERE DETERMINED TO BE IN AIRWORTHY CONDITION. James R. Cunningham
AD 95-26-13 NICHOLAS:						
TOTALS	C/W BY REPLACEMENT.			A&P 543683418 IA		
	NEXT DUE 2005			All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
5 JULY 1998	TACH 1046, ENGINE TOTAL TIME 3263.8, ENGINE TIME SINCE OVERHAUL 716.4, PROP TOTAL TIME - UNKNOWN, PROP TIME SINCE OVERHAUL 218.5 ANNUAL INSPECTION COMPLETED IAW FAR 43 APPENDIX D. CHANGED OIL & REPLACED CH48110 FILTER. SERVICED W/ 8 QT. AERO SHELL 15W50. CHECKED COMPRESSION: 1) 48/80 2) 78/80 3) 46/80 4) 74/80. CHECKED MAG TIMING. CLEANED/GAPPED/ROTATED SPARKPLUGS. C/W AD 98-02-08 HOLLOW CRANKSHAFT - PARA (C) INSPECTION. NO CORROSION PITS FOUND. AD RECURRING EA. 5 YRS. I CERTIFY THAT THIS ENGINE & PROPELLER HAVE BEEN INSPECTED IAW AN ANNUAL INSPECTION & WERE DETERMINED TO BE IN AIRWORTHY CONDITION. James R. Cunningham A&P 543683418 IA

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	2/1/95 CONT'D) DRESSED PROPELLER. RE-INSTALLED FOLLOWING REMOVAL & REPAIR, LH & RH EXHAUST STACK ASSEMBLIES. UNITS REPAIRED BY AEROFABRICATORS W/O 0318063, CRS # Q12R113L. C/W AD 94-01-03R1 BENDIX COILS & ROTORS - BY INSPECTION. RED COILS & ROUND ROTOR MAGNETS FOUND INSTALLED. STAMPED 'C' ON MAG HOUSING PER AD. AD 94-14-13 ENGINE DAMAGE - N/A BY A/C N7086W. AD 93-18-03 MA4 CARB. - N/A UNIT M/N. AD 93-19-04 MA4 CARB. - N/A BY DATE. AD 94-06-09 BENDIX MAG CAPACITORS - N/A BY DATE. I CERTIFY THAT THIS ENGINE & PROPELLER HAVE BEEN INSPECTED IAW AN ANNUAL INSPECTION & WERE DETERMINED TO BE IN AIRWORTHY CONDITION.					
TOTALS	:	:	:	James R Cunningham A:P 543683418 IA		
All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.						

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
11 MARCH 1996	TACH 959, ENGINE TOTAL TIME 3176.8, ENGINE TIME SINCE OVERHAUL 629.4, PROPELLER TOTAL TIME - UNKNOWN, PROPELLER TIME SINCE OVERHAUL 131.5. ANNUAL INSPECTION COMPLETED IAW FAR 43 APPENDIX D REQUIREMENTS. OWNER CHANGED OIL & FILTER. COMPRESSION CHECKED 1) 75/80 2) 76/80 3) 75/80 4) 75/80. CHECKED MAG TIMING & E-GAP. CLEANED SPARKPLUGS. DRESSED PROPELLER. C/W AD 95-26-13 OIL COOLER HOSES - BY INSPECTION. HOSES REQUIRE REPLACEMENT ^{IN} 1997 PER AD. AD 95-07-01 ROD BOLTS - N/A BY DATE. AD 95-26-02 ENGINE DAMAGE - N/A BY N# & DATE. AD SUPERCEDES AD 94-14-13. I CERTIFY THAT THIS ENGINE & PROPELLER HAVE BEEN INSPECTED IAW AN ANNUAL INSPECTION & WERE DETERMINED TO BE IN AIRWORTHY CONDITION. James R Cunningham A:P 543683418 IA

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	5/22/92 CONTD)			DATED 7/16/90, PAGES 1-4, INSPECTION & REASSEMBLY PERFORMED IAW PARA. 1-3, 6, & 8. INSTALLED NEW LW 18639 LOCK PLATE, NEW STD-2213 BOLT & NECESSARY GASKETS. FINAL BOLT TORQUE 204 IN/LBS & LOCK TAB BENT AROUND BOLT HEAD.		
	:	:	:	James R. Cunningham		
	:	:	:	A&P 543683418		
	8 AUGUST 1992			TACH 817.5, ENGINE TOTAL TIME 3045.3, ENGINE TIME SINCE OVERHAUL 497.9. ANNUAL INSPECTION COMPLETED IAW FAR 43 APPENDIX D REQUIREMENTS. CHANGED OIL & REPLACED FILTER. REFILLED W/ AEROSHELL 15W50. CHECKED COMPRESSION ① 76/80 ② 76/80 ③ 70/80 ④ 78/80. CLEANED/GAPPED/TESTED/ROTATED		
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

CONTINUED NEXT PAGE →

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
8/8/92 CONTD)	SPARKPLUGS. RETORQUED ENGINE AS NECESSARY. FABRICATED NEW #4 PRIMER LINE. CHECKED MAG TIMING & E-CAP. REMOVED PROPELLER SIN 39074K FOR OVERHAUL, INSTALLED EXCHANGE OVERHAULED PROPELLER; SENSENICH 76EMB-D-60, SIN 26776K. PROPELLER TOTAL TIME - UNKNOWN, PROP. TIME SINCE OVERHAUL - 00.0 HR. C/W AD 78-09-07R3 BENDIX IMPULSE, ON LH MAG IAW SB599D. DIMENSIONS FOUND SATISFACTORY. AD RECURRING EA. EDHRS. & NEXT DUE @ TACH 1317.5. AD 92-12-05 PISTON PINS - N/A BY O/H DATE. AD 82-20-01 BENDIX IMPULSE - N/A AS UNIT TIME IN SERVICE GREATER THAN 300 HR. AD 63-22-03 MA4 CARR. - P/C/W @ UNIT OVERHAUL 5/18/87. I CERTIFY THAT THIS ENGINE & PROPELLER HAVE BEEN INSPECTED

CONTINUED NEXT PAGE →

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	7-18-91	TACK	749.3	Annual inspection + service complete This date		
	Compression as follows 1) 7/80 2) 80/80 3) 7/80 4) 40/80. Removed #4 cylinder due to low compression + ground both valves + seats. Reinstalled according to the overhaul manual with new Gasket set P/N 552320. Changed oil + Filter cut open Filter Found no defects serviced with 7QTS A/S 15W/50 oil. cleaned gapped + rotated spark plugs. inspected exhaust system + intake system Found no defects checked engine controls for proper movement + lubricated Adjusted timing on right mag washed engine + test run Found no defects					
				I certify that this aircraft/engine has been inspected in accordance with <u>Annual</u> inspection and was determined to be in airworthy condition.		
				Pertinent details of this inspection are on file at this repair station under Work Order No. <u>7815</u>		
				For EL AERO SERVICES, INC. FAA approved Repair Station, No. AQHD225C		
				For <u>EL Aero Services, Inc.</u>		
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
2-3-92	Tack 797.2 Changed oil + Filter serviced engine with 8QTS AEROSHELL 15W/50 oil cut open Filter Found no defects Test run engine checked for leaks Found none, Repair CARBON HEAT SHROUD AS NECESSARY
	DATE: <u>2-3-92</u>
	APPROVED FOR RETURN
	TO SERVICE W.O. # <u>8529</u>
	CHIEF INSPECTOR-CRS AQHD225C
	<u>Burt Bailey</u>
22 MAY 1992	TACH 801 c/w AD 91-14-22 CRANK-SHAFT GEAR, BY INSPECTION + REWORK PER PARA. 2, b (1-5). GEAR INSPECTED + MODIFIED IAW LYCOMING SB 475A BY ENGINE COMPONENTS NW, w/o #ECN 9844 (CRS. YECR508L) GEAR p/n 13519646, c/w LYCOMING SB 475 REVISION A

DATE JULY 90	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	2: JULY 1990	TACH 625.6	COMPRESSIONS AS			
	: FOLLOWS; 1) 80/80 2) 80/80 3) 80/80 4) 70/80					
	: OIL: DRAINED, OIL FILTER REMOVED AND INSPECTED					
	: A/C SERVICED WITH					
	: 8 QTS: 15 W50 AERO SHELL					
	: CH 48/10 OIL FILTER, SPARK					
	: PLUGS: CLEANED AND GAPPED					
	: MAG: TIMING CHECKED					
	: ROCKER BOX COVERS TIGHTENED					
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:			

I certify that this aircraft/engine has been inspected in accordance with ANNUAL inspection and was determined to be in airworthy condition.

Pertinent details of this inspection are on file at this repair station under Work Order No. 6360

EL AERO SERVICES, INC.
FAA approved Repair Station, No. AQHD225C
By Bruce Bailey FIC ELAERO

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS
4 Oct 90	Tach 659.02 Removed alternator and starter to gain access to broken alternator mount bolt, Removed broken bolt from crankcase - Reinstalled alternator, starter and replaced bolt, performed operation checks and found ok, Returned ACFT to service jiffy k. <u>525327816 A+P</u>
10-12-90	TACH- 678.99 - OIL CHANGE & FILTER - CHAMPION 48110 - AERO SHELL 1100 - SOLVENT WASH DOWN ENGINE & COUPLING - RUN UP FOR LEAK TEST AOK - J.B. MEYERS A/P 462008698JA

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	May 19, 1989			Tach 522.33 Clean, gap and rotate spark plugs, remove + replace ducting hose to carb heat box. David S Zore ARP 559744736. Ran engine checked operation, checked normal.		
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
	:	:	:			
TOTALS	:	:	:	All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.		

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS				
	^{2786.4} Date 6-28-89 Tach 551.0 TT 2667.68 TTS in OH 239.00 I certify that this aircraft/engine has been inspected in accordance with AIAA/CAL inspection and was determined to be in airworthy condition. Pertinent details of this inspection are on file at this repair station under Work Order No. 6126 EL AERO SERVICES, INC. FAA approved Repair Station, No. 411-10A <u>Burt E Bailey</u>				
	A/S 15-50W OIL NEW OIL FILTER ALL NEW FLUID FLEXIBLE HOSES RIP EXHAUST GASKETS COMPRESSION 1) 74/100 2) 79/100 3) 78/100 4) 77/100 SET MAG TIMING				
	Feb 23, 1990 TACH 598.4 OIL DRAINED, OIL FILTER REMOVED, A/C SERVICED WITH 8 QTS 15W50 AERO SHELL OIL, AND CH48110 OIL FILTER, A/C RUN-UP AND LEAK CHECKED NO DEFECTS NOTED. <u> Mitch Bonstedt ARP 307503258</u>				

DATE	GROUND TIME	AIR TIME	TOTAL TIME	SIGNATURE OF PERSON MAKING ENTRY	TACHOMETER READING	INSPECTION REFERENCE DATA
BRT. FWD.	31:00	87	Tach 344.3	24.7 TSMOH		
:	:	:	:	Changed oil & filter serviced with		
:	:	:	:	8 qts Aeroshell 40 Det & Champion		
:	:	:	:	CH 48110 Filter		
:	:	:	:	Mark  528629398		
:	:	:	:			
21 May 88	:	:	Tach 398.2	changed oil serviced		
:	:	:	:	with 6 qts Aeroshell W 50 wt		
:	:	:	:	Mark  528629398		
:	:	:	:			
:	:	:	:			
:	:	:	:			
:	:	:	:			
TOTALS	:	:	:			

All repairs, inspections, alterations must be endorsed by a certificated mechanic or repair agency with name, rating and cert. no.

DATE	MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS					
6-14-88	Tach	431.32	TSMOH	118.72	100 hour	Annual insp.
	complete in accordance with F.A.A. 43 appendix D and Piper service manual. Changed oil and oil filter serviced engine with 8 quarts Aero Shell 50 oil. Compression 1 77% 2 75% 3 76% 4 75%. Replaced #1 2 4 cylinder primer lines with new. Dale A Don ACP 530547160IA					
	I certify that this <u>engine</u> has been inspected in accordance with <u>Annual</u> inspection and have determined it to be in airworthy condition.					
9-30-88	TACH	483.1	C/W	50 HR.	INSP.	ASW 100 OIL
					woods	R.S. 411-6

CERTIFIED OVERHAUL TO
NEW ENGINE TOLERANCES
ZERO-TIME EQUIVALENT

PACIFIC CONTINENTAL ENGINES, INC.
FAA APPROVED REPAIR STATION #4595
16041 ARMINTA ST. • VAN NUYS, CA.

818-781-4947

Make LYCOMING

Model 0-360-A3A

S/N L-6066-36

HRS. SMOH 0.00

This engine was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this Repair Station under

Work Order NO. 85294

Date: May 18, 1987

[Signature]
Authorized Signature

Total time on engine before overhaul 2547.4

Pacific Continental Engines, Inc. warrants this engine for 100% parts and labor for 6 months or 240 hours whichever comes first. Further warranted on a pro-rated basis to the T.B.O. of the engine, at a minimum rate of 40 hours per month except that no labor allowance will exist for the period between the end of the FIRST SIX (6) months and the T.B.O. of the engine. NO OTHER WARRANTY IMPLIED OR EXPRESSED.

Inspected by a certificated
cert. no.

INSPECTION
REFERENCE
DATA

ALL ENGINE ACCESSORIES ARE GUARANTEED FOR SIX MONTHS OR 240 HOURS WHICHEVER OCCURS FIRST. NO EXCEPTIONS! ENGINE ACCESSORIES DEFINED AS: CONTINENTAL AND LYCOMING FUEL INJECTION SYSTEMS (FUEL SERVOS, FUEL PUMPS, MANIFOLD VALVES, LINES, NOZZLES), CARBURETOR, MAGNETOS, STARTER, ALTER-

DATE

MAINTENANCE, INSPECTIONS, REPAIRS AND ALTERATIONS

22 May 87 Tach 319.6 TT 2547.4
Installed Engine in PA-28-180
N 7086W, Engine supplied with
overhauled MAGNETO's STARTER, & CARBURETOR
installed overhauled ALTERNATOR PART # 301
SERIAL # 6100733

Left mag S/N 1003843
Right mag S/N 556530
STARTER S/N 00357
CARBURETOR S/N 648-6573

Mark Peterson 528629398 AS
Serviced with 8qt Shell 80 Non Det & R&W
No Leaks Found
MGP 528629398

AIRCRAFT ENGINE LOG FOR

BOOK NO.

#2

ENGINE MAKE

Lycoming

MODEL

O-360-A3A

SERIAL NO.

L-6066-36

MANUFACTURER

DATE OF MFG.

WEIGHT

HP.

AT

RPM DISPLACEMENT

CU. IN.

OIL WEIGHT - SUMMER

WINTER

OIL CAPACITY

QTS.

FUEL MIN. OCTANE

FIRING ORDER

SPARK PLUG GAP

BREAKER POINT GAP

IGNITION TIMING

VALVE CLEARANCES

OIL PRESSURE

OIL TEMP. RANGE

PROPELLER MAKE

MODEL

SERIAL NO.

PITCH

LENGTH

REMARKS

WARNING... AUTOMOTIVE FUELS ARE NOT RECOMMENDED FOR
USE IN AIRCRAFT ENGINES. THE USE OF ANY FUEL OTHER
THAN AN AVIATION GRADE FUEL WILL VOID ALL WARRANTIES.

NO WARRANTY ON PARTS AND/OR LABOR
WITHOUT PRIOR WRITTEN AUTHORIZATION
FROM PACIFIC CONTINENTAL ENGINE, INC.