



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK					A/R			
055002	ACCOMPLISH OVERSPEED CHECK					A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK					A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK					A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK					A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK					A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK					A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK					A/R			
5-12-01 051201	INSPECTION DOCUMENT 01 SMF		MTH HRS LDG	18-May-2023 1099 624		450		1549	319
5-12-02 051202	INSPECTION DOCUMENT 02 CYHM		MTH HRS LDG	01-May-2015 754.1 408		900		1654.1	424.1
5-12-03 051203	INSPECTION DOCUMENT 03 *CF		MTH HRS	06-Nov-2007 0		1350		1350	120
5-12-04 051204	INSPECTION DOCUMENT 04 *CF		MTH HRS	06-Nov-2007 0		1800		1800	570
5-12-05 051205	INSPECTION DOCUMENT 05 *CF		MTH HRS	06-Nov-2007 0		3150		3150	1920
5-12-06 051206	INSPECTION DOCUMENT 06 SMF		MTH HRS LDG	04-Apr-2024 1192 680		12		30-Apr-2025	2 m 26 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK) SMF		PN-UNKNOWN SN-UNKNOWN MTH HRS LDG	04-Apr-2024 1192 680		12		30-Apr-2025	2 m 26 d
5-12-07 051207	INSPECTION DOCUMENT 07 SMF		MTH HRS LDG	18-May-2023 1099 624		24		31-May-2025	3 m 27 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) SMF		MTH HRS LDG	13-May-2022 1020.7 574		60			
B262004 051210 : FB	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) SMF		30401102-2 57130B1 MTH	13-May-2022		60		31-May-2027	27 m 27 d
Hydro Check Date: 13-May-2022									
5-12-11 051211	INSPECTION DOCUMENT 11 UNK		MTH HRS LDG	19-Mar-2019 937.5 514		72		31-Mar-2025	1 m 27 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION) UNK		PN-UNKNOWN SN-UNKNOWN MTH HRS LDG	19-Mar-2019 937.5 514		72		31-Mar-2025	1 m 27 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
				MTH	06-Nov-2007		144			
B262101 051212	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)									
		UNK		PN-UNKNOWN SN-UNKNOWN	MTH 19-Mar-2019		144		31-Mar-2031	73 m 27 d
Hydro Check Date: 19-Mar-2019										
5-12-13 051213	INSPECTION DOCUMENT 13									
		SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12 450		30-Apr-2025 1642	2 m 26 d 412
5-12-14 051214	INSPECTION DOCUMENT 14									
		SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12 900		30-Apr-2025 2092	2 m 26 d 862
5-12-15 051215	INSPECTION DOCUMENT 15									
		SMF			MTH 18-May-2023 HRS 1099 LDG 624		24 1350		31-May-2025 2449	3 m 27 d 1219
5-12-16 051216	INSPECTION DOCUMENT 16									
		SMF			MTH 13-May-2022 HRS 1020.7 LDG 574		36 1350		31-May-2025 2370.7	3 m 27 d 1140.7
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK 29-10-00-720									
				HM50C-3 060B	MTH HRS		36 1350		31-May-2025 2370.7	3 m 27 d 1140.7
5-12-17 051217	INSPECTION DOCUMENT 17									
		SMF			MTH 13-May-2022 HRS 1020.7 LDG 574		36 1800		31-May-2025 2820.7	3 m 27 d 1590.7
5-12-18 051218	INSPECTION DOCUMENT 18									
		SMF			MTH 13-May-2022 HRS 1020.7 LDG 574		36 2250		31-May-2025 3270.7	3 m 27 d 2040.7
5-12-20 051220	INSPECTION DOCUMENT 20									
		SMF			MTH 18-May-2023 HRS 1099 LDG 624		48 2700		31-May-2027 3799	27 m 27 d 2569
5-12-21 051221	INSPECTION DOCUMENT 21									
		SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12		30-Apr-2025	2 m 26 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
		SMF			MTH 18-May-2023 HRS 1099 LDG 624		24			
B341001 AIRSPEED 051222 : A/S	CALIBRATION TEST INDICATOR 14 CFR PART 91.411									
		SMF		261440-1143 288948A	MTH 18-May-2023		24		31-May-2025	3 m 27 d
Calibration Date: 18-May-2023										
B341001 NO. 1 051222 : ADC	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411									
		SMF		011-01110-00 43800514	MTH 18-May-2023		24		31-May-2025	3 m 27 d
Calibration Date: 18-May-2023										
B341001 NO. 2 051222 : ADC#2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411									
		SMF		011-01110-00 43800517	MTH 18-May-2023		24		31-May-2025	3 m 27 d
Calibration Date: 18-May-2023										
B341001 STANDBY 051222 : STDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411									
		SMF		162350-1161 174589B	MTH 18-May-2023		24		31-May-2025	3 m 27 d
Calibration Date: 18-May-2023										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)									
		SMF			MTH 18-May-2023 HRS 1099 LDG 624		24		31-May-2025	3 m 27 d



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B345000 LEFT <i>051222 : XPDR1</i> Calibration Date: 18-May-2023	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	SMF		011-00779-21 84805304	MTH 18-May-2023		24		31-May-2025	3 m 27 d
B345000 RIGHT <i>051222 : XPDR2</i> Calibration Date: 18-May-2023	G1000 NXI UPGRADE STC SA01896WI (XPDR 91.413)	SMF		011-03303-00 3EH029192	MTH 18-May-2023		24		31-May-2025	3 m 27 d
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	UNK		3-1640 0058	MTH 19-Mar-2019 HRS 937.5 LDG 514		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	UNK		3-1642 0079	MTH 26-Jun-2018 HRS 910.6 LDG 498		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	UNK		3-1640 0056	MTH 19-Mar-2019 HRS 937.5 LDG 514		A/R			
5-12-30 <i>051230</i>	INSPECTION DOCUMENT 30	SMF			MTH 18-May-2023 HRS 1099 LDG 624		48 1800		31-May-2027 2899	27 m 27 d 1669
5-12-31 <i>051231</i>	INSPECTION DOCUMENT 31	UNK			MTH 26-Jun-2018 HRS 910.6 LDG 498		450		1360.6	130.6
5-12-32 <i>051232</i>	INSPECTION DOCUMENT 32	UNK			MTH 20-Feb-2020 HRS 948.82 LDG 523		72 1800		28-Feb-2026 2323	12 m 24 d 1615
5-12-34	INSPECTION DOCUMENT 34	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		6 450		31-Oct-2024 1642	-3 m 4 d 412
Over Due										
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK)	SMF		S4324-1 G03202410	MTH 04-Apr-2024 HRS 1192 LDG 680		6 450		31-Oct-2024 1642	-3 m 4 d 412
Over Due										
5-12-35	INSPECTION DOCUMENT 35	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		6		31-Oct-2024	-3 m 4 d
Over Due										
5-12-37	INSPECTION DOCUMENT 37				MTH 19-Mar-2019 HRS 937.5 LDG 514		7200		8137.5	6907.5
5-12-MA <i>0512MA</i>	INSPECTION DOCUMENT MA	UNK			MTH 19-Mar-2019 HRS 937.5 LDG 514		500		1437.5	207.5
5-12-MB <i>0512MB</i>	INSPECTION DOCUMENT MB	UNK			MTH 26-Jun-2018 HRS 910.6 LDG 498		950		1860.6	630.6
5-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC	*CF			MTH 06-Nov-2007 HRS 0		4000		4000	2770
5-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12		30-Apr-2025	2 m 26 d



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME SMF			MTH HRS LDG	04-Apr-2024 1192 680		36 1400		30-Apr-2027 2592	26 m 26 d 1362
5-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF *CF			MTH HRS	06-Nov-2007 0		12000		12000	10770
5-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG *CF			MTH HRS	06-Nov-2007 0		5000		5000	3770
5-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH *CF			MTH HRS	06-Nov-2007 0		8250		8250	7020
5-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI *CF			MTH HRS	06-Nov-2007 0		12000		12000	10770
5-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ *CF			MTH HRS	06-Nov-2007 0		10600		10600	9370
5-12-MK <i>0512MK</i>	INSPECTION DOCUMENT MK *CF			MTH HRS	06-Nov-2007 0		10400		10400	9170
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE KMKE			MTH HRS LDG	04-May-2021 951.5 526		A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	06-Nov-2007		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS	06-Nov-2007		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS	06-Nov-2007		A/R			
0521009A	ENVIRO SYSTEMS 12 MONTH INSPECTION SMF			MTH HRS LDG	04-Apr-2024 1192 680		12		30-Apr-2025	2 m 26 d
262003A LEFT <i>262003 : L</i>	REPLACE FIRE EXT CARTRIDGE CYHM		13083-5 10-2021	MTH HRS LDG	13-May-2022 1020.7 574		72	7	31-Oct-2027	32 m 27 d
262003A RIGHT <i>262003 : R</i>	REPLACE FIRE EXT CARTRIDGE CYHM		13083-5 10-2021	MTH HRS LDG	13-May-2022 1020.7 574		72	7	31-Oct-2027	32 m 27 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT) SMF			MTH HRS LDG	04-Apr-2024 1192 680		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT) SMF			MTH HRS LDG	18-May-2023 1099 624		A/R			
32-30-40-960 <i>051208 : LG</i>	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST) SMF		40005369-2 5365	MTH	05-May-2022	-61	36		31-Mar-2025	1 m 27 d
Hydro Check Date: 05-May-2022										
32-40-00-960 <i>051208 : EB</i>	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST) SMF		40005399-1 5349	MTH	05-May-2022	-61	36		31-Mar-2025	1 m 27 d
Hydro Check Date: 05-May-2022										
34-60-00-5	G1000 INTERGRATED AVIONICS SYSTEMS ADJUSTMENT TEST KMKE		011-04475-00 48V001325	MTH HRS LDG	08-Jun-2021 951.6 526		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
35-00-00-960 051210 : OXY	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	SMF		4441073-022 ALT280-8521	MTH 01-Oct-2021		60		31-Oct-2026	20 m 27 d
Hydro Check Date: 01-Oct-2021										
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12 450		30-Apr-2025 (1642)1642	2 m 26 d 412
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12 450		30-Apr-2025 (1642)1642	2 m 26 d 412
710010 E1	COMPRESSOR DESALINATION WASH	CYHM			MTH 24-Mar-2011 HRS 754.1 LDG 408		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010 E2	COMPRESSOR DESALINATION WASH	CYHM			MTH 24-Mar-2011 HRS 754.1 LDG 408		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010A E1	DESALINATION/FRESH WATER RINSE	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		O/C			
710010A E2	DESALINATION/FRESH WATER RINSE	SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		O/C			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 06-Nov-2007		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 06-Nov-2007		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 06-Nov-2007		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 06-Nov-2007		A/R			
72-00-00-620-805- 01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-805- 01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-805- 02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-805- 02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 06-Nov-2007		A/R			
72-00-00-620-806- 01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH 06-Nov-2007		A/R			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS			MTH 06-Nov-2007		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER			MTH 06-Nov-2007		A/R			
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER			MTH 06-Nov-2007		A/R			
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH 06-Nov-2007		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH 06-Nov-2007		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 06-Nov-2007		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 06-Nov-2007		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 06-Nov-2007		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 06-Nov-2007		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 06-Nov-2007		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 06-Nov-2007		A/R			
720000 E1	PERFORM ENGINE OVERHAUL			MTH 06-Nov-2007 HRS 0		3500		(3500)3500	2270
720000 E2	PERFORM ENGINE OVERHAUL			MTH 06-Nov-2007 HRS 0		3500		(3500)3500	2270
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION *CF			MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION *CF			MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
720003 E1	INSPECT LOW UTILIZATION ENGINE SMF			MTH 18-May-2023 HRS 1099 LDG 624		24		31-May-2025	3 m 27 d
720003 E2	INSPECT LOW UTILIZATION ENGINE SMF			MTH 18-May-2023 HRS 1099 LDG 624		24		31-May-2025	3 m 27 d
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER			MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER			MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT SMF			MTH 04-Apr-2024 HRS 1192 LDG 680		12 900		30-Apr-2025 (2092)2092	2 m 26 d 862



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT SMF				MTH 04-Apr-2024 HRS 1192 LDG 680		12 900		30-Apr-2025 (2092)2092	2 m 26 d 862
731055 E1	REPLACE FUEL MANIFOLD			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
731055 E2	REPLACE FUEL MANIFOLD			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
790015 E1	REPLACE OIL FILTER ELEMENT KMKE				MTH 04-May-2021 HRS 951.5 LDG 526		900		(1851.5)1851.5	621.5
790015 E2	REPLACE OIL FILTER ELEMENT KMKE				MTH 04-May-2021 HRS 951.5 LDG 526		900		(1851.5)1851.5	621.5
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS SMF			PN SN-UNKNOWN	MTH 04-Apr-2024 HRS 1192 LDG 680		6 100		31-Oct-2024 (1292)1292	-3 m 4 d 62
Over Due										
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS SMF			PN SN-UNKNOWN	MTH 04-Apr-2024 HRS 1192 LDG 680		6 100		31-Oct-2024 (1292)1292	-3 m 4 d 62
Over Due										
793015A E1	CHECK 10 HOUR ENGINE CHIP COLLECTOR				MTH 10-Aug-2016 HRS 766.4 LDG 418		10			
793015A E2	CHECK 10 HOUR ENGINE CHIP COLLECTOR				MTH 10-Aug-2016 HRS 766.4 LDG 418		10			
793015B E1	CHECK 50 HOUR ENGINE CHIP COLLECTOR				MTH 18-May-2016 HRS 754.1 LDG 408		50			
793015B E2	CHECK 50 HOUR ENGINE CHIP COLLECTOR				MTH 18-May-2016 HRS 754.1 LDG 408		50			
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL *CF				MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL *CF				MTH 06-Nov-2007 HRS 0		1750		(1750)1750	520



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY. *CF			0113-12 1184	MTH 06-Nov-2007		O/C			
213001	KAPS II CONTROLLER 9912661-6			52811-102 1180	MTH 10-Aug-2016 HRS 766.4 LDG 418		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 873	MTH 06-Nov-2007		O/C			
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 847	MTH 06-Nov-2007		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14 *CF			1133610-4 104	MTH 06-Nov-2007		O/C			
215002	CONDENSOR ASSEMBLY 9912660-3 MCO			1134620-5 320	MTH 12-May-2009 ACH 1		O/C	0		
215003	RECEIVER DRYER ASSY 9912583-3 *CF			1134275-1 1506	MTH 06-Nov-2007		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 232	MTH 06-Nov-2007		O/C			
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 231	MTH 06-Nov-2007		O/C			
215005	VANE AXIAL BLOWER ASSY.			1250435-10 341	MTH 12-May-2009 HRS 459 LDG 268		O/C	0 0 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD			PN SN-UNKNOWN	MTH 06-Nov-2007 ACH 0		800	0	800	409.4
216000 LH	THERMAL ACTUATOR SMF			74S235H6F255 NSN	MTH 04-Apr-2024 HRS 1192 LDG 680		O/C	0 0 0		
216000 RH	THERMAL ACTUATOR KIWA			74S235H6F255 NSN	MTH 01-May-2024 HRS 1206.2 LDG 686		O/C	0 0 0		
221001 AILERON	GSA 80 TORQUE SERVO *CF			011-00877-00 66305038	MTH 06-Nov-2007		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO *CF			011-00877-00 66305036	MTH 06-Nov-2007		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO *CF			011-00878-10 71305022	MTH 06-Nov-2007		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO *CF			011-00878-10 71305028	MTH 06-Nov-2007		O/C			
221003 AILERON	GSM 85A SERVO MOUNT *CF			011-01436-A2 10905011	MTH 06-Nov-2007		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT *CF			011-01436-A0 11205010	MTH 06-Nov-2007		O/C			
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT *CF			011-01436-A1 11305003	MTH 06-Nov-2007		O/C			
221003 RUDDER	GSM 85 SERVO MOUNT *CF			011-01436-A3 11005006	MTH 06-Nov-2007		O/C			
221004	GMC 710 AFCS CONTROLLER *CF			011-01020-00 87805085	MTH 06-Nov-2007		O/C			
231002 NO. 1	GMA 1347D AUDIO PANEL KMKE			011-3568-20 4QF105626	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
231002 NO. 2	GMA 1347D AUDIO PANEL	KMKE		011-3568-20 4QF105633	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
231003 NO. 1	VHF COMM ANTENNA	*CF		VHF10-829 0068	MTH 06-Nov-2007		O/C			
231003 NO. 2	VHF COMM ANTENNA	*CF		VHF10-829 0135	MTH 06-Nov-2007		O/C			
243001 LEFT	DIGITAL GCU 9912682-3	ICT		GCSG550-5 08224150	MTH 24-Jul-2009 HRS 500		O/C	0		
243001 RIGHT	DIGITAL GCU 9912682-1	*CF		GCSG550-4 1092H	MTH 06-Nov-2007		O/C			
243002	EMER INST BATTERY	KIWA		CBS24 00909	MTH 01-May-2024 HRS 1206.2 LDG 686		O/C			
243007	MAIN SHIP BATTERY TELEDYNE GILL LEAD ACID	KTPA		S4324-1 G03202410	MTH 17-Oct-2023 HRS 1140.6		O/C	0 0		
243015	RELAY DISCONNECT BATTERY S3155-1	*CF		A-931F CP-57151	MTH 06-Nov-2007		O/C			
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0197	MTH 06-Nov-2007		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0191	MTH 06-Nov-2007		O/C			
245003	FLAP CONTROL MODULE	*CF		7018916-9 0189	MTH 06-Nov-2007		O/C			
245005 LEFT	ICE PROTECTION CONTROL	*CF		7018917-9 0149	MTH 06-Nov-2007		O/C			
245005 RIGHT	ICE PROTECTION CONTROL	*CF		7018918-13 0125A	MTH 06-Nov-2007		O/C			
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0189	MTH 06-Nov-2007		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0193	MTH 06-Nov-2007		O/C			
245008	DOOR MONITOR-	*CF		7018921-5 0163	MTH 06-Nov-2007		O/C			
245009	LANDING GEAR MONITOR-	*CF		7018923-12 0106	MTH 06-Nov-2007		O/C			
245010 LEFT	START CONTROL	*CF		7018924-5 0197	MTH 06-Nov-2007		O/C			
245010 RIGHT	START CONTROL	*CF		7018924-5 0198	MTH 06-Nov-2007		O/C			
245011	FLAP MONITOR-	*CF		7018925-11 0154	MTH 06-Nov-2007		O/C			
245012 LEFT	SPEEDBRAKE ASSY	*CF		7018926-1 0228	MTH 06-Nov-2007		O/C			
245012 RIGHT	SPEEDBRAKE ASSY	*CF		7018926-1 0227	MTH 06-Nov-2007		O/C			
245013	DIAGNOSTIC UNIT	*CF		7018927-7 0173	MTH 06-Nov-2007		O/C			
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	*CF		85-230-2 0722-549M2	MTH 06-Nov-2007		O/C			
251001	GLARESHIELD ASSEMBLY	*CF		4319027-9 80994-1	MTH 06-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description		Part Number		C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
256001 NO. 1	LIFE VEST	SMF		P01074-101 21101690303	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256001 NO. 2	LIFE VEST	SMF		P01074-101 21101690265	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256001 NO. 3	LIFE VEST	SMF		P01074-101 21101690282	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256001 NO. 4	LIFE VEST	SMF		P01074-101 21101690284	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256001 NO. 5	LIFE VEST	SMF		P01074-101 21101690151	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256001 NO. 6	LIFE VEST	SMF		P01074-101 21101690190	MTH 13-May-2022 HRS 1020.7 LDG 574		60	7 0 0	31-Oct-2026	20 m 27 d
256002	ELT BATTERY	SMF		452-0133 1007232-001	MTH 04-Apr-2024 HRS 1192 LDG 680	1	60	0 0 0	31-May-2029	51 m 27 d
256003A CABIN	FIRST AID KIT --	SMF		932-1528-61 DEC-2022	MTH 18-May-2023 HRS 1099 LDG 624		DUE DUE DUE DUE		30-Nov-2024	-2 m 4 d
Expiration Date: 30-Nov-2024										
256004	ELT ANTENNA	*CF		110-340 159889	MTH 06-Nov-2007		O/C			
256007 256001	ELT PROCESSOR C406N	*CF		453-5060 03903	MTH 06-Nov-2007		O/C			
256016 CO-PILOT	DUAL USB CHARGE PORT - KMKE			6430202-3 J19-11051	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
256016 PILOT	DUAL USB CHARGE PORT - KMKE			6430202-3 D21-11340	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207730	MTH 06-Nov-2007		O/C			
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 208156	MTH 06-Nov-2007		O/C			
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	SMF		30401102-2 57130B1	MTH 13-May-2022 HRS 1020.7 LDG 574		O/C	174 0 574		
262003 LEFT	FIRE EXT CARTRIDGE	SMF		13083-5 10-2021	MTH 13-May-2022 HRS 1020.7 LDG 574		72	7 0 0	31-Oct-2027	32 m 27 d
Manufacture Date: 31-Oct-2021										
262003 RIGHT	FIRE EXT CARTRIDGE	SMF		13083-5 10-2021	MTH 13-May-2022 HRS 1020.7 LDG 574		72	7 0 0	31-Oct-2027	32 m 27 d
Manufacture Date: 31-Oct-2021										
262004	PORTABLE FIRE EXTINGUISHER UNK			PN-UNKNOWN SN-UNKNOWN	MTH 19-Mar-2019 HRS 937.5 LDG 514		O/C	0 0 0		

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
271001 LEFT	CONTROL WHEEL ASSY *CF	4319065-1 1117	MTH 06-Nov-2007		O/C			
271001 RIGHT	CONTROL WHEEL ASSY *CF	4319065-2 1074	MTH 06-Nov-2007		O/C			
271002 --	ELEVATOR TRIM TAB ACTUATOR	PN SN-UNKNOWN	MTH 06-Nov-2007		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0085	MTH 06-Nov-2007		O/C			
273002	AILERON TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0083	MTH 06-Nov-2007		O/C			
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1 *CF	MP50Y-1 068	MTH 06-Nov-2007		O/C			
275002 LEFT	FLAP ACTUATOR 9912640-1 *CF	41013930-101 0161	MTH 06-Nov-2007		O/C			
275002 RIGHT	FLAP ACTUATOR 9912640-2 *CF	41013930-102 0134	MTH 06-Nov-2007		O/C			
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-52 *CF	140527-5200 07050178	MTH 06-Nov-2007		O/C			
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344-52 *CF	140527-5200 07040147	MTH 06-Nov-2007		O/C			
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-1	41014070-104 0598	MTH 20-Apr-2010 HRS 617.1 LDG 345		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-2 *CF	41014070-103 0121	MTH 06-Nov-2007		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C1306	MTH 06-Nov-2007		O/C			
282001 RIGHT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C1274	MTH 06-Nov-2007		O/C			
282002	TRANSFER VALVE 9914103-6 *CF	ZSV57 NSN	MTH 06-Nov-2007		O/C			
282003 LEFT	DC FUEL PUMP 9912553-1 *CF	1C7-23 6BC143	MTH 06-Nov-2007		O/C			
282003 RIGHT	DC FUEL PUMP 9912553-1 *CF	1C7-23 6BC144	MTH 06-Nov-2007		O/C			
282004 L1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C311	MTH 06-Nov-2007		O/C			
282004 L2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C315	MTH 06-Nov-2007		O/C			
282004 R1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C116	MTH 06-Nov-2007		O/C			
282004 R2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C326	MTH 06-Nov-2007		O/C			
282005 LEFT	VALVE-FUEL MOTOR 9912014-3 *CF	AV24B1507 AA118197	MTH 06-Nov-2007		O/C			
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3 *CF	AV24B1507 AA118228	MTH 06-Nov-2007		O/C			
284001 L1	FUEL PROBE 9912664-1 *CF	020-251-001 0208	MTH 06-Nov-2007		O/C			
284001 L2	FUEL PROBE 9912664-2 *CF	020-251-002 0197	MTH 06-Nov-2007		O/C			
284001 L3	FUEL PROBE 9912664-3 *CF	020-251-003 0213	MTH 06-Nov-2007		O/C			
284001 L4	FUEL PROBE 9912664-4 *CF	020-251-004 0212	MTH 06-Nov-2007		O/C			
284001 L5	FUEL PROBE 9912664-5 *CF	020-251-005 0236	MTH 06-Nov-2007		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
284001 R1	FUEL PROBE 9912664-1	*CF 020-251-001 0215	MTH 06-Nov-2007		O/C			
284001 R2	FUEL PROBE 9912664-2	*CF 020-251-002 0235	MTH 06-Nov-2007		O/C			
284001 R3	FUEL PROBE 9912664-3	*CF 020-251-003 0222	MTH 06-Nov-2007		O/C			
284001 R4	FUEL PROBE 9912664-4	*CF 020-251-004 0196	MTH 06-Nov-2007		O/C			
284001 R5	FUEL PROBE 9912664-5	*CF 020-251-005 0239	MTH 06-Nov-2007		O/C			
284002	SIGNAL CONDITIONER 9912664-6	*CF 367-350-001 1063	MTH 06-Nov-2007		O/C			
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2	*CF HM50C-3 060B	MTH 06-Nov-2007		O/C			
291002	HYDRAULIC CHECK VALVE *CF	CV02-267 NSN	MTH 06-Nov-2007		O/C			
291003	HYDRAULIC SYS PRESSURE GAUGE *CF	19940933-1 -	MTH 06-Nov-2007		O/C			
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	*CF 80665 NSN	MTH 06-Nov-2007		O/C			
291007	HYDRAULIC MANIFOLD 9912657-14	*CF 8257-3 0020	MTH 06-Nov-2007		O/C			
291008	HYDRAULIC RELIEF VALVE 9912657-2	*CF 2672 NSN	MTH 06-Nov-2007		O/C			
291009	BRAKE PRESSURE SWITCH 9912657-3	*CF 80664 NSN	MTH 06-Nov-2007		O/C			
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	*CF 4251 NSN	MTH 06-Nov-2007		O/C			
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	*CF 4252 NSN	MTH 06-Nov-2007		O/C			
291011	HYDRAULIC DUMP VALVE 9912657-15	*CF 9625-1 NSN	MTH 06-Nov-2007		O/C			
291012	HYDRAULIC RESERVOIR ASSEMBLY *CF	7017005-24 NSN	MTH 06-Nov-2007		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	*CF 7550-2 0145	MTH 06-Nov-2007		O/C			
301001 LEFT	WING DE-ICE BOOT	SMF 9912662-17 NGI1020	MTH 21-Oct-2022 HRS 1060.9 LDG 602		O/C	0 0 0		
301001 RIGHT	WING DE-ICE BOOT	KMKE P35-4D5317-18 NFR7950	MTH 04-May-2021 HRS 951.5 LDG 526		O/C	0 0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT	KMKE P29S4D5317-05 NFS6630	MTH 04-May-2021 HRS 951.5 LDG 526		O/C	0 0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT	SMF 9912662-4 NFU2450	MTH 21-Oct-2022 HRS 1060.9 LDG 602		O/C	0 0 0		
301004 L1	DE-ICE PRESSURE SWITCH *CF	1106P55-1 4924A	MTH 06-Nov-2007		O/C			
301004 L2	DE-ICE PRESSURE SWITCH *CF	1106P55-1 4875A	MTH 06-Nov-2007		O/C			
301004 L3	DE-ICE PRESSURE SWITCH *CF	1106P55-1 4395A	MTH 06-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301004 R1	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4860A	MTH 06-Nov-2007		O/C			
301004 R2	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4877A	MTH 06-Nov-2007		O/C			
301004 R3	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4440A	MTH 06-Nov-2007		O/C			
301004	VERT DE-ICE BOOT 9912662-13	SMF		P29S4D5317-13 NGH9260	MTH 18-May-2023 HRS 1099 LDG 624		O/C	0 0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY *CF			5285-00-3 1239	MTH 06-Nov-2007		O/C			
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY *CF			5285-00-3 1035	MTH 06-Nov-2007		O/C			
302002 LEFT	TEMP SWITCH *CF			1173T0759 4143	MTH 06-Nov-2007		O/C			
302002 RIGHT	TEMP SWITCH *CF			1173T0759 4162	MTH 06-Nov-2007		O/C			
304001 L1	DE-ICE VALVE *CF			3D2353-06 N072702	MTH 06-Nov-2007		O/C			
304001 L2	DE-ICE VALVE *CF			3D2353-06 N072330	MTH 06-Nov-2007		O/C			
304002 LEFT	WINDSHIELD CONTROLLER *CF			7018108-25 0101	MTH 06-Nov-2007		O/C			
304002 RIGHT	WINDSHIELD CONTROLLER *CF			7018108-25 0112	MTH 06-Nov-2007		O/C			
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF			7041020-5 36	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF			7041020-6 33	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
321001	NOSE LANDING GEAR TRUNNION *CF			7042020-1 35	MTH 06-Nov-2007		O/C			
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY *CF			7041050-3 33	MTH 06-Nov-2007 LDG 0		12000	0	12000	11292
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY *CF			7041050-3 31	MTH 06-Nov-2007 LDG 0		12000	0	12000	11292
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF			7041030-1 40	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY UNK			7041030-2 26241113	MTH 20-Feb-2020 HRS 948.82 LDG 523		20000	15	20508	19800
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK *CF			6327504-6 1699	MTH 06-Nov-2007		O/C			
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK *CF			6327504-6 1721	MTH 06-Nov-2007		O/C			
322002	NOSE GEAR FORK & PISTON ASSEMBLY *CF			7042040-1 NSN	MTH 06-Nov-2007		O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1	*CF		FA100036-001 FA100036-1-0076	MTH 06-Nov-2007 LDG 0		12000	0	12000	11292
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-5	*CF		FA100104-001 FA100104-1-0030	MTH 06-Nov-2007 LDG 0		12000	0	12000	11292



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR				MTH	06-Nov-2007				
RIGHT	9912653-6	*CF		FA100105-001 FA100105-1-0038	LDG	0	12000	0	12000	11292
322011	NOSE LANDING GEAR ACTUATOR				MTH	06-Nov-2007				
	9912654-2	*CF		FA100087-001 FA100087-1-0053	LDG	0	12000	0	12000	11292
322202	SHIMMY DAMPER	*CF		7042030-2 NSN	MTH	06-Nov-2007	O/C			
322205	LANDING GEAR STRUT ASSEMBLY				MTH	06-Nov-2007				
NOSE		*CF		7042010-4 NSN	LDG	0	20000	0	20000	19292
322206	LANDING GEAR DRAG BRACE ASSY				MTH	06-Nov-2007				
NOSE		*CF		7042120-1 NSN	LDG	0	20000	0	20000	19292
323001	LANDING GEAR ASSEMBLY				MTH	06-Nov-2007	O/C			
LEFT		*CF		7041010-5 36			O/C			
323001	LANDING GEAR ASSEMBLY				MTH	06-Nov-2007	O/C			
RIGHT		*CF		7041010-6 33			O/C			
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE				MTH	19-Mar-2019	288		30-Apr-2031	74 m 26 d
	9914678-3	UNK		40005369-2 5365	HRS	937.5				
					LDG	514		514		
Manufacture Date: 30-Apr-2007										
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE				MTH	19-Mar-2019	288		30-Apr-2031	74 m 26 d
	9914678-4	UNK		40005399-1 5349	HRS	937.5				
					LDG	514		514		
Manufacture Date: 30-Apr-2007										
323003	EMER BLOW DOWN BTL PRESSURE GAUGE				MTH	06-Nov-2007	O/C			
		*CF		19940931-1 -						
324001	MAIN LANDING GEAR TIRE				MTH	19-Mar-2019	O/C	0		
LEFT	9912646-1	UNK		021-523-0 8040S00311	HRS	937.5		0		
					LDG	514		0		
324001	MAIN LANDING GEAR TIRE				MTH	19-Mar-2019	O/C	0		
RIGHT	9912646-1	UNK		021-523-0 8039S00347	HRS	937.5		0		
					LDG	514		0		
324002	NOSE LANDING GEAR TIRE				MTH	26-Jun-2018	O/C	0		
	9912649-1	UNK		079-606-0 7137S00232	HRS	910.6		0		
					LDG	498		0		
324003	MAIN LANDING GEAR WHEEL				MTH	19-Mar-2019	O/C	0		
LEFT	9912645-1	UNK		3-1640 0058	HRS	937.5		0		
					LDG	514		514		
324003	MAIN LANDING GEAR WHEEL				MTH	19-Mar-2019	O/C	0		
RIGHT	9912645-1	UNK		3-1640 0056	HRS	937.5		0		
					LDG	514		514		
324004	NOSE LANDING GEAR WHEEL				MTH	26-Jun-2018	O/C			
NOSE	9912648-1	UNK		3-1642 0079	HRS	910.6				
					LDG	498		498		
324005	MAIN LANDING GEAR BRAKE ASSY				MTH	06-Nov-2007	O/C			
LEFT	9912645-3	*CF		2-1706-1 0147						
324005	MAIN LANDING GEAR BRAKE ASSY				MTH	06-Nov-2007	O/C			
RIGHT	9912645-3	*CF		2-1706-1 0152						
324006	SHUTTLE VALVE	*CF		5145-1 NSN	MTH	06-Nov-2007	O/C			
LEFT	9914689-4									
324006	SHUTTLE VALVE	*CF		5145-1 NSN	MTH	06-Nov-2007	O/C			
RIGHT	9914689-4									
324007	BRAKE METERING VALVE				MTH	06-Nov-2007	O/C			
	9912650-9	*CF		84-75 0067						

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324101 LEFT	WHEEL SPEED SENSOR 9912650-5 *CF	466-23-1 NSN	MTH 06-Nov-2007		O/C			
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5 MCO	466-23-1 0031	MTH 02-Dec-2008 HRS 393		O/C			
324101	PARKING BRAKE VALVE 9912388-10 *CF	98433-1 0067	MTH 06-Nov-2007		O/C			
324102	ANTISKID CONTROL UNIT 9912650-1 *CF	556-3 302820159	MTH 06-Nov-2007		O/C			
324103	ANTISKID CONTROL VALVE 9912650-6 *CF	211-134-1 0022	MTH 06-Nov-2007		O/C			
324104	EMERGENCY BRAKE VALVE 9912651-1 ICT	72298 0313	MTH 03-Jul-2010 HRS 644.9 LDG 356		O/C	0 0 0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE *CF	19940931-1 -	MTH 06-Nov-2007		O/C			
325001	BUNGE ASSEMBLY *CF	7042072-9 NSN	MTH 06-Nov-2007		O/C			
334001 LEFT	POWER SUPPLY *CF 9912677-3	82004-1 000231	MTH 06-Nov-2007		O/C			
334001 RIGHT	POWER SUPPLY *CF 9912677-3	82004-1 000190	MTH 06-Nov-2007		O/C			
334002	GROUND RECOGNITION LIGHT 9912679-3 *CF	84003-2 000114	MTH 06-Nov-2007		O/C			
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1 *CF	84005-1 000189	MTH 06-Nov-2007 HRS 0		8000	0	8000	6770
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2 MCO	84005-2 000052	MTH 09-May-2008 HRS 192		8000	0	8192	6962
341001	SWAAT UNIT *CF 9912689-1	0863B2 122	MTH 06-Nov-2007		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM *CF	011-01110-00 43800514	MTH 06-Nov-2007		O/C			
341002 NO. 2	GDC 74B AIRDATA SYSTEM *CF	011-01110-00 43800517	MTH 06-Nov-2007		O/C			
341003 NO. 1	GTP 59 OAT PROBE SYSTEM *CF	011-00978-00 47908643	MTH 06-Nov-2007		O/C			
341003 NO. 2	GTP 59 OAT PROBE SYSTEM SMF	011-00978-00 47989242	MTH 04-Apr-2024 HRS 1192 LDG 680		O/C	0 0 0		
341004 LEFT	PITOT PROBE *CF 9912678-1	0851LN 254108	MTH 06-Nov-2007		O/C			
341004 RIGHT	PITOT PROBE *CF 9912678-1	0851LN 254104	MTH 06-Nov-2007		O/C			
342001 STANDBY	ALTIMETER MCO S3100-465	162350-1161 174589B	MTH 09-May-2008 HRS 192		O/C	0		
342002 AIRSPEED	INDICATOR *CF	261440-1143 288948A	MTH 06-Nov-2007		O/C			
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE *CF	011-00831-00 46706369	MTH 06-Nov-2007		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE *CF	011-00831-00 46706499	MTH 06-Nov-2007		O/C			
342003	MAGNETIC COMPASS *CF	S2800-821 NSN	MTH 06-Nov-2007		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342004 NO. 1	GDU 1040A DISPLAY	KMKE		011-03470-10 494106161	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
342004 NO. 2	GDU 1040A DISPLAY	KMKE		011-03470-10 494106211	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	*CF		011-00868-10 42006650	MTH 06-Nov-2007		O/C			
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	*CF		011-00868-10 42006656	MTH 06-Nov-2007		O/C			
342006 NO. 1	GMU 44 MAGNETOMETER	*CF		011-00870-00 47508865	MTH 06-Nov-2007		O/C			
342006 NO. 2	GMU 44 MAGNETOMETER	*CF		011-00870-00 47508860	MTH 06-Nov-2007		O/C			
342007	GDU 1500 MFD UNIT	KMKE		011-03472-00 496001917	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513	*CF		4200-21 F06-11421	MTH 06-Nov-2007		O/C			
3420SD	FLIGHT STREAM 510 SOFTWARE SD CARD	KMKE		011-03595-00 NSN	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR FXE			011-00883-20 47202209	MTH 28-Oct-2008 HRS 344		O/C	0		
344002	GARMIN GDL-69A DATA LINK *CF			011-00987-00 47758073	MTH 06-Nov-2007		O/C			
345001	GPS/WAAS/XM ANTENNA *CF			013-00245-00 5011	MTH 06-Nov-2007		O/C			
345002 RIGHT	TRANSPONDER	KMKE		011-03303-00 3EH029192	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
345003 LEFT	TRANSPONDER	MCO		011-00779-21 84805304	MTH 09-Dec-2016 HRS 808.32 LDG 443		O/C	1		
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KMKE			011-04475-00 48V001325	MTH 08-Jun-2021 HRS 951.6 LDG 526		O/C	0 0 0		
345005	ADF RECEIVER	*CF		013-00166-00 2465	MTH 06-Nov-2007		O/C			
345006	ADF ANTENNA	*CF		013-00165-00 3130	MTH 06-Nov-2007		O/C			
345007	MARKER BEACON ANTENNA *CF			MB10-754-2 0068	MTH 06-Nov-2007		O/C			
345008	GLIDE SLOPE ANTENNA *CF			RGS10-48 12282	MTH 06-Nov-2007		O/C			
345009 LEFT	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0448	MTH 06-Nov-2007		O/C			
345009 RIGHT	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0468	MTH 06-Nov-2007		O/C			
345009 UPPER	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0436	MTH 06-Nov-2007		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 0458	MTH 06-Nov-2007		O/C			
345010	VOR/LOC ANTENNA *CF			VT10-767-3 0362	MTH 06-Nov-2007		O/C			
345011	KN63 DME TRANSCEIVER *CF		7	066-01070-0001 31200	MTH 06-Nov-2007		O/C			
345013	RMI CONVERTER *CF			013-00167-00 0678	MTH 06-Nov-2007		O/C			
345014	GPS/WAAS/ ANTENNA *CF			013-00244-00 5075	MTH 06-Nov-2007		O/C			
345015	DME ANTENNA *CF			L10-611-14 0471	MTH 06-Nov-2007		O/C			
346010	TAS PROCESSOR *CF			066-01152-0101 NSN	MTH 06-Nov-2007		O/C			
346011 BOTTOM	TAS ANTENNA *CF			L10-611-14 0455	MTH 06-Nov-2007		O/C			
346011 TOP	TAS ANTENNA *CF			071-01599-0100 19381	MTH 06-Nov-2007		O/C			
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT *CF			011-01105-01 15W005069	MTH 06-Nov-2007		O/C			
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT *CF			011-01105-01 15W005081	MTH 06-Nov-2007		O/C			
350001	OXYGEN BOTTLE SMF			4441073-022 ALT280-8521	MTH 13-May-2022 HRS 1020.7 LDG 574		180	0 0	31-Oct-2036	140 m 27 d
Manufacture Date: 01-Oct-2021										
350002	OXYGEN PRESSURE GAUGE C668512-0101 *CF			MD97-1 E07-10088	MTH 06-Nov-2007		O/C			
351001 LEFT	CREW OXYGEN MASK 9914067-41 SMF			MC10-16-101 SE29580	MTH 13-May-2022 HRS 1020.7 LDG 574		72	4 0 0	31-Jan-2028	35 m 27 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41 UNK			MC10-16-101 122767	MTH 20-Feb-2020 HRS 948.82 LDG 523		72	0	28-Feb-2026	12 m 24 d
361001 LEFT	PRECOOLER 9914402-7 *CF			8315-2 T0085	MTH 06-Nov-2007		O/C			
361001 RIGHT	PRECOOLER 9914402-7 *CF			8315-2 T0089	MTH 06-Nov-2007		O/C			
361002 LEFT	VARIABLE VENTURI VALVE ASSY CYHM			2601-34 0029A	MTH 26-Nov-2010 HRS 717.9 LDG 390		O/C			
361002 RIGHT	VARIABLE VENTURI VALVE ASSY CYHM			2601-34 0027A	MTH 26-Nov-2010 HRS 717.9 LDG 390		O/C	717.9		
361003	SERVICE AIR REGULATOR ASSY 9912510-2 *CF			1H75-23 7B 040	MTH 06-Nov-2007		O/C			
361004 LEFT	B/A SHUTOFF VALVE *CF			5253-00-1 1756	MTH 06-Nov-2007		O/C			
361004 RIGHT	B/A SHUTOFF VALVE *CF			5253-00-1 1774	MTH 06-Nov-2007		O/C			
361101 R1	DE-ICE VALVE *CF			3D2353-06 N072332	MTH 06-Nov-2007		O/C			
361101 R2	DE-ICE VALVE *CF			3D2353-06 N072335	MTH 06-Nov-2007		O/C			
522001	CABIN DOOR SEAL 9912674-3 ICT			S-22560-3 N/A	MTH 24-Jul-2009 HRS 500		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
522002	ESCAPE HATCH SEAL 9912675-1	*CF		S-22561 062	MTH 06-Nov-2007		O/C			
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-3 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-4 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-11 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-10 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
534101 FWD	ENGINE BEAM	*CF		7012061-3 41	MTH 06-Nov-2007		O/C			
552001 LEFT	ELEVATOR ASSEMBLY	*CF		7034001-7 0000022	MTH 06-Nov-2007		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY	*CF		7034001-8 0000022	MTH 06-Nov-2007		O/C			
553001	VERTICAL STABILIZER ASSY	*CF		7031001-801-7 0000033	MTH 06-Nov-2007		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) 9912745-5	*CF		P03100-5 00123	MTH 06-Nov-2007		O/C			
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-8	*CF		P03100-8 00265	MTH 06-Nov-2007		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1	*CF		93310-1 1171	MTH 06-Nov-2007		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2	*CF		93310-2 1192	MTH 06-Nov-2007		O/C			
562003 L1	CABIN WINDOW 9912747-10	ICT		93320-10 2745	MTH 06-Aug-2009 HRS 509		O/C	0		
562003 L2	CABIN WINDOW 9912747-10	ICT		93320-10 2545	MTH 06-Aug-2009 HRS 509		O/C	0		
562003 L3	CABIN WINDOW 9912747-10	ICT		93320-10 2754	MTH 06-Aug-2009 HRS 509		O/C	0		
562003 R1	CABIN WINDOW 9912747-10	ICT		93320-10 2543	MTH 06-Aug-2009 HRS 509		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10	ICT		93320-10 2743	MTH 06-Aug-2009 HRS 509		O/C	0		
562003 R3	CABIN WINDOW 9912747-10	ICT		93320-10 2746	MTH 06-Aug-2009 HRS 509		O/C	0		
572001 LEFT WING	FWD SPAR	*CF		7022022-1 45486	MTH 06-Nov-2007		O/C			
572001 RIGHT WING	FWD SPAR	*CF		7022022-2 45481	MTH 06-Nov-2007		O/C			
572002 LEFT WING	REAR SPAR	*CF		7022032-3 45490	MTH 06-Nov-2007		O/C			
572002 RIGHT WING	REAR SPAR	*CF		7022032-4 45441	MTH 06-Nov-2007		O/C			
572003 LEFT WING	MAIN SPAR	*CF		7022027-1 -	MTH 06-Nov-2007		O/C			
572003 RIGHT WING	MAIN SPAR	*CF		7022027-2 -	MTH 06-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-5 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-6 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-9 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-10 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-5 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-6 NSN	MTH 06-Nov-2007 LDG 0		20000	0	20000	19292
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1			7051001-1 41	MTH 06-Nov-2007		O/C			
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0153	MTH 06-Nov-2007 HRS 0		4000	0	4000	2770
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0164	MTH 06-Nov-2007 HRS 0		4000	0	4000	2770
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF			7051001-2 57	MTH 06-Nov-2007		O/C			
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0125	MTH 06-Nov-2007 HRS 0		4000	0	4000	2770
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0173	MTH 06-Nov-2007 HRS 0		4000	0	4000	2770
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1662	MTH 06-Nov-2007 HRS 0		8000	0	8000	6770
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1695	MTH 06-Nov-2007 HRS 0		8000	0	8000	6770
712003 AFT	ENGINE BEAM *CF			7012066-2 41	MTH 06-Nov-2007		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL *CF			7051001-3 48	MTH 06-Nov-2007		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL *CF			7051001-4 63	MTH 06-Nov-2007		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE *CF			35C0510-01 PCE-LB0091	MTH 06-Nov-2007		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE *CF			35C0510-01 PCE-LB0088	MTH 06-Nov-2007		E/C			
720010 E1	FAN ROTOR *CF			35C1940-01 TXA1B3068	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
720010 E2	FAN ROTOR *CF			35C1940-01 TXA1B2461	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
721010 E1	HP TURBINE DISK *CF			35C2311-01 A0026EWA	MTH 06-Nov-2007 LDG 0 ACCC YC		5250	0	(5250)5250	4542 4542
721010 E2	HP TURBINE DISK *CF			35C2311-01 A0025LN7	MTH 06-Nov-2007 LDG 0 ACCC YC		5250	0	(5250)5250	4542 4542
721020 E1	LP TURBINE DISK *CF			35C2372-01 A0027212	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
721020 E2	LP TURBINE DISK *CF			35C2372-01 A0027CLT	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
723010 E1	IMPELLER AND SHAFT ASSEMBLY *CF			35C4419-01 A0027144	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
723010 E2	IMPELLER AND SHAFT ASSEMBLY *CF			35C4419-01 A0027146	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
725010 E1	HP COMPRESSOR ROTOR *CF			35C3661-01 TXA1B3081	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
725010 E2	HP COMPRESSOR ROTOR *CF			35C3661-01 TXA1B3090	MTH 06-Nov-2007 LDG 0 ACCC YC		10500	0	(10500)10500	9792 9792
726010 E1	AGB STARTER MAGNETIC SEAL			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750	0	(1750)1750	520
726010 E2	AGB STARTER MAGNETIC SEAL			PN SN-UNKNOWN	MTH 06-Nov-2007 HRS 0		1750	0	(1750)1750	520
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 7769	MTH 06-Nov-2007		O/C			
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 7507	MTH 06-Nov-2007		O/C			
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 *CF			TFF1573-4 0709-005	MTH 06-Nov-2007		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1 *CF			TFF1573-4 0718-019	MTH 06-Nov-2007		O/C			
732101 E1	FUEL METERING UNIT (F.M.U.) *CF			35C0794-03 15245135	MTH 06-Nov-2007		H/T H/T			
732101 E2	FUEL METERING UNIT (F.M.U.) *CF			35C0794-03 15191285	MTH 06-Nov-2007		H/T H/T			
741001 E1	IGNITION EXCITER *CF			35C3895-01 15012112	MTH 06-Nov-2007		O/C			
741001 E2	IGNITION EXCITER *CF			35C3895-01 15276066	MTH 06-Nov-2007		O/C			
741002 E1 LEFT	IGNITER CABLE *CF			35C0844-01 NSN	MTH 06-Nov-2007		O/C			
741002 E2 LEFT	IGNITER CABLE *CF			35C0844-01 NSN	MTH 06-Nov-2007		O/C			
741003 E1 RIGHT	IGNITER CABLE *CF			35C0799-01 WDA100781	MTH 06-Nov-2007		O/C			
741003 E2 RIGHT	IGNITER CABLE *CF			35C0799-01 WDA100887	MTH 06-Nov-2007		O/C			
741004 E1 INBOARD	SPARK IGNITER *CF			35C2353-01 NSN	MTH 06-Nov-2007		O/C			
741004 E2 INBOARD	SPARK IGNITER *CF			35C2353-01 NSN	MTH 06-Nov-2007		O/C			
741005 E1 OUTBOARD	SPARK IGNITER *CF			35C2353-01 NSN	MTH 06-Nov-2007		O/C			
741005 E2 OUTBOARD	SPARK IGNITER *CF			35C2353-01 NSN	MTH 06-Nov-2007		O/C			
751003 E1	BLEED VALVE ACTUATOR *CF			35C2851-01 15277364	MTH 06-Nov-2007		H/T H/T			
751003 E2	BLEED VALVE ACTUATOR *CF			35C2851-01 15263852	MTH 06-Nov-2007		H/T H/T			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
761001 E1	FADEC 9912637-2	*CF	35C4035-03 07-232	MTH 06-Nov-2007		O/C			
761001 E2	FADEC 9912637-2	*CF	35C4035-03 07-246	MTH 06-Nov-2007		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.) *CF		35C3778-01 WA24700	MTH 06-Nov-2007		H/T H/T			
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.) *CF		35C3778-01 WA28960	MTH 06-Nov-2007		H/T H/T			
793001 E1	OIL TEMP SENSOR *CF		102-00083 06110	MTH 06-Nov-2007		O/C			
793001 E2	OIL TEMP SENSOR *CF		102-00083 05684	MTH 06-Nov-2007		O/C			
793002 E1	OIL PRESSURE TRANSMITER *CF		APTE-304A-250G 7390-10-310	MTH 06-Nov-2007		O/C			
793002 E2	OIL PRESSURE TRANSMITER *CF		APTE-304A-250G 7390-10-101	MTH 06-Nov-2007		O/C			
793010 E1	CHIP COLLECTOR		PN SN-UNKNOWN	MTH 06-Nov-2007		O/C	0		
793010 E2	CHIP COLLECTOR		PN SN-UNKNOWN	MTH 06-Nov-2007		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1		MG94E-1 398D	MTH 20-Jan-2017 HRS 811.57 LDG 445		1500	1 0	2311.57	1081.57
801000 RIGHT	STARTER GENERATOR 9912676-1		MG94E-1 428D	MTH 20-Jan-2017 HRS 811.57 LDG 445		1500	1 0	2311.57	1081.57



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)									
	INFORMATIONAL									
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
	RECOMMENDED									
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)									
	RECOMMENDED									
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
	INFORMATIONAL									
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)									
	INFORMATIONAL									
	MOC :									
SL 510-99-03 99SL-03	TUBE ASSEMBLY SLEEVE INSPECTION	RECOMMENDED	MTH 09-May-2008				A/R		Complete	
	MCO		HRS 192							
	MOC : COMPLIED WITH									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS									
	INFORMATIONAL									
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION									
	INFORMATIONAL									
	MOC :									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)									
	INFORMATIONAL									
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS									
	INFORMATIONAL									
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)									
	INFORMATIONAL									
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
			MTH				-			
	RECOMMENDED									
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)									
	INFORMATIONAL									
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									
	INFORMATIONAL									
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)									
	INFORMATIONAL									
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)									
	INFORMATIONAL									
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									
	INFORMATIONAL									
	MOC :									
SL 510-21-01 21SL-01	COMPRESSOR ISOLATOR MOUNT INSPECTION	RECOMMENDED	MTH 21-Oct-2008				A/R		Complete	
	MCO		HRS 341							
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0061 THRU -0181.									
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT	UNK		RECOMMENDED	MTH 30-Oct-2019 HRS 948.6 LDG 522		-			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER.									
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT	UNK		OPTIONAL	MTH 07-Feb-2020 HRS 948.82 LDG 523		-			Complete
	MOC : COMPLIED WITH - C/W FAN REPLACED I.A.W SL & SB INSTRUCTIONS KIT P/N: K1134608-3									
ASL 510-22-01 22ASL01	AUTOPILOT SERVO GUARD PIN INSPECTION	MCO		MANDATORY	MTH 21-Oct-2008 HRS 341		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT			OPTIONAL			A/R			
	MOC :									
SL 510-24-03 24SL-03	CREW ALERTING SYSTEM (CAS) ELECTRICAL WIRING INSPECTION	MCO		MANDATORY	MTH 21-Oct-2008 HRS 341		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-24-06 24SL-06	FUSE LIMITER INSPECTION	MCO		MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-24-06 BY INSPECTING THE AFT POWER J BOX FOR INCCORECT FUSE LIMITERS IAW SERVICE LETTER INSTRUCTIONS.									
SL 510-24-08 24SL-08	STARTER/GENERATOR INSPECTION (SUPERSEDED BY SL510-24-08 REV 01)	MCO		MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-24-08 BY REPLACING THE STARTER GENERATORS IAW SERVICE LETTER INSTRUCTIONS.									
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.									
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER -									
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)			MANDATORY			A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.									
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.									
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION	CYHM		MANDATORY	MTH 30-Nov-2011 HRS 754.1 LDG 408		A/R			Complete
	MOC : COMPLIED WITH - SL510-24-13 ELECTRICAL POWER THROTTLE QUADRANT WIRE BUNDLE INSPECTION C/O WITH NO FAULTS FOUND.									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION MANDATORY		DAYS 07-Nov-2016 HRS 798.1 LDG 437		-			N/A
	MOC : NOT APPLICABLE - DATE NOT IN AFFECTED RANGE							
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT OPTIONAL				A/R			
	MOC :							
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER DISCRETIONARY				A/R			
	MOC :							
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS OPTIONAL				-			
	MOC :							
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION ICT MANDATORY		DAYS 03-Jul-2010 HRS 644.9 LDG 356		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL510-25-02 CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION, ORIGINAL ISSUE DATED MAY 12, 2010.							
SB 510-27-01 27SB-01	AILERON SHIELD SEALANT REVISION MCO	MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-27-01 BY FILLET SEALING BETWEEN THE AILERON COVER AND THE LOWER SKIN ASSEMBLY IAW SERVICE BULLETIN INSTRUCTIONS.							
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION RECOMMENDED				-			
	MOC :							
SL 510-27-01 27SL-01	FLAP ACTUATOR INSTALLATION SETSCREW INSPECTION MCO RECOMMENDED		MTH 09-May-2008 HRS 192		A/R			Complete
	MOC : COMPLIED WITH							
SL 510-27-02 27SL-02	CONTROL YOKE ASSEMBLY TIE STRAP INSPECTION MCO MANDATORY		MTH 21-Oct-2008 HRS 341		A/R			Complete
	MOC : COMPLIED WITH							
SL 510-27-05 27SL-05	FLAP ACTUATOR INSPECTION YHM	MANDATORY	MTH 11-Dec-2009 HRS 588		-			Complete
	MOC : COMPLIED WITH							
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL				-			
	MOC :							
SL 510-28-01 28SL-01	LEFT AND RIGHT FUEL PROBE WIRE BUNDLE ASSEMBLY INSPECTION MCO MANDATORY		MTH 12-May-2009 HRS 459		A/R			Complete
	MOC : COMPLIED WITH							
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT DISCRETIONARY				-			
	MOC :							
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT DISCRETIONARY				A/R			
	MOC :							
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01) DISCRETIONARY				A/R			
	MOC :							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT			MANDATORY MTH			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.										
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	CYHM		MANDATORY MTH	05-Mar-2013		-			Complete
HRS 754.1 LDG 408										
MOC : COMPLIED WITH										
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT			RECOMMENDED MTH			-			
MOC :										
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)			RECOMMENDED MTH			-			
MOC :										
ASL 510-30-02 30ASL02	WATER SEPARATOR DRAIN CAP	MCO		MANDATORY MTH	09-May-2008		A/R			Complete
HRS 192										
MOC : COMPLIED WITH										
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)			INFORMATIONAL			A/R			
MOC :										
SB 510-31-01 31SB-01	MASTER CAUTION WARNING LIGHT WIRING MODIFICATION	MCO		DISCRETIONARY MTH	21-Oct-2008		A/R			Complete
HRS 341										
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION			MANDATORY MTH			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
MOC :										
SL 510-32-02 REV 01 32SL-02 : 510R1	EMERGENCY GEAR RELEASE INSPECTION	MCO		MANDATORY MTH	20-Mar-2010		A/R			Complete
HRS 611.5 LDG 342										
MOC : COMPLIED WITH - COMPLIED WITH SL510-32-02R1 BY PERFORMING AN EMERGENCY GEAR RELEASE FUNCTIONAL CHECK IAW SERVICE LETTER INSTRUCTIONS										
SL 510-32-03 32SL-03	RIGHT BRAKE STOP BRACKET INSPECTION	MCO		MANDATORY MTH	20-Mar-2010		A/R			Complete
HRS 611.5 LDG 342										
MOC : COMPLIED WITH - COMPLIED WITH BY SL510-32-03 INSPECTING THE 7017151-35 BRAKE STOP SUPPORT BRACKET FOR THE CORRECT FASTENERS IAW SERVICE LETTER INSTRUCTIONS										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-32-04	NOSE LANDING GEAR (NLG) UPLOCK BRACKET CORROSION REPAIR			INFORMATIONAL			A/R			
	MOC :									
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	CYHM		RECOMMENDED	MTH 10-May-2012 HRS 754.1 LDG 408		-			Complete
	MOC :	COMPLIED WITH								
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION			MANDATORY	DAYS 02-May-2017 HRS 831.2 LDG 455		-			N/A
	MOC :	NOT APPLICABLE - BRAKES CURRENTLY INSTALLED ARE NOT AFFECTED BY SERVICE LETTER								
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	KMCO		MANDATORY	DAYS 07-Aug-2017 HRS 879.33 LDG 477		-			Complete
	MOC :	COMPLIED WITH - COMPLIED WITH SL510-32-08 BY VISUAL INSPECTION OF BRAKE SERIAL NUMBERS AND FOUND INSTALLED BRAKES NOT AFFECTED IAW SL INSTRUCTIONS.								
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL			-			
	MOC :									
SB 510-34-02 34SB-02	HARDWARE AND SOFTWARE UPDATE FOR GARMIN G1000 AVIONICS	MCO		MANDATORY	MTH 21-Oct-2008 HRS 341		A/R			Complete
	MOC :	COMPLIED WITH								
SB 510-34-09 34SB-09	GARMIN G1000 SOFTWARE VERSION 010-00435-16 UPGRADE	MCO		RECOMMENDED	MTH 12-May-2009 HRS 459		A/R			Complete
	MOC :	COMPLIED WITH								
SB 510-34-10 34SB-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	ICT		OPTIONAL	MTH 24-Jul-2009 HRS 500		A/R			Complete
	MOC :	COMPLIED WITH								
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	CYHM		MANDATORY	MTH 05-Mar-2013 HRS 754.1 LDG 408		A/R			Complete
	MOC :	COMPLIED WITH								
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01)			MANDATORY	MTH		A/R			
	MOC :									
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	CYHM		MANDATORY	MTH 05-Mar-2013 HRS 754.1 LDG 408		-			Complete
	MOC :	COMPLIED WITH								
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)			MANDATORY	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	CYHM	MANDATORY	MTH 05-Mar-2013 HRS 754.1 LDG 408		-				Complete
MOC : COMPLIED WITH										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 Ahrs SOFTWARE UPDATE		MANDATORY	MTH 02-May-2017 HRS 831.2 LDG 455		-				Complete
MOC : COMPLIED WITH - BY INCORPORATION OF SB510-34-17										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)	MCO	OPTIONAL	MTH 09-Dec-2016 HRS 808.32 LDG 443		-				Complete
MOC : COMPLIED WITH										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)		OPTIONAL			-				
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE		OPTIONAL			-				
MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE	UNK	RECOMMENDED	MTH 19-Mar-2019 HRS 937.3 LDG 514		-				Complete
MOC : COMPLIED WITH - SB510-34-18 GARMIN G1000 ADS-B OUT SOFTWARE UPDATE CARRIED OUT. SOFTWARE INSTALLED USING SD CARD P/N: 010-00435-30.										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE		INFORMATIONAL			-				
MOC :										
SL 510-34-03 34SL-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING	MCO	INFORMATIONAL	MTH 21-Oct-2008 HRS 341			A/R			Complete
MOC : COMPLIED WITH										
SL 510-34-04 34SL-04	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0816	MCO	MANDATORY	MTH 02-Dec-2008 HRS 393			A/R			Complete
MOC : COMPLIED WITH										
SL 510-34-09 34SL-09	GROUNDING STRIP INSPECTION	MCO	MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342			A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-34-09 BY INSTALLING A GROUNDING STRIP ON MFD INSTRUMENT PANEL STRUCTURE IAW SERVICE LETTER INSTRUCTIONS.										
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A		INFORMATIONAL				A/R			
MOC :										
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	CYHM	RECOMMENDED	MTH 26-Aug-2011 HRS 754.1 LDG 408			A/R			Complete
MOC : COMPLIED WITH - INSTALLED AND TESTED IAW CESSNA MUSTANG 34-40-00 FOLLOWING COMPLETION OF SERVICE BULLETIN UPDATE. ALL SYSTEM TESTS AND CHECKS WERE NORMAL.										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE INFORMATIONAL				A/R			
MOC :								
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE INFORMATIONAL				A/R			
MOC :								
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA UNK INFORMATIONAL		MTH 19-Mar-2019 HRS 937.47 LDG 514		A/R			Complete
MOC : COMPLIED WITH - PREVIOUSLY C/W ON MARCH 19, 2019 @ 937:28 HRS, 514 CYCLES.								
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS INFORMATIONAL				A/R			
MOC :								
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS INFORMATIONAL				A/R			
MOC :								
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION INFORMATIONAL				-			
MOC :								
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL INFORMATIONAL				-			
MOC :								
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT UNK RECOMMENDED		MTH 23-Jun-2017 HRS 850.72 LDG 465		-			Complete
MOC : COMPLIED WITH - C/W								
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS INFORMATIONAL				-			
MOC :								
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM) INFORMATIONAL				-			
MOC :								
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG INFORMATIONAL				-			
MOC :								
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS) INFORMATIONAL				-			
MOC :								
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 MANDATORY		MTH 04-Feb-2016 DAYS 754.1 HRS 408 LDG		-			N/A
MOC : NOT APPLICABLE - OXYGEN MASK N/A BY PART NUMBER								
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02) MANDATORY				-			
MOC :								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
	MOC :									
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	CYHM		MANDATORY	MTH 30-Nov-2011 HRS 754.1 LDG 408		-			Complete
	MOC : COMPLIED WITH - SL510-35-01 INSPECTION OF O2 HARNESS ASSY C/O. HARNESS SERIAL NUMBERS WERE FOUND TO BE BEFORE EFFECTIVE SERIAL NUMBERS.									
SB 510-52-03 52SB-03	NOSE BAGGAGE DOOR HINGE IMPROVEMENT	MCO		RECOMMENDED	MTH 09-May-2008 HRS 192		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY			A/R			
	MOC :									
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	UNK		MANDATORY	DAYS 20-Feb-2020 HRS 948.82 LDG 523		-			Complete
	MOC : COMPLIED WITH - C/W HARDWARE REPLACED IAW SB510-52-06 INSTRUCTIONS KIT P/N: SB510-52-06.									
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION	MCO		MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-52-01R1 BY INSPECTING THE CABIN DOOR HINGE FOR MISSING FASTENERS IAW SERVICE LETTER INSPECTIONS.									
SL 510-52-01 52SL-01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION (SUPERSEDED BY SL510-52-01 REV 01)	MCO		MANDATORY	MTH 12-May-2009 HRS 459		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-52-03 52SL-03	DOOR FRAME CORNER FASTENER INSPECTION	MCO		MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-52-03 BY INSPECTING DOOR FRAME FASTENERS FOR PROPER INSTALLATION IAW SERVICE LETTER INSTRUCTIONS									
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
	MOC :									
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT	UNK		MANDATORY	DAYS 07-Feb-2020 HRS 948.82 LDG 523		-			Complete
	MOC : COMPLIED WITH - C/W HARDWARE REPLACED IAW SL & SB INSTRUCTIONS KIT P/N: SB510-52-06.									
SB 510-53-01 53SB-01	AFT CABIN STRUCTURE INSPECTION	MCO		MANDATORY	DAYS 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-53-01 AFT CABIN STRUCTURE INSPECTION BY INSPECTING FOR A NON-SHEAR CONDITION IN THE AFT CABIN SEAT STRUCTURE IAW SERVICE BULLETIN INSTRUCTIONS.									
ASL 510-53-02 53ASL02	TAILCONE SEALANT INSPECTION (SUPERSEDED BY ASL510-53-02 REV 01)	MCO		MANDATORY	MTH 21-Oct-2008 HRS 341		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-53-01 53SL-01	FORWARD PRESSURE BULKHEAD INSPECTION	MCO		RECOMMENDED	MTH 09-May-2008 HRS 192		A/R			Complete
MOC : COMPLIED WITH										
SL 510-53-03	FUSELAGE - DRAIN HOLE INSPECTION	ICT		MANDATORY	MTH 03-Jul-2010 HRS 644.9 LDG 356		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-53-03 DRAIN HOLE INSPECTION, ORIGINAL ISSUE DATED MAY 5, 2010.										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS			DISCRETIONARY			-			
MOC :										
ASL 510-54-01 54ASL01	PYLON RAM AIR DUCT VISUAL INSPECTION	MCO		MANDATORY	MTH 09-May-2008 HRS 192		A/R			Complete
MOC : COMPLIED WITH										
SL 510-55-01 55SL-01	HORIZONTAL STABILIZER RIB INSPECTION	MCO		MANDATORY	MTH 12-May-2009 HRS 459		A/R			Complete
MOC : COMPLIED WITH										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)	CYHM		MANDATORY	DAYS 11-Jul-2011 HRS 754.1 LDG 408		A/R			Complete
MOC : COMPLIED WITH										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)			MANDATORY			A/R			
MOC :										
SB 510-56-02 56SB-02	CABIN WINDOW FROST PANE MODIFICATION	ICT		DISCRETIONARY	MTH 06-Aug-2009 HRS 509		A/R			Complete
MOC : COMPLIED WITH										
SL 510-56-01 56SL-01	WINDSHIELD WIRE BUNDLE ASSEMBLY INSPECTION	MCO		MANDATORY	MTH 12-May-2009 HRS 459		A/R			Complete
MOC : COMPLIED WITH										
SL 510-57-01 57SL-01	FLAP HINGE INSPECTION (SUPERSEDED BY SL510-57-01 REV 01)	ICT		MANDATORY	MTH 24-Jul-2009 HRS 500		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 17-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 14-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 17-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72- 63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 14-Aug-2007		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5			MTH	14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9			MTH	14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6			MTH	14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH	17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER	*CF		CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH		-			
MOC :										
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH		-			
MOC :										
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)			CATEGORY 8	MTH 17-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)			CATEGORY 8	MTH 14-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY	*CF		CATEGORY 5	MTH		-			
MOC :										
SB PW600-72-63028 R01 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 5	MTH		-			
MOC :										
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)			CATEGORY 7	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH		-			
	MOC :									
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH		-			
	MOC :									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63037 R01 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63043 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02)			CATEGORY 6	MTH		-			
	MOC :									
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY CATEGORY 6						-			
MOC :										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7 MTH						-			
MOC :										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7 MTH						-			
MOC :										
SB PW600-72-63051 R01 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02) CATEGORY 7 MTH						-			
MOC :										
SB PW600-72-63051 R02 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03) CATEGORY 6						-			
MOC :										
SB PW600-72-63051 R02 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03) CATEGORY 6						-			
MOC :										
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6						-			
MOC :										
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6						-			
MOC :										
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7 A/R									
MOC :										
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7 A/R									
MOC :										
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) CATEGORY 7 MTH						-			
MOC :										
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
MOC :										
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7 MTH			-			
	MOC :									
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7 MTH			-			
	MOC :									
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63059 R01 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63059 R01 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6 MTH			-			
	MOC :									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7 MTH			-			
	MOC :									
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH		-			
	MOC :									
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH		A/R			
	MOC :									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6				-			
MOC :								
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6				A/R			
MOC :								
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6				A/R			
MOC :								
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6				-			
MOC :								
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6				-			
MOC :								
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6				A/R			
MOC :								
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6				A/R			
MOC :								
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7				A/R			
MOC :								
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7				A/R			
MOC :								
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6				-			
MOC :								
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6				-			
MOC :								
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5				A/R			
MOC :								
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5				A/R			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5			A/R			
MOC :										
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5			A/R			
MOC :										
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	CYHM		CATEGORY 3	MTH 05-Mar-2013 HRS 754.1 LDG 408		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	CYHM		CATEGORY 3	MTH 05-Mar-2013 HRS 754.1 LDG 408		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7			-			
	MOC :									
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7			-			
	MOC :									
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3	MTH		HSI			
	MOC :						HSI			
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3	MTH		HSI			
	MOC :						HSI			
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			RECOMMENDED	MTH		-			
	MOC :									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			RECOMMENDED	MTH		-			
	MOC :									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5			-			
	MOC :									
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5			-			
	MOC :									
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE			CATEGORY 5			-			
	MOC :									
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE			CATEGORY 5			-			
	MOC :									
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	CYKF		CATEGORY 3	MTH 04-Dec-2018 HRS 935.5 LDG 512		-			N/A
	MOC :									
	NOT APPLICABLE - N/A DUE TO FOHE S/N. NO IN AFFECTED LIST.									
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	CYKF		CATEGORY 3	MTH 04-Dec-2018 HRS 935.5 LDG 512		-			N/A
	MOC :									
	NOT APPLICABLE - N/A DUE TO FOHE S/N. NO IN AFFECTED LIST.									
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KTRM		CATEGORY 3	MTH 21-Oct-2021 HRS 967.4 LDG 547		-			N/A
	MOC :									
	NOT APPLICABLE - DUE TO SB63062 NOT PREVIOUSLY COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KTRM		MTH 21-Oct-2021 HRS 967.4 LDG 547			-			N/A
MOC : NOT APPLICABLE - DUE TO SB63062 NOT PREVIOUSLY COMPLIED WITH										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)	MCO		CATEGORY 3	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW600-72- A63071R1 BY REPLACING THE FUEL OIL HEAT EXCHANGER FILTER BYPASS VALVE IAW SERVICE BULLETIN INSTRUCTIONS.										
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)	MCO		CATEGORY 3	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW600-72- A63071R1 BY REPLACING THE FUEL OIL HEAT EXCHANGER FILTER BYPASS VALVE IAW SERVICE BULLETIN INSTRUCTIONS										
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
MOC :										
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
MOC :										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
MOC :										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 510-73-01 LEFT 73ASL01 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	MANDATORY			A/R			
MOC :								
ASL 510-73-01 RIGHT 73ASL01 : R	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	MANDATORY			-			
MOC :								
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	MCO MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL510-73-02 BY ACCOMPLISHING PW600-72- A63071R1 REPLACING THE FUEL OIL HEAT EXCHANGER FILTER BYPASS VALVE IAW ALERT SERVICE LETTER INSTRUCTIONS.								
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	MCO MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL510-73-02 BY ACCOMPLISHING PW600-72- A63071R1 REPLACING THE FUEL OIL HEAT EXCHANGER FILTER BYPASS VALVE IAW ALERT SERVICE LETTER INSTRUCTIONS.								
SB PW600-72- 63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE	CATEGORY 6			A/R			
MOC :								
SB PW600-72- 63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE	CATEGORY 6			A/R			
MOC :								
SB PW600-72- 63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)	CATEGORY 7			A/R			
MOC :								
SB PW600-72- 63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)	CATEGORY 7			A/R			
MOC :								
SB PW600-72- 63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY	CATEGORY 7			A/R			
MOC :								
SB PW600-72- 63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY	CATEGORY 7			A/R			
MOC :								
SB PW600-72- 63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)	CATEGORY 6			A/R			
MOC :								
SB PW600-72- 63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)	CATEGORY 6			A/R			
MOC :								
SB PW600-72- 63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)	CATEGORY 6			A/R			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
SB PW600-72-63082 E2	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3			A/R			
	MOC :									
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3			A/R			
	MOC :									
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3			A/R			
	MOC :									
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3			A/R			
	MOC :									
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)			CATEGORY 3			-			
	MOC :									
ASB PW600-72-A63069 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)			CATEGORY 3	MTH		A/R			
	MOC :									
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 8	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 8	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	17-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	14-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	17-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	14-Aug-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8			MTH			-			
MOC :										
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8			MTH			-			
MOC :										
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6	MTH		-			
MOC :										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7	MTH		-			
MOC :										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087	CYHM		MANDATORY	MTH 05-Mar-2013 HRS 754.1 LDG 408		-			Complete
MOC : COMPLIED WITH										
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH		-			
MOC :										
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL			-			
MOC :										
SL 510-79-01 79SL-01	OIL PRESSURE TRANSMITTER INSPECTION	MCO		MANDATORY	MTH 20-Mar-2010 HRS 611.5 LDG 342		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-79-01 BY VERIFYING THAT THE OIL PRESSURE TRANSMITTERS INSTALLED ON THIS AIRCRAFT DO NOT FALL WITH IN THE SERIAL NUMBER RANGE CALLED OUT IAW SERVICE LETTER INSTRUCTIONS										
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION	CYHM		MANDATORY	DAYS 11-Jul-2011 HRS 754.1 LDG 408		A/R			Complete
MOC : COMPLIED WITH										
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
MOC :										
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
MOC :										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB PW600-72- 63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72- 63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-72- 63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-79- 63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 17-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 14-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79- 63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79- 63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79- 63047 R01 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02)			CATEGORY 3	MTH		-			
	MOC :									
SB PW600-79- 63047 R02 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03)			CATEGORY 3	MTH		-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63047 R03 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS	KMKE		CATEGORY 3	MTH 04-May-2021 HRS 951.5 LDG 526		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 1 ENGINE PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-79-63047 REV 3 DATED 10 JUL 2018 TURBOFAN ENGINE AIR-COOLED OIL-COOLER PRESSURE OIL TUBE BOLTS REPLACEMENT OF.										
SB PW600-79-63047 R03 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS	KMKE		CATEGORY 3	MTH 04-May-2021 HRS 951.5 LDG 526		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 2 ENGINE PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-79-63047 REV 3 DATED 10 JUL 2018 TURBOFAN ENGINE AIR-COOLED OIL-COOLER PRESSURE OIL TUBE BOLTS REPLACEMENT OF.										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM	UNK		RECOMMENDED	MTH 20-Jan-2017 HRS 811.95 LDG 445		-			Complete
MOC : COMPLIED WITH - STARTERS R&R WITH OVERHAULED UNITS MOD 'B' UNITS REMOVED, MOD 'D' UNITS INSTALLED. C/W ON JAN. 20, 2017@ 811:57 HRS, 445 CYCLES										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
TCOA CF-2013-25	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES	CYHM		MANDATORY	DAYS 18-Feb-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY P/N										
EASA 2013-0020 R04 (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	CYHM		MANDATORY	MTH 19-Sep-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD N/A AS ALL SEAT BELTS ARE ORIGINAL AND HAVE NOT BEEN REPAIRED										
EASA 2013-0020 R04 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	CYHM		MANDATORY	MTH 19-Sep-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD N/A AS ALL SEAT BELTS ARE ORIGINAL AND HAVE NOT BEEN REPAIRED										
EASA 2013-0020 R04 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	CYHM		MANDATORY	MTH 19-Sep-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD N/A AS ALL SEAT BELTS ARE ORIGINAL AND HAVE NOT BEEN REPAIRED										
EASA 2013-0020 R04 (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD	CYHM		MANDATORY	MTH 19-Sep-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD N/A AS ALL SEAT BELTS ARE ORIGINAL AND HAVE NOT BEEN REPAIRED										
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	CYHM		MANDATORY	MTH 19-Sep-2014 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD N/A AS ALL SEAT BELTS ARE ORIGINAL AND HAVE NOT BEEN REPAIRED										
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS			MANDATORY			-			
MOC :										
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.			MANDATORY			-			
MOC :										
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.			MANDATORY			-			
MOC :										
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).			MANDATORY			-			
MOC :										
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / REPLACEMENT			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	UNK		MTH	08-Dec-2017		-			N/A
				HRS	891.48					
				LDG	484					
	MOC : NOT APPLICABLE - THIS TYPE OF ELT NOT INSTALLED									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	UNK		MANDATORY	MTH	08-Dec-2017	-			N/A
					HRS	891.48				
					LDG	484				
	MOC : NOT APPLICABLE - THIS TYPE OF ELT NOT INSTALLED									
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	UNK		MANDATORY	MTH	08-Dec-2017	-			N/A
					HRS	891.48				
					LDG	484				
	MOC : NOT APPLICABLE - THIS TYPE OF ELT NOT INSTALLED									
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
	MOC :									
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
	MOC :									
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
	MOC :									
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
	MOC :									
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		6		07-Sep-2025	New Req
	MOC :									
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		12		07-Mar-2026	New Req
	MOC :									
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
	MOC :									
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
	MOC :									
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART			MANDATORY	MTH	04-Feb-2016	-			N/A
					HRS	754.1				
					LDG	408				
	MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2	MANDATORY	MTH 04-Feb-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3	MANDATORY	MTH 04-Feb-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1	MANDATORY	MTH 04-Feb-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'	MANDATORY	MTH 04-Feb-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0024	FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	MANDATORY	MTH 04-Feb-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1	MANDATORY	MTH 18-May-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED ON AIRCRAFT								
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).	MANDATORY	MTH 18-May-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED ON AIRCRAFT								
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N	MANDATORY	MTH 18-May-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED ON AIRCRAFT								



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL			MANDATORY	MTH 18-May-2016 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED ON AIRCRAFT										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS			MANDATORY			-			
MOC :										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	UNK		MANDATORY	DAYS 26-Jun-2018 HRS 910.6 LDG 498		-			Complete
MOC : COMPLIED WITH - C/W - PROPER WEAR PINS FOUND INSTALLED AND MARKED WITH YELLOW PAINT I.A.W. S.B. INSTRUCTIONS.										
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)			MANDATORY			-			
MOC :										
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD			MANDATORY			-			
MOC :										
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT			MANDATORY			-			
MOC :										
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD			MANDATORY			-			
MOC :										
EASA 2015-0093	APPLIANCE AD - NAVIGATION & ATTITUDE HEADING REFERENCE SYSTEM & MODIFICATION / REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
MOC :										
EASA 2014-0142 R01 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS	CYHM		MANDATORY	MTH 01-May-2015 HRS 754.1 LDG 408		-			N/A
MOC : NOT APPLICABLE - PART NUMBERS AND SERIAL NUMBERS AFFECTED NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
EASA 2014-0142 R01 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD									
			MANDATORY	MTH	01-May-2015	-				N/A
		CYHM		HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - PART NUMBERS AND SERIAL NUMBERS AFFECTED NOT INSTALLED										
EASA 2014-0142 R01 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD									
			MANDATORY	MTH	01-May-2015	-				N/A
		CYHM		HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - PART NUMBERS AND SERIAL NUMBERS AFFECTED NOT INSTALLED										
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN & OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE & IDENTIFICATION / REPLACEMENT									
		CYHM	MANDATORY	MTH	01-May-2015	-				N/A
				HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - PART NUMBERS AND SERIAL NUMBERS AFFECTED NOT INSTALLED										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12									
			MANDATORY	MTH	21-Jul-2016	-				N/A
				HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - P.B.E. EQUIPMENT NOT INSTALLED ON A/C C-GMMU.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12									
			MANDATORY	MTH	21-Jul-2016	-				N/A
				HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - P.B.E. EQUIPMENT NOT INSTALLED ON A/C C-GMMU.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12									
			MANDATORY	MTH	21-Jul-2016	-				N/A
				HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - P.B.E. EQUIPMENT NOT INSTALLED ON A/C C-GMMU.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12									
			MANDATORY	MTH	21-Jul-2016	-				N/A
				HRS	754.1					
				LDG	408					
MOC : NOT APPLICABLE - P.B.E. EQUIPMENT NOT INSTALLED ON A/C C-GMMU.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
		UNK	MANDATORY	MTH	08-Dec-2017	-				N/A
				HRS	891.48					
				LDG	484					
MOC : NOT APPLICABLE - NO PBE'S INSTALLED ON AIRCRAFT										



CESCOM 10 - Aircraft Status Report

Owner: **SHIKARI EQUIPMENT, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0042**
Unit: **0042** Reg No: **N71G**
Airworthiness: **06-Nov-2007**
Print Date: **04-Feb-2025 11:14AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1230	708	31-Aug-2024	.13
ENG 1	1230	708	31-Aug-2024	.13
ENG 2	1230	708	31-Aug-2024	.13
AIR COND	390.6		31-Aug-2024	1.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	UNK		MANDATORY	MTH 08-Dec-2017 HRS 891.48 LDG 484		-			N/A
MOC : NOT APPLICABLE - NO PBE'S INSTALLED ON AIRCRAFT										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	UNK		MANDATORY	MTH 08-Dec-2017 HRS 891.48 LDG 484		-			N/A
MOC : NOT APPLICABLE - NO PBE'S INSTALLED ON AIRCRAFT										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	UNK		MANDATORY	MTH 08-Dec-2017 HRS 891.48 LDG 484		-			N/A
MOC : NOT APPLICABLE - NO PBE'S INSTALLED ON AIRCRAFT										
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	CYHM		MANDATORY	MTH 24-Aug-2010 HRS 661.9 LDG 364		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY PREVIOUSLY C/W BY CARRYING OUT ASB PW600-72-A63071 R1										
FAA 2010-17-06 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	CYHM		MANDATORY	MTH 24-Aug-2010 HRS 661.9 LDG 364		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY PREVIOUSLY C/W BY CARRYING OUT ASB PW600-72-A63071 R1										