



TIFFIN AIRE INC.

**1778 West State Route 224
Seneca County Airport (16G)
Tiffin, Ohio 44883
1-800-553-PROP (7767)
1-419-447-4263
Fax 419-448-0064
E-mail taiprop@tiffinaire.com**

Propeller Log Book

The subject aircraft was involved in an incident /
accident on 3/9/2025 rendering it a Constructive
Total Loss as not repairable within its insured value.
For further details refer to insurance claim:
2256030424US.

Signed: *Underwriters Salvage Company*

Date: **5/12/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100
Atlanta, GA 30326

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/1/2021	Propeller Log			N4515H
Tach Time: 1381.42 Total Time: 316.88				
SMOH: 316.88 (2/21/2020)				
Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.				
See the AD Compliance Report for a complete listing of AD note compliance and recurring times.				
I certify that I have inspected this propeller in accordance with a 100-hour inspection, and have found it to be in an airworthy condition.				
				
DALE LINDSTROM 1995900AP				
5/1/2023	Propeller Log			N4515H
Tach Time: 1550.48 Total Time: 485.94				
SMOH: 485.94 (2/21/2020)				
Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.				
See the AD Compliance Report for a complete listing of AD note compliance and recurring times.				
I certify that I have inspected this propeller in accordance with a 100-hour inspection, and have found it to be in an airworthy condition.				
				
DALE LINDSTROM 1995900AP				
10/1/2023	Propeller Log			N4515H
Tach Time: 1651.43 Total Time: 586.89				
SMOH: 586.89 (2/21/2020)				
Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.				
See the AD Compliance Report for a complete listing of AD note compliance and recurring times.				
I certify that I have inspected this propeller in accordance with a 100-hour inspection, and have found it to be in an airworthy condition.				
				
DALE LINDSTROM 1995900AP				

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/24/2024	Propeller Log			N4515H
Tach Time: 1749.80 Total Time: 685.26				
SMOH: 685.26 (2/21/2020)				
Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.				
See the AD Compliance Report for a complete listing of AD note compliance and recurring times.				
I certify that I have inspected this propeller in accordance with a 100-hour inspection and have found it to be in an airworthy condition.				
				
DALE LINDSTROM 1995900AP				
10/24/2024	Propeller Log			N4515H
Tach Time: 1847.29 (New tach installed: 00.0) Total Time: 741.2				
SMOH: 741.2 (2/21/2020)				
Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.				
See the AD Compliance Report for a complete listing of AD note compliance and recurring times.				
I certify that I have inspected this propeller in accordance with a 100-hour inspection and have found it to be in an airworthy condition.				
				
DALE LINDSTROM 1995900AP				

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
2/27/2020	0.0		2483.54 TT 1064.54 Tach	Installed on PA15, S/N: 15-288 AP 1995900

5/23/2020

Propeller Log

N4515H

Tach Time: 1082.07 Total Time: 17.53

SMOH: 17.53 (2/21/2020)

Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.

See the AD Compliance Report for a complete listing of AD note compliance and recurring times.

I certify that I have inspected this propeller in accordance with a 100 hour inspection, and have found it to be in an airworthy condition.



DALE LINDSTROM 1995900AP

5/1/2021

Propeller Log

N4515H

Tach Time: 1220.84 Total Time: 156.3

SMOH: 156.3 (2/21/2020)

Inspected i.a.w. the applicable sections of Appendix D of FAR Part 43.

See the AD Compliance Report for a complete listing of AD note compliance and recurring times.

I certify that I have inspected this propeller in accordance with a 100-hour inspection, and have found it to be in an airworthy condition.



DALE LINDSTROM 1995900AP

PROPELLER MAINTENANCE RECORD

Position: Front

Propeller Model: 1B90/CM7147

Propeller S/N: GG035

Blade Design: _____

Blade S/N's: _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather: _____

Start Lock: _____

Low: _____

Reverse: _____

Aircraft Manufacturer Piper

Aircraft Model PA15

S/N: 15/298

Registration: N4515H

Installed on this Aircraft 2/27/2020