

NG795N

3/2000 -



PROPELLER SERVICE, INC.

FAA -PS4R451M

**Burlington - Alamance Regional Airport
Burlington, NC 27215**

**Propeller Logbook
(336) 227-1467
1-800-334-6437**

Reg # N6795N **Interstate Turbine Management** Date 5/13/22
W/O # 22-054 2700 Fort Trenholm Road Tach 7034.1
Model HC-C2YK-1BF Johns Island, SC 29455 SOH 167.5
SN# CH36620B

Propeller: C/W Annual Insp. IAW Mooney M20C Checklist.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.


DATE

 3541816 A&P IA

Model HC-C2YK-1BF **Interstate Turbine Management** Date 6/16/23
S/N CH36620B 2700 Fort Trenholm Rd. Tach 7160.7
Reg # N6795N Johns Island, SC 29455 TSOH 126.6
WO# 23-106

Propeller: C/W Annual Inspection IAW the Mooney International Annual Inspection Guide.


I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

 3541816 A&P IA

Model HC-C2YK-1BF **Interstate Turbine Management** Date 8/8/24
S/N CH36620B 2700 Fort Trenholm Rd. Tach 7269
Reg # N6795N Johns Island, SC 29455 TSOH 402.4
WO# 24-116

Propeller: C/W Annual Inspection IAW the Mooney International Annual Inspection Guide.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

 3541816 A&P IA

WO# 25-139 **Interstate Turbine Management** Date 11/5/25
Reg# N6795N 2700 Fort Trenholm Rd. Tach 7364.4
Model# HC-C2YK-1BF Johns Island, SC 29455 TSOH 497.8
SN# CH36620B PTT 1745.4

Propeller: C/W Annual Inspection IAW ITM's 43 Appendix D Checklist, with Ref to Mooney International Insp Guide. C/W SAIB NE-13-32 Spinner Cracks Insp, no defects. Lubed IAW AMM.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

 3541816 A&P IA


**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
10 Dec 19		Overhauled (1) propeller m/n HC-C2YK-1BF s/n CH36620B c/w s/b 118F, 136I, 374R1, s/l 61-61Y, 348, AD Note (07-26-09). Greased, painted and balanced. Bld. Dwg.# F7666A-2 #1) D42983 #2) D42980. H & H PROPELLER SERVICE, INC. 3439 S. AVIATION DR. BURLINGTON, NC 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	

Model	<u>HC-C2YK-1BF</u>	Interstate Turbine Management	Date	<u>3/24/20</u>
S/N	<u>CH36620B</u>	6070 Perimeter Rd.	Tach	<u>6866.6</u>
Reg #	<u>N6795N</u>	North Charleston, SC 29406	TTAF	<u>6866.6</u>
WO#	<u>4759</u>			

Re-installed Propeller after Overhaul By H&H Propeller Service Ref W.O. # 23702.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

 2822956 A&P IA

Reg #	<u>N6795N</u>	Interstate Turbine Management	Date	<u>4/23/21</u>
W/O #	<u>21-035</u>	2700 Fort Trenholm Road	Tach	<u>6941.2</u>
		Johns Island, SC 29455	SOH	0074.6

Propeller: Prepped/Painted Face & Back.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

 3731415 A&P IA

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 03/01/10
TACH 5893.4
WO# 24220

I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.




CRS# I1BR578Y

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 06/05/13
TACH 6323.1
WO# 25552

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.



CRS# I1BR578Y

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 04/06/11
TACH 6103.8
WO# 24802

I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.




CRS# I1BR578Y

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 07/09/14
TACH 6418.3
WO# 25959

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.



CRS# I1BR578Y

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 05/17/12
TACH 6218.2
WO# 25198

I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.




CRS# I1BR578Y

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 8/11/15
TACH 6485.3
WO# 26378

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.



CRS# I1BR578Y

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
21 JAN 08		Disassembled (D) propeller MIN HC-C2YK-1BF S/N CH36620B installed factory new hub c/w SIB 269, S/L 154, S/T 152A, A.D. Note (06-18-15). Assembled, greased, painted tips and balanced. Bld. Dwg. * F7666A-2 4) D42983 5) D42980	
		H & H PROPELLER SERVICE, INC. 3439 SOUTH AVIATION DRIVE BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	<i>[Signature]</i>

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1/25/08	5619.0	WO# 23132. R+R PROP TO C/W AD 06-18-15 HUB REPLACEMENT	<i>[Signature]</i> CRS.# I1BR5787

Model HC-C2YK-1BF
S/N CH36620B
Reg. # N6795N

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 02/01/09
TACH 5768.9
WO# 23704

C/W Annual insp. IAW FAR 43 appendix D and Mooney M/M. AD 08-13-28 propeller hub lubrication holes is N/A, not left hand turning.

I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

[Signature]

CRS# I1BR578Y