



## HA420 - Basic Empty Weight & Balance Form

This form is to record weighing by <u>Jack up load cells only</u>.

Airplanes 42000011+





Nose Jacking Point Sta = 69.0

Wing Jacking Point Sta = 269.34

Location	Customer Service Center 10/26/2021		Serial #	42000163		Reg #	N103JT
Date			Weighed	by	Jeremy Stut	zman	
Quality Stamp	Reaction Points	Scale Reading	Tare	Net Weight	F-Station	Mom/100	% MAC
HACI QI 70250	Left Main	3,343.3	0.0	3,343.3			
	Right Main	3,291.0	0.0	3,291.0	The later of the l	ASSOCIATION OF	PARTIES N
	Main Total	6,634.3		6,634.3	269.34	17,869	No service
	Nose	522.7	0.0	522.7	69.00	361	Children Washing
As weighed Total (lb)				7,157.0	254.71	18,230	37.69%
Additions/	Subtractions to as	weighted con	dition	lb	F-Sta	Mom/100	0/1446
Additions/Subtractions to as weighted condition Subtract:				10	1-314	10111/100	%MAC
Nose Jack Pad			0.7	69.00	0		
						0	
						0	
						0	
						0	
						0	
						0	
Add:							
Unusable Fuel (Left Wing)			18	258.00	46		
Unusable Fuel (Right Wing)				18	258.00	46	
Unusable Fuel (Center)			4.9	283.76	14		
						0	
						0	
						0	
						0	
						0	
						0	
				VELOCIAL CAMES			