



Status Report

HAWKER 850XP

S/N 258789 N850EC

OWNER: ROCK JET SOLUTIONS, LLC
ADDRESS: 960 PENN AVENUE, SUITE 400
PA 15222

OFFICE:
FAX:

**OPERATOR: AIRCRAFT MANAGEMENT
GROUP INC.**

ADDRESS: PITTSBURGH INT'L AIRPORT -
AIRSIDE BUSINESS PARK
MOON TOWNSHIP PA 15108

OFFICE: 412-889-8894
FAX:

ANALYST: GLEN WATSON
EMAIL: GWATSON@CAMPSYSTEMS.COM

+1-316-462-2438 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT	SERIAL/REGNO: 258789/N850EC	MODEL: HAWKER 850XP	MANUFACTURER: TEXTRON AVIATION INC.
	CERTIFICATION DATE: 29-JUN-2006	LAST ACTUALS: 7660.2 A/C HRS as of 31-JUL-2025 5623 AFL as of 31-JUL-2025 4522 APH as of 31-JUL-2025	
APU	SERIAL/PART: P-913/3800304-1	MODEL: GTCP36-150(W)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 30-AUG-2006	LAST ACTUALS: 4522 APU HRS as of 31-JUL-2025 0 APUS as of 31-JUL-2025	
	0 APU HRS 0 A/C HRS 0 APUS		
ENGINE NO. 1	SERIAL/PART: P-129230/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
	INSTALLED ON: 18-NOV-2019	LAST ACTUALS: 7579.6 ENG. HRS as of 31-JUL-2025 5563 ENC as of 31-JUL-2025	
	4649.2 ENG. HRS 4729.8 A/C HRS 3648 ENC		
ENGINE NO. 2	SERIAL/PART: P-129231/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
	INSTALLED ON: 18-NOV-2019	LAST ACTUALS: 7579.6 ENG. HRS as of 31-JUL-2025 5564 ENC as of 31-JUL-2025	
	4649.2 ENG. HRS 4729.8 A/C HRS 3648 ENC		



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
000001	^U	AIRCRAFT REGISTRATION						Service	ATA:00
	MOS	14-Dec-20	35 (+1m)		31-Oct-27 (M)	30-Nov-27	781 d (+30)		
	HRS	4914.2							
	AFL	3815							
000010	^U	AIRCRAFT PAINT						Service	ATA:00
	MOS/MSC	10-Aug-18	O/C						
	HRS	4113.7							
	AFL	3247							
000015	^U	AIRCRAFT INTERIOR						Service	ATA:00
	MOS/MSC	10-Aug-18	O/C						
	HRS	4113.7							
	AFL	3247							
BCXP-160901		REVIEW HAWKER 750/800XP/850XP/900XP AFMS REVISION 32 DATED SEP.16 REVISION SUMMARY CHANGE FORM						Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF BCXPPROC. REF: RCF BCXP									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050001		INSPECTION PRE-FLIGHT						Service	ATA:05
	MOS/MSC	12-Oct-21	A/R						
	HRS	5511.5							
WC#: 05.T01	AFL	4175							
PROC. REF: AMS 5-20-01, AFMS 05-00-00PROC. REF: AMS 5-20-01, AFMS 05-00-00									
050005		INSPECTION POST FLIGHT						Service	ATA:05
	MOS/MSC	20-Feb-23	A/R						
	HRS	6377.7							
WC#: 05.T02	AFL	4717							
PROC. REF: AFMS 05-00-00, AMS 5-20-02PROC. REF: AFMS 05-00-00, AMS 5-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050110	INSPECTION B1-B12 COMPLETE							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)	Adj -15.9	8363.7	8403.7	703.5 (+40)		
	AFL	5563							
PROC. REF: AMS 5-21-00PROC. REF: AMS 5-21-00									PKG:91
050120	INSPECTION B1							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-01PROC. REF: AMS 5-21-01									PKG:7
050130	INSPECTION B2							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-02PROC. REF: AMS 5-21-02									PKG:8
050140	INSPECTION B3							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-03PROC. REF: AMS 5-21-03									PKG:9
050141 ^S	INSPECT AREA F1-800 HOURS							Service	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.203	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:9,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050150	INSPECTION B4							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-04PROC. REF: AMS 5-21-04									PKG:10
050160 ^S	INSPECTION B5							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	800 (+50)						
	AFL	4989							
PROC. REF: AMS 5-21-05PROC. REF: AMS 5-21-05									PKG:11
050170	INSPECTION B6							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-06PROC. REF: AMS 5-21-06									PKG:12
050171 ^S	INSPECT AREA F3 ABOVE FLOOR-800 HOURS							Service	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.206	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:12,91
050180	INSPECTION B7							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-07PROC. REF: AMS 5-21-07									PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050181	^S	INSPECT AREA F4-800 HOURS							Service ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.207	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:13,91
050190		INSPECTION B8							Package ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -41.6	8338	8388	677.8 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-08PROC. REF: AMS 5-21-08									PKG:14
050191	^S	INSPECT AREA T1-800 HOURS							Service ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.208	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:14,91
050200		INSPECTION B9							Package ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-09PROC. REF: AMS 5-21-09									PKG:15
050201	^S	INSPECT AREA W1-800 HOURS							Service ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.209	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:15,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050210	INSPECTION B10							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-10PROC. REF: AMS 5-21-10									PKG:16
050211 ^S	INSPECT AREA W2-800 HOURS							Service	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.210	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:16,91
050220	INSPECTION B11							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 5-21-11PROC. REF: AMS 5-21-11									PKG:17
050221 ^S	INSPECT AREA M1/M2-800 HOURS							Service	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.211	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:17,91
050230	INSPECTION B12							Package	ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+50)	Adj -15.9	8363.7	8413.7	703.5 (+50)		
	AFL	5563							
PROC. REF: AMS 05-21-12PROC. REF: AMS 05-21-12									PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050231 ^S	INSPECT AREA G-800 HOURS								Service ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 05.212	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:18,91
050240	INSPECTION C1-C12 COMPLETE								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)		8363.7	8413.7	703.5 (+50)		
	AFL	4989							
PROC. REF: AMS 5-22-00PROC. REF: AMS 5-22-00									PKG:92
050250	INSPECTION C1								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-01PROC. REF: AMS 5-22-01									PKG:19
050260	INSPECTION C2								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-02PROC. REF: AMS 5-22-02									PKG:20
050270	INSPECTION C3								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)	Adj -68.4	8295.3	8395.3	635.1 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-03PROC. REF: AMS 5-22-03									PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050271	^S	INSPECT AREA F1-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.303	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:21,92
050280		INSPECTION C4							Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-04PROC. REF: AMS 5-22-04									PKG:22
050281	^S	INSPECT AREA F2-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.304	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:22,92
050290		INSPECTION C5							Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-05PROC. REF: AMS 5-22-05									PKG:23
050291	^S	INSPECT AREA F3 UNDERFLOOR-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.305	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:23,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050300	INSPECTION C6							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-06PROC. REF: AMS 5-22-06									PKG:24
050301 ^S	INSPECT AREA F3- ABOVE FLOOR-1600 HOURS							Service	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.306	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:24,92
050310	INSPECTION C7							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-07PROC. REF: AMS 5-22-07									PKG:25
050311 ^S	INSPECT AREA F4-1600 HOURS							Service	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.307	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:25,92
050320	INSPECTION C8							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-08PROC. REF: AMS 5-22-08									PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050321	^S	INSPECT AREA T1-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.308	AFL	4989							PKG:26,92
050330		INSPECTION C9							Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							PKG:27
PROC. REF: AMS 5-22-09PROC. REF: AMS 5-22-09									
050331	^S	INSPECT AREA W1-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.309	AFL	4989							PKG:27,92
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									
050340		INSPECTION C10							Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							PKG:28
PROC. REF: AMS 5-22-10PROC. REF: AMS 5-22-10									
050341	^S	INSPECT AREA W2-1600 HOURS							Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.310	AFL	4989							PKG:28,92
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050350	INSPECTION C11								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-11PROC. REF: AMS 5-22-11									PKG:29
050351 ^S	INSPECT AREA M1/M2-1600 HOURS								Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.311	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:29,92
050360	INSPECTION C12								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-22-12PROC. REF: AMS 5-22-12									PKG:30
050361 ^S	INSPECT AREA G-1600 HOURS								Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 05.312	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:30,92
050370	INSPECTION D1-D12 COMPLETE								Package ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)		9963.7	10113.7	2303.5 (+150)		
	AFL	4989							
PROC. REF: AMS 5-23-00PROC. REF: AMS 5-23-00									PKG:93

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050380	INSPECTION D1							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)	Adj -97.1	9866.6	9966.6	2206.4 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-01PROC. REF: AMS 5-23-01									PKG:31
050390	INSPECTION D2							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-02PROC. REF: AMS 5-23-02									PKG:32
050400	INSPECTION D3							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-03PROC. REF: AMS 5-23-03									PKG:33
050410	INSPECTION D4							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-04PROC. REF: AMS 5-23-04									PKG:34
050411 ^S	INSPECT AREA F2-3200 HOURS							Service	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 05.404	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:34,93

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050420	INSPECTION D5							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-05PROC. REF: AMS 5-23-05									PKG:35
050430	INSPECTION D6							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-06PROC. REF: AMS 5-23-06									PKG:36
050431 ^S	INSPECT AREA F3 ABOVE FLOOR-3200 HOURS							Service	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 05.406	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:36,93
050440	INSPECTION D7							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-07PROC. REF: AMS 5-23-07									PKG:37
050441 ^S	INSPECT AREA F4-3200 HOURS							Service	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 05.407	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:37,93

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050450	INSPECTION D8							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-08PROC. REF: AMS 5-23-08									PKG:38
050460	INSPECTION D9							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-09PROC. REF: AMS 5-23-09									PKG:39
050470	INSPECTION D10							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-10PROC. REF: AMS 5-23-10									PKG:40
050480	INSPECTION D11							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-11PROC. REF: AMS 5-23-11									PKG:41
050490	INSPECTION D12							Package	ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+100)		9963.7	10063.7	2303.5 (+100)		
	AFL	4989							
PROC. REF: AMS 5-23-12PROC. REF: AMS 5-23-12									PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050491 ^S	INSPECT AREA G-3200 HOURS								Service ATA:05
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 05.412	AFL	4989							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:42,93
050500	INSPECTION E1-E12 COMPLETE								Package ATA:05
	MOS	04-Jun-25	12 (+1m/-1m)	Adj -42d	23-Apr-26	23-May-26	225 d (+30)		
	HRS	7579.6							
	AFL	5563							
PROC. REF: AMS 5-24-00PROC. REF: AMS 5-24-00									PKG:94
050571 ^S	INSPECT AREA F4-12 MONTHS								Service ATA:05
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 05.506	AFL	5563							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:49,94
050630	INSPECTION F1-F12 COMPLETE								Package ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)		23-Apr-26	23-Jun-26	225 d (+61)		
	HRS	7002.4							
	AFL	5138							
PROC. REF: AMS 5-25-00PROC. REF: AMS 5-25-00									PKG:95
050661 ^S	INSPECT AREA F1-24 MONTHS								Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.603	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:57,95

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050671	^S	INSPECT AREA F2-24 MONTHS							Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.604	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:58,95
050691	^S	INSPECT AREA F3-24 MONTHS							Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.606	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:60,95
050701	^S	INSPECT AREA F4-24 MONTHS							Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.607	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:61,95
050721	^S	INSPECT AREA W1-24 MONTHS							Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.609	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:63,95
050731	^S	INSPECT AREA W2-24 MONTHS							Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.610	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:64,95

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050751 ^S	INSPECT AREA G-24 MONTHS								Service ATA:05
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 05.612	AFL	5138							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:66,95
050760	INSPECTION G COMPLETE								Package ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)		12-Oct-26	12-Dec-26	397 d (+61)		
	HRS	6156.5							
	AFL	4577							
PROC. REF: AMS 5-26-00PROC. REF: AMS 5-26-00									PKG:96
050761 ^S	INSPECT AREA F1-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.703	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96
050762 ^S	INSPECT AREA F2-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.704	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96
050763 ^S	INSPECT AREA F3-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.705	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050764 ^S	INSPECT AREA F4-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.707	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96
050765 ^S	INSPECT AREA T1-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.708	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96
050766 ^S	INSPECT AREA W1/W2-48 MONTHS								Service ATA:05
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 05.709	AFL	4577							
PROC. REF: AMS 5-00-00PROC. REF: AMS 5-00-00									PKG:96
050771	INSPECTION 400 HOUR DETAILED WALK-AROUND								Service ATA:05
	MOS	04-Jun-25							
	HRS	7579.6	400 (+40/-10)	Adj -13.5	7966.1	8006.1	305.9 (+40)		
WC#: 05.100	AFL	5563							
PROC. REF: AMS 5-20-07PROC. REF: AMS 5-20-07									
055005	ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.710	AFL	0							
PROC. REF: AMS 5-50-01PROC. REF: AMS 5-50-01									
055010	ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.711	AFL	0							
PROC. REF: AMS 5-50-02PROC. REF: AMS 5-50-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
055015	ACCOMPLISH INSPECTIONS AFTER A LIGHTNING STRIKE							Service	ATA:05
	MOS/MSC	12-Jul-10	A/R						
	HRS	579							
WC#: 05.712	AFL	495							
PROC. REF: AMS 5-50-03PROC. REF: AMS 5-50-03									
055020 ^U	INSPECTION AFTER SEVERE NOSEWHEEL SHIMMY							Service	ATA:05
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
	AFL	0							
055035	ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C							Service	ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.713	AFL	0							
PROC. REF: AMS 5-50-06PROC. REF: AMS 5-50-06									
055040	ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST							Service	ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.714	AFL	0							
PROC. REF: AMS 5-50-04PROC. REF: AMS 5-50-04									
055045	ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION							Service	ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.715	AFL	0							
PROC. REF: AMS 5-50-05PROC. REF: AMS 5-50-05									
055050	ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW							Service	ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.716	AFL	0							
PROC. REF: AMS 5-50-07PROC. REF: AMS 5-50-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
055060	ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.717	AFL	0							
PROC. REF: AMS 5-50-08PROC. REF: AMS 5-50-08									
055065	ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.718	AFL	0							
PROC. REF: AMS 5-50-09PROC. REF: AMS 5-50-09									
055070	ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.719	AFL	0							
PROC. REF: AMS 5-50-10PROC. REF: AMS 5-50-10									
055075	ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 05.720	AFL	0							
PROC. REF: AMS 5-50-11PROC. REF: AMS 5-50-11									
055080	ACCOMPLISH INSPECTIONS FOR HYDRAULIC CONTAMINATION OF THE CABIN VENTILATION SYSTEM								Service ATA:05
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMS 5-50-12PROC. REF: AMS 5-50-12									
057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION								Package ATA:05
	MOS	04-Jun-25							
	HRS	7499	150 (+100)		(7649) 7729.6	7749	69.4 (+100)		
	ENC	5503							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
PKG:1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION								Package ATA:05
	MOS	04-Jun-25							
	HRS	7499	150 (+100)		(7649) 7729.6	7749	69.4 (+100)		
	ENC	5504							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:1
057120	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION								Package ATA:05
	MOS	04-Jun-25							
	HRS	7499	300 (+100)		(7799) 7879.6	7899	219.4 (+100)		
	ENC	5503							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:2
057120	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION								Package ATA:05
	MOS	04-Jun-25							
	HRS	7499	300 (+100)		(7799) 7879.6	7899	219.4 (+100)		
	ENC	5504							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:2
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION								Package ATA:05
	MOS	29-Oct-24							
	HRS	7145.2	800 (+50)		(7945.2) 8025.8	7995.2	365.6 (+50)		
	ENC	5244							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									PKG:4
057140	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION								Package ATA:05
	MOS	31-Oct-24							
	HRS	7145.2	800 (+50)		(7945.2) 8025.8	7995.2	365.6 (+50)		
	ENC	5244							
									PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
057160	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION								Package ATA:05
	MOS	29-Oct-24							
	HRS	7145.2	1200 (+200)		(8345.2) 8425.8	8545.2	765.6 (+200)		
	ENC	5244							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
057160	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION								Package ATA:05
	MOS	31-Oct-24							
	HRS	7145.2	1200 (+200)		(8345.2) 8425.8	8545.2	765.6 (+200)		
	ENC	5244							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION								Package ATA:05
	MOS	29-Oct-24							
	HRS	7145.2	1600 (+50)		(8745.2) 8825.8	8795.2	1165.6 (+50)		
	ENC	5244							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
									PKG:5
057170	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION								Package ATA:05
	MOS	31-Oct-24							
	HRS	7145.2	1600 (+50)		(8745.2) 8825.8	8795.2	1165.6 (+50)		
	ENC	5244							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
									PKG:5
T05T03 ^U	INSPECTION CRITERIA/STRUCTURAL INSPECTIONS								Service ATA:05
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 05.T03	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 06 - DIMENSIONS AND AREAS									
T06T01	U	GENERAL INSPECTION PANEL LOCATION CHARTS							Service ATA:06
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 06.T01	AFL	0							
ATA 08 - LEVELING AND WEIGHING									
080005	U	WEIGH AIRCRAFT AND UPDATE FLIGHT MANUAL W&B INFO							Service ATA:08
	MOS	13-Nov-24	36		13-Nov-27		794 d		
	HRS	7229.5							
	AFL	5306							
ATA 12 - SERVICING									
120001		LUBRICATE AREA G-200 HOURS							Service ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	200 (+40/-10)	Adj -9.5	7770.1	7810.1	109.9 (+40)		
WC#: 12.001	AFL	5563							
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120003		LUBRICATE AREA F1-400 HOURS							Service ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	400 (+40/-10)		7979.6	8019.6	319.4 (+40)		
WC#: 12.003	AFL	5563							
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120004		LUBRICATE AREA T1-400 HOURS							Service ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	400 (+40/-10)		7979.6	8019.6	319.4 (+40)		
WC#: 12.004	AFL	5563							
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120007		LUBRICATE AREA W1/W2-400 HOURS							Service ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	400 (+40/-10)		7979.6	8019.6	319.4 (+40)		
WC#: 12.007	AFL	5563							
PROC. REF: AMM NO REF 2, AMS 5-20-11PROC. REF: AMM NO REF 2, AMS 5-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
120012	^S	LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS						Service	ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 12.012	AFL	5563							
									PKG:12,91
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120013	^S	LUBRICATE AREA F4-800 HOURS						Service	ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 12.009	AFL	5563							
									PKG:13,91
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120015	^S	LUBRICATE AREA W1-800 HOURS						Service	ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 12.015	AFL	5563							
									PKG:15,91
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120016	^S	LUBRICATE AREA W2-800 HOURS						Service	ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 12.016	AFL	5563							
									PKG:16,91
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120018	^S	LUBRICATE AREA G-800 HOURS						Service	ATA:12
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 12.018	AFL	5563							
									PKG:18,91
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
120019	^S	LUBRICATE AREA F1-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.013	AFL	4989							
									PKG:21,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120020	^S	LUBRICATE AREA F2-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.020	AFL	4989							
									PKG:22,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120021	^S	LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.021	AFL	4989							
									PKG:23,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120022	^S	LUBRICATE AREA F3-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.022	AFL	4989							
									PKG:24,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120023	^S	LUBRICATE AREA F4-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.023	AFL	4989							
									PKG:25,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
120024	^S	LUBRICATE AREA T1-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.024	AFL	4989							
									PKG:26,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120025	^S	LUBRICATE AREA W1-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.025	AFL	4989							
									PKG:27,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120026	^S	LUBRICATE AREA W2-1600 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 12.026	AFL	4989							
									PKG:28,92
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120030	^S	LUBRICATE AREA F2-3200 HOURS						Service	ATA:12
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 12.030	AFL	4989							
									PKG:34,93
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
120049	^S	LUBRICATE AREA F1-24 MONTHS						Service	ATA:12
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 12.049	AFL	5138							
									PKG:57,95
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
120050	^S	LUBRICATE AREA F2-24 MONTHS						Service	ATA:12
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 12.050	AFL	5138							
								PKG:58,95	
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									
ATA 20 - STANDARD PRACTICES - AIRFRAME									
200001	^S	BONDING CHECK CONTROL SURFACES						Service	ATA:20
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 20.010	AFL	5563							
								PKG:7,91	
200002	^S	FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF)						Service	ATA:20
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 20.020	AFL	5563							
								PKG:7,91	
200003	^S	CHECK RADIO RACKING, ELECTRICAL-BONDING						Service	ATA:20
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 20.030	AFL	4577							
								PKG:96	
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									
ATA 21 - AIR CONDITIONING									
210002	^S	CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE						Service	ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 21.075	AFL	5563							
								PKG:7,91	
PROC. REF: AMM 21-10-155PROC. REF: AMM 21-10-155									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
210003 ^S	BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 21.110	AFL	5563							
PROC. REF: AMM 21-10-76PROC. REF: AMM 21-10-76									PKG:7,91
210004 ^S	CHECK MANUAL CABIN ALTITUDE CONTROL VALVE								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 21.270	AFL	5563							PKG:10,91
210005 ^S	CHECK COOLING TURBINE EXHAUST DUCT DRAIN								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 21.260	AFL	5563							PKG:13,91
210006	INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	400 (+10%)	Adj -13.5	7966.1	8006.1	305.9 (+40)		
WC#: 21.221	AFL	5563							
PROC. REF: AMM 21-10-95PROC. REF: AMM 21-10-95									
210007	INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	400 (+10%)	Adj -13.5	7966.1	8006.1	305.9 (+40)		
WC#: 21.280	AFL	5563							
PROC. REF: AMM 21-10-95PROC. REF: AMM 21-10-95									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
210008 ^S		VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER						Service	ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.118	AFL	4989							PKG:22,92
210009 ^S		CHECK PRESSURIZATION CONTROL VENTURI SCREEN						Service	ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.275	AFL	4989							PKG:24,92
210010 ^S		CLEAN PRESSURE REGULATOR FILTER SCREENS						Service	ATA:21
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 21.155	AFL	4577							PKG:96
PROC. REF: AMM 21-30-55PROC. REF: AMM 21-30-55									
210011 ^S		CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES						Service	ATA:21
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 21.120	AFL	4577							PKG:96
PROC. REF: AMM 21-30-25, AMM 21-30-25PROC. REF: AMM 21-30-25, AMM 21-30-25									
210012 ^S		INSPECT AIR CONDITIONING DUCTS						Service	ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.250	AFL	4989							PKG:25,92
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
210013 ^S	INSPECT RAM AIR DUCT								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.255	AFL	4989							PKG:25,92
210014 ^S	INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM)								Service ATA:21
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 21.310	AFL	4577							PKG:96
210015 ^S	INSPECT SILENCER DUCT/SOUNDPROOFING								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 21.015	AFL	4989							PKG:37,93
210016 ^S	BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 21.195	AFL	4989							PKG:37,93
210018 ^S	FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING								Service ATA:21
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 21.135	AFL	4577							PKG:96
PROC. REF: AMM 21-30-70PROC. REF: AMM 21-30-70									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
210019 ^S	INSPECT CABIN SUPPLY NON-RETURN VALVE								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 21.065	AFL	4989							
PROC. REF: AMM 21-10-165PROC. REF: AMM 21-10-165									PKG:37,93
210020 ^S	FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.180	AFL	4989							
PROC. REF: AMM 21-60-105PROC. REF: AMM 21-60-105									PKG:19,92
210021 ^S	INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 21.030	AFL	4989							
PROC. REF: AMM 21-10-165PROC. REF: AMM 21-10-165									PKG:37,93
210022	CHECK TORQUE AIR CONDITIONING DUCTS								Service ATA:21
	MOS/MS	04-Feb-19	O/C						
	HRS	4402.4							
WC#: 21.010	AFL	3451							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
210024 ^S	CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER								Service ATA:21
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 21.290	AFL	5563							
PROC. REF: AMM 21-60-61PROC. REF: AMM 21-60-61									PKG:13,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
210025 ^S	INSPECT PATS APU GTCP36-150W BLEED AIR SYSTEM								Service ATA:21
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 21.035	AFL	4989							
PKG:25,92									
211013	LEFT SWITCHES BLEED AIR OVER TEMPERATURE TEST								Service ATA:21
	MOS	28-May-21	60		28-May-26		260 d		
	HRS	5243.7							
WC#: 21.265	AFL	3991							
211014	RIGHT SWITCHES BLEED AIR OVER TEMPERATURE TEST								Service ATA:21
	MOS	28-May-21	60		28-May-26		260 d		
	HRS	5243.7							
WC#: 21.265	AFL	3991							
211019	APU SHUTOFF VALVE								Component ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.020	AFL	0		TSN 0					
PROC. REF: AMM 21-10-195PROC. REF: AMM 21-10-195									
211031	APU BLEED AIR NON-RETURN VALVE								Component ATA:21
PN:123190-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7380	HRS	0		TSN 0					
WC#: 21.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212001	LEFT MAIN AIR VALVE								Component ATA:21
PN:321292-1	MOS/MSC	22-Oct-21	O/C	TSO 12					
SN:P-1649	HRS	5520.1		TSO 0					
WC#: 21.040	AFL	4179		TSO 0					
PROC. REF: AMM 21-10-25PROC. REF: AMM 21-10-25									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212002	RIGHT MAIN AIR VALVE							Component	ATA:21
PN:HTE250072-1	MOS/MSC	27-Jul-12	O/C	TSR 5					
SN:30040957	HRS	1526.3		TSR 0					
WC#: 21.045	AFL	1237		TSR 0					
PROC. REF: AMM 21-10-24PROC. REF: AMM 21-10-24									
212005 ^U	ACM COOLING TURBINE							Component	ATA:21
PN:2205490-3	MOS/MSC	29-Aug-17	O/C	TSO 7					
SN:86-292	HRS	3723.6		TSO 0					
	AFL	2939		TSO 0					
212008	PRESSURE REGULATOR VALVE							Component	ATA:21
PN:3215086-3	MOS/MSC	08-Dec-23	O/C						
SN:361	HRS	6763.7							
WC#: 21.295	AFL	4989							
PROC. REF: AMM 21-10-76PROC. REF: AMM 21-10-76									
212026	NO. 1 ENGINE BLEED AIR NON-RETURN VALVE							Component	ATA:21
PN:HTE4168	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:MO371VNR0306	HRS	0		TSN 0					
WC#: 21.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212027	NO. 2 ENGINE BLEED AIR NON-RETURN VALVE							Component	ATA:21
PN:HTE4168	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M0353VNR0306	HRS	0		TSN 0					
WC#: 21.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212050	AUXILIARY HEATING BLEED AIR NON-RETURN VALVE							Component	ATA:21
PN:104568	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:13557	HRS	0		TSN 0					
WC#: 21.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212057 ^U	#4 AIR VALVE ACTUATOR							Component	ATA:21
PN:822-9405-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4320D	HRS	0		TSN 0					
	AFL	0		TSN 0					
212062	LEFT (HP/LP) MIXING VALVE							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.060	AFL	0		TSN 0					
PROC. REF: AMM 21-10-35PROC. REF: AMM 21-10-35									
212063	RIGHT (HP/LP) MIXING VALVE							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.060	AFL	0		TSN 0					
PROC. REF: AMM 21-10-35PROC. REF: AMM 21-10-35									
212074	MAIN SUPPLY NON-RETURN VALVE (OVERHAUL)							Component	ATA:21
PN:AWE124-51A	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN:M5931	HRS	6763.7	12000	TSO 0	18763.7		11103.5		
WC#: 21.245	AFL	4989		TSO 0					
PROC. REF: AMM 21-10-107PROC. REF: AMM 21-10-107									
212082	BLEED AIR CHECK VALVE							Component	ATA:21
PN:HTE4405	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1206397	HRS	0		TSN 0					
WC#: 21.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212086	RAM AIR NON-RETURN VALVE							Component	ATA:21
PN:321262-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1579	HRS	0		TSN 0					
WC#: 21.075	AFL	0		TSN 0					
PROC. REF: AMM 21-10-165PROC. REF: AMM 21-10-165									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212098	RAM AIR SUPPLY NON-RETURN VALVE								Component ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.080	AFL	0		TSN 0					
PROC. REF: AMM 21-10-165PROC. REF: AMM 21-10-165									
212103	TEMPERATURE DUCT SWITCH								Component ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.085	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212122	UPPER CHECK VALVE								Component ATA:21
PN:130156-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:36-A0663	HRS	0		TSN 0					
WC#: 21.095	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212123	LOWER CHECK VALVE								Component ATA:21
PN:130156-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:36-A066B	HRS	0		TSN 0					
WC#: 21.095	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212146	CABIN RECIRCULATING FAN								Component ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212504 ^U	#1 AIR VALVE ACTUATOR								Component ATA:21
PN:822-9405-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4281D	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212505 ^U	#2 AIR VALVE ACTUATOR							Component	ATA:21
PN:822-9405-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3638D	HRS	0		TSN 0					
	AFL	0		TSN 0					
212506 ^U	#3 AIR VALVE ACTUATOR							Component	ATA:21
PN:822-9405-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3641D	HRS	0		TSN 0					
	AFL	0		TSN 0					
212508 ^U	#5 AIR VALVE ACTUATOR							Component	ATA:21
PN:822-9405-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4259D	HRS	0		TSN 0					
	AFL	0		TSN 0					
212599 ^U	GROUND BLOWER MOTOR ASSEMBLY, REAR CABIN							Component	ATA:21
PN:800-8856-02	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:0758	HRS			TSN 0					
	AFL			TSN 0					
213001	NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE							Component	ATA:21
PN:B01A2-14128A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HAY0151	HRS	0		TSN 0					
WC#: 21.105	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213002	NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE							Component	ATA:21
PN:B01A214128A	MOS/MSC	28-Jul-21	O/C	TSO 20					
SN:TV706	HRS	5375.2		TSO 0					
WC#: 21.105	AFL	4075		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213019	OUTFLOW/SAFETY VALVE CONTROLLER								Component ATA:21
PN:130530-5	MOS/MSC	24-Jun-10	O/C	TSO 3					
SN:95-C0137	HRS	565.6		TSO 0					
WC#: 21.115	AFL	478		TSO 0					
PROC. REF: AMM 21-30-16PROC. REF: AMM 21-30-16									
213031	LEFT OUTFLOW VALVE								Component ATA:21
PN:103278-18	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:36-G0174	HRS	0		TSN 0					
WC#: 21.120	AFL	0		TSN 0					
PROC. REF: AMM 21-30-25PROC. REF: AMM 21-30-25									
213032	RIGHT OUTFLOW VALVE								Component ATA:21
PN:103278-13	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:46-A0824	HRS	0		TSN 0					
WC#: 21.120	AFL	0		TSN 0					
PROC. REF: AMM 21-30-25PROC. REF: AMM 21-30-25									
213035	2" BUTTERFLY VALVE								Component ATA:21
PN:AWE113-13A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HAY0075	HRS	0		TSN 0					
WC#: 21.320	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213067	CABIN ALTITUDE CONTROL VALVE								Component ATA:21
PN:131004-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:85-6155	HRS	0		TSN 0					
WC#: 21.125	AFL	0		TSN 0					
PROC. REF: AMM 21-30-95PROC. REF: AMM 21-30-95									
213073	MECHANICAL DUMP VALVE								Component ATA:21
PN:HTE940008	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:34050201	HRS	0		TSN 0					
WC#: 21.130	AFL	0		TSN 0					
PROC. REF: AMM 21-30-136PROC. REF: AMM 21-30-136									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213081	U	GROUND PRESSURE CONNECTOR						Component	ATA:21
PN:WGE133-2A-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HAY0020	HRS	0		TSN 0					
	AFL	0		TSN 0					
213097		ALTIMETER PRESSURE SWITCH						Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213098		ALTIMETER PRESSURE SWITCH						Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.300	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213109		VENTURI						Component	ATA:21
PN:131052-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:36-4270	HRS	0		TSN 0					
WC#: 21.140	AFL	0		TSN 0					
PROC. REF: AMM 21-30-105PROC. REF: AMM 21-30-105									
213115		FAN OPERATED VENTURI						Component	ATA:21
PN:132322-3-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:36-A0708	HRS	0		TSN 0					
WC#: 21.145	AFL	0		TSN 0					
PROC. REF: AMM 21-30-65PROC. REF: AMM 21-30-65									
213121		LEFT PNEUMATIC VALVE						Component	ATA:21
PN:107312-4-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:46-12932	HRS	0		TSN 0					
WC#: 21.150	AFL	0		TSN 0					
PROC. REF: AMM 21-30-35PROC. REF: AMM 21-30-35									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213122	RIGHT PNEUMATIC VALVE							Component	ATA:21
PN:107312-4-1	MOS/MSC	03-Sep-11	O/C	TSO 0					
SN:81-9785	HRS	1169.4		TSO 0					
WC#: 21.150	AFL	953		TSO 0					
PROC. REF: AMM 21-30-35PROC. REF: AMM 21-30-35									
213133	LEFT ABSOLUTE PRESSURE CONTROL							Component	ATA:21
PN:102466-13	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:26-A0558	HRS	0		TSN 0					
WC#: 21.155	AFL	0		TSN 0					
PROC. REF: AMM 21-30-55PROC. REF: AMM 21-30-55									
213134	RIGHT ABSOLUTE PRESSURE CONTROL							Component	ATA:21
PN:102466-13	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:26-A0565	HRS	0		TSN 0					
WC#: 21.155	AFL	0		TSN 0					
PROC. REF: AMM 21-30-55PROC. REF: AMM 21-30-55									
213157	JET PUMP							Component	ATA:21
PN:131150-1-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:46-3359	HRS	0		TSN 0					
WC#: 21.160	AFL	0		TSN 0					
PROC. REF: AMM 21-30-45PROC. REF: AMM 21-30-45									
213169	CABIN DIFFERENTIAL PRESSURE INDICATOR							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.165	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213181	GROUND PRESSURE CONNECTOR							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.170	AFL	0		TSN 0					
PROC. REF: AMM 21-30-85PROC. REF: AMM 21-30-85									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213516 ^U	BANJO ASSEMBLY							Component	ATA:21
PN:FRH460001C	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:45050644	HRS	0		TSN 0					
	AFL	0		TSN 0					
216001	CABIN TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:104968	MOS/MSC	14-Mar-17	O/C	TSO 0					
SN:1340	HRS	3481.6		TSO 0					
WC#: 21.175	AFL	2742		TSO 0					
PROC. REF: AMM 21-60-57PROC. REF: AMM 21-60-57									
216025	AUXILIARY HEATING VALVE							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.180	AFL	0		TSN 0					
PROC. REF: AMM 21-60-105PROC. REF: AMM 21-60-105									
216055	CABIN TEMPERATURE (CONTROLLER) SENSOR							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.185	AFL	0		TSN 0					
PROC. REF: MMA 21-60-05PROC. REF: MMA 21-60-05									
216073	CABIN TEMPERATURE CONTROLLER							Component	ATA:21
PN:617452-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:617452-01652	HRS	0		TSN 0					
WC#: 21.190	AFL	0		TSN 0					
PROC. REF: AMM 21-60-67PROC. REF: AMM 21-60-67									
216097	TEMPERATURE DUCT SELECTOR							Component	ATA:21
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.195	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216115	COLD AIR UNIT PACK								Component ATA:21
PN:2214070-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:744	HRS	0		TSN 0					
WC#: 21.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
216121	MODULATING VALVE								Component ATA:21
PN:978836-5-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:949	HRS	0		TSN 0					
WC#: 21.210	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
216127	CONTROL SENSOR								Component ATA:21
PN:1150642-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1150642-11420	HRS	0		TSN 0					
WC#: 21.215	AFL	0		TSN 0					
PROC. REF: AMM 21-60-60PROC. REF: AMM 21-60-60									
216135	TOTAL TEMPERATURE SENSOR								Component ATA:21
PN:102ER1EC	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:A64089	HRS	0		TSN 0					
WC#: 21.305	AFL	0		TSN 0					
PROC. REF: AMM 34-60-25PROC. REF: AMM 34-60-25									
217001	WATER SEPARATOR								Component ATA:21
PN:25VF1351-131	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1670	HRS	0		TSN 0					
WC#: 21.220	AFL	0		TSN 0					
PROC. REF: AMM 21-10-95PROC. REF: AMM 21-10-95									
217014	CABIN TRIPLE INDICATOR								Component ATA:21
PN:51010-1113	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5078994	HRS	0		TSN 0					
WC#: 21.225	AFL	0		TSN 0					
PROC. REF: AMM 21-30-90PROC. REF: AMM 21-30-90									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
217023	PRESSURE SWITCH							Component	ATA:21
PN:HTE690090	MOS/MSC	27-Sep-12	O/C	TSN 98					
SN:20221	HRS	1607.1		TSN 4930.8					
WC#: 21.235	AFL	1293		TSN 4010					
PROC. REF: AMM 21-10-39PROC. REF: AMM 21-10-39									
ATA 22 - AUTO FLIGHT									
221001	AFCS CONTROL PANEL							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
221007	NO. 1 FLIGHT GUIDANCE COMPUTER							Component	ATA:22
PN:822-1108-023	MOS/MSC	05-Nov-15	O/C	TSO 1					
SN:2MXGW	HRS	2685.1		TSO 0					
WC#: 22.015	AFL	2146		TSO 0					
221008	NO. 2 FLIGHT GUIDANCE COMPUTER							Component	ATA:22
PN:822-1108-023	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:26W1T	HRS	0		TSN 0					
WC#: 22.015	AFL	0		TSN 0					
221010	NO. 1 AUTO PILOT MODE SELECT PANEL							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.040	AFL	0		TSN 0					
PROC. REF: MMA 34-22-56PROC. REF: MMA 34-22-56									
221011	NO. 2 AUTO PILOT MODE SELECT PANEL							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.040	AFL	0		TSN 0					
PROC. REF: MMA 34-22-56PROC. REF: MMA 34-22-56									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221037	AUTOPILOT ELEVATOR SERVO							Component	ATA:22
PN:822-1168-002	MOS/MSC	07-Aug-12	O/C	TSN 74					
SN:265KB	HRS	1543.8		TSN 1543.8					
WC#: 22.020	AFL	1247		TSN 1247					
PROC. REF: AMM 22-10-30PROC. REF: AMM 22-10-30									
221039	ELEVATOR SERVO MOUNT							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.050	AFL	0		TSN 0					
PROC. REF: AMM 22-10-30PROC. REF: AMM 22-10-30									
221043	AUTOPILOT RUDDER SERVO							Component	ATA:22
PN:822-1168-002	MOS/MSC	05-Nov-15	O/C	TSO 0					
SN:1C9PM	HRS	2685.1		TSO 0					
WC#: 22.020	AFL	2146		TSO 0					
PROC. REF: AMM 22-10-20PROC. REF: AMM 22-10-20									
221045	RUDDER SERVO MOUNT							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.050	AFL	0		TSN 0					
PROC. REF: AMM 22-10-20PROC. REF: AMM 22-10-20									
221049	AUTOPILOT AILERON SERVO							Component	ATA:22
PN:822-1168-002	MOS/MSC	06-Jul-16	O/C	TSO 0					
SN:4LL7P	HRS	3072.4		TSO 0					
WC#: 22.020	AFL	2438		TSO 0					
PROC. REF: AMM 22-10-10PROC. REF: AMM 22-10-10									
221052	AILERON SERVO MOUNT							Component	ATA:22
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 22.050	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231001	NO. 1 HF COMMUNICATIONS CONTROLLER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.015	AFL	0		TSN 0					
PROC. REF: AMM 23-10-22PROC. REF: AMM 23-10-22									
231002	NO. 2 HF COMMUNICATIONS CONTROLLER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.015	AFL	0		TSN 0					
PROC. REF: MMA 23-10-05PROC. REF: MMA 23-10-05									
231004	NO. 1 HF CONTROLLER ADAPTER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.020	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231006	NO. 2 HF CONTROLLER ADAPTER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.020	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231011	NO. 1 HF COMMUNICATIONS POWER AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231012	NO. 2 HF COMMUNICATIONS POWER AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231016	COLLINS HF 9031A RECEIVER/TRANSMITTER							Component	ATA:23
PN:685-0350-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6429	HRS	0		TSN 0					
WC#: 23.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231017 ^U	#2 HF ANTENNA COUPLER							Component	ATA:23
PN:SSPD113-13	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1012	HRS	0		TSN 0					
	AFL	0		TSN 0					
231025	NO. 1 HF RECEIVER EXCITER							Component	ATA:23
PN:822-0101-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2490	HRS	0		TSN 0					
WC#: 23.030	AFL	0		TSN 0					
PROC. REF: AMM 23-10-06PROC. REF: AMM 23-10-06									
231026	NO. 2 HF RECEIVER EXCITER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.030	AFL	0		TSN 0					
PROC. REF: AMM 23-10-06PROC. REF: AMM 23-10-06									
231027	NO. 1 HF BRIDGING AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231028	NO. 2 HF BRIDGING AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231029	DUAL HF CAPACITOR							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.040	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231041	VHF COMMUNICATION (CTL-23D) CONTROL							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.136	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231043	NO. 1 VHF COMMUNICATIONS TRANSCEIVER							Component	ATA:23
PN:822-1468-102	MOS/MSC	13-Jun-14	O/C	TSO 1					
SN:30RBG	HRS	2196.2		TSO 0					
WC#: 23.045	AFL	1738		TSO 0					
PROC. REF: MMA 23-20-79, MMA 23-20-80, MMA 23-20-81, AMM 23-10-21, AMM 23-10-22, AMM 23-20-12PROC. REF: MMA 23-20-79, MMA 23-20-80, MMA 23-20-81, AMM 23-10-21, AMM 23-10-22, AMM 23-20-12									
231049	NO. 2 VHF COMMUNICATIONS TRANSCEIVER							Component	ATA:23
PN:822-1468-102	MOS/MSC	07-Dec-16	O/C	TSO 0					
SN:1MDWB	HRS	3331		TSO 0					
WC#: 23.045	AFL	2635		TSO 0					
PROC. REF: MMA 23-20-79, MMA 23-20-80, MMA 23-20-81, AMM 23-10-21, AMM 23-10-22, AMM 23-20-12PROC. REF: MMA 23-20-79, MMA 23-20-80, MMA 23-20-81, AMM 23-10-21, AMM 23-10-22, AMM 23-20-12									
231050	ATC UPPER ANTENNA							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231055	NO. 1 VHF AERIAL							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.055	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231056	NO. 2 VHF AERIAL							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.055	AFL	0		TSN 0					
PROC. REF: AMM 23-10-35PROC. REF: AMM 23-10-35									
231058	AUDIO TONE GENERATOR							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.060	AFL	0		TSN 0					
PROC. REF: MMA 23-50-67PROC. REF: MMA 23-50-67									
231061	NO. 1 RADIO MANAGEMENT UNIT							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.065	AFL	0		TSN 0					
231062	NO. 2 RADIO MANAGEMENT UNIT							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.065	AFL	0		TSN 0					
231064	CLEARANCE DELIVERY CONTROL							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
234001	SATELLITE TRANSCEIVER (SAT PHONE)							Component	ATA:23
PN:400-10680-001	MOS/MSC	11-Sep-10	O/C	TSN 0					
SN:1068014499	HRS	652.2		TSN 0					
WC#: 23.075	AFL	562		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
234007	MOBILE RADIO ANTENNA							Component	ATA:23
PN:S65-8282-101	MOS/MSC	03-Sep-11	O/C	TSN 0					
SN:2054	HRS	1169.4		TSN 0					
WC#: 23.080	AFL	953		TSN 0					
234013	COCKPIT MOBILE RADIO TELEPHONE HANDSET							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.085	AFL	0		TSN 0					
PROC. REF: MMA 23-16-05, MMA 23-16-10PROC. REF: MMA 23-16-05, MMA 23-16-10									
234019	CABIN MOBILE RADIO TELEPHONE HANDSET							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.085	AFL	0		TSN 0					
PROC. REF: MMA 23-16-05, MMA 23-16-10PROC. REF: MMA 23-16-05, MMA 23-16-10									
234041	FLITEFONE AUXILIARY BELL							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
235001	NO. 1 AUDIO CONTROLLER							Component	ATA:23
PN:803-004	MOS/MSC	14-Mar-24	O/C						
SN:821	HRS	6924							
WC#: 23.095	AFL	5088							
PROC. REF: MMA 23-50-67PROC. REF: MMA 23-50-67									
235002	NO. 2 AUDIO CONTROLLER							Component	ATA:23
PN:803-004	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:817	HRS	0		TSN 0					
WC#: 23.095	AFL	0		TSN 0					
PROC. REF: MMA 23-50-67PROC. REF: MMA 23-50-67									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
235017	NO. 1 HANDHELD AUDIO MICROPHONE							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
235019	NO. 2 HANDHELD AUDIO MICROPHONE							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.100	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237001	COCKPIT VOICE RECORDER							Component	ATA:23
PN:1603-02-12	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1584	HRS	0		TSN 0					
WC#: 23.105	AFL	0		TSN 0					
PROC. REF: MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37PROC. REF: MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37									
237004	COCKPIT VOICE RECORDER NO.1 MICROPHONE							Component	ATA:23
PN:16301-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2033	HRS	0		TSN 0					
WC#: 23.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237005	COCKPIT VOICE RECORDER NO.2 MICROPHONE							Component	ATA:23
PN:16301-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1903	HRS	0		TSN 0					
WC#: 23.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component	ATA:23
PN:DK120/90	MOS/MSC	08-Dec-23	O/C	TSN 0					
SN:AT194467	HRS	6763.7		TSN 0					
WC#: 23.105	AFL	4989		TSN 0					
PROC. REF: MMA 23-70-35, AMM 23-70-37, AMM 25-60-110PROC. REF: MMA 23-70-35, AMM 23-70-37, AMM 25-60-110									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237015		TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON						Service	ATA:23
	MOS	04-Jun-25	24		03-Jun-27		631 d		
	HRS	7579.6							
WC#: 23.105	AFL	5563							
Test Date: : 03-Jun-25									
PROC. REF: CMM DUKANE, MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110PROC. REF: CMM DUKANE, MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110									
237016		CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON						Service	ATA:23
	MOS	08-Dec-23	24		08-Dec-25		89 d		
	HRS	6763.7							
WC#: 23.105	AFL	4989							
PROC. REF: CMM DUKANE, MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110PROC. REF: CMM DUKANE, MMA 23-70-05, MMA 23-70-35, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110									
237017		REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY						Service	ATA:23
	MOS/MSC	08-Dec-23	DUE		01-Sep-30 (M)		1817 d		
	HRS	6763.7							
WC#: 23.105	AFL	4989							
PROC. REF: MMA 23-70-05, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110PROC. REF: MMA 23-70-05, AMM 23-70-36, AMM 23-70-37, AMM 25-60-110									
237019		LEFT COCKPIT VOICE RECORDER CONTROL						Component	ATA:23
PN:1634-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:840	HRS	0		TSN 0					
WC#: 23.125	AFL	0		TSN 0					
PROC. REF: AMM 23-70-36, AMM 23-70-37PROC. REF: AMM 23-70-36, AMM 23-70-37									
237020		RIGHT COCKPIT VOICE RECORDER CONTROL						Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.125	AFL	0		TSN 0					
PROC. REF: AMM 23-70-36PROC. REF: AMM 23-70-36									
237021		VOICE RECORDER INERTIA SWITCH						Component	ATA:23
PN:3LO453-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:81319	HRS	0		TSN 0					
WC#: 23.115	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237022	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Component	ATA:23
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
238015	SELCAL DECODER UNIT							Component	ATA:23
PN:1200008-000	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4630	HRS	0		TSN 0					
WC#: 23.120	AFL	0		TSN 0					
PROC. REF: MMA 23-20-05, AMM 23-20-11PROC. REF: MMA 23-20-05, AMM 23-20-11									
ATA 24 - ELECTRICAL POWER									
240001	INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR							Service	ATA:24
PN:23080-064	MOS	04-Jun-25							
SN:P2389	HRS	7579.6	400 (+10%)	Adj -32.3	7947.3	7987.3	287.1 (+40)		
WC#: 24.045	AFL	5563							
PROC. REF: AMM 24-30-21PROC. REF: AMM 24-30-21									
240001	INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR							Service	ATA:24
PN:23080-064	MOS	04-Jun-25							
SN:P1897	HRS	7579.6	400 (+10%)		7979.6	8019.6	319.4 (+40)		
WC#: 24.045	AFL	5563							
PROC. REF: AMM 24-30-21PROC. REF: AMM 24-30-21									
240002 ^S	OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS							Service	ATA:24
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 24.010	AFL	5563							
									PKG:7,91
240003 ^S	FUNCTION TEST FREQUENCY WILD A.C. SYSTEM							Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.030	AFL	4989							
									PKG:31,93

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
PROC. REF: AMM 24-22-02PROC. REF: AMM 24-22-02									
240004	^S	CHECK BUSBAR CONTACTOR CONTROL						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 24.145	AFL	4989							
									PKG:19,92
PROC. REF: AMM 24-30-142PROC. REF: AMM 24-30-142									
240006	^S	CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.070	AFL	4989							
									PKG:36,93
PROC. REF: AMM 24-30-146PROC. REF: AMM 24-30-146									
240007	^S	BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED).						Service	ATA:24
	MOS	08-Dec-23							
	HRS		3200 (+150/-50)						
WC#: 24.110	AFL								
BenchCheck Date: : 08-Dec-23									PKG:37,93
PROC. REF: AMM 24-30-146PROC. REF: AMM 24-30-146									
240009	^S	FUNCTIONAL TEST D.C. GENERATING SYSTEM						Service	ATA:24
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 24.065	AFL	5563							
									PKG:7,91
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
240010	^S	INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 24.160	AFL	4989							
									PKG:24,92
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
240011	^S	FUNCTIONAL TEST OF THE BUSBAR PE, PS1 AND PS2 FEEDER FUSES						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 24.150	AFL	4989							
								PKG:25,92	
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									
240012	^U ^S	INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 24.165	AFL	4989							
								PKG:25,92	
240013	^S	FUNCTION TEST ALL CIRCUIT BREAKERS						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.005	AFL	4989							
								PKG:31,93	
240014	^S	FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.040	AFL	4989							
								PKG:31,93	
PROC. REF: AMM 24-30-07PROC. REF: AMM 24-30-07									
240015	^S	FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.040	AFL	4989							
								PKG:31,93	
PROC. REF: AMM 24-36-03PROC. REF: AMM 24-36-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
240016	^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200	(+150/-50)					
WC#: 24.235	AFL	4989							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									PKG:33,93
240017	^S	INSPECT/CHECK EARTH STATIONS *16, *17, *18, AND *19						Service	ATA:24
	MOS	12-Oct-22	48	(+2m/-2m)					
	HRS	6156.5							
WC#: 24.155	AFL	4577							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									PKG:96
240018	^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200	(+150/-50)					
WC#: 24.235	AFL	4989							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									PKG:37,93
240024		INSPECT/CHECK APU STARTER/GENERATOR						Service	ATA:24
PN:23080-005	MOS	23-May-23							
SN:5875	HRS	6556.1							
WC#: 24.085	AFL	4826							
	APH	4514	500		5014		492		
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
240025	^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200	(+150/-50)					
WC#: 24.245	AFL	4989							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									PKG:35,93

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
240026	^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)						Service	ATA:24
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 24.240	AFL	4989							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									PKG:34,93
240027	^S	CHECK MAIN BATTERIES						Service	ATA:24
	MOS	17-Jul-24							
	HRS	7153.7	3200 (+150/-50)						
WC#: 24.250	AFL	5254							
PROC. REF: AMM 24-30-151PROC. REF: AMM 24-30-151									PKG:37,93
240028		VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M						Service	ATA:24
	MOS	04-Jun-25							
	HRS	7579.6	400 (+10%)		7979.6	8019.6	319.4 (+40)		
WC#: 24.095	AFL	5563							
PROC. REF: AMM 24-01-00PROC. REF: AMM 24-01-00									
240029	^S	VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF HEAT DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS						Service	ATA:24
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 24.260	AFL	5563							
									PKG:48,94
240030		FUNCTION TEST CABIN INVERTER (115 VAC) SYSTEM (IF INSTALLED)						Service	ATA:24
	DAYS	04-Jun-25							
	HRS	7579.6	200 (+10%/-10%)		7779.6	7799.6	119.4 (+20)		
WC#: 24.255	AFL	5563							
PROC. REF: MMA 24-20-00, MMA 24-20-05, MMA 24-20-10PROC. REF: MMA 24-20-00, MMA 24-20-05, MMA 24-20-10									
242001		NO. 1 (MAIN) INVERTER						Component	ATA:24
PN:ASH664-5	MOS/MSC	05-Jul-22	O/C	TSO 29					
SN:ES1049	HRS	6050.1		TSO 0					
WC#: 24.015	AFL	4508		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
PROC. REF: AMM 24-21-102PROC. REF: AMM 24-21-102									
242002	NO. 2 (MAIN) INVERTER								Component ATA:24
PN:140-380010-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2129	HRS	0		TSN 0					
WC#: 24.015	AFL	0		TSN 0					
PROC. REF: AMM 24-21-102PROC. REF: AMM 24-21-102									
242013	NO. 3 (STANDBY) INVERTER								Component ATA:24
PN:SPS-1607A	MOS/MSC	21-Nov-14	O/C	TSO 0					
SN:418	HRS	2399.6		TSO 0					
WC#: 24.015	AFL	1907		TSO 0					
PROC. REF: AMM 24-21-105PROC. REF: AMM 24-21-105									
242031	NO. 1 INVERTER CONTACTOR (OVERHAUL)								Component ATA:24
PN:SD-130L/140-380020	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:CN-66587	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 24.020	AFL	3858		TSO 0					
242032	NO. 2 INVERTER CONTACTOR (OVERHAUL)								Component ATA:24
PN:SD-130L	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:CN-81719	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 24.020	AFL	3858		TSO 0					
242073	NO. 1 ENGINE AC GENERATOR (OVERHAUL)								Component ATA:24
PN:BA02801-1	MOS	03-May-21	96	TSO 1	03-Apr-29		1301 d	OVERHAUL	
SN:1536	HRS	5219	3000	TSO 0	8219		558.8		
WC#: 24.025	AFL	3979		TSO 0					
PROC. REF: AMM 24-22-21PROC. REF: AMM 24-22-21									
242074	NO. 2 ENGINE AC GENERATOR (OVERHAUL)								Component ATA:24
PN:BA02801-1	MOS	21-Feb-25	96	TSO 0	21-Feb-33		2721 d	OVERHAUL	
SN:3273	HRS	7403.7	3000	TSO 0	10403.7		2743.5		
WC#: 24.025	AFL	5430							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
PROC. REF: AMM 24-22-21PROC. REF: AMM 24-22-21									
242097	LEFT AC GENERATOR CONTROL UNIT							Component	ATA:24
PN:CB02701	MOS/MSC	31-Mar-17	O/C	TSN 102					
SN:1022	HRS	3527.5		TSN 3100.5					
WC#: 24.035	AFL	2779		TSN 2434					
PROC. REF: AMM 24-30-07PROC. REF: AMM 24-30-07									
242098	RIGHT AC GENERATOR CONTROL UNIT							Component	ATA:24
PN:CB02701	MOS/MSC	05-Jan-18	O/C	TSO 0					
SN:H1619	HRS	3887.1		TSO 0					
WC#: 24.035	AFL	3077		TSO 0					
PROC. REF: AMM 24-30-07PROC. REF: AMM 24-30-07									
243001	NO. 1 ENGINE STARTER/GENERATOR (OVERHAUL)							Component	ATA:24
PN:23080-064	MOS	12-Jul-24		TSO 0				OVERHAUL	
SN:P2389	HRS	7147.3	1000	TSO 0	8147.3		487.1		
WC#: 24.045	AFL	5249		TSO 0					
PROC. REF: AMM 24-30-21PROC. REF: AMM 24-30-21									
243002	NO. 2 ENGINE STARTER/GENERATOR (OVERHAUL)							Component	ATA:24
PN:23080-064	MOS	13-Nov-24		TSR 0				OVERHAUL	
SN:P1897	HRS	7229.5	1000	TSO 0, TSR 0	8229.5		569.3		
WC#: 24.045	AFL	5306		TSO 0, TSR 0					
PROC. REF: AMM 24-30-21PROC. REF: AMM 24-30-21									
243037	NO. 1 DC GENERATOR CONTROL UNIT							Component	ATA:24
PN:51539-006H	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:P1438	HRS	6763.7		TSO 0					
WC#: 24.050	AFL	4989		TSO 0					
PROC. REF: AMM 24-30-07PROC. REF: AMM 24-30-07									
243038	NO. 2 DC GENERATOR CONTROL UNIT							Component	ATA:24
PN:51539-006H	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:Y0101	HRS	6763.7		TSO 0					
WC#: 24.050	AFL	4989		TSO 0					
PROC. REF: AMM 24-30-07PROC. REF: AMM 24-30-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243049	H (UPPER) CONTACTOR							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243050	H (LOWER) CONTACTOR							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243061	G (UPPER) CONTACTOR							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243062	G (LOWER) CONTACTOR							Component	ATA:24
PN:A-703ZS	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:CO52436	HRS	6763.7		TSO 0					
WC#: 24.060	AFL	4989		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243079	DC VOLTAGE SENSING UNIT							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243091	GROUND SUPPLY START (E) CONTACTOR (OVERHAUL)							Component	ATA:24
PN:SD105K	MOS	28-Apr-22		TSO 4				OVERHAUL	
SN:CN-83862	HRS	5938	6000	TSO 0	11938		4277.8		
WC#: 24.075	AFL	4436		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243103	APU STARTER/GENERATOR CONTROL UNIT							Component	ATA:24
PN:51539-006H	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:P2208	HRS	6763.7		TSO 0					
WC#: 24.080	AFL	4989		TSO 0					
PROC. REF: AMM 24-30-21, AMM 49-11-00PROC. REF: AMM 24-30-21, AMM 49-11-00									
243115	APU STARTER/GENERATOR (OVERHAUL)							Component	ATA:24
PN:23080-005	MOS	14-May-22		TSO 0				OVERHAUL	
SN:5875	HRS	5967		TSO 0					
WC#: 24.085	AFL	4454		TSO 0					
	APH	4043	1000	TSO 0	5043		521		
PROC. REF: MMA 49-16-00, AMM 24-30-21PROC. REF: MMA 49-16-00, AMM 24-30-21									
243137	NO. 1 BATTERY							Component	ATA:24
PN:9750W0640	MOS/MSC	17-Jul-24	O/C	TSN 0					
SN:240540012	HRS	7153.7		TSN 0					
WC#: 24.090	AFL	5254							
PROC. REF: AMM 24-30-151PROC. REF: AMM 24-30-151									
243138	NO. 2 BATTERY							Component	ATA:24
PN:9750W0640	MOS/MSC	17-Jul-24	O/C	TSN 0					
SN:240540011	HRS	7153.7		TSN 0					
WC#: 24.090	AFL	5254							
PROC. REF: AMM 24-30-151PROC. REF: AMM 24-30-151									
243139	NO. 3 BATTERY							Component	ATA:24
PN:100-0540-04	MOS	05-Jan-22	48	TSO 0	05-Jan-26		117 d		
SN:1090	HRS	5677.2		TSO 0					
WC#: 24.210	AFL	4276		TSO 0					
PROC. REF: AMM 24-30-155, AMM 24-30-151PROC. REF: AMM 24-30-155, AMM 24-30-151									
243140	NO. 4 BATTERY							Component	ATA:24
PN:100-0540-04	MOS	21-Sep-23	48	TSO 0	21-Sep-27		741 d		
SN:0705387	HRS	6702							
WC#: 24.220	AFL	4945							
PROC. REF: AMM 24-30-07, AMM 24-30-155PROC. REF: AMM 24-30-07, AMM 24-30-155									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243141	NO. 5 BATTERY							Component	ATA:24
PN:100-0540-04	MOS	04-Jun-25	48	TSO 1	04-May-29		1332 d		
SN:1785	HRS	7579.6							
WC#: 24.230	AFL	5563							
PROC. REF: AMM 24-30-155PROC. REF: AMM 24-30-155									
243142	NO. 6 BATTERY							Component	ATA:24
PN:100-0540-04	MOS	13-Nov-24	48	TSO 2	13-Sep-28		1099 d		
SN:1128764	HRS	7229.5		TSO 0					
	AFL	5306		TSO 0					
PROC. REF: AMM 24-30-155PROC. REF: AMM 24-30-155									
243143	NO. 7 BATTERY							Component	ATA:24
PN:100-0540-04	MOS	18-Mar-22	48	TSN 0	18-Mar-26		189 d		
SN:1211244	HRS	5874.1		TSN 0					
	AFL	4403		TSN 0					
243154	CAPACITY CHECK NO. 1 BATTERY							Service	ATA:24
PN:9750W0640	MOS	17-Jul-24	T:18 (+45d/-45d)		17-Jan-26		129 d	STC ICA	
SN:240540012	HRS	7153.7	T:4500 (+450/-450)		11653.7		3993.5		
WC#: 24.090	AFL	5254							
PROC. REF: AMM 24-30-151PROC. REF: AMM 24-30-151									
243155	CAPACITY CHECK NO. 2 BATTERY							Service	ATA:24
PN:9750W0640	MOS	17-Jul-24	T:18 (+45d/-45d)		17-Jan-26		129 d	STC ICA	
SN:240540011	HRS	7153.7	T:4500 (+450/-450)		11653.7		3993.5		
WC#: 24.090	AFL	5254							
PROC. REF: AMM 24-30-151PROC. REF: AMM 24-30-151									
243156	ENERGY LEVEL TEST NO. 3 BATTERY							Service	ATA:24
PN:100-0540-04	MOS	18-Dec-24	12 (+30d/-30d)		18-Dec-25	17-Jan-26	99 d (+30)		
SN:1090	HRS	7294.8							
WC#: 24.210	AFL	5348							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243157	ENERGY LEVEL TEST NO. 4 BATTERY								Service ATA:24
PN:100-0540-04	MOS	13-Nov-24	12 (+30d/-30d)		13-Nov-25	13-Dec-25	64 d (+30)		
SN:0705387	HRS	7229.5							
WC#: 24.220	AFL	5306							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
243158	ENERGY LEVEL TEST NO. 5 BATTERY								Service ATA:24
PN:100-0540-04	MOS	04-Jun-25	12 (+30d/-30d)		04-Jun-26	04-Jul-26	267 d (+30)		
SN:1785	HRS	7579.6							
WC#: 24.230	AFL	5563							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
243159	ENERGY LEVEL TEST NO. 6 BATTERY								Service ATA:24
PN:100-0540-04	MOS	13-Nov-24	12 (+30d/-30d)		13-Nov-25	13-Dec-25	64 d (+30)		
SN:1128764	HRS	7229.5							
	AFL	5306							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
243160	ENERGY LEVEL TEST NO. 7 BATTERY								Service ATA:24
PN:100-0540-04	MOS	25-Mar-25	12 (+30d/-30d)	Adj 9d	03-Apr-26	03-May-26	205 d (+30)		
SN:1211244	HRS	7456.9							
	AFL	5465							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243238	OVERVOLTAGE SENSOR								Component ATA:24
PN:E311TS	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:CP-25050	HRS	0		TSN 0					
WC#: 24.110	AFL	0		TSN 0					
PROC. REF: AMM 24-30-146PROC. REF: AMM 24-30-146									
243246	THERMAL SWITCH								Component ATA:24
PN:21346-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5547	HRS	0		TSN 0					
WC#: 24.115	AFL	0		TSN 0					
PROC. REF: AMM 26-16-03PROC. REF: AMM 26-16-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243247	S CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243253	FORWARD U CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243259	J CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243265	K CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243271	AFT U CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243277	L CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

243283	M CONTACTOR							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

245001	BUS TIE (T) CONTACTOR (OVERHAUL)							Component	ATA:24
PN:LDA150-A8C	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:A3219	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 24.140	AFL	3858		TSO 0					

245043	TEMPERATURE SENSOR							Component	ATA:24
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.170	AFL	0		TSN 0					
PROC. REF: AMM 34-60-25PROC. REF: AMM 34-60-25									

248128 ^U	NO. 1 STARTER GENERATOR AIR/OIL-GARLOCK CARBON SEAL							Component	ATA:24
PN:3072784-2	MOS/MSC	12-Dec-17	O/C	TSN 0					
SN:NSN	HRS	3863.3		TSN 0					
	AFL	3060		TSN 0					

248129 ^U	NO. 2 STARTER GENERATOR AIR/OIL-GARLOCK CARBON SEAL SEAL							Component	ATA:24
PN:3072784-2	MOS/MSC	08-Dec-18	O/C	TSN 0					
SN:NSN	HRS	4330.3		TSN 0					
	AFL	3402		TSN 0					

ATA 25 - EQUIPMENT/FURNISHINGS

250003 ^S	CHECK 3RD CREW MEMBERS SEAT							Service	ATA:25
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 25.115	AFL	5563							
									PKG:12,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
250005 ^S		INSPECT EMERGENCY PACKS (IF FITTED)						Service	ATA:25
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 25.125	AFL	5563							PKG:48,94
250006 ^S		CHECK FIRST AID KITS						Service	ATA:25
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 25.130	AFL	5563							PKG:48,94
250007 ^S		OPERATIONAL CHECK CREW SEATS						Service	ATA:25
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 25.145	AFL	5563							PKG:10,91
250008 ^S		DETAILED CHECK CREW SEATS						Service	ATA:25
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 25.150	AFL	4989							PKG:34,93
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
251001		NO. 1 CREW SEAT						Component	ATA:25
PN:3A026-0013-00-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:44544	HRS	0		TSN 0					
WC#: 25.010	AFL	0		TSN 0					
PROC. REF: AMM 25-10-14PROC. REF: AMM 25-10-14									
251002		NO. 2 CREW SEAT						Component	ATA:25
PN:3A026-0014-00-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:44553	HRS	0		TSN 0					
WC#: 25.010	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
PROC. REF: AMM 25-10-14PROC. REF: AMM 25-10-14									
251020	THROTTLE BOX							Component	ATA:25
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 25.020	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
251038	FLIGHT DECK CONTROLLER							Component	ATA:25
PN:922000-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:H02260730	HRS	0		TSN 0					
WC#: 25.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
251049 ^U	#3 SPEAKER (MIDRANGE/TWEETER)							Component	ATA:25
PN:AI-5.25CX-8	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
251051 ^U	#1 SPEAKER (WOFFER)							Component	ATA:25
PN:DT-AWSP-4MRH	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:060912004	HRS	0		TSN 0					
	AFL	0		TSN 0					
251053 ^U	#2 SPEAKER (WOFFER)							Component	ATA:25
PN:DT-AWSP-4MRH	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:060912005	HRS	0		TSN 0					
	AFL	0		TSN 0					
251057	NO. 1 DIGITAL AUDIO AMPLIFIER							Component	ATA:25
PN:MODEL 700-007	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:2101	HRS			TSN 0					
WC#: 25.050	AFL			TSN 0					
PROC. REF: AMM 23-50-10PROC. REF: AMM 23-50-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
251058	NO. 2 DIGITAL AUDIO AMPLIFIER							Component	ATA:25
PN:MODEL 700-007	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:2103	HRS			TSN 0					
WC#: 25.050	AFL			TSN 0					
PROC. REF: AMM 23-50-10PROC. REF: AMM 23-50-10									
251063 ^U	COFFEE MAKER							Component	ATA:25
PN:400-1794-04	MOS/MSC	06-Apr-16	O/C	TSR 0					
SN:07-09-42033	HRS	2919.5		TSR 0					
	AFL	2325		TSR 0					
252501 ^U	CABIN CHAIR							Component	ATA:25
PN:303709-1BS2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32471	HRS	0		TSN 0					
	AFL	0		TSN 0					
252502 ^U	CABIN CHAIR							Component	ATA:25
PN:303709-1D4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32472	HRS	0		TSN 0					
	AFL	0		TSN 0					
252503 ^U	CABIN CHAIR							Component	ATA:25
PN:303709-1S2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32468	HRS	0		TSN 0					
	AFL	0		TSN 0					
252504 ^U	CABIN CHAIR							Component	ATA:25
PN:303709-2S2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32469	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252505 ^U	CABIN CHAIR							Component	ATA:25
PN:303709-2S2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32470	HRS	0		TSN 0					
	AFL	0		TSN 0					
252509 ^U	DIVAN							Component	ATA:25
PN:160080-15DL5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:32462	HRS	0		TSN 0					
	AFL	0		TSN 0					
253089	MICROWAVE OVEN							Component	ATA:25
PN:400-1744-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:05-11-67955	HRS	0		TSN 0					
WC#: 25.055	AFL	0		TSN 0					
PROC. REF: MMA 25-30-31PROC. REF: MMA 25-30-31									
255616 ^U	SUNVISOR KIT							Component	ATA:25
PN:RBA800-300-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M020696	HRS	0		TSN 0					
	AFL	0		TSN 0					
256001	EMERGENCY LOCATOR TRANSMITTER (ELT)							Component	ATA:25
PN:453-5000	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:13684	HRS	6763.7		TSO 0					
WC#: 25.025	AFL	4989		TSO 0					
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05									
256005	INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT)							Service	ATA:25
PN:453-5000	MOS	04-Dec-24	12		04-Dec-25		85 d		
SN:13684	HRS	7267.7							
WC#: 25.025	AFL	5331							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256006	ELT REMOTE (CONTROL UNIT) SWITCH							Component	ATA:25
PN:453-9701	MOS/MSC	31-May-11	O/C						
SN:UNKNOWN	HRS	1059							
WC#: 25.030	AFL	857							
PROC. REF: AMM 25-60-05PROC. REF: AMM 25-60-05									
256007	REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Service	ATA:25
PN:452-0133	MOS/MSC	19-Oct-23	DUE		29-Feb-28 (M)		902 d		
SN:398874-007	HRS	6755.2							
WC#: 25.025	AFL	4984							
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05, AMM 25-61-15PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05, AMM 25-61-15									
256009	EMERGENCY LOCATOR TRANSMITTER ANTENNA							Component	ATA:25
PN:110-337	MOS/MSC	16-Sep-11	O/C	TSN 0					
SN:350019	HRS	1179.8		TSN 0					
WC#: 25.015	AFL	964		TSN 0					
PROC. REF: AMM 25-61-20PROC. REF: AMM 25-61-20									
256010	FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT)							Service	ATA:25
PN:453-5000	MOS	04-Dec-24	12		04-Dec-25		85 d		
SN:13684	HRS	7267.7							
WC#: 25.025	AFL	5331							
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05, AMM 25-61-15PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15, AMM 25-60-05, AMM 25-61-15									
256011	REPLACE ELT REMOTE (CONTROL UNIT) SWITCH BATTERY							Service	ATA:25
PN:453-9701	MOS/MSC	31-May-11	N/A						
SN:UNKNOWN	HRS	1059							
WC#: 25.030	AFL	857							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
256013	INSPECT LIFE VESTS							Service	ATA:25
	MOS/MSC	29-Jun-06	N/R						
	HRS	0							
WC#: 25.040	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256080A	^U	PILOT AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	09-Feb-16	120		09-Feb-26		152 d		
	HRS	2835.7							
	AFL	2258							
256081A	^U	COPILOT AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	13-Oct-15	120		13-Oct-25		33 d		
	HRS								
	AFL								
256082A	^U	PASSENGER NO.1 AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256083A	^U	PASSENGER NO.2 AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256084A	^U	PASSENGER NO.3 AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	26-Oct-15	120		26-Oct-25		46 d		
	HRS	2668.1							
	AFL	2133							
256085A	^U	PASSENGER NO.4 AIR CRUISER LIFE VEST INSPECTION						Service	ATA:25
	MOS	21-Feb-25	120		21-Feb-35		3451 d		
	HRS	7403.7							
	AFL	5430							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256086A ^U	PASSENGER NO.5 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256087A ^U	PASSENGER NO.6 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256088A ^U	PASSENGER NO.7 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256089A ^U	PASSENGER NO.8 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256090A ^U	PASSENGER NO.9 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	05-Nov-15	120		05-Nov-25		56 d		
	HRS								
	AFL								
256092A ^U	PASSENGER NO.10 AIR CRUISER LIFE VEST INSPECTION								Service ATA:25
	MOS	09-Feb-16	120		09-Feb-26		152 d		
	HRS	2835.7							
	AFL	2258							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256097		DIGITAL INTERFACE UNIT						Component	ATA:25
PN:453-6500	MOS/MSC	27-Jan-17	O/C	TSN 127, TSR 0					
SN:5535	HRS	3394.5		TSN 3394.5, TSR 0					
WC#: 25.140	AFL	2685		TSN 2685, TSR 0					
PROC. REF: MMA 23-33-40, MMA 23-33-41PROC. REF: MMA 23-33-40, MMA 23-33-41									
256301		EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY						Component	ATA:25
PN:452-0133	MOS/MSC	19-Oct-23	O/C	TSN 0					
SN:398874-007	HRS	6755.2		TSN 0					
	AFL	4984							
256310 ^U		(NOAA) 406 MHZ EMERGENCY LOCATOR TRANSMITTER REGISTRATION						Service	ATA:25
	MOS	29-Jul-24	24	29-Nov-25 (M)			80 d		
	HRS	7169.1							
	AFL	5264							
259990 ^U		3.8 INCH COLOR DISPLAY SWITCH ASSEMBLY						Component	ATA:25
PN:2516-1-1	MOS/MSC	30-Jan-13	O/C	TSR 0					
SN:205460085	HRS	1747.4		TSR 0					
	AFL	1397		TSR 0					
25R000 ^U		LIFE RAFT ELT RE-REGISTRATION						Service	ATA:25
	MOS	11-Jun-24	24	11-Jun-26			274 d		
	HRS	7107.6							
	AFL	5214							
25R001 ^U		NO. 1 LIFE RAFT						Component	ATA:25
PN:RAF1212-305T1	MOS/MSC	28-Aug-23	O/C	TSN 36, TSO 0					
SN:1120030667H	HRS	6683.4		TSN 6683.4, TSO 0					
	AFL	4926		TSN 4926, TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25R002 ^U	INSPECT							Service	ATA:25
	MOS/MSC	28-Aug-23	36 / -		28-Aug-26		352 d		
	HRS	6683.4							
	AFL	4926							
25R003 ^U	SURVIVAL EQUIPMENT							Component	ATA:25
PN:EQU1212-303T1	MOS/MSC	28-Aug-23	36 / -	TSN 35, TSO 0	28-Aug-26		352 d		
SN:3120090865	HRS			TSO 0					
	AFL			TSO 0					
25W002 ^U	TOP ASSEMBLY, HARDWARE, GOGO AVANCE L3							Component	ATA:25
PN:P34110-003	MOS/MSC	29-May-24	O/C						
SN:341100031012E	HRS	7070.4							
	AFL	5189							
25W003 ^U	TOP ASSEMBLY, AXCESS CONFIGURATION MODULE							Component	ATA:25
PN:P14126	MOS/MSC	31-Aug-20	O/C						
SN:1412625509	HRS	4766.8							
	AFL	3736							
25W004 ^U	ANTENNA, AIR TO GROUND (ATG), LRU							Component	ATA:25
PN:P12949	MOS/MSC	31-Aug-20	O/C						
SN:634122	HRS	4766.8							
	AFL	3736							
25W005 ^U	ANTENNA, AIR TO GROUND (A TG), LRU							Component	ATA:25
PN:P12949	MOS/MSC	31-Aug-20	O/C						
SN:634121	HRS	4766.8							
	AFL	3736							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25W006 ^U	TOP ASSEMBLY, CELLULAR, CABIN ANTENNA							Component	ATA:25
PN:P18350-001	MOS/MSC	31-Aug-20	O/C						
SN:1835006411	HRS	4766.8							
	AFL	3736							
25W007 ^U	TOP ASSEMBLY, CELLULAR, CABIN ANTENNA							Component	ATA:25
PN:P18350-001	MOS/MSC	31-Aug-20	O/C						
SN:1835006417	HRS	4766.8							
	AFL	3736							
25W008 ^U	ASSEMBLY, WIFI, CABIN ANTENNA							Component	ATA:25
PN:P16917-001	MOS/MSC	31-Aug-20	O/C						
SN:1691700113449	HRS	4766.8							
	AFL	3736							
25W009 ^U	ASSEMBLY, WIFI, CABIN ANTENNA							Component	ATA:25
PN:P16917-001	MOS/MSC	31-Aug-20	O/C						
SN:1691700113445	HRS	4766.8							
	AFL	3736							
25W010 ^U	ASSEMBLY, WIFI, CABIN ANTENNA							Component	ATA:25
PN:P16917-001	MOS/MSC	31-Aug-20	O/C						
SN:1691700113427	HRS	4766.8							
	AFL	3736							
25W011 ^U	ASSEMBLY, WIFI, CABIN ANTENNA							Component	ATA:25
PN:P16917-001	MOS/MSC	31-Aug-20	O/C						
SN:1691700113453	HRS	4766.8							
	AFL	3736							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
25W012 ^U		ASSEMBLY, WIFI, CABIN ANTENNA						Component	ATA:25
PN:P16917-001		MOS/MSC	31-Aug-20	O/C					
SN:1691700113441		HRS	4766.8						
		AFL	3736						
25W013 ^U		ASSEMBLY, WIFI, CABIN ANTENNA						Component	ATA:25
PN:P16917-001		MOS/MSC	31-Aug-20	O/C					
SN:1691700113421		HRS	4766.8						
		AFL	3736						
25W014 ^U		TOP ASSEMBLY, MOUNTING TRAY W/COOLING FANS, GOGO AVANCE						Component	ATA:25
PN:P41234		MOS/MSC	31-Aug-20	O/C					
SN:UNKNOWN		HRS	4766.8						
		AFL	3736						
342551 ^U		#1 ENVIRONMENTAL CONTROLLER						Component	ATA:25
PN:2090-1-2		MOS/MSC	10-Sep-14	O/C	TSR 0				
SN:206200295		HRS	2296.4		TSR 0				
		AFL	1830		TSR 0				
ATA 26 - FIRE PROTECTION									
260001 ^S		CHECK AFT ENGINE FIRE EXTINGUISHER						Service	ATA:26
		MOS	04-Jun-25	12 (+1m/-1m)					
		HRS	7579.6						
WC#: 26.020		AFL	5563						
								PKG:43,94	
260001 ^S		CHECK FORWARD ENGINE FIRE EXTINGUISHER						Service	ATA:26
		MOS	04-Jun-25	12 (+1m/-1m)					
		HRS	7579.6						
WC#: 26.010		AFL	5563						
								PKG:43,94	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
260002 ^S	FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM								Service ATA:26
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 26.035	AFL	5563							
PROC. REF: AMM 26-10-00PROC. REF: AMM 26-10-00									PKG:7,91
260003 ^S	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER								Service ATA:26
PN:C354TS	MOS	04-Jun-25	12 (+1m/-1m)						
SN:G-12594290	HRS	7579.6							
WC#: 26.080	AFL	5563							
WeightCheck Date : : 04-Jun-25									PKG:46,94
260004 ^S	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER								Service ATA:26
PN:16578-888	MOS	04-Jun-25	12 (+1m/-1m)						
SN:G-45679044	HRS	7579.6							
WC#: 26.075	AFL	5563							
WeightCheck Date : : 04-Jun-25									PKG:48,94
260008	FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)								Service ATA:26
	MOS	04-Jun-25	6 (+10%)	Adj -21d	13-Nov-25	01-Dec-25	64 d (+18)		
	HRS	7579.6							
WC#: 26.115	AFL	5563							
PROC. REF: MMA 26-11-00PROC. REF: MMA 26-11-00									
260010 ^S	CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER								Service ATA:26
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 26.085	AFL	5563							
PROC. REF: AMM 49-61-20, CMM 26-20-02PROC. REF: AMM 49-61-20, CMM 26-20-02									PKG:49,94
261030	APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH								Component ATA:26
PN:17343-62	MOS/MSC	28-May-21	O/C						
SN:33623	HRS	5243.7							
WC#: 26.120	AFL	3991							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
PROC. REF: AMM 26-16-03PROC. REF: AMM 26-16-03									
261031 APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH Component ATA:26									
PN:17343-62	MOS/MSC	28-May-21	O/C						
SN:33620	HRS	5243.7							
WC#: 26.125	AFL	3991							
PROC. REF: AMM 26-16-03PROC. REF: AMM 26-16-03									
261032 APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH Component ATA:26									
PN:17343-62	MOS/MSC	28-May-21	O/C						
SN:33622	HRS	5243.7							
WC#: 26.130	AFL	3991							
PROC. REF: AMM 26-16-03PROC. REF: AMM 26-16-03									
261033 APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH Component ATA:26									
PN:17343-62	MOS/MSC	28-May-21	O/C						
SN:33621	HRS	5243.7							
WC#: 26.135	AFL	3991							
PROC. REF: AMM 26-16-03PROC. REF: AMM 26-16-03									
261034 TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH Service ATA:26									
PN:17343-62	MOS	28-May-21	60		28-May-26		260 d		
SN:33623	HRS	5243.7							
WC#: 26.120	AFL	3991							
261035 TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH Service ATA:26									
PN:17343-62	MOS	28-May-21	60		28-May-26		260 d		
SN:33620	HRS	5243.7							
WC#: 26.125	AFL	3991							
261036 TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH Service ATA:26									
PN:17343-62	MOS	28-May-21	60		28-May-26		260 d		
SN:33622	HRS	5243.7							
WC#: 26.130	AFL	3991							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261037	TEST APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH							Service	ATA:26
PN:17343-62	MOS	28-May-21	60		28-May-26		260 d		
SN:33621	HRS	5243.7							
WC#: 26.135	AFL	3991							
261074	OVERHEAT DETECTION SWITCHES TEST							Service	ATA:26
	MOS	28-May-21	60		28-May-26		260 d		
	HRS	5243.7							
WC#: 26.030	AFL	3991							
261171	NO. 1 ENGINE ZONE 1 FIRE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.050	AFL	0		TSN 0					
PROC. REF: AMM 26-10-12PROC. REF: AMM 26-10-12									
261172	NO. 2 ENGINE ZONE 1 FIRE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-10-12PROC. REF: AMM 26-10-12									
261183	NO. 1 ENGINE ZONE 2 FIRE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.050	AFL	0		TSN 0					
PROC. REF: AMM 26-10-12PROC. REF: AMM 26-10-12									
261184	NO. 2 ENGINE ZONE 2 FIRE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.055	AFL	0		TSN 0					
PROC. REF: AMM 26-10-12PROC. REF: AMM 26-10-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262001	ENGINE FORWARD FIRE EXTINGUISHER							Component	ATA:26
PN:33200009-3	MOS/MSC	13-Nov-24	O/C	TSN 0					
SN:37099C1	HRS	7229.5		TSN 0					
WC#: 26.010	AFL	5306		TSN 0					
PROC. REF: AMM 26-20-12PROC. REF: AMM 26-20-12									
262002	ENGINE AFT FIRE EXTINGUISHER							Component	ATA:26
PN:33200009-3	MOS/MSC	13-Nov-24	O/C	TSO 1					
SN:24168C1	HRS	7229.5		TSO 0					
WC#: 26.020	AFL	5306		TSO 0					
PROC. REF: AMM 26-20-00, AMM 26-20-12PROC. REF: AMM 26-20-00, AMM 26-20-12									
262025	HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER							Service	ATA:26
PN:33200009-3	MOS	13-Nov-24	120		05-Nov-34		3343 d		
SN:37099C1	HRS	7229.5							
WC#: 26.010	AFL	5306							
HydroCheck Date: : 05-Nov-24									
262026	HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER							Service	ATA:26
PN:33200009-3	MOS	13-Nov-24	120		05-Nov-34		3343 d		
SN:24168C1	HRS	7229.5							
WC#: 26.020	AFL	5306							
HydroCheck Date: : 05-Nov-24									
262027	FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE							Component	ATA:26
PN:30900000M	MOS/MSC	13-Nov-24	O/C	TSN 5					
SN:1670DF	HRS	7229.5		TSN 0					
WC#: 26.015	AFL	5306		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262028	AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE							Component	ATA:26
PN:30900000M	MOS/MSC	13-Nov-24	O/C	TSN 3					
SN:1690DF	HRS	7229.5		TSN 0					
WC#: 26.025	AFL	5306		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262029	FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE							Component	ATA:26
PN:AE30900000M	MOS/MSC	13-Nov-24	O/C	TSN 9					
SN:2116	HRS	7229.5		TSN 0					
WC#: 26.015	AFL	5306		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262030	AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE							Component	ATA:26
PN:30900000M	MOS/MSC	13-Nov-24	O/C	TSN 3					
SN:1691DF	HRS	7229.5		TSN 0					
WC#: 26.025	AFL	5306		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262037	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	120		01-Jun-34 (M)		3186 d	LIFE LIMIT	
SN:1670DF	HRS	7229.5							
WC#: 26.015	AFL	5306							
Installation Date: : 13-Nov-24									
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22									
262038	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	120		01-Aug-34 (M)		3247 d	LIFE LIMIT	
SN:1690DF	HRS	7229.5							
WC#: 26.025	AFL	5306							
Installation Date: : 13-Nov-24									
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22									
262049	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:AE30900000M	MOS	13-Nov-24	120		01-Feb-34 (M)		3066 d	LIFE LIMIT	
SN:2116	HRS	7229.5							
WC#: 26.015	AFL	5306							
Installation Date: : 13-Nov-24									
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
262050		REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	120		01-Aug-34 (M)		3247 d	LIFE LIMIT		
SN:1691DF	HRS	7229.5								
WC#: 26.025	AFL	5306								
			Installation Date: : 13-Nov-24							
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22										
262061		REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	180		01-Jun-39		5012 d	LIFE LIMIT		
SN:1670DF	HRS	7229.5								
WC#: 26.015	AFL	5306								
			Manufacture Date:: 01-Jun-24							
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22										
262062		REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	180		01-Aug-39		5073 d	LIFE LIMIT		
SN:1690DF	HRS	7229.5								
WC#: 26.025	AFL	5306								
			Manufacture Date:: 01-Aug-24							
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22										
262073		REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:AE30900000M	MOS	13-Nov-24	180		01-Feb-39		4892 d	LIFE LIMIT		
SN:2116	HRS	7229.5								
WC#: 26.015	AFL	5306								
			Manufacture Date:: 01-Feb-24							
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22										
262074		REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:30900000M	MOS	13-Nov-24	180		01-Aug-39		5073 d	LIFE LIMIT		
SN:1691DF	HRS	7229.5								
WC#: 26.025	AFL	5306								
			Manufacture Date:: 01-Aug-24							
PROC. REF: AMM 26-20-22PROC. REF: AMM 26-20-22										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262091	CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:16578-888	MOS/MSC	12-Oct-22	O/C	TSN 0					
SN:G-45679044	HRS	6156.5		TSN 0					
WC#: 26.075	AFL	4577		TSN 0					
262101 ^U	MID-LIFE INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER							Service	ATA:26
PN:C354TS	MOS	15-Dec-21	72		31-Mar-26 (M)		202 d		
SN:G-12594290	HRS	5643.6							
	AFL	4255							
262102 ^U	MID-LIFE INSPECTION CABIN PORTABLE FIRE EXTINGUISHER							Service	ATA:26
PN:16578-888	MOS	09-Aug-21	72		09-Aug-27		698 d		
SN:G-45679044	HRS	6156.5							
	AFL	4577							
262103	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER							Service	ATA:26
PN:16578-888	MOS	09-Aug-21	144		09-Aug-33		2890 d		
SN:G-45679044	HRS								
WC#: 26.075	AFL								
HydroCheck Date: : 09-Aug-21									
262109	COCKPIT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:C354TS	MOS/MSC	15-Dec-21	O/C	TSN 0					
SN:G-12594290	HRS	5643.6		TSN 0					
WC#: 26.080	AFL	4255		TSN 0					
262121	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER							Service	ATA:26
PN:C354TS	MOS	15-Dec-21	144		31-Mar-32 (M)		2394 d		
SN:G-12594290	HRS								
WC#: 26.080	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262127	APU FIRE EXTINGUISHER							Component	ATA:26
PN:4190-01	MOS/MSC	04-Jun-25	O/C	TSO 0					
SN:487	HRS	7579.6							
WC#: 26.085	AFL	5563							
PROC. REF: MMA 26-16-00, AMM 49-61-20PROC. REF: MMA 26-16-00, AMM 49-61-20									
262137	LEAK CHECK APU FIRE EXTINGUISHER							Service	ATA:26
	MOS/MSC	04-Jun-25	O/C						
	HRS	7579.6							
WC#: 26.085	AFL	5563							
PROC. REF: CMM 26-20-02PROC. REF: CMM 26-20-02									
262139	HYDROSTATIC TEST APU FIRE EXTINGUISHER							Service	ATA:26
PN:4190-01	MOS	04-Jun-25	60		28-Feb-30		1632 d		
SN:487	HRS	7579.6							
WC#: 26.085	AFL	5563							
HydroCheck Date: : 28-Feb-25									
262143	APU FORWARD CARTRIDGE							Component	ATA:26
PN:AE30900000M	MOS/MSC	04-Jun-25	O/C	TSN 0					
SN:2008	HRS	7579.6		TSN 0					
WC#: 26.060	AFL	5563							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262145	REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:AE30900000M	MOS	04-Jun-25	120		04-Jun-35		3554 d	LIFE LIMIT	
SN:2008	HRS	7579.6							
WC#: 26.060	AFL	5563							
Installation Date: : 04-Jun-25									
PROC. REF: CMM 26-20-02PROC. REF: CMM 26-20-02									
262157	REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:AE30900000M	MOS	04-Jun-25	180		28-Feb-39		4919 d	LIFE LIMIT	
SN:2008	HRS	7579.6							
WC#: 26.060	AFL	5563							
Manufacture Date:: 29-Feb-24									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
PROC. REF: CMM 26-20-02PROC. REF: CMM 26-20-02									
262190	FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED							Component	ATA:26
PN:A1003(1)	MOS/MSC	06-Mar-24	O/C						
SN:UNKNOWN	HRS	6917.1							
WC#: 26.100	AFL	5082							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262195	AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED							Component	ATA:26
PN:A1003(1)	MOS/MSC	06-Mar-24	O/C						
SN:UNKNOWN	HRS	6917.1							
WC#: 26.105	AFL	5082							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262199	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT)							Service	ATA:26
PN:A1003(1)	MOS	04-Mar-24	48		04-Mar-28		906 d	LIFE LIMIT	
SN:UNKNOWN	HRS								
WC#: 26.100	AFL								
Manufacture Date:: 04-Mar-24									
PROC. REF: AMM 26-20-41PROC. REF: AMM 26-20-41									
262200	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT)							Service	ATA:26
PN:A1003(1)	MOS	04-Mar-24	48		04-Mar-28		906 d	LIFE LIMIT	
SN:UNKNOWN	HRS								
WC#: 26.105	AFL								
Manufacture Date:: 04-Mar-24									
PROC. REF: AMM 26-20-41PROC. REF: AMM 26-20-41									
262201	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE)							Service	ATA:26
PN:A1003(1)	MOS	06-Mar-24	36		06-Mar-27		542 d	LIFE LIMIT	
SN:UNKNOWN	HRS								
WC#: 26.100	AFL								
Installation Date: : 06-Mar-24									
PROC. REF: AMM 26-20-41PROC. REF: AMM 26-20-41									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262202	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE)							Service	ATA:26
PN:A1003(1)	MOS	06-Mar-24	36		06-Mar-27		542 d	LIFE LIMIT	
SN:UNKNOWN	HRS								
WC#: 26.105	AFL								
Installation Date: : 06-Mar-24									
PROC. REF: AMM 26-20-41PROC. REF: AMM 26-20-41									
262301	SMOKE DETECTOR AMPLIFIER							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.070	AFL	0		TSN 0					
262307	FORWARD BAGGAGE COMPARTMENT SMOKE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.110	AFL	0		TSN 0					
PROC. REF: MMA 26-11-00PROC. REF: MMA 26-11-00									
262308	AFT BAGGAGE COMPARTMENT SMOKE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.110	AFL	0		TSN 0					
PROC. REF: MMA 26-11-00PROC. REF: MMA 26-11-00									
262309	VANITY SMOKE DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 26.110	AFL	0		TSN 0					
PROC. REF: MMA 26-11-00PROC. REF: MMA 26-11-00									
26R102 ^U	MONTHLY PORTABLE FIRE EXTINGUISHER INSPECTION							Service	ATA:26
	MOS	29-Jul-25	1		31-Aug-25		OVD		
	HRS	7659.5							
	AFL	5622							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270001	OPERATIONAL TEST AIRBRAKE SELECTOR LEVER BAULK								Service ATA:27
	MOS/MSC	14-Sep-06	N/R						
	HRS	8.5							
WC#: 27.265	AFL	7							
PROC. REF: AMM 27-61-03, AMS 5-20-08PROC. REF: AMM 27-61-03, AMS 5-20-08									
270002 ^S	INSPECT LEFT WING FLAP VANE INNER								Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.490	AFL	4989							PKG:27,92
270003 ^S	INSPECT LEFT WING FLAP SCREWJACKS SCREW THREADS								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.495	AFL	5563							PKG:15,91
270004 ^S	FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.120	AFL	5563							PKG:8,91
PROC. REF: AMM 27-33-00PROC. REF: AMM 27-33-00									
270008 ^S	FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.060	AFL	5563							PKG:8,91
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270011	^S	INSPECT GUST LOCKS/AILERONS AND ELEVATORS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.415	AFL	5563							PKG:10,91
270012	^S	CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.450	AFL	5563							PKG:14,91
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									
270013	^S	CHECK AND INSPECT ELEVATORS AND TRIM TABS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.485	AFL	5563							PKG:14,91
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
270014	^S	INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.420	AFL	5563							PKG:14,91
270015	^S	OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.425	AFL	5563							PKG:15,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270016	^S	CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.435	AFL	5563							
									PKG:15,91
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
270017	^S	CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.500	AFL	5563							
									PKG:15,91
PROC. REF: AMM 27-50-141PROC. REF: AMM 27-50-141									
270018	^S	INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.550	AFL	5563							
									PKG:15,91
270019	^S	CHECK FLAP CONTROL UNIT						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.525	AFL	5563							
									PKG:15,91
PROC. REF: AMM 27-50-121PROC. REF: AMM 27-50-121									
270020	^S	OPERATE FLAP CONTROL UNIT						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.520	AFL	5563							
									PKG:15,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270021	^S	INSPECT LEFT FLAP DRIVE SHAFTS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.510	AFL	5563							PKG:15,91
270022	^S	OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.425	AFL	5563							PKG:16,91
270023	^S	CHECK AND INSPECT RIGHT AILERON SERVO TABS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.435	AFL	5563							PKG:16,91
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									
270024	^S	CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.500	AFL	5563							PKG:16,91
PROC. REF: AMM 27-50-141PROC. REF: AMM 27-50-141									
270025	^S	INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.550	AFL	5563							PKG:16,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270026 ^S	INSPECT RIGHT FLAP DRIVE SHAFTS								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.510	AFL	5563							PKG:16,91
270027 ^S	FUNCTIONAL TEST FLAP CONTROL SYSTEM								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.200	AFL	5563							PKG:18,91
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270028 ^S	FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM								Service ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 27.260	AFL	5563							PKG:18,91
PROC. REF: AMM 27-61-02PROC. REF: AMM 27-61-02									
270030 ^S	CHECK ELEVATOR TRIM SERVO								Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.095	AFL	4989							PKG:20,92
270032 ^S	CHECK AILERON AUTOPILOT SERVO CONTROL CABLES								Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.440	AFL	4989							PKG:22,92
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270033	^S	INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.100	AFL	4989							PKG:22,92
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
270034	^S	CHECK ELEVATOR PRIMARY CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.460	AFL	4989							PKG:23,92
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270035	^S	CHECK FLAP CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.540	AFL	4989							PKG:23,92
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270036	^S	CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.465	AFL	4989							PKG:25,92
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									
270037	^S	CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.455	AFL	4989							PKG:25,92
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270038 ^S	CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES							Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.475	AFL	4989							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									PKG:25,92
270039 ^S	CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES							Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.445	AFL	4989							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									PKG:25,92
270040 ^S	CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES							Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.480	AFL	4989							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:25,92
270041 ^S	INSPECT ELEVATOR TRIM CABLES							Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.470	AFL	4989							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:26,92
270042 ^S	CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES							Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.430	AFL	4989							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:27,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270043	^S	INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.565	AFL	4989							PKG:27,92
270044	^S	CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.535	AFL	4989							PKG:27,92
270045	^S	CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.515	AFL	4989							PKG:27,92
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270046	^S	CHECK FLAP/AIRBRAKE BAULK BOBBIN						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.575	AFL	4989							PKG:27,92
270047	^S	CHECK FLAP SPRING DRUM PULLEY-LEVER						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.555	AFL	4989							PKG:27,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270048	^S	CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.505	AFL	4989							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									PKG:27,92
270049	^S	CHECK LEFT FLAP SYNCHRONIZING SYSTEM						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.530	AFL	4989							
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									PKG:27,92
270050	^S	CHECK LEFT AIRBRAKE CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.570	AFL	4989							
PROC. REF: AMM 27-61-02PROC. REF: AMM 27-61-02									PKG:27,92
270051	^S	CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.430	AFL	4989							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00									PKG:28,92
270052	^S	INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.565	AFL	4989							
									PKG:28,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270053 ^S		CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY							Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.535	AFL	4989							PKG:28,92
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
270054 ^S		CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX							Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.505	AFL	4989							PKG:28,92
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270055 ^S		CHECK RIGHT FLAP SYNCHRONIZING SYSTEM							Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.530	AFL	4989							PKG:28,92
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
270056 ^S		CHECK RIGHT AIRBRAKE CONTROL CABLES							Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.570	AFL	4989							PKG:28,92
PROC. REF: AMM 27-61-02PROC. REF: AMM 27-61-02									
270057 ^S		CHECK FLAP CONTROL FORWARD SPRING STRUT							Service ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 27.560	AFL	4989							PKG:34,93
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270058 ^S		CHECK FLAP CONTROL INPUT-CIRCUIT						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 27.210	AFL	4989							PKG:34,93
270059 ^S		INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD						Service	ATA:27
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 27.545	AFL	5563							PKG:49,94
270060 ^S		REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 27.215	AFL	4989							PKG:40,93
270061		CHECK FLIGHT CONTROL CABLES TENSION						Service	ATA:27
	MOS/MSC	13-Jul-07	O/C						
	HRS	264.1							
WC#: 27.010	AFL	212							
270063		LUBRICATE/CLEAN SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS/MSC	29-Jun-06	N/R						
	HRS	0							
WC#: 27.030	AFL	0							
270064 ^S		INSPECT RIGHT WING FLAP VANE INNER						Service	ATA:27
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 27.490	AFL	4989							PKG:28,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270065	^S	INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.495	AFL	5563							
									PKG:16,91
270066	^S	INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.600	AFL	5563							
									PKG:15,91
270067	^S	INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS						Service	ATA:27
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 27.605	AFL	5563							
									PKG:16,91
270068	^S	LUBRICATE/CLEAN AILERON SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	12-Oct-22	48	(+2m/-2m)					
	HRS	6156.5							
WC#: 27.610	AFL	4577							
									PKG:96
270069	^S	LUBRICATE/CLEAN ELEVATOR SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	12-Oct-22	48	(+2m/-2m)					
	HRS	6156.5							
WC#: 27.615	AFL	4577							
									PKG:96

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
270070 ^S		LUBRICATE/CLEAN RUDDER SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 27.620	AFL	4577							
									PKG:96
270071 ^S		INSPECT RUDDER TRIM JACK						Service	ATA:27
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
	AFL	4577							
									PKG:96
PROC. REF: AMM 27-20-111PROC. REF: AMM 27-20-111									
270072 ^S		INSPECT ELEVATOR TRIM JACK						Service	ATA:27
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
	AFL	4577							
									PKG:96
PROC. REF: AMM 27-30-51PROC. REF: AMM 27-30-51									
270100		LEFT CONTROL COLUMN						Component	ATA:27
PN:25-8CF53-217A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPLS/DH/2099	HRS	0		TSN 0					
WC#: 27.015	AFL	0		TSN 0					
PROC. REF: AMM 27-10-11PROC. REF: AMM 27-10-11									
270102		RIGHT CONTROL COLUMN						Component	ATA:27
PN:25-8CF55-215A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPLS/DH/2098	HRS	0		TSN 0					
WC#: 27.015	AFL	0		TSN 0					
PROC. REF: AMM 27-10-11PROC. REF: AMM 27-10-11									
271001		LEFTAILERON						Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.020	AFL	0		TSN 0					
PROC. REF: AMM 27-10-31PROC. REF: AMM 27-10-31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271002	RIGHT AILERON								Component ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.020	AFL	0		TSN 0					
PROC. REF: AMM 27-10-31PROC. REF: AMM 27-10-31									
271025	AILERON TRIM SCREWJACK								Component ATA:27
PN:25-8CW49-43A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18299	HRS	0		TSN 0					
WC#: 27.025	AFL	0		TSN 0					
PROC. REF: AMM 27-10-71PROC. REF: AMM 27-10-71									
272001	RUDDER								Component ATA:27
PN:25-8TR105-11A	MOS/MSC		O/C						
SN:SD-DH-025	HRS								
WC#: 27.045	AFL								
PROC. REF: AMM 27-20-23PROC. REF: AMM 27-20-23									
272019	RUDDER TRIM JACK								Component ATA:27
PN:25CW573G	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18563	HRS	0		TSN 0					
WC#: 27.050	AFL	0		TSN 0					
PROC. REF: AMM 27-20-111PROC. REF: AMM 27-20-111									
272020	RUDDER GEARED TAB								Component ATA:27
PN:25TR209AG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-025	HRS	0		TSN 0					
WC#: 27.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272021	RUDDER TRIM TAB								Component ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.285	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272022	LEFT RUDDER PEDAL ASSEMBLY							Component	ATA:27
PN:25-8CF549-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18176 HRS		0		TSN 0					
WC#: 27.065	AFL	0		TSN 0					
PROC. REF: AMM 27-20-35PROC. REF: AMM 27-20-35									
272023	RIGHT RUDDER PEDAL ASSEMBLY							Component	ATA:27
PN:25-8CF549-2A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18182 HRS		0		TSN 0					
WC#: 27.065	AFL	0		TSN 0					
PROC. REF: AMM 27-20-35PROC. REF: AMM 27-20-35									
272049	LEFT RUDDER BIAS STRUT							Component	ATA:27
PN:ACA1218	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:EMC084	HRS	0		TSN 0					
WC#: 27.055	AFL	0		TSN 0					
PROC. REF: AMM 27-20-51PROC. REF: AMM 27-20-51									
272050	RIGHT RUDDER BIAS STRUT							Component	ATA:27
PN:ACA1218	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:EMC089	HRS	0		TSN 0					
WC#: 27.055	AFL	0		TSN 0					
PROC. REF: AMM 27-20-51PROC. REF: AMM 27-20-51									
272066	LEFT RUDDER BIAS STRUT HEATER MUFF							Component	ATA:27
PN:259W03486-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1726	HRS	0		TSN 0					
WC#: 27.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272067	RIGHT RUDDER BIAS STRUT HEATER MUFF							Component	ATA:27
PN:259W03486-3A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1723	HRS	0		TSN 0					
WC#: 27.061	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272103	LEFT RUDDER BIAS PRESSURE SWITCH							Component	ATA:27
PN:HTE690011	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6060814	HRS	0		TSN 0					
WC#: 27.290	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272105	RIGHT RUDDER BIAS PRESSURE SWITCH							Component	ATA:27
PN:HTE690011	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6060825	HRS	0		TSN 0					
WC#: 27.290	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273001	LEFT ELEVATOR							Component	ATA:27
PN:PN	MOS/MSC	23-Jul-10	O/C	TSN 49					
SN:UNKNOWN	HRS	580.2		TSN 580.2					
WC#: 27.070	AFL	496		TSN 496					
PROC. REF: AMM 27-30-22PROC. REF: AMM 27-30-22									
273002	RIGHT ELEVATOR							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.070	AFL	0		TSN 0					
PROC. REF: AMM 27-30-22PROC. REF: AMM 27-30-22									
273021	ELEVATOR TRIM SERVOMOTOR (OVERHAUL)							Component	ATA:27
PN:622-3260-001	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN:2TXKC	HRS	6763.7	3500	TSO 0	10263.7		2603.5		
WC#: 27.085	AFL	4989		TSO 0					
PROC. REF: AMM 27-30-61PROC. REF: AMM 27-30-61									
273022	ELEVATOR TRIM SERVOMOTOR MOUNT ASSEMBLY							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.701	AFL	0		TSN 0					
PROC. REF: AMM 22-10-30PROC. REF: AMM 22-10-30									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273025	LEFT ELEVATOR TRIM JACK							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.080	AFL	0		TSN 0					
PROC. REF: AMM 27-30-51PROC. REF: AMM 27-30-51									
273026	RIGHT ELEVATOR TRIM JACK							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.080	AFL	0		TSN 0					
PROC. REF: AMM 27-30-51PROC. REF: AMM 27-30-51									
273040	LEFT ELEVATOR TRIM TAB							Component	ATA:27
PN:258TE3-1A	MOS/MSC	23-Aug-18	O/C	TSR 214					
SN:DHB/R/DHB/187	HRS	4134.5		TSR 3533.5					
WC#: 27.090	AFL	3260		TSR 2751					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273041	RIGHT ELEVATOR TRIM TAB							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273104	LEFT STICK SHAKER							Component	ATA:27
PN:B1443-2	MOS/MSC	22-May-14	O/C	TSO 0					
SN:8622	HRS	2168.7		TSO 0					
WC#: 27.140	AFL	1712		TSO 0					
PROC. REF: AMM 27-33-20PROC. REF: AMM 27-33-20									
273105	RIGHT STICK SHAKER							Component	ATA:27
PN:B1443-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:9400	HRS	0		TSN 0					
WC#: 27.140	AFL	0		TSN 0					
PROC. REF: AMM 27-33-20PROC. REF: AMM 27-33-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273110	FORWARD STALL WARNING DETECTOR							Component	ATA:27
PN:C87706-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1116	HRS	0		TSN 0					
WC#: 27.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273111	AFT STALL WARNING DETECTOR							Component	ATA:27
PN:C87706-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1121	HRS	0		TSN 0					
WC#: 27.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273115	NO. 1 STALL WARNING VANE							Component	ATA:27
PN:1703-12	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2608	HRS	0		TSN 0					
WC#: 27.150	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273116	NO. 2 STALL WARNING VANE							Component	ATA:27
PN:1703-12	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2598	HRS	0		TSN 0					
WC#: 27.150	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
273121	THIRD CHANNEL STALL DETECTOR							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.305	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
274139 ^U	LOW LEVEL FLOAT SWITCH, VENTRAL TANK							Component	ATA:27
PN:3515000-149	MOS/MSC	30-Aug-06	O/C	TSN 0, TSO 0					
SN:FR024BP	HRS			TSN 0, TSO 0					
	AFL			TSN 0, TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275001	LEFT FLAP							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.155	AFL	0		TSN 0					
PROC. REF: AMM 27-50-151PROC. REF: AMM 27-50-151									
275002	RIGHT FLAP							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.155	AFL	0		TSN 0					
PROC. REF: AMM 27-50-151PROC. REF: AMM 27-50-151									
275025	LEFT FLAP SCREWJACK AND REDUCTION GEARBOX (OVERHAUL)							Component	ATA:27
PN:25-8EW159AC	MOS	10-Aug-18		TSO 0				OVERHAUL	
SN:BPEB/1DHB20869	HRS	4113.7		TSO 0					
WC#: 27.160	AFL	3247	4000	TSO 0	7247		1624		
PROC. REF: AMM 27-50-141PROC. REF: AMM 27-50-141									
275026	RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX (OVERHAUL)							Component	ATA:27
PN:25-8CW161AC	MOS	10-Aug-18		TSO 9				OVERHAUL	
SN:BPEB/DHB14961	HRS	4113.7		TSO 0					
WC#: 27.160	AFL	3247	4000	TSO 0	7247		1624		
PROC. REF: AMM 27-50-141PROC. REF: AMM 27-50-141									
275049	LEFT OUTBOARD FLAP VANE							Component	ATA:27
PN:25-8WF13-65A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-1459	HRS	0		TSN 0					
WC#: 27.165	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275050	RIGHT OUTBOARD FLAP VANE							Component	ATA:27
PN:25-8WF13-66A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-1442	HRS	0		TSN 0					
WC#: 27.170	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275051	LEFT INBOARD FLAP VANE							Component	ATA:27
PN:25-7WF101A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-1427	HRS	0		TSN 0					
WC#: 27.165	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275052	RIGHT INBOARD FLAP VANE							Component	ATA:27
PN:25-7WF102A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-1450	HRS	0		TSN 0					
WC#: 27.170	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275057	LEFT FLAP BEVEL SHAFT ASSEMBLY							Component	ATA:27
PN:25CF2667D	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18916	HRS	0		TSN 0					
WC#: 27.175	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275058	RIGHT FLAP BEVEL SHAFT ASSEMBLY							Component	ATA:27
PN:25CF2668D	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BPEB/DHB/18926	HRS	0		TSN 0					
WC#: 27.175	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
275073	FLAP CONTROL UNIT (OVERHAUL)							Component	ATA:27
PN:TYPE614MK2	MOS	18-Mar-21		TSO 6				OVERHAUL	
SN:1472	HRS	5100.8		TSO 0					
WC#: 27.180	AFL	3919	6000	TSO 0	9919		4296		
PROC. REF: AMM 27-50-121PROC. REF: AMM 27-50-121									
275074	FLAP POSITION TRANSMITTER							Component	ATA:27
PN:S132-3-22	MOS/MSC	31-Oct-19	O/C	TSO 0					
SN:83593	HRS	4712.1		TSO 0					
WC#: 27.590	AFL	3699		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275085	FLAP SYNCHRONIZING SYSTEM RECEIVER (OVERHAUL)							Component	ATA:27
PN:617MK4	MOS	28-Apr-22		TSO 0				OVERHAUL	
SN:1062	HRS	5938		TSO 0					
WC#: 27.185	AFL	4436	4500	TSO 0	8936		3313		
PROC. REF: AMM 27-50-162PROC. REF: AMM 27-50-162									
275091	FLAP POSITION INDICATOR							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.190	AFL	0		TSN 0					
PROC. REF: AMM 27-50-181PROC. REF: AMM 27-50-181									
275097	FLAP POSITION TRANSMITTER							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.195	AFL	0		TSN 0					
PROC. REF: AMM 27-50-181PROC. REF: AMM 27-50-181									
275145	LEFT FLAP INBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-19A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.220	AFL	4989	5000	TSN 0	9989		4366		
275146	RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-11A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.225	AFL	4989	5000	TSN 0	9989		4366		
275147	LEFT FLAP INBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-17A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.220	AFL	4989	5000	TSN 0	9989		4366		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275148	RIGHT FLAP INBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-9A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.225	AFL	4989	5000	TSN 0	9989		4366		
275149	LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-7A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.230	AFL	4989	5000	TSN 0	9989		4366		
275150	RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-13A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.235	AFL	4989	5000	TSN 0	9989		4366		
275151	LEFT FLAP OUTBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-3A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.230	AFL	4989	5000	TSN 0	9989		4366		
275152	RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component	ATA:27
PN:25CF3455-15A	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:NSN	HRS	6763.7		TSN 0					
WC#: 27.235	AFL	4989	5000	TSN 0	9989		4366		
276001	LEFT UPPER AIRBRAKE							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.240	AFL	0		TSN 0					
PROC. REF: AMM 27-61-21PROC. REF: AMM 27-61-21									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276002	RIGHT UPPER AIRBRAKE							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.245	AFL	0		TSN 0					
PROC. REF: AMM 27-61-21PROC. REF: AMM 27-61-21									
276003	LEFT LOWER AIRBRAKE							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.240	AFL	0		TSN 0					
PROC. REF: AMM 27-61-21PROC. REF: AMM 27-61-21									
276004	RIGHT LOWER AIRBRAKE							Component	ATA:27
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.245	AFL	0		TSN 0					
PROC. REF: AMM 27-61-21PROC. REF: AMM 27-61-21									
276039	LEFT AIRBRAKE JACK ASSEMBLY							Component	ATA:27
PN:AIR46521-2	MOS	29-Apr-22						OVERHAUL	
SN:APB001372	HRS	5938	3000	TSO 230.6	8707.4		1047.2		
WC#: 27.250	AFL	4436							
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									
276040	RIGHT AIRBRAKE JACK ASSEMBLY							Component	ATA:27
PN:AIR46520/2	MOS	29-Apr-22		TSO 0				OVERHAUL	
SN:LK8804666	HRS	5938	3000	TSO 0	8938		1277.8		
WC#: 27.255	AFL	4436		TSO 0					
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									
276051	LEFT AIRBRAKE JACK BODY (LIFE LIMIT)							Component	ATA:27
PN:AIR111463	MOS	29-Apr-22						LIFE LIMIT	
SN:NP2198	HRS	5938							
WC#: 27.250	AFL	4436	25000	TSN 12846	16590		10967		
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 27 - FLIGHT CONTROLS

276052	RIGHT AIRBRAKE JACK BODY (LIFE LIMIT)							Component	ATA:27
PN: AIR111462	MOS	29-Apr-22		TSN 0				LIFE LIMIT	
SN: TUR17706	HRS	5938		TSN 0					
WC#: 27.255	AFL	4436	25000	TSN 0	29436		23813		
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									

276063	LEFT AIRBRAKE JACK EYE END							Component	ATA:27
PN: PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: UNKNOWN	HRS	0		TSN 0					
WC#: 27.250	AFL	0		TSN 0					
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									

276064	RIGHT AIRBRAKE JACK EYE END							Component	ATA:27
PN: PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: UNKNOWN	HRS	0		TSN 0					
WC#: 27.255	AFL	0		TSN 0					
PROC. REF: AMM 27-61-31PROC. REF: AMM 27-61-31									

276110	STICK PUSHER							Component	ATA:27
PN: 104829001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: DH-0160-06	HRS	0		TSN 0					
WC#: 27.585	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

ATA 28 - FUEL

280001 ^S	FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS							Service	ATA:28
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 28.075	AFL	5563							
								PKG:7,91	

280002 ^S	CHECK FUEL VALVE CONTROL CABLES							Service	ATA:28
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 28.010	AFL	4989							
								PKG:23,92	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
PROC. REF: AMM 28-20-83PROC. REF: AMM 28-20-83									
280003 ^S FUNCTIONAL TEST LP VALVES Service ATA:28									
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 28.050	AFL	4989							
								PKG:31,93	
PROC. REF: AMM 28-20-00PROC. REF: AMM 28-20-00									
280005 ^S VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS Service ATA:28									
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 28.165	AFL	4989							
								PKG:27,92	
280006 ^S VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS Service ATA:28									
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 28.170	AFL	4989							
								PKG:27,92	
280007 ^S VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS Service ATA:28									
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 28.165	AFL	4989							
								PKG:28,92	
280008 ^S VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS Service ATA:28									
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 28.170	AFL	4989							
								PKG:28,92	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
280010	CHECK CABLE TENSION OF FUEL CONTROL VALVES								Service ATA:28
	MOS/MSC	13-Jul-07	O/C						
	HRS	264.1							
WC#: 28.020	AFL	212							
PROC. REF: AMM 28-20-83PROC. REF: AMM 28-20-83									
280014	CHECK LEFT BOOST PUMP BRUSH LENGTH								Service ATA:28
PN:2C40-2	MOS/MSC		N/R						
SN:UNKNOWN	HRS								
WC#: 28.080	AFL								
									PKG:27,92
280015	CHECK RIGHT BOOST PUMP BRUSH LENGTH								Service ATA:28
PN:2C40-2	MOS/MSC	03-Mar-16	N/R						
SN:UNKNOWN	HRS	2853.9							
WC#: 28.080	AFL	2274							
									PKG:28,92
280016 ^S	VISUAL INSPECTION LOW PRESSURE FUEL VALVE SUPPORT STRUT. PART NO. 25 PF361, 25 PF361-5A (MOD. 25G310A) AND 25 PF363								Service ATA:28
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 28.195	AFL	4577							
									PKG:96
281067	VENTRAL FUEL TANK								Component ATA:28
PN:25-8PT463-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-576	HRS	0		TSN 0					
WC#: 28.015	AFL	0		TSN 0					
PROC. REF: AMM 28-10-15PROC. REF: AMM 28-10-15									
281509 ^U	#1 NON-RETURN VALVE								Component ATA:28
PN:9840000J	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5060294	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281510 ^U	#2 NON-RETURN VALVE							Component	ATA:28
PN:9840000J	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:43050832	HRS	0		TSN 0					
	AFL	0		TSN 0					
281511 ^U	LH NON-RETURN VALVE							Component	ATA:28
PN:9840078J	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:44050435	HRS	0		TSN 0					
	AFL	0		TSN 0					
281512 ^U	RH NON-RETURN VALVE							Component	ATA:28
PN:9840078J	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:51051085	HRS	0		TSN 0					
	AFL	0		TSN 0					
281513 ^U	LH ACTUATOR							Component	ATA:28
PN:HTE9044-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M162GB0106	HRS	0		TSN 0					
	AFL	0		TSN 0					
281514 ^U	RH ACTUATOR							Component	ATA:28
PN:HTE9044-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M188GB1205	HRS	0		TSN 0					
	AFL	0		TSN 0					
282001	LEFT WING HIGH LEVEL FLOAT SWITCH							Component	ATA:28
PN:3515000-107	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:38050135	HRS	0		TSN 0					
WC#: 28.025	AFL	0		TSN 0					
PROC. REF: AMM 28-22-143PROC. REF: AMM 28-22-143									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282002	RIGHT WING HIGH LEVEL FLOAT SWITCH							Component	ATA:28
PN:3515000-107	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:47050951	HRS	0		TSN 0					
WC#: 28.025	AFL	0		TSN 0					
PROC. REF: AMM 28-22-143PROC. REF: AMM 28-22-143									
282004	LOW PRESSURE FUEL COCK VALVE							Component	ATA:28
PN:HTE9596-1	MOS/MSC	07-Mar-14	O/C	TSO 0					
SN:29110456	HRS	2137.3		TSO 0					
WC#: 28.191	AFL	1688		TSO 0					
PROC. REF: AMM 28-20-52PROC. REF: AMM 28-20-52									
282005	LEFT FUEL COCK							Component	ATA:28
PN:7913003K	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49050191	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282006	RIGHT FUEL COCK							Component	ATA:28
PN:7913003K	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49050186	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282007	LEFT FUEL ACTUATOR							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.185	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282008	RIGHT FUEL ACTUATOR							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.185	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282009	LEFT FUEL NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
PROC. REF: AMM 28-20-32PROC. REF: AMM 28-20-32									
282010	RIGHT FUEL NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
282011	LEFT FUEL NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.192	AFL	0		TSN 0					
PROC. REF: AMM 28-20-32PROC. REF: AMM 28-20-32									
282012	RIGHT FUEL NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.193	AFL	0		TSN 0					
PROC. REF: AMM 28-20-32PROC. REF: AMM 28-20-32									
282025	APU FUEL PRESSURE SWITCH							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.030	AFL	0		TSN 0					
PROC. REF: AMM 28-22-91PROC. REF: AMM 28-22-91									
282053	LEFT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.035	AFL	0		TSN 0					
PROC. REF: AMM 28-20-32PROC. REF: AMM 28-20-32									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282054	RIGHT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.035	AFL	0		TSN 0					
PROC. REF: AMM 28-20-32PROC. REF: AMM 28-20-32									
282253	LEFT HAND LP FUEL VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.045	AFL	0		TSN 0					
PROC. REF: AMM 28-20-52PROC. REF: AMM 28-20-52									
282254	RIGHT HAND LP FUEL VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.045	AFL	0		TSN 0					
PROC. REF: AMM 28-20-52PROC. REF: AMM 28-20-52									
282289	FUEL 3C VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.055	AFL	0		TSN 0					
PROC. REF: AMM 28-20-61PROC. REF: AMM 28-20-61									
282295	FUEL 4S VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.060	AFL	0		TSN 0					
PROC. REF: AMM 28-20-61, AMM 28-20-71PROC. REF: AMM 28-20-61, AMM 28-20-71									
282301	VENTRAL TANK FUEL TRANSFER VALVE							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.065	AFL	0		TSN 0					
PROC. REF: AMM 28-20-78PROC. REF: AMM 28-20-78									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282343	LEFT BOOST PUMP							Component	ATA:28
PN:2C40-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.080	AFL	0		TSN 0					
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12									
282344	RIGHT BOOST PUMP							Component	ATA:28
PN:2C40-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.080	AFL	0		TSN 0					
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12									
282384	SINGLE-POINT PRESSURE CONTROL VALVE							Component	ATA:28
PN:1159000-1	MOS/MSC	22-Oct-21	O/C	TSO 19					
SN:FR011BK	HRS	5520.1		TSO 0					
WC#: 28.175	AFL	4179		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282500 ^U	LH NON-RETURN VALVE							Component	ATA:28
PN:9807870	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:51050685	HRS	0		TSN 0					
	AFL	0		TSN 0					
282501 ^U	RH NON-RETURN VALVE							Component	ATA:28
PN:9807870	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:51050684	HRS	0		TSN 0					
	AFL	0		TSN 0					
282502 ^U	#1 FUEL VALVE							Component	ATA:28
PN:HTE1984-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49051162	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282503 ^U	#2 FUEL VALVE							Component	ATA:28
PN:HTE1984-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49051158	HRS	0		TSN 0					
	AFL	0		TSN 0					
282504 ^U	#3 FUEL VALVE							Component	ATA:28
PN:HTE1984-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49051159	HRS	0		TSN 0					
	AFL	0		TSN 0					
282505 ^U	#4 FUEL VALVE							Component	ATA:28
PN:HTE1984-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49051161	HRS	0		TSN 0					
	AFL	0		TSN 0					
282506 ^U	PRESSURE SWITCH							Component	ATA:28
PN:HTE690009	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:11060926	HRS	0		TSN 0					
	AFL	0		TSN 0					
284013	LEFT NO. 1 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU04	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0099304	HRS	0		TSN 0					
WC#: 28.100	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284014	RIGHT NO.1 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU04	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0112802	HRS	0		TSN 0					
WC#: 28.100	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284015	LEFT NO.2 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0131607	HRS	0		TSN 0					
WC#: 28.105	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284016	RIGHT NO.2 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0131609	HRS	0		TSN 0					
WC#: 28.105	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284017	LEFT NO.3 FUEL TANK UNIT								Component ATA:28
PN:0207KTU3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0131505	HRS	0		TSN 0					
WC#: 28.110	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284018	RIGHT NO.3 FUEL TANK UNIT								Component ATA:28
PN:0207KTU3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0131508	HRS	0		TSN 0					
WC#: 28.110	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284019	LEFT NO.4 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0127802	HRS	0		TSN 0					
WC#: 28.115	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284020	RIGHT NO.4 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0127803	HRS	0		TSN 0					
WC#: 28.115	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284021	LEFT NO.5 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0137702	HRS	0		TSN 0					
WC#: 28.120	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284022	RIGHT NO.5 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0137703	HRS	0		TSN 0					
WC#: 28.120	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284023	LEFT NO.6 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0134106	HRS	0		TSN 0					
WC#: 28.125	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284024	RIGHT NO.6 FUEL TANK UNIT								Component ATA:28
PN:0204KTU-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR1034108	HRS	0		TSN 0					
WC#: 28.125	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284025	LEFT NO.7 FUEL TANK CONTENTS UNIT								Component ATA:28
PN:0204KTU-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0143202	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284026	RIGHT NO.7 FUEL TANK CONTENTS UNIT								Component ATA:28
PN:0204KTU-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FR0147904	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284115	LEFT FUEL QUANTITY INDICATOR							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.140	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284116	RIGHT FUEL QUANTITY INDICATOR							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.140	AFL	0		TSN 0					
PROC. REF: AMM 28-42-03PROC. REF: AMM 28-42-03									
284130	FUEL PRESSURE SWITCH							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.194	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
284139	VENTRAL TANK LOW LEVEL FLOAT SWITCH							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.145	AFL	0		TSN 0					
PROC. REF: AMM 28-44-33PROC. REF: AMM 28-44-33									
284145	VENTRAL TANK HIGH LEVEL FLOAT SWITCH							Component	ATA:28
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.150	AFL	0		TSN 0					
PROC. REF: AMM 28-44-33PROC. REF: AMM 28-44-33									
284151	LEFT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:51050005	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
PROC. REF: AMM 28-44-43PROC. REF: AMM 28-44-43									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284152	RIGHT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:46050635	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
PROC. REF: AMM 28-44-43PROC. REF: AMM 28-44-43									
289000 ^U	MAIN REFUEL VALVE ACTUATOR							Component	ATA:28
PN:HTE9044-001	MOS/MSC	07-Mar-14	O/C	TSO 0					
SN:189GB245/H	HRS	2137.3		TSO 0					
	AFL	1688		TSO 0					
ATA 29 - HYDRAULIC POWER									
290003 ^S	REPLACE HYDRAULIC SUCTION FILTER ELEMENT							Service	ATA:29
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 29.070	AFL	5563							
PROC. REF: AMM 29-10-21PROC. REF: AMM 29-10-21									
290004 ^S	FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM							Service	ATA:29
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 29.075	AFL	5563							
PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00									
290005 ^S	OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM							Service	ATA:29
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 29.115	AFL	5563							
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
290006 ^S	DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM							Service	ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 29.160	AFL	4989							PKG:25,92
290007 ^S	TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING							Service	ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 29.165	AFL	4989							PKG:30,92
PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00									
290008 ^S	CHECK EMERGENCY BRAKE SYSTEM LEAK RATE							Service	ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 29.175	AFL	4989							PKG:30,92
290009 ^S	FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM							Service	ATA:29
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 29.180	AFL	5563							PKG:18,91
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00									
290010 ^S	FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM							Service	ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 29.170	AFL	4989							PKG:30,92
PROC. REF: AMM 29-10-13PROC. REF: AMM 29-10-13									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
290011	^S	CLEAN FULL-FLOW RELIEF VALVE							Service ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#:	29.005	AFL	4989						
PROC. REF: AMM 29-10-71PROC. REF: AMM 29-10-71									PKG:37,93
290012	^S	INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM							Service ATA:29
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#:	29.145	AFL	4989						
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00									PKG:37,93
291018		PRESSURE REGULATOR VALVE							Component ATA:29
PN:PAS129-163	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HAY0070	HRS	0		TSN 0					
WC#:	29.010	AFL	0	TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291025		NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#:	29.015	AFL	0	TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291026		NO. 2 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#:	29.015	AFL	0	TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291037		LEFT HYDRAULIC SUCTION VALVE							Component ATA:29
PN:7907015E	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49050265	HRS	0		TSN 0					
WC#:	29.020	AFL	0	TSN 0					
PROC. REF: AMM 29-10-31PROC. REF: AMM 29-10-31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291038	RIGHT HYDRAULIC SUCTION VALVE							Component	ATA:29
PN:7907015E	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:49050271	HRS	0		TSN 0					
WC#: 29.020	AFL	0		TSN 0					
PROC. REF: AMM 29-10-31PROC. REF: AMM 29-10-31									
291049	NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE (OVERHAUL)							Component	ATA:29
PN:AIR45394-0	MOS	28-Apr-22		TSO 7				OVERHAUL	
SN:APB950328	HRS	5938		TSO 0					
WC#: 29.025	AFL	4436	4500	TSO 0	8936		3313		
291050	NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE (OVERHAUL)							Component	ATA:29
PN:AIR45394-0	MOS	28-Apr-22		TSO 16				OVERHAUL	
SN:LK8806127	HRS	5938		TSO 0					
WC#: 29.025	AFL	4436	4500	TSO 0	8936		3313		
291061	NO. 1 DUNLOP VALVE							Component	ATA:29
PN:AC69536	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:ELR190	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291073	PRESSURE MAINTAINING VALVE (OVERHAUL)							Component	ATA:29
PN:AIR45474-0	MOS	08-Dec-23		TSN 0				OVERHAUL	
SN:APB95092	HRS	6763.7		TSN 0					
WC#: 29.030	AFL	4989	5000	TSN 0	9989		4366		
291079	GROUND SERVICE HANDPUMP SUPPLY NONRETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291091	MAIN HYDRAULIC RESERVOIR							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.040	AFL	0		TSN 0					
PROC. REF: AMM 29-10-13PROC. REF: AMM 29-10-13									
291096	HYDRAULIC PRESSURE GAUGE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291103	MAIN HYDRAULIC ACCUMULATOR							Component	ATA:29
PN:AIR45574-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB060920	HRS	0		TSN 0					
WC#: 29.050	AFL	0		TSN 0					
PROC. REF: AMM 29-10-81PROC. REF: AMM 29-10-81									
291109	EMERGENCY BRAKE ACCUMULATOR							Component	ATA:29
PN:AIR45574-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB060912	HRS	0		TSN 0					
WC#: 29.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291131	HYDRAULIC FILTER							Component	ATA:29
PN:MFHA15104	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF06/0107	HRS	0		TSN 0					
WC#: 29.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291132	PRESSURE FILTER ASSEMBLY							Component	ATA:29
PN:2125H4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FYH208419	HRS	0		TSN 0					
WC#: 29.065	AFL	0		TSN 0					
PROC. REF: AMM 29-10-61PROC. REF: AMM 29-10-61									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291163	NO. 1 ENGINE HYDRAULIC PUMP								Component ATA:29
PN:4202203	MOS/MSC	28-Jul-21	O/C	TSO 0					
SN:AK677	HRS	5375.2		TSO 0					
WC#: 29.080	AFL	4075		TSO 0					
PROC. REF: AMM 29-10-54PROC. REF: AMM 29-10-54									
291164	NO. 2 ENGINE HYDRAULIC PUMP								Component ATA:29
PN:4202203	MOS/MSC	02-Mar-23	O/C	TSO 2					
SN:BR 174	HRS	6393.7		TSO 0					
WC#: 29.080	AFL	4729		TSO 0					
PROC. REF: AMM 29-10-54PROC. REF: AMM 29-10-54									
291182	GROUND SERVICING HANDPUMP								Component ATA:29
PN:AIR45424-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB051822	HRS	0		TSN 0					
WC#: 29.085	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291186	NO. 1 NON-RETURN TANK PRESSURE VALVE								Component ATA:29
PN:HTE4350	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M0160VNR0106	HRS	0		TSN 0					
WC#: 29.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291193	NO. 2 NON-RETURN TANK PRESSURE VALVE								Component ATA:29
PN:HTE4350	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:M0161VNR0106	HRS	0		TSN 0					
WC#: 29.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
291507 ^U	RELIEF VALVE								Component ATA:29
PN:AIR45418-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB051921	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291509 ^U	NON-RETURN VALVE							Component	ATA:29
PN:AIR45468-0	MOS/MSC	23-Jul-10	O/C	TSO 0					
SN:APB082713	HRS	580.2		TSO 0					
	AFL	496		TSO 0					
291514 ^U	NON-RETURN VALVE							Component	ATA:29
PN:AIR48026-0-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB050654	HRS	0		TSN 0					
	AFL	0		TSN 0					
291515 ^U	RELIEF VALVE HYDRAULIC RES.							Component	ATA:29
PN:AIR87236-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB052145	HRS	0		TSN 0					
	AFL	0		TSN 0					
291516 ^U	NON-RETURN VALVE							Component	ATA:29
PN:AIR87240-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB052591	HRS	0		TSN 0					
	AFL	0		TSN 0					
291519 ^U	HYDRAULIC FILTER							Component	ATA:29
PN:AIR87366-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF05/0346	HRS	0		TSN 0					
	AFL	0		TSN 0					
291523 ^U	NON RETURN VALVE HYDRAULIC RES.							Component	ATA:29
PN:HTE4853	MOS/MSC	27-Sep-12	O/C	TSN 0					
SN:39115885	HRS	1607.1		TSN 0					
	AFL	1293		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
292001	EMERGENCY HYDRAULIC TANK							Component	ATA:29
PN:25HC161D	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:WN110916/7	HRS	0		TSN 0					
WC#: 29.095	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
292003	SUCTION FILTER ASSEMBLY							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.100	AFL	0		TSN 0					
PROC. REF: AMM 29-10-21PROC. REF: AMM 29-10-21									
292007	EMERGENCY HYDRAULIC HAND PUMP							Component	ATA:29
PN:AIR45448-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB060257	HRS	0		TSN 0					
WC#: 29.105	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
292013	AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH							Component	ATA:29
PN:3515000-76	MOS/MSC	26-Apr-19	O/C	TSO 0					
SN:FR.609BG	HRS	4513.7		TSO 0					
WC#: 29.110	AFL	3535		TSO 0					
292031	EMERGENCY TANK ON/OFF HAND PUMP VALVE							Component	ATA:29
PN:AIR45446-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB061122	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
292037	EMERGENCY SYSTEM CHECK VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
293001	NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH							Component	ATA:29
PN:211C223-647	MOS/MSC	18-Jul-14	O/C						
SN:M017902	HRS	2236.1							
WC#: 29.130	AFL	1773							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
293002	NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
293013	EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH (OVERHAUL)							Component	ATA:29
PN:TP42001	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:1635	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 29.135	AFL	3858		TSO 0					
293019	HYDRAULIC PRESSURE TRANSDUCER							Component	ATA:29
PN:695-4-20	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7092-3-218	HRS	0		TSN 0					
WC#: 29.140	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
293024	HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.145	AFL	0		TSN 0					
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00									
294001	LEFT HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.183	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
294002	RIGHT HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.184	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
294003	NO. 1 HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.186	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
294004	NO. 2 HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.187	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
294005	HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.188	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
294006	HYDRAULIC RELIEF VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.189	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
294007	LEFT HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.190	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
294008	RIGHT HYDRAULIC NON-RETURN VALVE							Component	ATA:29
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 29.191	AFL	0		TSN 0					
PROC. REF: AMM 29-10-68PROC. REF: AMM 29-10-68									
ATA 30 - ICE AND RAIN PROTECTION									
300001 ^S	FUNCTIONAL TEST ROTARY ICE DETECTOR							Service	ATA:30
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 30.085	AFL	5563							
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00									
300002 ^S	OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM							Service	ATA:30
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 30.080	AFL	4989							
PROC. REF: AMM 30-41-00PKG:7,91									
300003 ^S	REPLACE AIRFRAME DE-ICING FILTER ELEMENT							Service	ATA:30
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 30.020	AFL	5563							
PROC. REF: AMM 30-10-52PKG:12,91									
300004 ^S	FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS							Service	ATA:30
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 30.065	AFL	4989							
PROC. REF: AMM 30-35-15PKG:19,92									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
300005 ^S		REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER						Service	ATA:30
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 30.045	AFL	4989							
PROC. REF: AMM 30-10-43PROC. REF: AMM 30-10-43									PKG:24,92
300007		PURGE ICE PROTECTION SYSTEM						Service	ATA:30
	MOS	09-Jul-25	1		09-Aug-25		OVD		
	HRS	7618.8							
WC#: 30.090	AFL	5593							
PROC. REF: AMM 12-30-00PROC. REF: AMM 12-30-00									
301001		TKS DE-ICER TANK						Component	ATA:30
PN:08301-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST05L271	HRS	0		TSN 0					
WC#: 30.010	AFL	0		TSN 0					
PROC. REF: AMM 30-10-35PROC. REF: AMM 30-10-35									
301007		AIRFRAME DE-ICING PUMP ASSEMBLY						Component	ATA:30
PN:XA9511E009	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06B590	HRS	0		TSN 0					
WC#: 30.015	AFL	0		TSN 0					
PROC. REF: AMM 30-10-43PROC. REF: AMM 30-10-43									
301013		AIRFRAME DE-ICING FILTER ASSEMBLY						Component	ATA:30
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.020	AFL	0		TSN 0					
PROC. REF: AMM 30-10-52PROC. REF: AMM 30-10-52									
301025		DE-ICING VALVE ASSEMBLY						Component	ATA:30
PN:FV131-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06B582	HRS	0		TSN 0					
WC#: 30.025	AFL	0		TSN 0					
PROC. REF: AMM 30-10-43PROC. REF: AMM 30-10-43									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301037	DE-ICING SYSTEM CONTENTS GAUGE							Component	ATA:30
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
301043	DE-ICING SYSTEM CONTENTS FLOAT							Component	ATA:30
PN:FRH070001	MOS/MSC	07-Feb-24	O/C	TSN 0					
SN:45230153	HRS	6863.5		TSN 0					
WC#: 30.035	AFL	5052							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
301063	EMPENNAGE TKS PROPORTION UNIT							Component	ATA:30
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 30.050	AFL	0		TSN 0					
PROC. REF: AMM 30-10-25PROC. REF: AMM 30-10-25									
301067	TKS VENT VALVE							Component	ATA:30
PN:FV141	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST05M391	HRS	0		TSN 0					
WC#: 30.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
301069	TKS PRESSURE SWITCH							Component	ATA:30
PN:P067D075	MOS/MSC	23-Oct-17	O/C	TSN 0					
SN:CAV117F192	HRS	3789.1		TSN 0					
WC#: 30.060	AFL	3002		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
301509 ^U	VHF AERIAL							Component	ATA:30
PN:16-21-1T	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7161	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
302000 ^U	PIPE TUBE WELDED BLEED AIR-R/H							Component	ATA:30
PN:C46P18121-1	MOS/MSC	21-Mar-19	O/C	TSN 0					
SN:UNKNOWN	HRS	4466.8		TSN 0					
	AFL	3503		TSN 0					
304019	NO. 1 WINDSCREEN (A PANEL) CONTROLLER							Component	ATA:30
PN:ND0075-2001	MOS/MSC	28-Jul-21	O/C	TSN 180					
SN:L355781	HRS	5375.2		TSN 5375.2					
WC#: 30.070	AFL	4075		TSN 4075					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
304020	NO. 2 WINDSCREEN (A PANEL) CONTROLLER							Component	ATA:30
PN:ND0075-2001	MOS/MSC	28-Jul-21	O/C	TSN 180					
SN:L355788	HRS	5375.2		TSN 5375.2					
WC#: 30.070	AFL	4075		TSN 4075					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
304022	NO. 1 WINDSCREEN (B PANEL) CONTROLLER							Component	ATA:30
PN:ND0075-2011	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355845	HRS	0		TSN 0					
WC#: 30.075	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
304023	NO. 2 WINDSCREEN (B PANEL) CONTROLLER							Component	ATA:30
PN:ND0075-2011	MOS/MSC	03-Jan-23	O/C	TSN 73					
SN:L461427	HRS	6323.7		TSN 0					
WC#: 30.075	AFL	4680		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
304500 ^U	FILTER UNIT							Component	ATA:30
PN:25-9NF4027-645	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355693	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
304501 ^U	FILTER UNIT							Component	ATA:30
PN:25-9NF4027-647	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355701	HRS	0		TSN 0					
	AFL	0		TSN 0					
304502 ^U	FILTER UNIT							Component	ATA:30
PN:25-9NF4027-649	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355716	HRS	0		TSN 0					
	AFL	0		TSN 0					
304503 ^U	FILTER UNIT							Component	ATA:30
PN:25-9NF4027-651	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355589	HRS	0		TSN 0					
	AFL	0		TSN 0					
308001	ROTARY ICE DETECTOR							Component	ATA:30
PN:NF0075-667	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:L355594	HRS	0		TSN 0					
WC#: 30.085	AFL	0		TSN 0					
PROC. REF: AMM 30-80-11PROC. REF: AMM 30-80-11									
ATA 31 - INDICATING/RECORDING SYSTEMS									
310002	LIGHTNING SENSOR ANTENNA							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.015	AFL	0		TSN 0					
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
310006 ^U	#1 CURRENT MONITOR							Component	ATA:31
PN:E37040S	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4389	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
310007 ^U		#2 CURRENT MONITOR						Component	ATA:31
PN:E37040S	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4392	HRS	0		TSN 0					
	AFL	0		TSN 0					
310100		LIGHTNING PROCESSOR UNIT						Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.010	AFL	0		TSN 0					
PROC. REF: MMA 34-43-05, MMA 34-43-10PROC. REF: MMA 34-43-05, MMA 34-43-10									
311001		TKS TIMER						Component	ATA:31
PN:100-1805-02	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:05H8	HRS	0		TSN 0					
WC#: 31.020	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
311508 ^U		CONTROL						Component	ATA:31
PN:822-1121-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:168D81	HRS	0		TSN 0					
	AFL	0		TSN 0					
311597 ^U		CONTACTOR						Component	ATA:31
PN:A848MAS	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:CP-13352	HRS	0		TSN 0					
	AFL	0		TSN 0					
312001		PILOT CLOCK						Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
312002	COPILOT CLOCK							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
312008	O.A.T. INDICATOR							Component	ATA:31
PN:2141-01-0014	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82655	HRS	0		TSN 0					
WC#: 31.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
312009	PITOT AMMETER							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313005	LEFT CURRENT LEVEL INDICATOR							Component	ATA:31
PN:770-537	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2393	HRS	0		TSN 0					
WC#: 31.040	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313006	RIGHT CURRENT LEVEL INDICATOR							Component	ATA:31
PN:770-537	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2410	HRS	0		TSN 0					
WC#: 31.040	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313007	CABIN TEMPERATURE INDICATOR							Component	ATA:31
PN:2132-01-0015	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82596	HRS	0		TSN 0					
WC#: 31.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313008	DC VOLTMETER							Component	ATA:31
PN:2132-01-0012	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82483	HRS	0		TSN 0					
WC#: 31.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313009	LEFT DC AMMETER							Component	ATA:31
PN:2132-01-0013	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82896	HRS	0		TSN 0					
WC#: 31.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313010	AC VOLTMETER							Component	ATA:31
PN:2132-01-0014	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82639	HRS	0		TSN 0					
WC#: 31.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313011	RIGHT DC AMMETER							Component	ATA:31
PN:2132-01-0013	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82967	HRS	0		TSN 0					
WC#: 31.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313014	DUCT AIR TEMPERATURE INDICATOR							Component	ATA:31
PN:2132-01-0018	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82591	HRS	0		TSN 0					
WC#: 31.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313015	TEMPERATURE SELECTOR							Component	ATA:31
PN:25-6MC415	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:627578-01492	HRS	0		TSN 0					
WC#: 31.075	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313020	FUEL PROCESSOR UNIT							Component	ATA:31
PN:0107KPU1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FE003253	HRS	0		TSN 0					
WC#: 31.080	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313101	ANGLE OF ATTACK INDICATOR COMPUTER							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.095	AFL	0		TSN 0					
PROC. REF: MMA 31-20-06, AMM 31-20-05PROC. REF: MMA 31-20-06, AMM 31-20-05									
313109	NO. 1 ANGLE OF ATTACK INDEXER							Component	ATA:31
PN:965-0113-003	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2999	HRS	0		TSN 0					
WC#: 31.100	AFL	0		TSN 0					
PROC. REF: MMA 31-20-06, AMM 31-20-05PROC. REF: MMA 31-20-06, AMM 31-20-05									
313110	NO. 2 ANGLE OF ATTACK INDEXER							Component	ATA:31
PN:965-0113-003	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3000	HRS	0		TSN 0					
WC#: 31.100	AFL	0		TSN 0					
PROC. REF: MMA 31-20-06, AMM 31-20-05PROC. REF: MMA 31-20-06, AMM 31-20-05									
313201	BRAKE PRESSURE INDICATOR							Component	ATA:31
PN:696-1-13	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:82681	HRS	0		TSN 0					
WC#: 31.105	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313301	FATIGUE METER							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	N/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.110	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

314008	NO. 1 INCLINOMETER							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.115	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

314009	NO. 2 INCLINOMETER							Component	ATA:31
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.115	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

314012	NO. 1 IAPS (ICC 3000) CARD CAGE							Component	ATA:31
PN:822-1129-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27Y8R	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

314300 ^U	S1 PC BOARD B							Component	ATA:31
PN:25-6NF693-3A	MOS/MSC	30-Jun-10	O/C	TSN 0					
SN:L2140	HRS	573.3		TSN 0					
	AFL	488		TSN 0					

ATA 32 - LANDING GEAR

320001 ^S	TEST BRAKING SYSTEMS							Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 32.305	AFL	5563							
								PKG:18,91	
PROC. REF: AMM 32-40-00PROC. REF: AMM 32-40-00									

320002 ^S	FUNCTIONAL TEST MAXARET UNITS							Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 32.370	AFL	5563							
								PKG:18,91	
PROC. REF: AMM 32-40-101PROC. REF: AMM 32-40-101									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320003	^S	CHECK NOSE GEAR LEG ASSEMBLY						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.430	AFL	5563							
									PKG:18,91
320004	^S	CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.435	AFL	5563							
									PKG:18,91
320005	^S	INSPECT NOSEWHEEL STEERING JACK						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.470	AFL	5563							
									PKG:18,91
PROC. REF: AMM 32-50-00PROC. REF: AMM 32-50-00									
320006	^S	INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.450	AFL	5563							
									PKG:18,91
320007	^S	INSPECT NOSEWHEEL STEERING ON/OFF VALVE						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.350	AFL	5563							
									PKG:18,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320008	^S	CHECK NOSE GEAR DRAG STAY ASSEMBLY						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.440	AFL	5563							
PROC. REF: AMM 32-20-21PROC. REF: AMM 32-20-21									PKG:18,91
320009	^S	DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.545	AFL	5563							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									PKG:18,91
320010	^S	CHECK MAIN GEAR LEG ASSEMBLIES						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.420	AFL	5563							
PROC. REF: AMM 12-32-00, AMM 32-10-12PROC. REF: AMM 12-32-00, AMM 32-10-12									PKG:18,91
320011	^S	INSPECT MAIN LANDING GEAR SIDE-STAYS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.010	AFL	5563							
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									PKG:18,91
320012	^S	CHECK MAIN LANDING GEAR TORQUE LINKS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.015	AFL	5563							
PROC. REF: AMM 32-10-12PROC. REF: AMM 32-10-12									PKG:18,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320013	^S	INSPECT MAIN LANDING GEAR DOORS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.460	AFL	5563							PKG:18,91
320014	^S	INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.425	AFL	5563							PKG:18,91
320015	^S	INSPECT REVERSING VALVES AND OPERATING MECHANISMS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.445	AFL	5563							PKG:18,91
320016	^S	CHECK STEERING SYSTEM CABLES AND CHAINS						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600	(+50/-50)					
WC#: 32.475	AFL	4989							PKG:22,92
PROC. REF: AMM 32-50-00PROC. REF: AMM 32-50-00									
320017	^S	CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600	(+50/-50)					
WC#: 32.180	AFL	4989							PKG:30,92
PROC. REF: AMM 32-20-21PROC. REF: AMM 32-20-21									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320018 ^S		CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 32.350	AFL	4989							PKG:30,92
320019 ^S		INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 32.385	AFL	4989							PKG:42,93
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									
320020 ^S		CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 32.185	AFL	4989							PKG:42,93
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									
320021 ^S		CLEAN RESTRICTOR VALVES						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 32.145	AFL	4989							PKG:42,93
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01									
320022 ^S		CHECK BRAKE MASTER CYLINDERS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 32.465	AFL	5563							PKG:10,91
PROC. REF: AMM 32-40-00PROC. REF: AMM 32-40-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320023	^S	CHECK BRAKE HOSES TO MASTER CYLINDERS						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 32.455	AFL	4989							PKG:22,92
320024	^S	REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 32.375	AFL	4989							PKG:30,92
PROC. REF: AMM 32-40-91PROC. REF: AMM 32-40-91									
320027	^S	VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE						Service	ATA:32
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 32.350	AFL	4577							PKG:96
320028		INSPECT/NDT MAIN LANDING GEAR FAIRING STRUT						Service	ATA:32
	MOS/MSC	22-May-14	O/C						
	HRS	2168.7							
WC#: 32.035	AFL	1712							
PROC. REF: NTM 32-10-05PROC. REF: NTM 32-10-05									
320029		CHECK NOSE LANDING GEAR DRAG STAY						Service	ATA:32
	MOS/MSC	30-Aug-18	A/R						
	HRS	4143.7							
WC#: 32.070	AFL	3268							
PROC. REF: AMM 32-20-21PROC. REF: AMM 32-20-21									
320033	^S	DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 32.095	AFL	5563							PKG:18,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
320034	^S	INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.510	AFL	5563							
									PKG:18,91
320035	^S	INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600	(+50/-50)					
WC#: 32.520	AFL	4989							
									PKG:30,92
320036	^S	INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK						Service	ATA:32
	MOS	08-Dec-23							
	HRS	6763.7	1600	(+50/-50)					
WC#: 32.530	AFL	4989							
									PKG:30,92
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
320037	^S	CHECK NOSE LEG ASSEMBLY TORQUE LINKS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800	(+40/-10)					
WC#: 32.540	AFL	5563							
									PKG:18,91
PROC. REF: AMM 32-20-12PROC. REF: AMM 32-20-12									
320038		LUBRICATE MAIN LANDING GEAR SIDESTAY SHIMS						Service	ATA:32
	MOS/MSC	23-Jan-16	A/R						
	HRS	2801.6							
WC#: 32.570	AFL	2235							
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320039 ^S		INSPECTION OF LEFT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
	AFL	5563							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:18,91
320039 ^S		INSPECTION OF RIGHT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS						Service	ATA:32
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
	AFL	5563							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:18,91
320500 ^U		FAIRING SUB ASSY						Component	ATA:32
PN:25-8FC3603-601A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7286878	HRS	0		TSN 0					
	AFL	0		TSN 0					
320501 ^U		FAIRING						Component	ATA:32
PN:259W01185-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06A082	HRS	0		TSN 0					
	AFL	0		TSN 0					
321001		LEFT MAIN LEG (OVERHAUL)						Component	ATA:32
PN:140-810044-17	MOS	10-Aug-18	144	TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0072/06	HRS	4113.7		TSO 0					
WC#: 32.020	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-10-12PROC. REF: AMM 32-10-12									
321002		RIGHT MAIN LEG (OVERHAUL)						Component	ATA:32
PN:140-810044-18	MOS	10-Aug-18	144	TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0053/06	HRS	4113.7		TSO 0					
WC#: 32.020	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-10-12PROC. REF: AMM 32-10-12									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321013	LEFT SIDESTAY (OVERHAUL)							Component	ATA:32
PN:140-810043-11	MOS	10-Aug-18	144	TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0070/06	HRS	4113.7		TSO 0					
WC#: 32.025	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									
321014	RIGHT SIDESTAY (OVERHAUL)							Component	ATA:32
PN:140-810043-12	MOS	10-Aug-18	144	TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0070/06	HRS	4113.7		TSO 0					
WC#: 32.030	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									
321015	LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM (LIFE LIMIT)							Component	ATA:32
PN:140-810125-0001	MOS	10-Aug-18						LIFE LIMIT	
SN:PLT0067	HRS	4113.7							
WC#: 32.025	AFL	3247	10000	TSN 3247	10000	10000	4377		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									
321016	RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM (LIFE LIMIT)							Component	ATA:32
PN:140-810125-0002	MOS	10-Aug-18						LIFE LIMIT	
SN:PLT-0062	HRS	4113.7							
WC#: 32.030	AFL	3247	10000	TSN 3247	10000	10000	4377		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									
321017	LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM (LIFE LIMIT)							Component	ATA:32
PN:140-810064-0001	MOS	10-Aug-18						LIFE LIMIT	
SN:PLT0088	HRS	4113.7							
WC#: 32.025	AFL	3247	12000	TSN 3247	12000	12000	6377		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									
321018	RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM (LIFE LIMIT)							Component	ATA:32
PN:140-810064-0002	MOS	10-Aug-18						LIFE LIMIT	
SN:SAM006	HRS	4113.7							
WC#: 32.030	AFL	3247	12000	TSN 3247	12000	12000	6377		
PROC. REF: AMM 32-10-25PROC. REF: AMM 32-10-25									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321050	LEFT MAIN LANDING GEAR UPPER CASING (LIFE LIMIT)							Component	ATA:32
PN:25-8UM169-5	MOS	10-Aug-18						LIFE LIMIT	
SN:J001479-000/11427	HRS	4113.7							
WC#: 32.390	AFL	3247	24000	TSN 2182	25065		19442		
321051	RIGHT MAIN LANDING GEAR UPPER CASING (LIFE LIMIT)							Component	ATA:32
PN:25-8UM69-6	MOS	10-Aug-18						LIFE LIMIT	
SN:J002030-000/W11470	HRS	4113.7							
WC#: 32.390	AFL	3247	24000	TSN 2043	25204		19581		
321061	LEFT MAIN LANDING GEAR JACK PIVOT							Component	ATA:32
PN:25UM1333-1A	MOS/MSC	10-Aug-18	O/C						
SN:UNKNOWN	HRS	4113.7							
WC#: 32.040	AFL	3247							
321062	RIGHT MAIN LANDING GEAR JACK PIVOT							Component	ATA:32
PN:25-UM1333-1	MOS/MSC	10-Aug-18	O/C	TSN 0					
SN:UNKNOWN	HRS	4113.7		TSN 0					
WC#: 32.040	AFL	3247		TSN 0					
321065	LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN							Component	ATA:32
PN:25-8UM131-11A	MOS/MSC	10-Aug-18	O/C						
SN:UNKNOWN	HRS	4113.7							
WC#: 32.400	AFL	3247							
321066	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN							Component	ATA:32
PN:25-8UM131-11A	MOS/MSC	10-Aug-18	O/C						
SN:UNKNOWN	HRS	4113.7							
WC#: 32.400	AFL	3247							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321067	LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN							Component	ATA:32
PN:25-8UM131-11A	MOS/MSC	10-Aug-18	O/C						
SN:UNKNOWN	HRS	4113.7							
WC#: 32.495	AFL	3247							
321068	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN							Component	ATA:32
PN:25-8UM131-11A	MOS/MSC	10-Aug-18	O/C						
SN:UNKNOWN	HRS	4113.7							
WC#: 32.495	AFL	3247							
321071	LEFT MAIN LANDING GEAR JACK DISTANCE PIN (LIFE LIMIT)							Component	ATA:32
PN:25UM423	MOS	10-Aug-18						LIFE LIMIT	
SN:UNKNOWN	HRS	4113.7							
WC#: 32.045	AFL	3247	24000	TSN 3247	24000		18377		
321072	RIGHT MAIN LANDING GEAR JACK DISTANCE PIN (LIFE LIMIT)							Component	ATA:32
PN:25UM423	MOS	10-Aug-18						LIFE LIMIT	
SN:UNKNOWN	HRS	4113.7							
WC#: 32.045	AFL	3247	24000	TSN 3247	24000		18377		
321075	LEFT MAIN LANDING GEAR PLUNGER TUBE (LIFE LIMIT)							Component	ATA:32
PN:NP-8UM-7	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN:AV8-00004	HRS	4113.7		TSN 0					
WC#: 32.410	AFL	3247	17000	TSN 0	20247		14624		
321076	RIGHT MAIN LANDING GEAR PLUNGER TUBE (LIFE LIMIT)							Component	ATA:32
PN:NP-8UM8	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN:AV8-00002	HRS	4113.7		TSN 0					
WC#: 32.410	AFL	3247	17000	TSN 0	20247		14624		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321081	LEFT MAIN LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component	ATA:32
PN:25-9UM9-3	MOS	10-Aug-18						LIFE LIMIT	
SN:W081047-7	HRS	4113.7							
WC#: 32.550	AFL	3247	20000	TSN 3247	20000		14377		
321082	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component	ATA:32
PN:25-9UM9-	MOS	10-Aug-18						LIFE LIMIT	
SN:W0810471-6	HRS	4113.7							
WC#: 32.550	AFL	3247	20000	TSN 3247	20000		14377		
321083	LEFT MAIN LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)							Component	ATA:32
PN:25-9UM11-3	MOS	10-Aug-18						LIFE LIMIT	
SN:W081075-8	HRS	4113.7							
WC#: 32.555	AFL	3247	20000	TSN 3247	20000		14377		
321084	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)							Component	ATA:32
PN:NP-9UM11-1	MOS	10-Aug-18						LIFE LIMIT	
SN:W01181015	HRS	4113.7							
WC#: 32.555	AFL	3247	20000	TSN 3247	20000		14377		
321087	LEFT MAIN LANDING GEAR AXLE ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.571	AFL	0		TSN 0					
321088	RIGHT MAIN LANDING GEAR AXLE ASSEMBLY							Component	ATA:32
PN:25-8UM53-34A	MOS/MSC	09-Nov-20	O/C	TSO 0					
SN:J004448-000/W12701	HRS	4842.8		TSO 0					
WC#: 32.572	AFL	3769		TSN 2002, TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322001	NOSE LEG ASSEMBLY (OVERHAUL)							Component	ATA:32
PN:25-9UN1-407A	MOS	10-Aug-18	144	TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0042/05	HRS	4113.7		TSO 0					
WC#: 32.050	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-20-12PROC. REF: AMM 32-20-12									
322003	NOSE LANDING GEAR PIVOT PIN (LIFE LIMIT)							Component	ATA:32
PN:25UN645	MOS	10-Aug-18						LIFE LIMIT	
SN:WO81170-2	HRS	4113.7							
WC#: 32.055	AFL	3247	16000	TSN 3247	16000		10377		
322007	NOSE LANDING GEAR DRAG STAY (OVERHAUL)							Component	ATA:32
PN:25-8UN3-143A	MOS	10-Aug-18	144	TSN 146, TSO 2	10-Jun-30		1734 d	OVERHAUL	
SN:DCL0031/06	HRS	4113.7		TSN 4113.7, TSO 0					
WC#: 32.070	AFL	3247	5000	TSN 3247, TSO 0	8247		2624		
PROC. REF: AMM 32-20-21PROC. REF: AMM 32-20-21									
322009	NOSE LANDING GEAR JACK LOWER PIVOT PIN (LIFE LIMIT)							Component	ATA:32
PN:25UN597	MOS	10-Aug-18						LIFE LIMIT	
SN:DCL42/05	HRS	4113.7							
WC#: 32.075	AFL	3247	22000	TSN 3247	22000		16377		
322011	NOSE LANDING GEAR DRAG STAY BRIDGE CASTING (LIFE LIMIT)							Component	ATA:32
PN:25-8UN487-5	MOS	10-Aug-18						LIFE LIMIT	
SN:PLT00384	HRS	4113.7							
WC#: 32.075	AFL	3247	33000	TSN 3247	33000		27377		
322015	NOSE LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component	ATA:32
PN:25-8UN267-5	MOS	10-Aug-18						LIFE LIMIT	
SN:EPI0032	HRS	4113.7							
WC#: 32.080	AFL	3247	32000	TSN 3247	32000		26377		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322016	NOSE LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)								Component ATA:32
PN:25-8UN269-3	MOS	10-Aug-18						LIFE LIMIT	
SN:EPI0045	HRS	4113.7							
WC#: 32.080	AFL	3247	32000	TSN 3247	32000		26377		
322017	NOSE LANDING GEAR DRAG STRUT PICK-UP (LIFE LIMIT)								Component ATA:32
PN:NPR-8UN265-1	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN:AV8-00018	HRS	4113.7		TSN 0					
WC#: 32.560	AFL	3247	13900	TSN 0	17147		11524		
322025	NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS (LIFE LIMIT)								Component ATA:32
PN:A102-28J	MOS	10-Aug-18						LIFE LIMIT	
SN:UNKNOWN	HRS	4113.7							
WC#: 32.380	AFL	3247	10000	TSN 3247	10000		4377		
322031	NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS (LIFE LIMIT)								Component ATA:32
PN:A102-21J	MOS	10-Aug-18						LIFE LIMIT	
SN:UNKNOWN	HRS	4113.7							
WC#: 32.085	AFL	3247	10000	TSN 3247	10000		4377		
322045	NOSE LANDING GEAR PLUNGER TUBE (LIFE LIMIT)								Component ATA:32
PN:25UN649	MOS	10-Aug-18						LIFE LIMIT	
SN:SAM2201	HRS	4113.7							
WC#: 32.075	AFL	3247	20000	TSN 2576	20671		15048		
323001	NOSE LANDING GEAR RETRACTION JACK (OVERHAUL)								Component ATA:32
PN:AIR45404-1	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN:LK9201897	HRS	6763.7		TSO 0					
WC#: 32.090	AFL	4989	5000	TSO 0	9989		4366		
PROC. REF: AMM 32-30-28PROC. REF: AMM 32-30-28									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323007	LEFT MAIN LANDING GEAR RETRACTION JACK (OVERHAUL)							Component	ATA:32
PN: AIR48502-7	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN: APB060881	HRS	6763.7		TSO 0					
WC#: 32.100	AFL	4989	5000	TSO 0	9989		4366		
PROC. REF: AMM 32-30-27PROC. REF: AMM 32-30-27									
323008	RIGHT MAIN LANDING GEAR RETRACTION JACK (OVERHAUL)							Component	ATA:32
PN: AIR48503-7	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN: APB081966	HRS	6763.7		TSO 0					
WC#: 32.100	AFL	4989	5000	TSO 0	9989		4366		
PROC. REF: AMM 32-30-27PROC. REF: AMM 32-30-27									
323019	LEFT MAIN LANDING GEAR DOOR JACK (OVERHAUL)							Component	ATA:32
PN: AIR48485-3	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN: APB021848	HRS	6763.7		TSO 0					
WC#: 32.105	AFL	4989	5000	TSO 0	9989		4366		
323020	RIGHT MAIN LANDING GEAR DOOR JACK (OVERHAUL)							Component	ATA:32
PN: AIR48484-3	MOS	08-Dec-23		TSO 0				OVERHAUL	
SN: APB071549	HRS	6763.7		TSO 0					
WC#: 32.105	AFL	4989	5000	TSO 0	9989		4366		
323031	LEFT SEQUENCE VALVE							Component	ATA:32
PN: AIR48540-1	MOS/MSC	31-Mar-17	O/C	TSO 0					
SN: APB060230	HRS	3527.5		TSO 0					
WC#: 32.110	AFL	2779		TSO 0					
PROC. REF: AMM 32-30-41PROC. REF: AMM 32-30-41									
323032	RIGHT SEQUENCE VALVE							Component	ATA:32
PN: AIR48540-1	MOS/MSC	29-Nov-16	O/C	TSO 0					
SN: LK8807251	HRS	3313.5		TSO 0					
WC#: 32.110	AFL	2626		TSO 0					
PROC. REF: AMM 32-30-41PROC. REF: AMM 32-30-41									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323043	LEFT REVERSING VALVE							Component	ATA:32
PN: AIR48542/1	MOS/MSC	10-Aug-18	O/C	TSO	0				
SN: LK1000876	HRS	4113.7		TSO	0				
WC#: 32.115	AFL	3247		TSO	0				
PROC. REF: AMM 32-30-31PROC. REF: AMM 32-30-31									
323044	RIGHT REVERSING VALVE							Component	ATA:32
PN: AIR48542/1	MOS/MSC	10-Aug-18	O/C	TSO	0				
SN: APB051168	HRS	4113.7		TSO	0				
WC#: 32.115	AFL	3247		TSO	0				
PROC. REF: AMM 32-30-31PROC. REF: AMM 32-30-31									
323079	LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE							Component	ATA:32
PN: AIR48026-0-1	MOS/MSC	29-Jun-06	O/C	TSN	0				
SN: APB060034	HRS	0		TSN	0				
WC#: 32.120	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323079-1 ^U	LH NON-RETURN VALVE							Component	ATA:32
PN: AIR87246-0	MOS/MSC	29-Jun-06	O/C	TSN	0				
SN: APB052291	HRS	0		TSN	0				
	AFL	0		TSN	0				
323080	RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE							Component	ATA:32
PN: AIR48026-0-1	MOS/MSC	29-Jun-06	O/C	TSN	0				
SN: APB060047	HRS	0		TSN	0				
WC#: 32.120	AFL	0		TSN	0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323080-1 ^U	RH NON-RETURN VALVE							Component	ATA:32
PN: AIR87246-0	MOS/MSC	29-Jun-06	O/C	TSN	0				
SN: APB052298	HRS	0		TSN	0				
	AFL	0		TSN	0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323090	FRAME 15A NON-RETURN VALVE							Component	ATA:32
PN: AIR45420-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: AP0600130	HRS	0		TSN 0					
WC#: 32.505	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323091	MAIN LANDING GEAR CENTER NONRETURN VALVE							Component	ATA:32
PN: AIR48026-0-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB060037	HRS	0		TSN 0					
WC#: 32.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323097	FRAME 14 NON-RETURN VALVE							Component	ATA:32
PN: AIR45420-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: AP0600132	HRS	0		TSN 0					
WC#: 32.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323098	FRAME 14A NONRETURN VALVE							Component	ATA:32
PN: AIR45420-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB051506	HRS	0		TSN 0					
WC#: 32.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323099	FRAME 15A NONRETURN VALVE							Component	ATA:32
PN: AIR45420-0-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB060152	HRS	0		TSN 0					
WC#: 32.130	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323103	LANDING GEAR SELECTOR/DUMP VALVE							Component	ATA:32
PN: AIR45406-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB060040	HRS	0		TSN 0					
WC#: 32.135	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323115	LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE							Component	ATA:32
PN: AIR45444-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB052684	HRS	0		TSN 0					
WC#: 32.140	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323116	RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE							Component	ATA:32
PN: AIR45444-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: APB052688	HRS	0		TSN 0					
WC#: 32.140	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323139	LEFT MAIN LANDING GEAR JACK PIVOT BOLT (LIFE LIMIT)							Component	ATA:32
PN: 25UM153A	MOS	10-Aug-18						LIFE LIMIT	
SN: UNKNOWN	HRS	4113.7							
WC#: 32.150	AFL	3247	30000	TSN 3247	30000		24377		
323140	RIGHT MAIN LANDING GEAR JACK PIVOT BOLT (LIFE LIMIT)							Component	ATA:32
PN: 25UM153A	MOS	10-Aug-18						LIFE LIMIT	
SN: UNKNOWN	HRS	4113.7							
WC#: 32.150	AFL	3247	30000	TSN 3247	30000		24377		
323151	LEFT MAIN LANDING GEAR JACK CYLINDER HEAD (LIFE LIMIT)							Component	ATA:32
PN: AIR141082	MOS	08-Dec-23						LIFE LIMIT	
SN: UNKNOWN	HRS	6763.7							
WC#: 32.155	AFL	4989	20000	TSN 3300	21689		16066		
323152	RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD (LIFE LIMIT)							Component	ATA:32
PN: AIR141082	MOS	08-Dec-23						LIFE LIMIT	
SN: UNKNOWN	HRS	6763.7							
WC#: 32.155	AFL	4989	20000	TSN 15000	9989		4366		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323163	LEFT MAIN LANDING GEAR JACK EYE END (LIFE LIMIT)								Component ATA:32
PN:PN	MOS	08-Dec-23						LIFE LIMIT	
SN:UNKNOWN	HRS	6763.7							
WC#: 32.160	AFL	4989	10000	TSN 3300	11689		6066		
323164	RIGHT MAIN LANDING GEAR JACK EYE END (LIFE LIMIT)								Component ATA:32
PN:PN	MOS	08-Dec-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	6763.7		TSN 0					
WC#: 32.160	AFL	4989	10000	TSN 0	14989		9366		
323175	LEFT MAIN LANDING GEAR RETRACTION ARM (LIFE LIMIT)								Component ATA:32
PN:NP-8UM63-1A	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN:AV8-00002	HRS	4113.7		TSN 0					
WC#: 32.165	AFL	3247	12000	TSN 0	15247		9624		
323176	RIGHT MAIN LANDING GEAR RETRACTION ARM (LIFE LIMIT)								Component ATA:32
PN:NP-8UM63-2A	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN:AV8-00023	HRS	4113.7		TSN 0					
WC#: 32.165	AFL	3247	12000	TSN 0	15247		9624		
323181	LEFT MAIN LANDING GEAR RETRACTION ARM PIN (LIFE LIMIT)								Component ATA:32
PN:25UM787	MOS	10-Aug-18						LIFE LIMIT	
SN:SAM7206/1	HRS	4113.7							
WC#: 32.170	AFL	3247	32000	TSN 3247	32000		26377		
323182	RIGHT MAIN LANDING GEAR RETRACTION ARM PIN (LIFE LIMIT)								Component ATA:32
PN:25UM787	MOS	10-Aug-18						LIFE LIMIT	
SN:DCL06	HRS	4113.7							
WC#: 32.170	AFL	3247	32000	TSN 3247	32000		26377		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323187	LANDING GEAR LEVER LOCK SOLENOID							Component	ATA:32
PN:D5327	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:H5687	HRS	0		TSN 0					
WC#: 32.175	AFL	0		TSN 0					
PROC. REF: AMM 32-30-21PROC. REF: AMM 32-30-21									
324001	NOSE LANDING GEAR AXLE BARREL (LIFE LIMIT)							Component	ATA:32
PN:25-8UN257-3	MOS	10-Aug-18						LIFE LIMIT	
SN:BB143	HRS	4113.7							
WC#: 32.195	AFL	3247	30000	TSN 3255	29992		24369		
PROC. REF: AMM 32-40-31PROC. REF: AMM 32-40-31									
324002	NOSE LANDING GEAR AXLE ASSEMBLY							Component	ATA:32
PN:25-9UN1-403A	MOS/MSC	22-May-14	O/C	TSR 0					
SN:258789	HRS	2168.7		TSR 0					
WC#: 32.573	AFL	1712		TSR 0					
324003	LEFT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.574	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324004	RIGHT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.575	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324006	NOSE LANDING GEAR OUTER CASING							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.576	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324007	LEFT NOSE WHEEL							Component	ATA:32
PN:AH52339	MOS/MSC	17-Jun-25	O/C						
SN:AY186/NL204	HRS	7587.1							
WC#: 32.200	AFL	5570							
PROC. REF: AMM 32-40-21PROC. REF: AMM 32-40-21									
324008	RIGHT NOSE WHEEL							Component	ATA:32
PN:AH52339	MOS/MSC	17-Jun-25	O/C						
SN:DB024	HRS	7587.1							
WC#: 32.205	AFL	5570							
PROC. REF: AMM 32-40-21PROC. REF: AMM 32-40-21									
324009	NOSE LANDING GEAR TOP LEVER ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.577	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324010	NOSE LANDING GEAR BOTTOM LEVER ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.578	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324019	LEFT NOSE TIRE							Component	ATA:32
PN:031-595-0	MOS/MSC	17-Jun-25	T/C	TSN 0					
SN:2331T00467	HRS	7587.1		TSN 0					
WC#: 32.200	AFL	5570							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									
324020	RIGHT NOSE TIRE							Component	ATA:32
PN:031-595-0	MOS/MSC	17-Jun-25	T/C	TSN 0					
SN:2330T00493	HRS	7587.1		TSN 0					
WC#: 32.205	AFL	5570							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324031	LEFT OUTBOARD MAIN WHEEL							Component	ATA:32
PN: AHA1814	MOS/MSC	01-May-25	O/C						
SN: RS194	HRS	7522.8							
WC#: 32.210	AFL	5519							
PROC. REF: AMM 32-40-12PROC. REF: AMM 32-40-12									
324032	RIGHT OUTBOARD MAIN WHEEL							Component	ATA:32
PN: AHA1814	MOS/MSC	24-Jul-25	O/C						
SN: UF069	HRS	7641							
WC#: 32.215	AFL	5606							
PROC. REF: AMM 32-40-12PROC. REF: AMM 32-40-12									
324033	LEFT INBOARD MAIN WHEEL							Component	ATA:32
PN: AHA1814	MOS/MSC	01-May-25	O/C						
SN: 2508RT/5014DH	HRS	7522.8							
WC#: 32.220	AFL	5519							
PROC. REF: AMM 32-40-12PROC. REF: AMM 32-40-12									
324034	RIGHT INBOARD MAIN WHEEL							Component	ATA:32
PN: AHA1814	MOS/MSC	24-Jul-25	O/C						
SN: YV191	HRS	7641							
WC#: 32.225	AFL	5606							
PROC. REF: AMM 32-40-12PROC. REF: AMM 32-40-12									
324055	LEFT OUTBOARD MAIN TIRE							Component	ATA:32
PN: 033-504-0	MOS/MSC	01-May-25	T/C	TSN 0					
SN: 3243P05061	HRS	7522.8		TSN 0					
WC#: 32.210	AFL	5519							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									
324056	RIGHT OUTBOARD MAIN TIRE							Component	ATA:32
PN: 033-504-0	MOS/MSC	24-Jul-25	T/C	TSN 0					
SN: 4119P05029	HRS	7641		TSN 0					
WC#: 32.215	AFL	5606							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324057	LEFT INBOARD MAIN TIRE							Component	ATA:32
PN:033-504-0	MOS/MSC	01-May-25	T/C	TSN 0					
SN:3251P05111	HRS	7522.8		TSN 0					
WC#: 32.220	AFL	5519							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									
324058	RIGHT INBOARD MAIN TIRE							Component	ATA:32
PN:033-504-0	MOS/MSC	24-Jul-25	T/C	TSN 0					
SN:4037P05156	HRS	7641		TSN 0					
WC#: 32.225	AFL	5606							
PROC. REF: AMM 32-40-41PROC. REF: AMM 32-40-41									
324065	RIGHT WHEEL WELL FILTER							Component	ATA:32
PN:AIR48538-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF05/0242	HRS	0		TSN 0					
WC#: 32.230	AFL	0		TSN 0					
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									
324066	LEFT FRAME 14A FILTER							Component	ATA:32
PN:AIR48538-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF06/0027	HRS	0		TSN 0					
WC#: 32.235	AFL	0		TSN 0					
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									
324067	RIGHT FRAME 14A FILTER							Component	ATA:32
PN:AIR48538-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF06/0026	HRS	0		TSN 0					
WC#: 32.235	AFL	0		TSN 0					
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									
324068	FRAME 15 FILTER							Component	ATA:32
PN:AIR48538-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:BF06/0025	HRS	0		TSN 0					
WC#: 32.235	AFL	0		TSN 0					
PROC. REF: AMM 32-30-22PROC. REF: AMM 32-30-22									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324069	NOSE WHEEL STEERING FILTER								Component ATA:32
PN: AIR45412-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: BF05/0446	HRS	0		TSN 0					
WC#: 32.240	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324115	BRAKE CONTROL VALVE								Component ATA:32
PN: AC67732	MOS/MSC	10-Aug-18	O/C	TSR 0					
SN: HF247	HRS	4113.7		TSR 0					
WC#: 32.245	AFL	3247		TSR 0					
PROC. REF: AMM 32-40-71PROC. REF: AMM 32-40-71									
324121	BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE (LIFE LIMIT)								Component ATA:32
PN: ACO34629	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN: UNKNOWN	HRS	4113.7		TSN 0					
WC#: 32.245	AFL	3247	4500	TSN 0	7747		2124		
PROC. REF: AMM 32-40-71PROC. REF: AMM 32-40-71									
324122	BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE (LIFE LIMIT)								Component ATA:32
PN: ACO34630	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN: UNKNOWN	HRS	4113.7		TSN 0					
WC#: 32.245	AFL	3247	4500	TSN 0	7747		2124		
PROC. REF: AMM 32-40-71PROC. REF: AMM 32-40-71									
324123	BRAKE CONTROL VALVE INNER KNIFE EDGE (LIFE LIMIT)								Component ATA:32
PN: ACO36133	MOS	10-Aug-18		TSN 0				LIFE LIMIT	
SN: UNKNOWN	HRS	4113.7		TSN 0					
WC#: 32.245	AFL	3247	4500	TSN 0	7747		2124		
PROC. REF: AMM 32-40-71PROC. REF: AMM 32-40-71									
324145	MAIN REDUCING VALVE								Component ATA:32
PN: AC61518	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN: 87EA	HRS	0		TSN 0					
WC#: 32.250	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324151	EMERGENCY REDUCING VALVE								Component ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.255	AFL	0		TSN 0					
PROC. REF: AMM 32-40-51PROC. REF: AMM 32-40-51									
324157	EMERGENCY REDUCING VALVE LEFT KNIFE EDGE (LIFE LIMIT)								Component ATA:32
PN:ACO34629	MOS	28-Apr-22		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	5938		TSN 0					
WC#: 32.255	AFL	4436	4500	TSN 0	8936		3313		
324158	EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE (LIFE LIMIT)								Component ATA:32
PN:ACO34630	MOS	28-Apr-22		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	5938		TSN 0					
WC#: 32.255	AFL	4436	4500	TSN 0	8936		3313		
324169	EMERGENCY BRAKE PRESSURE NONRETURN VALVE								Component ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.500	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324175	LEFT OUTBOARD BRAKE UNIT								Component ATA:32
PN:AHA1897	MOS/MSC	27-Feb-25	O/C	TSO 0					
SN:5219G	HRS	7409.1		TSO 0					
WC#: 32.265	AFL	5432							
PROC. REF: AMM 32-40-114PROC. REF: AMM 32-40-114									
324176	RIGHT OUTBOARD BRAKE UNIT								Component ATA:32
PN:AHA1897	MOS/MSC	28-Apr-22	O/C	TSO 3					
SN:5044FZ	HRS	5938		TSO 0					
WC#: 32.260	AFL	4436		TSO 0					
PROC. REF: AMM 32-40-114PROC. REF: AMM 32-40-114									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324177	LEFT INBOARD BRAKE UNIT							Component	ATA:32
PN: AHA1897	MOS/MSC	27-Feb-25	O/C	TSO 0					
SN: 5038DP	HRS	7409.1		TSO 0					
WC#: 32.265	AFL	5432							
PROC. REF: AMM 32-40-114PROC. REF: AMM 32-40-114									
324178	RIGHT INBOARD BRAKE UNIT							Component	ATA:32
PN: AHA1897	MOS/MSC	01-Apr-23	O/C	TSO 2					
SN: 5025KF	HRS	6452.9		TSO 0					
WC#: 32.260	AFL	4766		TSO 0					
PROC. REF: AMM 32-40-114PROC. REF: AMM 32-40-114									
324223	LEFT OUTBOARD MAXARET (OVERHAUL)							Component	ATA:32
PN: AC65218	MOS	28-Sep-17		TSO 1				OVERHAUL	
SN: MN320	HRS	3763.6		TSO 0					
WC#: 32.270	AFL	2975	3000	TSO 0	5975		352		
PROC. REF: AMM 32-40-101PROC. REF: AMM 32-40-101									
324224	RIGHT OUTBOARD MAXARET (OVERHAUL)							Component	ATA:32
PN: AC65216	MOS	14-May-22		TSO 7				OVERHAUL	
SN: PP119	HRS	5967		TSO 0					
WC#: 32.275	AFL	4454	3000	TSO 0	7454		1831		
PROC. REF: AMM 32-40-101PROC. REF: AMM 32-40-101									
324225	LEFT INBOARD MAXARET (OVERHAUL)							Component	ATA:32
PN: AC65216	MOS	28-Sep-17		TSO 1				OVERHAUL	
SN: V11789	HRS	3763.6		TSO 0					
WC#: 32.270	AFL	2975	3000	TSO 0	5975		352		
PROC. REF: AMM 32-40-101PROC. REF: AMM 32-40-101									
324226	RIGHT INBOARD MAXARET (OVERHAUL)							Component	ATA:32
PN: AC65218	MOS	14-May-22		TSO 5				OVERHAUL	
SN: YU162	HRS	5967		TSO 0					
WC#: 32.275	AFL	4454	3000	TSO 0	7454		1831		
PROC. REF: AMM 32-40-101PROC. REF: AMM 32-40-101									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324260	LEFT MAIN LANDING GEAR DOOR							Component	ATA:32
PN:25-8UD505-235A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7303593	HRS	0		TSN 0					
WC#: 32.280	AFL	0		TSN 0					
PROC. REF: AMM 32-10-41PROC. REF: AMM 32-10-41									
324261	RIGHT MAIN LANDING GEAR DOOR							Component	ATA:32
PN:25-8UD505-236A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7294631	HRS	0		TSN 0					
WC#: 32.280	AFL	0		TSN 0					
PROC. REF: AMM 32-10-41PROC. REF: AMM 32-10-41									
324262	LEFT NOSE GEAR DOOR							Component	ATA:32
PN:25-8UD501-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:414069	HRS	0		TSN 0					
WC#: 32.285	AFL	0		TSN 0					
PROC. REF: AMM 32-20-42PROC. REF: AMM 32-20-42									
324263	RIGHT NOSE GEAR DOOR							Component	ATA:32
PN:25-8UD501-2A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4260601	HRS	0		TSN 0					
WC#: 32.285	AFL	0		TSN 0					
PROC. REF: AMM 32-20-42PROC. REF: AMM 32-20-42									
324264	NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY							Component	ATA:32
PN:25-8UD503-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4130602	HRS	0		TSN 0					
WC#: 32.290	AFL	0		TSN 0					
PROC. REF: AMM 32-20-42PROC. REF: AMM 32-20-42									
324265	LEFT MAIN LANDING GEAR FAIRING							Component	ATA:32
PN:25-8UD507-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7284792	HRS	0		TSN 0					
WC#: 32.295	AFL	0		TSN 0					
PROC. REF: AMM 32-10-32PROC. REF: AMM 32-10-32									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324266	RIGHT MAIN LANDING GEAR FAIRING							Component	ATA:32
PN:25-8UD507-2A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7281973	HRS	0		TSN 0					
WC#: 32.295	AFL	0		TSN 0					
PROC. REF: AMM 32-10-32PROC. REF: AMM 32-10-32									
324271	LEFT BRAKE MODULATOR							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.300	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324272	RIGHT BRAKE MODULATOR							Component	ATA:32
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.300	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324301	PILOT LEFT BRAKE MASTER CYLINDER							Component	ATA:32
PN:ACM30946	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7DT	HRS	0		TSN 0					
WC#: 32.310	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324302	PILOT RIGHT BRAKE MASTER CYLINDER							Component	ATA:32
PN:ACM30946	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4DT	HRS	0		TSN 0					
WC#: 32.310	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324303	COPILOT LEFT BRAKE MASTER CYLINDER							Component	ATA:32
PN:ACM30946	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:8DT	HRS	0		TSN 0					
WC#: 32.315	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324304	COPILOT RIGHT BRAKE MASTER CYLINDER							Component	ATA:32
PN:ACM30946	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5DT	HRS	0		TSN 0					
WC#: 32.315	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324325	LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH (OVERHAUL)							Component	ATA:32
PN:TP42000	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:2972	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 32.320	AFL	3858		TSO 0					
324326	RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH (OVERHAUL)							Component	ATA:32
PN:TP42000	MOS	27-Jan-21		TSO 0				OVERHAUL	
SN:2466	HRS	4991.6	5000	TSO 0	9991.6		2331.4		
WC#: 32.320	AFL	3858		TSO 0					
324337	FORWARD HIGH PRESSURE TRANSDUCER							Component	ATA:32
PN:APTE-29-1000-2000*	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7121-1-58	HRS	0		TSN 0					
WC#: 32.325	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324338	AFT HIGH PRESSURE TRANSDUCER							Component	ATA:32
PN:APTE-29-1000-2000*	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7042-3-331	HRS	0		TSN 0					
WC#: 32.325	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324508 ^U	LH SHUTTLE VALVES							Component	ATA:32
PN:AH081963	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5093RQ	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324509 ^U	RH SHUTTLE VALVES							Component	ATA:32
PN:AH081963	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5074EC	HRS	0		TSN 0					
	AFL	0		TSN 0					
324510 ^U	LH SHUTTLE VALVES							Component	ATA:32
PN:AH081964	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5235EE	HRS	0		TSN 0					
	AFL	0		TSN 0					
324511 ^U	RH SHUTTLE VALVES							Component	ATA:32
PN:AH081964	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:5238EE	HRS	0		TSN 0					
	AFL	0		TSN 0					
325001	STEERING JACK							Component	ATA:32
PN:AIR45396-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB051937	HRS	0		TSN 0					
WC#: 32.330	AFL	0		TSN 0					
PROC. REF: AMM 32-50-11PROC. REF: AMM 32-50-11									
325003	NOSE LANDING GEAR CONNECTING ROD (LIFE LIMIT)							Component	ATA:32
PN:25-8UN433-3	MOS	10-Aug-18						LIFE LIMIT	
SN:EPI0060	HRS	4113.7							
WC#: 32.335	AFL	3247	20000	TSN 3247	20000		14377		
325007	STEERING JACK EYE END (LIFE LIMIT)							Component	ATA:32
PN:AIR110646	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.340	AFL	0	14400	TSN 0	14400		8777		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325011	NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE (LIFE LIMIT)							Component	ATA:32
PN:25-8UN441/5	MOS	10-Aug-18						LIFE LIMIT	
SN:BB116	HRS	4113.7							
WC#: 32.335	AFL	3247	20000	TSN 3694	19553		13930		
325015	NOSE LANDING GEAR STEERING PIN (LIFE LIMIT)							Component	ATA:32
PN:25UN605	MOS	10-Aug-18						LIFE LIMIT	
SN:W081086-2	HRS	4113.7							
WC#: 32.345	AFL	3247	25000	TSN 3247	25000		19377		
325021	NOSE LANDING GEAR MAIN CASING BOLT (LIFE LIMIT)							Component	ATA:32
PN:25UN603	MOS	10-Aug-18						LIFE LIMIT	
SN:W081123-3	HRS	4113.7							
WC#: 32.345	AFL	3247	33000	TSN 3247	33000		27377		
325025	NOSE WHEEL STEERING ON/OFF VALVE							Component	ATA:32
PN:AIR45408-0	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:APB050027	HRS	0		TSN 0					
WC#: 32.350	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325031	NOSE WHEEL ANTI-SHIMMING VALVE							Component	ATA:32
PN:AIR48284-2	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:APB051074	HRS			TSN 0					
WC#: 32.355	AFL			TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325041	NOSE LANDING GEAR UPPER STEERING MAIN MEMBER (LIFE LIMIT)							Component	ATA:32
PN:25-8UN431-3	MOS	10-Aug-18						LIFE LIMIT	
SN:W081026-2	HRS	4113.7							
WC#: 32.360	AFL	3247	35000	TSN 3247	35000		29377		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325042	NOSE LANDING GEAR LOWER STEERING MAIN MEMBER (LIFE LIMIT)							Component	ATA:32
PN:25-8UN431-4	MOS	10-Aug-18						LIFE LIMIT	
SN:W081060-2	HRS	4113.7							
WC#: 32.360	AFL	3247	35000	TSN 3247	35000		29377		
325051	NOSE LANDING GEAR STEERING JACK PICK-UP (LIFE LIMIT)							Component	ATA:32
PN:25-8UN263-5	MOS	10-Aug-18						LIFE LIMIT	
SN:EPI0072	HRS	4113.7							
WC#: 32.365	AFL	3247	18000	TSN 3247	18000		12377		
325058	NOSE LANDING GEAR STEERING SLEEVE (LIFE LIMIT)							Component	ATA:32
PN:25-8UN439-1A	MOS	10-Aug-18						LIFE LIMIT	
SN:EPI0090	HRS	4113.7							
WC#: 32.365	AFL	3247	20000	TSN 3247	20000		14377		
326012 ^U	LEFT MAIN GEAR DOWN LOCK SWITCH							Component	ATA:32
PN:9006EN42	MOS/MSC	19-May-11	O/C	TSN 0					
SN:UNKNOWN	HRS	1036.6		TSN 0					
	AFL	837		TSN 0					
326013 ^U	RH MLG STANDBY DOWNLOCK SWITCH							Component	ATA:32
PN:9006EN42	MOS/MSC	21-Nov-18	O/C	TSN 0					
SN:N/A	HRS	4279.7		TSN 0					
	AFL	3370		TSN 0					
32W000 ^U	PERFORM NOSE TIRE WEAR INSPECTION							Service	ATA:32
	MOS	17-Jun-25							
	HRS	7587.1							
	AFL	5570	195 (+30)		5765	5795	142 (+30)		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32W001 ^U	PERFORM #1 MAIN TIRE WEAR INSPECTION								Service ATA:32
	MOS	04-Jun-25							
	HRS	7579.6							
	AFL	5563	150 (+30)		5713	5743	90 (+30)		
32W002 ^U	PERFORM #2 MAIN TIRE WEAR INSPECTION								Service ATA:32
	MOS	04-Jun-25							
	HRS	7579.6							
	AFL	5563	150 (+30)		5713	5743	90 (+30)		
32W003 ^U	PERFORM #3 MAIN TIRE WEAR INSPECTION								Service ATA:32
	MOS	24-Jul-25							
	HRS	7641							
	AFL	5606	150 (+30)		5756	5786	133 (+30)		
32W004 ^U	PERFORM #4 MAIN TIRE WEAR INSPECTION								Service ATA:32
	MOS	24-Jul-25							
	HRS	7641							
	AFL	5606	150 (+30)		5756	5786	133 (+30)		
32W005 ^U	PERFORM #1 BRAKE WEAR INSPECTION								Service ATA:32
	MOS	27-Feb-25							
	HRS	7409.1							
	AFL	5432	750 (+200)		6182	6382	559 (+200)		
32W006 ^U	PERFORM #2 BRAKE WEAR INSPECTION								Service ATA:32
	MOS	27-Feb-25							
	HRS	7409.1							
	AFL	5432	750 (+200)		6182	6382	559 (+200)		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32W007	^U	PERFORM #3 BRAKE WEAR INSPECTION							Service ATA:32
	MOS	21-Feb-25							
	HRS	7403.7							
	AFL	5430	750 (+200)		6180	6380	557 (+200)		
32W008 ^U PERFORM #4 BRAKE WEAR INSPECTION Service ATA:32									
	MOS	21-Feb-25							
	HRS	7403.7							
	AFL	5430	750 (+200)		6180	6380	557 (+200)		
ATA 33 - LIGHTS									
330003	^S	CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM							Service ATA:33
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 33.080	AFL	5563							
									PKG:7,91
330007 MAIN CG ILLUMINATED LABEL Component ATA:33									
PN:PN	MOS/MS	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
330008 FORWARD CG ILLUMINATED LABEL Component ATA:33									
PN:PN	MOS/MS	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
330605 ^U LOGO LIGHTS Component ATA:33									
PN:12500001-2	MOS/MS	29-Jun-06	O/C	TSN 0					
SN:NSN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331500 ^U	#1 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17941	HRS	0		TSN 0					
	AFL	0		TSN 0					
331501 ^U	#2 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17940	HRS	0		TSN 0					
	AFL	0		TSN 0					
331502 ^U	#3 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17942	HRS	0		TSN 0					
	AFL	0		TSN 0					
331503 ^U	#4 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17938	HRS	0		TSN 0					
	AFL	0		TSN 0					
331504 ^U	#5 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17783	HRS	0		TSN 0					
	AFL	0		TSN 0					
331505 ^U	#6 POWER CONVERTER/DIMMER UNIT							Component	ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17782	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331506 ^U	#7 POWER CONVERTER/DIMMER UNIT								Component ATA:33
PN:LT-52A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:17953	HRS	0		TSN 0					
	AFL	0		TSN 0					
334001	TOP ANTI COLLISION BEACON								Component ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.020	AFL	0		TSN 0					
PROC. REF: AMM 33-40-42PROC. REF: AMM 33-40-42									
334002	BOTTOM ANTI COLLISION BEACON								Component ATA:33
PN:01-0790044-54	MOS/MSC	31-Jan-14	O/C	TSN 0					
SN:07811	HRS	2094.1		TSN 0					
WC#: 33.020	AFL	1667		TSN 0					
PROC. REF: AMM 33-40-42PROC. REF: AMM 33-40-42									
334013	LEFT WING STROBE LIGHT								Component ATA:33
PN:01-00770935-02	MOS/MSC	08-Dec-23	O/C	TSN 0					
SN:N/A	HRS	6763.7		TSN 0					
WC#: 33.025	AFL	4989		TSN 0					
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
334014	RIGHT WING STROBE LIGHT								Component ATA:33
PN:01-0770935-02	MOS/MSC	08-Dec-23	O/C	TSN 0					
SN:N/A	HRS	6763.7		TSN 0					
WC#: 33.025	AFL	4989		TSN 0					
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
334016	TEST LEFT WING STROBE LIGHT INTENSITY								Service ATA:33
PN:01-00770935-02	MOS	04-Jun-25							
SN:N/A	HRS	7579.6	400 (+50/-50)	Adj 17.6	7997.2	8047.2	337 (+50)		
WC#: 33.025	AFL	5563							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334017	TEST RIGHT WING STROBE LIGHT INTENSITY								Service ATA:33
PN:01-0770935-02	MOS	04-Jun-25							
SN:N/A	HRS	7579.6	400 (+50/-50)	Adj 17.6	7997.2	8047.2	337 (+50)		
WC#: 33.025	AFL	5563							
334025 ^U ACCOMPLISH EMERGENCY LIGHTING DEGRADATION TEST									
	MOS	08-Dec-23							Service ATA:33
	HRS	6763.7	3500		10263.7		2603.5		
	AFL	4989							
334044 TAIL STROBE LIGHT (REPLACE)									
PN:30-0531-1	MOS	08-Dec-23		TSN 0				REPLACE	Component ATA:33
SN:10707	HRS	6763.7	1500	TSN 0	8263.7		603.5		
WC#: 33.040	AFL	4989		TSN 0					
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
334047 TEST TAIL STROBE LIGHT INTENSITY									
PN:30-0531-1	MOS/MSC	08-Dec-23	O/C						Service ATA:33
SN:10707	HRS	6763.7							
WC#: 33.040	AFL	4989							
334061 STROBE LIGHTS POWER SUPPLY									
PN:701571	MOS/MSC	30-Sep-21	O/C	TSN 0					Component ATA:33
SN:4157397	HRS	5486.4		TSN 0					
WC#: 33.045	AFL	4154		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334501 ^U OVER FIN									
PN:25-8TF513-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					Component ATA:33
SN:AST06C028	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
335001	EMERGENCY LIGHTING INERTIA SWITCH							Component	ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.050	AFL	0		TSN 0					
PROC. REF: MMA 33-50-05PROC. REF: MMA 33-50-05									
335025	NO. 1 (AA PNL) DIMMER							Component	ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
335027	NO. 2 (AA PNL) DIMMER							Component	ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
335029	NO. 1 (AB PNL) DIMMER							Component	ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
335031	NO. 2 (AB PNL) DIMMER							Component	ATA:33
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.060	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
335123 ^U	FWD EMERGENCY LIGHTS BATTERY							Component	ATA:33
PN:60-1321-1	MOS/MSC	12-Oct-22	O/C	TSN 3					
SN:71050	HRS	6156.5		TSN 0					
	AFL	4577		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
335124 ^U	AFT EMERGENCY LIGHTS BATTERY							Component	ATA:33
PN:60-1321-1	MOS/MSC	12-Oct-22	O/C	TSN 3					
SN:71049	HRS	6156.5		TSN 0					
	AFL	4577		TSN 0					
335200	PULSELIGHT CONTROL UNIT							Component	ATA:33
PN:2401S	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:00949	HRS	0		TSN 0					
WC#: 33.085	AFL	0		TSN 0					
PROC. REF: MMA 33-40-10, MMA 33-40-15PROC. REF: MMA 33-40-10, MMA 33-40-15									
336001 ^U	LANDING/TAXI LIGHT LENS, LH							Component	ATA:33
PN:251W00129-1	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:PPA3017	HRS			TSN 0					
	AFL			TSN 0					
336002 ^U	LANDING/TAXI LIGHT LENS, RH							Component	ATA:33
PN:251W00129-2	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:PPA2584	HRS			TSN 0					
	AFL			TSN 0					
336020 ^U	ORDINANCE SIGN							Component	ATA:33
PN:1202-009	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:138352	HRS	0		TSN 0					
	AFL	0		TSN 0					
336022 ^U	ORDINANCE SIGN (GALLEY)							Component	ATA:33
PN:1202-009	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:138417	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
336040	ESCAPE HATCH BETALIGHT "EXIT" SIGN (REPLACE)								Component ATA:33
PN:132848-11	MOS	16-Jul-25	72 (+24m)	TSN 0, Adj -52d	10-May-31	10-May-33	2068 d (+731)	REPLACE	
SN:60473	HRS	7629.2							
	AFL	5600							
Manufacture Date:: 01-Jul-25									
PROC. REF: AMM 33-50-05PROC. REF: AMM 33-50-05									
339001 ^U	LOWER BEACON								Component ATA:33
PN:01-0790044-54	MOS/MSC	15-Apr-19	O/C	TSN 0					
SN:08252	HRS	4500.6		TSN 0					
	AFL	3522		TSN 0					
33R798 ^U	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM NOSE MOUNTED HID LIGHTS IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS								Service ATA:33
	MOS	18-Dec-24	24 (+2m)		18-Dec-26	18-Feb-27	464 d (+62)		
	HRS	7294.8	1800 (+50)		9094.8	9144.8	1434.6 (+50)		
	AFL	5348							
33R799 ^U	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS IN IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS								Service ATA:33
	MOS	09-Aug-24	24 (+2m)		09-Aug-26	09-Oct-26	333 d (+61)		
	HRS	7193.9	1800 (+50)		8993.9	9043.9	1333.7 (+50)		
	AFL	5277							
33R800 ^U	INSPECT LOPRESTI BOOM BEAM NOSE MOUNTED HID LIGHTS (IN ACCORDANCE WITH INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT)								Service ATA:33
	MOS	18-Dec-24	24		18-Dec-26		464 d		
	HRS	7294.8	1800		9094.8		1434.6		
	AFL	5348							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
33R801	^U	INSPECT LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IN ACCORDANCE WITH INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT)						Service	ATA:33
	MOS/MSC	26-Jul-24	24 / -		26-Jul-26		319 d		
	HRS	7166.1	1800		8966.1		1305.9		
	AFL	5261							
ATA 34 - NAVIGATION									
340002		DRAIN PITOT/STATIC DRAIN TRAPS						Service	ATA:34
	MOS	15-Dec-23	24 (+2m)	Adj -40d	05-Nov-25		56 d (+61)		
	HRS	6772.6							
WC# : 34.025	AFL	4994							
PROC. REF: AMM 34-11-19PROC. REF: AMM 34-11-19									
340003	^S	INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT						Service	ATA:34
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC# : 34.405	AFL	4989							PKG:22,92
340004	^S	INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR						Service	ATA:34
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC# : 34.410	AFL	4989							PKG:25,92
340005	^S	INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT						Service	ATA:34
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC# : 34.415	AFL	4989							PKG:25,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
340006	PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS								Service ATA:34
	MOS	08-Dec-23	24 (+2m)	Adj -33d	05-Nov-25	05-Jan-26	56 d (+61)		
	HRS	6763.7							
WC#: 34.015	AFL	4989							
PROC. REF: AMM 34-11-19PROC. REF: AMM 34-11-19									
340007	CHECK PITOT SYSTEM ISOLATION VALVES								Service ATA:34
	MOS	08-Dec-23	24 (+2m)	Adj -33d	05-Nov-25	05-Jan-26	56 d (+61)		
	HRS	6763.7							
WC#: 34.290	AFL	4989							
340008 ^S	TEST MACH TRIM SYSTEM								Service ATA:34
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 34.270	AFL	4989							
PROC. REF: AMM 22-20-00PROC. REF: AMM 22-20-00									PKG:31,93
340010 ^S	TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY								Service ATA:34
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 34.425	AFL	4989							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:31,93
340012	SWING CHECK NO. 1 COMPASS								Service ATA:34
	MOS	23-May-23	36 (+2m)		23-May-26	23-Jul-26	255 d (+61)		
	HRS	6556.1							
WC#: 34.095	AFL	4826							
PROC. REF: AMM 34-20-05, AMM 34-09-112PROC. REF: AMM 34-20-05, AMM 34-09-112									
340012	SWING CHECK NO. 2 COMPASS								Service ATA:34
	MOS	23-May-23	36 (+2m)		23-May-26	23-Jul-26	255 d (+61)		
	HRS	6556.1							
WC#: 34.095	AFL	4826							
PROC. REF: AMM 34-20-05, AMM 34-09-112PROC. REF: AMM 34-20-05, AMM 34-09-112									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
340012	SWING CHECK STANDBY COMPASS								Service ATA:34
	MOS	23-May-23	36 (+2m)	Adj -1d	22-May-26	22-Jul-26	254 d (+61)		
	HRS	6556.1							
WC#: 34.095	AFL	4826							
PROC. REF: AMM 34-20-05, AMM 34-09-112PROC. REF: AMM 34-20-05, AMM 34-09-112									
340013	COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME								Service ATA:34
	MOS	04-Jun-25	12 (+1m/-1m)		04-Jun-26	04-Jul-26	267 d (+30)		
	HRS	7579.6							
WC#: 34.020	AFL	5563							
PROC. REF: AMM 34-11-29PROC. REF: AMM 34-11-29									
341001	LEFT PITOT PRESSURE HEAD								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.010	AFL	0		TSN 0					
PROC. REF: AMM 34-11-24PROC. REF: AMM 34-11-24									
341002	RIGHT PITOT PRESSURE HEAD								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.010	AFL	0		TSN 0					
PROC. REF: AMM 34-11-24PROC. REF: AMM 34-11-24									
341097	GARMIN GL-275 SECONDARY STANDBY FLIGHT DISPLAY								Component ATA:34
PN:010-02326-30	MOS/MSC	08-Dec-23	O/C	TSN 0					
SN:5MZ114676	HRS	6763.7		TSN 0					
WC#: 34.040	AFL	4989		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341103	TEST STANDBY ALTIMETER (FAR 91.411)								Service ATA:34
PN:010-02326-30	MOS	08-Dec-23	24		08-Dec-25		89 d	MANDATORY	
SN:5MZ114676	HRS								
WC#: 34.040	AFL								
Test Date: : 08-Dec-23									
PROC. REF: FAR FAR PART 91PROC. REF: FAR FAR PART 91									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341109	LEFT AIRSPEED INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.050	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341110	RIGHT AIRSPEED INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.055	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341111	NO. 1 AIRSPEED REFERENCE PANEL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.315	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341112	NO. 2 AIRSPEED REFERENCE PANEL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.315	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341115	STANDBY AIRSPEED INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.045	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341163	LEFT SAT/TAS INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.320	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341164	RIGHT SAT/TAS INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.320	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341195	VOICE ADVISORY							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.060	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 31-50-00PROC. REF: AMM NO REF 1, MMA 31-50-00									
341228	NO. 1 AIR DATA COMPUTER							Component	ATA:34
PN:822-1106-015	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:3PF3F	HRS	6763.7		TSO 0					
WC#: 34.065	AFL	4989		TSO 0					
PROC. REF: AMM 34-10-19PROC. REF: AMM 34-10-19									
341229	NO. 2 AIR DATA COMPUTER							Component	ATA:34
PN:822-1109-015	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:4827T	HRS	6763.7		TSO 0					
WC#: 34.066	AFL	4989		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341230	NO. 1 AIR DATA MODULE							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.325	AFL	0		TSN 0					
PROC. REF: AMM 31-20-66PROC. REF: AMM 31-20-66									
341231	NO. 2 AIR DATA MODULE							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.325	AFL	0		TSN 0					
PROC. REF: AMM 31-20-66PROC. REF: AMM 31-20-66									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341234	SIGNAL INTERFERENCE ADAPTER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.330	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341235	(ESIS) MAGNETOMETER							Component	ATA:34
PN:19004-00-01	MOS/MSC	03-Dec-21	O/C	TSN 206, TSO 1					
SN:M016107	HRS	5612.2		TSO 0					
WC#: 34.485	AFL	4240		TSO 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341237	AIR DATA ESIS UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.435	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
341240	TEST NO.1 AIR DATA COMPUTER (FAA 91.411)							Service	ATA:34
PN:822-1106-015	MOS	08-Dec-23	24		08-Dec-25		89 d	MANDATORY	
SN:3PF3F	HRS								
WC#: 34.065	AFL								
Test Date: : 08-Dec-23									
PROC. REF: AMM 34-10-19, FAR FAR PART 91PROC. REF: AMM 34-10-19, FAR FAR PART 91									
341241	TEST NO.2 AIR DATA COMPUTER (FAA 91.411)							Service	ATA:34
PN:822-1109-015	MOS	08-Dec-23	24		08-Dec-25		89 d	MANDATORY	
SN:4827T	HRS								
WC#: 34.066	AFL								
Test Date: : 08-Dec-23									
PROC. REF: AMM 34-10-19, FAR FAR PART 91PROC. REF: AMM 34-10-19, FAR FAR PART 91									
341276	RADIO ALTIMETER UNIT							Component	ATA:34
PN:822-0615-206	MOS/MSC	05-Oct-15	O/C	TSO 0					
SN:3LVRF	HRS	2632.9		TSO 0					
WC#: 34.070	AFL	2102		TSO 0					
PROC. REF: AMM 34-40-05PROC. REF: AMM 34-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341279	LEFT RADIO ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:543-34809	HRS	0		TSN 0					
WC#: 34.075	AFL	0		TSN 0					
PROC. REF: AMM 34-40-05, AMM 34-40-25PROC. REF: AMM 34-40-05, AMM 34-40-25									
341281	RIGHT RADIO ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:543-34883	HRS	0		TSN 0					
WC#: 34.080	AFL	0		TSN 0					
PROC. REF: AMM 34-40-05, AMM 34-40-25PROC. REF: AMM 34-40-05, AMM 34-40-25									
342013	EMERGENCY GYRO HORIZON INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.090	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342014	SECONDARY FLIGHT DISPLAY							Component	ATA:34
PN:39213-00-01	MOS/MSC	15-May-19	O/C	TSO 0					
SN:M017658	HRS	4541.6		TSO 0					
WC#: 34.490	AFL	3559		TSO 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342097	STANDBY COMPASS (E2B) INDICATOR							Component	ATA:34
PN:KCA0104W	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AU9270905	HRS	0		TSN 0					
WC#: 34.106	AFL	0		TSN 0					
PROC. REF: AMM 34-09-112PROC. REF: AMM 34-09-112									
342141	NO. 1 VLF/OMEGA SENSOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342142	NO. 2 VLF/OMEGA SENSOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342143	H FIELD (TOP) ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.110	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342144	H FIELD (BOTTOM) ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.110	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342145	NO. 1 DATA LOADER							Component	ATA:34
PN:822-3000-202	MOS/MSC	09-Aug-18	O/C	TSN 0					
SN:4DV101	HRS	4113.7		TSN 0					
WC#: 34.115	AFL	3247		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342220	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component	ATA:34
PN:822-0868-139	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:1MRWB	HRS	4113.7		TSO 0					
WC#: 34.350	AFL	3247		TSO 0					
PROC. REF: AMM 34-60-10PROC. REF: AMM 34-60-10									
342221	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component	ATA:34
PN:822-0868-139	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:26G8R	HRS	4113.7		TSO 0					
WC#: 34.350	AFL	3247		TSO 0					
PROC. REF: AMM 34-60-10PROC. REF: AMM 34-60-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342240	REMOTE TUNING UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.340	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342253	NO. 1 COMPASS FLUX VALVE							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.120	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342254	NO. 2 COMPASS FLUX VALVE							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.120	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342265	NO. 1 AHRs COMPUTER							Component	ATA:34
PN:822-1110-002	MOS/MSC	27-Jan-18	O/C	TSO 0					
SN:46JKG	HRS	3920		TSO 0					
WC#: 34.125	AFL	3109		TSO 0					
PROC. REF: AMM 34-20-05PROC. REF: AMM 34-20-05									
342266	NO. 2 AHRs COMPUTER							Component	ATA:34
PN:822-1110-002	MOS/MSC	04-Sep-10	O/C	TSO 0					
SN:2V33F	HRS	635.7		TSO 0					
WC#: 34.125	AFL	548		TSO 0					
PROC. REF: AMM 34-20-05PROC. REF: AMM 34-20-05									
342289	NO. 1 AHRs CONTROLLER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.140	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342290	NO. 2 AHRS CONTROLLER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.140	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342501	NO. 1 MULTIFUNCTION DISPLAY							Component	ATA:34
PN:822-1753-452	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:2WVPL	HRS	4113.7		TSO 0					
WC#: 34.130	AFL	3247		TSO 0					
PROC. REF: AMM 34-60-35PROC. REF: AMM 34-60-35									
342502	NO. 2 MULTIFUNCTION DISPLAY							Component	ATA:34
PN:822-1753-452	MOS/MSC	16-Jul-22	O/C	TSO 0					
SN:126DL	HRS	6078.7		TSO 0					
WC#: 34.135	AFL	4526		TSO 0					
PROC. REF: AMM 34-60-35PROC. REF: AMM 34-60-35									
342513	NO. 1 PRIMARY FLIGHT DISPLAY							Component	ATA:34
PN:822-1753-452	MOS/MSC	08-Jul-22	O/C	TSO 3					
SN:18X0W	HRS	6056.4		TSO 63.3					
WC#: 34.130	AFL	4512		TSO 39					
PROC. REF: AMM 34-60-35PROC. REF: AMM 34-60-35									
342514	NO. 2 PRIMARY FLIGHT DISPLAY							Component	ATA:34
PN:822-1753-452	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:2WVJJ	HRS	4113.7		TSO 0					
WC#: 34.135	AFL	3247		TSO 0					
PROC. REF: AMM 34-60-35PROC. REF: AMM 34-60-35									
342515	EFIS MULTIFUNCTION ELECTRONIC DISPLAY							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.140	AFL	0		TSN 0					
PROC. REF: MMA 34-70-13PROC. REF: MMA 34-70-13									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342516	NO. 1 REMOTE INSTRUMENT CONTROL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.145	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342517	NO. 2 REMOTE INSTRUMENT CONTROL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.145	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342523	MULTIFUNCTION PROCESS UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.335	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342525	NO. 1 EFIS DISPLAY PROCESSOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.335	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-13PROC. REF: AMM NO REF 1, MMA 34-70-13									
342526	NO. 2 EFIS DISPLAY PROCESSOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.335	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-13PROC. REF: AMM NO REF 1, MMA 34-70-13									
342527	NO. 1 EFIS SYMBOL GENERATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.150	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342528	NO. 2 EFIS SYMBOL GENERATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.150	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342530	MULTIFUNCTION SYMBOL GENERATOR							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.150	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342537	NO. 1 DISPLAY CONTROL PANEL							Component	ATA:34
PN:822-1485-066	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:273VD	HRS	0		TSN 0					
WC#: 34.155	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-13PROC. REF: AMM NO REF 1, MMA 34-70-13									
342538	NO. 2 DISPLAY CONTROL PANEL							Component	ATA:34
PN:822-1485-066	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:24F0Y	HRS	0		TSN 0					
WC#: 34.155	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-13PROC. REF: AMM NO REF 1, MMA 34-70-13									
342539	MULTI FUNCTION EFIS CONTROL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.160	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342540	FLIGHT GUIDANCE PANEL							Component	ATA:34
PN:822-1107-102	MOS/MSC	28-May-21	O/C	TSO 0					
SN:2D0YX	HRS	5243.7		TSO 0					
WC#: 34.440	AFL	3991		TSO 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342541	NO. 1 CONSOLE CONTROL DISPLAY UNIT							Component	ATA:34
PN:822-2117-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27R0N	HRS	0		TSN 0					
WC#: 34.445	AFL	0		TSN 0					
PROC. REF: MMA 23-80-10, AMM 23-80-05PROC. REF: MMA 23-80-10, AMM 23-80-05									
342542	NO. 2 CONSOLE CONTROL DISPLAY UNIT							Component	ATA:34
PN:822-2117-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2891X	HRS	0		TSN 0					
WC#: 34.450	AFL	0		TSN 0					
PROC. REF: MMA 23-80-10, AMM 23-80-05PROC. REF: MMA 23-80-10, AMM 23-80-05									
342543	PILOT OPTIONAL CONTROL MODULE							Component	ATA:34
PN:822-1484-248	MOS/MSC	09-Aug-18	O/C	TSN 0					
SN:4D93MN	HRS	4113.7		TSN 0					
WC#: 34.495	AFL	3247		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342544	COPILOT OPTIONAL CONTROL MODULE							Component	ATA:34
PN:822-1484-248	MOS/MSC	09-Aug-18	O/C	TSN 0					
SN:4D93MP	HRS	4113.7		TSN 0					
WC#: 34.495	AFL	3247		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342545	NO. 1 FLUX DETECTOR							Component	ATA:34
PN:822-1193-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:34528	HRS	0		TSN 0					
WC#: 34.500	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342546 ^U	#2 FLUX DETECTOR							Component	ATA:34
PN:822-1193-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:34476	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342550	IAPS ENVIROMENTAL CONTROLLER							Component	ATA:34
PN:822-1167-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2802H	HRS	0		TSN 0					
WC#: 34.505	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342552 ^U	#2 ENVIRONMENTAL CONTROLLER							Component	ATA:34
PN:2052-1-2	MOS/MSC	04-May-17	O/C						
SN:4CNLR	HRS	3584.2							
	AFL	2826							
342553 ^U	#3 ENVIRONMENTAL CONTROLLER							Component	ATA:34
PN:2052-1-2	MOS/MSC	04-May-17	O/C						
SN:32XFL	HRS	3584.2							
	AFL	2826							
342561	TCAS COMPUTER							Component	ATA:34
PN:822-1294-032	MOS/MSC	09-Jul-25	O/C						
SN:158570	HRS	7618.8							
WC#: 34.175	AFL	5593							
PROC. REF: MMA 34-45-06, MMA 34-45-07, AMM 34-50-35PROC. REF: MMA 34-45-06, MMA 34-45-07, AMM 34-50-35									
342562	TCAS (TOP) ANTENNA							Component	ATA:34
PN:622-8973-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1X9XP	HRS	0		TSN 0					
WC#: 34.180	AFL	0		TSN 0					
PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-50-35PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-50-35									
342563	TCAS (BOTTOM) ANTENNA							Component	ATA:34
PN:622-8973-001	MOS/MSC	01-Mar-19	O/C	TSN 0					
SN:4G30PY	HRS	4433.1		TSN 0					
WC#: 34.180	AFL	3477		TSN 0					
PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-50-35PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-50-35									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342601	NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.185	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342602	NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.185	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342624	NO. 1 ADF ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.190	AFL	0		TSN 0					
PROC. REF: AMM 34-50-15PROC. REF: AMM 34-50-15									
342625	NO. 2 ADF ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.190	AFL	0		TSN 0					
PROC. REF: AMM 34-50-15PROC. REF: AMM 34-50-15									
342640	EGPWS COMPUTER							Component	ATA:34
PN:965-0976-040-212	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:22052	HRS	0		TSN 0					
WC#: 34.455	AFL	0		TSN 0					
PROC. REF: MMA 34-44-06, AMM 34-40-35PROC. REF: MMA 34-44-06, AMM 34-40-35									
342701	NO. 1 DATA CONCENTRATOR UNIT							Component	ATA:34
PN:822-1483-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27BPR	HRS	0		TSN 0					
WC#: 34.515	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342703	NO. 2 DATA CONCENTRATOR UNIT							Component	ATA:34
PN:822-1483-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27BRX	HRS	0		TSN 0					
WC#: 34.515	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342705	NO. 3 DATA CONCENTRATOR UNIT							Component	ATA:34
PN:822-1483-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:25BRY	HRS	0		TSN 0					
WC#: 34.520	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342707	NO. 4 DATA CONCENTRATOR UNIT							Component	ATA:34
PN:822-1483-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27BTB	HRS	0		TSN 0					
WC#: 34.520	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342801	NO. 1 INPUT / OUTPUT CONCENTRATOR MODULE							Component	ATA:34
PN:822-2065-101	MOS/MSC	09-Aug-18	O/C	TSN 0					
SN:4F1F9C	HRS	4113.7		TSN 0					
WC#: 34.530	AFL	3247		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342802	NO. 2 INPUT / OUTPUT CONCENTRATOR MODULE							Component	ATA:34
PN:822-2065-101	MOS/MSC	09-Aug-18	O/C	TSN 0					
SN:4D93PR	HRS	4113.7		TSN 0					
WC#: 34.530	AFL	3247		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342803 ^U	#1 EXTERNAL COMPENSATION UNIT							Component	ATA:34
PN:822-1200-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1M4WH	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342804 ^U	#2 EXTERNAL COMPENSATION UNIT							Component	ATA:34
PN:822-1200-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2GPHX	HRS	0		TSN 0					
	AFL	0		TSN 0					
342805	NO. 1 IAPS POWER SUPPLY							Component	ATA:34
PN:822-1137-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:280BY	HRS	0		TSN 0					
WC#: 34.535	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342806	NO. 2 IAPS POWER SUPPLY							Component	ATA:34
PN:822-1137-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:280CB	HRS	0		TSN 0					
WC#: 34.535	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
342809	AURAL WARNING GENERATOR							Component	ATA:34
PN:630-003	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:296	HRS	0		TSN 0					
WC#: 34.540	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
343001	GLIDE SLOPE AERIAL							Component	ATA:34
PN:17-21F6MODI	MOS/MSC	29-Jan-11	O/C	TSN 0					
SN:7951	HRS	887.9		TSN 0					
WC#: 34.195	AFL	721		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
343013	MARKER AERIAL							Component	ATA:34
PN:17-5C	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7439	HRS	0		TSN 0					
WC#: 34.200	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344001	NO. 1 WEATHER RADAR CONTROL PANEL								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.205	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-41-29PROC. REF: AMM NO REF 1, MMA 34-41-29									
344002	NO. 2 WEATHER RADAR CONTROL PANEL								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.205	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-41-29PROC. REF: AMM NO REF 1, MMA 34-41-29									
344005	WEATHER RADAR TRANSCEIVER								Component ATA:34
PN:622-8441-004	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:26DGB	HRS	0		TSN 0					
WC#: 34.210	AFL	0		TSN 0					
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
344016	RADAR CHECKLIST MODULE								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.215	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
344036	ISOLATION VALVE								Component ATA:34
PN:25MC2175	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:38050385	HRS	0		TSN 0					
WC#: 34.220	AFL	0		TSN 0					
PROC. REF: AMM 34-11-52PROC. REF: AMM 34-11-52									
345001	NO. 1 VHF NAVIGATION RECEIVER								Component ATA:34
PN:822-1465-101	MOS/MSC	17-Nov-22	O/C	TSO 2					
SN:3XGWB	HRS	6226.3		TSO 0					
WC#: 34.300	AFL	4623		TSO 0					
PROC. REF: AMM 34-32-30PROC. REF: AMM 34-32-30									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345002	NO. 2 VHF NAVIGATION RECEIVER							Component	ATA:34
PN:822-1579-101	MOS/MSC	16-May-25	O/C						
SN:2HW3L	HRS	7556.8							
WC#: 34.300	AFL	5543							
PROC. REF: AMM 34-32-30PROC. REF: AMM 34-32-30									
345008	SENSOR UNIT DISPLAY							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.295	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-22PROC. REF: AMM NO REF 1, MMA 34-70-22									
345009	SENSOR DRIVER DISPLAY							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.295	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-70-22PROC. REF: AMM NO REF 1, MMA 34-70-22									
345015	ILS CONVERTER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.300	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345019	NO. 1 ADF RECEIVER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.310	AFL	0		TSN 0					
PROC. REF: MMA 34-52-01, AMM 34-50-15, AMM 34-50-20PROC. REF: MMA 34-52-01, AMM 34-50-15, AMM 34-50-20									
345020	NO. 2 ADF RECEIVER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.310	AFL	0		TSN 0					
PROC. REF: MMA 34-52-01, AMM 34-50-15, AMM 34-50-20PROC. REF: MMA 34-52-01, AMM 34-50-15, AMM 34-50-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345037	LEFT VOR/LOC AERIAL							Component	ATA:34
PN:S65-247-12	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6267	HRS	0		TSN 0					
WC#: 34.230	AFL	0		TSN 0					
PROC. REF: AMM 34-32-35PROC. REF: AMM 34-32-35									
345038	RIGHT VOR/LOC AERIAL							Component	ATA:34
PN:S65-247-12	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6268	HRS	0		TSN 0					
WC#: 34.230	AFL	0		TSN 0					
PROC. REF: AMM 34-32-35PROC. REF: AMM 34-32-35									
345049	NO. 1 ADF LOOP ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.235	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345097	PHASING COUPLER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.240	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345098	COUPLER ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.245	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345109	NO. 1 DME AERIAL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.250	AFL	0		TSN 0					
PROC. REF: AMM 34-50-05PROC. REF: AMM 34-50-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345110	NO. 2 DME AERIAL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.250	AFL	0		TSN 0					
PROC. REF: AMM 34-50-05PROC. REF: AMM 34-50-05									
345133	NO. 1 ATC TRANSPONDER AERIAL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.255	AFL	0		TSN 0					
PROC. REF: AMM 34-50-25PROC. REF: AMM 34-50-25									
345134	NO. 2 ATC TRANSPONDER AERIAL							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.255	AFL	0		TSN 0					
PROC. REF: AMM 34-50-25PROC. REF: AMM 34-50-25									
345135	FORWARD TRANSPONDER ANTENNA							Component	ATA:34
PN:S65-5366-10L	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6422	HRS	0		TSN 0					
WC#: 34.460	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345136	AFT TRANSPONDER ANTENNA							Component	ATA:34
PN:S65-5366-10L	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:6600	HRS	0		TSN 0					
WC#: 34.465	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345205	NO. 1 DME TRANSCEIVER							Component	ATA:34
PN:822-1466-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:278FK	HRS	0		TSN 0					
WC#: 34.305	AFL	0		TSN 0					
PROC. REF: MMA 34-42-13, AMM 34-50-05PROC. REF: MMA 34-42-13, AMM 34-50-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345206	NO. 2 DME TRANSCEIVER							Component	ATA:34
PN:822-1466-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:278FP	HRS	0		TSN 0					
WC#: 34.305	AFL	0		TSN 0					
PROC. REF: MMA 34-42-13, AMM 34-50-05PROC. REF: MMA 34-42-13, AMM 34-50-05									
345217	NO. 1 ATC TRANSPONDER							Component	ATA:34
PN:622-9210-501	MOS/MSC	08-Dec-23	O/C	TSN 64					
SN:30N3D	HRS	6763.7		TSN 2650					
WC#: 34.260	AFL	4989		TSN 1742					
PROC. REF: MMA 34-43-64, AMM 34-50-25PROC. REF: MMA 34-43-64, AMM 34-50-25									
345218	NO. 2 ATC TRANSPONDER							Component	ATA:34
PN:622-9210-501	MOS/MSC	08-Dec-23	O/C	TSN 64					
SN:4G9U	HRS	6763.7		TSN 2650					
WC#: 34.260	AFL	4989		TSN 1742					
PROC. REF: MMA 34-43-64, AMM 34-50-25PROC. REF: MMA 34-43-64, AMM 34-50-25									
345229	SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413)							Service	ATA:34
PN:622-9210-501	MOS	08-Dec-23	24		08-Dec-25		89 d	MANDATORY	
SN:30N3D	HRS								
WC#: 34.260	AFL								
Test Date: : 08-Dec-23									
PROC. REF: FAR FAR PART 91PROC. REF: FAR FAR PART 91									
345230	SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413)							Service	ATA:34
PN:622-9210-501	MOS	08-Dec-23	24		08-Dec-25		89 d	MANDATORY	
SN:4G9U	HRS								
WC#: 34.260	AFL								
Test Date: : 08-Dec-23									
PROC. REF: FAR FAR PART 91PROC. REF: FAR FAR PART 91									
345305	MACH TRIM COMPUTER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.270	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345309	AFIS DMU								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.470	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1, MMA 34-61-05, MMA 34-61-10, MMA 34-61-15, MMA 34-61-20PROC. REF: AMM NO REF 1, MMA 34-61-05, MMA 34-61-10, MMA 34-61-15, MMA 34-61-20									
345310	AFIS CONFIGURATION MODULE								Component ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.475	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345404	NO. 1 GPS SENSOR UNIT								Component ATA:34
PN:822-2189-004	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:3LPHT	HRS	4113.7		TSO 0					
WC#: 34.275	AFL	3247		TSO 0					
PROC. REF: AMM 34-50-45PROC. REF: AMM 34-50-45									
345405	NO. 2 GPS SENSOR UNIT								Component ATA:34
PN:822-2189-004	MOS/MSC	09-Aug-18	O/C	TSO 0					
SN:371CC	HRS	4113.7		TSO 0					
WC#: 34.275	AFL	3247		TSO 0					
PROC. REF: AMM 34-50-45PROC. REF: AMM 34-50-45									
345406	NO. 1 GPS ANTENNA								Component ATA:34
PN:CI 429-410	MOS/MSC	08-Dec-18	O/C	TSN 0					
SN:447962	HRS	4330.3		TSN 0					
WC#: 34.280	AFL	3402		TSN 0					
PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-50-45PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-50-45									
345407	NO. 2 GPS ANTENNA								Component ATA:34
PN:CI 429-200	MOS/MSC	09-Jun-10	O/C	TSN 0					
SN:321068	HRS	535.1		TSN 0					
WC#: 34.280	AFL	450		TSN 0					
PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-50-45PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-50-45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345413	NO. 1 CONFIGURATION STRAPPING UNIT							Component	ATA:34
PN:822-1363-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27YGB	HRS	0		TSN 0					
WC#: 34.285	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345414	NO. 2 CONFIGURATION STRAPPING UNIT							Component	ATA:34
PN:822-1363-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:27YGC	HRS	0		TSN 0					
WC#: 34.285	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345513	NO. 1 (AHRS) EXTERNAL COMPENSATION UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.480	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
345514	NO. 2 (AHRS) EXTERNAL COMPENSATION UNIT							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.480	AFL	0		TSN 0					
PROC. REF: AMM NO REF 1PROC. REF: AMM NO REF 1									
346810	OBSERVERS AMPLIFER							Component	ATA:34
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.601	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
349001 ^U	NAV DATABASE UPDATE (J8)							Service	ATA:34
	DAYS	09-Jul-25	28		03-Sep-25 (M)		OVD		
	HRS	7579.6							
	AFL	5563							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
349002 ^U	NO. 1 FILE SERVER UNIT							Component	ATA:34
PN:822-1543-101	MOS/MSC		O/C	TSN 115					
SN:28X6F	HRS			TSN 2846.3					
	AFL			TSN 2266					
349003 ^U	NO. 2 FILE SERVER UNIT							Component	ATA:34
PN:822-1543-101	MOS/MSC	26-Oct-12	O/C	TSO 0					
SN:4B9XK	HRS	1626.3		TSO 0					
	AFL	1311		TSO 0					
349020 ^U	AMPLIFIER PASSENGER SPEAKER							Component	ATA:34
PN:MODEL 240	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3461	HRS	0		TSN 0					
	AFL	0		TSN 0					
349030 ^U	CMU-4000 UNIT							Component	ATA:34
PN:822-1739-003	MOS/MSC	18-Jul-13	O/C	TSO 0					
SN:3B3NL	HRS	1912.2		TSO 0					
	AFL	1516		TSO 0					
349050 ^U	MAINTENANCE DIAGNOSTIC COMPUTER							Component	ATA:34
PN:822-1987-005	MOS/MSC	30-Nov-18	O/C	TSO 0					
SN:285MN	HRS	4303.5		TSO 0					
	AFL	3383		TSO 0					
349081 ^U	ANTENNA, ADF							Component	ATA:34
PN:622-7384-001	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2683D	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
349998	ADJUSTMENT/TEST COLLINS AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)							Service	ATA:34
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 34.T04	AFL	0							
PROC. REF: AMM 34-10-19PROC. REF: AMM 34-10-19									
349999	ADJUSTMENT/TEST HONEYWELL ADZ-810 AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)							Service	ATA:34
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 34.T05	AFL	0							
34K101 ^U	XM WEATHER RECEIVER							Component	ATA:34
PN:270-2826-020	MOS/MSC		-						
SN:809001847	HRS								
	AFL								
34R005 ^U	ACCOMPLISH NO. 1 PITOT STATIC SYSTEM CERTIFICATION (FAR 91.411)							Service	ATA:34
	MOS	08-Dec-23	24		08-Dec-25		89 d		
	HRS	6763.7							
	AFL	4989							
34R006 ^U	ACCOMPLISH NO. 2 PITOT STATIC SYSTEM CERTIFICATION (FAR 91.411)							Service	ATA:34
	MOS	08-Dec-23	24		08-Dec-25		89 d		
	HRS	6763.7							
	AFL	4989							
34R019 ^U	COMPLY WITH RVSM CERTIFICATION							Service	ATA:34
	MOS	08-Dec-23	24		08-Dec-25		89 d		
	HRS	6763.7							
	AFL	4989							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
34R107 ^U		EGPWS SOFTWARE VERIFICATION AND UPDATE						Service	ATA:34
	MOS	14-May-25	6		14-Nov-25		65 d		
	HRS	7546							
	AFL	5538							
34S001 ^U		SYNTHETIC VISION COMPUTER SVC-3000						Component	ATA:34
PN:866-0232-010,	MOS/MSC	19-Oct-23	O/C	TSR 0					
SN:4RTM3	HRS	6755.2		TSR 0					
	AFL	4984		TSR 0					
34S002 ^U		SYNTHETIC VISION VIDEO INTERFACE UNIT VIU-3000						Component	ATA:34
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
34S003 ^U		SYNTHETIC VISION CONFIGURATION SVCM-3000						Component	ATA:34
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
ATA 35 - OXYGEN									
350001 ^S		CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE						Service	ATA:35
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 35.110	AFL	5563							
								PKG:10,91	
350002 ^S		FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE						Service	ATA:35
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 35.035	AFL	4989							
								PKG:32,93	
PROC. REF: AMM 35-10-141PROC. REF: AMM 35-10-141									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
350004	^S	TEST/INSPECT PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 35.075	AFL	5563							
PROC. REF: MMA 35-06-00, MMA 35-20-05, AMM 35-06-00PROC. REF: MMA 35-06-00, MMA 35-20-05, AMM 35-06-00									PKG:44,94
350005	^S	CHECK BAROMATIC CONTROL VALVE							Service ATA:35
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 35.100	AFL	5563							
									PKG:44,94
350006	^S	INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES							Service ATA:35
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 35.115	AFL	5563							
									PKG:46,94
350007	^S	INSPECT PORTABLE BREATHING EQUIPMENT							Service ATA:35
	MOS	04-Jun-25	12 (+1m/-1m)						
	HRS	7579.6							
WC#: 35.120	AFL	5563							
PROC. REF: AMM 35-35-15PROC. REF: AMM 35-35-15									PKG:46,94
350008	^S	INSPECT OXYGEN CYLINDERS							Service ATA:35
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 35.105	AFL	4989							
									PKG:25,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351001	MASTER OXYGEN SUPPLY VALVE								Component ATA:35
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.030	AFL	0		TSN 0					
PROC. REF: AMM 35-10-62PROC. REF: AMM 35-10-62									
351013	OXYGEN PRESSURE GAUGE								Component ATA:35
PN:18430901-1	MOS/MSC	21-Nov-14	O/C	TSN 0					
SN:074630	HRS	2399.6		TSN 0					
WC#: 35.040	AFL	1907		TSN 0					
PROC. REF: AMM 35-10-32PROC. REF: AMM 35-10-32									
351014	ALTERNATIVE OXYGEN PRESSURE GAUGE								Component ATA:35
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.040	AFL	0		TSN 0					
PROC. REF: AMM 35-10-33PROC. REF: AMM 35-10-33									
351015	OXYGEN CHARGING FILTER ASSEMBLY								Component ATA:35
PN:WKA27942-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1732	HRS	0		TSN 0					
WC#: 35.215	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351025	OXYGEN REDUCING VALVE								Component ATA:35
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351031	PILOT OXYGEN MASK (OVERHAUL)								Component ATA:35
PN:MF10-03-02	MOS	17-Aug-23	72	TSO 0	17-Aug-29		1437 d	OVERHAUL	
SN:SE57076	HRS	6657							
WC#: 35.050	AFL	4901							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351032	COPILOT OXYGEN MASK (OVERHAUL)							Component	ATA:35
PN:MF10-03-02	MOS	17-Aug-23	72	TSO 0	17-Aug-29		1437 d	OVERHAUL	
SN:SE5775	HRS	6657							
WC#: 35.050	AFL	4901							
351043	LEFT OXYGEN OUTLET VALVE							Component	ATA:35
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351044	RIGHT OXYGEN OUTLET VALVE							Component	ATA:35
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351050	CREW CABINET OXYGEN MASK							Component	ATA:35
PN:289-601-228	MOS/MSC	15-Jan-16	A/R						
SN:UNKNOWN	HRS	2779.3		TSN 0					
WC#: 35.145	AFL	2221		TSN 0					
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351051	NO. 1 PASSENGER OXYGEN MASK							Component	ATA:35
PN:289-601-228	MOS/MSC	15-Jan-16	A/R						
SN:UNKNOWN	HRS	2779.3		TSN 0					
WC#: 35.150	AFL	2221		TSN 0					
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351052	NO. 2 PASSENGER OXYGEN MASK							Component	ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 0					
SN:UNKNOWN	HRS	1320.3		TSN 0					
WC#: 35.150	AFL	1070		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351053	NO. 3 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 0					
SN:UNKNOWN	HRS	1320.3		TSN 0					
WC#: 35.155	AFL	1070		TSN 0					
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351054	NO. 4 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 0					
SN:UNKNOWN	HRS	1320.3		TSN 0					
WC#: 35.155	AFL	1070		TSN 0					
351055	NO. 5 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 0					
SN:UNKNOWN	HRS	1320.3		TSN 0					
WC#: 35.160	AFL	1070		TSN 0					
351056	NO. 6 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 0					
SN:UNKNOWN	HRS	1320.3		TSN 0					
WC#: 35.160	AFL	1070		TSN 0					
351057	NO. 7 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	28-Apr-22	A/R	TSN 0					
SN:UNKNOWN	HRS	5938		TSN 0					
WC#: 35.170	AFL	4436		TSN 0					
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351058	NO. 8 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 3					
SN:NA	HRS	1320.3		TSN 0					
WC#: 35.170	AFL	1070		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351059	NO. 9 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 3					
SN:NA	HRS	1320.3		TSN 0					
WC#: 35.180	AFL	1070		TSN 0					
351060	NO. 10 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 3					
SN:NA	HRS	1320.3		TSN 0					
WC#: 35.180	AFL	1070		TSN 0					
351061	NO. 11 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 3					
SN:NA	HRS	1320.3		TSN 0					
WC#: 35.190	AFL	1070		TSN 0					
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351062	NO. 12 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-228	MOS/MSC	20-Jan-12	A/R	TSN 3					
SN:NA	HRS	1320.3		TSN 0					
WC#: 35.190	AFL	1070		TSN 0					
351080	NO. 1 MASK DEPLOYMENT CONTAINER								Component ATA:35
PN:833-649-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:0474	HRS	0		TSN 0					
WC#: 35.195	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351081	NO. 2 MASK DEPLOYMENT CONTAINER								Component ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2927	HRS	0		TSN 0					
WC#: 35.195	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351082	NO. 3 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2928	HRS	0		TSN 0					
WC#: 35.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351083	NO. 4 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2929	HRS	0		TSN 0					
WC#: 35.200	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351084	NO. 5 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2930	HRS	0		TSN 0					
WC#: 35.205	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351085	NO. 6 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2931	HRS	0		TSN 0					
WC#: 35.205	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351086	NO. 7 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:2932	HRS	0		TSN 0					
WC#: 35.210	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351093	OXYGEN PRESSURE SWITCH							Component	ATA:35
PN:1106P76-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1144	HRS	0		TSN 0					
WC#: 35.125	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351101		NO. 1 OXYGEN CYLINDER						Component	ATA:35
PN:WKA37447	MOS/MSC	13-Nov-24	O/C	TSN 220, TSO 0					
SN:5772-2820	HRS	7229.5	TSO 0						
WC#: 35.010	AFL	5306	TSO 0						
PROC. REF: AMM 35-10-14PROC. REF: AMM 35-10-14									
351102		NO. 2 OXYGEN CYLINDER						Component	ATA:35
PN:WKA37447	MOS/MSC	13-Nov-24	O/C	TSN 218, TSO 0					
SN:2272-280	HRS	7229.5	TSO 0						
WC#: 35.015	AFL	5306	TSO 0						
PROC. REF: AMM 35-10-14PROC. REF: AMM 35-10-14									
351103		NO. 3 OXYGEN CYLINDER						Component	ATA:35
PN:WKA37447	MOS/MSC	13-Nov-24	O/C	TSO 0					
SN:560683	HRS	7229.5	TSO 0						
WC#: 35.020	AFL	5306	TSO 0						
PROC. REF: MMA 35-06-01, AMM 35-10-14PROC. REF: MMA 35-06-01, AMM 35-10-14									
351104		NO. 4 OXYGEN CYLINDER						Component	ATA:35
PN:WKA37447	MOS/MSC	13-Nov-24	O/C	TSO 0					
SN:680871	HRS	7229.5	TSO 0						
WC#: 35.025	AFL	5306	TSO 0						
PROC. REF: MMA 35-06-01PROC. REF: MMA 35-06-01									
351110		HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER						Service	ATA:35
PN:WKA37447	MOS	13-Nov-24	60	29-Oct-29			1510 d		
SN:5772-2820	HRS	7229.5							
WC#: 35.010	AFL	5306							
			HydroCheck Date: : 29-Oct-24						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351110		HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER						Service	ATA:35
PN:WKA37447	MOS	13-Nov-24	60	29-Oct-29			1510 d		
SN:2272-280	HRS	7229.5							
WC#: 35.015	AFL	5306							
			HydroCheck Date: : 29-Oct-24						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351110	HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER								Service ATA:35
PN:WKA37447	MOS	13-Nov-24	60		29-Oct-29		1510 d		
SN:560683	HRS	7229.5							
WC#: 35.020	AFL	5306							
HydroCheck Date: : 29-Oct-24									
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
351110	HYDROSTATIC TEST NO. 4 OXYGEN CYLINDER								Service ATA:35
PN:WKA37447	MOS	13-Nov-24	60		01-Oct-29 (M)		1482 d		
SN:680871	HRS	7229.5							
WC#: 35.025	AFL	5306							
HydroCheck Date: : 29-Oct-24									
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
352001	ON/OFF OXYGEN VALVE								Component ATA:35
PN:SDV1012	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:14463	HRS	0		TSN 0					
WC#: 35.065	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
352007	BAROMATIC VALVE								Component ATA:35
PN:K39117/1	MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:1215	HRS			TSN 0					
WC#: 35.070	AFL			TSN 0					
PROC. REF: AMM 35-20-42PROC. REF: AMM 35-20-42									
353031	(PBE) PROTECTIVE BREATHING EQUIPMENT (LIFE LIMIT)								Component ATA:35
PN:MR-1022N	MOS	06-Mar-24	120		14-Nov-33		2987 d	LIFE LIMIT	
SN:#2306602	HRS	6917.1							
WC#: 35.085	AFL	5082							
Manufacture Date:: 14-Nov-23									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
354000	AUTOMATIC SHUT OFF VALVE								Component ATA:35
PN:WKA35964-1	MOS/MSC	08-Dec-23	O/C	TSO 0					
SN:1929	HRS	6763.7		TSO 0					
WC#: 35.130	AFL	4989		TSO 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

PROC. REF: AMM 35-10-141PROC. REF: AMM 35-10-141

ATA 38 - WATER/WASTE

380001	^S	INSPECT TOILET AND GALLEY WATER SYSTEMS						Service	ATA:38
		MOS	04-Jun-25						
		HRS	7579.6	800 (+40/-10)					
WC#: 38.010		AFL	5563						
									PKG:12,91
PROC. REF: AMM 12-38-00PROC. REF: AMM 12-38-00									

381091	^S	CLEAN LAVATORY WATER SYSTEM						Service	ATA:38
		DAYS/MSC	24-Nov-20	A/R					
		HRS	4871.1						
WC#: 38.030		AFL	3789						
PROC. REF: MMA 38-20-00, MMA 38-20-05PROC. REF: MMA 38-20-00, MMA 38-20-05									

383028	^U	TOILET						Component	ATA:38
PN:4620-106		MOS/MSC	29-Jun-06	O/C	TSN 0				
SN:190		HRS	0		TSN 0				
		AFL	0		TSN 0				

383030	^U	TOILET BUNG						Component	ATA:38
PN:4259-31		MOS/MSC	21-Nov-18	O/C					
SN:NSN		HRS	4279.7						
		AFL	3370						

389000	^U	LAVATORY WATER PUMP/BACKET ASSY						Component	ATA:38
PN:9168		MOS/MSC	14-Jun-23	O/C					
SN:1193892		HRS	6574.2						
		AFL	4842						

ATA 44 - CABIN SYSTEMS

442516	^U	#1 VIDEO MONITOR						Component	ATA:44
PN:2710-1-1501		MOS/MSC	29-Jun-06	O/C	TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 44 - CABIN SYSTEMS									
SN:206180101	HRS	0		TSN 0					
	AFL	0		TSN 0					
442517 ^U	#2 VIDEO MONITOR							Component	ATA:44
PN:2710-1-1501	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:206180103	HRS	0		TSN 0					
	AFL	0		TSN 0					
442519 ^U	8X8 AUDIO VIDEO CONTROL MODULELOCATED AFT SIDE OF DA PANEL							Component	ATA:44
PN:2022-1-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:205410192	HRS	0		TSN 0					
	AFL	0		TSN 0					
442520 ^U	DVD PLAYER							Component	ATA:44
PN:866-0027-004	MOS/MSC	08-May-17	O/C	TSO 0					
SN:004695	HRS	3587.2		TSO 0					
	AFL	2828		TSO 0					
442524 ^U	CD CHANGER - CONTROLLER							Component	ATA:44
PN:3201-1-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:206070165	HRS	0		TSN 0					
	AFL	0		TSN 0					
443503 ^U	#1 HANDSET (FLIGHTPHONE)							Component	ATA:44
PN:310-10590-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1059511191	HRS	0		TSN 0					
	AFL	0		TSN 0					
443504 ^U	#2 HANDSET (FLIGHTPHONE)							Component	ATA:44
PN:310-10590-002	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1059011238	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 44 - CABIN SYSTEMS

ATA 49 - AIRBORNE AUXILIARY POWER

490001	INSPECT PATS APU GTCP36-150W							Service	ATA:49
	MOS	21-Feb-25	12 (+1m)		28-Feb-26	21-Mar-26	171 d (+21)		
	HRS	7403.7	1000 (+10%)		8403.7	8503.7	743.5 (+100)		
WC#: 49.205	AFL	5430							

490002	REMOVE/CLEAN/INSPECT APU IGNITER PLUG							Service	ATA:49
	MOS	20-May-23							
	HRS	6556.1							
WC#: 49.210	AFL	4826							
	APH	4514	750		5264		742		

490003	ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION							Service	ATA:49
	MOS	19-Feb-25	12 (+1m)		28-Feb-26	19-Mar-26	171 d (+19)		
	HRS	7403.7	1000 (+10%)		8403.7	8503.7	743.5 (+100)		
WC#: 49.220	AFL	5430							

490003	ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK							Service	ATA:49
	MOS/MSC	29-Jun-06	N/R						
	HRS	0							
WC#: 49.221	AFL	0							

490004	REMOVE AND REPLACE APU FUEL FILTER ELEMENT							Service	ATA:49
	MOS	20-May-23							
	HRS	6556.1							
WC#: 49.230	AFL	4826							
	APH	4514	1000		5514		992		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
490005	FLOW CHECK APU FUEL NOZZLE ASSEMBLIES								Service ATA:49
	MOS	20-May-23							
	HRS	6556.1							
WC#: 49.240	AFL	4826							
	APH	4514	4500		9014		4492		
490006	ACCOMPLISH APU DETAILED HOT SECTION INSPECTION								Service ATA:49
	MOS	20-May-23							
	HRS	6556.1							
WC#: 49.250	AFL	4826							
	APH	4514	4500		9014		4492		
490007	VISUALLY CHECK APU COMPRESSOR ROTOR								Service ATA:49
	MOS	20-May-23							
	HRS	6556.1							
WC#: 49.260	AFL	4826							
	APH	4514	4500		9014		4492		
491005	APU BLEED AIR CHECK VALVE								Component ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
491010	APU - TURBINE ROTOR (LIFE LIMIT)								Component ATA:49
PN:3615880-1	MOS	06-Mar-06		TSN 0				LIFE LIMIT	
SN:060134501096	HRS	0	10000	TSN 0	10000		5478		
WC#: 49.010	APUS	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
491020	APU - COMPRESSOR ROTOR (LIFE LIMIT)								Component ATA:49
PN:3822101-1	MOS	06-Mar-06		TSN 0				LIFE LIMIT	
SN:050350108912	HRS	0	100000	TSN 0	100000		95478		
WC#: 49.015	APUS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
491025 ^S	APU - INSPECT COMPRESSOR ROTOR							Service	ATA:49
PN:3822101-1	MOS	20-May-23							
SN:050350108912	HRS	4514	4500						
WC#: 49.020	APUS								
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00									
491030 ^S	APU - INSPECT HOT SECTION							Service	ATA:49
	MOS	20-May-23							
	HRS	4514	4500						
WC#: 49.025	APUS								
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00									
493010	APU - FUEL CONTROL							Component	ATA:49
PN:3882730-9	MOS/MSC	06-Mar-06	O/C	TSN 0					
SN:30346	HRS	0		TSN 0					
WC#: 49.030	APUS	0		TSN 0					
PROC. REF: MM 49-30-52PROC. REF: MM 49-30-52									
493020 ^S	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service	ATA:49
	MOS	20-May-23							
	HRS	4514	1000						
WC#: 49.035	APUS								
PROC. REF: MM 49-30-52PROC. REF: MM 49-30-52									
493030	APU - ORIFICE FITTING							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.040	APUS	0		TSN 0					
PROC. REF: MM 49-30-56PROC. REF: MM 49-30-56									
493040	APU - FUEL SHUTOFF VALVE							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.045	APUS	0		TSN 0					
PROC. REF: MM 49-30-54PROC. REF: MM 49-30-54									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
493050 ^S	APU - CHECK FUEL NOZZLE FLOW RATE								Service ATA:49
	MOS	20-May-23							
	HRS	4515	4500						
WC#: 49.050	APUS								
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00									
493060	APU - CONTROLLER								Component ATA:49
PN:2118330-2	MOS/MSC	15-Jun-10	O/C	TSR 4					
SN:11-B0415	HRS	537		TSR 0					
WC#: 49.055	APUS	1090		TSR 0					
PROC. REF: MM 49-60-46PROC. REF: MM 49-60-46									
493070	APU - LOAD CONTROL VALVE								Component ATA:49
PN:109812-9	MOS/MSC	06-Mar-06	O/C	TSN 0					
SN:4177	HRS	0		TSN 0					
WC#: 49.060	APUS	0		TSN 0					
PROC. REF: MM 49-50-33PROC. REF: MM 49-50-33									
494010	APU - IGNITION UNIT								Component ATA:49
PN:3888000-2	MOS/MSC	03-Aug-23	O/C						
SN:91310867	HRS	4522							
WC#: 49.065	APUS	0							
PROC. REF: MM 49-40-32PROC. REF: MM 49-40-32									
494020	APU - IGNITER PLUG								Component ATA:49
PN:3888002-2	MOS/MSC	20-May-23	O/C	TSN 0					
SN:N/A	HRS	4514		TSN 0					
WC#: 49.070	APUS			TSN 0					
PROC. REF: MM 49-40-33PROC. REF: MM 49-40-33									
494030 ^S	APU - REMOVE AND INSPECT IGNITER PLUG								Service ATA:49
PN:3888002-2	MOS	20-May-23							
SN:N/A	HRS	4514	750						
WC#: 49.075	APUS								
PROC. REF: MM 49-40-33PROC. REF: MM 49-40-33									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
497010	APU - MOTION PICK UP TRANSDUCER							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.080	APUS	0		TSN 0					
PROC. REF: MM 49-60-43PROC. REF: MM 49-60-43									
497020	APU - IMMERSION THERMOCOUPLE							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.085	APUS	0		TSN 0					
PROC. REF: MM 49-60-45PROC. REF: MM 49-60-45									
497030	APU - HOURMETER							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.090	APUS	0		TSN 0					
PROC. REF: MM 49-70-41PROC. REF: MM 49-70-41									
499010	APU - ROTARY OIL PUMP							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.095	APUS	0		TSN 0					
PROC. REF: MM 49-90-51PROC. REF: MM 49-90-51									
499020	APU - INSPECT MAGNETIC DRAIN PLUG							Service	ATA:49
	MOS	19-Feb-25	12		19-Feb-26		162 d		
	HRS	4522	750		5272		750		
WC#: 49.100	APUS	0							
PROC. REF: MM 49-90-46PROC. REF: MM 49-90-46									
499030	APU - CHANGE OIL							Service	ATA:49
	MOS	19-Feb-25	12		19-Feb-26		162 d		
	HRS	4522	750		5272		750		
WC#: 49.105	APUS	0							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
499040	APU - REMOVE AND REPLACE OIL FILTER ELEMENT							Service	ATA:49
	MOS	19-Feb-25	12		19-Feb-26		162 d		
	HRS	4522	750		5272		750		
WC#: 49.110	APUS	0							
PROC. REF: MM 49-90-47PROC. REF: MM 49-90-47									
499050	APU - PRESSURE REGULATOR VALVE							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.115	APUS	0		TSN 0					
PROC. REF: MM 49-90-52PROC. REF: MM 49-90-52									
499060	APU - HIGH OIL TEMPERATURE SWITCH							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.120	APUS	0		TSN 0					
PROC. REF: MM 49-60-46PROC. REF: MM 49-60-46									
499070	APU - LOW OIL PRESSURE SWITCH							Component	ATA:49
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 49.125	APUS	0		TSN 0					
PROC. REF: MM 49-60-43PROC. REF: MM 49-60-43									
499110 ^S	APU - SOAP CHECK OIL							Service	ATA:49
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 49.130	APUS	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
499999 ^U	APU MONTHLY HOURS READING							Service	ATA:49
	MOS	29-Jul-25	1		31-Aug-25		OVD		
	HRS	7659.5							
	AFL	5622							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
49APU1	APU							Component	ATA:49
PN:3800304-1	MOS/MSC	30-Aug-06	E/C	TSN 0					
SN:P-913	HRS	0		TSN 0					
WC#: 49.APU1	AFL	0		TSN 0					
PROC. REF: AMM 49-11-00PROC. REF: AMM 49-11-00									
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
510001	INSPECT/NDT NOSE LANDING GEAR BAY SIDEWALLS							Service	ATA:51
	MOS	10-Aug-18	144 (+3m)	Adj -42d	29-Jun-30	29-Sep-30	1753 d (+92)		
	HRS	4113.7							
WC#: 51.100	AFL	3247	5000 (+10%)		8247	8747	2624 (+500)		
PROC. REF: NTM 53-10-10PROC. REF: NTM 53-10-10									
510002	DETAIL INSPECT FRONT PRESSURE BULKHEAD							Service	ATA:51
	MOS	08-Dec-23							
	HRS	6763.7							
WC#: 51.010	AFL	4989	1000 (+10%)		5989	6089	366 (+100)		
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
510003	INSPECT/NDT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS							Service	ATA:51
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 51.020	AFL	4577							
PROC. REF: NTM 53-10-30, NTM 53-10-35PROC. REF: NTM 53-10-30, NTM 53-10-35									
510004	DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS							Service	ATA:51
	MOS	14-Sep-06							
	HRS	8.5							
WC#: 51.030	AFL	7	20000 (+500)		20007	20507	14384 (+500)		
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
510005	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19							Service	ATA:51
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 51.040	AFL	5306							
PROC. REF: NTM 53-10-45PROC. REF: NTM 53-10-45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
510006	DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14								Service ATA:51
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 51.050	AFL	5306							
510007	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17								Service ATA:51
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 51.060	AFL	5306							
PROC. REF: NTM 53-10-45PROC. REF: NTM 53-10-45									
510008	X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16								Service ATA:51
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 51.070	AFL	5306							
PROC. REF: NTM 53-10-45PROC. REF: NTM 53-10-45									
510009	DETAIL INSPECT ENTRY DOOR SURROUND								Service ATA:51
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 51.080	AFL	4577							
510010	INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR								Service ATA:51
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 51.090	AFL	5306							
PROC. REF: NTM 53-10-40PROC. REF: NTM 53-10-40									
ATA 52 - DOORS									
520004 ^S	CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES								Service ATA:52
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 52.025	AFL	4989							
									PKG:24,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
520005 ^S	CHECK ESCAPE HATCH RELEASE MECHANISM								Service ATA:52
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 52.015	AFL	5563							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									PKG:12,91
520006 ^S	INSPECT ESCAPE HATCH SEALS								Service ATA:52
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 52.035	AFL	5563							
									PKG:12,91
520007 ^S	INSPECT/CHECK ENTRY DOOR								Service ATA:52
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 52.010	AFL	4989							
PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00									PKG:24,92
520008	INSPECT/NDT MAIN ENTRY DOOR								Service ATA:52
	MOS	10-Aug-18	96 (+3m)		10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	4113.7							
WC#: 52.010	AFL	3247							
PROC. REF: NTM 52-80-10PROC. REF: NTM 52-80-10									
520009	DETAIL INSPECT ESCAPE HATCH								Service ATA:52
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 52.015	AFL	5306							
520010 ^S	INSPECT MAIN ENTRY DOOR - FOLDING HANDRAIL (IF FITTED)								Service ATA:52
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 52.050	AFL	4989							
									PKG:24,92

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 52 - DOORS

PROC. REF: MMA 52-15-00PROC. REF: MMA 52-15-00

521001	MAIN ENTRY DOOR ASSEMBLY							Component	ATA:52
PN:259W03838-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:SD-DH-678	HRS	0		TSN 0					
WC#: 52.010	AFL	0		TSN 0					
PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00									

521016	LONG RANGE TANK DOOR							Component	ATA:52
PN:25-8PT111-87A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PZL-DH-866	HRS	0		TSN 0					
WC#: 52.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

522001	ESCAPE HATCH							Component	ATA:52
PN:25-8FC3601-147A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7271427	HRS	0		TSN 0					
WC#: 52.015	AFL	0		TSN 0					
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00									

522501 ^U	ESCAPE HATCH WINDOW							Component	ATA:52
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6181	HRS	0		TSN 0					
	AFL	0		TSN 0					

ATA 53 - FUSELAGE

530001	DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19							Service	ATA:53
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 53.115	AFL	4577							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
530002	INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS								Service ATA:53
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 53.040	AFL	4577							
530003	DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).								Service ATA:53
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 53.110	AFL	5306							
530004	DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)								Service ATA:53
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 28.015	AFL	5306							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
530007	DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS								Service ATA:53
	MOS	10-Aug-18	96 (+3m)		10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	4113.7							
WC#: 53.105	AFL	3247							
PROC. REF: AMM 53-40-01PROC. REF: AMM 53-40-01									
530009	INSPECT/NDT FUSELAGE LAP JOINTS								Service ATA:53
	MOS	14-Sep-06							
	HRS	8.5							
WC#: 53.125	AFL	7	T:27000 (+500)		27007 (M)	27507	21384 (+500)		
PROC. REF: NTM 53-10-25PROC. REF: NTM 53-10-25									
530010	DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING								Service ATA:53
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 53.020	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
530011	INSPECT LEFT-HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)								Service ATA:53
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 53.175	AFL	4577							
530012	INSPECT RIGHT- HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)								Service ATA:53
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5							
WC#: 53.070	AFL	4577							
530013	INSPECT/NDT NO. 1 ENGINE MOUNTING PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS								Service ATA:53
	MOS	14-Sep-06							
	HRS	8.5	10000 (+500)		10008.5	10508.5	2348.3 (+500)		
WC#: 53.030	AFL	7							
PROC. REF: NTM 53-10-05PROC. REF: NTM 53-10-05									
530014	INSPECT/NDT NO. 1 REAR ENGINE MOUNT FITTINGS								Service ATA:53
	MOS	14-Sep-06							
	HRS	8.5	20000 (+500)		20008.5	20508.5	12348.3 (+500)		
WC#: 53.035	AFL	7							
PROC. REF: NTM 53-10-05PROC. REF: NTM 53-10-05									
530015	INSPECT/NDT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE								Service ATA:53
	MOS	14-Sep-06							
	HRS	8.5	30000 (+500)		30008.5	30508.5	22348.3 (+500)		
WC#: 53.015	AFL	7							
PROC. REF: NTM 55-30-20PROC. REF: NTM 55-30-20									
530016	DETAIL INSPECT NO. 1 ENGINE MOUNTING ENGINE BEAM								Service ATA:53
	MOS	14-Sep-06							
	HRS	8.5	10000 (+500)		10008.5	10508.5	2348.3 (+500)		
WC#: 53.080	AFL	7							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
530017	INSPECT NO. 1 ENGINE MOUNTING BRACKETS								Service ATA:53
	MOS/MSC	13-Nov-24	E/C					PART OF MPI	
	HRS	7229.5							
WC#: 53.200	AFL	5306							
530017	INSPECT NO. 2 ENGINE MOUNTING BRACKETS								Service ATA:53
	MOS/MSC	13-Nov-24	E/C					PART OF MPI	
	HRS	7229.5							
WC#: 53.200	AFL	5306							
530018	DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS								Service ATA:53
	MOS	23-May-23							
	HRS	6556.1	2400 (+10%)	Adj -42.4	8913.7	9153.7	1253.5 (+240)		
WC#: 53.205	AFL	4826							
530019	DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE								Service ATA:53
	MOS	25-Apr-25	12 (+1m)		30-Apr-26	25-May-26	232 d (+25)		
	HRS	7510.9							
WC#: 53.210	AFL	5509							
530021	DETAIL INSPECT APU SUPPORT STRUCTURE								Service ATA:53
	MOS	22-Jul-19							
	HRS	4614.2							
WC#: 53.010	AFL	3618							
	APH	2999	3000		5999		1477		
530022	DETAIL INSPECT APU MOUNTING HARDWARE								Service ATA:53
	MOS	23-May-23							
	HRS	6556.1							
WC#: 53.215	AFL	4826							
	APH	4514	4500		9014		4492		
PROC. REF: AMS 5-20-09PROC. REF: AMS 5-20-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
530023	DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS								Service ATA:53
	MOS	23-May-23							
	HRS	6556.1							
WC#: 53.220	AFL	4826							
	APH	4514	4500		9014		4492		
530024	FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE								Service ATA:53
	MOS	06-Mar-06							
	HRS	0							
WC#: 53.225	AFL	0							
	APH	0	22500		22500		17978		
PROC. REF: AMS 5-20-09PROC. REF: AMS 5-20-09									
530025	DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS								Service ATA:53
	MOS	29-Jun-06							
	HRS	0							
WC#: 53.170	AFL	0	10000 (+500)		10000	10500	4377 (+500)		
530027 ^S	VISUAL INSPECTION FUSELAGE SKIN								Service ATA:53
	MOS	12-Oct-22	48 (+2m/-2m)						
	HRS	6156.5							
WC#: 53.235	AFL	4577							
PKG:96									
531146	RADOME								Component ATA:53
PN:DOIW00019-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:C162214	HRS	0		TSN 0					
WC#: 53.135	AFL	0		TSN 0					
PROC. REF: AMM 53-50-14PROC. REF: AMM 53-50-14									
531152	TAIL CONE FAIRING								Component ATA:53
PN:25-8GFZ27-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06D186	HRS	0		TSN 0					
WC#: 53.140	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
PROC. REF: AMM 53-50-16PROC. REF: AMM 53-50-16									
531154	FUSELAGE								Component ATA:53
PN:25-8FA1-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:8789	HRS	0		TSN 0					
WC#: 53.145	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
532500 ^U	LH WING TO FUSELAGE FAIRING								Component ATA:53
PN:25-6FC601A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:DHB-2523	HRS	0		TSN 0					
	AFL	0		TSN 0					
532501 ^U	RH WING TO FUSELAGE FAIRING								Component ATA:53
PN:25FC5808A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:DHB/2536	HRS	0		TSN 0					
	AFL	0		TSN 0					
532502 ^U	UNDERCARRIAGE FAIRING								Component ATA:53
PN:25-8FC307-155A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:DHB-794	HRS	0		TSN 0					
	AFL	0		TSN 0					
534500 ^U	COVER								Component ATA:53
PN:25-8FR91-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1521179	HRS	0		TSN 0					
	AFL	0		TSN 0					
534501 ^U	VENTRAL FAIRING								Component ATA:53
PN:259W03059-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06D174	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
550001	DETAIL INSPECT ELEVATORS AND TABS								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 27.070	AFL	4577							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
550002	LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 55.075	AFL	4577							
PROC. REF: AMM 27-00-00, AMM 27-30-00PROC. REF: AMM 27-00-00, AMM 27-30-00									
550003	XRAY ELEVATORS								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 55.055	AFL	4577							
PROC. REF: NTM 55-20-10PROC. REF: NTM 55-20-10									
550004	DETAIL INSPECT RUDDER AND TAB								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 27.045	AFL	4577							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
550005	INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 55.065	AFL	4577							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
550006	X-RAY RUDDER (IN-SITU)								Service ATA:55
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 27.045	AFL	4577							
PROC. REF: NTM 55-40-05PROC. REF: NTM 55-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
550007	DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS								Service ATA:55
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5							
WC#: 27.045	AFL	4577							
550008 ^S	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING								Service ATA:55
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 55.010	AFL	5138							PKG:62,95
550009	DETAIL INSPECT HORIZONTAL STABILIZER								Service ATA:55
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5							
WC#: 55.040	AFL	4577							
550010	INSPECT/NDT VERTICAL STABILIZER								Service ATA:55
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 55.050	AFL	5306							
PROC. REF: NTM 55-30-05, NTM 55-30-10, NTM 55-30-15PROC. REF: NTM 55-30-05, NTM 55-30-10, NTM 55-30-15									
550011	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS								Service ATA:55
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5							
WC#: 55.025	AFL	4577							
550012	INSPECT/NDT HORIZONTAL STABILIZER								Service ATA:55
	MOS	14-Sep-06	T:288 (+3m)		14-Sep-30	14-Dec-30	1830 d (+91)		
	HRS	8.5							
WC#: 55.045	AFL	7							
PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
550013	X-RAY HORIZONTAL STABILIZER								Service ATA:55
	MOS	13-Nov-24	96 (+3m)		13-Nov-32	13-Feb-33	2621 d (+92)		
	HRS	7229.5							
WC#: 55.035	AFL	5306							
PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15, NTM 55-10-20PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15, NTM 55-10-20									
550014	DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER								Service ATA:55
	MOS	14-Sep-06							
	HRS	8.5							
WC#: 55.060	AFL	0	T:15000 (+500)		15000	15500	9377 (+500)		
550015	INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS								Service ATA:55
	MOS	24-May-24	24 (+2m)		24-May-26	24-Jul-26	256 d (+61)		
	HRS	7061.1							
WC#: 55.070	AFL	5182							
PROC. REF: AMM 27-30-91PROC. REF: AMM 27-30-91									
551004	UPPER VERTICAL STABILIZER								Component ATA:55
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 55.015	AFL	0		TSN 0					
PROC. REF: AMM 55-32-00PROC. REF: AMM 55-32-00									
551006	TAILPLANE								Component ATA:55
PN:25-8TP509-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:FL-DHB-8791	HRS	0		TSN 0					
WC#: 55.020	AFL	0		TSN 0					
PROC. REF: AMM 55-13-00PROC. REF: AMM 55-13-00									
551010	BULLET FAIRING								Component ATA:55
PN:25-8NF4033-6109	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:RG-8789	HRS	0		TSN 0					
WC#: 55.030	AFL	0		TSN 0					
PROC. REF: AMM 53-50-18PROC. REF: AMM 53-50-18									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 55 - STABILIZERS										
551599 ^U		HORIZONTAL STABALIZER LEADING EDGE, LH							Component	ATA:55
PN:25-8TP259-1A		MOS/MSC	30-Aug-06	O/C	TSN 0					
SN:FL-DHB-8783		HRS			TSN 0					
		AFL			TSN 0					
553005		FIN LEADING EDGE							Component	ATA:55
PN:25-8TF133-3A		MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06B001		HRS	0		TSN 0					
		AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
ATA 56 - WINDOWS										
560004 ^S		INSPECT WINDOWS DRY-AIR SYSTEM FILTER ELEMENT (IF FITTED)							Service	ATA:56
		MOS	08-Dec-23							
		HRS	6763.7	1600 (+50/-50)						
WC#: 56.065		AFL	4989							
								PKG:24,92		
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2										
560005 ^S		CHECK PASSENGER CABIN WINDOWS							Service	ATA:56
		MOS	04-Jun-25							
		HRS	7579.6	800 (+40/-10)						
WC#: 56.090		AFL	5563							
								PKG:9,91		
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2										
560006 ^S		INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER							Service	ATA:56
		MOS	04-Jun-25							
		HRS	7579.6	800 (+40/-10)						
WC#: 56.070		AFL	5563							
								PKG:10,91		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
560007 ^S		SCREEN HEAT CIRCUIT BREAKERS - DO A VISUAL INSPECTION FOR HEAT DISTRESS, DISCOLORATION AND DEFORMATION						Service	ATA:56
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
	AFL	5138							
									PKG:60,95
561001		LEFT (PANEL A) HEATED WINDSCREEN						Component	ATA:56
PN:NF24016-415	MOS/MSC	10-Feb-25	O/C	TSN 0					
SN:10327	HRS	7390.2		TSN 0					
WC#: 56.010	AFL	5420							
PROC. REF: AMM 56-10-11PROC. REF: AMM 56-10-11									
561002		RIGHT (PANEL A) HEATED WINDSCREEN						Component	ATA:56
PN:NF24016-416	MOS/MSC	25-Feb-25	O/C	TSN 0					
SN:L604560	HRS	7403.7		TSN 0					
WC#: 56.010	AFL	5430							
PROC. REF: AMM 56-10-11PROC. REF: AMM 56-10-11									
561003		LEFT DIRECT VIEW B WINDOW						Component	ATA:56
PN:LANH24016-091	MOS/MSC	23-Apr-22	O/C	TSN 3					
SN:10012	HRS	5938		TSN 0					
WC#: 56.015	AFL	4436		TSN 0					
PROC. REF: AMM 56-10-22PROC. REF: AMM 56-10-22									
561004		RIGHT DIRECT VIEW B WINDOW						Component	ATA:56
PN:LANH24016-092	MOS/MSC	28-Jul-21	O/C	TSN 0					
SN:10009	HRS	5375.2		TSN 0					
WC#: 56.015	AFL	4075		TSN 0					
PROC. REF: AMM 56-10-22PROC. REF: AMM 56-10-22									
561005		LEFT C WINDOW						Component	ATA:56
PN:259W03925-1A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:CW0293	HRS	0		TSN 0					
WC#: 56.020	AFL	0		TSN 0					
PROC. REF: AMM 56-10-31PROC. REF: AMM 56-10-31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
561006	RIGHT C WINDOW								Component ATA:56
PN:259W03925-2A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:CW0352	HRS	0		TSN 0					
WC#: 56.020	AFL	0		TSN 0					
PROC. REF: AMM 56-10-31PROC. REF: AMM 56-10-31									
562001	NO. 1 LEFT CABIN WINDOW								Component ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6240	HRS	0		TSN 0					
WC#: 56.025	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562002	NO. 1 RIGHT CABIN WINDOW								Component ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6233	HRS	0		TSN 0					
WC#: 56.025	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562003	NO. 2 LEFT CABIN WINDOW								Component ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6098	HRS	0		TSN 0					
WC#: 56.030	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562004	NO. 2 RIGHT CABIN WINDOW								Component ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6321	HRS	0		TSN 0					
WC#: 56.030	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562005	NO. 3 LEFT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6126	HRS	0		TSN 0					
WC#: 56.035	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562006	NO. 3 RIGHT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6318	HRS	0		TSN 0					
WC#: 56.035	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562007	NO. 4 LEFT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6207	HRS	0		TSN 0					
WC#: 56.040	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562008	NO. 4 RIGHT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6265	HRS	0		TSN 0					
WC#: 56.040	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									
562009	NO. 5 LEFT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6123	HRS	0		TSN 0					
WC#: 56.045	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 56 - WINDOWS

562010	NO. 5 RIGHT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6194	HRS	0		TSN 0					
WC#: 56.045	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									

562011	NO. 6 LEFT CABIN WINDOW							Component	ATA:56
PN:25FC7881-41AENG	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:PPA6227	HRS	0		TSN 0					
WC#: 56.050	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									

562012	NO. 6 RIGHT CABIN WINDOW							Component	ATA:56
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 56.050	AFL	0		TSN 0					
PROC. REF: AMM 56-20-11PROC. REF: AMM 56-20-11									

56A002 ^U	VISUAL INSPECTION OF THE RIGHT DIRECT VIEW B WINDOW IAW LAI-ICA-118							Service	ATA:56
	MOS	04-Jun-25							
	HRS	7579.6	400 (+50/-50)		7979.6	8029.6	319.4 (+50)		
	AFL	5563							

56A004 ^U	RIGHT WINDOW PANEL B HEATER FUNCTIONAL TEST							Service	ATA:56
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+100/-100)		8363.7	8463.7	703.5 (+100)		
	AFL	4989							

ATA 57 - WINGS

570001 ^S	INSPECT LEFT FLAP HINGE FITTINGS							Service	ATA:57
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 57.095	AFL	5563							

PKG:15,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570002	^S	INSPECT RIGHT FLAP HINGE FITTINGS							Service ATA:57
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 57.095	AFL	5563							PKG:16,91
570003	^S	DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service ATA:57
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 57.090	AFL	5138							PKG:63,95
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
570005	^S	DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service ATA:57
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 57.090	AFL	5138							PKG:64,95
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
570006	^S	INSPECT RIGHT FLAP SKIN PROTECTION PANELS (IF FITTED)							Service ATA:57
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
WC#: 57.140	AFL	5138							PKG:64,95
570007		X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4							Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 57.040	AFL	4577							
PROC. REF: NTM 57-30-05PROC. REF: NTM 57-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570008	DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 57.035	AFL	4577							
570009	DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8								Service ATA:57
	MOS	23-May-23							
	HRS	6556.1	1200 (+10%)	Adj -42.4	7713.7	7833.7	53.5 (+120)		
WC#: 57.070	AFL	4826							
570010	DETAIL INSPECT WING FRONT SPAR, FORWARD FACE								Service ATA:57
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5	4800 (+10%)		10956.5	11436.5	3296.3 (+480)		
WC#: 57.020	AFL	4577							
PROC. REF: MMS 57-00-00, MMS 57-00-00PROC. REF: MMS 57-00-00, MMS 57-00-00									
570011	INSPECT WING REAR SPAR, REAR FACE								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 57.030	AFL	4577							
570012	DETAIL INSPECT LEFT LOWER AIRBRAKE								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 27.240	AFL	4577							
570012	DETAIL INSPECT LEFT UPPER AIRBRAKE								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 27.240	AFL	4577							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570012	DETAIL INSPECT RIGHT LOWER AIRBRAKE								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 27.245	AFL	4577							
570012	DETAIL INSPECT RIGHT UPPER AIRBRAKE								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 27.245	AFL	4577							
570013	DETAIL INSPECT AILERONS								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 27.020	AFL	4577							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
570014	LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 57.145	AFL	4577							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
570015	INSPECT/X RAY AILERONS								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 57.100	AFL	4577							
PROC. REF: NTM 57-50-25PROC. REF: NTM 57-50-25									
570016	INSPECT/X RAY FLAPS AND FLAP VANES								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5	2400 (+10%)		8556.5	8796.5	896.3 (+240)		
WC#: 57.130	AFL	4577							
PROC. REF: NTM 57-50-15, NTM 57-50-20PROC. REF: NTM 57-50-15, NTM 57-50-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570017	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7								Service ATA:57
	MOS	14-Sep-06							
	HRS	8.5	T:24000 (+500)	Adj 8.5	24017	24517	16356.8 (+500)		
WC#: 57.055	AFL	7							
PROC. REF: MMS 57-00-00PROC. REF: MMS 57-00-00									
570018	DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP								Service ATA:57
	MOS	14-Sep-06							
	HRS	8.5	T:24000 (+500)		24008.5 (M)	24508.5	16348.3 (+500)		
WC#: 57.080	AFL	7							
PROC. REF: MMS 57-00-00PROC. REF: MMS 57-00-00									
570019	INSPECT/NDT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0								Service ATA:57
	MOS	14-Sep-06							
	HRS	8.5	T:24000 (+500)		24008.5 (M)	24508.5	16348.3 (+500)		
WC#: 57.060	AFL	7							
PROC. REF: NTM 57-30-15, MMS 57-00-00PROC. REF: NTM 57-30-15, MMS 57-00-00									
570020	INSPECT/NDT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)								Service ATA:57
	MOS	14-Sep-06							
	HRS	8.5	T:24000 (+500)		24008.5 (M)	24508.5	16348.3 (+500)		
WC#: 57.075	AFL	7							
PROC. REF: NTM 57-00-10PROC. REF: NTM 57-00-10									
570021	DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS.								Service ATA:57
	MOS/MSC	29-Jun-06	A/R						
	HRS	0							
WC#: 57.010	AFL	0							
570022	DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH								Service ATA:57
	MOS	10-Aug-18							
	HRS	4113.7	4800 (+10%)		8913.7	9393.7	1253.5 (+480)		
WC#: 57.050	AFL	3247							
PROC. REF: MMS 57-00-00PROC. REF: MMS 57-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570023	INSPECT/NDT AILERON HORN BALANCE WEIGHT								Service ATA:57
	MOS/MSC	22-May-14	N/R						
	HRS	2168.7							
WC#: 57.135	AFL	1712							
PROC. REF: NTM 57-50-25, MMS 57-00-00PROC. REF: NTM 57-50-25, MMS 57-00-00									
570024	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH								Service ATA:57
	MOS	14-Sep-06							
	HRS	8.5	T:12000 (+500)		12008.5 (M)	12508.5	4348.3 (+500)		
WC#: 57.065	AFL	7							
PROC. REF: MMS 57-00-00PROC. REF: MMS 57-00-00									
570025	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH								Service ATA:57
	MOS	10-Aug-18							
	HRS	4113.7	4800 (+10%)		8913.7	9393.7	1253.5 (+480)		
WC#: 57.050	AFL	3247							
PROC. REF: MMS 57-00-00PROC. REF: MMS 57-00-00									
570026	INSPECT WING LEADING EDGES								Service ATA:57
	MOS	12-Oct-22	48 (+3m)	Adj -63d	10-Aug-26	10-Nov-26	334 d (+92)		
	HRS	6156.5							
WC#: 57.025	AFL	4577							
570027	DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP								Service ATA:57
	MOS	12-Oct-22	96 (+3m)	Adj -143d	22-May-30	22-Aug-30	1715 d (+92)		
	HRS	6156.5	4800 (+10%)		10956.5	11436.5	3296.3 (+480)		
WC#: 57.045	AFL	4577							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
570028	INSPECT AILERON AT OUTBOARD HINGE CASTING								Service ATA:57
	MOS/MSC	22-May-14	N/R						
	HRS	2168.7							
WC#: 57.125	AFL	1712							
PROC. REF: AMM 27-10-31PROC. REF: AMM 27-10-31									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
570029	VISUALLY INSPECT WING OUTER, UPPER AND LOWER SKINS								Service ATA:57
	MOS	20-May-25							
	HRS	7564.5	300 (+10%)	Adj -35	7829.5	7859.5	169.3 (+30)		
WC#: 57.155	AFL	5551							
570030 ^S	INSPECT LEFT WING RIB 16 AND SPAR FITTING WHERE THE WINGLET IS ATTACHED TO THE WING								Service ATA:57
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
	AFL	5138							
									PKG:63,95
570031 ^S	INSPECT RIGHT WING RIB 16 AND SPAR FITTING WHERE THE WINGLET IS ATTACHED TO THE WING								Service ATA:57
	MOS	23-Apr-24	24 (+2m/-2m)						
	HRS	7002.4							
	AFL	5138							
									PKG:64,95
571010	WING								Component ATA:57
PN:25-8WS1-5A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:8789	HRS	0		TSN 0					
WC#: 57.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
571109	REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS								Service ATA:57
	MOS	29-Jun-06						LIFE LIMIT	
	HRS	0							
WC#: 57.150	AFL	0	14600		14600		8977		
571110	REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS								Service ATA:57
	MOS	29-Jun-06						LIFE LIMIT	
	HRS	0							
WC#: 57.150	AFL	0	14600		14600		8977		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574001	LEFT LEADING EDGE ASSEMBLY							Component	ATA:57
PN:25-8WS3299-3A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06C064	HRS	0		TSN 0					
WC#: 57.085	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
574002	RIGHT LEADING EDGE ASSEMBLY							Component	ATA:57
PN:25-8WS3299-4A	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:AST06D022	HRS	0		TSN 0					
WC#: 57.085	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 71 - POWER PLANT									
710049	COMPRESSOR WASH NO. 1 ENGINE							Service	ATA:71
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 71.025	AFL	0							
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
710050	COMPRESSOR WASH NO. 2 ENGINE							Service	ATA:71
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 71.025	AFL	0							
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM									
710081	NO. 1 ENGINE INLET COWL							Component	ATA:71
PN:C46B11000-21	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:B-635	HRS	0		TSN 0					
WC#: 71.055	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
710082	NO. 2 ENGINE INLET COWL							Component	ATA:71
PN:C46B11000-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:B-635	HRS	0		TSN 0					
WC#: 71.055	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
710083	NO. 1 ENGINE UPPER FAN COWL DOOR							Component	ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.060	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
710084	NO. 2 ENGINE UPPER FAN COWL DOOR							Component	ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.060	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
710089	NO. 1 ENGINE LOWER FAN COWL DOOR							Component	ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.070	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
710090	NO. 2 ENGINE LOWER FAN COWL DOOR							Component	ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.070	AFL	0		TSN 0					
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00									
710512 ^U	LH ENGINE MOUNTING							Component	ATA:71
PN:C46BM10100-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1592	HRS	0		TSN 0					
	AFL	0		TSN 0					
710513 ^U	RH ENGINE MOUNTING							Component	ATA:71
PN:C46BM10100-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1497	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712001	NO. 1 ENGINE MOUNTING								Component ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.075	AFL	0		TSN 0					
712002	NO. 2 ENGINE MOUNTING								Component ATA:71
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.080	AFL	0		TSN 0					
713500 ^U	LH FIREWIRE ENGINE								Component ATA:71
PN:3001-112-900-400-*	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:88108	HRS	0		TSN 0					
	AFL	0		TSN 0					
713501 ^U	RH FIREWIRE ENGINE								Component ATA:71
PN:3001-112-900-400-*	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:87787	HRS	0		TSN 0					
	AFL	0		TSN 0					
713502 ^U	LH FIREWIRE ELEMENT (JET PIPE)								Component ATA:71
PN:3001-133-900-500-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:88275	HRS	0		TSN 0					
	AFL	0		TSN 0					
713503 ^U	RH FIREWIRE ELEMENT (JET PIPE)								Component ATA:71
PN:3001-133-900-500-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:88255	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
714010 ^S		NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						Service	ATA:71
	MOS	29-Oct-24							
	HRS	7145.2	800						
WC#: 71.030	ENC	5244							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
714010 ^S		NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						Service	ATA:71
	MOS	31-Oct-24							
	HRS	7145.2	800						
WC#: 71.030	ENC	5244							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
715010 ^S		NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						Service	ATA:71
	MOS	29-Oct-24							
	HRS	7145.2	800						
WC#: 71.040	ENC	5244							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
715010 ^S		NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						Service	ATA:71
	MOS	31-Oct-24							
	HRS	7145.2	800						
WC#: 71.040	ENC	5244							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:4
71EN1		NO. 1 ENGINE						Component	ATA:71
PN:3075160-4	MOS/MSC	18-Nov-19	E/C						
SN:P-129230	HRS	4729.8		TSN 4649.2					
WC#: 71.EN1	AFL	3709							
PROC. REF: AMM 71-00-01, SIL F731-88PROC. REF: AMM 71-00-01, SIL F731-88									
71EN2		NO. 2 ENGINE						Component	ATA:71
PN:3075160-4	MOS/MSC	18-Nov-19	E/C						
SN:P-129231	HRS	4729.8		TSN 4649.2					
WC#: 71.EN2	AFL	3709							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 71 - POWER PLANT

PROC. REF: AMM 71-00-01, SIL F731-88PROC. REF: AMM 71-00-01, SIL F731-88

71U998 ^U	NO. 1 ENGINE - #1 CARBON SEAL							Component	ATA:71
PN:3060457-1	MOS/MSC	29-Oct-24	O/C	TSN 0					
SN:24-152826-52367	HRS	7145.2		TSN 0					
	ENC	5244		TSN 0					

71U998 ^U	NO. 2 ENGINE - #1 CARBON SEAL							Component	ATA:71
PN:3060457-1	MOS/MSC	31-Oct-24	O/C	TSN 0					
SN:24-152826-52378	HRS	7145.2		TSN 0					
	ENC	5244		TSN 0					

ATA 72 - ENGINE

720002	INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service	ATA:72
	MOS	13-Nov-24						PART OF MPI	
	HRS	7229.5	2500 (+10%)	9729.5	9979.5	2069.3 (+250)			
WC#: 72.030	AFL	5306							

720002	INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service	ATA:72
	MOS	13-Nov-24						PART OF MPI	
	HRS	7229.5	2500 (+10%)	9729.5	9979.5	2069.3 (+250)			
WC#: 72.030	AFL	5306							

720003	DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service	ATA:72
	MOS	13-Nov-24						PART OF MPI	
	HRS	7229.5	2500 (+10%)	9729.5	9979.5	2069.3 (+250)			
WC#: 72.040	AFL	5306							

720003	DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service	ATA:72
	MOS	13-Nov-24						PART OF MPI	
	HRS	7229.5	2500 (+10%)	9729.5	9979.5	2069.3 (+250)			
WC#: 72.040	AFL	5306							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								Service ATA:72
	MOS	29-Oct-24							
	HRS	7145.2	2500 (+100)		(9645.2) 9725.8	9745.2	2065.6 (+100)		
WC#: 71.010	ENC	5244							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
720120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								Service ATA:72
	MOS	31-Oct-24							
	HRS	7145.2	2500 (+100)		(9645.2) 9725.8 (M)	9745.2	2065.6 (+100)		
WC#: 71.010	ENC	5244							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
720130 ^S	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								Service ATA:72
	MOS	29-Oct-24							
	HRS	7145.2	800						
WC#: 71.020	ENC	5244							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:4
720130 ^S	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								Service ATA:72
	MOS	31-Oct-24							
	HRS	7145.2	800						
WC#: 71.020	ENC	5244							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:4
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Jun-06	O/C						
	HRS	0							
WC#: 72.001	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								Service ATA:72
	MOS	05-Nov-19							
	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.010	ENC	3648							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								Service ATA:72
	MOS	11-Oct-19							
	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.010	ENC	3648							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE								Component ATA:72
PN:3072443-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.020	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE								Component ATA:72
PN:3072443-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.020	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE								Service ATA:72
PN:3072443-5	MOS	29-Oct-24							
SN:UNKNOWN	HRS	7145.2	2500 (+100)		(9645.2) 9725.8	9745.2	2065.6 (+100)		
WC#: 72.030	ENC	5244							
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04									
724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE								Service ATA:72
PN:3072443-5	MOS	31-Oct-24							
SN:UNKNOWN	HRS	7145.2	2500 (+100)		(9645.2) 9725.8	9745.2	2065.6 (+100)		
WC#: 72.030	ENC	5244							
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:70080021-2	MOS	06-Jan-14		TSN 1				LIFE LIMIT	
SN:12-156103-00651	HRS	2066.6		TSN 0					
WC#: 72.040	ENC	1645	10000	TSN 0	(11645) 11705		6082		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:70080021-2	MOS	06-Jan-14		TSN 1				LIFE LIMIT	
SN:12-156103-00671	HRS	2066.6		TSN 0					
WC#: 72.040	ENC	1645	10000	TSN 0	(11645) 11704		6081		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075426-3	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050322903706	HRS	0		TSN 0					
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 10060		4437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075426-3	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050322903290	HRS	0		TSN 0					
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 10059		4436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075574-3	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050322906030	HRS	0		TSN 0					
WC#: 72.060	ENC	0	12000	TSN 0	(12000) 12060		6437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075574-3	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050322906018	HRS	0		TSN 0					
WC#: 72.060	ENC	0	12000	TSN 0	(12000) 12059		6436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075772-1	MOS	29-Oct-24						LIFE LIMIT	
SN:071217200830	HRS	7145.2							
WC#: 72.070	ENC	5244	10000	TSN 4841	(10403) 10463		4840		
PROC. REF: LMM 72-50-06PROC. REF: LMM 72-50-06									
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC (LIFE LIMIT)								Component ATA:72
PN:3075772-1	MOS	06-Jan-14		TSN 1				LIFE LIMIT	
SN:061217200359	HRS	2066.6		TSN 0					
WC#: 72.070	ENC	1645	10000	TSN 0	(11645) 11704		6081		
PROC. REF: LMM 72-50-06PROC. REF: LMM 72-50-06									
725050	NO. 1 ENGINE - FAN DISC (LIFE LIMIT)								Component ATA:72
PN:3074622-9	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:061365101773	HRS	0		TSN 0					
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 10060		4437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725050	NO. 2 ENGINE - FAN DISC (LIFE LIMIT)								Component ATA:72
PN:3074622-9	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:061365101772	HRS	0		TSN 0					
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 10059		4436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component	ATA:72
PN:3070440-11	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316004005	HRS	0		TSN 0					
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 10060		4437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component	ATA:72
PN:3070440-11	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316004006	HRS	0		TSN 0					
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 10059		4436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component	ATA:72
PN:3075839-1	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316002856	HRS	0		TSN 0					
WC#: 72.100	ENC	0	20000	TSN 0	(20000) 20060		14437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component	ATA:72
PN:3075839-1	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316002864	HRS	0		TSN 0					
WC#: 72.100	ENC	0	20000	TSN 0	(20000) 20059		14436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component	ATA:72
PN:3072417-7	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316003273	HRS	0		TSN 0					
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10060		4437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)								Component ATA:72
PN:3072417-7	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316003286	HRS	0		TSN 0					
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10059		4436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)								Component ATA:72
PN:3075351-5	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050350110574	HRS	0		TSN 0					
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 20060		14437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)								Component ATA:72
PN:3075351-5	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050350107842	HRS	0		TSN 0					
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 20059		14436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:3074744-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:06P04643	HRS	0		TSN 0					
WC#: 72.130	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10									
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:3074744-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:06P01240	HRS	0		TSN 0					
WC#: 72.130	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER (LIFE LIMIT)								Component ATA:72
PN:3073398-2	MOS	29-Oct-24						LIFE LIMIT	
SN:4-23315-803	HRS	7145.2							
WC#: 72.140	ENC	5244	10000	TSN 5983	(9261) 9321		3698		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER (LIFE LIMIT)								Component ATA:72
PN:3075765-1	MOS	06-Jan-14						LIFE LIMIT	
SN:020322902561	HRS	2066.6		TSN 4237					
WC#: 72.140	ENC	1645	10000	TSN 2927	(8718) 8777		3154		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT (LIFE LIMIT)								Component ATA:72
PN:3072545-1	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:06P15356	HRS	0		TSN 0					
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 12060		6437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT (LIFE LIMIT)								Component ATA:72
PN:3072545-1	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:06P15355	HRS	0		TSN 0					
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 12059		6436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE (LIFE LIMIT)								Component ATA:72
PN:3075579-1	MOS	29-Oct-24						LIFE LIMIT	
SN:05316003554	HRS	7145.2							
WC#: 72.160	ENC	5244	30000	TSN 5244	(30000) 30060		24437		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE (LIFE LIMIT)								Component ATA:72
PN:3075579-1	MOS	29-Jun-06		TSN 0				LIFE LIMIT	
SN:050316003553	HRS	0		TSN 0					
WC#: 72.160	ENC	0	30000	TSN 0	(30000) 30059		24436		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725150	NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3074641-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:06P15155	HRS	0		TSN 0					
WC#: 72.170	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725150	NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3074641-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:06P15156	HRS	0		TSN 0					
WC#: 72.170	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3074766-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.180	ENC	0		TSN 0					
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05									
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3075292-4	MOS/MSC	06-Jan-14	O/C	TSO 1					
SN:5P3495	HRS	2066.6		TSO 0					
WC#: 72.180	ENC	1645		TSO 0					
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05									
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								Component ATA:72
PN:3075271-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.190	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component	ATA:72
PN:3075271-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.190	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component	ATA:72
PN:3073765-9	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.200	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component	ATA:72
PN:3073765-9	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.200	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component	ATA:72
PN:3074052-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.210	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component	ATA:72
PN:3074052-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.210	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725230	NO. 1 ENGINE - FAN SPINNER							Component	ATA:72
PN:3074623-3	MOS/MSC	29-Oct-24	O/C						
SN:4-13262-459	HRS	7145.2							
WC#: 72.220	ENC	5244							
PROC. REF: GENERIC NO REF, LMM 72-70-01PROC. REF: GENERIC NO REF, LMM 72-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230	NO. 2 ENGINE - FAN SPINNER								Component ATA:72
PN:3074623-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:062784300017	HRS	0		TSN 0					
WC#: 72.220	ENC	0		TSN 0					
PROC. REF: GENERIC NO REF, LMM 72-70-01PROC. REF: GENERIC NO REF, LMM 72-70-01									
726110	NO. 1 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3070003-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.230	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
726110	NO. 2 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3070003-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.230	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX								Service ATA:72
PN:3070003-15	MOS	05-Nov-19							
SN:UNKNOWN	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.240	ENC	3648							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX								Service ATA:72
PN:3070003-15	MOS	11-Oct-19							
SN:UNKNOWN	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.240	ENC	3648							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
726130	NO. 1 ENGINE - TRANSFER GEARBOX								Component ATA:72
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.250	ENC	0		TSN 0					
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726130	NO. 2 ENGINE - TRANSFER GEARBOX							Component	ATA:72
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.250	ENC	0		TSN 0					
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01									
726140	NO. 1 ENGINE - INSPECT TRANSFER GEARBOX							Service	ATA:72
PN:PN	MOS/MSC	29-Jun-06	O/C						
SN:UNKNOWN	HRS	0							
WC#: 72.280	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726140	NO. 2 ENGINE - INSPECT TRANSFER GEARBOX							Service	ATA:72
PN:PN	MOS/MSC	29-Jun-06	O/C						
SN:UNKNOWN	HRS	0							
WC#: 72.280	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726500 ^U	NO. 1 ENGINE - #1 SEAL ROTOR							Component	ATA:72
PN:3071980-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
726500 ^U	NO. 2 ENGINE - #1 SEAL ROTOR							Component	ATA:72
PN:3071980-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
726505 ^U	NO. 1 ENGINE - #3 SEAL ROTOR							Component	ATA:72
PN:3075516-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726505 ^U	NO. 2 ENGINE - #3 SEAL ROTOR								Component ATA:72
PN:3075516-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY								Service ATA:72
	MOS	05-Nov-19							
	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.270	ENC	3648							
PROC. REF: LMM 72-70-06PROC. REF: LMM 72-70-06									
727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY								Service ATA:72
	MOS	11-Oct-19							
	HRS	4649.2	5000 (+200)		(9649.2) 9729.8	9849.2	2069.6 (+200)		
WC#: 72.270	ENC	3648							
PROC. REF: LMM 72-70-06PROC. REF: LMM 72-70-06									
72U652 ^U	NO. 1 ENGINE - PINION GEAR								Component ATA:72
PN:3075398-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
72U652 ^U	NO. 2 ENGINE - PINION GEAR								Component ATA:72
PN:3075398-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
72U657 ^U	NO. 1 ENGINE - COMBUSTOR								Component ATA:72
PN:3072963-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72U657 ^U	NO. 2 ENGINE - COMBUSTOR							Component	ATA:72
PN:3075583-2	MOS/MSC	31-Oct-24	O/C						
SN:06P18391	HRS								
	ENC								
ATA 73 - ENGINE FUEL AND CONTROL									
73-10-01.1	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY							Component	ATA:73
PN:3075368-2	MOS/MSC	29-Oct-24	A/R	TSO 0					
SN:93-583	HRS	7145.2		TSO 0					
	ENC	5244		TSO 0					
PROC. REF: LMM 73-10-01PROC. REF: LMM 73-10-01									
73-10-01.1	NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY							Component	ATA:73
PN:3075368-2	MOS/MSC	31-Oct-24	A/R	TSO 0					
SN:MS042923400004	HRS	7145.2		TSO 0					
	ENC	5244		TSO 0					
PROC. REF: LMM 73-10-01PROC. REF: LMM 73-10-01									
730001 ^S	DRAIN PT2 PIPELINES TO FUEL COMPUTERS							Service	ATA:73
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 73.050	AFL	5563							
PKG:13,91									
731110	NO. 1 ENGINE - FUEL PUMP							Component	ATA:73
PN:3060710-23	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1224	HRS	0		TSN 0					
WC#: 73.010	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-21-02PROC. REF: LMM 73-20-01, LMM 73-21-02									
731110	NO. 2 ENGINE - FUEL PUMP							Component	ATA:73
PN:3060710-23	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1223	HRS	0		TSN 0					
WC#: 73.010	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-21-02PROC. REF: LMM 73-20-01, LMM 73-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731110-1 ^U	NO. 1 ENGINE - FUEL PUMP								Component ATA:73
PN:3070850-57	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
731110-1 ^U	NO. 2 ENGINE - FUEL PUMP								Component ATA:73
PN:3070850-57	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
731120	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:73
	MOS	04-Jun-25							
	HRS	7499	650		(8149) 8229.6		569.4		
WC#: 73.010	ENC	5503							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									PKG:2
731120	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:73
	MOS	04-Jun-25							
	HRS	7499	650		(8149) 8229.6		569.4		
WC#: 73.010	ENC	5504							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									PKG:2
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:394396-2-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.030	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:394396-2-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.030	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 73 - ENGINE FUEL AND CONTROL

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

731140	NO. 1 ENGINE - FUEL HEATER							Component	ATA:73
PN:158670-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.040	ENC	0		TSN 0					
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04									

731140	NO. 2 ENGINE - FUEL HEATER							Component	ATA:73
PN:158670-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.040	ENC	0		TSN 0					
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04									

731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.060	ENC	0		TSN 0					
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04									

731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.060	ENC	0		TSN 0					
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04									

732025	NO. 1 ENGINE LOW FUEL PRESSURE SWITCH							Component	ATA:73
PN:HTE690014-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:9061010	HRS	0		TSN 0					
WC#: 73.020	AFL	0		TSN 0					
PROC. REF: AMM 73-32-11PROC. REF: AMM 73-32-11									

732026	NO. 2 ENGINE LOW FUEL PRESSURE SWITCH							Component	ATA:73
PN:HTE690014-2	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:9061019	HRS	0		TSN 0					
WC#: 73.020	AFL	0		TSN 0					
PROC. REF: AMM 73-32-11PROC. REF: AMM 73-32-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732037	NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH								Component ATA:73
PN:HE60010	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1766TW	HRS	0		TSN 0					
WC#: 73.025	AFL	0		TSN 0					
PROC. REF: AMM 73-33-11PROC. REF: AMM 73-33-11									
732038	NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH								Component ATA:73
PN:HE60010	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:1770TW	HRS	0		TSN 0					
WC#: 73.025	AFL	0		TSN 0					
PROC. REF: AMM 73-33-11PROC. REF: AMM 73-33-11									
732109	ENGINE FUEL SYNCHRONIZER								Component ATA:73
PN:2118756-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:46-C0594	HRS	0		TSN 0					
WC#: 73.035	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732110	NO. 1 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-35	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:18306	HRS	0		TSN 0					
WC#: 73.070	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01									
732110	NO. 2 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-22	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.070	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01									
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE								Component ATA:73
PN:3070685-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.080	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE							Component	ATA:73
PN:3070685-6	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.080	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732160	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.090	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732160	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.090	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732501 ^U	NO. 1 ENGINE - A.P.R. CONTROL UNIT							Component	ATA:73
PN:2101822-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732501 ^U	NO. 2 ENGINE - A.P.R. CONTROL UNIT							Component	ATA:73
PN:2101822-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732502 ^U	NO. 1 ENGINE - ENGINE SYNCHRONIZER							Component	ATA:73
PN:2118114-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732502 ^U	NO. 2 ENGINE - ENGINE SYNCHRONIZER							Component	ATA:73
PN:2118114-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732505 ^U	NO. 1 ENGINE - FUEL FILTER TEMPERATURE SWITCH							Component	ATA:73
PN:HTE60010	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732505 ^U	NO. 2 ENGINE - FUEL FILTER TEMPERATURE SWITCH							Component	ATA:73
PN:HTE60010	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732508 ^U	NO. 1 ENGINE - FUEL LOW PRESSURE SWITCH							Component	ATA:73
PN:HE12358-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
732508 ^U	NO. 2 ENGINE - FUEL LOW PRESSURE SWITCH							Component	ATA:73
PN:HE12358-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
733001	NO. 1 ENGINE FUEL FLOW TRANSMITTER							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.040	AFL	0		TSN 0					
PROC. REF: AMM 73-31-11PROC. REF: AMM 73-31-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
733002	NO. 2 ENGINE FUEL FLOW TRANSMITTER							Component	ATA:73
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 73.040	AFL	0		TSN 0					
PROC. REF: AMM 73-31-11PROC. REF: AMM 73-31-11									
733013	NO. 1 ENGINE FUEL FLOW INDICATOR							Component	ATA:73
PN:9-127-55	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:J10077	HRS	0		TSN 0					
WC#: 73.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
733014	NO. 2 ENGINE FUEL FLOW INDICATOR							Component	ATA:73
PN:9-127-55	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:J10079	HRS	0		TSN 0					
WC#: 73.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 74 - IGNITION									
741110	NO. 1 ENGINE - IGNITION UNIT							Component	ATA:74
PN:3073776-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:50218061950	HRS	0		TSN 0					
WC#: 74.010	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
741110	NO. 2 ENGINE - IGNITION UNIT							Component	ATA:74
PN:3073776-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:50218063837	HRS	0		TSN 0					
WC#: 74.010	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
741120 ^S	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service	ATA:74
	MOS	29-Oct-24							
	HRS	7145.2	1200 (+200)						
WC#: 74.010	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
PKG:0									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
741120 ^S	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM								Service ATA:74
	MOS	31-Oct-24							
	HRS	7145.2	1200 (+200)						
WC#: 74.010	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	03-Dec-21	O/C	TSN 39					
SN:NSN	HRS	5531.6		TSN 0					
WC#: 74.030	ENC	4179		TSN 0					
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	31-Oct-24	O/C						
SN:UNKNOWN	HRS	7145.2							
WC#: 74.030	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742120 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE								Service ATA:74
	MOS	29-Oct-24							
	HRS	7145.2	1600						
WC#: 74.030	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742120 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE								Service ATA:74
	MOS	31-Oct-24							
	HRS	7145.2	1600						
WC#: 74.030	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	05-Nov-19	O/C	TSN 0					
SN:NSN	HRS	4649.2		TSN 0					
WC#: 74.050	ENC	3648		TSN 0					
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 74 - IGNITION

742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	31-Oct-24	O/C						
SN:UNKNOWN	HRS	7145.2							
WC#: 74.050	ENC	5244							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

742140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	29-Oct-24							
	HRS	7145.2	1600						
WC#: 74.050	ENC	5244							
									PKG:5
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

742140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	31-Oct-24							
	HRS	7145.2	1600						
WC#: 74.050	ENC	5244							
									PKG:5
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

ATA 75 - AIR

750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component	ATA:75
PN:3070816-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.010	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01									

750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component	ATA:75
PN:3070816-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.010	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
751010	NO. 1 ENGINE - ANTI-ICE VALVE							Component	ATA:75
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.020	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
751010	NO. 2 ENGINE - ANTI-ICE VALVE							Component	ATA:75
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.020	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
751013	NO. 1 ENGINE THERMAL ANTI-ICE VALVE							Component	ATA:75
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.020	AFL	0		TSN 0					
751014	NO. 2 ENGINE THERMAL ANTI-ICE VALVE							Component	ATA:75
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 75.021	AFL	0		TSN 0					
754010	NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH							Component	ATA:75
PN:12423	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:4344TW	HRS	0		TSN 0					
WC#: 75.015	AFL	0		TSN 0					
PROC. REF: AMM 75-40-11PROC. REF: AMM 75-40-11									
754010-1 ^U	LH ANTI-ICE VALVE							Component	ATA:75
PN:F10A5SCP102-5	MOS/MSC	21-Sep-16	O/C	TSN 123					
SN:2BB24	HRS	3191.2		TSN 3191.2					
	AFL	2533		TSN 2533					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 75 - AIR									
754011	NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH							Component	ATA:75
PN:12423	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:29151TW	HRS	0		TSN 0					
WC#: 75.015	AFL	0		TSN 0					
PROC. REF: AMM 75-40-11PROC. REF: AMM 75-40-11									
754011-1 ^U	RH ANTI-ICE VALVE							Component	ATA:75
PN:F10A5SCP102-5	MOS/MSC	22-Jun-17	O/C	TSO 0					
SN:5AF4	HRS	3650.2		TSO 0					
	AFL	2878		TSO 0					
ATA 76 - ENGINE CONTROLS									
760001 ^S	CHECK THROTTLE LEVER CONTROLS							Service	ATA:76
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 76.030	AFL	5563							
PROC. REF: AMM 27-72-00PROC. REF: AMM 27-72-00									
760002 ^S	CHECK ENGINE POWER CONTROL CABLES							Service	ATA:76
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 76.010	AFL	4989							
PROC. REF: AMM 76-10-00PROC. REF: AMM 76-10-00									
760003	CHECK POWER CONTROL CABLES							Service	ATA:76
	MOS/MSC	13-Jul-07	O/C						
	HRS	264.1							
WC#: 76.020	AFL	212							
PROC. REF: AMM 76-10-00PROC. REF: AMM 76-10-00									
760004	LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service	ATA:76
	MOS	11-Jun-24							
	HRS	7107.6	2400		9507.6		1847.4		
WC#: 76.040	AFL	5214							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 76 - ENGINE CONTROLS

PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11

760004	LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service	ATA:76
	MOS	11-Jun-24							
	HRS	7107.6	2400		9507.6		1847.4		
WC#: 76.040	AFL	5214							
PROC. REF: AMS 5-20-11PROC. REF: AMS 5-20-11									

760110 ^U	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL							Component	ATA:76
PN:2119010-8000	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:056-BY0682	HRS	0		TSN 0					
WC#: 76.010	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

760110 ^U	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL							Component	ATA:76
PN:2119010-8000	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:046-BY0641	HRS	0		TSN 0					
WC#: 76.010	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

760120 ^S	NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service	ATA:76
	MOS	04-Jun-25							
	HRS	7499	300 (+100)						
WC#: 76.020	ENC	5503							
									PKG:2
PROC. REF: LMM 76-10-03, LMM 72-00-00PROC. REF: LMM 76-10-03, LMM 72-00-00									

760120 ^S	NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service	ATA:76
	MOS	04-Jun-25							
	HRS	7499	300 (+100)						
WC#: 76.020	ENC	5504							
									PKG:2
PROC. REF: LMM 76-10-03, LMM 72-00-00PROC. REF: LMM 76-10-03, LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
760130	NO. 1 ENGINE - DOWNLOAD ECTM								Service ATA:76
	MOS	09-Jul-25							
	HRS	7538.2							
WC#: 76.050	ENC	5533	40 (+10)		(5573) 5633	5583	10 (+10)		
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03									
760130	NO. 2 ENGINE - DOWNLOAD ECTM								Service ATA:76
	MOS	09-Jul-25							
	HRS	7538.2							
WC#: 76.050	ENC	5534	40 (+10)		(5574) 5633	5584	10 (+10)		
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03									
761310	NO. 1 ENGINE - SURGE BLEED VALVE								Component ATA:76
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 76.030	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01									
761310	NO. 2 ENGINE - SURGE BLEED VALVE								Component ATA:76
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 76.030	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01									
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE								Component ATA:76
PN:109696-4-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 76.040	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE								Component ATA:76
PN:109696-4-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 76.040	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761501 ^U	NO. 1 ENGINE - ITT INVERTER							Component	ATA:76
PN:UNKNOWN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
761501 ^U	NO. 2 ENGINE - ITT INVERTER							Component	ATA:76
PN:UNKNOWN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
ATA 77 - ENGINE INDICATING									
771025	NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
771026	NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
771037	NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
771038	NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component	ATA:77
PN:3073827-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.010	ENC	0		TSN 0					
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03									
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component	ATA:77
PN:3073827-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.010	ENC	0		TSN 0					
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03									
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.020	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05									
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.020	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05									
771500 ^U	NO. 1 ENGINE - N1 RPM AMPLIFIER							Component	ATA:77
PN:UNKNOWN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
771500 ^U	NO. 2 ENGINE - N1 RPM AMPLIFIER							Component	ATA:77
PN:UNKNOWN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771502 ^U	NO. 1 ENGINE - TIME DELAY SWITCH							Component	ATA:77
PN:TD240/605	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
771502 ^U	NO. 2 ENGINE - TIME DELAY SWITCH							Component	ATA:77
PN:TD240/605	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS							Component	ATA:77
PN:3073605-1	MOS/MSC	05-Nov-19	O/C	TSN 0					
SN:1915027700153	HRS	4649.2		TSN 0					
WC#: 77.030	ENC	3648		TSN 0					
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01									
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS							Component	ATA:77
PN:3073605-1	MOS/MSC	31-Oct-24	O/C	TSN 0					
SN:2415027700163	HRS	7145.2		TSN 0					
WC#: 77.030	ENC	5244		TSN 0					
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01									
773005	LEFT TIME DELAY SWITCH							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
773006	RIGHT TIME DELAY SWITCH							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
774013	NO. 1 ENGINE ITT INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
774014	NO. 2 ENGINE ITT INDICATOR							Component	ATA:77
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 77.030	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 78 - EXHAUST									
780001 ^S	INSPECT THRUST REVERSER LINK ARM ASSEMBLIES							Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.110	AFL	5563							
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2								PKG:17,91	
780002 ^S	INSPECT REVERSER DOOR SEALS							Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.120	AFL	5563							
PROC. REF: AMM 78-31-20PROC. REF: AMM 78-31-20								PKG:17,91	
780003 ^S	TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES							Service	ATA:78
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 78.130	AFL	4989							
PROC. REF: AMM 78-34-20PROC. REF: AMM 78-34-20								PKG:22,92	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
780004 ^S	INSPECT PYLON SKIN PANELS								Service ATA:78
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 78.135	AFL	4989							PKG:29,92
780005 ^S	DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS								Service ATA:78
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 78.140	AFL	4989							PKG:29,92
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									
780006 ^S	CHECK THRUST REVERSER LEVER BAULK MECHANISM								Service ATA:78
	MOS	08-Dec-23							
	HRS	6763.7	3200 (+150/-50)						
WC#: 78.125	AFL	4989							PKG:34,93
780009 ^S	INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS								Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.155	AFL	5563							PKG:17,91
780010 ^S	INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS								Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.160	AFL	5563							PKG:13,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
780011 ^S		DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES							Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.165	AFL	5563							PKG:17,91
780012 ^S		INSPECT THRUST REVERSER HYDRAULIC LINES							Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.170	AFL	5563							PKG:17,91
780013 ^S		INSPECT THRUST REVERSER WIRE HARNESSSES							Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.175	AFL	5563							PKG:17,91
780014 ^S		INSPECT THRUST REVERSER FAN DUCTS							Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.180	AFL	5563							PKG:17,91
780015 ^S		INSPECT THRUST REVERSER LATCH BOX SPRINGS							Service ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.185	AFL	5563							PKG:17,91

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
780016 ^S		OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.190	AFL	5563							
								PKG:17,91	
PROC. REF: AMM 78-33-50PROC. REF: AMM 78-33-50									
780017 ^S		INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.195	AFL	5563							
								PKG:17,91	
PROC. REF: AMM 78-31-35PROC. REF: AMM 78-31-35									
780018 ^S		INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.200	AFL	5563							
								PKG:17,91	
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									
780019 ^S		INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.205	AFL	5563							
								PKG:17,91	
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
780020 ^S		INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.210	AFL	5563							
								PKG:17,91	
PROC. REF: AMM NO REF 2PROC. REF: AMM NO REF 2									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
780021 ^S		INSPECT THRUST REVERSER PYLON PLUGS						Service	ATA:78
	MOS	04-Jun-25							
	HRS	7579.6	800 (+40/-10)						
WC#: 78.215	AFL	5563							
									PKG:17,91
780022 ^S		CHECK DOOR LINK RODS						Service	ATA:78
	MOS	08-Dec-23							
	HRS	6763.7	1600 (+50/-50)						
WC#: 78.220	AFL	4989							
									PKG:29,92
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									
781001		NO. 1 ENGINE THRUST REVERSER AFTERBODY						Component	ATA:78
PN:5451101-79	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX493-79	HRS	0		TSN 0					
WC#: 78.015	AFL	0		TSN 0					
PROC. REF: AMM 78-33-40PROC. REF: AMM 78-33-40									
781001A ^U		NO. 1 ENGINE - THRUST REVERSER AFTERBODY						Component	ATA:78
PN:5451101-51	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781001A ^U		NO. 2 ENGINE - THRUST REVERSER AFTERBODY						Component	ATA:78
PN:5451101-51	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781002		NO. 2 ENGINE THRUST REVERSER AFTERBODY						Component	ATA:78
PN:5451101-81	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX493-81	HRS	0		TSN 0					
WC#: 78.015	AFL	0		TSN 0					
PROC. REF: AMM 78-33-40PROC. REF: AMM 78-33-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781013	NO. 1 ENGINE THRUST REVERSER ASSEMBLY								Component ATA:78
PN:HS7830100-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX493-3	HRS	0		TSN 0					
WC#: 78.010	AFL	0		TSN 0					
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
781014	NO. 2 ENGINE THRUST REVERSER ASSEMBLY								Component ATA:78
PN:HS7830100-4	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX493-4	HRS	0		TSN 0					
WC#: 78.011	AFL	0		TSN 0					
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
781026	NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.020	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
781026A ^U	NO. 1 ENGINE - INBD THRUST REVERSER ACTUATOR LATCH ASSEMBLY								Component ATA:78
PN:5453512-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781026A ^U	NO. 2 ENGINE - INBD THRUST REVERSER ACTUATOR LATCH ASSEMBLY								Component ATA:78
PN:5453512-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781027	NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.020	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781027A ^U	NO. 1 ENGINE - OTBD THRUST REVERSER ACTUATOR LATCH ASSEMBLY							Component	ATA:78
PN:5453521-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781027A ^U	NO. 2 ENGINE - OTBD THRUST REVERSER ACTUATOR LATCH ASSEMBLY							Component	ATA:78
PN:5453521-5	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781028	NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781028A ^U	NO. 1 ENGINE - INBD THRUST REVERSER PRIMARY ACTUATOR							Component	ATA:78
PN:5453512-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781028A ^U	NO. 2 ENGINE - INBD THRUST REVERSER PRIMARY ACTUATOR							Component	ATA:78
PN:5453512-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781029	NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.025	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781029A ^U	NO. 1 ENGINE - OUTBD THRUST REVERSER PRIMARY ACTUATOR								Component ATA:78
PN:5453512-9	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781029A ^U	NO. 2 ENGINE - OUTBD THRUST REVERSER PRIMARY ACTUATOR								Component ATA:78
PN:5453512-9	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781053	NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.030	AFL	0		TSN 0					
PROC. REF: AMM 78-32-50PROC. REF: AMM 78-32-50									
781054	NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.030	AFL	0		TSN 0					
PROC. REF: AMM 78-32-50PROC. REF: AMM 78-32-50									
781055	NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.035	AFL	0		TSN 0					
PROC. REF: AMM 78-32-50PROC. REF: AMM 78-32-50									
781056	NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY								Component ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.035	AFL	0		TSN 0					
PROC. REF: AMM 78-32-50PROC. REF: AMM 78-32-50									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781090	NO. 1 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.040	AFL	0		TSN 0					
PROC. REF: AMM 78-32-60PROC. REF: AMM 78-32-60									
781091	NO. 1 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.040	AFL	0		TSN 0					
PROC. REF: AMM 78-32-60PROC. REF: AMM 78-32-60									
781092	NO. 2 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.045	AFL	0		TSN 0					
PROC. REF: AMM 78-32-60PROC. REF: AMM 78-32-60									
781093	NO. 2 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.045	AFL	0		TSN 0					
PROC. REF: AMM 78-32-60PROC. REF: AMM 78-32-60									
781117	NO. 1 ENGINE RETARD THROTTLE ASSEMBLY							Component	ATA:78
PN:5453305-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX177-5-01	HRS	0		TSN 0					
WC#: 78.050	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
781118	NO. 2 ENGINE RETARD THROTTLE ASSEMBLY							Component	ATA:78
PN:5453305-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX177-5-02	HRS	0		TSN 0					
WC#: 78.050	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781129	THRUST REVERSER TIME DELAY RELAY							Component	ATA:78
PN:5400619-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX237-110	HRS	0		TSN 0					
WC#: 78.055	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781130	CONTROL RELAY BOX							Component	ATA:78
PN:5400612-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX254-102	HRS	0		TSN 0					
WC#: 78.060	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
781130A ^U	NO. 1 ENGINE - THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:5400612-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781130A ^U	NO. 2 ENGINE - THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:5400612-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781136	AUXILIARY RELAY BOX							Component	ATA:78
PN:5400605-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX213-1	HRS	0		TSN 0					
WC#: 78.065	AFL	0		TSN 0					
PROC. REF: AMM 78-33-30PROC. REF: AMM 78-33-30									
781142	NO. 1 ENGINE THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:064135141-11	MOS/MSC	02-Dec-17	O/C	TSO 32					
SN:A30041347	HRS	3846.3		TSO 1349.7					
WC#: 78.070	AFL	3048		TSO 1988					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781143	NO. 2 ENGINE THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:064135141-11	MOS/MSC	18-Mar-22	O/C	TSO 7					
SN:A30040989	HRS	5874.1		TSO 0					
WC#: 78.070	AFL	4403		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
781155	THRUST REVERSER ACCUMULATOR							Component	ATA:78
PN:DS259-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:60209-1025	HRS	0		TSN 0					
WC#: 78.075	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
781155A ^U	NO. 1 ENGINE - THRUST REVERSER ACCUMULATOR							Component	ATA:78
PN:DS259-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781155A ^U	NO. 2 ENGINE - THRUST REVERSER ACCUMULATOR							Component	ATA:78
PN:DS259-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781156	HYDRAULIC RELIEF VALVE							Component	ATA:78
PN:MS28893D6-3450	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:67859	HRS	0		TSN 0					
WC#: 78.080	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781161	THRUST REVERSER CONTROL PANEL							Component	ATA:78
PN:5412600-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:HX280-103	HRS	0		TSN 0					
WC#: 78.085	AFL	0		TSN 0					
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781167	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH								Component ATA:78
PN:2365-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3729	HRS	0		TSN 0					
WC#: 78.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781167A ^U	NO. 1 ENGINE - THRUST REVERSER PRESSURE SWITCH								Component ATA:78
PN:2365-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781167A ^U	NO. 2 ENGINE - THRUST REVERSER PRESSURE SWITCH								Component ATA:78
PN:2365-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
781169	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH								Component ATA:78
PN:2365-15	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:3733	HRS	0		TSN 0					
WC#: 78.090	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781173	THRUST REVERSER PRESSURE GAUGE								Component ATA:78
PN:MS28061T7	MOS/MSC	18-Mar-15	O/C	TSO 0					
SN:2317	HRS	2492.9		TSO 0					
WC#: 78.090	AFL	1984		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
781173A ^U	NO. 1 ENGINE - THRUST REVERSER PRESSURE GUAGE								Component ATA:78
PN:5413508-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
781173A ^U	NO. 2 ENGINE - THRUST REVERSER PRESSURE GUAGE							Component	ATA:78
PN:5413508-1	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
782001 ^U	LEFT ENGINE THRUST REVERSER DEPLOY SWITCH (S7)							Component	ATA:78
PN:DS159-1	MOS/MSC	02-Feb-18	O/C	TSN 0					
SN:UNKNOWN	HRS	3926		TSN 0					
	AFL	3113		TSN 0					
783008	NO. 1 ENGINE LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-9	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:TECAV0438	HRS	0		TSN 0					
WC#: 78.095	AFL	0		TSN 0					
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									
783009	NO. 2 ENGINE LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-10	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:TECAV0434	HRS	0		TSN 0					
WC#: 78.095	AFL	0		TSN 0					
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									
783010	NO. 1 ENGINE UPPER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:TECAV0879	HRS	0		TSN 0					
WC#: 78.100	AFL	0		TSN 0					
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									
783011	NO. 2 ENGINE UPPER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:TECAV0865	HRS	0		TSN 0					
WC#: 78.100	AFL	0		TSN 0					
PROC. REF: AMM 78-31-10PROC. REF: AMM 78-31-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 78 - EXHAUST

783013	NO. 1 ENGINE INNER FAN DUCT ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.230	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

783014	NO. 2 ENGINE INNER FAN DUCT ASSEMBLY							Component	ATA:78
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.231	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

784512A ^U	NO. 1 ENGINE - THRUST REVERSER UPPER DOOR							Component	ATA:78
PN:5453101-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

784512A ^U	NO. 2 ENGINE - THRUST REVERSER UPPER DOOR							Component	ATA:78
PN:5453101-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

ATA 79 - OIL

790111 ^S	NO. 1 ENGINE - ANALYZE OIL AND FILTER							Service	ATA:79
	MOS	04-Jun-25							
	HRS	7499	150 (+100)						
WC#: 79.010	ENC	5503							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
									PKG:1

790111 ^S	NO. 2 ENGINE - ANALYZE OIL AND FILTER							Service	ATA:79
	MOS	04-Jun-25							
	HRS	7499	150 (+100)						
WC#: 79.010	ENC	5504							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
									PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790120	NO. 1 ENGINE - CHANGE OIL								Service ATA:79
	MOS	29-Oct-24							
	HRS	7145.2	1200 (+100)		(8345.2) 8425.8	8445.2	765.6 (+100)		
WC#: 79.020	ENC	5244							
PROC. REF: AMM 79-00-00, LMM 72-00-00PROC. REF: AMM 79-00-00, LMM 72-00-00									
790120	NO. 2 ENGINE - CHANGE OIL								Service ATA:79
	MOS	31-Oct-24							
	HRS	7145.2	1200 (+100)		(8345.2) 8425.8	8445.2	765.6 (+100)		
WC#: 79.020	ENC	5244							
PROC. REF: AMM 79-00-00, LMM 72-00-00PROC. REF: AMM 79-00-00, LMM 72-00-00									
790130 ^S	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR								Service ATA:79
	MOS	04-Jun-25							
	HRS	7499	150 (+100)						
WC#: 79.030	ENC	5503							
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03									
790130 ^S	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR								Service ATA:79
	MOS	04-Jun-25							
	HRS	7499	150 (+100)						
WC#: 79.030	ENC	5504							
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03									
791504 ^U	NO. 1 ENGINE - OIL TEMPERATURE VALVE								Component ATA:79
PN:158465-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
791504	U	NO. 2 ENGINE - OIL TEMPERATURE VALVE						Component	ATA:79
PN:158465-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792110		NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3071949-11	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.040	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03									
792110		NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	18-May-21	O/C						
SN:051405700656	HRS	5160.7		TSN 2822.6					
WC#: 79.040	ENC	3929							
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03									
792120		NO. 1 ENGINE - BY-PASS INDICATOR VALVE						Component	ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.050	ENC	0		TSN 0					
PROC. REF: LMM 79-30-01PROC. REF: LMM 79-30-01									
792120		NO. 2 ENGINE - BY-PASS INDICATOR VALVE						Component	ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.050	ENC	0		TSN 0					
PROC. REF: LMM 79-30-01PROC. REF: LMM 79-30-01									
792130		NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY						Component	ATA:79
PN:3075323-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.060	ENC	0		TSN 0					
PROC. REF: LMM 79-20-02PROC. REF: LMM 79-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								Component ATA:79
PN:3075323-3	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.060	ENC	0		TSN 0					
PROC. REF: LMM 79-20-02PROC. REF: LMM 79-20-02									
792140	NO. 1 ENGINE - UPPER OIL COOLER								Component ATA:79
PN:158600-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.070	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									
792140	NO. 2 ENGINE - UPPER OIL COOLER								Component ATA:79
PN:158600-7	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.070	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									
792144	NO. 1 ENGINE OIL LOW PRESSURE SWITCH								Component ATA:79
PN:HTE690012	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:9060831	HRS	0		TSN 0					
WC#: 79.030	AFL	0		TSN 0					
PROC. REF: AMM 79-33-11PROC. REF: AMM 79-33-11									
792145	NO. 2 ENGINE OIL LOW PRESSURE SWITCH								Component ATA:79
PN:HTE690012	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:9060820	HRS	0		TSN 0					
WC#: 79.030	AFL	0		TSN 0					
PROC. REF: AMM 79-33-11PROC. REF: AMM 79-33-11									
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.080	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.080	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.090	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.090	ENC	0		TSN 0					
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09									
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:158610-8	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.100	ENC	0		TSN 0					
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07									
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:158610-8	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.100	ENC	0		TSN 0					
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07									
793001	NO. 1 ENGINE OIL PRESSURE TRANSMITTER								Component ATA:79
PN:APTE-354-1000-70G	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7097-3-623	HRS	0		TSN 0					
WC#: 79.040	AFL	0		TSN 0					
PROC. REF: AMM 79-32-11PROC. REF: AMM 79-32-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 850XP Serial: 258789 RegNo: N850EC HRS: 7660.2 AFL: 5623 As Of: 31-Jul-2025

10-Sep-2025 03:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793002	NO. 2 ENGINE OIL PRESSURE TRANSMITTER								Component ATA:79
PN:APTE-354-1000-70G	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:7133-3-109	HRS	0		TSN 0					
WC#: 79.040	AFL	0		TSN 0					
PROC. REF: AMM 79-32-11PROC. REF: AMM 79-32-11									
793037	NO. 1 ENGINE OIL PRESSURE INDICATOR								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793038	NO. 2 ENGINE OIL PRESSURE INDICATOR								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793049	NO. 1 ENGINE OIL TEMPERATURE INDICATOR								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793050	NO. 2 ENGINE OIL TEMPERATURE INDICATOR								Component ATA:79
PN:PN	MOS/MSC	29-Jun-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.050	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task