

The subject aircraft was involved in an incident /
accident on 2/16/2026 rendering it a Constructive Total
Loss as not repairable within its insured value. For
further details refer to insurance claim: 2047518891US.

Signed: *Underwriters Salvage Company*

Date: 3/10/2026

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100



McCAULEY™

PROPELLER LOGBOOK

MAINTENANCE & SERVICE HISTORY

A/c # 3364 - TOTAL Aircraft Time 7144.0 N 5019E

Date	Total Propeller Time	Time New Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
2010				
19 Sept 10	0	0	INSTALLED New Prop. ON A/C N 5019E - in accordance with McCauley Prop. MPC-11 & Cessna mm - D-60290	
	FAA Form 8130-3			
	Tracking # 10-1003		INSTALLATION INSTRUCTIONS for Prop & Spinner Torque Lub	
	WO# 21490464			
Approval Brian Johnson - ODA100129-CE			A-1637-15, Torque To 45 FT Lbs	
Date May 6 2010			Prop. P/N 2A34C203-C - RUN-UP & LEAK CK - OK for Further Service	
Listed on Type Cert. 5A6			D-7520 EK CW SK 180-45 Spinner & Prop	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Reg#: N5019E
 Make: McCauley
 Model: 2A34C203-C
 S/N: 100469



WFC-Maintenance, LLC
 Williamsburg, VA 23185

Date: 11-28-2015
 Hobbs:
 Tach: 3390.2

-AD's current Ref. AD Toolbox Rev. 2015-11A.
 -Re-shimmed spinner per McCauley manual.

I certify this propeller has been inspected IAW an Annual/100HR inspection per FAR 43 appendix D and was determined to be in airworthy condition at this time.

Shawn Cole 

AP3142798IA

Reg#: N5019E
 Make: McCauley
 Model: 2A34C203-C
 S/N: 100469




WFC-Maintenance, LLC
 Williamsburg, VA 23185

Date: 01-25-17
 Hobbs:
 Tach: 3394.2

-AD's current Ref. Triton Aviation Data Library

I certify this propeller has been inspected IAW an Annual/100HR inspection per FAR 43 appendix D and was determined to be in airworthy condition at this time.



Mark Jennings 

AP3137950IA

Date
2011
1 Apr 11
1 Apr 12

Note: Enter C

HISTORY

	Authorized Signatures Repairman and Station Certificate Numbers
	2081057-APP
	
	2081057-APP
	

Continues On Pages 11 & 12

Owner Name _____

Address _____

Propeller Model 2A34C203-C

Blade Model G-90DCA-8

Hub Serial No. 100469

Blade Serial No. 1 AEA 26164

2 AEA 26178

3 Woodward Gov. 210105

4 SK180-45 + Sprinckle-0752004

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
MAY 05 2010	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR- WORTHY ON THIS DATE.	1021