None State State of the



Nol

wo: BW4355V-02253



Propeller · page 1 of 1

Blackwater Aero LLC · 525 Airport Road, Hangar 4 · Martinsville, VA 24112 · 276-254-4942

N4355V

HOBBS: 899.37

March 01, 2023

Propeller 100 Hour/Annual Inspection Due – This propeller has been inspected IAW an 100 HOUR/Condition inspection IAW FAR 43 appendix D and IAW FAR 43.11. This propeller was found to be in an airworthy condition and is approved for return to service.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Blackwater Aero LLC under work order: BW4355V-02253.

Kevin Campbell A&P/IA AP3537913IA

Hi Can

3 A;

wo: BW4355V-02253



Airframe - page 1 of 1

Blackwater Aero LLC · 525 Airport Road, Hangar 4 · Martinsville, VA 24112 · 276-254-4942

N4355V

HOBBS: 899.37

Fantasy Air SRO, Allegro 2000, S/N: 05-207

March 01, 2023

I certify this aircraft has been serviced and inspected IAW a CONDITION INSPECTION IAW FAR 43.9 appendix D and IAW FAR 43.11. This aircraft was found to be in an airworthy condition ad is approved for return to service.

Kevin Campbell A&P/IA AP3537913IA

2: C

마	wo: E	3W4355V-0506	11 P	ropeller · page 1 of 1		<u></u>	wo: BW43	355V-05061		
Year		Blackw	vater Aero LLC · 525 Airport Road, Hangar 4 · Martinsville, VA 24112 · 276-25	54-4942					Airframe · page 1 of 1	FIONS [
Date Next	N43 HOE	55V 3BS: 917.18	WoodComp, Klassic 760-3-R, S/N: 70-54, 70-76	May 25, 2022		! -	N40551/		Aero LLC · 525 Airport Road, Hangar 4 · Martinsville, VA 24112 · 276-254-4942	
Due:	1.	Propeller 10	00 Hour/Annual Inspection Due – This propeller has been inspection inspection IAW FAR 43 appendix D and IAW FAR 43.11. This property condition and is approved for return to position and is approved for return to position.	cted IAW an 100		1 1	N4355V HOBBS:	917.18	Fantasy Air SRO, Allegro 2000, S/N: 05-207 May 25, 2022	
==	l				l d ap	I certify this aircraft has been serviced and inspected IAW a CONDITION INSPECTION IAW FAR 43 appendix D and IAW FAR 43.11. This aircraft was found to be in an airworthy condition and is approved for return to service.				
Year Date	With forme	With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Blackwater Aero LLC under work order: BW4355V-05061.			ret	return to service.				
Next Due:			P/IA AP3537913IA			Ke	evin Cam	npbell A&P/IA	A AP3537913IA	
		1	Mech. Cert. # or Repair Station #						Mech. Cert. # or Repair Station #	
Year: _		Total Time in Service	Description					Total Time	Description	
Date:					— j	Year: Date:		in Service	Description	
Next In: Due:	spection	on Time Since Overhaul		— j	Next Insp	pection 1	Time Since			
			Mech. Cert. # or Repair Station #			Due:	(Overhaul	Mech. Cert. # or Repair Station #	

wo: BW4355V-05061	(276) 957-1109	ırtinsville, VA 24112	525 Airport Rd, Martir	k Service	Blue Ridge Aircraft Sales &
	Date: 5/25/2019 S/N: 70-54 and 70-76		ke/ Model: Fantasy Air SRO ller Model: Klassic 760-3-R Hobbs: 839.18	Propelle	Tail Number: N4355V Propeller Make: WoodComp Propeller TT: 87.98
N4355V HOBBS: 899.3	AR 43 appendix D and	hour Inspection I/A/W FAI	l inspected I/A/W a 150 hou	serviced and	I certify this propeller has been
1. Propeller HOUR/Co to be in ar	return to service.		2	er was found to	I/A/W FAR 43.11. This propelle
		nship A&P4063914	Kris Blankenshi		
With respect to formed are on file	(276) 957-1109	Martinsville, VA 24112	525 Airport Rd, Mar	s & Service	Blue Ridge Aircraft Sales
Kevin Campbell	Date: 5/01/2020		Make/ Model: Fantasy Air SF		Tail Number: N4355V
Voor	o S/N: 70-54 and 70-76	-3-K Propeller Hub	oeller Model: Klassic 760-3-F ft Hobbs: 865.5		Propeller Make: WoodComp Propeller TT: 114.3

Kris Blankenship A&P4063914

Blackwater Aero LLC · 525 Airport Road, Hangar 4 · Martinsville, VA 24112 · 276-254-4942 WoodComp, Klassic 760-3-R, S/N: 70-54, 70-76 BS: 899.37 May 20, 2021 Propeller 100 Hour/Annual Inspection Due – This propeller has been inspected IAW an 100 HOUR/Condition inspection IAW FAR 43 appendix D and IAW FAR 43.11. This propeller was found to be in an airworthy condition and is approved for return to service. n respect to the work performed, this propeller is approved for return to service. Details of work permed are on file with Blackwater Aero LLC under work order: BW4355V-05061. vin Campbell A&P/IA AP3537913IA IULAI IIIIU Description in Service Date: **Next Inspection** Time Since Overhaut Mech. Cert. # or Repair Station #

HIIR & BLADE INSPECTIONS. REPAIRS AND ALTERATIONS \Box

Propeller - page 1 of 1

I certify this propeller has been serviced and inspected I/A/W a 100/150 hour Inspection I/A/W FAR 43 appendix D and I/A/W FAR 43.11. This propeller was found to be in an airworthy condition and is approved for return to service.

☐ HUB & BL		TIONS, REPAIRS AND ALTERATIONS			HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS \Box
Year	Total Time	Paradiate	Year:	Total Time in Service	Description
Date ——— Next Due:			Date:	Time Since Overhaul	
Prope	eller replace ced and aut	- 12/14/2017 NY355V 7775/ ed with new Woodcomp Klassic 160 propeller. Propeller is exactly as thorized by Allegro manufacturer as the proper propeller for all 912UL b. LSA America, Inc. 20-5919040 Mech. Cert. # or Repair Station #	Tail Number: Propeller Ma	Airport Authorit	Mech. Cert. # or Repair Station # ity 525 Airport Rd, Martinsville, VA (276) 957-1109 Fax (276) 957-2292 Aircraft Make/ Model: Fantasy Air SRO Allegro 2000 Date: 4/25/2018 Propeller Model: Klassic 760-3-R Propeller Hub S/N: 70-54 and 70-76 Aircraft Hobbs: 721-37
Year:	Total Time in Service	Description	I certify this pro	opeller has be 11. This prope	een serviced and inspected I/A/W a 150 hour Inspection I/A/W FAR 43 appendix D and eller was found to be in an airworthy condition and is approved for return to service.
Next Inspection Due:	Time Since Overhaul				Kris Blankenship A&P4063914
		Mech. Cert. # or Repair Station #			~

Y D N D	Propelle Propelle Service	nber: N4355V r Make: Wood r TT: 577.1 e performed nufactures spe	Aircraft Hobbs: 577.1 Removed and replaced this propeller after gearbox inspection. All hardware torqued
I certify this propeller has been inspected on 4/6/2015 in accordance with a 150 Hour Inspection in referent to the manufacturer's maintenance and inspection procedures and was found to be in a condition for safe of and is approved for return to service at this time. Kevin Campbell A&P3537913		turn to service at this time.	
		1	Mech. Cert. # or Repair Station #
Year:		Total Time in Service	Description
Date:			
Next Inspection Due:		Time Since Overhaul	

Mech. Cert. # or Repair Station #

− Y∈ Da	Tail Number: N4355V Propeller Make: WoodComp Propeller TT: 649.01	Aircraft Make/ Model: Fantasy Air SRO Allegro 2000 Date: 3/16/2016 Propeller Model: Klassic 760-3-R Propeller Hub S/N: 70-54 and 70-76 Aircraft Hobbs: 649.01						
No Di	I certify this propeller has been inspected on 3/16/2016 in accordance with a 150 Hour Inspection per the manufacturer's maintenance and inspection procedures and was found to be in a condition for safe operation and is approved for return to service at this time. Kevin Campbell A&P3537913							
Da	t I							
Blu	ue Ridge Airport Authority 525	Airport Rd, Martinsville, VA (276) 957-1109 Fax (276) 957-2292						
Tai	Number NASELY	rcroft Molec/Maria I. E.						

Propeller Make: WoodComp Propeller TT: 721.57

Aircraft Make/ Model: Fantasy Air SRO Allegro 2000

Date: 4/2/2017

Propeller Model: Klassic 760-3-R

Aircraft Hobbs: 721.57

I certify this propeller has been serviced and inspected I/A/W a **150 hour Inspection** I/A/W FAR 43 appendix D and I/A/W FAR 43.11. This propeller was found to be in an airworthy condition and is approved for return to service.

Michael B Smith A&P409570064IA

☐ HUB & BL	ADE INSPECT	TIONS, REPAIRS AND ALTERATIONS	Blue Ridge Airport Authority 525 Airport Rd, Martinsville, VA (276) 957-1109 Fax (276) 957-2292			
Tail Num Propeller	Total Time in Service Description Use Ridge Airport Authority 525 Airport Rd, Martinsville, VA (276) 957-1109 Fax (276) 957-2292 Aircraft Make/ Model: Fantasy Air SRO Allegro 2000 Date: 2/12/2013 Propeller Make: WoodComp Opeller TT: 415.35 Aircraft Hobbs: 415.35 Description Description Fax (276) 957-2292 Aircraft Make/ Model: Fantasy Air SRO Allegro 2000 Date: 2/12/2013 Aircraft Hobbs: 415.35		Tail Number: N4355V Propeller Make: WoodComp Propeller TT: 491.57 Aircraft Make/ Model: Fantasy Air SRO Allegro 2000 Propeller Model: Klassic 760-3-R Aircraft Hobbs: 491.57 I certify this propeller has been inspected on 3/7/2014 in accordance with a 150 Hour Inspection per the and is approved for return to service at this time.			- - -
I certify this propeller has been inspected on 2/12/2013 in accordance with a 150 Hour Inspection per the manufacturer's maintenance and inspection procedures and was found to be in a condition for safe operation and is approved for return to service at this time. Kevin Campbell A&P3537913		Next Inspection Due:	Time Since Overhaul	Kevin Campbell A&P3537913 Mech. Cert. # or Repair Station #		
Date:	İ	I	Year:	Total Time in Service	Description	
Next Inspection	Time Since		Date:			
Due:	Overhaul		Next Inspection Due:	Time Since Overhaul		
		Mech. Cert. # or Repair Station #			Mech. Cert. # or Repair Station #	

Propeller Record General Information	
Propeller Manufacturer WoodComp	
Model Klassic 760-3-R	_
Hub Series # #1: 70-54, #2: 70-76 Blade #	1: 5005633R
	d. 5005633R
•	3: 5005633R
Make/Model Aircraft Installed On: Fantasy Air SRO	Serial # 05 - 207
Allegro 2000	