

Total projection:

Company

Owner: Executive Flight Services
Operator:

Major Assemblies

Airframe	Challenger 300	20428	03-Mar-2023	2,321.8 Hrs	1,268 Ldg	1,971 Hrs(APU)
Eng 1	AS907-1-1A	P118995	03-Mar-2023	2,321.8 Hrs	1,268 Enc	
Eng 2	AS907-1-1A	P118996	03-Mar-2023	2,321.8 Hrs	1,268 Enc	
APU 1	GTCP36-150[BD]	P-544	03-Mar-2023	1,971 Hrs	0 APUS	

Additional Information

Program Type: Standard, General Categories: HASC,RVSM,Standard

Cost:
Man Hrs: 2,512.5+

Analyst: Jon Dolan jdolan@jetsupport.com

Task No	Description								Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
21-51-01-301	Restoration (Bench Test) of the Ozone Converters						RE	MRB - Systems/Powerplant	≈01-Sep-2023	
	21 A/F	Lower			Mos					
					Hrs		2,500	-/+40	2,500	7% (+1.6%)
	Alias1:215000-208, AMTOSS:21-51-01-840-801				Ldg					
21-51-01-301	Restoration (Bench Test) of the Ozone Converters						RE	MRB - Systems/Powerplant	≈01-Sep-2023	
	21 A/F	Upper			Mos					
					Hrs		2,500	-/+40	2,500	7% (+1.6%)
	Alias1:215000-208, AMTOSS:21-51-01-840-801				Ldg					
▼ 24 - ELECTRICAL POWER										
24-31-05-201	Restoration (Overhaul) of the Main Generator						RE	MRB - Systems/Powerplant	≈20-Jan-2025	
	24 A/F	Left			Mos					
					Hrs		3,000	-/+40	3,000	23% (+1.3%)
	Alias1:243000-201, AMTOSS:24-31-05-610-801				Ldg					
24-31-05-201	Restoration (Overhaul) of the Main Generator						RE	MRB - Systems/Powerplant	≈20-Jan-2025	
	24 A/F	Right			Mos					
					Hrs		3,000	-/+40	3,000	23% (+1.3%)
	Alias1:243000-201, AMTOSS:24-31-05-610-801				Ldg					
24-31-09-201	Restoration (Overhaul) of the Auxiliary Power Unit (APU) Generator.						RE	MRB - Systems/Powerplant	≈08-Jan-2028	
	24 A/F				Mos	06-Oct-2016				
					Hrs					
	Alias1:243000-202, AMTOSS:24-31-09-610-801				Ldg					
					Hrs (APU)	717	3,000	-/+40	3,717	58% (+1.3%)
24-32-01-302	Restoration (Bench Check) of the Batteries						RE	MRB - Systems/Powerplant		
	24 A/F	Aft			Mos	24-Jun-2022	12	-/+1m	30-Jun-2023	OVD
	Restored Date 24-Jun-2022				Hrs	2,196.3				
	Alias1:243000-205, AMTOSS:24-32-01-610-801				Ldg	1,205				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
24-32-01-302	Restoration (Bench Check) of the Batteries						RE	MRB - Systems/Powerplant		
	24 A/F	Fwd			Mos	24-Jun-2022	12	-/+1m	30-Jun-2023	OVD
	Restored Date 24-Jun-2022				Hrs	2,196.3				
	Alias1:243000-205, AMTOSS:24-32-01-610-801				Ldg	1,205				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
24-32-05-101*	Restoration (Overhaul) of the integrated Standby-Instrument (ISI) Battery						RE	Time Limits - Supplementary Limitations		
	24 A/F				Mos	07-Jan-2022	36		31-Jan-2025	OVD
					Hrs	1,962.1				
	AMTOSS:24-32-05-610-801				Ldg	1,085				

Total projection:

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
24-61-01-101*	Restoration of the Left DC Power Center (DCPC) (Pre SB100-24-30), Part No. 975GC02Y04 / 975GC02Y05 / 975GC02Y06 / 975GC02Y07					RE	Time Limits - Supplementary Limitations		≈10-Jun-2026
 24 A/F	Left				Mos				
					Hrs	3,500		3,500	34%
	AMTOSS:24-61-01-160-801				Ldg				
▼ 25 - EQUIPMENT/FURNISHINGS									
	Kit, First Aid					RE (O/C)			
 25 A/F					Mos	24-Jun-2022		30-Jun-2023	??%
	AFAK 1.0				Hrs	2,196.3			
	052407006				Ldg	1,205			
	Expiration Date 30-Jun-2023								
	Alias1:25-06-00								
	Protective Breathing Equipment (PBE) for the Flight Crew					RE	MRB - Systems/Powerplant		
 25 A/F	Fwd				Mos	08-Jan-2021	120	-/+1m	32% (+0.8%)
	119003-21				Hrs	1,773.8			
	0A4-46695M				Ldg	958			
	Manufactured Date 30-Jun-2018								
	AMTOSS:25-62-05-960-801, MSG-3 Task No.:256200-207, TLMC:25-62-00-203								
256115-7103A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Left No.1				Mos		120	31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								
256115-7104A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Right No.1				Mos		120	31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								
256115-7105A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Left No.2				Mos		120	24-May-2023	OVD
	Restored Date 24-May-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								
256115-7106A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Right No.2				Mos		120	31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								
256115-7107A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Left No.3				Mos		120	31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								
256115-7108A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Right No.3				Mos		120	31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024								

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
256115-7109A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Left No.4				Mos	120		31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
256115-7110A	Restoration Passenger Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Right No.4				Mos	120		31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
256115-7112A	Restoration of Lifevest (25-62-00-601)					RE		STLMC, BCCM	
 25 A/F	Aft Lavatory				Mos	120		31-Jul-2023	OVD
	Restored Date 31-Jul-2013				Hrs				
	AMTOSS:25-61-00-610-801				Ldg				
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
25-62-00-201	Restoration (Overhaul) of the Crew Life Vests					RE	MRB - Systems/Powerplant		
 25 A/F	Copilot				Mos	26-Sep-2018	60	-/+1m 30-Sep-2023	OVD
	Restored Date 26-Sep-2018				Hrs	1,251.7			
	Alias1:256200-201, AMTOSS:25-62-01-610-801				Ldg	688			
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
25-62-00-201	Restoration (Overhaul) of the Crew Life Vests					RE	MRB - Systems/Powerplant		
 25 A/F	Pilot				Mos	26-Sep-2018	60	-/+1m 30-Sep-2023	OVD
	Restored Date 26-Sep-2018				Hrs	1,251.7			
	Alias1:256200-201, AMTOSS:25-62-01-610-801				Ldg	688			
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
256200-7101B	Restoration Forward Closet Life Raft (25-62-00-602)					RE (Due)		STLMC, BCCM	
 25 A/F	No.1				Mos	26-Jul-2022		01-Jul-2025	??%
	Expiration Date 01-Jul-2025				Hrs				
	AMTOSS:25-61-00-610-802				Ldg				
256200-7102B	Restoration Forward Closet Life Raft (25-62-00-602)					RE (Due)		STLMC, BCCM	
 25 A/F	No.2				Mos	26-Jul-2022		01-Jul-2025	??%
	Expiration Date 01-Jul-2025				Hrs				
	AMTOSS:25-61-00-610-802				Ldg				
256200-7103B	Restoration Aft Cabinet Life Raft (25-62-00-602)					RE (Due)		STLMC, BCCM	
 25 A/F	No.3				Mos	26-Jul-2022		01-Jul-2025	??%
	Expiration Date 01-Jul-2025				Hrs				
	AMTOSS:25-61-00-610-802				Ldg				
262301-7103B	Restoration of Portable Fire Extinguisher (25-62-00-610)					RE			
 25 A/F	Aft Lavatory				Mos	31-May-2022	72	31-May-2028	53%
					Hrs				
					Ldg				
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									
▼ 26 - FIRE PROTECTION									
	Fire-Extinguisher Discharge Cartridge					RE		AWL - Life Limit/MRB	
 26 A/F	Left No.1				Mos	120		31-May-2023	OVD
	446518-1 New				Hrs				
	ACV2626				Ldg				
	Manufactured Date 01-May-2013								
	Alias1:26-21-05-101*,262000-203, AMTOSS:26-21-05-961-801								
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024									

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No	Description									Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining	
	Fire-Extinguisher Discharge Cartridge						RE		AWL - Life Limit/MRB		
	26 A/F	Left No.2	0		Mos		120		31-Jul-2023	OVD	
	446518-1	New	0		Hrs						
	ACV3968		0		Ldg						
	Manufactured Date 31-Jul-2013										
Alias1:26-21-05-101*,262000-203, AMTOSS:26-21-05-961-801											
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024											
	Fire-Extinguisher Discharge Cartridge						RE		AWL - Life Limit/MRB		
	26 A/F	Right No.1	0		Mos		120		31-May-2023	OVD	
	446518-1	New	0		Hrs						
	ACX2629		0		Ldg						
	Manufactured Date 31-May-2013										
Alias1:26-21-05-101*,262000-203, AMTOSS:26-21-05-961-801											
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024											
	Fire-Extinguisher Discharge Cartridge						RE		AWL - Life Limit/MRB		
	26 A/F	Right No.2	0		Mos		120		31-Jul-2023	OVD	
	446518-1	New	0		Hrs						
	ACX3933		0		Ldg						
	Manufactured Date 01-Jul-2013										
Alias1:26-21-05-101*,262000-203, AMTOSS:26-21-05-961-801											
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024											
	Fire-Extinguisher Discharge Cartridge (APU)						RE		AWL - Life Limit/MRB		
	26 A/F	Right No.3	0		Mos		120		31-Jul-2023	OVD	
	446518-1	New	0		Hrs						
	ACX3941		0		Ldg						
	Manufactured Date 01-Jul-2013										
Alias1:26-21-05-101*,262000-203, AMTOSS:26-21-05-961-801											
 0ER-WP-001 / WO# 2024127 START 18-JAN-2024											
262301B		Restoration - Flight Compartment Portable Fire Extinguisher						RE			
	26 A/F	Cockpit			Mos	31-Jan-2022	72		31-Jan-2028	47%	
	Restored Date 31-Jan-2022				Hrs						
					Ldg						
▼ 27 - FLIGHT CONTROLS											
	Bolt of the Flap Inboard Actuator						RE		AWL - Life Limit	≈19-Jun-2040	
	27 A/F	Fwd - Left	0		Mos	25-Nov-2013					
	1005756020-001	New	0		Hrs	0					
	STR0953		0		Ldg	0	7,500		7,500	83%	
	Alias1:27-52-13-101*,57-50-106,27-52-13, AMTOSS:27-52-13-961-802										
	Bolt of the Flap Inboard Actuator						RE		AWL - Life Limit	≈19-Jun-2040	
	27 A/F	Fwd - Right	0		Mos	25-Nov-2013					
	1005756020-001	New	0		Hrs	0					
	STR0944		0		Ldg	0	7,500		7,500	83%	
	Alias1:27-52-13-101*,57-50-106,27-52-13, AMTOSS:27-52-13-961-802										
	Bolt of the Flap Outboard Actuator						RE		AWL - Life Limit	≈19-Jun-2040	
	27 A/F	Aft - Left	0		Mos	25-Nov-2013					
	1005756020-003	New	0		Hrs	0					
	STR1060		0		Ldg	0	7,500		7,500	83%	
	Alias1:27-52-15-101*,57-50-106,27-52-15, AMTOSS:27-52-15-961-802										
	Bolt of the Flap Outboard Actuator						RE		AWL - Life Limit	≈19-Jun-2040	
	27 A/F	Aft - Right	0		Mos	25-Nov-2013					
	1005756020-003	New	0		Hrs	0					
	STR1048		0		Ldg	0	7,500		7,500	83%	
	Alias1:27-52-15-101*,57-50-106,27-52-15, AMTOSS:27-52-15-961-802										

Total projection:

Challenger 300 N300ER, SN 20428

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
		Bushing, Primary Loadpath, HSTB Instl							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	1005510807-005	New	0		Mos	25-Nov-2013				
507			0		Hrs	0				
TLMC:55-31-00-131*			0		Ldg	0	7,500		7,500	83%
		Bushing, Secondary Loadpath, HSTB Instl							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	1005510809-001	New	0		Mos	25-Nov-2013				
437			0		Hrs	0				
TLMC:55-31-00-131*			0		Ldg	0	7,500		7,500	83%
		FPU Ecology Bottle							RE	AWL - Life Limit
27 A/F	1754A0000-01		2		Mos	30-Nov-2022	60		30-Sep-2027	50%
Unknown					Hrs	2,249				
Alias1:27-52-35-101*,27-52-35, AMTOSS:27-52-35-961-801					Ldg	1,229				
		Horizontal Stabilizer Trim Actuator (HSTA)							RE	AWL - Life Limits (Structures) ≈14-Apr-2061
27 A/F	C47100-004	New	0		Mos	25-Nov-2013				
457			0		Hrs	0				
AMTOSS:27-41-05-961-801, AMTOSS:27-41-05-961-802, Ref. No.:27-40-001, Ref. No.:27-40-002, TLMC:27-41-05-102*, TLMC:27-41-05-103*			0		Ldg	0	15,000		15,000	92%
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.1		0		Mos	25-Nov-2013				
1005776020-001	New		0		Hrs	0				
12CAM0516			0		Ldg	0	7,500		7,500	83%
Alias1:27-63-05, TLMC:57-71-00-107*										
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.2		0		Mos	25-Nov-2013				
1005776020-001	New		0		Hrs	0				
12CAM0471			0		Ldg	0	7,500		7,500	83%
Alias1:27-63-05, TLMC:57-71-00-107*										
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.3		0		Mos	25-Nov-2013				
1005776020-001	New		0		Hrs	0				
13CAM0529			0		Ldg	0	7,500		7,500	83%
Alias1:27-63-05, TLMC:57-71-00-107*										
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.4		0		Mos	25-Nov-2013				
1005776020-001	New		0		Hrs	0				
13CAM0555			0		Ldg	0	7,500		7,500	83%
Alias1:27-63-05, TLMC:57-71-00-107*										
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.5		0		Mos	25-Nov-2013				
1005776030-001	New		0		Hrs	0				
13CAM0502			0		Ldg	0	7,500		7,500	83%
Alias1:27-62-01, TLMC:57-72-00-114*										
		Shoulder Bolt							RE	AWL - Life Limit ≈19-Jun-2040
27 A/F	No.6		0		Mos	25-Nov-2013				
1005776030-001	New		0		Hrs	0				
13CAM0533			0		Ldg	0	7,500		7,500	83%
Alias1:27-62-01, TLMC:57-72-00-114*										

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No	Description	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN								DUE	Remaining
Shoulder Bolt							RE		AWL - Life Limit	≈19-Jun-2040
	27 A/F	No.7		0	Mos	25-Nov-2013				
	1005776030-001	New		0	Hrs	0				
	13CAM0531			0	Ldg	0	7,500		7,500	83%
	Alias1:27-62-01, TLMC:57-72-00-116*									
Shoulder Bolt							RE		AWL - Life Limit	≈19-Jun-2040
	27 A/F	No.8		0	Mos	25-Nov-2013				
	1005776030-001	New		0	Hrs	0				
	13CAM0537			0	Ldg	0	7,500		7,500	83%
	Alias1:27-62-01, TLMC:57-72-00-116*									
27-12-05-301		Restoration (Overhaul) of the Aileron Trim Actuator					RE		MRB - Systems/Powerplant	≈16-May-2043
	27 A/F				Mos					
					Hrs		9,600	-/+40	9,600	76% (+0.4%)
	Alias1:271000-211, AMTOSS:27-12-05-610-801									
27-40-00-104*		Restoration (Overhaul) of the Horizontal Stabilizer Trim Actuator (HSTA), Part No. C47100-004 and subs.					RE		AWL - CMR	≈19-Jun-2040
	27 A/F				Mos	25-Nov-2013				
					Hrs	0	10,000		10,025	77%
	AMTOSS:27-41-05-610-801									
27-40-00-108**		Restoration (Inspection) of the Horizontal Stabilizer Trim Actuator (HSTA), Part No. C47100-003 and subs.					RE		AWL - CMR	
	27 A/F				Mos		120		[31-Jan-2025]	OVD
	Restored Date 25-Apr-2013				Hrs					
					Ldg					
27-41-05-104*		Restoration (Overhaul) of the Horizontal Stabilizer Trim Actuator (HSTA), Part No. C47100-004/-005					RE		Time Limits - Supplementary Limitations	≈19-Jun-2040
	27 A/F				Mos					
					Hrs		10,000		10,000	77%
	AMTOSS:27-41-05-610-801									
▼ 29 - HYDRAULIC POWER										
		Auxiliary Hydraulic System Accumulator (TLMC 29-21-13-101*)					RE		AWL - Life Limit	≈24-Oct-2060
	29 A/F				Mos	25-Jan-2016				
	900095-1				Hrs	648.7				
	60199-1793ENA		532		Ldg	362	15,000		14,830	90%
AMTOSS:29-21-13-961-801, TLMC:29-21-13-101*,29-21-13										
▼ 31 - INDICATING / RECORDING SYSTEM										
		Battery in the Underwater Locating Device (FDR)					RE (Due)		MRB - Systems/Powerplant	
	31 A/F				Mos	07-Oct-2019		-/+1m	30-Apr-2025	??%
	266E0305-00				Hrs	1,541.2				
	SD19904				Ldg	830				
Expiration Date 30-Apr-2025										
Alias1:31-31-13-202,313100-204, AMTOSS:31-31-13-961-801										
▼ 32 - LANDING GEAR										
		Axle of the Main Landing Gear					RE		AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Left		92	Mos	25-Jul-2021				
	40112-1			1,813.2	Hrs	1,813.2				
	12SPP0802			976	Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-25-961-802, AMTOSS:(CH300) 32-11-25-961-801, Ref:32-10-01, Ref:32-11-25, Task#:(CL300) 32-11-25-101*, Task#:(CL350) 32-11-25-102*										
		Axle of the Main Landing Gear					RE		AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Right		92	Mos	25-Jul-2021				
	40112-1			1,813.2	Hrs	1,813.2				
	12SPP0801			976	Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-25-961-802, AMTOSS:(CH300) 32-11-25-961-801, Ref:32-10-01, Ref:32-11-25, Task#:(CL300) 32-11-25-101*, Task#:(CL350) 32-11-25-102*										

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER, SN 20428

Total projection:

Task No	Description	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN								DUE	Remaining
Axle of the Nose Landing Gear										
32 A/F						Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40642-101			1,813.2			Hrs	1,813.2			≈14-Apr-2061
11HMO121276			976			Ldg	976	15,000	15,000	92%
AMTOSS:(CL350) 32-21-05-961-814, AMTOSS:(CL300) 32-21-05-961-804, Ref:32-21-01, Ref:32-10-02, Task#:(CL350) 32-21-01-108*, Task#:(CL300) 32-21-01-102*										
Brake Accumulator (TLMC 32-43-37-101*)										
32 A/F			0			Mos	25-Nov-2013		RE	AWL - Life Limit
33-147500	New		0			Hrs	0			≈04-Nov-2061
60218-2398NAE			0			Ldg	0	15,200	15,200	92%
TLMC:32-43-37-101*,32-43-37										
Cylinder (Main Fitting) of the Nose Landing Gear										
32 A/F			92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40640-107			1,813.2			Hrs	1,813.2			≈19-Jun-2040
12MDC08460			976			Ldg	976	7,500	7,500	83%
AMTOSS:(CL300) 32-21-05-961-801, AMTOSS:(CL350) 32-21-05-961-813, Ref:32-10-02, Ref:32-20-08, Task#:(CL300) 32-21-05-102*, Task#:(CL350) 32-21-05-105*										
Cylinder Trunnion Pin of the Nose Landing Gear										
32 A/F	Left		92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40631-1			1,813.2			Hrs	1,813.2			≈14-Apr-2061
12CPS0930			976			Ldg	976	15,000	15,000	92%
AMTOSS:(CL300) 32-21-05-961-810, AMTOSS:(CL360) 32-21-05-961-816, Ref:32-21-05, Ref:32-10-02, Task#:(CL300) 32-21-05-101*, Task#:(CL350) 32-21-05-104*										
Cylinder Trunnion Pin of the Nose Landing Gear										
32 A/F	Right		92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40631-1			1,813.2			Hrs	1,813.2			≈14-Apr-2061
12CPS0931			976			Ldg	976	15,000	15,000	92%
AMTOSS:(CL300) 32-21-05-961-810, AMTOSS:(CL350) 32-21-05-961-816, Ref:32-21-05, Ref:32-10-02, Task#:(CL300) 32-21-05-101*, Task#:(CL350) 32-21-05-104*										
Drag Brace Apex-Pin of the Nose Landing Gear										
32 A/F			92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
16404-1			1,813.2			Hrs	1,813.2			≈14-Apr-2061
12CPS2622			976			Ldg	976	15,000	15,000	92%
AMTOSS:(CL300) 32-21-13-961-801, AMTOSS:(CL350) 32-21-13-961-806, Ref:32-10-02, Ref:32-21-13, Task#:(CL300) 32-21-13-101*, Task#:(CL350) 32-21-13-106*										
Emergency/Parking Brake Accumulator (TLMC 32-44-05-101*)										
32 A/F			0			Mos	25-Nov-2013		RE	AWL - Life Limit
33-155500	New		0			Hrs	0			≈09-Sep-2042
60219-2409NAE			0			Ldg	0	8,300	8,300	85%
TLMC:32-44-05-101*,32-44-05										
Lower Drag Brace of the Nose Landing Gear										
32 A/F			92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40912-101			1,813.2			Hrs	1,813.2			≈14-Apr-2061
12EXC0463			976			Ldg	976	15,000	15,000	92%
AMTOSS:(CL350) 32-21-13-961-808, AMTOSS:(CL300) 32-21-13-961-804, Ref:32-20-09, Ref:32-10-02, Task#:(CL350) 32-21-13-108*, Task#:(CL300) 32-21-13-104*										
Lower Drag/Cylinder Pin of the Nose Landing Gear										
32 A/F			92			Mos	25-Jul-2021		RE	AWL - Life Limit, Standard
40615-1			1,813.2			Hrs	1,813.2			≈14-Apr-2061
12EXC0473			976			Ldg	976	15,000	15,000	92%
AMTOSS:31-21-13-961-802, Ref:32-21-13, Ref:32-10-02, Task#:32-21-13-102*										

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER, SN 20428

Total projection:

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
	Lower Pin of the Shock Strut of the Main Left						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40124-1		1,813.2		Hrs	1,813.2				
	12CPSI817		976		Ldg	976	15,000		15,000	92%
AMTOSS:32-11-05-961-805, Ref:32-10-01, Ref:32-11-05, Task#:32-11-05-104*										
	Lower Pin of the Shock Strut of the Main Right						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40124-1		1,813.2		Hrs	1,813.2				
	12CPSI814		976		Ldg	976	15,000		15,000	92%
AMTOSS:32-11-05-961-804, Ref:32-11-05, Ref:32-10-01, Task#:32-11-05-104*										
	Lower Pin of the Torque Link of the Nose Landing Gear						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40842-1		1,813.2		Hrs	1,813.2				
	12EXC1682		976		Ldg	976	15,000		15,000	92%
AMTOSS:(CL300) 32-21-05-961-808, AMTOSS:(CL350) 32-21-05-961-815, Ref:32-10-02, Ref:32-20-08, Task#:(CL300) 32-21-01-106*, Task#:(CL350) 32-21-01-109*										
	Lower Torque Link of the Nose Landing Gear						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40646-101		1,813.2		Hrs	1,813.2				
	12MER191126		976		Ldg	976	15,000		15,000	92%
Ref:32-20-08, Ref:32-21-01-104*										
	Main Fitting of the Main Landing Gear Left						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40140-101		1,813.2		Hrs	1,813.2				
	12SPP5291		976		Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-05-961-806, AMTOSS:(CH300) 32-11-05-961-801, Ref:32-11-05, Ref:32-10-01, Task#:(CL350) 32-11-01-104*, Task#:(CL300) 32-11-01-102*										
	Main Fitting of the Main Landing Gear Right						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40140-102		1,813.2		Hrs	1,813.2				
	12SPP5273		976		Ldg	976	15,000		15,000	92%
AMTOSS:(CH300) 32-11-05-961-801, AMTOSS:(CH350) 32-11-05-961-806, Ref:32-10-01, Ref:32-11-05, Task#:(CL300) 32-11-01-102*, Task#:(CL350) 32-11-01-104*										
	Pintle Pin of the Main Landing Gear Left						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40118-103		1,813.2		Hrs	1,813.2				
	12SPP1015		976		Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-01-961-802, AMTOSS:(CH300) 32-11-01-961-801, Ref:32-10-01, Ref:32-11-01, Task#:(CL300) 32-11-01-101*, Task#:(CL350) 32-11-01-103*										
	Pintle Pin of the Main Landing Gear Right						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F		92		Mos	25-Jul-2021				
	40118-104		1,813.2		Hrs	1,813.2				
	12SPP1046		976		Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-01-961-802, AMTOSS:(CH300) 32-11-01-961-801, Ref:32-10-01, Ref:32-11-01, Task#:(CL300) 32-11-01-101*, Task#:(CL350) 32-11-01-103*										
	Piston of the Nose Landing Gear						RE	AWL - Life Limit, Standard	≈14-Apr-2061	
	32 A/F				Mos	25-Jul-2021				
	40831-1		1,813.2		Hrs	1,813.2				
	12MBM00517		976		Ldg	976	15,000		15,000	92%
AMTOSS:32-21-05-961-802, Ref:32-10-02, Ref:32-20-08, Task#:32-21-05-103*										

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER, SN 20428

Total projection:

Task No		Description	Component Condition			Categories			Time
SEQ	PN/SN		TSNI	TSOI	TSRI	CW	REQ	TOL	Remaining
		Piston Tube Pin of the Nose Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F		92		Mos	25-Jul-2021			
	40672-1		1,813.2		Hrs	1,813.2			
	12EXC0528		976		Ldg	976	15,000	15,000	92%
		AMTOSS:32-21-01-105*, Ref:32-10-02, Ref:32-20-08							
		Pivot Pin of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Left	92		Mos	25-Jul-2021			
	40111-1		1,813.2		Hrs	1,813.2			
	12SPP0728		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH350) 32-11-09-961-803, AMTOSS:(CH300) 32-11-09-961-801, Ref:32-10-01, Ref:32-11-09, Task#:(CL300) 32-11-09-101*, Task#:(CL350) 32-11-09-103*							
		Pivot Pin of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Right	92		Mos	25-Jul-2021			
	40111-1		1,813.2		Hrs	1,813.2			
	12SPP0730		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH350) 32-11-09-961-803, AMTOSS:(CH300) 32-11-09-961-801, Ref:32-10-01, Ref:32-11-09, Task#:(CL300) 32-11-09-101*, Task#:(CL350) 32-11-09-103*,							
		Shock Strut Cylinder of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Left	92		Mos	25-Jul-2021			
	40405-101		1,813.2		Hrs	1,813.2			
	12SPP5457		976		Ldg	976	15,000	15,000	92%
		AMTOSS:32-11-05-961-803, Ref:32-10-01, Ref:32-10-18, Task#:32-11-05-102*							
		Shock Strut Cylinder of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Right	92		Mos	25-Jul-2021			
	40405-101		1,813.2		Hrs	1,813.2			
	12SPP5475		976		Ldg	976	15,000	15,000	92%
		AMTOSS:32-11-05-961-803, Ref:32-10-01, Ref:32-10-18, Task#:32-11-05-102*							
		Shock Strut Piston of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Left	92		Mos	25-Jul-2021			
	40415-101		1,813.2		Hrs	1,813.2			
	12SPP5429		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH350) 32-11-05-961-807, AMTOSS:(CH300) 32-11-05-961-802, Ref:32-10-01, Ref:32-10-18, Task#:(CL300) 32-11-05-101*, Task#:(CL350) 32-11-05-105*							
		Shock Strut Piston of the Main Landing Gear					RE	AWL - Life Limit, Standard	≈14-Apr-2061
	32 A/F	Right	92		Mos	25-Jul-2021			
	40415-101		1,813.2		Hrs	1,813.2			
	12SPP5428		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH350) 32-11-05-961-807, AMTOSS:(CH300) 32-11-05-961-802, Ref:32-10-01, Ref:32-10-18, Task#:(CL300) 32-11-05-101*, Task#:(CL350) 32-11-05-105*							
		Side Brace Cylinder of the Main Landing Gear					RE	AWL - Life Limit	≈14-Apr-2061
	32 A/F	Left	92		Mos	25-Jul-2021			
	40302-1		1,813.2		Hrs	1,813.2			
	928		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH300) 32-32-07-961-803, AMTOSS:(CH350) 32-32-07-961-807, Ref:32-11-00, Ref:32-10-01, Task#:(CL350) 32-11-17-107*, Task#:(CL300) 32-11-17-103*							
		Side Brace Cylinder of the Main Landing Gear					RE	AWL - Life Limit	≈14-Apr-2061
	32 A/F	Right	92		Mos	25-Jul-2021			
	40302-1		1,813.2		Hrs	1,813.2			
	390		976		Ldg	976	15,000	15,000	92%
		AMTOSS:(CH350) 32-32-07-961-807, AMTOSS:(CH300) 32-32-07-961-803, Ref:32-10-01, Ref:32-11-00, Task#:(CL300) 32-11-17-103*, Task#:(CL350) 32-11-17-107*							

Total projection:

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
Side Brace Piston of the Main Landing Gear										RE		AWL - Life Limit	≈14-Apr-2061
32 A/F		Left				92			Mos	25-Jul-2021			
40303-2						1,813.2			Hrs	1,813.2			
922						976			Ldg	976	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-808, AMTOSS:(CH300) 32-32-07-961-804, Ref:32-10-01, Ref:32-11-00, Task#:(CL300) 32-11-17-104*, Task#:(CL350) 32-11-17-108*													
Side Brace Piston of the Main Landing Gear										RE		AWL - Life Limit	≈14-Apr-2061
32 A/F		Right				92			Mos	25-Jul-2021			
40303-2						1,813.2			Hrs	1,813.2			
857						976			Ldg	976	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-808, AMTOSS:(CH300) 32-32-07-961-804, Ref:32-10-01, Ref:32-11-00, Task#:(CL300) 32-11-17-104*, Task#:(CL350) 32-11-17-108*													
Side-Brace Lower Pin of the Main Landing Gear										RE		AWL - Life Limit, Standard	≈14-Apr-2061
32 A/F		Left				92			Mos	25-Jul-2021			
40245-105						1,813.2			Hrs	1,813.2			
12SPP5198						976			Ldg	976	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-809, AMTOSS:(CH300) 32-32-07-961-805, Ref:32-10-01, Ref:32-11-01, Task#:(CL300) 32-11-17-105*, Task#:(CL350) 32-11-17-109*													
Side-Brace Lower Pin of the Main Landing Gear										RE		AWL - Life Limit, Standard	≈14-Apr-2061
32 A/F		Right				92			Mos	25-Jul-2021			
40245-106						1,813.2			Hrs	1,813.2			
12SPP5197						976			Ldg	976	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-809, AMTOSS:(CH300) 32-32-07-961-805, Ref:32-10-01, Ref:32-11-01, Task#:(CL300) 32-11-17-105*, Task#:(CL350) 32-11-17-109*													
Side-Brace Rod-End of the Main Landing Gear										RE		AWL - Life Limit	≈14-Apr-2061
32 A/F		Left				92			Mos	25-Jul-2021			
19400-1						1,813.2			Hrs	1,813.2			
0676						976			Ldg	976	15,000	15,000	92%
AMTOSS:32-32-07-961-801, Ref:32-11-00, Ref:32-10-01, Task#:32-11-17-101*													
Side-Brace Rod-End of the Main Landing Gear										RE		AWL - Life Limit	≈14-Apr-2061
32 A/F		Right				92			Mos	25-Jul-2021			
19400-1						1,813.2			Hrs	1,813.2			
0559						976			Ldg	976	15,000	15,000	92%
AMTOSS:32-32-07-961-801, Ref:32-10-01, Ref:32-11-00, Task#:32-11-17-101*													
Side-Brace Upper Pin of the Main Landing Gear										RE		AWL - Life Limit, Standard	≈14-Apr-2061
32 A/F		Left				0			Mos	25-Nov-2013			
40241-101		New				0			Hrs	0			
12EXC0883						0			Ldg	0	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-806, AMTOSS:(CH300) 32-32-07-961-802, Ref:32-10-01, Ref:32-32-07, Task#:(CL300) 32-11-17-102*, Task#:(CL350) 32-11-17-106*													
Side-Brace Upper Pin of the Main Landing Gear										RE		AWL - Life Limit, Standard	≈14-Apr-2061
32 A/F		Right				0			Mos	25-Nov-2013			
40241-101		New				0			Hrs	0			
12EXC0894						0			Ldg	0	15,000	15,000	92%
AMTOSS:(CH350) 32-32-07-961-806, AMTOSS:(CH300) 32-32-07-961-802, Ref:(CL300) 32-11-17-102*, Ref:(CL350) 32-11-17-106*, Ref:32-10-01, Ref:32-32-07													
Trailing Arm of the Main Landing Gear										RE		AWL - Life Limit, Standard	≈14-Apr-2061
32 A/F		Left				92			Mos	25-Jul-2021			
40142-101						1,813.2			Hrs	1,813.2			
12SPP5553						976			Ldg	976	15,000	15,000	92%
AMTOSS:(CH350) 32-11-09-961-804, AMTOSS:(CH300) 32-11-09-961-802, Ref:32-10-01, Ref:32-11-09, Task#:(CL300) 32-11-09-102*, Task#:(CL350) 32-11-09-104*													

Total projection:

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
		Trailing Arm of the Main Landing Gear										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40142-101						1,813.2		Hrs	1,813.2				
12SP552						976		Ldg	976	15,000		15,000	92%
AMTOSS:(CH350) 32-11-09-961-804, AMTOSS:(CH300) 32-11-09-961-802, Ref:32-10-01, Ref:32-11-09, Task#:(CL300) 32-11-09-102*, Task#:(CL350) 32-11-09-104*													
		Upper Drag Brace of the Nose Landing Gear										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40910-101						1,813.2		Hrs	1,813.2				
12MBM00491						976		Ldg	976	15,000		15,000	92%
AMTOSS:(CL300) 32-21-13-961-803, AMTOSS:(CL350) 32-21-13-961-807, Ref:32-10-02, Ref:32-20-09, Task#:(CL350) 32-21-13-107*, Task#:(CL300) 32-21-13-103*													
		Upper Pin of the Shock Strut of the Main										RE	AWL - Life Limit, Standard
		Left										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40124-1						1,813.2		Hrs	1,813.2				
12CPSI816						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-11-05-961-804, Ref:32-11-05, Ref:32-10-01, Task#:32-11-05-103*													
		Upper Pin of the Shock Strut of the Main										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40124-1						1,813.2		Hrs	1,813.2				
12CPS1813						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-11-05-961-804, Ref:32-11-05, Ref:32-10-01, Task#:32-11-05-103*													
		Upper Pin of the Torque Link on the Nose Landing Gear										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40637-1						1,813.2		Hrs	1,813.2				
12CPS0481						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-21-05-961-803, Ref:32-10-02, Ref:32-20-08, Task#:32-21-01-101*													
		Upper Torque Link of the Nose Landing Gear										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40644-103						1,813.2		Hrs	1,813.2				
12MER225908						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-21-05-961-805, Ref:32-10-02, Ref:32-20-08, Task#:32-21-01-103*													
		Upper Trunnion Pin of the Upper Drag Brace on the Nose Landing Gear										RE	AWL - Life Limit, Standard
		Left										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40914-1						1,813.2		Hrs	1,813.2				
12CPS1015						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-21-13-961-805, Ref:32-10-02, Ref:32-21-13, Task#:32-21-13-105*													
		Upper Trunnion Pin of the Upper Drag Brace on the Nose Landing Gear										RE	AWL - Life Limit, Standard
		Right										≈14-Apr-2061	
32 A/F						92		Mos	25-Jul-2021				
40914-1						1,813.2		Hrs	1,813.2				
12CPS1016						976		Ldg	976	15,000		15,000	92%
AMTOSS:32-21-13-961-805, Ref:30-10-02, Ref:32-21-13, Task#:32-21-13-105*													
32-11-00-208		Restoration (Overhaul) of the Main Landing Gear (MLG) Assembly										RE	MRB - Systems/Powerplant
		Left											
32 A/F								Mos		192	-/+1m	30-Nov-2029	29% (+0.5%)
Restored Date 30-Nov-2013								Hrs					
Alias1:320000-215, AMTOSS:32-11-00-280-803								Ldg					
32-11-00-208		Restoration (Overhaul) of the Main Landing Gear (MLG) Assembly										RE	MRB - Systems/Powerplant
		Right											
32 A/F								Mos		192	-/+1m	30-Nov-2029	29% (+0.5%)
Restored Date 30-Nov-2013								Hrs					
Alias1:320000-215, AMTOSS:32-11-00-280-803								Ldg					

Task No	Description	Categories	Time								
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining	
32-21-00-207 Restoration (Overhaul) of the Nose Landing Gear (NLG) Assembly											
	32 A/F				Mos		192	-/+1m	30-Nov-2029	29% (+0.5%)	
	Restored Date 30-Nov-2013				Hrs						
	Alias1:320000-213, AMTOSS:32-21-00-610-801				Ldg						
32-21-01-107* Discard the Apex Pin of the Torque Links of the Nose Landing Gear, Part No. 40950-1											
	32 A/F				Mos				RE	AWL - Life Limit, Standard	≈14-Apr-2061
					Hrs						
	Alias1:32-10-02, AMTOSS:32-21-05-961-809				Ldg		15,000		15,000	92%	
▼ 33 - LIGHTS											
33-51-17-201 Restoration (Bench Test) of the Emergency-Lighting Power Supplies											
	33 A/F	Aft			Mos	09-May-2022	18	-/+1m	30-Nov-2023	OVD	
	Restored Date 09-May-2022				Hrs	2,115					
	Alias1:335100-201, AMTOSS:33-51-00-720-801				Ldg	1,169					
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024										
33-51-17-201 Restoration (Bench Test) of the Emergency-Lighting Power Supplies											
	33 A/F	Fwd			Mos	09-May-2022	18	-/+1m	30-Nov-2023	OVD	
	Restored Date 09-May-2022				Hrs	2,115					
	Alias1:335100-201, AMTOSS:33-51-00-720-801				Ldg	1,169					
	0ER-WP-001 / WO# 2024127 START 18-JAN-2024										
▼ 34 - NAVIGATION											
Pitot-Static Probe											
	34 A/F	Left						RE	AWL - Life Limit (RVSM), RVSM	≈16-May-2043	
	0856WC1	New		0	Mos	25-Nov-2013					
	281109			0	Hrs	0	9,600		9,600	76%	
	AMTOSS:34-11-01-961-801, TLMC:34-11-00-101*			0	Ldg	0					
Pitot-Static Probe											
	34 A/F	Right						RE	AWL - Life Limit (RVSM), RVSM	≈16-May-2043	
	0856WC2	New		0	Mos	25-Nov-2013					
	28114			0	Hrs	0	9,600		9,600	76%	
	AMTOSS:34-11-01-961-801, TLMC:34-11-00-101*			0	Ldg	0					
▼ 35 - OXYGEN											
Oxygen Storage Cylinder (115 Cu. Ft.)											
	35 A/F	Aft						RE	AWL - Life Limit, MRB - Systems/Powerplant		
	806371-111				Mos	17-Nov-2017	180		30-Jun-2028	22%	
	C13080336			1,045.6	Hrs	1,045.6					
	Manufactured Date 01-Jun-2013			584	Ldg	584					
	AMTOSS:35-11-05-961-801, TLMC:35-11-05-101*,350000-202,35-00-00										
Oxygen Storage Cylinder (77 Cu. Ft.)											
	35 A/F	Fwd						RE	AWL - Life Limit, MRB - Systems/Powerplant		
	806371-121				Mos	17-Nov-2017	180		31-Jul-2028	22%	
	C13080382			1,045.6	Hrs	1,045.6					
	Manufactured Date 01-Jul-2013			584	Ldg	584					
	AMTOSS:35-11-01-961-801, TLMC:35-11-01-101*,350000-202,35-00-00										
35-11-07-202 Restoration (Overhaul) of the Crew Oxygen Mask											
	35 A/F	Left			Mos	16-Mar-2022	72	-/+1m	31-Mar-2028	50% (+1.4%)	
	Restored Date 16-Mar-2022				Hrs						
	Alias1:350000-204, AMTOSS:35-11-07-610-801				Ldg						
35-11-07-202 Restoration (Overhaul) of the Crew Oxygen Mask											
	35 A/F	Right			Mos	15-Mar-2022	72	-/+1m	31-Mar-2028	50% (+1.4%)	
	Restored Date 15-Mar-2022				Hrs						
	Alias1:350000-204, AMTOSS:35-11-07-610-801				Ldg						

Total projection:

Challenger 300 N300ER,SN 20428

Task No	Description	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN								DUE	Remaining
351107-7201B		Restoration of Crew PBE, Personal Breathing Unit (35-00-00-605)							RE	STLMC, BCCM
	35 A/F	Aft Lavatory				Mos	06-Jul-2016	120	31-Jul-2026	13%
		Restored Date 06-Jul-2016				Hrs				
		AMTOSS:35-30-00-610-801				Ldg				
351107-7201C		Discard of Crew PBE, Personal Breathing Unit (35-00-00-606)							RE	
	35 A/F	Aft Lavatory				Mos	06-Jul-2016	240	31-Jul-2036	57%
						Hrs				
						Ldg				
▼ 36 - PNEUMATIC										
		Uroseal Connector Assy (Flexible Joint)							RE	AWL - Life Limit
	36 A/F		0			Mos	25-Nov-2013			≈07-Dec-2038
	GG468-4054-19	New	0			Hrs	0	8,000	8,000	71%
	4967		0			Ldg	0			
		Alias1:36-11-49-101*,36-11-49								
▼ 49 - AIRBORNE AUXILIARY POWER										
		APU Compressor Rotor							RE	AWL - Life Limit, MRB - Systems/Powerplant
	49 APU1		0			Mos	03-Jun-2013			≈21-Jan-2189
	3822101-1		0			Hrs	0	100,000	100,000	98%
	12-162053-51987		0			APUS	0			
		AMTOSS:49-20-00-961-803, MSG-3:492200-201, SIL:APU-56, TLMC:49-20-00-101*, TLMC:49-20-00-202								
		APU Turbine Rotor							RE	AWL - Life Limit, MRB - Systems/Powerplant
	49 APU1		0			Mos	03-Jun-2013			≈15-Jun-2045
	3615880-002		0			Hrs	0	10,000	10,000	80%
	12-156101-11905		0			APUS	0			
		AMTOSS:49-20-00-961-804, MSG-3:492400-201, SIL:APU-56, TLMC:49-20-00-102*, TLMC:49-20-00-204								
▼ 52 - DOORS										
		Passenger Door Actuator (Cable)							RE	AWL - Life Limit
	52 A/F		0			Mos	25-Nov-2013			≈19-Jun-2040
	Unknown		0			Hrs	0			
	Unknown		0			Ldg	0	7,500	7,500	83%
		Alias1:52-11-25-101*,52-11-25								
▼ 54 - NACELLES/PYLONS										
		Aft Engine-Thrust-Link Bolt							RE	AWL - Life Limit
	54 A/F	Left	0			Mos	25-Nov-2013			≈19-Jun-2040
	1005451658-005	New	0			Hrs	0			
	4049		0			Ldg	0	7,500	7,500	83%
		Alias1:54-51-00-109*,54-51-104,54-51-00, AMTOSS:54-51-00-961-803								
		Aft Engine-Thrust-Link Bolt							RE	AWL - Life Limit
	54 A/F	Right	0			Mos	25-Nov-2013			≈19-Jun-2040
	1005451658-005	New	0			Hrs	0			
	4050		0			Ldg	0	7,500	7,500	83%
		Alias1:54-51-00-109*,54-51-104,54-51-00, AMTOSS:54-51-00-961-803								
		Forward Engine-Thrust-Link Bolt							RE	AWL - Life Limit
	54 A/F	Lower - Left	0			Mos	25-Nov-2013			≈19-Jun-2040
	1005451657-005	New	0			Hrs	0			
	4157		0			Ldg	0	7,500	7,500	83%
		Alias1:54-51-00-108*,54-51-104,54-51-00, AMTOSS:54-51-00-961-802								

Total projection:

Challenger 300 N300ER,SN 20428

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	Component	Condition					DUE	Remaining	
⚙	54 A/F		Forward Engine-Thrust-Link Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451657-005		Lower - Right	0	Mos	25-Nov-2013				
	4159		New	0	Hrs	0				
	Alias1:54-51-00-108*,54-51-104,54-51-00, AMTOSS:54-51-00-961-802			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Forward Engine-Thrust-Link Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451657-005		Upper - Left	0	Mos	25-Nov-2013				
	4156		New	0	Hrs	0				
	Alias1:54-51-00-108*,54-51-104,54-51-00, AMTOSS:54-51-00-961-802			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Forward Engine-Thrust-Link Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451657-005		Upper - Right	0	Mos	25-Nov-2013				
	4158		New	0	Hrs	0				
	Alias1:54-51-00-108*,54-51-104,54-51-00, AMTOSS:54-51-00-961-802			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Rear Engine Mount Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451659-003		Lower - Left	0	Mos	25-Nov-2013				
	4196		New	0	Hrs	0				
	Alias1:54-51-00-107*,54-51-104,54-51-00, AMTOSS:54-51-00-961-801			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Rear Engine Mount Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451659-003		Lower - Right	0	Mos	25-Nov-2013				
	4250		New	0	Hrs	0				
	Alias1:54-51-00-107*,54-51-104,54-51-00, AMTOSS:54-51-00-961-801			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Rear Engine Mount Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451659-003		Upper - Left	0	Mos	25-Nov-2013				
	4296		New	0	Hrs	0				
	Alias1:54-51-00-107*,54-51-104,54-51-00, AMTOSS:54-51-00-961-801			0	Ldg	0	7,500	7,500	83%	
⚙	54 A/F		Rear Engine Mount Bolt					RE	AWL - Life Limit	≈19-Jun-2040
	1005451659-003		Upper - Right	0	Mos	25-Nov-2013				
	4298		New	0	Hrs	0				
	Alias1:54-51-00-107*,54-51-104,54-51-00, AMTOSS:54-51-00-961-801			0	Ldg	0	7,500	7,500	83%	
▼ 55 - STABILIZERS										
⚙	55 A/F		Vertical Stabilizer Pitch Trim Bolt					RE	Life Limit	≈19-Jun-2040
	Unknown			0	Mos	25-Nov-2013				
	Unknown			0	Hrs	0				
				0	Ldg	0	7,500	7,500	83%	
▼ 57 - WINGS										
⚙	57 A/F		Bolt (Aft Link, Left Outboard)					RE	AWL - Life Limit	≈19-Jun-2040
	Unknown		Lower	0	Mos	25-Nov-2013				
	Unknown			0	Hrs	0				
	AMTOSS:57-51-03-961-807, Ref:57-50-102, TLMC:57-51-00-122*			0	Ldg	0	7,500	7,500	83%	
⚙	57 A/F		Bolt (Aft Link, Left Outboard)					RE	AWL - Life Limit	≈19-Jun-2040
	Unknown		Upper	0	Mos	25-Nov-2013				
	Unknown			0	Hrs	0				
	AMTOSS:57-51-03-961-807, Ref:57-50-102, TLMC:57-51-00-122*			0	Ldg	0	7,500	7,500	83%	

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
	57 A/F	Bolt (Aft Link, Right Outboard) Lower	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	Unknown		0		Hrs	0				
	Unknown		0		Ldg	0	7,500		7,500	83%
	AMTOSS:57-51-03-961-807, Ref:57-50-102, TLMC:57-51-00-122*									
	57 A/F	Bolt (Aft Link, Right Outboard) Upper	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	Unknown		0		Hrs	0				
	Unknown		0		Ldg	0	7,500		7,500	83%
	AMTOSS:57-51-03-961-807, Ref:57-50-102, TLMC:57-51-00-122*									
	57 A/F	Bolt, Spoiler No.1	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771409-001	New	0		Hrs	0				
	STR0667		0		Ldg	0	7,500		7,500	83%
	Alias1:57-71-00, TLMC:57-71-00-107*									
	57 A/F	Bolt, Spoiler No.2	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771409-001	New	0		Hrs	0				
	STR0665		0		Ldg	0	7,500		7,500	83%
	Alias1:57-71-00, TLMC:57-71-00-107*									
	57 A/F	Bolt, Spoiler No.3	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771409-001	New	0		Hrs	0				
	STR0655		0		Ldg	0	7,500		7,500	83%
	Alias1:57-71-00, TLMC:57-71-00-107*									
	57 A/F	Bolt, Spoiler No.4	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771409-001	New	0		Hrs	0				
	STR0649		0		Ldg	0	7,500		7,500	83%
	Alias1:57-71-00, TLMC:57-71-00-107*									
	57 A/F	Bolt, Spoiler No.5	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771410-001	New	0		Hrs	0				
	12CAM0483		0		Ldg	0	7,500		7,500	83%
	Alias1:57-72-00, TLMC:57-72-00-114*									
	57 A/F	Bolt, Spoiler No.6	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771410-001	New	0		Hrs	0				
	12CAM0455		0		Ldg	0	7,500		7,500	83%
	Alias1:57-72-00, TLMC:57-72-00-114*									
	57 A/F	Bolt, Spoiler No.7	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771410-001	New	0		Hrs	0				
	12CAM0442		0		Ldg	0	7,500		7,500	83%
	Alias1:57-72-00, TLMC:57-72-00-116*									
	57 A/F	Bolt, Spoiler No.8	0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
	1005771410-001	New	0		Hrs	0				
	12CAM0484		0		Ldg	0	7,500		7,500	83%
	Alias1:57-72-00, TLMC:57-72-00-116*									

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER,SN 20428

Total projection:

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
Center Support-Link Assembly of the Flap										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		Aft - Left				0			Mos	25-Nov-2013			
1005751391N500101		New				0			Hrs	0			
81988-08						0			Ldg	0	7,500	7,500	83%
TLMC:57-51-00-116*,57-51-00													
Center Support-Link Assembly of the Flap										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		Aft - Right				0			Mos	25-Nov-2013			
1005751391N500101		New				0			Hrs	0			
81988-24						0			Ldg	0	7,500	7,500	83%
TLMC:57-51-00-116*,57-51-00													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.1				0			Mos	25-Nov-2013			
1005731115-001		New				0			Hrs	0			
KS0740						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802(CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.2				0			Mos	25-Nov-2013			
1005731115-001		New				0			Hrs	0			
KS0752						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.3				0			Mos	25-Nov-2013			
1005731115-001		New				0			Hrs	0			
KS0744						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.4				0			Mos	25-Nov-2013			
1005731115-001		New				0			Hrs	0			
KS0758						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.5				0			Mos	25-Nov-2013			
1005731115-003		New				0			Hrs	0			
KS0742						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.6				0			Mos	25-Nov-2013			
1005731115-003		New				0			Hrs	0			
KS0765						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.7				0			Mos	25-Nov-2013			
1005731115-003		New				0			Hrs	0			
KS0789						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-801(CH 300), AMTOSS:57-31-01-961-802 (CH 350), TLMC:57-20-00-103*													
Discard the Wing-to-Winglet Pins/Bolts. NOTE: This task is applicable to Part Numbers: 1005731115-001 Serialized and 1005731115-003 Serialized.										RE		AWL - Life Limit	≈19-Jun-2040
57 A/F		No.8				0			Mos	25-Nov-2013			
1005731115-003		New				0			Hrs	0			
KS0811						0			Ldg	0	7,500	7,500	83%
AMTOSS:57-31-01-961-802 (CH 350), AMTOSS:57-31-01-961-801(CH 300), TLMC:57-20-00-103*													

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER,SN 20428

Total projection:

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	57 A/F Unknown Unknown	Flap Aft Link Lower Bolt Left Inboard				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Lower Bolt Left Mid				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Lower Bolt Right Inboard				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Lower Bolt Right Mid				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Upper Bolt Left Inboard				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Upper Bolt Left Mid				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Upper Bolt Right Inboard				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F Unknown Unknown	Flap Aft Link Upper Bolt Right Mid				0		Mos	25-Nov-2013			RE	≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%
	57 A/F 1005751419-005 STR0299 Alias1:57-51-03-101*,57-50-101,57-51-03, AMTOSS:57-51-03-961-804, AMTOSS:57-51-03-961-808 (CH 350)	Inboard Support Spigot of the Flap Left New				0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈24-Jan-2033
						0		Hrs	0				
						0		Ldg	0	4,832		4,832	74%
	57 A/F 1005751419-005 STR0294 Alias1:57-51-03-101*,57-50-101,57-51-03, AMTOSS:57-51-03-961-808 (CH 350), AMTOSS:57-51-03-961-804	Inboard Support Spigot of the Flap Right New				0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈24-Jan-2033
						0		Hrs	0				
						0		Ldg	0	4,832		4,832	74%
	57 A/F 1005751390N500101 81895-B AMTOSS:57-51-00-961-803, TLMC:57-51-00-118*,57-51-00	Inboard Support-Link Assembly of the Flap Fwd - Left New				0		Mos	25-Nov-2013			RE	AWL - Life Limit ≈19-Jun-2040
						0		Hrs	0				
						0		Ldg	0	7,500		7,500	83%

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Challenger 300 N300ER, SN 20428

Total projection:

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
Inboard Support-Link Assembly of the Flap										
57 A/F		Fwd - Right	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751390N500101		New	0		Hrs	0				≈19-Jun-2040
81895-S			0		Ldg	0	7,500		7,500	83%
AMTOSS:57-51-00-961-803, TLMC:57-51-00-118*,57-51-00										
Mid Support Spigot of the Flap										
57 A/F		Left	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751429-005		New	0		Hrs	0				≈24-Jan-2033
STR0319			0		Ldg	0	4,832		4,832	74%
Alias1:57-51-03-102*,57-50-101,57-51-03, AMTOSS:57-51-03-961-805(CH 300), AMTOSS:57-51-03-961-808(CH 350)										
Mid Support Spigot of the Flap										
57 A/F		Right	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751429-005		New	0		Hrs	0				≈24-Jan-2033
STR0330			0		Ldg	0	4,832		4,832	74%
Alias1:57-51-03-102*,57-50-101,57-51-03, AMTOSS:57-51-03-961-808(CH 350), AMTOSS:57-51-03-961-805(CH 300)										
Outboard Support Spigot of the Flap										
57 A/F		Left	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751439-005		New	0		Hrs	0				≈24-Jan-2033
STR0220			0		Ldg	0	4,832		4,832	74%
Alias1:57-51-03-103*,57-50-101,57-51-03, AMTOSS:57-51-03-961-806 (CH 300), AMTOSS:57-51-03-961-810(CH 350)										
Outboard Support Spigot of the Flap										
57 A/F		Right	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751439-005		New	0		Hrs	0				≈24-Jan-2033
STR0218			0		Ldg	0	4,832		4,832	74%
Alias1:57-51-03-103*,57-50-101,57-51-03, AMTOSS:57-51-03-961-806 (CH 300), AMTOSS:57-51-03-961-810(CH 350)										
Outboard Support-Link Assembly of the Flap										
57 A/F		Left	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751392N500101		New	0		Hrs	0				≈19-Jun-2040
82107-14			0		Ldg	0	7,500		7,500	83%
AMTOSS:57-51-00-961-802, TLMC:57-51-00-117*,57-51-00										
Outboard Support-Link Assembly of the Flap										
57 A/F		Right	0		Mos	25-Nov-2013			RE	AWL - Life Limit
1005751392N500101		New	0		Hrs	0				≈19-Jun-2040
82107-24			0		Ldg	0	7,500		7,500	83%
AMTOSS:57-51-00-961-802, TLMC:57-51-00-117*,57-51-00										
575100-0701 Flap (Carriage To Flap Fitting) Bolt										
57 A/F		Left Inboard	0		Mos	25-Nov-2013			RE	≈19-Jun-2040
Unknown			0		Hrs	0				
Unknown			0		Ldg	0	7,500		7,500	83%
575100-0702 Flap (Carriage To Flap Fitting) Bolt										
57 A/F		Right Inboard	0		Mos	25-Nov-2013			RE	≈19-Jun-2040
Unknown			0		Hrs	0				
Unknown			0		Ldg	0	7,500		7,500	83%
575100-0703 Mid Flap (Carriage To Flap Fitting) Bolt										
57 A/F		Left	0		Mos	25-Nov-2013			RE	≈19-Jun-2040
Unknown			0		Hrs	0				
Unknown			0		Ldg	0	7,500		7,500	83%

Task No		Description					Categories		Time	
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
575100-0704	 57 A/F Unknown Unknown	Mid Flap (Carriage To Flap Fitting) Bolt Right					RE			≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
575100-0801	 57 A/F Unknown Unknown	Flap (Carriage To Flap Fitting) Bolt Left Outboard					RE			≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
575100-0802	 57 A/F Unknown Unknown	Flap (Carriage To Flap Fitting) Bolt Right Outboard					RE			≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
▼ 71 - POWER PLANT										
	71 A/F WBA7122E014-101 H0517 Alias1:71-21-00-106*,71-22-101,71-21-00, AMTOSS:71-20-05-961-801	Bolts of the Aft Engine Mount Lower - Left New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F WBA7122E014-101 H0610 Alias1:71-21-00-106*,71-22-101,71-21-00, AMTOSS:71-20-05-961-801	Bolts of the Aft Engine Mount Lower - Right New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F WBA7122E014-101 H0618 Alias1:71-21-00-106*,71-22-101,71-21-00, AMTOSS:71-20-05-961-801	Bolts of the Aft Engine Mount Upper - Left New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F WBA7122E014-101 H0645 Alias1:71-21-00-106*,71-22-101,71-21-00, AMTOSS:71-20-05-961-801	Bolts of the Aft Engine Mount Upper - Right New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F 1005451660-003 3176 Alias1:71-21-00-107*,54-51-104,71-21-00, AMTOSS:71-20-01-961-805	Forward Engine-Mount Bolt Lower - Left New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F 1005451660-003 1057 Alias1:71-21-00-107*,54-51-104,71-21-00, AMTOSS:71-20-01-961-805	Forward Engine-Mount Bolt Lower - Right New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	
	71 A/F 1005451660-003 3401 Alias1:71-21-00-107*,54-51-104,71-21-00, AMTOSS:71-20-01-961-805	Forward Engine-Mount Bolt Upper - Left New					RE		AWL - Life Limit	≈19-Jun-2040
			0		Mos	25-Nov-2013				
			0		Hrs	0				
			0		Ldg	0	7,500	7,500	83%	

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			Categories			Time	
SEQ	PN/SN		TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
		Forward Engine-Mount Bolt					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		Upper - Right	0		Mos	25-Nov-2013				
1005451660-003		New	0		Hrs	0				
3327			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-107*,54-51-104,71-21-00, AMTOSS:71-20-01-961-805										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.1	0		Mos	25-Nov-2013				
WBA7121E015-109		New	0		Hrs	0				
6014			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-104*,71-21-101, AMTOSS:71-20-01-961-801										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.2	0		Mos	25-Nov-2013				
WBA7121E016-105		New	0		Hrs	0				
5894			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-105*,71-21-101, AMTOSS:71-20-01-961-802										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.3	0		Mos	25-Nov-2013				
WBA7121E015-109		New	0		Hrs	0				
5968			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-104*,71-21-101, AMTOSS:71-20-01-961-801										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.4	0		Mos	25-Nov-2013				
WBA7121E016-105		New	0		Hrs	0				
5858			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-105*,71-21-101, AMTOSS:71-20-01-961-802										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.5	0		Mos	25-Nov-2013				
WBA7121E014-107		New	0		Hrs	0				
6033			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-103*,71-21-101, AMTOSS:71-20-01-961-803										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.6	0		Mos	25-Nov-2013				
WBA7121E015-109		New	0		Hrs	0				
5947			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-104*,71-21-101, AMTOSS:71-20-01-961-801										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.7	0		Mos	25-Nov-2013				
WBA7121E014-107		New	0		Hrs	0				
6027			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-103*,71-21-101, AMTOSS:71-20-01-961-803										
		Yoke Bolt of the Engine Mount Fitting					RE		AWL - Life Limit	≈19-Jun-2040
71 A/F		No.8	0		Mos	25-Nov-2013				
WBA7121E015-109		New	0		Hrs	0				
5929			0		Ldg	0	7,500		7,500	83%
Alias1:71-21-00-104*,71-21-101, AMTOSS:71-20-01-961-801										
▼ 72 - ENGINE										
		Centrifugal Compressor Rotor (Impeller)					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1			0		Mos	26-May-2013				
3033182-2		New	0		Hrs	0				
12-182449-06768			0		Enc	0	15,000		15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
Centrifugal Compressor Rotor (Impeller)											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3033182-2	New				0			Mos	30-May-2013				
12-162246-06023						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Fan Disk											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3037077-2	New				0			Mos	26-May-2013				
12-182449-07261						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Fan Disk											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3037077-2	New				0			Mos	30-May-2013				
12-182449-06569						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Fan Seal Plate											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3037079-1	New				0			Mos	26-May-2013				
12-156138-02113						0			Hrs	0				
AMTOSS:72-70-20-907						0			Enc	0	15,000		15,000	92%
Fan Seal Plate											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3037079-1	New				0			Mos	30-May-2013				
13-156138-00178						0			Hrs	0				
AMTOSS:72-70-20-907						0			Enc	0	15,000		15,000	92%
Fan Stub Shaft											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3037099-1	New				0			Mos	26-May-2013				
12-102045-00640						0			Hrs	0				
AMTOSS:72-70-25-907						0			Enc	0	15,000		15,000	92%
Fan Stub Shaft											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3037099-1	New				0			Mos	30-May-2013				
12-102045-00661						0			Hrs	0				
AMTOSS:72-70-25-907						0			Enc	0	15,000		15,000	92%
HP Forward Coupler											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3033133-2	New				0			Mos	26-May-2013				
13-1034-38321						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
HP Forward Coupler											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3033133-2	New				0			Mos	30-May-2013				
13-1034-38317						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
HP Shaft														
											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3033084-4	New				0			Mos	26-May-2013				
12-102045-00304						0			Hrs	0				
AMTOSS:72-50-10-907						0			Enc	0	15,000		15,000	92%
HP Shaft														
											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3033084-4	New				0			Mos	30-May-2013				
12-102045-00307						0			Hrs	0				
AMTOSS:72-50-10-907						0			Enc	0	15,000		15,000	92%
HPT Interstage Seal														
											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035134-1	New				0			Mos	26-May-2013				
12-162045-01277						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
HPT Interstage Seal														
											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035134-1	New				0			Mos	30-May-2013				
12-162045-01259						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
HPT1 Blade														
											RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.1				0			Mos	26-May-2013				
12M65040		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
HPT1 Blade														
											RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.1				0			Mos	30-May-2013				
12M60440		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
HPT1 Blade														
											RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.10				0			Mos	26-May-2013				
12M68576		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
HPT1 Blade														
											RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.10				0			Mos	30-May-2013				
12M61204		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
HPT1 Blade														
											RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.11				0			Mos	26-May-2013				
12M68577		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035114-6 12M61205	No.11 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035114-6 12M68917	No.12 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035114-6 12M61207	No.12 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035114-6 12M68924	No.13 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035114-6 12M61280	No.13 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035114-6 12M68928	No.14 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035114-6 12M61281	No.14 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035114-6 12M70316	No.15 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035114-6 12M61282	No.15 New	HPT1 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.16				0			Mos	26-May-2013			
	12M70322	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.16				0			Mos	30-May-2013			
	12M61284	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.17				0			Mos	26-May-2013			
	12M70330	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.17				0			Mos	30-May-2013			
	12M61285	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.18				0			Mos	26-May-2013			
	12M70347	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.18				0			Mos	30-May-2013			
	12M61286	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.19				0			Mos	26-May-2013			
	12M70351	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035114-6	No.19				0			Mos	30-May-2013			
	12M61287	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035114-6	No.2				0			Mos	26-May-2013			
	12M67575	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035114-6 12M61013	No.2 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035114-6 12M70356	No.20 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035114-6 12M61288	No.20 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035114-6 12M71922	No.21 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035114-6 12M61289	No.21 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035114-6 12M71928	No.22 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035114-6 12M61291	No.22 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035114-6 12M71935	No.23 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035114-6 12M61293	No.23 New	HPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035114-6 12M71938	HPT1 Blade No.24 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	26-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG2 3035114-6 12M61294	HPT1 Blade No.24 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	30-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG1 3035114-6 12M71939	HPT1 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	26-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG2 3035114-6 12M61295	HPT1 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	30-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG1 3035114-6 12M71947	HPT1 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	26-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG2 3035114-6 12M61297	HPT1 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	30-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG1 3035114-6 12M71949	HPT1 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	26-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG2 3035114-6 12M67647	HPT1 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	30-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					
	72 ENG1 3035114-6 12M71951	HPT1 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
				0		Mos	26-May-2013						
				0		Hrs		0	15,000		15,000	85%	
				0		Enc		0					

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035114-6 12M68478	HPT1 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035114-6 12M71952	HPT1 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035114-6 12M68514	HPT1 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035114-6 12M68499	HPT1 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035114-6 12M61014	HPT1 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035114-6 12M71955	HPT1 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035114-6 12M68557	HPT1 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035114-6 12M71958	HPT1 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035114-6 12M68584	HPT1 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	No.32					0		Mos	26-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M72897						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	No.32					0		Mos	30-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M68600						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	No.33					0		Mos	26-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M72905						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	No.33					0		Mos	30-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M69414						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	No.34					0		Mos	26-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M72906						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	No.34					0		Mos	30-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M71948						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	No.35					0		Mos	26-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
13M00131						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	No.35					0		Mos	30-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
12M89946						0		Enc	0				
HPT1 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	No.36					0		Mos	26-May-2013				
3035114-6	New					0		Hrs	0	15,000		15,000	85%
13M00133						0		Enc	0				

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035114-6 13M06492	HPT1 Blade No.36 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035114-6 13M06476	HPT1 Blade No.37 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035114-6 13M06514	HPT1 Blade No.37 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035114-6 13M06505	HPT1 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035114-6 13M06526	HPT1 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035114-6 12M68506	HPT1 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035114-6 12M61196	HPT1 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035114-6 12M68512	HPT1 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035114-6 12M61197	HPT1 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035114-6 12M68515	No.6 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035114-6 12M61199	No.6 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035114-6 12M68525	No.7 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035114-6 12M61200	No.7 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035114-6 12M68554	No.8 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035114-6 12M61201	No.8 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035114-6 12M68575	No.9 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035114-6 12M61202	No.9 New	HPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035136-3 13-182449-07817	New	HPT1 Disk							RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
			0						Mos	26-May-2013			
			0						Hrs	0			
			0						Enc	0	15,000	15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
HPT1 Disk										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035136-3	New				0			Mos	30-May-2013			
13-182449-08111						0			Hrs	0			
						0			Enc	0	15,000	15,000	92%
HPT1 Seal Plate										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035124-1	New				0			Mos	26-May-2013			
12-182449-07515						0			Hrs	0			
AMTOSS:72-50-00-203						0			Enc	0	15,000	15,000	92%
HPT1 Seal Plate										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035124-1	New				0			Mos	30-May-2013			
12-182449-07511						0			Hrs	0			
AMTOSS:72-50-00-203						0			Enc	0	15,000	15,000	92%
HPT1 Seal Plate Coupler (Drive Arm)										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035030-3	New				0			Mos	26-May-2013			
13-182449-08367						0			Hrs	0			
AMTOSS:72-50-30-907						0			Enc	0	15,000	15,000	92%
HPT1 Seal Plate Coupler (Drive Arm)										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035030-3	New				0			Mos	30-May-2013			
12-162246-05384						0			Hrs	0			
AMTOSS:72-50-30-907						0			Enc	0	15,000	15,000	92%
HPT2 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035049-5	No.1				0			Mos	26-May-2013			
12M72040		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT2 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035049-5	No.1				0			Mos	30-May-2013			
12M84903		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT2 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035049-5	No.10				0			Mos	26-May-2013			
12M93244		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
HPT2 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035049-5	No.10				0			Mos	30-May-2013			
12M84955		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035049-5 12M93273	No.11 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M89126	No.11 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 13M07409	No.12 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M89130	No.12 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 13M07416	No.13 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M89137	No.13 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 13M07417	No.14 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M89142	No.14 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 13M07419	No.15 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035049-5 12M89152	No.15 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M07672	No.16 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M89173	No.16 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M08712	No.17 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M90407	No.17 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M08713	No.18 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M91947	No.18 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M08720	No.19 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M91954	No.19 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description											Categories		Time
SEQ	PN/SN	Component	Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE					Remaining
	72 ENG1 3035049-5 12M89150	No.2 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	26-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG2 3035049-5 12M84904	No.2 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	30-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG1 3035049-5 13M08845	No.20 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	26-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG2 3035049-5 12M91968	No.20 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	30-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG1 3035049-5 13M08852	No.21 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	26-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG2 3035049-5 12M91976	No.21 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	30-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG1 3035049-5 13M08883	No.22 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	26-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG2 3035049-5 12M91989	No.22 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	30-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							
	72 ENG1 3035049-5 13M08918	No.23 New	HPT2 Blade					RE	LMM 05-20-00	Recommended Replacement					≈11-May-2058
				0		Mos	26-May-2013								
				0		Hrs		0	15,000		15,000		85%		
				0		Enc		0							

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035049-5 12M93219	No.23 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M08937	No.24 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M93226	No.24 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M09188	No.25 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 12M93252	No.25 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M09189	No.26 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 13M08907	No.26 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035049-5 13M09868	No.27 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035049-5 13M08911	No.27 New	HPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035049-5 13M10510	HPT2 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035049-5 13M08912	HPT2 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035049-5 13M10512	HPT2 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035049-5 13M08913	HPT2 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035049-5 12M90372	HPT2 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035049-5 12M84905	HPT2 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035049-5 13M10513	HPT2 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035049-5 13M08924	HPT2 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035049-5 13M10514	HPT2 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035049-5 13M08925	HPT2 Blade No.31 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035049-5 13M10516	HPT2 Blade No.32 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035049-5 13M09820	HPT2 Blade No.32 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035049-5 13M10518	HPT2 Blade No.33 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035049-5 13M10338	HPT2 Blade No.33 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035049-5 13M10519	HPT2 Blade No.34 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035049-5 13M10515	HPT2 Blade No.34 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035049-5 12M91925	HPT2 Blade No.4 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035049-5 12M84910	HPT2 Blade No.4 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035049-5 12M93224	No.5 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M84912	No.5 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 12M93225	No.6 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M84922	No.6 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 12M93235	No.7 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M84938	No.7 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 12M93236	No.8 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035049-5 12M84949	No.8 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035049-5 12M93239	No.9 New	HPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
HPT2 Blade														
⚙	72 ENG2	No.9				0				Mos	30-May-2013			
	3035049-5	New				0				Hrs	0	15,000	15,000	85%
	12M84950					0				Enc	0			
HPT2 Coupler														
⚙	72 ENG1					0				Mos	26-May-2013			
	3035053-2	New				0				Hrs	0			
	13-1034-37992					0				Enc	0	15,000	15,000	92%
	AMTOSS:72-50-90-907													
HPT2 Coupler														
⚙	72 ENG2					0				Mos	30-May-2013			
	3035053-2	New				0				Hrs	0			
	13-1034-37520					0				Enc	0	15,000	15,000	92%
	AMTOSS:72-50-90-907													
HPT2 Disk														
⚙	72 ENG1					0				Mos	26-May-2013			
	3035123-1	New				0				Hrs	0			
	12-182449-07416					0				Enc	0	15,000	15,000	92%
HPT2 Disk														
⚙	72 ENG2					0				Mos	30-May-2013			
	3035123-1	New				0				Hrs	0			
	13-182449-07887					0				Enc	0	15,000	15,000	92%
HPT2 Seal Plate														
⚙	72 ENG1					0				Mos	26-May-2013			
	3035109-1	New				0				Hrs	0			
	12-162246-06199					0				Enc	0	15,000	15,000	92%
	AMTOSS:72-50-00-203													
HPT2 Seal Plate														
⚙	72 ENG2					0				Mos	30-May-2013			
	3035109-1	New				0				Hrs	0			
	12-182449-06805					0				Enc	0	15,000	15,000	92%
	AMTOSS:72-50-00-203													
LPT Drive Arm														
⚙	72 ENG1					0				Mos	26-May-2013			
	3035610-2	New				0				Hrs	0			
	12-182449-07158					0				Enc	0	15,000	15,000	92%
LPT Drive Arm														
⚙	72 ENG2					0				Mos	30-May-2013			
	3035610-2	New				0				Hrs	0			
	12-162246-02875					0				Enc	0	15,000	15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
LPT Shaft												RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035689-1	New				0			Mos	26-May-2013				
13-182476-11013						0			Hrs	0				
AMTOSS:72-51-10-907						0			Enc	0	15,000		15,000	92%
LPT Shaft												RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035689-1	New				0			Mos	30-May-2013				
13-182476-12023						0			Hrs	0				
AMTOSS:72-51-10-907						0			Enc	0	15,000		15,000	92%
LPT Stub Shaft												RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035691-1	New				0			Mos	26-May-2013				
13-162684-00010						0			Hrs	0				
AMTOSS:72-51-60-907						0			Enc	0	15,000		15,000	92%
LPT Stub Shaft												RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035691-1	New				0			Mos	30-May-2013				
13-162684-00015						0			Hrs	0				
AMTOSS:72-51-60-907						0			Enc	0	15,000		15,000	92%
LPT1 Blade												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG1	3035693-1	No.1				0			Mos	26-May-2013				
12HM55843		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
LPT1 Blade												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG2	3035693-1	No.1				0			Mos	30-May-2013				
12HM53467		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
LPT1 Blade												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG1	3035693-1	No.10				0			Mos	26-May-2013				
12HM55852		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
LPT1 Blade												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG2	3035693-1	No.10				0			Mos	30-May-2013				
12HM53476		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
LPT1 Blade												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG1	3035693-1	No.11				0			Mos	26-May-2013				
12HM55853		New				0			Hrs	0	15,000		15,000	85%
						0			Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035693-1 12HM53477	No.11 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG1 3035693-1 12HM55854	No.12 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG2 3035693-1 12HM53478	No.12 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG1 3035693-1 12HM55855	No.13 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG2 3035693-1 12HM53479	No.13 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG1 3035693-1 12HM55856	No.14 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG2 3035693-1 12HM53480	No.14 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG1 3035693-1 12HM55857	No.15 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					
	72 ENG2 3035693-1 12HM53481	No.15 New	LPT1 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013					
						0		Hrs	0	15,000		15,000	85%	
						0		Enc	0					

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 12HM55858	LPT1 Blade No.16 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 12HM53482	LPT1 Blade No.16 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 12HM55859	LPT1 Blade No.17 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 12HM53483	LPT1 Blade No.17 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 12HM56333	LPT1 Blade No.18 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 12HM53484	LPT1 Blade No.18 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 12HM56334	LPT1 Blade No.19 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 12HM53485	LPT1 Blade No.19 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 12HM55844	LPT1 Blade No.2 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035693-1 12HM53468	LPT1 Blade No.2 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035693-1 12HM56336	LPT1 Blade No.20 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035693-1 12HM53486	LPT1 Blade No.20 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035693-1 12HM56337	LPT1 Blade No.21 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035693-1 12HM53487	LPT1 Blade No.21 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035693-1 12HM56338	LPT1 Blade No.22 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035693-1 12HM53614	LPT1 Blade No.22 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035693-1 12HM56339	LPT1 Blade No.23 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035693-1 12HM53615	LPT1 Blade No.23 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 13AM63098	LPT1 Blade No.24 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035693-1 12HM55840	LPT1 Blade No.24 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035693-1 13HM63085	LPT1 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035693-1 12HM56332	LPT1 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035693-1 13HM63086	LPT1 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035693-1 12HM56342	LPT1 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035693-1 13HM63087	LPT1 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035693-1 12HM56344	LPT1 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035693-1 13HM63088	LPT1 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035693-1 12HM56345	LPT1 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63089	LPT1 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM56346	LPT1 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 12HM55845	LPT1 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53469	LPT1 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63090	LPT1 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM56347	LPT1 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63091	LPT1 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM56348	LPT1 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 13HM63092	LPT1 Blade No.32 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65409	LPT1 Blade No.32 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63093	LPT1 Blade No.33 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65410	LPT1 Blade No.33 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63094	LPT1 Blade No.34 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65411	LPT1 Blade No.34 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63095	LPT1 Blade No.35 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65412	LPT1 Blade No.35 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63096	LPT1 Blade No.36 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035693-1 13HM65413	LPT1 Blade No.36 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM63097	LPT1 Blade No.37 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65414	LPT1 Blade No.37 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM63099	LPT1 Blade No.38 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65415	LPT1 Blade No.38 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM63100	LPT1 Blade No.39 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65416	LPT1 Blade No.39 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 12HM55846	LPT1 Blade No.4 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 12HM53470	LPT1 Blade No.4 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 13HM63101	LPT1 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65417	LPT1 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63102	LPT1 Blade No.41 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65418	LPT1 Blade No.41 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63103	LPT1 Blade No.42 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65419	LPT1 Blade No.42 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63104	LPT1 Blade No.43 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65420	LPT1 Blade No.43 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM63105	LPT1 Blade No.44 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
												RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
72 ENG2 3035693-1 13HM65421	No.44 New	LPT1 Blade				0			Mos	30-May-2013	0	15,000		85%
72 ENG1 3035693-1 13HM63106	No.45 New	LPT1 Blade				0			Mos	26-May-2013	0	15,000		85%
72 ENG2 3035693-1 13HM65422	No.45 New	LPT1 Blade				0			Mos	30-May-2013	0	15,000		85%
72 ENG1 3035693-1 13HM63107	No.46 New	LPT1 Blade				0			Mos	26-May-2013	0	15,000		85%
72 ENG2 3035693-1 13HM65423	No.46 New	LPT1 Blade				0			Mos	30-May-2013	0	15,000		85%
72 ENG1 3035693-1 13HM63108	No.47 New	LPT1 Blade				0			Mos	26-May-2013	0	15,000		85%
72 ENG2 3035693-1 13HM65424	No.47 New	LPT1 Blade				0			Mos	30-May-2013	0	15,000		85%
72 ENG1 3035693-1 13HM63109	No.48 New	LPT1 Blade				0			Mos	26-May-2013	0	15,000		85%
72 ENG2 3035693-1 13HM65425	No.48 New	LPT1 Blade				0			Mos	30-May-2013	0	15,000		85%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 13HM65141	LPT1 Blade No.49 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65426	LPT1 Blade No.49 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 12HM55847	LPT1 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53471	LPT1 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM65142	LPT1 Blade No.50 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65427	LPT1 Blade No.50 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM65143	LPT1 Blade No.51 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 13HM65428	LPT1 Blade No.51 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 13HM65144	LPT1 Blade No.52 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035693-1 13HM65429	LPT1 Blade No.52 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM65145	LPT1 Blade No.53 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65430	LPT1 Blade No.53 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM65146	LPT1 Blade No.54 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65431	LPT1 Blade No.54 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM65147	LPT1 Blade No.55 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65432	LPT1 Blade No.55 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035693-1 13HM65148	LPT1 Blade No.56 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035693-1 13HM65433	LPT1 Blade No.56 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035693-1 12HM55848	No.6 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53472	No.6 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 12HM55849	No.7 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53473	No.7 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 12HM55850	No.8 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53474	No.8 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035693-1 12HM55851	No.9 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035693-1 12HM53475	No.9 New	LPT1 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035593-1 13-162246-01234	New	LPT1 Disk							RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
			0			Mos	26-May-2013						
			0			Hrs	0						
			0			Enc	0	15,000	15,000	92%			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time		
SEQ	PN/SN											DUE	Remaining		
	72 ENG2 3035593-1 13-162246-01240	LPT1 Disk New				RE								LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
						0		Mos	30-May-2013						
						0		Hrs	0						
						0		Enc	0	15,000	15,000	92%			
	72 ENG1 3035602-1 12HM56464	LPT2 Blade No.1 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG2 3035602-1 13HM65695	LPT2 Blade No.1 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG1 3035602-1 12HM56608	LPT2 Blade No.10 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG2 3035602-1 13HM66089	LPT2 Blade No.10 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG1 3035602-1 12HM56609	LPT2 Blade No.11 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG2 3035602-1 13HM66090	LPT2 Blade No.11 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG1 3035602-1 12HM56610	LPT2 Blade No.12 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	26-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						
	72 ENG2 3035602-1 13HM66091	LPT2 Blade No.12 New				RE								LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0		Mos	30-May-2013						
						0		Hrs	0	15,000	15,000	85%			
						0		Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG1 3035602-1 12HM56611	No.13 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66092	No.13 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 12HM56612	No.14 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66093	No.14 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 12HM56613	No.15 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66094	No.15 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 12HM56614	No.16 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66095	No.16 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 13HM66133	No.17 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035602-1 13HM66096	No.17 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 13HM66134	No.18 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66097	No.18 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 13HM66135	No.19 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66098	No.19 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 12HM46465	No.2 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM65696	No.2 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG1 3035602-1 13HM66136	No.20 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	26-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				
	72 ENG2 3035602-1 13HM66099	No.20 New	LPT2 Blade								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0			Mos	30-May-2013				
						0			Hrs	0	15,000	15,000	85%	
						0			Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 13HM66137	LPT2 Blade No.21 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66100	LPT2 Blade No.21 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66138	LPT2 Blade No.22 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66101	LPT2 Blade No.22 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66139	LPT2 Blade No.23 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66102	LPT2 Blade No.23 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66140	LPT2 Blade No.24 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66103	LPT2 Blade No.24 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66141	LPT2 Blade No.25 New									RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035602-1 13HM66104	LPT2 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66142	LPT2 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66105	LPT2 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66143	LPT2 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66106	LPT2 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66144	LPT2 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66107	LPT2 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66145	LPT2 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66170	LPT2 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 12HM36466	LPT2 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM65697	LPT2 Blade No.3 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66146	LPT2 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66233	LPT2 Blade No.30 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66148	LPT2 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66234	LPT2 Blade No.31 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66149	LPT2 Blade No.32 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66235	LPT2 Blade No.32 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66150	LPT2 Blade No.33 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035602-1 13HM66236	No.33 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035602-1 13HM66151	No.34 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035602-1 13HM66237	No.34 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035602-1 13HM66152	No.35 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035602-1 13HM66238	No.35 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035602-1 13HM66153	No.36 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035602-1 13HM66239	No.36 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG1 3035602-1 13HM66154	No.37 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					
	72 ENG2 3035602-1 13HM66240	No.37 New	LPT2 Blade								RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs		0	15,000	15,000	85%		
			0			Enc		0					

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 13HM66155	LPT2 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66241	LPT2 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66156	LPT2 Blade No.39 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66242	LPT2 Blade No.39 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 12HM26467	LPT2 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM65698	LPT2 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66158	LPT2 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66243	LPT2 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66159	LPT2 Blade No.41 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035602-1 13HM66244	No.41 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66160	No.42 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66245	No.42 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66161	No.43 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66246	No.43 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66162	No.44 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66247	No.44 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66163	No.45 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66248	No.45 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 13HM66164	LPT2 Blade No.46 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66249	LPT2 Blade No.46 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66165	LPT2 Blade No.47 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66250	LPT2 Blade No.47 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66166	LPT2 Blade No.48 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66251	LPT2 Blade No.48 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 13HM66167	LPT2 Blade No.49 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035602-1 13HM66252	LPT2 Blade No.49 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035602-1 12HM56603	LPT2 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035602-1 13HM66083	No.5 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66168	No.50 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66253	No.50 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66169	No.51 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66254	No.51 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66171	No.52 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66255	No.52 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035602-1 13HM66172	No.53 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035602-1 13HM66256	No.53 New	LPT2 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 13HM66173	LPT2 Blade No.54 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66257	LPT2 Blade No.54 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66174	LPT2 Blade No.55 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66283	LPT2 Blade No.55 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66175	LPT2 Blade No.56 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66297	LPT2 Blade No.56 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66176	LPT2 Blade No.57 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66298	LPT2 Blade No.57 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66177	LPT2 Blade No.58 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035602-1 13HM66299	LPT2 Blade No.58 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66178	LPT2 Blade No.59 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66300	LPT2 Blade No.59 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 12HM56604	LPT2 Blade No.6 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66084	LPT2 Blade No.6 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66179	LPT2 Blade No.60 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66301	LPT2 Blade No.60 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035602-1 13HM66180	LPT2 Blade No.61 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035602-1 13HM66302	LPT2 Blade No.61 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035602-1 13HM66181	LPT2 Blade No.62 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035602-1 13HM66303	LPT2 Blade No.62 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035602-1 12HM56605	LPT2 Blade No.7 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035602-1 13HM66085	LPT2 Blade No.7 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035602-1 12HM56606	LPT2 Blade No.8 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035602-1 13HM66087	LPT2 Blade No.8 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035602-1 12HM56607	LPT2 Blade No.9 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035602-1 13HM66088	LPT2 Blade No.9 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035661-1 12-162246-04676	LPT2 Disk New								RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
			0						Mos	26-May-2013			
			0						Hrs	0			
			0						Enc	0	15,000	15,000	92%

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT2 Disk										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035661-1	New				0			Mos	30-May-2013			
12-162246-04664						0			Hrs	0			
						0			Enc	0	15,000	15,000	92%
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.1				0			Mos	26-May-2013			
12HM55429		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.1				0			Mos	30-May-2013			
12HM53015		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.10				0			Mos	26-May-2013			
12HM55580		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.10				0			Mos	30-May-2013			
12HM53024		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.11				0			Mos	26-May-2013			
12HM55581		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.11				0			Mos	30-May-2013			
12HM53025		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.12				0			Mos	26-May-2013			
12HM55582		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.12				0			Mos	30-May-2013			
12HM53026		New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.13				0			Mos	26-May-2013			
	12HM55583	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.13				0			Mos	30-May-2013			
	12HM53027	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.14				0			Mos	26-May-2013			
	12HM55584	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.14				0			Mos	30-May-2013			
	12HM53028	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.15				0			Mos	26-May-2013			
	12HM55585	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.15				0			Mos	30-May-2013			
	12HM53029	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.16				0			Mos	26-May-2013			
	13HM59668	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.16				0			Mos	30-May-2013			
	12HM53030	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.17				0			Mos	26-May-2013			
	13HM59669	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.17				0			Mos	30-May-2013			
	12HM53031	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.18				0			Mos	26-May-2013			
	13HM59670	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.18				0			Mos	30-May-2013			
	12HM53032	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.19				0			Mos	26-May-2013			
	13HM59671	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.19				0			Mos	30-May-2013			
	12HM53033	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.2				0			Mos	26-May-2013			
	12HM55430	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.2				0			Mos	30-May-2013			
	12HM53016	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.20				0			Mos	26-May-2013			
	13HM59672	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.20				0			Mos	30-May-2013			
	12HM53034	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.21				0			Mos	26-May-2013			
	13HM59673	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.21				0			Mos	30-May-2013			
	12HM53035	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.22				0			Mos	26-May-2013			
	13HM59674	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.22				0			Mos	30-May-2013			
	12HM53037	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.23				0			Mos	26-May-2013			
	13HM60108	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.23				0			Mos	30-May-2013			
	12HM53038	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.24				0			Mos	26-May-2013			
	13HM60109	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.24				0			Mos	30-May-2013			
	12HM53039	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.25				0			Mos	26-May-2013			
	13HM60110	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035609-1 12HM54915	LPT3 Blade No.25 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60111	LPT3 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 12HM55077	LPT3 Blade No.26 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60112	LPT3 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 12HM55078	LPT3 Blade No.27 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60113	LPT3 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 12HM55079	LPT3 Blade No.28 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60114	LPT3 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 12HM55080	LPT3 Blade No.29 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.3				0			Mos	26-May-2013			
	12HM55431	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.3				0			Mos	30-May-2013			
	12HM53017	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.30				0			Mos	26-May-2013			
	13HM60115	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.30				0			Mos	30-May-2013			
	12HM55081	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.31				0			Mos	26-May-2013			
	13HM60116	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.31				0			Mos	30-May-2013			
	12HM55082	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.32				0			Mos	26-May-2013			
	13HM60117	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.32				0			Mos	30-May-2013			
	12HM55083	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.33				0			Mos	26-May-2013			
	13HM60118	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035609-1 12HM55084	LPT3 Blade No.33 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035609-1 13HM60119	LPT3 Blade No.34 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035609-1 12HM55086	LPT3 Blade No.34 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035609-1 13HM60120	LPT3 Blade No.35 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035609-1 12HM55087	LPT3 Blade No.35 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035609-1 13HM60121	LPT3 Blade No.36 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035609-1 12HM55089	LPT3 Blade No.36 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG1 3035609-1 13HM60122	LPT3 Blade No.37 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	26-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			
	72 ENG2 3035609-1 13HM62486	LPT3 Blade No.37 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0						Mos	30-May-2013			
			0						Hrs	0	15,000	15,000	85%
			0						Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035609-1 13HM60123	LPT3 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 13HM62487	LPT3 Blade No.38 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60124	LPT3 Blade No.39 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 13HM62588	LPT3 Blade No.39 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 12HM55432	LPT3 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 12HM53018	LPT3 Blade No.4 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM60125	LPT3 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG2 3035609-1 13HM62590	LPT3 Blade No.40 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						
	72 ENG1 3035609-1 13HM62271	LPT3 Blade No.41 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs		0	15,000	15,000	85%			
			0		Enc		0						

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035609-1 13HM62591	LPT3 Blade No.41 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035609-1 13HM62273	LPT3 Blade No.42 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035609-1 13HM62592	LPT3 Blade No.42 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035609-1 13HM62280	LPT3 Blade No.43 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035609-1 13HM62593	LPT3 Blade No.43 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035609-1 13HM62281	LPT3 Blade No.44 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035609-1 13HM62594	LPT3 Blade No.44 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG1 3035609-1 13HM62283	LPT3 Blade No.45 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								
	72 ENG2 3035609-1 13HM62595	LPT3 Blade No.45 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013								
			0		Hrs	0	15,000	15,000	85%					
			0		Enc	0								

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035609-1 13HM62488	LPT3 Blade No.46 New				0		Mos	26-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG2 3035609-1 13HM62596	LPT3 Blade No.46 New				0		Mos	30-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG1 3035609-1 13HM62489	LPT3 Blade No.47 New				0		Mos	26-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG2 3035609-1 13HM62597	LPT3 Blade No.47 New				0		Mos	30-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG1 3035609-1 13HM62490	LPT3 Blade No.48 New				0		Mos	26-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG2 3035609-1 13HM62598	LPT3 Blade No.48 New				0		Mos	30-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG1 3035609-1 13HM62491	LPT3 Blade No.49 New				0		Mos	26-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG2 3035609-1 13HM62599	LPT3 Blade No.49 New				0		Mos	30-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				
	72 ENG1 3035609-1 12HM55433	LPT3 Blade No.5 New				0		Mos	26-May-2013	RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
						0		Hrs	0	15,000	15,000	85%	
						0		Enc	0				

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG2 3035609-1 12HM53019	LPT3 Blade No.5 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035609-1 13HM62492	LPT3 Blade No.50 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035609-1 13HM62600	LPT3 Blade No.50 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035609-1 13HM62493	LPT3 Blade No.51 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035609-1 13HM62601	LPT3 Blade No.51 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035609-1 13HM62494	LPT3 Blade No.52 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035609-1 13HM62602	LPT3 Blade No.52 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG1 3035609-1 13HM62495	LPT3 Blade No.53 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	26-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							
	72 ENG2 3035609-1 13HM62603	LPT3 Blade No.53 New								RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0		Mos	30-May-2013							
			0		Hrs	0	15,000	15,000	85%				
			0		Enc	0							

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG1 3035609-1 13HM62496	LPT3 Blade No.54 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035609-1 13HM62604	LPT3 Blade No.54 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035609-1 13HM62497	LPT3 Blade No.55 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035609-1 13HM62605	LPT3 Blade No.55 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035609-1 13HM62498	LPT3 Blade No.56 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035609-1 13HM62606	LPT3 Blade No.56 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035609-1 13HM62499	LPT3 Blade No.57 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG2 3035609-1 13HM62607	LPT3 Blade No.57 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							
	72 ENG1 3035609-1 13HM62500	LPT3 Blade No.58 New									RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013							
			0			Hrs	0	15,000	15,000	85%				
			0			Enc	0							

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.58				0			Mos	30-May-2013			
	13HM62608	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.59				0			Mos	26-May-2013			
	13HM62501	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.59				0			Mos	30-May-2013			
	13HM62609	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.6				0			Mos	26-May-2013			
	12HM55436	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.6				0			Mos	30-May-2013			
	12HM53020	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.60				0			Mos	26-May-2013			
	13HM62502	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.60				0			Mos	30-May-2013			
	13HM62610	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.61				0			Mos	26-May-2013			
	13HM62503	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.61				0			Mos	30-May-2013			
	13HM62611	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
	72 ENG1 3035609-1 13HM62504	No.62 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035609-1 13HM66615	No.62 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035609-1 13HM62505	No.63 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035609-1 13HM66616	No.63 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035609-1 13HM62506	No.64 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035609-1 13HM66618	No.64 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035609-1 13HM62507	No.65 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG2 3035609-1 13HM66619	No.65 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	30-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						
	72 ENG1 3035609-1 13HM62508	No.66 New	LPT3 Blade							RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
			0			Mos	26-May-2013						
			0			Hrs	0	15,000	15,000	85%			
			0			Enc	0						

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.66				0			Mos	30-May-2013			
	13HM66620	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.67				0			Mos	26-May-2013			
	13HM62509	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.67				0			Mos	30-May-2013			
	13HM66621	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.68				0			Mos	26-May-2013			
	13HM62510	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.68				0			Mos	30-May-2013			
	13HM66622	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.69				0			Mos	26-May-2013			
	13HM62511	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.69				0			Mos	30-May-2013			
	13HM66630	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.7				0			Mos	26-May-2013			
	12HM55437	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.7				0			Mos	30-May-2013			
	12HM53021	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.70				0			Mos	26-May-2013			
	13HM62512	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.70				0			Mos	30-May-2013			
	13HM66631	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.71				0			Mos	26-May-2013			
	13HM64017	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.71				0			Mos	30-May-2013			
	13HM66632	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.72				0			Mos	26-May-2013			
	13HM64018	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.72				0			Mos	30-May-2013			
	13HM66633	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.73				0			Mos	26-May-2013			
	13HM64022	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG2	3035609-1	No.73				0			Mos	30-May-2013			
	13HM66634	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			
LPT3 Blade										RE	LMM 05-20-00	Recommended Replacement	≈11-May-2058
72 ENG1	3035609-1	No.74				0			Mos	26-May-2013			
	13HM64023	New				0			Hrs	0	15,000	15,000	85%
						0			Enc	0			

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN											DUE	Remaining	
	72 ENG2 3035609-1 13HM66635	LPT3 Blade No.74 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
	72 ENG1 3035609-1 12HM55578	LPT3 Blade No.8 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
	72 ENG2 3035609-1 12HM53022	LPT3 Blade No.8 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
	72 ENG1 3035609-1 12HM55579	LPT3 Blade No.9 New				0			Mos	26-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
	72 ENG2 3035609-1 12HM53023	LPT3 Blade No.9 New				0			Mos	30-May-2013		RE	LMM 05-20-00 Recommended Replacement	≈11-May-2058
						0			Hrs	0	15,000		15,000	85%
						0			Enc	0				
	72 ENG1 3035663-1 12-162246-05714	LPT3 Disk New				0			Mos	26-May-2013		RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
	72 ENG2 3035663-1 12-162246-05716	LPT3 Disk New				0			Mos	30-May-2013		RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
	72 ENG1 3033069-3 12-162045-02087	Rotating Seal (Spacer, 2-3, Compressor Rotor) New				0			Mos	26-May-2013		RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
	72 ENG2 3033069-3 12-162045-02814	Rotating Seal (Spacer, 2-3, Compressor Rotor) New				0			Mos	30-May-2013		RE	LMM 05-10-00 Airworthiness Limitations	≈14-Apr-2061
						0			Hrs	0				
						0			Enc	0	15,000		15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI		TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN												DUE	Remaining
Rotating Seal (Spacer, 3-4, Compressor Rotor)											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3033070-3	New				0			Mos	26-May-2013				
	12-162045-02574					0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Rotating Seal (Spacer, 3-4, Compressor Rotor)											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3033070-3	New				0			Mos	30-May-2013				
	12-162045-02735					0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Rotating Seal LPT1/LPT2											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3035595-1	New				0			Mos	26-May-2013				
	13-162246-00709					0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Rotating Seal LPT1/LPT2											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3035595-1	New				0			Mos	30-May-2013				
	12-162246-04751					0			Hrs	0				
						0			Enc	0	15,000		15,000	92%
Spinner Cover Ring											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3037101-2	New				0			Mos	26-May-2013				
	12-156138-02435					0			Hrs	0				
	AMTOSS:72-70-05-907					0			Enc	0	15,000		15,000	92%
Spinner Cover Ring											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3037101-2	New				0			Mos	30-May-2013				
	12-156138-02436					0			Hrs	0				
	AMTOSS:72-70-05-907					0			Enc	0	15,000		15,000	92%
Spinner Inner Ring											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3037063-3	New				0			Mos	26-May-2013				
	12-156138-01890					0			Hrs	0				
	AMTOSS:72-70-10-907					0			Enc	0	15,000		15,000	92%
Spinner Inner Ring											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG2	3037063-3	New				0			Mos	30-May-2013				
	13-156138-00196					0			Hrs	0				
	AMTOSS:72-70-10-907					0			Enc	0	15,000		15,000	92%
Stage 1 Compressor Blisk											RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
72 ENG1	3033053-7	New				0			Mos	26-May-2013				
	12-182449-06577					0			Hrs	0				
						0			Enc	0	15,000		15,000	92%

Total projection:

Challenger 300 N300ER,SN 20428

Task No	Description											Categories		Time
SEQ	PN/SN	Component	Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE			Remaining	
	72 ENG2 3033053-7 12-162246-06087	New	Stage 1 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	30-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG1 3033063-4 13-182449-08334	New	Stage 2 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	26-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG2 3033063-4 13-162246-00996	New	Stage 2 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	30-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG1 3033067-9 12-182449-07276	New	Stage 3 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	26-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG2 3033067-9 12-182449-07582	New	Stage 3 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	30-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG1 3033072-4 12-182449-06863	New	Stage 4 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	26-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG2 3033072-4 12-182449-06857	New	Stage 4 Compressor Blisk					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	30-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG1 Unknown Unknown AMTOSS:72-30-60-907		Vortex Sleeve					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	26-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					
	72 ENG2 Unknown Unknown AMTOSS:72-30-60-907		Vortex Sleeve					RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061			
			0		Mos	30-May-2013								
			0		Hrs	0								
			0		Enc	0	15,000	15,000	92%					

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description	Component Condition			TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN											DUE	Remaining
Vortex Spoiler										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
⚙	72 ENG1	New				0		Mos	26-May-2013				
	70040037-1					0		Hrs	0				
	12-162045-01679					0		Enc	0	15,000		15,000	92%
AMTOSS:72-30-70-907													
Vortex Spoiler										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
⚙	72 ENG2	New				0		Mos	30-May-2013				
	70040037-1					0		Hrs	0				
	13-162045-00131					0		Enc	0	15,000		15,000	92%
AMTOSS:72-30-70-907													
Vortex Spoiler Assembly										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
⚙	72 ENG1	Unknown Unknown				0		Mos	26-May-2013				
	Unknown					0		Hrs	0				
	Unknown					0		Enc	0	15,000		15,000	92%
Vortex Spoiler Assembly										RE	LMM 05-10-00	Airworthiness Limitations	≈14-Apr-2061
⚙	72 ENG2	Unknown Unknown				0		Mos	30-May-2013				
	Unknown					0		Hrs	0				
	Unknown					0		Enc	0	15,000		15,000	92%
▼ 73 - ENGINE - FUEL AND CONTROL													
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG1	No.1						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG2	No.1						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG1	No.10						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG2	No.10						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG1	No.11						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG2	No.11						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					
73-10-13-201		Restoration (Cleaning) of the Main Fuel Nozzles								RE	MRB - Systems/Powerplant	≈19-Jan-2030	
🔧	73 ENG1	No.12						Mos					
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801								Hrs	4,800	-/+40	4,800	52% (+0.8%)	
								Enc					

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.12					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.2					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.2					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.3					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.3					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.4					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.4					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.5					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.5					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.6					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.6					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.7					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.7					RE	MRB - Systems/Powerplant	≈19-Jan-2030	
						Mos				
						Hrs	4,800	-/+40	4,800	52% (+0.8%)
			Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801			Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801										

N300ER COMPONENT LIFE AND RESTORATION

BOMBARDIER

Total projection:

Challenger 300 N300ER, SN 20428

Task No		Description							Categories	Time	
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining	
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.8					RE	MRB - Systems/Powerplant	≈19-Jan-2030		
							Mos				
							Hrs	4,800	-/+40	4,800	52% (+0.8%)
							Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801											
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.8					RE	MRB - Systems/Powerplant	≈19-Jan-2030		
							Mos				
							Hrs	4,800	-/+40	4,800	52% (+0.8%)
							Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801											
73-10-13-201 	73 ENG1	Restoration (Cleaning) of the Main Fuel Nozzles No.9					RE	MRB - Systems/Powerplant	≈19-Jan-2030		
							Mos				
							Hrs	4,800	-/+40	4,800	52% (+0.8%)
							Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801											
73-10-13-201 	73 ENG2	Restoration (Cleaning) of the Main Fuel Nozzles No.9					RE	MRB - Systems/Powerplant	≈19-Jan-2030		
							Mos				
							Hrs	4,800	-/+40	4,800	52% (+0.8%)
							Enc				
Alias1:724000-203,731000-201, AMTOSS:73-10-13-961-801											
73-10-13-202 	73 ENG1	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Lower Left					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG2	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Lower Left					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG1	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Lower Right					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG2	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Lower Right					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG1	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Upper Left					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG2	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Upper Left					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG1	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Upper Right					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204,731000-205, AMTOSS:73-10-13-615-802											
73-10-13-202 	73 ENG2	Restoration (Cleaning) of the Start Fuel Nozzles on the Engine Upper Right					RE	MRB - Systems/Powerplant	≈21-May-2023		
							Mos				
							Hrs	2,400	-/+40	2,400	3% (+1.7%)
							Enc				
Alias1:724000-204,731000-205, AMTOSS:73-10-13-615-802											

Total projection:

Challenger 300 N300ER,SN 20428

Task No		Description							Categories	Time
SEQ	PN/SN	Component Condition	TSNI	TSOI	TSRI	CW	REQ	TOL	DUE	Remaining
▼ 76 - ENGINE CONTROLS										
		N1 Overspeed Shut-off Detector							RE LMM 05-10-00 Airworthiness Limitations	≈11-May-2058
⚙	76 ENG1	New	0		Mos	26-May-2013				
	3034256-2		0		Hrs	0	15,000		15,000	85%
	13-152330-00147		0		Enc	0				
AMTOSS:76-20-10-907										
		N1 Overspeed Shut-off Detector							RE LMM 05-10-00 Airworthiness Limitations	≈11-May-2058
⚙	76 ENG2	New	0		Mos	30-May-2013				
	3034256-2		0		Hrs	0	15,000		15,000	85%
	13-152330-00162		0		Enc	0				
AMTOSS:76-20-10-907										