



McCAULEYTM

PROPELLER LOGBOOK

AIRCRAFT PROPELLER

Model Number: 1B90/CM7447

Serial Number: XF40004

Overhauled Propeller Repaired Bent Blade 1. IAW: Manuals 730720 R6 SPM100

R4 BOM100 R5. Service Literature Referenced: A/D's: N/A. S/B's: 176E

03/03/03. S/L's: 1983-7 11/18/83, 1996-4A 04/22/97

TTSN: UNK

Hub TTSN: -0-

Work Order: CTO4340

Repair Station Q0PR011X


North Windham, CT 06256

Sensenich Propeller Service, Inc.

Phone: 860-456-7944

Gleve B. Burbage III

Date: 01/06/2012

A handwritten signature in black ink, appearing to read 'Gleve B. Burbage III', written in a cursive style.

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
6/1/04	Zero		Reg #: N1198K Tach: 1092 TSN: zero Date: 6-1-2004 Installed this propeller on N1198K, and torqued mounting bolts to mfg specs. Runup and ops. check ok.  Craig R Macdonald AP 2767400	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
Tach 1797.7 1422.5	705.7	New	Annual - J	Walter Wangert 2021079 IA
12/28/18	730.13	New	Annual	Walter Wangert 2021079 IA

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Owner Name _____

Address _____

Propeller Model 1B90/CM7447

Blade Model _____

Hub Serial No. XF 40004

Blade Serial No. 1 _____

2 _____

3 _____

4 _____

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
8.17.03	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	
10-27-03	1B90/CM7447 S/N XF 40004 Factory New Propeller Repitched from 43" to 47" pitch This was the only work performed.	AUTHORIZED BY  president
	REF: WO#-CR-29505	For NEW ENGLAND PROPELLER SERVICE, INC. EAST HADDAM, CT FAA REPAIR STATION # RC2R130L