

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL HC-224L-1BF

PROPELLER S/N AK1178B

LOGBOOK # 1

The subject aircraft was involved in an incident /  
accident on 9/12/2024 rendering it a Constructive Total  
Loss as not repairable within its insured value. For  
further details refer to insurance claim: 9495885238US.

Signed: ***Underwriters Salvage Company***

Date: **1/16/2025**

**ALG Aerospace Adjustment Services Inc**  
**3500 Lenox Road, Suite 1100**





Date

MYERS AVIATION, INC. - OSHKOSH, WI  
PROPELLER LOG ENTRY - N7878M

May 1, 2013 Tach 331.5

Annual inspection completed this time and date. Inspected prop and lubed.

*Steve J. Myers*  
Steve J. Myers AP35210971A  
Myers Aviation, Inc.

MYERS AVIATION, INC. - OSHKOSH, WI  
PROPELLER LOG ENTRY - N7878M

July 15, 2013 Tach 336.87

Annual inspection completed this time and date. Inspected prop and lubed.

*Steve J. Myers*  
Steve J. Myers AP35210971A

MYERS AVIATION, INC. - OSHKOSH, WI  
PROPELLER LOG ENTRY - N7878M

September 25, 2015 Tach 406.27

Annual inspection completed this time and date. Inspected prop and lubed hub.-end-

*Steve J. Myers*  
AP352 10971A

**PROPELLER:** Performed 100-hour inspection per FAR 43 App D, dressed blades and lubed hub, if applicable. This propeller inspected in accordance with a 100-hour inspection and found airworthy this date.

Dressed blades. Lubed hub per Hartzell instructions

Date 9-12-2016

Total Prop Time 208.4

TACH/HOBBS 426.5

TSPOH N/A

A&P # 393588930

Sig: *[Signature]*

T.C.'s Air Care

Baraboo-Wisconsin Dells Municipal Airport S3440 Hwy 12, Hanger 839 Baraboo, WI 53913

MYERS AVIATION, INC. – WITTMAN AIRPORT  
PROPELLER LOG ENTRY – N7878M

June 1, 2011 Tach 290.92 PTSN 72.82

Annual inspection completed this time and date. Inspected, dressed blades and lubed with Aeroshell #6.




Steve J. Myers AP35210971A  
Myers Aviation, Inc.

MYERS AVIATION, INC. – OSHKOSH, WI  
PROPELLER LOG ENTRY – N7878M

July 18, 2012

Tach 297.73

Annual inspection completed this time and date. Inspected, lubed and dressed faces.



Steve J. Myers AP35210971A  
Myers Aviation, Inc.

## PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

Propeller Model HC-C2YL-1BF

Propeller S/N AX1178B

Blade Design F8468A-1

Blade S/N's

No. 1 \_\_\_\_\_

No. 2 \_\_\_\_\_

No. 3 \_\_\_\_\_

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

### PITCH RANGE

High/Feather \_\_\_\_\_

Start Lock \_\_\_\_\_

Low \_\_\_\_\_

Reverse \_\_\_\_\_

Aircraft Manufacturer \_\_\_\_\_

Aircraft Model \_\_\_\_\_

S/N \_\_\_\_\_

Registration \_\_\_\_\_