

N3054L Date: 05-08-2024
Hobbs: 4670.9 Tach: 9620.78
Make: Seneca
Model: 760M6-D 60 SN: A 47706

Propeller inspected using the Piper Cherokee Warrior Service Manual, Table
18-1. Spinner removed and spinner backplates inspected for discrepancies.
Nicks dressed. I certify that this propeller has been inspected in accordance
with the scope and detail of 14 CFR 43 Appendix D Annual inspection and has
been found to be in airworthy condition at this time. END

Michael Scales

Michael Scales AP 2682993 IA

TOTAL - CARRY FORWARD TO NEXT PAGE















