



### Performace Air, Inc.

02/21/25 SMOH (L) 1505.7(R) 1505.7 A/CT T **PSMOH** 5563.7 (L)212.1R) 212.1 Flight Hobbs: N8339Y 439.2

(RH) Engine LIO-320-B1A sn# L-3150-55A

Compression are as follows: 1(72), 2(75), 3(70, 4(74)

l)Serviced engine with (1) new AA48110 and (7qs) Aeroshell 15W50 ,installed new airfilter BA-10. Alternate airbox was beyond repair .Replaced with servicable 23810-00 , replaced bellcrank 23995-000,(2) brackets W25246-000. Fightened and resaftied alternator brackets.

2)C/W the following A.D's 04-10-14C1 C/W 5/17/2023 by Williamson Aircraft ,15-19-07 C/W this date <no defects >, due at 100 hrs or anytime of a line or clamp removal, <u>24-21-02</u> C/W this date;no metal found <due every oil change or until bushing replacement>. <see A.D status sheets for further details >.

I certify that this engine has been inspected in accordance with an 100 hr inspection and was determined to be in airworthy condition.

P.B. Frido

A&P248679226

INSPECTION	&	MAIN	ITE	NA	NCE	RECORD
					_	
					·	

DATE					· ·	
	Performac	e Air ,Inc .	(RH) Engine LIO-320-B1A	Performace	Air ,Inc .	(RH) Engine LIO-320-B1A
	04/01/24	SMOH (L) 1355.5(R) 1355.5	sn# L-3150-55A	11/26/24	SMOH (L) 1409.0(R) 1409.0	sn# L-3150-55A
	A/CT T 5413.5	PSMOH (L )61.9(R) 61.9	- Installed Engine after prop strike inspection.	A/CT T 5467.0	PSMOH (L)115.4(R) 115.4	
	Flight Hobbs: 289.0	N8339Y		Flight Hobbs: 342.5	N8339Y	
	Serviced engine v	। vith (1) new AA48110 an	d (7qs) Aeroshell 100M mineral oil ,installed new airfilter BA-10.	 Serviced engine w	। vith (1) new AA48110 and (7qs) Aeroshe	ll 15W50 ,installed new airfilter BA
· · · · · · · · · · · · · · · · · · ·	C/W the following due at 100 hrs or	ng A.D's <u>04-10-14C1</u> C/W anytime of a line or clan	/ 5/17/2023 by Williamson Aircraft , <u>15-19-07</u> C/W this date <no defects="">,no p removal. <see a.d="" details.<="" for="" further="" sheets="" status="" td=""><td></td><td>g A.D's <u>04-10-14C1</u> C/W 5/17/2023 by anytime of a line or clamp removal. <se< td=""><td>Williamson Aircraft ,15-19-07_C/</td></se<></td></see></no>		g A.D's <u>04-10-14C1</u> C/W 5/17/2023 by anytime of a line or clamp removal. <se< td=""><td>Williamson Aircraft ,15-19-07_C/</td></se<>	Williamson Aircraft ,15-19-07_C/
		r. inspection and wa	en inspected in accordance as determined to be in A&P248679226	I certify th with an <u>100 h</u> airworthy cond	nat this engine has been inspected $\underline{\mathbf{r}}$ . inspection and was determin lition.	in accordance ed to be in A&P
	;					

filter BA-10. 9-07\_C/W this date <no defects >, rther details >.

A&P248679226

Performace Air ,Inc .	( <u>P</u> H) Engine LIO-320-B1A sn# L-3150-55A	
N8339Y Flight Hobbs:	Pulled engine due to propeller strike and sent  Aircraft Engines for AD Compliance 04-10-14 C	to Williamson
225.0	A/P248679226 WILLIAMSON AJRCRAFT	
435 Herndon Ave.	• Orlando Florida 32803 • (407)-649-7828 Fax	(407)-895-0024
LIO-320-B1A	Tear-Down and Inspection	L-3150-55/

Tear-down and inspection per' Service Bulletin 533C. All parts cleaned and inspected by Williamson Aircraft Inc. All steel parts inspected for cracks by Power Aviation Inc. FAA/R/S/# ZLZR567L (see 8130-3 and inspection report). Crankshaft, and Lifter bodies reworked by Aircraft Specialties Services FAA/R/S/# DD2R764K crankshaft turned M006 rods M003 mains (see 8130-3s). New camshaft 15M19407. Crankcase reworked by Crankcase Services Inc. FAA/R/S/# H1HR0960 (see 8130-3). 4 each Cylinders inspected and repaired as needed pistons cleaned new ring sets. Magneto inspected and repaired as needed. (see invoice 1566 for new parts). Crankshaft gear previously complied with S/B 475C. Engine

Date 5-23-2023 TSO 1250.1

Larry Williamson Signature Cert# 3557360P

reassembly in accordance with the Lycoming overhaul manual.



Flight Hobbs:

227.1

	Z	_	_	
erfo	rmad	ce A	ir I	nc.

11/01/23 SMOH (L) 1293.6(R) 1293.6 A/CT T PSMOH 5351.6 (L) 100.00(R) 00.00 (RH) Engine LIO-320-B1A sn# L-3150-55A

(L)00.00(N) 00.00	<ul> <li>Installed Engine after prop strike inspection.</li> </ul>
N8339Y	Marana and his artist to all victims and the second

Serviced engine with (1) new AA48110 and (7qs) Aeroshell 100M mineral oil ,installed new airfilter BA-10.

C/W the following A.D's <u>04-10-14C1</u> C/W 5/17/2023 by Williamson Aircraft ,<u>15-19-07</u> C/W this date <no defects >, due at 100 hrs or anytime of a line or clamp removal. <see A.D status sheets for further details >.

I certify that this engine has been inspected in accordance with an 100 hr. inspection and was determined to be in airworthy condition.

P.B. Funke

I/A,A&P248679226

_			

					-
0147.0	Twin Comanche				
:0194.9					
e oil and f	iltan Ol				-
V and (1)	iter. Checked filter	for metal none found	Serviced with		
y alid (1) A	A48110 oil filter.		. Serviced With	(6qts), Philli	ps 20 X C50
			11.	101	
		_	1 ang	0	1/
1			A/P248	3679226	
riormance	e Air, inc.				1 /
	TID				/ -
	rport (KLQK)				
ckens Air	rport (KLQK) N8339Y				
ckens Air 8/5/20	N8339Y	]			-
ckens Air	rport (KLQK) N8339Y Twin Comanche				Ì
ckens Air 3/5/20 Fach: 0147.0	N8339Y				
ckens Air /5/20 ach: 0147.0	N8339Y				
ckens Air	N8339Y				1

A/P248679226

DATE	TOTAL TIME		INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
Pic   O4   A/C   530   Flig   183   Insta   C/W   >, du     I cert   with	18.1  ht Hobbs:  i.6  illed new airfil  the following e at 100 hrs o	Air, Inc. ty (KLQK)  SMOH (L) 1250.1(R) 1250.1  PSMOH (L) 1493.0(R) 493.0  N8339Y  Ater BA-10.  A.D's 04-10-14C1 Due or anytime of a line or close inspection and wears inspection and wears.	Inspected and serviced engine this date: _4/1/21 Lycoming Service   Manual .  Compression are as follows :#1 ( 76 ), #2 ( 75), #3 ( 78), #4 ( 78 )  Serviced engine with (1) AA 48110 and (7ts) Phillips 20XC50 AW  when a propeller strike incident occurs, 15-19-07 C/W this date <no <see="" a.d="" amp="" defects="" details="" for="" further="" removal.="" sheets="" status="">.  Dected in accordance   S determined to be in   I/A,A&amp;P248679226</no>

Performance Air, Inc.  INSPECTION & MAINTENANCE RECORD					
	DATE Performance	Air, Inc.			
	Pickens Coun	ty (KLQK)			
Pickens Airport (KLQK)	03/09/20	SMOH			
- 10/28/19 N8339Y	A/CT T	(L) 1165.6(R) 1165.6 PSMOH	Inspected and serviced engine this date:_3/9/20 Lycoming Service  Manual .		
Flight Hobbs:	5223.6	(L)408.5(R) 408.5	wanuar.		
57.0 Engine Hobbs: 77.5	N8339Y Flight Hobbs: 99.1		Compression are as follows :#1 ( 74), #2 ( 74), #3 ( 76), #4( 74 )		
		1	Serviced engine with (1) new AA 48110 and (8ts) Aeroshell 15W50		
T) Drained oil about 151, 5	installed new airf	ilter BA-10.	- Authorities of the state of t		
1) Drained oil, checked filter for metal <none found!="">. Serviced engine with (7qts) hillips 100AW with Lycoming additive and (1) AA48110 oil filter.  IA/AP 248679226</none>	C/W the following A.D's <u>04-10-14C1</u> <u>Due when a propeller strike incident occurs, 15-19-07</u> <u>C/W this description of a line or clamp removal.</u> <see a.d="" details="" for="" further="" sheets="" status="">.  I certify that this engine has been inspected in accordance with an <u>100 hr</u>. inspection and was determined to be in airworthy condition.</see>				

Performance Air, Inc.	INSPECTION & MAINTENANCE RECORD
Pickens County (KLOK)  03/27/19   SMOH (L) 1006.5, (R) 1006.5  A/CTT   PSMOH 5124.5   (L) 309.4(R) 309.4   Manual.  N8339Y   Hobbs meter 00.00   Hobbs meter 00.00   Installed new airfilter BA-10, installed (4) new Lycoming cylinder assemblies pn# 05K21100, (4) new Rocker shafts pn# SL1390A and (8) rocker shaft thrust buttons pn# SL12892. Ran engines ~ no leaks found ~ performed compression test.  C/W the following A.D's 16-16-12 Researched: no record of ECI cylinders installed, 04-10-14 Due at a propeller strike, 15-19-07 C W this date by inspection, every 100 hrs. 17-16-11 Researched: parts not installed within dates listed <see a.d="" details="" for="" further="" sheets="" status="">.  I certify that this engine has been inspected in accordance with an 100 hr. inspection and was determined to be in airworthy condition.</see>	Pickens Airport (KLQK)  05/23/19 N8339Y  Engine Hobbs: 0019.8 Filght Hobbs: 00.14.4  1). Drained oil checked filter for metal <none found=""> and serviced with 7 qts Phillips 20XC50 and (1) AA4810110.  A/P248679226</none>

### **INSPECTION & MAINTENANCE RECORD** INSPECTION OR MAINTENANCE PERFORMED

TOTAL

DATE	TIME	INSPECTION OR MAINTENANCE PERFORMED		1	
	TIME	AGENCY & CERTIFICATE NO.	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
Jan .06-	2017 406	ss 616.6	1-4-2018	tsmo lovo	Chance Oil and filter open Filter + check
		V 1,021.1		HM 635.	for Wetal Chips. Cheek/clean Oil Suction
, 		D Engine, Engine Controls for Condition,			Screen Shell 100 W plus.
)		And FreeDOM of OPERATION. INSPECTED AN SPACE			Comprision 1/78 2/78 3/78 1/78/80
	Pluge So	CONDITION AND OPERATION PEROTMED COMPRESSION CHECK			I certify that this ENGINE has been
		\$ 1/20 43 7/30 K47/30 REMOVED & REPLACED OIL FILTER			inspected in accordance with a
	CH 48/1	0-1 AND SERVICES NOTH BOTS AFROSHEN 1/30			determined to be in airworthy condition.
	_,	2011-26-04 FUEL INTECON LINE T CETTIST THET			Paul P. Cutting, A&P 3014223 IA Paul P Cutting
		WE HAS BOOD INSPECTED IN ACCORDANCE WITH AN			
	ANNUM	INSPECTION HAL GOVAL TO BE IN HILLONTHY CONDITION			
		1388 105 1.W.	·		
			-		
<del></del>					
			A		

2475	TOTAL	INSPECTION & MAINTENANCE RECORD  INSPECTION OR MAINTENANCE PERFORMED	N83397 INSPECTION & MAINTENANCE RECORD				
DATE	TIME	AGENCY & CERTIFICATE NO.	DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED		
	Drained oil. inspection.	Lycoming 10320 B1A S/N L-3150-66C  D13 TACH 6,085.81 Hobbs 608.5 TSOH – 1,013 Hrs.  And replaced oil. C/W AD08-14-07 Fuel injection lines by	NOV-01-2015	- Hobbs TSOH 1	OPERATIONAL CHECK OF All ENGINE CONTrols		
		hat this ENGINE has been inspected in accordance with an spection as described under Title 14 CFR Part §43 Appendix D and		for FULL 7	TAVEL, FREEDOM OF MOVEMENT, SECURITY. REMOVED		
	was determ approved for	ined to be in an airworthy condition at this time. This engine is or return to service.		and Repla	TS AFROSHER 18/50 CON 40 2011-26-01 SUPEREDES		
	26₩	S. Coy A&P 1637619IA		AD08-14-0	Z 14 80 # 2 7/30 #3. 15 BD E4 7/80		
	91	determined to be in airwarthy condition					
7/8/14	HM: 613	I contify that this ename has been		I CERTIS	THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE		
	TSW0; (018	ond found to be in accordance with a 100h myselform.  Paul Pattery A+P 301 4223 JA.		GATHTO.	Junta process and found to be In pinestry		
		I certify that this has been accordance with a inspection and insp					
		determined to be in airworthy condition. Paul P. Curting, A&P 30142251A					

	11	NSPECTION & MAINTENANCE RECORD			INSPECTION & MAINTENANCE RECORD
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.	DATE	TOTAL TIME	INSPECTION OF AINTENANCE PERFORMED  AGENCY & CERTIFICATE NO.
	N 87		6/10/11	5 991	HM=589 T5 MO=991
6/2010	HM 567	June 20, 2010 HM=567 TSMO=972 N8339Y R Eng		7 11	
<b>.</b>	15mo 972	CW AD08-14-07 by Inspection of Fuel Injector Lines and Clamps. Replaced #1 Fuel Line. Changed Oil and			Changed OIL and FILTER. Shell 15W50 CheckEven
		Filter Cleaned Screen, Shell 80vv. Removed #3			Change of and FILTER. Shell 15W50 CheckEven Compression 475 3/75 4/75 180
		Cylinder and replaced Intake Guide. Installed #3.  Replace Intake Hoses, Rocker Drain Back Hoses and			Potate Spark PLUGS.
	6.00	Booker Cover Gaskets Replaced R&L Mag Points.			
	0H G-16-06 9.	Capacitors and Distributor Blocks, and Ignition Harness. Fuel Control and Spider Overhauled by			I certify that this ENGINE has been
	10 - 10	Mike's Fuel Metering. Compression Check 17/5 27/9  3/74 4/79 Replaced Crankshaft Nose Seal. Adjusted			inspected in accordance with a
· · · · · · · · · · · · · · · · · · ·	5.21° NA	Idle Speed and winkling. Tighteriod origins that save	-		determined to be in airworthy condition.
		bolts to torque spec.  I certify that this engine has been inspected in			Paul P. Cutting, ASP 3014223 IA Pulp Cutting
		accordance with a 100 hour inspection and was	Clar		
		determined to be in Airworthy Condition.	6/31/15	HM-604	TEMO 1009. Changed OIL + FILTER (Shall ISUSO)
		Paul P Cutting A&P 3014223			Clamad Scran. C/W AD OB-14-07 by Chackens
·		Paul P Cutting Adr 3014223	+		Fire To Leigh & Lines (SB 342F)
					I certify that this <u>ENGINE</u> has been
					inspected in accordance with a
					determined to be in airworthy condition.
					Paul P. Cutting, A&P 3014223 IA
					Paul F. Cully

INSPECTION & MAINTENANCE RECORD	INSPECTION & MAINTENANCE RECORD				
DATE:5-21-2007 RIGHT ENGINE LYCOMING IO-320-B1A S/N:L-3150-66C	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.		
HOBBS:0352.1 T.T:4797.1 TSMOH:0731.3 W/O# 9428  I certify that this engine has been inspected in accordance with an Annual Inspection per Piper Service Manual. Checked engine mounts and cradle. Checked electrical systems and harness. Checked engine accessories. Checked lines, tubing, and hoses. Checked induction system. Checked exhaust system. Sumped all fuel drains. Checked and lubricated engine controls and propeller controls. Checked engine baffling and cowling. Drained oil, removed oil filter and cut open, no metal noted. Installed new CH48103 oil filter and serviced engine with 8 qts 15w50 Aeroshell oil. Removed all spark plugs, cleaned and gapped. Checked and set timing.  Compression test: 1) 64/80 2) 76/80 3) 68/80 4) 76/80  A.D. 2005-12-06 on both magneto''s – Due again at Hobbs(0757.5 hrs)  C/W A.D.2002-26-01 Inspection of nozzles, lines and hardware. Due again MAY/2008  Checked and Complied with A. D. 's up to this date  Washed engine and performed engine run-up and set up per Lycoming/Overhaul Manual, no leaks noted. And have found this engine to be in an airworthy condition as of this date.  IA1676215 HARREL W. TIMMONS  All 1676215 HARREL W. TIMMONS  All 275 Above Lall 80W: Roan Engine Checked for behalf. All 1676215 Harrel Checked for behalf. All 1676215 Harrel Checked for behalf. All 1676215 Harrel Checked for behalf.	7-7-7008 7/9/2008 Hobbs-	HM: 48 Change AEROSh	ACCEPTED THIS ENGLE WAS TOUR CONTRACTOR SERVICED W/ YOUR WOIL OF HER NOTES AND THE SERVICED W/ YOUR WOIL FOR FOR THE WORL FOR THE WORL OF THE WORL SERVICED W/ AEROSHELL SOWT OIL SON- ICED SPARK Plogs ched may time, checked controls, Libert As required. Cheaned File Screens. But engine Pressures and cartious good, no Leaks front. Comp Q 80 pst #1-78 #2-62 #3-60 #4-75.  Time Time CIL A-SIL 2878533 IA		

INSPECTION & MAINTENANCE RECORD	INSPECTION & MAINTENANCE RECORD				
DATE:4-19-2006 RIGHT ENGINE LYCOMING IO-320-B1A S/N:L-3150-66C	DATE TOTAL INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.				
HOBBS:0257.5 T.T:4702.5 TSMOH:0636.7 W/O# 8998	11-2-2006 HIBES: 0308.6 changed oil and Filter Inspected Filter				
I certify that this engine has been inspected in accordance with an <b>Annual Inspection</b> per Piper Service Manual and Jet Air, Inc. forms. Checked engine mounts and cradle. Checked electrical	er and poted No metal. Serviced Engine with 15000				
systems and harness. Checked engine accessories. Checked lines, tubing, and hoses. Checked	····				
induction system. Checked exhaust system. Sumped all fuel drains. Checked and lubricated engine controls and propeller controls. Checked engine baffling and cowling. Drained oil,	All epankplus - End TOSRTIFY the maintenance and/or inspection				
removed oil filter and cut open, no metal noted. Installed new CH48103 oil filter and serviced	identified above was inspected in accordance with				
engine with 8 qts 15w50 Aeroshell oil. Removed all spark plugs, cleaned and gapped. Checked and set timing. Compression test: 1) 64/80 2) 70/80 3) 68/80 4) 72/80	d current regulations of the Federal Aviation Admin- istration and is airworthy for return to service.				
C/W A.D. 2005-12-06 on both magneto"s – Due again at Hobbs:0757.5 hrs.	Date 11-7- Zoole Signed Jan Oty				
C/W A.D.2002-26-01 Inspection of nozzles, lines and hardware. Due again APR/2007	JET AIR, INC. CRSTDAFR110F \ Galesburg, Illinois 61401				
Checked and Complied with A. D. 's up to this date  Washed engine and performed engine run-up and set up per LycomingOverhaul Manual, no	1-10-2007 HOBBS: 0324.2 Changelo: I And Filter Cut upen oil F: HER AND				
leaks noted. And have found this engine to be in an airworthy condition as of this date.	Noted NO mETAL. SETUICES Engine with 15 W TO AZM Shell i.				
I CERTIEV the maintain	aud a ctt48103 oil F! Her, -End				
CERTIFY the maintenance and/or inspection	I CERTIFY the maintenance and/or inspection identified above was inspected in accordance with				
istration and is airworthy for return to service.	current regulations of the Federal Aviation Admin- istration and is airworthy for return to service.				
Date 4-19-106 Signed J. O.L.	Date 1-10-2007 Signed Ni Oct				
Galesburg, Winers 61401	JET AIR, INC. CRS#JAFR110F Galesburg, Illinois 61401				
the set	Galesburg, filmois 61401				

r	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED	
N.	8/1/03 /40/165 SMO 14	242,5 621.7	Performed and impection in acordine with Time mountains manual and insection	149/04	TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.  1) 29/04 8339Y RIGHT ENGINE, HOBBS TIME: 251.4  PERFORMED ANNUAL INSPECTION PERFORMED IN ACCORDANCE WITH MANUFACTURERS MAINTENANCE MANUALS AND INSPECTION FORMS. PERFORMED ENGINE COMPRESSION CHECK I. 68/80 2. 76/80 3.63/80 4. 74/80. CHECKED ALL HOSES, WIRES, AND LEADS. INSPECTED BAFFLES, INTAKES AND EXHAUST SYSTEMS. PERFORMED AND COMPLIED WITH ALL APPLICABLE AD AND SB. REPLACED SPARK PLUG ON RIGHT ENGINE  REMOVED VALVE COVERS AND SPIKED VALVES TO OBTAINED PASSABLE COMPRESSION ON TWO CYLINDERS. REPLACED TWO ROCKER BOX GASKETS  CHANGED OIL AND FILTER ON BOTH ENGINES  INSTALLED THREE RIVETS ON RIGHT ENGINE (RIGHT REAR) INTAKE PIPE GASKET AND RUBBER TUBE.  OIL (15W-50 AEROSHELL)  OIL FILTER (ES48 103)  1 INTAKE GASKET (71973)  1 INTAKE GASKET (71973)  1 INTAKE TUBE (69603)  1 SPARK PLUG (REM40E)  1 VALVE COVER GASKETS (75906)  2 RIVETS (5/32)  3	Arthur F. Lawshare. IA 162460038 ASP

TOTAL INSPECTION OR MAINTENANCE PERFORMED DATE TIME AGENCY & CERTIFICATE NO. 2-4-00 SMOH 575 Date:2-4-co hobbs: 189 Completed inspection of engine and prop this date per Piper report. Compressions: 1. 70/80 2.74/80 3. 70/80 4. 73/80 Changed oil and filter with CH48110 and 7 qts. 15/50 Aeroshell. Serviced spark plugs, checked leads, controls and mount. Checked prop dome and blade condition. I certify this engine and prop have been inspected in accordance with an annual inspection and found airworthy. Dalo E Bally 1920985 IA 194 SMOH 580 Inspected engine per Pipal Compression: (1) 7/80 (374)80 (3760 (3) int spark plugs and son have been inspected in accordance o wil lo 5 24, How 1920985 IA

#### INSPECTION & MAINTENANCE RECORD

Aircraft:

Piper Twin Comanche

Date: October 9, 2001

Registration: N8339Y

Tach/Hobbs: 226.6

Right Engine: Removed accessory cover, replaced oil pump: housing, gears and drive shaft. Re-installed accessory cover, re-assembly done in accordance with Lycoming overhaul manual. Engine ground-run and no leaks noted at this time. Oil pressure was found to be within limits. - END -

. Verdiales A&P 148580607

4D 96-09-10C C/w at this Time &

10-09-01 hobbs 228.8 SMOH 608 Inpsected engine per Piper report. Oil and filter previously changed with oil pump replacement. Compressions: 1:70/80 2: 74/80 3: 72/80 4: 72/80 Checked controls, hoses and baffling.

I certify that this engine has been inspected in accordance

With an annual inspection and found to be airworthy.

INSPECTION & MAINTENANCE RECORD	
DATE TOTAL 444,8 TSM64:386. INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.	INSPECTION & MAINTENANCE RECORD
11/2/96 1894.8 Hobbs, Drained oil and inspected screen-	TIME INSPECTION OR MAINTENANCE PERFORMED
Found clean New CH48103 Filter Filled with 29th	pi trops + nspected and solviced Pillil
Aeroshell 150,50 oil Clean (8) spark plugs + check gap.	in anacklist Note: oil not changed due
compressiones Fellows 1) 76/80 2) 76/80 3) 72/80 4) 76/80	TO 100 time USO Test run accino All
Test han engine all temps and pressures normal no	11 and prossures hormal And abound
defects noted.	Tootify that this engine has
I CERTIFY THAT THIS ENGINE / PROPERTY HAS DEED INSPECTION ACCORDANCE WITH A 480HR/ANNUAL INSPECTION	inspector Mally and in the
AND WAS DETERMINED TO BE IN ALEWORTHY COMPLITION.	and best became dithere
ENGINE AD NOTES CHECKED THRU 76 09-10	1/2/00 1 10 Condition bishael ble 139682/65IA
DATE // Y/A ENGINE TOTAL TIME	139 SMOH 525 T.T: 4583.2 - END
SIGN. MCHAR HOLEY 1000210514	270) les engino me prop par Pian 100 to
int I mobiled	Tilter D 72/80 @ 74/80 Geeked ducts hoses and air
12/19/97 0081,2 Inspected per Paper report Serviced Spark	Coallad by Hr.
plugs Compression 10 980 8 780 3 7/80 Briton	and some with an annual inspection and found
	Dolo & Walter 1920985 IA.
or the state of th	
Supertien completed, no other repairs at this time.	
Dale E Hotte, ASP 1920985	

Evgene **INSPECTION & MAINTENANCE RECORD INSPECTION & MAINTENANCE RECORD** TOTAL INSPECTION OR MAINTENANCE PERFORMED DATE TIME AGENCY & CERTIFICATE NO. TOTAL DATE INSPECTION OR MAINTENANCE PERFORMED TIME AGENCY & CERTIFICATE NO. Trek ela monual insp. IAN piper form 230-209 1) 74/80 (3) 20/80 (3) 76/80 (9) 75/80 SERVICED with removal 15W-50 Shell, P/W AD 93-02-05 Feling lives 95-18 All MAMINS, ROSAFTIRD PROP, LEAK MANIFOLD DROSS. LINE, REPLACED ALL EXH GASKETS, #2 ROMOVED FOR EXH. PORT REPINE By STANDARD SULLY COS RE-INSTAILED with were Kines COMOTION YHT RESPONDED BOTTOM MARKE PASSETS & INJET SCAT HOSE ASWI MANATA MANASAD MOTES CHECKED THHOU Amelical Walker & ROCKER GASKETS Tich no 7.8 Total Time 4357.8 I certify that AIT - Wods & Repair Inc. the (margin land) has been inspected in accordance Old Bridge Airport (3N6) word was defer-182 Pension Rd. English Town. ma eato be in airworthy condition. N.J. 07726 (908) 446-0703 Time since last insp. 53.5 Dated 10/10/55 N.O. # DAVID MATHIESEN A & P 139641126 I.A. Signed Alument Title

DATE	TOTAL	INSPECTION & MAINTENANCE RECORD Right	Evej		INSPECTION & MAINTENANCE RECORD
DATE	TIME	AGENCY & CERTIFICATE NO.	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
DATE	TOTAL TIME	Time 'O' Smoth Date 7-1-91  I certify that this Frank a has been inspected in accordance with 1914 and inspection and was determined to be in airworthy condition.	9/1/94 9/4/93	Hobbs 1754.3	
7/12/93		A+ K # 2 cel due horor compression , Don			hoblem. Sent Eylender + PISTON _
Blilgs	1639,2	I CERTIFY I HAVE INSPECTED THIS ENGINE A/C PROP.  IN ACCORDANCE WITH AN ANNUAL INSPECTION HARVEY D. BARNETT IA1302210  HARVEY D. BARNETT IA1302210			Bock to Standard aircraft Parts N.C.  Standard aircraft

		THE RECORD
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORM AGENCY & CERTIFICATE NO.
		The first terms and the first terms.

### STANDARD AIRCRAFT ENGINE SERVICE, INC. MODEL LIO-320-B1A SERIAL# L-3150-66C

Engine was removed from aircraft for major overhaul. Engine was disassembled, cleaned and inspected. All steel parts were magnafluxed, all non feros metals were zyglo inspected. Crankshaft was assembled using all new main bearings, all new rod bearings, all new rod nuts and bolts. Installed new crankshaft gear & bolt per A.D. Note 91-14-22 C/W/. Camshaft and lifters were reground see tag, installed all seals, gaskets, rubbers and hoses. All cylinderswere cermichromed, installed all new seats and guides, new exhaust valves, reground intake valves, new valve springs and keepers. Installed all new pistons, new rings, piston pins plugs, exhaust studs. Starter, alternator and magnetos were overhauled, installed new impulse couplings on magnetos per A.D. Note. Installed new oil pump gears per A.D. 81-18-04 R2. Installed new spark plugs & ignition harness, fuel servo, flow divider, lines, and nozzels were overhauled. Prop govenor was overhauled see tag, installed new cylinder head temp probe/unit. Engine was overhauled in accordance with Lycoming overhaul manual 60294-7 and all A.D.Notes were complied with this date. 06/10/92 Hobbs 1508.2 TT 4058.2 Engine was installed back in aircraft, test run and returned to service this date. Gregg McConnell

### **INSPECTION & MAINTENANCE RECORD**

INSPECTION OR MAINTENANCE PERFORMED

AGENCY & CERTIFICATE NO.

DATE

TOTAL

TIME

WARRANTY: Star	adord already
그녀를 잃는 아이를 보고하셨다. [11]를 다 큐스큐큐	ndard aircraft warrants this engine, including
he accessories (if	supplied), to be free from defects in material
and workmanship for	urnished by Standard Aircraft for 360 hours
r 12 months v	which ever comes first. This engine, excluding
	ner warrant to be free from defects in material
urnished by Standa	ard Aircraft until T.B.O. on a pro-rated basis on
parts. For the calc	ulated pro-ration a minimum of 40 hours per
	te of overhaul will apply. To exercise this
mited warranty. St	andard Aircraft must be promptly notified in
writing of the disco	very of any defect or failure, fully describing
writing of the disco	
writing of the disco such defect or failure	
writing of the disco	

		INSPECTION & MAINTENANCE RECORD			INSPECTION & MAINTENANCE RECORD
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.	DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED
6-1-91	3967.7 HC			TIME	AGENCY & CERTIFICATE NO.
6-1-91	3967.7 Hr.	1867.98 SMOH 1917.7 Hobbs 100 hour inspection completed on this date. Checked mag timing. C/W/AD 90-04-06 by inspection. Replace oil line at removal or engine overhaul.  No other AD's due at this time. AD's checked through 6-3-91.  I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100  HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION  WARD DIE JUNE 1/99 LV IN SERVICE 1867.98  AD'S CHECKED THIM. 91-09 I WITH THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.  WITH A 100HIZ INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	1/27/92 model	1497,3 4330.7	Replaced both magnetos with row Slick med to engine, checked operation See tags.

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.	-
4/11/8	915541	Hobbs 1200,1 comp Al complete aller our	=
	8 9, 6	75/80 chequet of lob 25 mensions	
		HAS ENGINE HAS BEEN INSPECTED IN	
		SOURCE WITH AN HINDELINSPECTION AND WAR	_
bo		TIME IN SERVICE BY GANG I ALGORITHMAN ALGORITHMAN AND ALGORITH	
MID		TACH TIME 1306-12-12 1A	-
2/20/90	1633.7	Holls 1239,6 comp ex complete all cal your	_
		75/90 Replace all Phogs with REMISE, Fixed	
		B cigs ck Tinning Rephaced all Intake Hoses	`
_		Lyskets, chg oil & Filtor, Filled with Sof Mobil "1"	`
		I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN	-
		ACCORDANCE WITH AN AUXION INSPECTION AND WAS :	-
		TIME IN SERVICE 1633. ARWORTHY CONDITION.	-
		TACH TIME 1296 130221014	
			`
			/
			\
			-

#### INSPECTION & MAINTENANCE RECORD

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
b	. 7	
	14	
MA	KE LYC	MODEL 130 312 2:4 SERIAL NO (N. NO. 4 - 2/20 -6/6/

TACH READING DATE "Revermes como ches LAUGED ENGINE Cherry Finnerscheen FAA CONTON WHEND Serviced ENGINE with 6.5 at medil CLEANED FII ADJUSTED FDIE SPEED + MITTURE ADTUSTED Phesina Leux cheen tand MATTITUCK AIRBASE INC.

F.A.A. Repair Station QX2R125L W.O. No. 16546



Authorized Signature

Kisut en	24				
		INSPECTION & MAINTENANCE RECORD			
DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED			INSPECTION & MAINTENANCE RECORD
2-6-85	3046,0	AGENCY & CERTIFICATE NO.	DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
			04/09/86	3173.5	SMOH 1053.8 - CLEAN ENG AIN INDUCTION BOXS & INST
	Checked con Changed oil	npression, #1 79/80, #2 78/80, #3 78/80, #478/80, #5/80, #6/80; 7, 5 qts, 6 m 2 8 changed filter/inspected-cleaned oil screen;	1/su	Hobbs	NEW FICTRIS - INST 8 NEW REMUNEPLUAS - RESET GOV
	Cieumeu-insp	30cted-gapped-tested-rotated-spark-plugs: checked magnetos-breaker comp't-		709.5	BURNISH PROJEBLABES & PAINT. CHANGOIL TO 8QTS
	Engine contr	ected Engine-Prop-T <del>urbocharger</del> -Exhaust System; checked and lubed rols; washed down engine; eleaned fuel primer-nozzles-fuel injector			Amsoil-SCREEN ZMAN OH INST NEW 4" AIN INDUCTION DUCT
	& painted Pr	regulator/cerb inlet screen-drained/flushed carb bowl; dressed down op; cleaned/replaced induction air filter; engine ground runup okey.			REMOVE CHECK & CLEAN & REINSTAN AN INJECTORS "ON"
					REMOVE CARREST & CLARE & PEPTUSISTE ALTERNATURES (ALOR MIT 12154)
	0 1	11 = Speed, Replaced Adle clamp mainfield PRES. Live,			KEMOVE & FIRM NICK & 1051, ACT MICHONICKS (MCC)
	1508171	oped on Color Live, els AD 73-07-04 Bender Roloz ?			SEE 337 THIS DATE. COMP TO 50 80 80 (COLD) "ON"
	Cuic bod	1 Parts not is Enther mas (Right mac Red Plate SURD 21-#A04518)			CLEAR & WISH FOR DUNK Afin'S CHA to DATE
	SOW THEY	Red Plate 342021- # AD4=36) - T CERTRY This Eng has			M GUS 2143541 Also just NEW All OIL FICTEN
		BEED JOSP ITON A NOWSE INSP. I was Found ArRusally			A/I) 81-18-04 P.2 Due & I certify that this engine has been inspected in
		/ / / / AP 157243070 FA			was determined to 1 a in an airworthy condition.  Hr. TT 3/13.5.  Hr. S.M.O.H. 1053.8
7.7					Date 07-52-486 A&P-IA2143541
7-21-85	HOBBS 13	1.8 changed oil + Filter (Ansoil c/s) Replaced	D+0		
		SHOOK Aluge Cutt Seems at	andre	22/986	Port HA D. War Sna maintenance : Replaced
		Kinter cya 1 A 1161718	Des	cavergas	Performed the following maintenance ! Replaced lets #1+# 3, repaired wire to oil temp lender,
			The E	Halle	AxP 1920985 at Spruce Crock Oriateon
			1	202	17 17 LOTS SON Sprince Court Sister

DATE	TOTAL	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
		S/N Changed?
	T	
Les Al	EADING 440. 5-11-84 LLS, Rep	Remove #4 Cyl. Light Home Cyl  LACE PISTON RINGS. RETUSTALL #41 CYL  BASKETS ANDSEALS. ADJUST IDIE  OPERATIONAL CHECK SATISFACTORY.  FLOWN  ASEINC.

### AIRWORTHINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD

	AUTHORIZED SIG CERTIFICATI	NEXT COMP. DATE/HRS./CYCLE	TYPE OF A.D. 1 TIME/RECUR.	METHOD OF COMPLIANCE	DATE & HRS. AT COMP.	AFFECTED	A.D./BULL. NUMBER
				-			
has been							
n/ present	his ENGINE cordance with looms	inspected in a					
oction are on me av	was determined to be in ent details of this inspect	dition. Pertine					
03037	tion under W.O.# _OS	this repair sta					
tosold for	Ar21488	Signed Sirocco Aviati				*	
7	Repair Station #161-7	FAA Certified		-			
	t, Linden, N.J. 07036						
p. #161-7	Co Aviation Corp. Certified Repair St	Siroc					
Station # 10.	Airport, Linden,	Linde				€	
epair are on file	details of the rep repair station un 0030 51 Dat	Pertinent					
under order: late: //-/8-83	repair station un	at this		-			
ale. //-/8-83	0030 51 Dat	VV.O. NO.					-

DATE	TOTAL TIME	INSPECTION OR MAINTENANCE PERFORMED AGENCY & CERTIFICATE NO.
1-3-64	339	not an live
		The specific state of
		- REPLACED #2 ENG ALT GROUND WIRE / REINSTAILED SHIELDING
		The pressynty
	1	TO MAG P-LEADANTS/ ALSAFTIED HZ ENG
~j		ATR THE COB DRAIN HOSE POILED PROP BLADES
		STANTED # 2 Eng mags to CWAD 82-26-01
		(IMPFLYWT. HARDNESS TEST)/T/S EGT SYST/
		A+R FIZ F/cy/ As reg D/R+R Fuel sump
		DRAIN HOSE #2 ENG
		cu Ben Dix Redun AD 79-09-07(R3)
		INP COMPCLEBRANCE
	Check	ked compression, #176 /80, #276 /80, #3 70/80, #4 77/80, #5 /80, #6 /80;
		8 QFS DERESHELL 15-50W
		1

## ENGINE DESCRIPTION RIGHT ENG

MANUFACTURER Lycoming	MODELLIO 320 BIA
ERIAL NUMBER 3150-660	
ATED BHP	RPMMANIFOLD PRESSURE
UEL REQUIRED OCTANE/PERFORMANCE	

REGISTERED OWNER \_\_\_\_\_

STREET & NO.\_\_\_\_

CITY, STATE, ZIP\_\_\_\_\_

REGISTERED OWNER \_\_\_\_\_

CITY, STATE, ZIP

STREET & NO.



# "ENGINE LOG





PIPER AIRCRAFT CORP.,

LOCK HAVEN, PA.

ENG WASHED

Engine Serial .....

R. P. M.

WAS DETERMINED TO BE IN ARWORTHY

LS 629 AJ DATE

ISPECTED IN ACCORDANCE WITH A

HOBBS 204

COMPRESSION CHECK MADE # 721

Ground

CERTIFY THAT THIS ENGINE

Air

Date

Day

Year

Ground Time

Min

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

ENGINE LOG

REMARKS

SIGNATURE

OIL CHANGED DIL FILTER CHANGED SERVICED WITH OTS HERSCHELL, SOW (A) OIL SPARK PLUGGELEANED AND GAPPED AND TESTED IT GO LEADS CHECKED 286,1 MAG TIMEING VERIFIED ENG CONTROL CHECKED FOR SECURITY AND PROPER W Wrester TRAVEL AND LUBED AS PEONEED COMPRESSION CHECK MADE AR 1/80 # 3 72/80 #4 7/80 INTAKE AND EXT SICTEMS CHECKEN FOR INTECRIM, PROPELLER DRESSED AND PAINTED AD NOTES CHECKED THROUGH BIWEEKLY SEE REAR OF A POCRAFT LOG. ENG. WASHED AND KUNUP HERSORMEN SATISFACTOPLLI

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Engine Serial		N C			ENGINE LOG	ye i seld
Date R. P. M.	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs. Min.			
Year	Air		. "		REMARKS	SIGNATURE
2-24-81 Tac	141677.7 Jack	241619 RH	WO#01236		1-21-82 Hobbs 70.3	wo#01736
Changed oil and	filter. (both en				Changed oil and filter. Removed #3 cyl for	O/H and reinstalled
I MADE W. ERROR	B			3	Cyl. O/H by Mattruck Airbose Inc., WO#305	H 2000
Date	tobby				Added 150000 Multigrade AcrohallSirogg AV	AVE DESIGNATION AND POINT
1 - 1	,				FAA Certifi	ed Repair Station #161:/
3					Linden Airo	pp. Linden, N. de Ald U.S.
has been inspect	ed in accordance with	a	te see		- adolph s	handle
.Ames	inspection and was o	e-				2809 - appearance and a second
			S. West Land			No. of the last of
termined to be in	arrworthy condition.	DESCRIPTION OF THE PROPERTY OF				Carrier Total 2 Million
	and I sed					and the second
- L	IA 157464957				the state of the s	
Apr. (1)	30-17-2			1.		AS A CONTRACTOR OF THE SANCE
						Mary Mary Mary States
termined to be in	inspection and was on airworthy condition.	Lake A VAN			Linden Airo	Linden, N. 1.07036

Engine Se	rial		N C			ENGINE LOG
Date Year	R. P. M.	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs. Min.	12	REMARKS SIGNATURE
Mo. Bay	Ground Air					
2 - 30		Thronge oil	efilter.	2/44 09	1	13/8/80 THIS ENGINE INSPECTED IAW TT 2333.05
V		(Asho Shell 6.	tw)			A 100 HOUR INSPECTION - COMPRESS CHECK
/		Denni 68	server A+ P.	52323266		SHOWS ALL CYLINDERS 79/80.
						Michelon Jain BaP
4/16/79	Right Tach 21	51.30 REPAIL	a expust star	£		141125624
	1.	Genni		P152323261		
			The second secon	the parameters and an experience consistency when the constitution of the constitution		
7 18	Land March	Change oil +	tilton clos	vagop plug	r	I coulify that this enquire has been inspected in accordance
	Alexander	Licertify that this	Engine has been	////		enth a payual inspection and was determined to be in
-		accordance with	a phonen inspection	rand was	-	Alexanthy condition Tach Time 2333 10/9/80
-		determined to be	in airworthy condition.	-		Menni PK 10 I A 152323266
-		111	2222-04 00 0/	F/79		
-		Men.	1. Can			
-		1	A 152323266			
				, t. F.		
	TOTAL TIME					NOTICE: Note that the second s

ENGINE LOG Engine Serial ..... Date Min. R. P. M. Hrs. SIGNA REMARKS Year ...... Mo. Day Air Ground L10-320-BIA, SERIAL # 4-3150-554 A This ENGINE HAS BEEN REPAIRED Ray is approved for pature to service. 9/5/78 eeron Bx P 152323266 1 Rt. Tach 2009,72 CONNECT ENGINE to counter-ROTATION AS DER PIPER KIT 760-368 4 coming JERVICE INSTRUCTIONS IN 1000 has with by Mallituck Richase Ira. A. cylinder have been OH. I by Mallifyck FLIGHT LAPRECO GARGO MAINTENANCE WILNINGTON, GE TOTAL TIME NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty. NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

compression test readings #1-78, 2-7	9 3-79 4-76
Mil Bud out tilter eterment in anged of	1.41
Bottom Spank plags Change 4- REM40.	
Installed 3clips #55447-02 to C.W Pipy	-S.B. # 515.
wink enden # \$86A.	
Date 8/24/77 Total Aircraft Time 1950   certify this	
engine has been inspected in accordance with a 2 nn wel	
inspection and was determined to be in signarity condition	
Signature LE Cot leur ARP No 62 0639	IA:
LaFleur Airport, Northampton, Mass.	
	4
the Civil Aeronautics Act of 193	B. punishable by Civil Penalty.

	u	 	
 _			_

REMARKS	SIGNATURE
7-15.76 Tach 1845 Took Permotex oil sample	Q.Commu 1628408 IA
1-7-72 EMANGED OIL ADDED & glo ADD	5 gone Things 1442642
1-20-77 Tach 1881  (Cleaned injector sceren and all	
in exhaust manifold # 4 cyl	Detw Conner 1628408I
3-16-77 Tack 1923  @ Changed oil - 8 ats 2080	P. Conner 1628408 I
- @ Changed oil - 8 gts ADBO	The Contract of the Contract o
NOTICE: Wald Assensation	Act of 1938, punishable by Civil Penalty.

REMARKS	SIGNATURE
HEREBY CERTIFY THAT THIS HAS B	EN
INSPECTED IN ACCORDANCE WITH A 100-HOUR INSPECT	ON
TACHOMETER READING 1821 :A & P NAME Charles Described in Airworthy Condition	ow
NUMBER 1882308: DATE 5-28-26	
#1 89/09 #2 87/25 #3 80/21 #4 89/24	
2) Checked and adjusted magneto time-co	as nec. tion screen, serviced
with 9 gts Jeraco 40 AD oil.	indicate normal co were
B Washed and lubed engine.	777011512
NOTICE: Making false entries in this book is a violation of the Civil Aeronautics	Act of 1938, punishable by Civil Penalty.

REMARKS

SIGNATURE

Date J. J. J. Gotal Aircraft Time 800   certify this impaction and was determined to be in airworthy condition.	Oil changed serviced 8 ats. Ab-80 oil-filter element replaced-oil
Signalur Land The Carlo for A&P No. 1067001  Environt Airport, Northampton, Mass.  Cox - replaced all push rod se rocker Cox gaskets, compression  78/80 19/80 77/80	Repaired alt air le and new readings 19/00
700 780	
	cool annishable by Civil Penalty.

Date R. P. M.		R. P. M. Ground Time Hrs. Min.		Air Time Hrs. Min.		Total Time Hrs. Min.		
Year Mo. Day	Ground	Air						
182	aino-	finie	17530	hrs	6/2	9/7.	_	
	1					1		
(0)	ilci	hauge	de so	reen	& clea	nea	2	
		-	/					
60	ets &	xxor	VE-8	o an	ode 1	100	il le	elC
- 0				1	/-			
note	d. he	rual	selfe	essu	re.			
			U		10		20	
					on M	eury	bly	
					AYPA	183	VIII	
				/	, , , ,	, 00	0	
							+	
					-			-
NOTICE: Me	TOTAL TIM		book is a violation	of the Ci			0.1	Paral

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Engine Serial	ENGINE LOG
Date R. P. M.  Ground Time Hrs.  Min.  Air Time Hrs.  Min.  Total Time Hrs.  Min.  Hrs.  Min.	REMARKS
Date 1.0 1/174  Date 1.0 1/174  Fig. ne has been inspected in accordance with a 1.0.011 Replaced OF 11A 0:1  inspection and was determined to be in airworthy condition.  Signature. They have been airworthy condition.  ARNO 2213978  Filter  LaFleur Airport, Northampton, Mass  2-70-75  CLETA NED + RECAPPED SPARM PL:0-5 - IN SMILED NEW  INSECTOR NO 22LE IN # 4 CYLINDER - REMOVED AND  CLEMED CHEM 3 NO 22LES PER LY CHAINED & GHS # 30  TEXACC A.D. O.L. CHECKED COMPRESSION #1 7/190 # 2 74/10  # 3 7670 # 4 7570 # 1.1 3140 ATP 124 1674	Removed both mags to C. W with AD 74-26-09  Day 13-7-4. replaced both bushings to 10-163049.  Check fixed divider for AD 75-09-15 928 Ket o. K.  Oil and follow element changed 8 yts AD-80  Date 5-7-27 Total Aircraft Time. 17.03. I return this work on day  engine. has been inspected in accordance with a 2011/18/28 654 B.  inspection and was determined to be in airworthy condition.  Signature. C. C. C. Cher. A&P No. 6.46509 1 A  Latiour Airport, Northampton, Mass.
TOTAL TIME	The state of the s
NOTICE:—Making false entries in this book is a violation of the Civil Asserting to the Civi	1998 punishable by Civil Penalty.

REMARKS	SIGNATURE
HERRIEY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A  DETERMINED TO BE IN AIRWORMTY CONDITION  Lite. Serv. React  Comment of the continuous of the condition of th	REVALE STATE
NOTICE: No. 1. Accompanies	Act of 1938, punishable by

Engine Serial		N C		ENGINE LOG
Date R. P. M. Year Mo. Day Ground Air	Ground Time Hrs. Min.	Air Time Hrs. Min.	Total Time Hrs. Min.	REMARKS SIGNATURE
Changed  Replaced  Serviced  Date 5 Apr. 7 Afrenders determine transcription and was determined to the signature of the signa	#3 cyl into	ndition. 4	-	Replaced all sport plugs us the REM-40 E.  Replaced all and ail filter, 8 gto AP-80, Replaced  Vacuum pump with new pirhame unit  the gw-22 dry this talled new points Right  mag.  Date 6-11-17-1. Total Aircraft Time. 1465: certify this  emg. 17.4. has been inspected in accordance with a. 2. 17. M. w. 21  inspection and was determined to be in airworthy condition.  Signature. L. Carpellan A&P No. 6. 2063 9 I.A.  LaFleur Airport, Northampton, Mass.
		944 T		
TOTAL TIME				7-11-74 TT 1516 his Changed oil with AERO SHELL 100 - Performed 50 hr inspection per Pilex instructions.  Themas Q Para At? 2084230
NOTICE:—Making false entries in thi	s book is a violation of the Ci	ivil Aeronautics Act of 1938, p	punishable by Civil Penalty.	NOTICE NUMBER OF THE PROPERTY

ENGINE LOG

REMARKS

SIGNATURE

removed left man to realign breaken pour points reset and time magneto removed nort mooneto realone service propellow an change Install new ALFIOS oro be LaFlaur Airport, Northampton, Mass.

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

e Serial ..... ENGINE LOG Ground Time Total Time Air Time R. P. M. SIGNATURE Min. Year Mo. REMARKS Ground I certify that this aircres; engine has been inspected in accordance with a langual inspection as required Pluss; Compression by FAR 43 and found to be in an airworthy condition. Airworthiness Directives MAG TIMMING + RETIMMED AS REQUIRED, REPORTURED ALL Tachometer reading checked thru 73-13-9 and Rocker Cover Screws, checked STARTED + GENERATOR Total Time il applicable are listed in Brushes, Checked EXHAUST AND FUEL SYSTEMS FOR rear of this book. Date\_ RECHARGED RITHOP WITH NITHOPEN-DEGREESED ENG FOR FUTTER DETAILS SEE Wo# 2066 Cape Central Airways Inc., Municipal Airport CONTINUED ON NEXT Cape Girardeau, Mo. 63701 CRS 362-11 TOTAL TIME act of 1938, punishable by Civil Penalty. NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics A. J. 1999 and I hable by Civil Penalty. NOTE

	Serial	000-1411	N C		
Date	R. P. M.	Ground Time Hrs. Min.	Air. Time Hrs. Min.	Total Time Hrs. Min.	
Year Mo. Day	Oblound ADS Carte	ck apto 71/9	16 - None Repolin	alle this insp.	
	- Certify	this grown	It arreporter	according	
-	to 100 HR NA	pection TACH	Time 104.98. 1	1 1	
-			2 Barry DE	hearder	
			Pr 205817	0	
		10 4 - 1 N			
	light at				
	E LINE CONTRACTOR				
		NEW YORK THE THE		Washington and the second	
-	127-20-	Automatical Indiana	MALL WEST		
				Strain of the	
-			113	The state of the s	
			ED TRAINING	Mary and Comme	
	TOTAL TIME				
NOTICE:	daking false entries in this	book is a violation of the Ci	vil Aeronautics Act of 1938, p	unishable by Civil Penalty.	

## ENGINE LOG

		SIGNATURE
	REMARKS	
		d in
	I certify that this a dt/engine has been inspected	ired
1	I certify that this air adt/engine has been as requaccordance with a 100 hr/amuel inspection as requactordance with a loo hr/amuel inspection as requalities.	n.
	by FAR 43 and found to be in the	340
	Tachometer reading 1125.3	The Part of the Pa
	Total Time // 2513	The same of the sa
	Date 6/21/12	
	Signature She E. Carrell	
	13 P 30 667	
	Cano Control Airmone Inc., Municipal Airport	
	Cape Girardeau, Mo. 63701 CRS 362-11	manufacture publication and an artist and an artist and artist artist and artist and artist artist and artist artist and artist artist and artist
	The second section of the second seco	
		- 1 M 1/ D
7-11-	13 C/W AD 73-10-2 PAR	a feld 1 11 362-11
1	3 GW AD 73-10-2 PH	Act of 1938, punishable by Civil Penalty.
	Making to	Act of 1938, Pull-

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

ENGINE LOG

SIGNATURE TT: 1011.98 DATE: JUNE 3, 1971 ANSPECTION COMPLETED. REPLACED FOLLOWING PARTS ON BOTH MAGS, SERIALS 958403, 458410. BEARINGS, CAPACITOR, CONTACT ASSEMBLY, OIL SEALS, DISTRIBUTOR BLOCK, DISTRIBUTOR GEAR AND CONTACT BRUSH. REPLACED FOLLOWING PARTS ON GENERATOR, SERIAL , BEARINGS, BRUSHES, AND BREATHER TUBE, CHANGED OIL AND FILLED WITH SHELL SOW, INSTALLED NEW OIL FILTER. WELDED CRACKS ON ALTERNATE AIR BOX AND REPLACED ACTUATOR ARM AND HINGES, COMPRESSION CHECK - #1 80/68, #2 80/64, #3 80/67, #80/70. PROP. AIR CHARGE TO SOPSI. INSPECTED STARTER BRUSHES, CLEANED FUEL STRAINER, CLEANED INJECTION NOZZLES. INSPECTED, CLEANED, AND TESTED SPARK PLUES, FEBITION HARNESS AND CIERRETTES. PAINTED PROP TIPS VELLOW. VISUALLY INSPECTED LORD MOUNTS, COWLING, ENGINE BAFFLING, FIREWALL, LINES AND HOSES, AND CLAMPS. CHECKED THTAKE NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

D	ate	R. P.	M.	Ground T Hrs.	ime Min.	Air Time	e Min.	Total Time Hrs. M	
Year . Mo.	Day	Ground	Air						
1-64	P P.7	TAP	K 665.0	O- PMA	IUA	- moso	1587	Comp	,016
8	F	11750	CH	Gd, M	Eus	howER	RE	M 40 E	PLUG
MA	w	CHA	BB	1 R F-11	TER	- MAG	s C	HEEKED	I
CI	EA7	IFY	THUS	ENG.	HA	1 BEE	n 1.	vs aseta	011
AC	DA	PAN	PE L	17H	An	- A BEN	O'AL	INSOLEX	UND
PS	A	590	1900	BY F	Pa	& to	una	AIRWD	ATHY
			CED	VICE INC.		7000	in	e HUV116	829
	OWE	LL AIRCF	AFI SEN	L AIRPORT)	_	INSPE	e/+	AUIH,	
	P. 0.	BOX 1309	F 785-432						
	14 -	PHUI	CITY, FLO	RIDA					
		PANAMA	0,						
		28.12.10.11							
		14,0 8 4 7							
			12 11 1						
		TOTAL TIM	E	¥ -				unishable by Civil P	

## ENGINE LOG

	REMARKS	SIGNATURE
5-8-70 Lang!	resp. completed - Oil	hanged - Textalled
Mozzles clean.	of - Complete list or	maint and ivep.
Compression test  No1-80/10  2-80/12  3-80/15	I certify that this aircraft/engine has accordance with a 100-hr/annual institution by car 43 and found to be in an air Tachometer reading 834. Total time 834. O Date 5 8 70  Signature Accordance Accordance JACK E. GREMORE A&P AI 1. Cape Central Airways Inc., Municip	worthy condition.

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Fenancy.

ENGINE LOG Engine Serial ..... Air Time Ground Time Total Time Date SIGNATURE R. P. M. Hrs. 612.68 HRS. ON TRUH. Ground 100 Km. inspection completed this date as per 5,0, As 10-4-68 spectic l certify that this but has been inspected in accordance with a 100 ton \_inspection and was found to be in airworthy condition Date/o-4-68 Total Time Aircraft Engine\_ 5/2, 6 Southern Ohio Aviation Co. FAA Repair Station 4139 Montgomery County, Airport, Dayton, Ohio Signed (12) To Fautor V. Aut. Person TOTAL TIME Alex Act of 1938, punishable by Civil Penalty. NOTICE: Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty

## SIGNATURE REMARKS s Aircraft has been Inspected in Determined to be in Airworthy Condition" Mechanic Time on Aircraft Date NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

REMARKS	SIGNATURE
100 Hr Eugine Check	101111
Change oil. Change filter. Chec	to compression.
Clean-set and test spayk plug.	1 deck may point.
theck engine contrals. Wash	06 9 M MATH HE 1831
Lubricate engine controls. Do	nava mallion
til certifi	THAT this American has been inspected in
TI CORTIFICATION ACCORDANCE TO THE CORTIFICATION ACCORDANCE TO	tit - A - title   Tenganting and was
Betemin	et to be in Airworthy Condition"
La Constant	rald I reffith AE 1831
QUEEN CITY FLYING SERVICE, INC.	estianic Cert. No. /A-
HANGER 3, LUNKEN AIRPORT 6 - 2	24-67 100:42
CINCINIATI OUIO 45226	Time on Albert FNG INC
NOTICE:—Making false entries in this book is a violation of the Civil Aeronautic	s Act of 1938, punishable by Civil Tellally.

ENG. NO.	1-31-51-6	Block of the		PC-
FUEL-OCT, MIN.	91/59	PROP. RATI	O TOTAL STATE OF	
TAKE-OFF (5 MIN.)		H.P. AT		ENLAN
NORMAL RATED	160	H.P. AT	2700	R.R.
CRITICAL ALT.	FI	. VALVE C		coi
PATENT NO'S.			SPK A	m. 250

Instructions for the  1. This log must always accompany the engine to which it refers.  2. No pages shall be torn from Log Book. No erasures, and all entries to be made in ink.  3. Original entries shall be made and signed by manufacturer or seller. All other entries shall be made by Pilot, Chief Mechanic, or other competent person authorized to do so.  4. On journey, the pilot is responsible for carriage of Log Book and entries or omissions tilvein. Failure to do so will be considered a serious neglect of duty.  PIPER AIRCRAFT CORP.—LOCK HAVEN, PA., U. S. A.  8. Before departure on journey, pilot is personally to ascertain that entries in log have been made are correct, and then sign certificate to the effect.  6. Special data such as manufacturers notes, test data, reconditioning, etc., should be affixed to stubs provided for that purticular to the defect.  7. CAA-18-1 Repair and Alteration forms listed on last page.  8. This log book shall be available and produced, on demand of anyone so authorized.
ENGINE LOG License No.
MANUFACTURER Name Aucling him Serial No. License No.  Model 10-320-BIA H. P. Manifold Pressure Name Manifold Pressure Maximum
Stroke S. S. Manifold Pressure Normal Maximum  R.P.M. Normal S. O. O. B.H.P. Normal Maximum  Gear Reduction Ratio Coulet Alwaye Rotation of Propeller Certified Correct  Name  Normal Date  Normal Maximum  Rotation of Propeller Coulet Normal  Rotation of Propeller Coulet Normal  Normal Maximum  Rotation of Propeller Coulet Normal  Normal Maximum  Rotation of Propeller Coulet Normal
Bore 5.125 Maximum (Normal)
R.P.M. Normal 2000 B.H.P. Maximum 160
Gear Reduction Ratio . August . August Rotation of Propeller
Certified Correct
Address
NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.