

Reg. #:	N16DF	Date:	April 12, 2023	Work Order:	R3S7A
Make:	EMBRAER	Model:	EMB-505		
		Designator:	Phenom 300		
Aircraft S/N:	50500167	TT:	2396.4	Landings:	1359

Performed the following general maintenance under work order R3S7A:

- Removed Engine S/N: PCE-DG0338 from the #1 position on Embaer, EMB-505, Phenom 300, S/N:50500167 at aircraft TT:2396.4 and Landings:1359.
- Removed Engine S/N: PCE-DG0339 from the #2 position on Embaer, EMB-505, Phenom 300, S/N:50500167 at aircraft TT:2396.4 and Landings:1359.

A detailed record is on file under work order **R3S7A**.

Signed:



Duncan QI 1312
Martin Delisle

For Duncan Aviation Repair Station JGVR194F Phone: 800-228-4277

Reg. #: **N16DF**
Make: **PRATT &
WHITNEY**

Date: **April 12, 2023**
Model: **PW535E**

Work Order: **R3S7A**

#1 Eng S/N: **PCE-DG0338**

#1 Eng TSN: **2396.4**

#1 Eng CSN: **1359**

Performed the following general maintenance under work order R3S7A:

- Removed Engine S/N: PCE-DG0338 from the #1 position on Embraer, EMB-505, Phenom 300, S/N:50500167 at aircraft TT:2396.4 and Landings:1359.

A detailed record is on file under work order **R3S7A**.

Signed:



Duncan QI 1312
Martin Delisle

For Duncan Aviation Repair Station JGVR194F Phone: 800-228-4277

Reg. #: **N16DF**
Make: **PRATT &
WHITNEY**

Date: **April 12, 2023**
Model: **PW535E**

Work Order: **R3S7A**

#2 Eng S/N: **PCE-DG0339**

#2 Eng TSN: **2396.4**

#2 Eng CSN: **1359**

Performed the following general maintenance under work order R3S7A:

- Removed Engine S/N: PCE-DG0339 from the #2 position on Embraer, EMB-505, Phenom 300, S/N:50500167 at aircraft TT:2396.4 and Landings:1359.

A detailed record is on file under work order **R3S7A**.

Signed:



Duncan QI 1312
Martin Delisle

For Duncan Aviation Repair Station JGVR194F Phone: 800-228-4277