



The Standard

PROPELLER LOG

ASA-SP-1

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2017</u>	Total Time in Service	Description <u>Torque checked prop bolts.</u>
Date: <u>8/18</u>	<u>85.8</u>	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # <u>Chen & Son # AIP2726735</u>

Year: <u>2018</u>	Total Time in Service	Description <u>Torque checked prop bolts.</u>
Date: <u>9/6</u>	<u>107.85</u>	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # <u>Chen & Son # AIP2726735</u>

Year: <u>2019</u>	Total Time in Service	Description <u>Torque checked prop bolts.</u>
Date: <u>8/20</u>	<u>128.1</u>	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # <u>Chen & Son # AIP2726735</u>

Year: <u>2021</u>	Total Time in Service	Description <u>PERFORMED CONDITION INSPECTION AND BALANCE inspection. Replaced ATTACHING HARDWARE, AN6-44A. To CERTIFY THIS PROPELLER HAS BEEN FOUND TO BE IN CONDITION FOR SAFE FLIGHT. Tool Cal A+P/IA 2757998</u>
Date: <u>01-10</u>	<u>138.16</u>	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2009	Total Time in Service	Description
Date: 6/10/09	0	INSTALL PROP TORQUED TO 300 IN LBS
Next Inspection Due:	Time Since Overhaul	
	0	
Mech. Cert. # or Repair Station # Joseph H. Muehl #1385993		
Year: 2012	Total Time in Service	Description
Date: 9/1	5:15	TORQUED PROP BOLTS TO 24 FT/LBS Joseph H. Muehl cert # EXP/RE 3539374
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		
Year: 2013	Total Time in Service	Description
Date: 7/29	6:00	Torqued Prop bolts. Joseph H. Muehl cert # 3539374
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

Year: 2014	Total Time in Service	Description
Date: 8/23	28.5	Torque Prop bolts Paul B. Muehl cert # A+P2726735
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		
Year: 2015	Total Time in Service	Description
Date: 8/25	38.9	Torque check prop bolts Paul B. Muehl cert # A+P2726735
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		
Year: 2016	Total Time in Service	Description
Date: 9/7	59.45	Torque checked prop bolts Paul B. Muehl cert # A+P2726735
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

Propeller Record General Information

Propeller Manufacturer SENSENICH

Model W54SK-64G

Type WOOD FIX PITCH

Hub Series # SNAH2346

Blade # _____

Date of Manufacture _____

Make/Model

Serial #

Aircraft Installed On:

SONEX

0979