

10/10/10

10/10/10

10/10/10

10/10/10

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Burlington Air Center

703 Airport Rd. Burlington, WI, 53105
(262) 763-9500 Fax (262) 763-2910

4/26/24 Hobbs: 1278.9 N2698J Tach: 504.0 SNEW: 543.6

Inspections: Completed 100 Hour Inspection this date IAW FAR Pt. 43 App. D.

All AD's checked.

No repairs necessary.

All routine maintenance completed.

I certify; this Propeller has been inspected in accordance with a 100 Hour Inspection, determined to be in airworthy condition with regard to the work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.

JA 3243242

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Burlington Air Center

703 Airport Rd. Burlington, WI, 53105
(262) 763-9500 Fax (262) 763-2910

Year: _____

Date: _____

Next Ir
Due: _____

8/7/24 Hobbs: 1371.4 N2698J Tach: 576.7 SNEW: 616.3

Year: _____

Date: _____

Next Ir
Due: _____

Inspections: Completed Annual Inspection this date IAW FAR Pt. 43 App. D.

All AD's checked.

No repairs necessary.

All routine maintenance completed.

I certify; this Propeller has been inspected in accordance with an Annual Inspection, determined to be in airworthy condition with regard to the work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.

JA 3743242

Year: _____

Date: _____

Next Inspection
Due: _____

Time Since
Overhaul

Mech. Cert. # or Repair Station # _____

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year	Total Time in Service	Description
Burlington Air Center 703 Airport Rd. Burlington, WI, 53105 (262) 763-9500 Fax (262) 763-2910		
Year	10/23/23	Hobbs: 1018.3 N2698J Tach: 304.8 AFTT: 4713.7
Date	<u>Inspections:</u> Completed 100 Hour Inspection this date IAW FAR Pt. 43 App. D. <u>All AD's checked.</u>	
Next Due:	<u>No repairs necessary.</u> <u>All routine maintenance completed.</u>	
I certify; this <u>Propeller</u> has been inspected in accordance with a <u>100 Hour Inspection</u> , determined to be in airworthy condition with regard to the work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.		
Year	Date	
Next Due:	Date	
Overhaul		
Mech. Cert. # or Repair Station #		

JA 3743242

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year	Total Time in Service	Description
Burlington Air Center 703 Airport Rd. Burlington, WI, 53105 (262) 763-9500 Fax (262) 763-2910		
Year	1/16/24	Hobbs: 1149.9 N2698J Tach: 405.3 SNEW: 444.9
Date	<u>Inspections:</u> Completed 100 Hour Inspection this date IAW FAR Pt. 43 App. D. <u>All AD's checked.</u>	
Next Due:	<u>No repairs necessary.</u> <u>All routine maintenance completed.</u>	
I certify; this <u>Propeller</u> has been inspected in accordance with a <u>100 Hour Inspection</u> , determined to be in airworthy condition with regard to the work performed, and that the work has been accomplished in accordance with current Federal Aviation Regulations.		
Year	Date	
Next Due:	Date	
Overhaul		
Mech. Cert. # or Repair Station #		

JA 3743242

Propeller Record General Information

Propeller Manufacturer McCaughey

Model _____

Type _____

Hub Series # _____

Blade # _____

Date of Manufacture _____

Make/Model

Serial #

Aircraft Installed On: Cessna 150 G

15065698

MCCAULEY™

**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**

wo: PS23159



Propeller - page 1 of 1

Plane Safe Aircraft Maintenance, Inc. - 503 West Bluemound Rd - Waukesha, WI 53188 - 262-547-1800

N2698J

McCauley, 1A100/MCM6950, S/N: AQC41006

June 30, 2023

Hobbs: 886.8

Tach: 204.4

TSN: 243.99

1A100/MCM6950 Propeller PN: 1A100/MCM6950, SN: AQC41006, TT Tach: 243.99

1. Completed 100Hr/ Annual Inspection IAW FAR 43 appendix D, using Cessna 150 inspection forms as a guide.
2. Cleaned and inspected propeller, spinner and hub.
3. AD's checked through Bi-Weekly 2023-14.

I certify that this propeller has been inspected IAW an Annual Inspection, is found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Plane Safe Aircraft Maintenance, Inc. under work order: PS23159.

Druanne Pierce Airframe & Powerplant A&P393886792

A handwritten signature in blue ink, appearing to read "Druanne Pierce", is written over a horizontal line.

Signature &
Certificate
Number

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

wo: PS22159

Propeller - page 2 of 2



Plane Safe Aircraft Maintenance, Inc. • 503 West Bluemound Rd • Waukesha, WI 53188 • 262-547-1800

I certify that this propeller has been inspected IAW an Annual Inspection, is found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Plane Safe Aircraft Maintenance, Inc. under work order: PS22159.

Samuel Cryer Airframe & Powerplant A&P95526492 1A

Soni KC

Signature &
Certificate
Number

[illegible]

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
5-23-22			1A100/MCM6950	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	GC
		S/N	AQC41006		

wo: PS22159

Propeller - page 1 of 2



Plane Safe Aircraft Maintenance, Inc. · 503 West Bluemound Rd · Waukesha, WI 53188 · 262-547-1800

N2698J

McCauley, 1A100/MCM6950

June 14, 2022

Tach: 2908.92

SINCE NEW: 0.0

1A100/MCM6950 Propeller PN: 1A100/MCM6950, SN:AQC41006 TT Tach: 2908.92

1. Completed 100Hr/ Annual Inspection IAW FAR 43 appendix D, using Cessna 150 inspection forms as a guide.
2. Installed new Propeller, p/n: 1A100/MCM6950, S/N: AQC41006. Painted propeller hub as required to match. Torqued and safetied propeller and reinstalled all removed components.
3. All AD's checked current thru 2022-12