## 896 SM 912 N896SE



☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

## AEROVATIONS 517





## UNLIMITEDLLO

AEROVATIONS@HOTMAIL.COM 303-587-0174

N896SE PROPELLER LOGBOOK ENTRY 04/14/2019 HOUR METER TIME 73.5 ENGINE TOTAL TIME 73.5 Propeller Serial #C356

Inspected propeller per the Pipistrel Vario D Maintenance Manual

- -Visually inspected blades for damage. None found.
- -R/R Spinner. Inspected hub and retorqued bolts to the Maintenance Manual Specifications

Edmund D. Babovec: A&P/LSRM-A #2844669 Rotax #101120220-01

Da

Ne

Du

E DE House

I certify that this PROPELLER has been inspected in accordance with the Pipistrel Maintenance Manual and is found to be in condition for safe operation. Tach 286 Hobbs 345.1 April 28, 2022 Tim Quinn 1655843

Sim dum

4/25/23 Sec-Engine 15

\_

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS							and the serimenosted in	TIONS, REPAIRS AND ALTERATIONS
AEROVATIONS UNLIMITED LD			· · ·	-	Year:	accordance w	this PROPELLER has been inspected in with the Pipistrel Maintenance Manual and is n condition for safe operation. Tach 168.7	
\\.39	6SE PROPELLE	ER LOGBOOK EY	36	-	Next Inspection	Hobbs 205.6 1655843	Total Time 256.6 April 20, 2021 Tim Quinn	
		Rinspected by 1900 to	g et egen e e e e e e e e e e e e e e e e e	-	Year:	10000		
andsi	that this PROP found to be in it D. Babbasso	sate modific	<sup>१</sup> र स्थाप्त के प्राप्त	-	Date: Next Inspection		para and an annual control of the second con	
A&P(13R)(A+A #1344669 Z)				- D	Due:	Overhaul	Mech. Cert. # or Repair Station #	
, RC 3X F	FUGURA O 1.70.22	1		ر -	Year:	Total Time in Service	Description	
Date:					Date:			
Next Inspection Due:	Time Since Overhaul				Next Inspection Due:	Time Since Overhaul		
		Mech. Cert. # or Repair Station #				- Communication	Mech. Cert. # or Repair Station #	

☐ HUB & BL	ADE INSPECT	IONS, REPAIRS AND ALTERATIONS	_	нив				
11 DEC	Total Time in Service	New propeller installed on aircraft. All operations and	<del></del>	AEROVATIONS SITUS				
2017	NEW	performance acceptable.			11953 VERMILLION RD LONGMONT CO 30504			
Next Inspection Time since overhall	Consult propeller manual for inspection from new at 25 hours, 50 hours and then every 100 hours	_	N896SE PROPELLER LOGBOOK ENTRY 09/21/2018 HOUR METE					
25 Hours		nours, 30 hours and then every 100 hours	every 100 mours					
11953 /EF	AEROV	ATIONS SITUS  Three thre	4	-Visually inspected blades ffor damage. None foundR/R Spinner. Inspected hub and retorqued bolts to the				
	N896SE PROPEL	LER LOGBOOK ENTRY 04/01:2018 HOUR METER TIME 2 00 ENGINE TOTAL TIME 2.00 PROP SER. #C-356				5		
l certify instruc	· · ·	eller, Vario D (serial #C-356), has been installed per Pipistrel LSA s.r.l.		Edmund D	&P/LSRM-A #2844669 otax #101120220-01			
			·	Date:				
Edmund		A&P/LSRM-A #2844669 Rotax #101120220-01		lext Inspection	Time Since			
	Notax #101120220-01				Overhaul	Mech. Cert. # or Repair Station #		

## 8 & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS $\Box$

AEROVATIONS@HOTMAIL COM 303-587-0174

ce Manuai

Maintenance Manual Specifications

ER TIME 50.5 ENGINE TOTAL TIME 50.5 Propeller Serial #C356

Propeller Record - General Information					
Propeller Manufacturer: Pipistrel					
Propeller Model: Vario D	Type: Composite 2 blade				
Propeller Serial No: C356					
Date of Manufacture: 2017					
Aircraft currently installed					
Manufacturer: Pipistrel Italia s.r.l.	Model: Sinus MAX				

**Serial No:** 896 SM 912