

R RECO		FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of 1 Repair Facility. (See back pages for other specific entries.)	Technician or	YEAR 20 DATE	RECORDING TACH TIME		TIMEIN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	- Open Appe, annua inspec throug	ed panel ndix D. nl. Remo ction and	ls and inspected Inspected ELT be d measuren late. Repla	enance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 172D SN:17250412 Tach:1775.7 TAFT: 4927.7 ected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 and tested ELT unit IAW CFR 91.207 (d). Due again next attery. Placarded instrument panel. C/W AD 2011-10-09 by nent. Due again at 1875.7 or next annual. All AD's checked ced regulator filter, B3-5-1. Replaced o-rings in both brake astalled missing left flap chafe button. Stop drilled crack on left		9/	4/24 N	28120	172D d ELT batte	dbergh Ln, Fletcher, NC 28732 828-684-9191 SN:17250412 Tach:1778.3 ery. Battery expires August 2, 2029. A&P 3598992 G. Phillips
	I certi	fy that t	his aircraft orthy condi	has been inspected IAW an annual inspection and was found to tion. A&P 3598992 IA David G. Phillins						

YEA 202 DATI	3 E	TIME	TODAY'S FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20 23 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
04/	10	1683.0			Removed Primer Plumjer, Remove degraded O-Kings	11/08	1718,2		4870,2	
					replaced or rings + Lubed part # MS29513-012 * 2, Reinstelled, OPS Check, Good.	1.700	1710,2		110 1010	Remove instrument panel trim. Romaned in op Attitude Indicater part # 23-59-0
					x 2. Rejustelled. OPS Theck Ford	-	<u> </u>	ļ		in op Attitude Indicater part # 23-59-0
					the court of the c		ļ			Installed used removed working Attitude Indicator
						-				Installed used removed working Attitude Indicate part # 23-501-06-9. Re-assembled Panel Trim
					Kevin B. Clark	_				Ops check, satisfackey.
					Private Pilot ASEL					
					4050426 ASEL					Maria Commetil
					OWNER, Operator	-	 	<u> </u>		Marco Gonzalez 4519355 App
					16. R 161	-			<u> </u>	Marco Gon Eurez (31733) ANY
					is the	-	ļ			
						_				
			1		1		 			

YEAR 20 <u>23</u>	TOTAL TIME IN	Current Weight and Balance Information									
DATE	SERVICE	Empty Weight	Empty CG	Useful Load	Remarks						
9/10		1383,55	37.69937	916,45	Deto of War 07/16/2019						
		<u> </u>									

Aircraft Record General Information

Manufacturer (255 n a		Model	117017	
Serial 172 50 412		Registration Number	NZYIZ	<u> </u>
Date of Manufacture 1963				
Engine(s) currently installed:		0-3001)	Serial _	27905-03-0
manufacturer Continental	_ Model	0.0		
Manufacturer			Serial _	-
Propeller(s) currently include				
Manufacturer		_ Model		
model	Serial		Serial _	Serial
Blade Model	Serial			
Blade Model	Serial	Serial		Serial



Belle Aircr 8/29/24	oft Maintenance 20 Lindbo N2812U 172D TAFT: 49	SN:17250412	IC 28732 828-684-9191 Tach:1775.7	
Appendix D. I. annual. Removinspection and through this date	aspected and tested ELT un ed ELT battery. Placarded measurement. Due again a e. Replaced regulator filte system. Installed missing le	nit IAW CFR 91.20 I instrument panel. (It 1875.7 or next and Er, B3-5-1. Replace	C/W AD 2011-10-09 by nual. All AD's checked	
I certify that the	s aircraft has been inspecte hy condition.	^	nspection and was found to 598992 IA	

YEAR: RE TA TII	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 8/7/2023 N2812U C-172D Tach:1681.4	cian or Repair	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F AND APPENDIX E PARAGRAPH C.	ì
	Complied with a Annual inspection of this airframe IAW Bell Aircraft Inspection Guide and CFR 43 Appendix D. Inspected E.L.T. IAW CFR 91.207					TRANSPONDER MAKE: MODEL: S/N: ZO1597 TRANSPONDER MAKE: MODEL: S/N:	
	and replaced nose tire and tube with new Airhawk 5.00-5 6ply tire and 5.00-5 tube. Removed and replaced vacuum regulator filter P/N: ARB3-5-1. Removed					DATE: 8-24-2023 11451 Richard Ellinston	
	and replaced Central Vacuum filter P/N: RAD9-18-1. Remarked elevator trim Takeoff marking. Removed and replaced Bracket air filter element P/N: BA6108. Removed evidence of bird nests in tail. Removed and reinstalled RH					CAROLINA AVIONICS GROUP, LLC N 2812 U FAA APPROVED REPAIR STATION # OCCR-389K FAR 91.411 ALTIMETERS, ALTITUDE REPORTING EQUIPMENT AND STATIC	
	damper, no defects noted. C/W AD2011-10-09 by inspection and measurement, due again at tach: 1781 4 or Appual Verified AD compliance though 8/7/2023. I					PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E PART 43 ALTIMETER CERTIFIED TO	-
	Appendix D and has been determined to be in AIRWORTHY condition.					LEFT FEET RIGHT FEET	
	Patrick E. Gray AP3518803IA					S/N: 10902 S/N: DATE: 8-24-2023 1451 Kichen Lilington	-
						R-79-2023 11-25 LLC CAROLINA AVIONICS GROUP, LLC N2812U FAA APPROVED REPAIR STATION # QCCR-389K	-

2-22	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	2023 DATE	TIME	FLIGHT	SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE	1637.5		47895	2 /	07/25	140 KH	-	110022	Removed position 1.5 hr, IN OP. Bulb failed
3.70				Conwell x-25 Battery, Part # R6-25XC		1681.3		7853.5	light bulb 651777 Das Chi
				Removed Battery Part # 6:11 6-25					Removed position 1.5ht, IN OP. Bulb failed test, No Continuity, Replaced with Position 1.5ht bulb GE1777. Ops Check good. 12.8VX1.52A Keen B. Clark
									/ - /3 · / h
				Kevin B. Clark					Owner Jopenher.
				Privat Pilot 4050426					Jopen ren.
				owner/garater					
			ļ			<u> </u>			

2022	RECORDING TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	<u>l</u>	nician or Repair
06/03	1575.2 TAFT		4727.2	Removed part # 0442512-1 (Shimmy Dompered) from Nose gear, Cleaned area. Replaced with.		Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/29/22 N2812U 172D SN:17250412 Tach:1582.0 TAFT: 4734.0	
	: 1+1 7			Fart # MC0442512-1 (Shimmy Damperer), Tested operation, dampener worked satisfactory		Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d). Battery expires June 2024. C/W AD 2011-10-09 by inspection and measurement. Due again at 1682.0 or next annual. All AD's checked through this date. Replaced regulator filter, B3-5-1. Lubed	
				Keun B. Clark		carb heat cable. Adjusted vacuum.	
				Private Pilot ASEL 4050426 K.B. Ull		be in an airworthy condition. David G. Phillips T certify that this aircraft has been inspected IAW an annual inspection and was found to A&P 3598992 IA David G. Phillips	
				Owner			
		ļ	ļ		_		

T	ECORDING FACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repa Entries must be endorsed with Name, Rating and Facility. (See back pages for other specific entries	d Certificate Number of Technician of Repair	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician of Facility. (See back pages for other specific entries.)
	91.413 WEI PAR TRANSPON #1 TRANSPON #2 DATE:	RE PERFORT 43 APP NDER MAI	NDERS AND DRMED THIS ENDIX F, AN (E: MOI (E: MOI (E: MOI) (E: MOI) (E: INS	R 91.413 INSPECTIONS AS REQUIRED BY FAR DATE AND FOUND TO COMPLY WITH D APPENDIX E PARAGRAPH C. DEL: S/N:			Re G(emoved (3/18/202 3-25 battery	Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 22 N2812U C-172D Tach: 1563.8 Airframe Log S.N. G02935422 and installed new G-25 battery S/N: c of charging system satisfactory Mindle Lag 3518803 A&P Patrick E. Gray
	IN CERCO	TAAA!					Re		5/19/202	Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 N2812U C-172D Tach:1571.2 Airframe Log Taxi and landing light bulbs P/N: 4509, ops check good. Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 ———————————————————————————————————

AR:	chnician or Repair	RECORDING TACH TIME TODAY'S FLIGHT TIME IN SERVICE TOTAL
Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/22/21 N2812U 172D SN:17250412 Tach:1563.2 TAFT: 4715.2 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d). Battery expires June 2024. C/W AD 2011-10-09 by inspection and measurement. Due again at 1663.2 or next annual. All AD's checked through this date. Replaced regulator filter, B3-5-1. Lubed carb heat cable. Replaced scat hose from left muffler to baffle. Replaced left fuel cap seal. I certify that this airframe has been inspected IAW an annual inspection and was found to be in an airworthy condition. David G. Phillips		ALTIMETERS, ALTITUDE REPORTING EQUIPMENT AND STATIC PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43 ALTIMETER CERTIFIED TO LEFT FEET RIGHT FEET 2000 SIN: 10902 SIN: DATE: W/O INSPECTOR: CAROLINA AVIONICS GROUP, LLC CAROLINA AVIONICS GROUP, LLC VOICE OF PART 43 ALTIMETER CERTIFIED TO LEFT FEET RIGHT FEET CAROLINA AVIONICS GROUP, LLC VOICE OF PART 43 ALTIMETER CERTIFIED TO LIGHT FEET CAROLINA AVIONICS GROUP, LLC VOICE OF PART 43 ALTIMETER CERTIFIED TO LIGHT FEET COLOR OF PART 43 ALTIMETER CERTIFIED TO CAROLINA AVIONICA SERVICA SERV

INC/ VOIO

YEAR:	RECORDING TODAY'S TOTAL Description of Inspections Tools Description of Inspections Tools Description	er of Technician or Repair	RECORDING TODAY'S TOTAL TIME IN Entries must be endorsed with Name Rating and Cortificate Number of Tachnician or Repair
DATE	'an on (eq)		Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. All AD's checked this date. Inspected and tested ELT
	172D S/N 17250412 N2812U		unit IAW CFR 91.207 (d), battery expires June 2024 and remote battery expires 3.21. CWAD 2011-10-09 by inspection and measure, due again at 1655.1. Replaced Brackett air filter element with new BA 6108. Removed corrosion from the battery box, repaired and painted with acid proof paint. Replaced the right-wing fuel drain valve with a new CAV-170, no leaks noted. Repaired dome light switch as needed. Replaced the seal in
	Updated Garmin GTN-650 software: Main to 6.62, Com to 2.30 Nav to 6.03, and WAAS to 5.2. Aircraft returned to service.		the left brake caliper, serviced and bled the brake. I certify that this aircraft was inspected IAW an Annual Inspection and was approved for return to service.
	John Pruden A&P 3503331 Garmin Dealer 19069185		A&P30381091A Michael Everhalt

YEAR: DATE	RECC TACF TIME	Removed KT76A transponder and installed Appareo Stratus ES transponder P/N: 153510-000069 S/N 201597 IAW STC SA04112CH. Updated Weight and balance. **Market Log** **Market Log** **Patrick E. Gray** **Gray** **Gray** **Tach: 1555.0 **Airframe Log** **Removed KT76A transponder and installed Appareo Stratus ES transponder P/N: 153510-000069 S/N 201597 IAW STC SA04112CH. Updated Weight and balance.**	ı or Repair	YEAR: RE TA TH	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/29/19 N2812U 172D S/N: 17250412 Tach: 1555.1 Total Time: 4707.1 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D, Replaced the ELT battery, new expires June 7, 2024. Inspected and tested ELT unit IAW CFR 91.207 (d), remote battery expires 3/21. C/W AD 2011-10-09 by inspection and measure, due again at 1655.1. All AD's checked this date. Replaced Brackett air filter element with new BA 6108. Removed corrosion from the battery box and painted with acid proof paint. Installed DG after repair.
		TRANSPONDER MAKE: THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. TRANSPONDER MAKE: MODEL: S/N:			I certify that this aircraft was inspected IAW an Annual Inspection and was approved for return to service. A&P3038109IA Nichael Everhan
		TRANSPONDER MAKE: MODEL: #2 DATE: WO: INSPECTOR: 7-26-2019 8981 Richard Ellington CAROLINA AVIONICS GROUP, LLC NZYIZU FAA APPROVED REPAIR STATION # QCCR-389K			Removed ACK A-30 encoder S/N: 19905 and installed new ACK A-30.5 encoder S/N: 150834. **Total Log of the Edward Street S

PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43	Tests, Repairs and Alterations ne, Rating and Certificate Number of Technician or Repair specific entries.) DAT	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191
91.413 WERE PERF PART 43 AP TRANSPONDER MA #1 TRANSPONDER MA #2 DATE: W	MODEL: SIN:	Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d). Battery expires May 2019. C/W AD 2011-10-09 by inspection and measurement. Due again at 1648.0 or next annual. All AD's checked through this date. Replaced Brackett filter element BA 6108. Serviced nose strut with nitrogen. Tightened shimmy dampner. Replaced regulator filter, B3-5-1. Replaced primary instrument filter, D9-18-1. Replaced nose tire with new air hawk 5.00 x 5, 4 ply tire. Reglued copilot door seal. I certify that this airframe has been inspected IAW an annual inspection and was approved for return to service. David G. Phillips A&P 3598992 IA

The lower

YEAR: REC TAC TIMI DATE	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/27/16 N2812U 172D S/N: 17250412 Tach: 1529.7 Total Time: 4681.7 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and vested ELT unit IAW CFR 91.207 (d). battery expires 5/12/19, remote battery expires 3/21. C/W AD 2011-10-09 by inspection and measure, due again at 1629.7. All AD's checked this date. Replaced Brackett air filter element with new BA 6108. Replaced all tires with new Air Hawk 5.00-5-6 ply and 6.00-6-6 ply. Replaced all brake linings with new 66-105. Serviced nose strut with nitrogen. I certify that this aircraft was inspected IAW an Annual Inspection and was approved for return to service. A&P3038109IA	an or Repair	YEAR: REC TACI TIMI DATE	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/24/17 N2812U 172D S/N: 17250412 Tach: 1540.0 Total Time: 4692.0 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d), battery expires 5/12/19, remote battery expires 3/21. C/W AD 2011-10-09 by inspection and measure, due again at 1640.0. All Al)'s checked this date. Replaced Brackett air filter element with new BA 6108.Replaced the primer line from the firewall to the primer valve. I certify that this aircraft was inspected IAW an Annual Inspection and was approved for return to service. A&P3038109IA Michael Everhart	n or Repair

INC YOUN

Marie and the second se

YEAR: RECONTACT TACT TIME	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/23/15 N2812U 172D S/N: 17250412 Tach: 1511.9 Total Time: 4663.9 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide Opened panels and inspected and tested ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d), battery expires 5/12/19, remote battery expires 3/21. C/W AD 2011-10-09 by inspection expires 5/12/19, remote battery expires 3/21. C/W AD 2011-10-09 hy inspection and measure, due again at 1611.9. All AD's checked this date. Replaced Brackett air and measure, due again at 1611.9. The tend shipping dampener	FAR 91.411 ALTIMETERS,ALTITUDE REPORTING EQUIPMENT AND STATIC PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43 ALTIMETER CERTIFIED TO LEFT FEET RIGHT FEET O 000
	expires 5/12/19, Temote batters and measure, due again at 1611.9. All AD's checked this date. Replacted Butters and measure, due again at 1611.9. All AD's checked this date. Replacted Butters and measure, due again at 1611.9. All AD's checked this date. Replacted Butters on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted filter element with new BA 6108. Installed two flap buttons on right flap. Adjusted flap buttons on right flap. Adjusted flap buttons on right flap. Adjusted flap buttons on right flap buttons on right flap. Adjusted flap buttons on right flap buttons on right flap buttons on right flap. Adjusted flap buttons on right flap buttons on right flap buttons on right flap buttons on right flap buttons on righ	SIN: 1 C 9 O Z INSREGTOR: WIO INSREGTOR: WIDE CAROLINA AVIONICS GROUP, LI C O FAR 91.413 THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY: FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. TRANSPONDER MAKE: MODEL: S/N: #1 King KT76A I773 TRANSPONDER MAKE: J MODEL: S/N:
		DATE: WO: INSPECTOR: 7-27-2015 7087 Rucher Right Poh N28/20 FAA APPROVED REPAIR STATION # QCCR-389K

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Certific Facility. (See back pages for other specific entries.)	d Alterations ate Number of Technician or Re	year: pair	RECOI TACH TIME	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 7/11/14 N2812U 172D S/N: 17250412 Tach: 1484.6 Total Time:4636.6 or Re Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit IAW CFR 91.207 (d). battery expires 5/12/19, remote battery expires 3/21. C/W AD 2011-10-09 by inspection	Repair
	LOG ID# 440 N2812U S	27-Febr /N 172504	uary-2014 12 CESS	50 Airport Loop Road Salisbury, NC 28147 NA 172D TACH 1459.4 I installed RAMI AV-530 VHF Com Antenna per Inst Replaced existing RG-58 coax with new kG-400.	Pg 1/1 allation System ops test			and measure, due again at 1584.6. All AD's checked this date. Replaced Brackett air filter element with new BA 6108. Cleaned corrosion from under battery box and painted with acid proof paint. Replaced all elevator attach bearings and bushings with new. Replaced vacuum regulator filter. Removed debris from fuel tank vent tube. Cleaned contacts on right Nav light socket. Removed, replaced gasket and seals in fuel selector valve and reinstalled, no leaks noted. I certify that this aircraft was inspected IAW an Annual Inspection and was	
7	AP3549069 Ga	ry Jenkin	5	Date				approved for return to service. A&P3038109IA Michael Everhart	

RECORDING TACH TIME TACH TIME TIME TODAY'S FLIGHT TODAY'S FLIGHT TODAY'S FLIGHT TODAY'S FLIGHT TODAY'S Entries must be endorsed with Name, Rating and Certificate Number of Technician of Facility. (See back pages for other specific entries.)	YEAR: or Repair	RECORDING TODAY'S TOTAL TIME IN SERVICE TIME TODAY'S FLIGHT TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs Facility. (See back pages for other specific entries.)
Carolina Avionics Group, LLC 3650 Airport Loop Road Salisbury, NC 28147 LOG ID# 456 06-June-2014 N2812U S/N 17250412 CESSNA C172D TACH 1476.9 Pg 1 / 1	mo	Carolina Avionics Group, LLC 3650 Airport Loop Road Salisbury, NC 28147 LOG ID# 443 12-March-2014 N2812U S/N 17250412 CESSNA 172D TACH 1459.4 Pg 1 / 1
Remove Ameri-King AK-450 ELT with antenna and remote control panel. Installed ACK E-04 ELT S/N 010370 with E-04.8 antenna, RCPI E-04.5 and Audio alert E-04.7 as minor alteration per Model E-04 ELT Installation manual P/N E04M Rev 1.6. ELT, Antenna and RCPI installed in positions of previous ELT. Audio alert is installed on pilot instrument panel rear support strut above rudder pedals. System ops test good. Weight change negligable.		Remove and replaced Master switch P/N 0713026-5 and replaced wire from master switch contactor to switch and from switch to ground. Installed new spike diode across Master switch solenoid. OPs test good. AP3548069 Gary Jenkins Date
nex Code 2DC86-A5104-FFBFF LT Bat Lithium E-04.0 Lot 00022 Expiration date May 12, 2019 CCPI Lithium Battery Duracell FX28L Expiration date Mar 2021 audio Alert Lithium Battery Duracell CR-2 expiration date Mar 2021		
Hary Jerkins 6/7/14 AP3548069 Gary Jenkins Date		

ING TODAY'S	THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. TRANSPONDER MAKE: MODEL: S/N: #1 King Model: S/N: #2 MODEL: S/N: #2 INSPECTOR: #2 CAROLINA AVIONICS GROUP, LLC FAA APPROVED REPAIR STATION # QCCR-389K FAR 91.411 ALTIMETERS, ALTITUDE REPORTING EQUIPMENT AND STATIC PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43 ALTIMETER CERTIFIED TO	ons of Technician or Repair bar	TACI TIME	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 9/4/13 N2812U Cessna 172D S/N: 17250412 Tach: 1433.9 Total Time:4585.9 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide and CFR 43 Appendix D. Replaced ELT batteries, new expires Dec. 2023 and inspected IAW CFR 91.207 (d). C/W AD 2011-10-09 by inspection and measure. Replaced Brackett air filter element with new BA 6108. Cleaned corrosion from under battery box. Replaced beacon with FAA/PMA approved Whelen flashing beacon. P/N 02-0770029-29. I certify that this aircraft was inspected IAW an Annual Inspection and was approved for return to service.	n or Repair
=	LEFT FEET RIGHT FEET			Michael Everhart	
	DATE: 8-8-2013 WID 316 INSPECTOR: CAROLINA AVIONICS GROUP, LLC FAA APPROVED REPAIR STATION # QCCR-389K				

Carolina Avionics Group, LLC 3650 Airport Loop Road Salisbury, NC 28147 LOG ID# 391 26-January-2013 NZ812U S/N 17250412 CESSNA 172D TACH 1395.6 Pg 1/11 Removed Garmin GNC 300XL GFS/Com with rack, harness, CA-56 GPs antenna, King KX-155 with rack and harness, King KI-209 Nav Indicator and Maky Com system with GI-1066 GPS/VLOC indicator and Garmin GNC 300XL GPS/Com with rack harness and sense antenna. Sing KX-155 with rack and harness, King KI-209 Nav Indicator and Maky Com system with GI-1066 GPS/VLOC indicator and Garmin GNC 300XL GPS/Com with rack harness and sense antenna. Sing KX-155 with rack and related and installed If K Garmin GNC 50 GPS approach GPS/VLOC indicator and Garmin GNC 300XL GPS/Com with rack harness and sense antenna. Sing KX-155 with rack and related for Sing KING SING GPS/VLOC indicator and Garmin GNC 300XL GPS/Com system with GI-1066 GPS/VLOC indicator and Garmin GNC 300XL GPS/COM System with GI-1066 GPS/VLOC indicator and Garmin GNC 300XL GPS/COM System with GI-1066 GPS/VLOC indicator and Garmin GNC 300XL GPS/COM System with GI-1066 GPS/VLOC indicator and GAST SING GPS/VLOC indic	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs a Entries must be endorsed with Name, Rating and Certification (See back pages for other specific entries.)	ind Alterations ficate Number of Technician or Repair	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		Removed Garminarness, King Installed IFR SPS/WAAS Anterest abricated Avancess. Remove and releases. Remove and releases. Remove and releases.	GNC 3000 KI-209 Na Garmin C Inna. Ref F Onics C/E Sisponder C	CL GPS/Com av Indicato CTN-650 GPS AA Form 33 panel and B's to ne	with rack, harness, GA-56 GPS antenna, King KN r and Narco ADF-31 ADF with rack harness and s-WAAS/NAV/Com system with GI-106A GPS/VLOC incord to the control of the contro	-155 with rack and ense antenna. icator and GA-35 ocated existing Audio over R/H radio stack		A SATISFACTOR Section 5.8 A FAA APPROV Dec 2012 WAS SEE FAA FORM	26-Janu /N 172504 RY FLIGHT The PLAGED FLIGHT INSTALLE	TEST WAS PECARD THAT ST	REFORMED per Garmin GTN 6XX/7XX STC Installation manual Rev 4. TATES "GTN-650 GPS APPROVED FOR VFR USE ONLY" WAS REMOVED. PLEMENT FOR THE GARMIN'S GTN-650 Doc # 190-01007-A2 Rev 2 DATED 18 FT'S OPERATIONAL HANDBOOK. OUT THIS INSTALLATION DATED 01/26/2013

YEAR:		TODAY'S	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations	YEAR:	RE	2.2.5.1.mamaa	cian or Repair
V ,	TIME	1	SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		τî	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191 S/N: 17250412	
DATE	1	, ,	'		DATE	+	20 Lindbergh Ln, Fletcher, NC 20132 020	
W.	Ь	Pelle Air	craft Mai	intenance 20 Lindbergh Ln, Fletcher, NC 28732	_	1	8/74/17 N7812U CESSIA 1722	
<i>i</i> —	_	3/	3/6/12 N	N2812U C172D Tach:1354.4			Tach: 13/34 I Utal I lillo	
<u> </u>				001 S/N: 83427D for repair and reinstalled after repair.	- '	1	Tach: 1373.4 Total Time: 4525.4 Opened panels and inspected aircraft IAW Belle Aircraft Inspection Guide OFF 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery	
Ţ				d adjusted to proper pressure, pressure tested system,	_	_	Opened panels and inspected aircraft IAW Belle Aircraft hispection of and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 43 Appendix D. Inspected ELT unit IAW CFR 91.207 (d), battery and CFR 91.207 (
	→			Operates normally.		+-	and CFR 43 Appendix D. Inspected ELT unit IAW CTR 3 and measure. expires April 2013. C/W AD 2011-10-09 by inspection and measure. expires April 2013. C/W AD 2011-10-09 by inspection and measure.	
·	ı		Rep	placed central vacume air filter	-	\perp	expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires April 2013. C/W AD 2011-10-09 by inspection and ineasters expires approximately ap	!
, – 	-		1	Whick & Light 3518803 A&P	_		Replaced Brackett air filter element with new BA 6108. Cleaned ground state of the Replaced Brackett air filter element with new BA 6108. Cleaned ground check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket. Reinstalled wire for instrument lights, operational check left Nav light socket.	
	4		_1,	Patrick E. Grav	_	+-		
			+	Tunion L. Olay	-		circuit breaker, operational check normal.	
)		·			_	1	I certify that this aircraft was inspected IAW an Annual Inspection and was	_
<u> </u>		` +			_		I certify that this aircraft was inspected and	
	<u> </u>					-1		
		,		(1	A&P3038109IA	
		`+	·——			4_	Michael Everhart	
	t [·			_ ' _		l Marian Service Servi	
	•				_	+		
	'	`—— 	·					
1		`	'	t e e e e e e e e e e e e e e e e e e e		T		,

San are

....

1			FAR 91,411	7			-			Tests, Repairs and	Alterations	an or Repair
YEAR:	RECORDING	TODAY	ALTIMETERS, ALTITUDE REPORTING EQUIPMENT AND STATIC	ations	YEAR.	T	TODAYS	TOTAL	Descrip	tion of Inspections, Tests, Repairs and		and nepan
DATE	TACH TIME	FLIGH	PRESSURE SYSTEM HAVE BEEN CHECKED AND MEET ALL SPECIFICATIONS OF APPENDIX E OF PART 43	nber of Technician or Repair	DATE	TAC TIM	NG TODAY'S	1 2577	•			 .
<u> </u>		i	ALTIMETER CERTIFIED TO		- WIE	┸						
			LEFT FEET RIGHT FEET			1		j	Belle Aircr	aft Maintenance		
			20,000		_ -		20	Lindberg	gh Ln, Flete	cher, NC 28732 828-684-9191		
1			5/N: 1C902 S/N:		_	+	10/14	/11 Cess	sna 172D otal Time:	S/N: 17250412 Tach: 1332.0		
			PATE: W/O INSPECTOR: Elizator			+-	0	T d nonels an	otal 11me:	1484.0 Aircraft IAW Belle Aircraft Inspection Guerted ELT unit IAW CFR 91.207 (d), based on the CAN	uide otterv	
,eq		}	CAROLINA AVIÓNICS GROUP, LLC		_	+-	and (`I	4K44ADD6	elluix D. msp	check (/W		
		¦	FAA APPROVED REPAIR STATION # QCCR-389K FAR 91.413		_							
			HE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAI 1.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITI PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C.	₹ 		+	AD 20)[1-10-09 [by inspection	and measure. Replaced Brackett an inter- b with new GE-1940.Removed DG for re e 8130 for more information.	շբա	
			RANSPONDER MAKE: MODEL: S/N:			+-	and ic	ilistanca az			l was	
			#1 King KT76A 1773			4	I certi	fy that this	aircraft was	inspected IAW an Annual Inspection and		
			RANSPONDER MAKE: MODEL: S/N:			+	appro	vea for fell	urn to service	A&P3038109IA		
			DATE: WO: INSPECTOR:	1	_	4			Michael	Everhart		
			9.9-2011 5666 Kichar Ellington		_			-				
			CAROLINA AVIONICS GROUP, LLC U FAA APPROVED REPAIR STATION # QCCR-389K]	_ \		1	l				

f		The second secon						Description of Inspections, Tests, Repairs and Alterations Description of Inspections, Tests, Repairs and Certificate Number of Technician or Repair Description of Inspections, Tests, Repairs and Certificate Number of Technician or Repair
YEAR:	RECORD TACH TIME	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 11/02/2010 N 2812U Cessna 172D S/N: 17250412 Tach: 1305.0	hnician or Repair	YEAR: DATE	TACH TIME	FLIGHT	SERVICE	Facility. (See back pages for other specific entities.)
		Total Time: 4457.0 Opened panels and inspected aircraft I.A.W. Belle Aircraft Maintenance Inspection Guide and CFR 43 Appendix D. Inspected and tested ELT unit I.A.W. CFR 91.207 (d), battery expires April 2013. C/W AD 87-20-03R2 by inspection and measure. C/W AD 96-09-06.by replacing the Brackett air filter assy. with revision H, AD no longer applies. Cleaned contacts on right nav light socket. Lubed and worked bearing on right flap outboard bottom attach				Remov	ved & replaction 12, IAW STessna 172 M ctory. Form	Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 J C-172D Tach: 1307.0 Ced mixture cable assy with "vernier" cable assy p/n CED SA4519NM, ACS Products Drawing A-3310-A, TC SA4519NM, ACS Products Drawing A-3310-A, Maintenance Manual. Ground run operational check Maintenance Manual. Weight & balance change 3361212 AP
		point. Removed large birds nest from tail. Tightened nut on left steering rod attach point at rudder pedals. Replaced vacuum regulator filter. Installed screw on left forward engine baffling. Replaced both cabin door seals.		, ,				(Dovglas P. Wooffer)
		I certify that this aircraft was inspected I.A.W. an Annual Inspection and was approved for return to service.		, ,			-	
		Michael Everhart A&P30381091A		, ,	1			

YEAR: RI TA. TIR DATE	Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 10/23/09 N2812U C-172D S/N: 50412 Tach: 1280.5 TT: 4432.5 Airframe inspected in accordance with an FAR part 43, Appendix D Inspection guide. Lubricated all pulleys, bellcranks, rod ends, etc. Serviced, charged, and installed new G25 Aircraft battery. Serviced Brake reservoirs. Shimmed and adjusted nose gear torque links as needed. Replaced B3-5-1 Vac. Reg. filter. Replaced both brake rotors with new Cleveland 164-26A discs. Installed new 66-105 brake pads both sides. Installed new Airhawk 6:00X6-6 tire on L/H side. Cleaned and re-packed wheel bearings. Installed Carb Heat control placard on Inst.	cian or Repair	YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH 91.413 WERE PERFORMED THIS DATE AND APPENDIX E PARAGRAPH C. PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. PART 43 APPENDIX F, AND APPENDIX E PARAGRAPH C. MODEL: S/N: TRANSPONDER MAKE: MODEL: S/N: TRANSPONDER MAKE: MODEL: S/N: TRANSPONDER MAKE: MODEL: MOD
	Panel. Installed fuel cap placards at both sides. Resealed rear window. Checked and adjusted control cable tensions as needed. Replaced		_		-	CAROLINA REPAIR STATION # QCCR-303R
	Outer elevator tips with new Texas Aeroplastics units. Airframe treated		_			FAR 91.411
	with Corrosion-X product. Recommend re-treatment ea. 2 yrs. or as needed. C/W AD 87-20-03 R2 Seat rails and rollers by Insp. Next due		_	-		PRESSURE STORE OF APPENDIX E OF PART 43
	10/2010 or 1380.5.		_			ALTIMETER CERTIFIED TO
D 	C/W AD76-07-12 R1 Bendix Ignition switches by ops check. Next Due 10/2010 or 1380.5.		_	-		LEFT FEET RIGHT FEET
	I certify that this Aircraft has been Inspected in accordance with an		_	-		ZO,000 S/N:
	Annual Inspection and has found to be in an airworthy condition.		_			S/N: 1773 INSPECTOR:
	Jan	1	_			DATE: CIO3 Kichar Willington
-	Stephen M. Howard		- \			FAA APPROVED REPAIR STATION # QCCR-389K
	A ° 1.523642820 1A		1	<u> </u>		FAA AFFROYEE

2CC 8	TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	N 28/2 U Serial # 17258412	or Repair	DATE	TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/18/2003	1225.]		<u></u>	DATE 10/18/2008 TACH TIME 223 TT		1/20/24	1277.1			Replexed ELT Battonios. North Jug 04/2013.
				Completed annual inspection this date. Checked and lubed all controls, cables, bellcranks, hinges, pulleys, and fairleads. Clean fuel strainer, serviced battery,						Sut alla A+1 = 3030032
	_			repack wheel bearing, check brake linings. inspect control surfaces, inspect seat rails amd ;atejes. check bendix switch (by operation), inspect engine						
				(100 hr. inspection) run engine, OPPS check ok. Comply with ADs. スロロヤートリー ちじょく ちゅう ロタル はんり ませ						
				I certify that this aircraft has been inspected in accordance with an ARNIX inspection and is determined to be in an airworthy		_				
				condition at this time.			-			
				Joseph G. Brooks A&P 405640513 IA						
				repail Front Start			-	-		

....

AR: RECORDING TODAY'S TACH TIME TE	N 29124 Ser# 172-50412 Date 1/8/2007 Tach Time 1210, 4 TT 4362.4	nair		RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
767 1210.4	Completed annual inspection this date. Ccecked and lubed all controls, cables, belckanks, hinges, pulleys, and fairleads. Clean fuel strainer, serviced battery repack wheel bearings, check brake linnings, inspect control serfaces inspect seat rails and latches check bendix switch (by operation) inspect engine (100hr. inspection) run engine opps ok. Comply with ADS 1006-26 I certify that this aircraft has been inspected in accordance with an HANDAL inspection and is determined to be in an airworthy condition at this time Joseph G. Brooks A&P 405640513 IA		The alt on 8/19 Date of Certific	timeter was	91.411 h s tested t signature	to 20,000 Randall	Model KT76A S/N 1773 has been tested and found to comply with requirements of FAR 91.413.

YEAR:	RECORDING	TODAY'S	TOTAL	Proposition of the second seco					
DATE	TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
# / /	12005	18.6	_	Checked Litt Tank for Loose items works	12	06.201			Replaced Fltuth new unit AMERITANG - PX 450
				Swampers and insert campers correction		12 12	04.4		manual smerking AK \$50, No change in ut.
	:			chart.					and balance. Replaced short stacks with
		_		JEMarholl A.P. 1851374 IA					deto for details.
		-				-			Jamarkell pr1 1851374 IA
10							 		
						-			

Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Description of Inspections, Tests, Repairs and Alterations RECORDING TODAY'S TOTAL TIME IN TACH FLIGHT Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME IN FLIGHT SERVICE Facility. (See back pages for other specific entries.) Facility. (See back pages for other specific entries.) SERVICE Completed Annual inspection this date Completed Annual Inspection this date 12:07-2008 //4/2*00*4 checked all controls, cables, be/cranks checkel all controls, cables, belevante 1145.5 bing points, cleaned bue strainer, serviced Kingo points Cleaned gasedators, served bettery checked lights repucked wheel battery. checked Lighting system. Repulked bearings Replaced R.H. Fuel cap swing wheel bearings Cu AD. 86-26-04 not applicable Compass AD-2004-19-01 NOT AMPLICABLE, CWAD Cu AD 87-20-04 by impersion. 87.20-03R2 Seat Track by i-year in the pulat detify that of have inagented this at west du webs or terms | Sor AD Listing Son arright in suadance with an ARMAL insection and grand airently at this complete list of A.D. Compliance Time Markelland 1851374 IA · lave inspected this sireseft in Addrewith an Araust inspection and four awally Nose tive + tube - J.B The WOYN SMAN MAN 185137454 Modeller 11851374JA

									Turning and Alterations
YEAR: 7.004 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Feb .	14, 2004			Installed JASLU Alternator system in accordance with STC SA 971WE AND CESSUL Service MAN	7/3//	Zery			Replaced Axiral Bus Suspence with Circus, & brooker panel. OCLT DATI ELYDUC
<u> </u>	<u> </u>			with SIC SA 97/WE AND CESSAL Service MAN		1097.	9		Of Marshell ADD 1831374 91 I
				WI & BALLONE AND EQUIPMENT List KINISID					CHE Markell AST 10015.
				Sweet approved for arture to coming	8/12		 		dustalled Rosen Visoris/Herdelen 5TC Tiled in Aix plane File.
	<u> </u>			Sweet approved for action to service.	A Description	210975			STC Filed in Air plane File.
		_			200				ELT Battery Replace 1 - Replace Augzoo6
<u> </u>						—	-		ELI Dariery region
					, _	+	-		
					, \		-	 	

aft Record General Info		Model	D. D.
lacturer <u>CSS</u>	4	Model	N 2812 U
172504-1	2	Registration Numb	er
of Manufacture	963		
(S) currently include			_ Serial _ Z7 905-D3-D
facturer 2 17 1		a 300 D	Serial
4- 17 / 1	Model	4	Serial
flacturer	Model		
facturer		Model	
Model			Serial
ovel	Serial		Serial
e Model	Serial	Serial	Serial
e Model		Serial	
-	Serial		



The Standard



DA 19_		IONS UMBER OF ENTRIES.)	DATE RECORDING TACH TODAYS TIME FLIGHT	TOTAL TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
/ =	Cessna		10/18/2003	Charles all controls, celeles, belevantes, hinge
	Seet 20 2 x 2			wints . Severed betton, cleaner Fuel strainer,
	Transaction (Contraction of the Contraction of the	(Vallet		Repaired Rutation beacon and replaced but b Respected wheel bearings. Respected LH butter service for thes
	maked see the sent for numbers kits. A Wildere connections in tweed no periods noted this acid, a improved for return to	Inv 1 = 5 (A) 4 7 8 4 5		Repaired rulbig wire worder Slow. Kgplaced tack
	*	In lu		deathy that I have inspected this surjection secondarie worth an ANNUAL
		77 78 5-11 4 164;		ingretion and found arreath at the time

ATE F	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF	260,2	RECORDING TACH	TODAYS	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
	Conit	1 -1 -1 -1	Bau	MECHANIC ON REPAIR PACIENT. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	Delace	TIME	FLIGHT		VRANDURA N MUMBERS, REPARATED FUSG. S/C
				Cover bouck oft. REPLACED AIR SILTER.					applied Viahl alymber 19W FAR- 45-29-P
-				this accordance with					2. Radio plackerd as Not user (NOP.
	100			d contry that al have inspected this accordance with an ANNUAL inspection and found accordance with the following exceptions: JEMANDULAPPH3889992 DE 1-NO CURRENT REGISTRATION.	_				James Francisco
1				exceptions: JBMarchell APPH3889992 DA					
1				C-14-NUMBER-LETTERS DO NOT MEET					
				3- COMMUNICATION FREQUENCES PLANTO CAMMO					
				SE USED FOR TRANSMITTING.			+		

		2-		OF INSPECTION	S, TESTS, REPAIRS AND ALTERATIONS NAME, RATING AND CERTIFICATE NUMBER OF NAME, RACES FOR OTHER SPECIFIC ENTRIES.)
TACH TODAYS TIME IN ENTRIES MUST BE	ION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE RECORDING	TODAYS TIME IN	ENTRIES MUST BE CHOOSE FACILITY. (SEE	BACK PAOLS This date
	rear lop helt (wo# 4318 - Souther Safety Inc)	10/21/2002	Tuest	Completed Annus	s. Raplaced Battery will
	elevator trim wheel p/v 0510 127, repliced	TACK	1 2	1. 1000 / 2 3 600	, it will in chakal
Carpeneta ha	ent cable with we plat 51224-4. Installed right	1715		6.20:14	1 11. 17-14 Reveiller
In board bra	ake pad plu 066 - 10500, Installed Transporter	1 1500		1. w. 60	1 delberrens
	suith p/v 10-347200-1 and combind with	100		1 1001	. 1 1 1 1
AD 98-01-06	by vention in apritue. In private Countrols, serviced,		1 0,000	IMME I WARD &	27-20.03 by Ingpacifor
that this dirt	Dir complete to 2000-12 B, weekly . I contify			cw AB 69-1803 by.	Explaced Let whiel
inspection and	ed found and determined to be in aurworted			Lighting Jys Tem.	Contynual ment page
Condition,	May Paper IA 164464843				

DATE 1999	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 2000	RECORDING TACH	TODAYS	TOTAL TIME IN	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
MARIS	804,2		4159.3	Arefrome inspected, replace TAXI Light, replace	8-2-00	1015.3	FLIGHT	4166.4	1 1 a time a popul annual insportace
				hinger. This ourcraft was inspected in accordance	,				Sara Repliced left main 1: solvered right main out
		3		to be in an airworthy constan.					board wheel half plu 162 - 01 1 4 AD 97 - 20 -03 RZ - sant
				Steve Hansley 408689756 1, A.	,				boots p/N 054 30 15-6 (comp boots p/N 054 30 15-6 (comp locking mechanism, Next due Tock 1115, 3 and an 8-1-00. Installed
6-6-00	1014.9			This concrett has been inspected and found rate for the	, _			4	1 It tout full tout than I
				deted 6-6-00 to 6-16-00 GUN -019			7		1 to hell ale to 13 (to say
				F. Ml AN 255279317	-	-			1 2 1 11 11 11 11 11 11 11 11 11 11 11 1
					/				turn buckler. Installed ver vecera regulator to the finished right

							-		
DATE 19 <i>91</i>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE	WECOK!	H TODAYS	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
1029000	878.4		1 - 20 4	Removed All impaction panels luber All pulleys	1-25-	97 934	2,000	56	Drained Dil cleaned screens retalled with
75.	4029	7		Removed wheels packed Bearings I Certify this	1				Ornined oil cleaned screens with S. Welle 794 Aeroshell W100 SOW Seatt S. Welle Annual Inspection Replaced all redder Annual Inspection Replaced Fairing.
3-01-	911			Direcraft has been inspected in Accordance with	3-25	9898	5.5		ANNUAL INSPECTION CONTRACTOR
-				MANUAL INSPECTION AND NOS METERMINES to DE IN					podals. Repaired sol howard RH
	- N.			inspection due 3-97 Complied with 93-18-03 by	1				Tire sero trainer 6.00x6. Replaced
	0 8 3		Later-	By inspection Thomas M. Durand	· —	-			El Barro
No.				408277873 IA	, _	-			78ste 3-25-98r.T. (L) (R)
			-			1			regrify that the Burney
-	231			20123			1		remostion ()
-					_				Sig. Filt 23,5516TA
-									

DATE 1994	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATI	KECOKDIN	TODAYS	CEDVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
//-/	-94		ch con c	Removed theels Repacked Beaung	1-5-0	76 773.5	TT.		1 All Invection Panels lubed Control Cobbo
			1/00.5	Luturated Cantrol surface hung points	1 -				Subsed Control Surface hinge points Checked bearings installed could tensions Removed wheels procked bearings installed
-					* _				1 / L sale Whoren Dotter Febrate (1)
<u></u>				INSPECTED IN ACCORDANCE UNIT AND AND WAS DEPOSITED BY A COMMENT OF THE PROPERTY OF THE PROPERT	_				Bothery our Check OK C/w AD 87=20-03R2 Sept tracks by inspection - Certify this
_				DATE 11-1-94 TO FORT TOLOR ROBERT TAYLOR, AND STANDARD LA	, —				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5-5-95	TACH	722.9		OIL DRAINED, SCREEN LHECKED - REFILED ENGINE WITH	,				with Annual inspection and was correction
				ISWSO AEROSHEIL- GROUND RAND AND NOTED NO LEAKS.					to be in sirworthy condition thomas M. Famande IA 408217923
				By owner: Daniel S. Hody E)	_			/	y no pro-
					_				

-									
19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 1923	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
4-30-5	3 77 628	2,6		Installed Welen wingth STropes. 2 ea	7/1/9	TAC	463	37.6	Replaced LIHMAIN Tire & Replaced
			_	flash tubes. See 337 feem This date.	-				BRAKE LININGS ON LIM MAIN ENd-
-				Two Chapter AR P403-72-115/ Id					BEP408767158
400					10.6.9			8.71	The dilled Crack in lower Cowling Replaced Elt Bottery Lue date Oct 95 Removed Rotating beacen, Cheaned
5-84-	13	IT b		Generatos Inope Replaced Brostes P/M		Tota	13800	0.51	Lue date Oct 45 Rampice pour L'ertify this Direct to the state of the Annual hos been inspected in Accordance with Annual
				DR-87. Ops clerked generator checks	, —		Al		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
-				Ghi Coders					111 /11 /112 / 100/ 100 10 /10/19
				Nef 40372181					Thomas M Educarde 1200112
									Thomas M Thursda 408277823-A-P

						-				
DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)		DATE 19 90	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
6-12-6	552.	3		BUDG SIN 85030. Removed Geste Augha	٩	3.93	TACH R	eads.	372.04R	TTA 3723. BILLES. AN ANNUAL INSPECTION COMPLETED
-					1			This	PATE P	LL CONTROLS CHECKED AND LUBED. ALL WHEELS
145	<u> </u>		II	200 MAN/COM S/M MYCHUWN,	11			AND Z	PAKES C	MECKED AT MAID THE REPLACED. ALL LIGHTS CHECKED
360v	1 105			New AC Empty LT. 1598,55				Die A	De CHE	KEN TO DATE
	1 - 195	1.00	1-3× V	new . Useful load 901,45				nse ji		t age that this Aircraft has been inspected in
				New CG. 37,46						accordance with a/an Annuas inspection and was determined to be in Airworthy con-
				This Chochell	1	_				dition. IAW FAR 43 APPENDIA 3733.81
				Avionics America CRS TC4D539M	31					John S. McChy iii Adi 20110011011
				GREEN: I'VE ALIPETT		_				2 mily lo
				Greenville TH 37743						0
					0	,				
_	_	_		4	/			1		

DATE RECORDING	TODAYS FLIGHT	TIME IN FINITES MUST BE ENDOSED WITH NAME DATING AND CERTIFICATE NUMBER OF	RECORDING TACH TODAYS TIME TIME TIME TIME TIME TIME TOTAL TO
6-13-90 HLS. 412.7	191	I dertify that this transponder Make # 1 LING KI-JOA S/N # 1773 Make # 2 S/N # A has been tested and inspected and found to comply with Appendix F of FAR 43 as required by FAR 91 172 and automatic pressure altitude reporting system intergration test and inspection per FAR 43 appendix E paragraph C and in accordance with FAR 91.171 and found to comply.	2.91 PERACED LETT MAND TIRE DIM POLID AND AND OLYPSICIAL CONTROLS 2.91 TACH READS 494.348 AN ANNUAL INSPECTION COMPLETED THIS DATE ALL CONTROLS CHECKED AND LUBED ALL LITES CHECKED. ALL WHEELS I BRAKES CHECKED BY BRAKE LININGS REPLACED & MASTER CYL SERVICED, PILOTS GUTBARD SERT TRACK REPLACED.
		Details on W.O. # 4483 Avionics America, Inc. Date: 43-90 2287 Airport Hwy. Cert. #2347834 Alcoa, Tenn. 37701 Tech: 4284 CRS TC4R539M	ALL ADS CHECKED TO DATE Certify that this Aircraft flash and Annual inspection accordance with a/an Annual inspection and was determined to be in Airworthy condition. IAW FAR 43 APPENDIX D Date 8. 20.91 T.T. 494.3 John S. McCloy III A&P 2014893461A.

DATE RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERA 1990 TIME TODAYS TIME IN SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY.)	NUMBER OF
(e-13-90	
Avionics America, Inc. CRS TC4R539M 2287 Airport Highway Alcoa, TN 37701 Phone 615-970-9999 A/C Reg N 28/20 S/N 172504/2 GROSS WEIGHT 2320, 50 NEW A/C EMPTY WEIGHT 1409. 80 140/	1,30
NEW USEFUL LOAD 299, 70	
BY 224936	
	-
	TACH TIME TODAYS TIME IN SERVICE ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFICATE MECHANIC OR

19.90	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
28	390.9			Removed and Replaced ELT
				EXPIRES JAN 1992 - OP'S CHECK GOOD
				Lighter with 12 gauge wine with it's own
	les e			Sahap 913 To BUSS. Removed KX170 NAV
N.				Thomas a Berry AP 385 34 7570 end
	J.		,	

	19.20	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
*	Venez	1-1990	7.1.	4120	The Acoo Houn inspection Completed
1					THIS Dave Battery Serviced, Bapters end.
					CKd. Donate Holled, Captes of Uluga
					ckd. Diked Allanets, Kep med. Rose
1					Tine Replaced, All Tines, luxeets Col &
		•			OK. THIS DOVE ENTERED HOROS CAD.
	>				THIS PROCESTE HAS Seen ing
	TANGO	con	/s/wg	1-171	8300 Mafw An Amadade 1959. Hares
	SIP.	14 L	15	1-172	2 gent Edward & huby the At 141359295
		500	d /d	- JAN Y	1-18 de 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-

DATE RECORDING TACH TODAYS TIME IN SERVICE TOTAL TOTAL TIME IN SERVICE TOTAL T	DATE 19.59	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
3=1-88 Themound & Replaced Donational	MAY28	403	-	3554.8	TOTAL PROPELLER TIME SINCE OVERHALL 1216.2 HR
Replace Attimeter Sh. C902 & Preformed Static	_				PATCH LOWER ENGINE COWLING. CZERN & REPACK NOSE WHEEL, AD 87-20-07 RI SENT RAILS INSPECTED
- ORS Check Sat Sactory, Repair Station					In Accordance (1200+ PORT C (a) (1) THRO (7) FOUND
PS 361-16 AT #2158369					AD 76-07-12 BENDYX SWITCH
Stules Stules of the state of t	,				OPERATIONAL CHECK, ENT BATTERY DUE FEB 1490. "I CERTIFY THAT THIS AIRCRAFT HAS BEELUSPECTED
0/4/88 377 22 Tach Removed insperative artificial Horizon, installed					IN ACCORDENCE USITY AU AUNUAL INSPECTION ANOWAS
wo#2774 costones. Cuttong William ppy 716 77683.	_				DETERMINED TO BE IN GIRWORTHY CONDITION, Thomas E Dokoty 14 767/42
Je J					homas Charagen 181172

9.87	TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
16	293.2			VORS CHECKED OF BMI "O"EXROR Utilbate
2-1				98.88 TT A/C 3450.69
-= 4	INSTAG	Vac	4 NE	WELEVATOR HINGE BOLTS, NEW DOME LIGHT
	REPLA	raeu rce b	-LT BI	GULATOR FILTER AND NEW ELT BATTERY. PITTERY FEB. 1990. YW AD 87-20-03 BY
TRA	PARA.	II (B), (a	(1)(1)(2), (2), (3), (4), (5), (6) AND (7), No
- 1 - 1	PEAC	PROE	O UNIT	ION NEEDED AT THIS INSPECTION. TRANSPONDE
	ALL	CONT	eor Si	IRFACE HINGES AND CONTROL CABLE PULLEY
44.4	BATTE	RY.	PRAINE	EABLES. INSPECTED ALLERON HINGE PINS, SERVED & CLEANED GASCELATOR, PAINTER MAKE, MODEL

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
ANI	5/N 0	NZH	S10€ 0	F FUSELAGE, FORWARD OF STABILIZER
100	RTIFY	THIS	AIRERA	FT HAS BEEN INSPECTED YAIW A 100 HR INSPEC
Tion	AND	AS D	ETERMI	NEO TO BE IN AIRWORTHY CONDITION.
-Feb.	13-88	TT 1/2.	3450.69	Tac 398.88 Jeanard S. Daman P: P484386871
-	Doert	ify th	ct this	Ac has been inspected I/A/w on Annual
- (in	pection	and	was do	termined to be in Mishorthy Condition.
		2		Thugh Denn AP 485 64 53 83 714
_				
_				
_		_		

DATE RECORDING TACH TIME	22 March, 1986 Tach 237 3789 Complied with STC SA1948CE for the use of leaded or unleaded automotive fuel. Fuel must be a	JMBER OF	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
	form 337 this date. Samuel L. Evans		Dec. 29	1986 - A ASEX. Ex	RCRAP	By Part	Indicate NO FORM 337 Completed on Charlend wheels I BRAGE
	Replaced Left main Tile.		1	Not Pag	toFA	Je Reco	ed: at OKA litt FAA AIRCRAPT Records Section on MICROFICE.
	Dearings. Reparted wheels +		JEN-5,19	85 -Cleck	ed 411	CONTRO!	5 - Now BRake pade - R-wheel ONNY, New 6.00 X6-6 THE
	A+P 2 8 2 5 1 8 9			Removed	Rights	hert Do	one - Repaired Loose Rivets in Nings STRAP ON BETH Doche Date To Car T Un TACH: 292.02.
		_	Man. 5	1987 -NO	AK Rec	ands on	FORM 337 FOR I Certify that this AIRCRAFT has been
4/12 241.6 -	VORS CHECKED @ BMI 'O"ERROR WESTE	la		Elomplet	d Foky	337 Thi	inspected in accordance with a ANNUAL
Sept. Market Sept.	The same of the sa			Records -	TA FIG	5. Sly	airworthy condition. The 15 Acts

TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TACH TODAYS TIME IN SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENT	R OF
certify that the Static Pressure System, Altimeter :	
FAR 91.171, Part 43, Appendix F and 5	
Static System Test date 3/3 to 2000 et #1 Altm Model 27 TAUSTS S/N 1/4/ Date 3-/8 25	
#2 Altm ModelS/ND3/	
Altm Enc Model S/N July Air Data Model KING 716 S/N Data 11 IXP Model KING 716 S/N 77.3 Data 2-18-35	
#2 TXP Model S/N Date	
Pertinent details are on file at this Agency under Work Order Number 1977 Signature De Confile	
Skytravel Avionics, Inc. Repair Station #1176	
Adams Field - 2503 Frazier Pike Little Rock, Arkansas	
you cheek at farm satisfit 40 error All	heer
Wor Church at that was a Della	
187,77 NEW 3 DITTERY	

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
9-18-8	5 191.	6	INSTAL	LED. SERVICIABLE PUEL SELECTOR VALVE
		* *	CHECKE	P FOR LEARS.
				Ginny Danel PAP2218299
12-10-85	198.7		3350.5	- Replaced right main time with serucable
			7	tire, Routine maintenance & inspertion
-				Derformed . ELT Battery on order. A'S racord
_			-/	ittached to rear of this lockook Run up ok.
			6	CERTIFY THIS CURCULATE
Et	batte	Ty.		AS BEEN INSPECTED IN ACCORDANCE
ine	talled	1		WITH AN COMMINICAL INSPECTION AND AND AND AND AND AND AND AND AND AN
Goo	Itil 8	87-m	11.	CONDITION Conald Herron
12.	10-85			IA#430922117
	Rett.			

DATE RECORDING TACH TODAYS TIME FLIGHT	TOTAL TIME IN SERVICE DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE RECORDING TOTAL TACH TODAYS TIME IN TIME FLIGHT SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
11-9-	1984	3-5 144.69	VOR CK SKYTRAVEL AVIONICS #1-0
	I CERTIFY THAT THIS ACCOMPANCE WITH		THIS TRANSPONDER OI MAKE SIN 6-MODEL SIN 1773 MODEL SIN
	AN AND HISPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CON-		HAS BEEN TESTED AND INSPECTED AND FOUND TO COMPLY WITH ADDINITY OF PART 43 IN ACCORDANCE WITH FAR 91 172
	TACH TIME 3263		W. 0 # 45/17 DATE 3-18-85 SIGNED B. WILLIAM SKYTRAVEL AVIONICS. INC
	WILLIAM P. HELMS Intellians & Dimis		REPAIR STATION #1176 ADAMS FIELD 2503 FRAZIER PIKE LITTLE ROCK, ARKANSAS
	ARPIA 431942176		

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS RECORDING DATE RECORDING TOTAL ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TODAYS TIME IN TACH TODAYS TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TACH MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) FLIGHT SERVICE TIME FLIGHT SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) TIME 3-1-84 TOMLINSON AVIONICS INC. RT. 3 BOY 10-C PINE BLUFF, ART. 7.501 FAA APPROVED REPAIR STATION #200-2

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE RECORDING TACH TODAYS TIME IN SERVICE TIME OF TIME FLIGHT SERVICE TOTAL TIME TOTAL TIME TOTAL TIME TOTAL TIME TOTAL TOTAL TIME TOTAL
JAN 14					2-6-84 Removed and Jack, Old Jack reading 3/5/. 8
1984		0		REPLACED ELT BATTERY - DUE DEC 1985 BY UNNEL	2-6-84 Removed old Jach. Old Jach reading 3/5/.8. Onstalled new Jach. New Jach reading
1-28-84	3147,51			ATTITUDE INDICATOR (HORIZON) REPLACED.	0000.00.
		r.J.			0000.00. Jelly & ligiton 303/860
- San					
-					
-					
-					
-		-			

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
1-14-85	TACh	3113	9	Rephase nose bowl with
				Jeovice ble used unil.
				26840648 Jos Holm
0-8-83	3120,77		3121,46	Replaced Mose tire & tubes with servedly
-				he runes and julied hearings
	Time 1			WHERE PART,
_				
-				

TODAYS TIME IN ENTRIES MUST E	ION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
3113.2 Replac	e noce bowl with	17.5035	3126	+ 1		Lube puller check cables install new windshield new Strut Fairings
3121,46 Rophosa used us by our	The tire & tubes with permually with parked julied hearings were Bulansan 101574 LED NOSE	5576	mison mison	Te Je		Seinstall wheel pools completely strip & Repaint Aircraft using Dupont Imanon install STC'd wing lips Repair wheel bearings Service haltery
						CERTIFY THAT THIS ACJENG HAS BUSH INSPECTED ID ACCORDANCE WITH AUNUAL 189HE INSPECTION AND WAS DETERMINED TO PENAME WORTHY CONDITION, DATE 1110. TORSUSTINIS 134, THEN THE 3134 AND

PATE 19.23	TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
4	Deil	14/	983	Tlertity That This Aircraft
	111	5 1	een 7	aspected to Acco of acc
	w	05	Foun	Agnual Terpert-on And
	Co.	nd.	1-04	" He Herd of the
To	10/710			.2 0 1.4
Tot		iPig	2	10/13 a 11/C
119	3024	00		1777167
120				TURNE BANK Replaces with
	3070,45			DIL CHANGED FITTERS CHANED
19-83	3073,22			AIR FILTER REPLACED

DATE 2-10-83	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK, PAGES, FOR OTHER SPECIFIC ENTRIES.)
		1 - 4		Water that the Jungonder
				tests of Checks required for
				EAR 91.172 were grefer this
				date and found top coffee
				V Afferd Hofeles
			-	TOMLINSON AVIONICS INC.
				RT. 3 BOX 69-2 /66
_				PINE BLUFF, ARK. 71691
7-20				FAA APPROVED REPAIR STATION #206-2
29-83	3107.43			DIL CHANGED 20050 PHILLIPS
1-5-8	3109,37			REPLACED MAIN TIRES & TUBES, PACKED WHERE BEARINGS
_				

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS DATE TOTAL ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF RECORDING DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TOTAL DATE RECORDING ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TIME IN MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC, ENTRIES.) TACH TODAYS TODAYS TIME IN TACH MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) SERVICE FLIGHT TIME FLIGHT SERVICE TIME 12-2923:45 in factor Declar all serve on the UPL TO BE IN AIRWORTHY CONDITION.

NOT TO BE FLOWN IFR FAL 91-170 DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS DATE TOTAL ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS RECORDING MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TIME IN TODAYS TACH TODAYS TIME IN TACH SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) TIME FLIGHT SERVICE TIME FLIGHT Juni 21 2677:12 Calles Dulkeys of Com 2677:12 VAIL6-21-78 Relat DETERMINEDROSS sherry & Rhimmy dempor TO BE IN AIRWORTHY CONDITION. INSPECTED IN ACCORDANCE WITH A ANN CHACINSPECTION AND WAS DETERMINED David TO BE IN ARWORTHM CONDITION. M 1010/0/

	AIRCRAFT RECORD -	GENERAL INFOR	MATION	
MFG	28/2UL MODEL 0 300 D		72 P FG SERIAL SERIAL	SERIAL 17250412
PROPELLER(S) CURRENTLY INSTALLED. MFG		MODEL		
HUB MODEL	SERIAL		SERIAL	
BLADE MODEL	_ SERIAL	SERIAL		SERIAL
BLADE MODEL	CEDIAL	SERIAL		SERIAL

The Standard









AIRCRAFT LOG AND MAINTENANCE RECORD

N28/22

322 SERIAL NO.17250412

MEMORANDA anuam 36.1976 Meter 2508.5 april 22.1976 annual injusion. Check + ail controls - Replace Date JATE april 22, 1976 I CERTIN THAT THIS AIRCRAFT HAS PISPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETER-MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2508.5 SIGNED To A & P 13481 Sent-10-77 A+P1510757

MEMORANDA Mety 2605.8 Frank Edney 1A + A+P 13481 ANNUAL INSPECTION AND WAS DELY MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2605.8 kg SIC IFO hand Edna 11-13481 A & P 13481 Justalled KX-170, KI-ZOIC, KT-76A, and ADF 31 AB

DATE 73	FLIGHT FROM	то	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMUL TOTA FLYING HOURS	IOTHS	SIGNATURE OF PILOT
nuy.	12,1973	TAG 23	38.6 dn	stall	new	ti	e on BH Wheel.
yplace	both 1	sake line	nis of Odn	9.	RH	137	ape Remove
# E-4	to 48 re	e release	in rest of	this	loc.	Si	wing Company,
1	I	certify that t	nis aircraft	e has be	en		
	ir	spected in ac	cordance with a	o be in	11		
		orthy condition					
		ate NOV 12	, 773 Total ti	ne 233	8.6		
		marke	ell RC	aus			
		Maxwell R	Crausby A&P 1	317680 V			
		-		y nan			

Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. Manuary 28.1975		Alle IIII
and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. Lannany 28:1915 Annual misquism. Chule and aid controls. Annual whole the following the first whole the firs	DATE	
ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. Annuary 28:1975		Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters -
JATE PHART JASSAN LANDS OLING THAT THE ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2403 138 he. SIGNED Land Contact 1848		and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK."
JATE PRIMARY 281973 I CELL Y THAT THIS AIRCRAFT HAS a PISPECTION AND WAS DETERMENT AND ANNUAL INSPECTION AND WAS DETERMENT AND SIGNED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2493138 hum. SIGNED Land Column 1413481		ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
JATE JAMEN 281973 I CE: IN THAT THIS AIRCRAFT HAS COURSE TO BE IN AIRWORTHY CONDITION. JOHN TOTAL TIME 249338 ht. SIGNED LAND LAND MAS DETER. SIGNED LAND LAND MAS JET R.		Vannay 28.1975 annual injulian. Chel and ail controle, Green while.
JATE JAMES 28, 1973 I CENTRY THAT THIS AIRCRAFT HAS L PISPIC ED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR MINED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2403 38 hr. SIGNED Land Language 13421		INITIAL DE MILL CAECO III -
JATE JAMES 28, 1973 I CENTRY THAT THIS AIRCRAFT HAS L PISPIC ED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR MINED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2403 38 hr. SIGNED Land Language 13421		teamments and antenna or Lucialage at vertical slabely is bright & better
JATE JAMES 28, 1973 I CENTRY THAT THIS AIRCRAFT HAS L PISPIC ED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR MINED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2403 38 hr. SIGNED Land Language 13421		us letel are 337 this date I mitall placed agreed for they thight to
JATE JAMES 28, 1973 I CENTRY THAT THIS AIRCRAFT HAS L PISPIC ED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR MINED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2403 38 hr. SIGNED Land Language 13421		on per 74-74-13, Course with 74-18-05 Slick Marito courses
JATE JAMES 28, 1973 I CENTRY THAT THIS AIRCRAFT HAS L PISPIC ED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR MINED TO BE IN AIRWORTHY CONDITION, TOTAL TIME 2403 38 hr. SIGNED Land Language 13421		Jackameter - 2405, 38. M. FAA-ADS cheked then 75-2 as I'm -
PISPIC PD IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR. MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2403 38 hs. SIGNED Land Land 1813 481		
PISPIC PD IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR. MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2403 38 hs. SIGNED Land Land 1813 481		
PISPIC PD IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETAR. MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2403 38 hs. SIGNED Land Land 1813 481		JATE January 28,1975
MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 2403:38 hs. SIGNED Land Land Land 181348		CERTARY THAT THIS AIRCRAFT HAS L
MINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 3403.38 hs. SIGNED Land Edward 184348 f		TISPEC, ED IN ACCORDANCE WITH AN
SIGNED Land Carry 18 13481		
SIGNED Land Carry 18 13481		MINED TO BE IN AIRWORTHY CONDITION.
Market and the second of the s		
A & P 15481		SIGNED Land Edny 1813481
		A & P 19481

			AIRCRAFT	LOG			1	AIRCRAFT LOG
DATE 19 72	FLIGHT FROM	то	FLIGHT	FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS IOTHS	PILOT	DATE 19_72	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
men to	the on le	Jun stri	whell of n	rose m	cheel. Re	ted . dustall aloce loves bolt	1	if g air. MR Crowney AT 81817680
CWAD		Placovel I certify that	this aircraft ca	ine has	peen		Jine	1,1973 to 2321.5 Replace both Sing on LH Brake.
		All A.D. notes	through 72-19	C/W				
		Maxwell	1972 Total gwelf (): (R. Crausby A&P	1817680	85,6			
		Censyst	thin carthe	gatin				
CARRY FORW	VARD THE TOTAL AC	CUMULATED FLYING 1	TIME TO THE TOP OF NEX	T PAGE				

AIRCRAFT LOG	AIRCRAFT LOG
DATE FLIGHT TO NATURE OF FLIGHT FLIGH	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
9-11-71 TAC 2131.8 (TOTAL) arrelast cleaned of annual mine completed. complied with 71-18-1 more tanks. Feel sel temporal maked centil placered is carrilable. duilable in mine in left tank after children tire on Right main. as int elevrite cables.	Apr 20, 1977 Ton 2203.0 Sustall new Batter Reliat 525 MR Clausty At P/8/7680 may 12, 1972 Comine coul repaired by replacing following Cause part 0552010-17 skim, 0552010-45 doubles, 0552010-46 doubles. MRCrause 44 P 1817680
inspected in accordance with a A. W.A. inspection and was determined to be mail worthy condition. All A.D. notes through 7/~/8 C/W Date 9 - //~ 7/ Total time 2/3/28 Maxwell R. Crausby A&P 1817680 /A	
11-12-71 metall 6511167-20 placerd 12 14 D 71-18-11 May 1517680 CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE	

	AIRCRAFT LOG
DATE	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endormement of a certificated mechanic, and his rating and certificate number must be shown.
n accordar letermined Lime in Se Lact. Time Signature_ HI-A	that this UZZZZZ has been inspected inspection and war to be in airworthy condition. ervice 1994:75 Date of Insp. 9/6/70 1994:75 Work Order No. 1991 IR, INC./ pair Station No. 5471
Men 245	nphis Metro Airport 1 Democrat Road nphis, Tennessee
Ju	ne 18, 1971 row 2094.5 suitalf consider Suit # 511 172. Bound

	AIRCRAFT LOG
DATE	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
Aub-14-	all Cobbe, Pullent Turnbukles inco all wheel frances reporked.
	Flight Contraled checked. Electuif system Checked. Buttery + Bukes
	Ferried in accordance
	I certify that this aircraft has been inspected in accordance
-	with a Joolus: inspection and was determined to be
	in airworthy condition.
	AU-14-1969 1821: fre.
	Date Total time
	1 10 when 12 pt 1379726
	June 1 Learning that this aircraft has been inspected in accordance
	(A) & M Flying Service, Inc. 357-3865 vith a ANN A inspection and was determined to be
	in airworthy condition.
	8/14/69 1821.2
	Date Total time
	Lal Kay A. A& PAI 1571125
	A & M Flying Service, Inc. 357-3865

				. O G	L	AIRCRAFT			
DATE Enter here genera and changes in pro ALL DATA must	SIGNATURE OF PILOT	IOTHS	ACCUMUI TOTA FLYING HOURS	ATION F GHT	0	NATURE OF FLIGHT	то	FLIGHT FROM	DATE
1-29-69 The LEDR	beacon bull replaced	tan	rota	neu	red	n tires repla	Both main	1968 6	Peril 9
LEAR Total	cables and	el?	estalle U con	and	de	ft whl cylin	e-hauled leg wheel bear	as as	
NEW A NEW E					97120	ATION, INC.			
Maxim			PENNIN TENNIN	4 / MI	rd-	spected in according to inspection a	engine was in	craft,	
This East			ristals Innt	nined	inent file	e in airworthy /66/.0. Perti pection are on	. Total time s of this ins	dition detail	
ON FAA Added To			Total	15	148	Brazid 1A 15	m. 0.0		
Weight + 1 Computed					XT PAGE	TIME TO THE TOP OF NEX	CCUMULATED FLYING	RWARD THE TOTAL A	CARRY FO

REMARKS al data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters ropeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. Following Equipment Kemored From AireROFT TRACTEDUSCEVIER 2214 CONVERTER + POWER SUPPLY 2215 Indicator- MARKER ANTERNO + Cables. 40 EMATY WEIGHT 1376, 0 LbS: 37,3 Ins AFTOF Datum 924,0 Lbs. 3200.0 Lbs UMI WEIGHT 12 Hed And Wright + Balanes Computed FORM 337 Dated 12/24/64. Equipment Was Not Equipment List. No Record de Removal OR Baldnez Correction Was Made-Weight + Balance 1-Wzight + Balance Sheet CORREcted By. Lee R. From L.
A+PAI 1571125 1-28-69

AIRCRAFT LOG								AIRCRAFT LOG		
DATE	FLIGHT FROM	то	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME HOURS IOTHS	SIGNATURE OF PILOT	DATE 19_67	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.		
	I certicated and was detected dition. details at this	th a 100 M2 ermined to be Total time 1 of this insp agency under	ON NO. 4632 9-6/ this air- ected in accord- inspection and in airworthy of 173-58 Pertinection are on fi	nt le	No acco	DERCINE SVIATION LOS STRANCE STATION LOS STRANCES STATION LOS STATIONS SAND SAND SAND SAND SAND SAND SAND SA	9-26	ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. Belline replaced this date - Mose gea fairing mustabled new 7.7.1546:44 Malcolm Brayia 181544815 I certify that on 1145 1967, the aircraft / engine was inspected in according with a 100 MR inspection and was determined to be in airworthy condition. Tach time 1599.0 by Malcolm Brayia Total A/C time 1599 o A& 1599 114		
CARRY FOI	RWARD THE TOTAL A	CCUMULATED FLYING	TIME TO THE TOP OF NEX	XT PAGE		STORES		file at this agency under W.O.#@335		

AIR	CRAFT LOG		AIRCRAFT LOG
TO	TURE OF DURATION OF FLIGHT FLIGHT	ACCUMULATED TOTAL SIGNATURE OF HOURS IOTHS PILOT	DATE REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
7-26 T.T. 1164:13 IHRS Plew recap tires installe cleaned + greased. Both 30045 ACCW	on both me in Brazio Axp	gen craws wheel bearings	H-25 Alh Control Cables, hinkeye and surfaces checked Alf Efactorial Sestems, Fuch Systems and Phomburg, and Hydrolic System and Phomburg Check Ok. Majurgear, Bearings and Moss wheel Bearings changed and Regarded, Light Majuriae Reglaced, Sand Brake himse, Right Brake Replaced, BETLINE AVIATION, INC. FAA REPAIR STATION NO. 4632 The aircraft and/or component identi- fied above was remired and inspected craft/engine was inspected in accord- in accordance with current civil air ance with a Annual inspection and societies and found airworthy was determined to be in airworthy con- for return to service. Pertinent de- details of the repair are on 1:50 at this details of this inspection are on file seeds where was related and inspected details of this inspection are on file
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE	HE TOP OF NEXT PAGE		Signed Hershell R. A. 1744010
			01(01)

AIRCRAFT LOG	AIRCRAFT LOG
A I R C R A F T L O G DATE FLIGHT TO NATURE OF FLIGHT FLIGHT FLIGHT FLIGHT FLIGHT FLIGHT FLIGHT FLIGHT FLIGHT HOURS 10THS PILOT A I R C R A F T L O G NATURE OF DURATION OF. FLYING TIME FLYING TIME HOURS 10THS PILOT PILOT PILOT REELINE AVIATION, NC. 1 certify that on FEB 11960, his orieraft / engine was inspected in accordance with a 100 HB inspection and was determined to be in always to addition. Tach time 999.90 Mala Arranga	AIRCRAFT LOG DATE REMARKS Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. BEELINE AVIATION, INC. I certify that on 28 / 1966 this aircraft / segine was inspected in accordance with a error of the certification. BEELINE AVIATION, INC. I certify that on 28 / 1966 this aircraft / segine was inspected in accordance with a error of the certification. BEELINE AVIATION, INC. I certify that on 28 / 1966 this aircraft / segine was inspected in accordance Total A/C time 1995 50 by for the certification are on determined to be in airworthy condition. Total A/C time 1995 50 by for the certification are on file at this agency under W.O. # 1545
Total A/C time // A 2/5-9/48//S Pertinent details of this inspection are of file at this agency under W. O. # /4/5-4 CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE	Total A/C time/195, 50A&E / 22594 Pertinent details of this inspection are on file at this agency under W.O.#/565

DATE FLIGHT TO		O G TON ACCUMULATED TOTAL FLYING TIME HOURS IOTHS	SIGNATURE OF PILOT	DATE	AIRCRAFT LOG REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
l certify that on aircraft / engine was with a determined to be in Tach time Poole Total A/C time Poole Pertinent details of the second	by Paul Bayes A&F / 525 5/4 I this inspection are on under W.O.# / 205				BEELINE AVIATION, INC. I certify that on 23 New 1945, this aircraft / Sine was inspected in accordance with a 100 inspection and was determined to be in airworthy condition. Tach time 9/1.40 by Caule Basic Total A/C time 9/1.40 A&E 1525544 Pertinent details of this inspection are on file at this agency under W.O.# 1341

	FLIGHT			DURATION A	ACCUMUL AT			AIRCRAFT LOG
19 4 5	FROM	ТО	NATURE OF FLIGHT		TOTAL FLYING TIME HOURS IOT	SIGNATURE OF	19	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
l certify aircraft / with a determined Tach time Total A/C Pertined file at the	to be in airwork Local by time Lod. 0 t details of this in is agency under the	1965, this cted in accordance section and was thy condition. A&E / 5275/	AI AC IN TO	TES 7-45 CORDAN SE WISPECT IN A REI HAROID IN A&P J	TACK	THAT THIS PIO DIC TEMINED DITION		BEELINE AVIATION, INC. I certify that on 14 floric 1965, this aircraft / stains was inspected in accordance with a 100 inspection and was determined to be in airworthy condition. Tach time 203.0 by Paul Congress. Total A/C time 203.0 A&E / 52 5 544 Pertinent details of this inspection are on Cle at this agency under W. O. # 1/244

			AIRCRAFT					AIRCRAFT LOG
19 64	FLIGHT FROM	то	NATURE OF FLIGHT .	DURATION OF . FLIGHT	N ACCUMULATED TOTAL FLYING TIME HOURS IOTHS	SIGNATURE OF PILOT	DATE	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
	BEE	LINE AVIATION,	INC.					ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
	I certify that aircraft / eng	on 2 Dec	d in accordance					BEELINE AVIATION, INC.
	with adetermined to	o be in airworthy	tion and was					I certify that on FEB.15 1965, this aircraft / engine was Inspected in accordance
	Total A/C time	me 404.0 by As details of this inspe	ELIZES14	2				with a 100 HR inspection and was determined to be in airworthy condition.
	file at this e	agency under W.	0.# 944					Total A/C time 499.79 A&E/5-44815
								Pertinent details of this inspection are on file at this agency under W.O.#1000
CARRY FOF	WARD THE TOTAL AC	CCUMULATED FLYING T	TIME TO THE TOP OF NEX	(T PAGE				

DATE 19	REMARKS Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
	Installed kan 150AG (unce Marco V5P39 little Bit)
/	337 To be executed () I full his)
	#1) The component identified on Work
	accordance with annual Cities and State and St
	a map round sirworthy for retain to
	Date 1-31-64
	MERCUT AVIATION COPP.
	FAA Station No. 4039 Airframe Class I, III
	Radio Class I, III Hanger #8
	Tucson International Airport Tucson, Arizona

			AIRCRAFT	LOG	j			
DATE	FLIGHT		NATURE OF					AIRCRAFT LOG
*	FROM	ТО		OF.	ACCUMULATED TOTAL FLYING TIME	SIGNATURE OF	DATE	Enter here general data with reference to W.L. III. III.
19	· itom		FLIGHT	FLIGHT	HOURS IOTHS	PILOT	1964	and changes in propeller or engine — as outlined in the front of this book, under the heading. "INSTRICTIONS — Repairs — Service Letters —
								the characteristic of a certificated mechanic, and his rating and certificate number must be shown
				<u> </u>			+19 NOV.	6.4 Talle sime 387.86 - 1. H. Ming Bringge
		<u> </u>					1,,	
				1 P				Repaired New Rear Span Sectioned to inbury
		//		1				Sta 23.625 10 100, 1/N 0523400-51, Replaced.
M-1								Sta 23.625 To 100. PN 0523400-51 Replaced. Retento FAA Form 3.32 For Details. Alla Mork Performed Heading To Ming. Specifications
		/						mort fertamed the Tomber Sun Fact
								10 / Jell 100 1000
		BEELI	THE AVIATION, INC					Gall Brage 1/2/525514
		I certify that	1				19 NOV.	
		+ 1.1.	on 24 Hug	1964, thi			1-7 NOV.	
		aircraft / c.	11	accordance			,	Right wine, Regar, And Found to
		with a 10	o inspection	and was	A		-	
		determined to	be in airworthy con	ndition				be in Histyarthy Coastitions
		Tach time 3	304, by Ga	100			•	Now Barker C1437768
		Fot I A /C time	2	me 15	ager!			
			THE ACT	15255	4			
		Pertinent det	etails of this inspection	on are on		-	4	
		file at this as	sency under W O II	1 SPC			1	
		1	Joney onaci II. O. W	1				
CARRY FORW/	ARD THE TOTAL AC	CCUMULATED FLYING	TIME TO THE TOP OF NEXT	TRACE				
				PAGE				

AIRCRAFT LOG DATE REMARKS Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK," 1964 ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown. 100 HR. INSPECTION COMPLETED THIS DATE, AIRFRAME, CONTROLS, & CABLES CHECKED - TIRES & BEAR BOX'S CHECKED ALL SURFACES, SKIN, & WINDOWS CHECKED TACH TIME 209:49 HRS. I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH 100 HR INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION Malcolm Brazie at P 1544815 July 7 th 1964

	AIRCRAFT LOG						
DATE	DEM A DUC						
	Enter here general data with reference to "I hell and III and						
19 63	and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LGG BOOK."						
=	to destructed incomance, and his rating and certificate number must be shown.						
23 VUL	1863 Tock Time 6.0						
	Installed Redio- Name Mark IV Such						
	en recordance with cossis there verine						
	Manualo Keter To Form 332 Dated 23 July 1063						
	For Wto & Balance						
1	Gant Brager 1525514						
0							
apral	1964 Jack READS 100.0 REPLACED BRAKE DISAS						
1 "							
	both mains.						
	CERTIFY THAT THIS HIR FRAME HAS BEEN I CERTIFY THAT THIS PROCEED HAS BEEN						
	INSPECTED IN ACCORDANCE WITH A 200 his INSPECTED IN ACCORDANCE WITH A Prevodice						
	JANO WAS DETERMINED BY DE IN AIN						
	C. MOITION.						
	Bernard Pert WORTHY CONDITION.						
	MECHANIC (Matthew To Man)						
	A&P # I/4 /3/6940						
	DATE Cype 21, 1964 DATE A DR 21, 1964						
	ACH. 100, 0 HOURS TACH 100, 0 HOURS						
	TACH, management to the Company of t						

DATE			AIRCRAFT	LO	G			
19 63	FLIGHT	то		QF, FLIGHT	ACCUMU TOT FLYING	JLATED AL TIME		DA 19
	Weehite	Found	Lest		5	12	Jumer.	
								-1
U. T.				-		1		
1								-1
								-
-								
-								_
CARRY FO	RWARD THE TOTAL							
	WARD THE TOTAL AC	CCUMULATED FLYING	TIME TO THE TOP OF NEXT	PAGE				

9	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Cha and changes in propeller or engine — as outlined in the front of this book, under the heading ALL DATA must bear the endorsement of a certificated mechanic, and his rating and cer	g, "INSTRUCTIONS FOR USE OF THIS LOG BOO
	I have inspected this aircraft and found it complies with the requirements of CAR 1.67. All mandatory changes have been complied with. Certificate of Airworthiness dated June was issued by me. DMCR 3-1 Executive Engineer, Commercial Div. CESSNA AIRCRAFT COMPANY D. ESTH TOSIN	



AIRCRAFT LOG AND MAINTENANCE RECORD

Record of Consider	1720 Skalisenke 17	250412	0/15/3/11
With Engine Contental	Model Model	Serial 2790	
From	19to		Serial
Detailing Time From	То	Hours	
Owner		,	* *
Address			