

☐

Propeller

HC-C3YR-1RF

S/N PA1155B

Date

9/2/2024

TTSN

528.6

TACH

1918.6

TSMOH

Ye

HOBBS

TSPOH

N/A

Da

Ne

Di

I certify that this propeller has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

=

SIGNED



Ye

Kevin Booth A&P/IA 2764111

Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #
Year: _____	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HARTZELL PROPELLER INC

INSPECTION

Item Number: C3R00022

Date: 6/2/2015

Work Order #: M332970

Model Number
HC-C3YR-1RF/F7282

Ass'y Ser No. PA1155B	Hydr Unit No. NA	Bulkhead No. NA	Rod NA	Piston NA	Cylinder NA	Fork NA
Blade 1: L60854	Blade 2: L60855	Blade 3: L60856	Blade 4:	Blade 5:	Blade 6:	
Clamp 1:	Clamp 2:	Clamp 3:	Clamp 4:	Clamp 5:		

Reverse NA	Start Lock NA	Low Pitch 12.5	High Pitch 30.0	Feather NA	Position 2	Orient. L	Qty: AI 1	St 0	Scrw 0	A-2424-1 0	Washer 0
Ref Radius (inches) for angles: 30					3	T	0	0	2	0	0

Comments:
Deice Kit: NAPacking
Certified By: _____ Date: _____

Inspected By: Tim Jess

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

The propeller covered by this certificate has passed a functional test as required by 14 CFR Part 21.137(e)(2).

Mech. Cert. # or Repair Station # _____

PROP MODEL:
HC-C3YR-1RF/F7282
PROP S/N: PA1155B
REG. NO: N2689W
WORK ORDER:
1096-06-2023

GoldStrike Aircraft Services

2705 Airport Dr
North Las Vegas, NV 89032
Phone: (702) 899-1150DATE: 9/12/2023
A/C TSN: 3627.97
PROP TT: 487.97
TSPOH:
TACH: 1877.97ALTERATIONS ☐

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.
New propeller log created. Checked Airworthiness Directives through bi-weekly 2023-18. See Hartzell Propeller Inc. Inspection form number C3R00022.
Total time adjusted from engine log entry dated 11/10/2015 mentioning new propeller installation.

The aircraft and/or component(s) on N2689W was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details and any inspection packages are on file at this facility under work order number 1096-06-2023.

DATE: 9/12/2023

SIGNED:

Work Order: 1096-06-2023

Mark Blackwood, A&P: 4484732

Printed by EBis 3 (datcomedia.com)

Due:

Overhaul

Mech. Cert. # or Repair Station # _____

Year: _____

Total Time
in Service

Description

Date: _____

Next Inspection
Due:Time Since
Overhaul

Mech. Cert. # or Repair Station # _____

Propeller Record General Information

Propeller Manufacturer HARTZELL

Model HC-C3YR-1RF/F7282

Hub Series # S/N: PA1155B

Date of Manufacture 6/2/2015

Type _____

Blade # 1: L60854

2: L60855

3: L60856

Make/Model

Aircraft Installed On: MOONEY M20E

Serial #

1006