

The Standard
AIRCRAFT LOG

ASA/SA-2

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

wo: WO_652



Airframe - page 1 of 2

Romanair WDR, Inc. - 839 Ronald Wood Road - Winder, GA 30680

N66189

Tach: 3261.5

CESSNA, 172P, S/N: 17275976

AFTT: 3261.5

October 09, 2023

Annual Inspection performed per 14 CFR Part 43 Appendix D, using a Romanair check list.

1. Pre-Inspection ground run & systems operational check completed.
2. Removed cowlings & inspection panels as necessary.
3. Airframe inspected & lubricated.
4. Fuel Filter Assembly cleaned & inspected.
5. Battery cleaned, charged & inspected.
6. Induction Filter Removed & replaced with new p/n-BA-6108.
7. Exhaust System visually inspected & pressure checked including heat exchanger.
8. Brake Reservoirs serviced with MIL-H-5606 fluid.
9. ELT inspected & tested per 14 CFR Part 91.207(d). Battery expires September, 2024.
10. Instrument Air Filters replaced with new Inlet Filter p/n-AAD9-18-1 & Relief Filter ARB-3-5-1.
11. Engine Cowling Lord mounts replaced as needed with new p/n- J-7444-14.
12. Starter replaced with new p/n-149NU/EC, s/n-H-X072761.
13. Starter Contactor replaced with new p/n-S2443-2.
14. Starter wire from starter to contactor replaced with new M22759/16-0 wire.
15. Tires serviced with air.
16. AD's researched at this time.
17. AD2001-23-03 complied with by visual inspection per AD para (d). Next due 10/2024.
18. AD2011-10-09 complied with by visual, dimensional & functional inspections per AD para (g). Next due Tach: 3361.5 or 10/2024.
19. Reinstalled cowlings & inspection panels.

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

wo: WO_652



Airframe - page 2 of 2

Romanair WDR, Inc. - 839 Ronald Wood Road - Winder, GA 30680

20. Washed Aircraft.

21. Post-Inspection ground run & systems operational check completed.

I certify this AIRCRAFT has been inspected IAW an ANNUAL inspection & was determined to be in AIRWORTHY condition. Additional details of work performed are on file with Romanair WDR, Inc. under WO_652.

Drew Mancini A&P/IA 2720159

Blue Ridge Sport Flight LLC.

419 Bradshaw Ave. Hendersonville, NC 28792

N66189 Cessna 172P S/N 17275976 Tach: 3280.2 AFTT: 3280.2

All cowlings and panels removed, controls lubricated, airframe inspected. Bearings lubricated. Exhaust, fuel filter, battery, propeller inspected, all in accordance with FAR Part 43. ELT inspected IAW 91.207(d), battery replaced, due Sept. 2026. AD's researched, AD2001-23-03 complied with, due 10/2025. AD2011-10-09 complied with, due at 3380.2 Tach or 10/2025. I certify that this aircraft has been inspected IAW an Annual Inspection and is an Airworthy Condition as of 10/17/2024.

Gregory S. Collins 2745213A&P/IA

ELT Battery
good until
Oct 2026

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------	---------------------------	------------------	-----------------------------	---

wo: WO_243



Airframe - page 1 of 1

Romanair WDR Inc. - 839 Ronald Wood Road - Winder, GA 30680

N66189

Hobbs: 435.6

CESSNA, 172P, S/N: 17275976

Tach: 3247.9

March 21, 2022

Main Battery installed new Gill P/N G-243 S/N G03149998 per Cessna 172P Service Manual and Gill Teledyne Battery Products CMM TBP 1560 Rev I and Dwg #1700-90 Rev A. ICA Capacity Test next due at 800 FLT Hours or 12 Months (TACH: 4047.9 or MAR 2023).

This Aircraft is approved for return to service with respect to stated work performed in accordance with Title 14 CFR Part 43.13. Details of work performed are on file with Romanair WDR Inc. under work order: WO_243.

Vincent A. Wolczek A&P/IA 40784739

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------	---------------------------	------------------	-----------------------------	---

wo: WO_291



Airframe - page 1 of 2

Romanair WDR Inc. - 839 Ronald Wood Road - Winder, GA 30680

N66189

TACH: 3252.1

HOBBES: 440.6

CESSNA, 172P, S/N: 17275976

AFTT: 3252.1

ENG TSO: 1318.1

August 04, 2022
ENG TT: 3252.1

- 100 Hour/ Annual Inspection complied with per Manufactures Maintenance Manual, Approved Check-list, and Title 14 CFR Part 43 Appendix D.
- Performed pre-inspection ground performance test of systems, recorded engine parameters.
 - Static compression test results: 70,73,76,74 /80.
 - Removed inspection panels.
 - Inspected airframe and lubricated.
 - Inspected engine and lubricated controls.
 - Cleaned, inspected and lubricated wheels and wheel bearings.
 - Reinstalled all inspection panels.
 - Performed post-inspection ground performance run and function test of systems and recorded engine parameters.
 - Washed Aircraft.
- Main inlet/pressure filter installed new P/N AAD9-18-1. Relief filter installed new P/N AR B3-5-1.
- Fuel filter assembly cleaned and inspected filter and bowl.
- ELT temporarily removed for repair. Placarded Instrument panel as required per Title 14 CFR Part 91. 207(f) (10) (i) (ii). Continued Operations valid through 07 NOV 2022.

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19__				

wo WO_85



Romanair WDR Inc. - 839 Ronald Wood Road - Winder, GA 30680

Airframe - page 1 of 2

N66189
AFTT: 3242.3CESSNA, 172P, S/N: 17275976
HOBBS: 428.5

June 17, 2021

1. Performed Ground Performance run of engine and aircraft systems.
2. Inspected seat rail IAW AD2011-10-09. No Defects Noted this date
3. Installed new seat stops (2) P/N 0511242-1.
4. Removed fuel filter assembly. Cleaned and inspected filter and bowl. Installed (1) MS29513-111 - O-Ring, (1) MS29513-138.
5. Replaced main inlet filter with a new AAD9-18-1 filter. Replaced relief filter with a new B3-5-1 filter.
6. Serviced battery on 24V battery minder.
7. Serviced Battery with distilled water. Cleaned terminals and protected with T-9.
8. Serviced brake reservoirs with 5506 fluid.
9. Removed ELT. Battery due 6/2022. Inspected & tested ELT IAW FAR 91.207(d). No defects noted this date.
10. Calculated airframe total time & component times. Performed AD note research & compiled list of applicable AD's.
11. Installed a new Induction Air Filter Element P/N BA6108.
12. C/W AD 2001-23-03 Door Post Map Light per AD instructions. No defects noted this date. Next inspection Due 06/20/22.
13. C/W AD 2011-10-09 by visual, dimensional inspection IAW AD 2011-10-09 instructions. No defects noted. Next inspection Due 06/20/2022 or Hobbs 528.5.
14. Researched AD2020-18-01 requirements and procedure AD Not due until 4000 hrs. TIS.

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19__				

wo WO_85



Romanair WDR Inc. - 839 Ronald Wood Road - Winder, GA 30680

Airframe - page 2 of 2

15. CPC Treated and Cleaned Minor surface corrosion as required and applied LPS 3 as required.
16. Installed new cowling mount isolators (3) P/N J-7444-14 - Lord mount, Installed (7) MS21045-08 - Locknut, Installed (7) AN525-832R9 - Screw.
17. Applied RTV to secure Throttle cable to fire wall.
18. Installed new Cabin heat hose Duct P/N 05-30612.

Annual/100 Hour Inspection complied with per Manufactures Maintenance Manual. Approved Checklist, and FAA Title 14 CFR Part 43 Appendix D. I Certify that this Aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition this date.

With respect to the work performed, this Aircraft is approved for return to service. Details of work performed are on file with Romanair WDR Inc. under work order: WO_85.

Matt Barnard A&P/IA 3395206

DATE 19__	REG. #: N66189	DATE: March 2, 2018	NS (BER OF ENTRIES.)
	TACH: 3193.1	HOBBS: 367.9	TT: 3193.1
AIRFRAME Opened aircraft as needed to inspect & lubricate all control cables, pulleys, push/pull rods, bell cranks, & control hinge points. Replaced ship battery with new G-243 battery & serviced. Cleaned & inspected fuel filter. Replaced instrument air filters & induction filter with new. ELT tested IAW 91.207(d) & new battery installed, battery due 2/2020. Replaced elevator & rudder bushings w/new McFarlane bushings. Installed new LH brake master cylinder anchor. Installed new GE4587 taxi light. Installed new MC0756005-2 gascolator top. This action terminates the repetitive inspection required by AD2000-06-01. C/W the following AD's: AD83-22-06 via visual inspection IAW AD para (a)(1), this action terminates this AD. AD2001-23-03 via visual inspection IAW AD para (d). AD2008-26-10 via visual inspection IAW AD para (e)(2), this action terminates this AD. AD2011-10-09 by visual, dimensional & functional inspections IAW AD para (g). "I certify this AIRCRAFT has been inspected IAW an ANNUAL inspection using a Romanair check list & was found in an AIRWORTHY condition." ***END***			
Mechanic <u>MANNSUG AP3736101 IA</u> Romanair WDR Inc.			
	REG. #: N66189	DATE: September 27, 2018	
	TACH: 3202.9	HOBBS: 380.4	TT: N/A
AIRFRAME Replaced master switch w/new S1994-1-1 switch. Replaced nose strut packings w/new & serviced w/5606 & nitrogen IAW Cessna AMM. Installed Enhanced Flight battery charger harness, p/n BM-AIK2A, IAW Enhanced Flight instructions & AC43-13. Ops check of replaced/installed components OK. ***END***			
Romanair WDR Signed: <u>MANNSUG AP3736101</u>			

DATE 19__	REG. #: N66189	DATE: April 23, 2019	TIONS (NUMBER OF ENTRIES.)
	TACH: 3209.1	HOBBS: 387.7	TT: 3209.1
AIRFRAME Opened aircraft as needed to inspect & lubricate all control cables, pulleys, push/pull rods, bell cranks, & control hinge points. Serviced ship battery. Cleaned & inspected fuel filter. Replaced instrument air filters & induction filter with new. ELT tested IAW FAR 91.207(d), battery due 2/2020. Replaced landing light w/new GE4596 lamp. C/W the following AD's: AD2001-23-03 via visual inspection IAW AD para (d) & AD2011-10-09 by visual, dimensional & functional inspections IAW AD para (g). "I certify this AIRCRAFT has been inspected IAW an ANNUAL inspection using a Romanair check list & was found in an AIRWORTHY condition." ***END***			
Mechanic <u>MANNSUG AP3736101 IA</u> Romanair WDR Inc. 820 Donald Wood Road Winder Ga 30680			
	REG. #: N66189	DATE: August 29, 2019	
	TACH: 3218.5	HOBBS: 399.0	TT: N/A
AIRFRAME Removed LH nav light assembly. Installed uAvionix SkyBeacon, p/n UAV-1001856-002, s/n 1005487 IAW STC SA04362CH. See FAA Form 337 dated this date. ***END***			
Romanair WDR Signed: <u>MANNSUG AP3736101 IA</u>			

DATE
19__

AIRCRAFT AVIATION SERVICES.
JACKSON COUNTY AIRPORT { JCA }
706-540-1895

ERATIONS
TE NUMBER OF
CIFIC ENTRIES.)

DATE: OCT 3, 2016
REG. NO: N66189

TACK TIME: 3,157.7
MODEL: 172P

REMOVED ROCHESTER TACHOMETER FOR OVERHAUL PART # 3320-00011,
SERIAL # 682 UNIT OVERHAUL BY RUDY AIRCRAFT INSTRUMENTS. WORK
ORDER 48431, UNIT REINSTALL AFTER OVERHAUL.
REMOVED SHIMMY DAMPER AND INSTALL ALL NEW SEAL AND SERVICE
WITH 5606 HYD. FLUID AND REINSTALLED. SERVICE TIRE WITH AIR.
WASH AIRCRAFT 258969139 A/P

THIS ENTRY OUT OF CHRONOLOGICAL ORDER

REG. #: N66189

DATE: July 25, 2017

TACH: 3177.4

HOBBS: 347.2

TT: N/A

AIRFRAME

Replaced the following components, with new, on the NLG wheel as follows; (1) Michelin
Airstop 5.00x5 tube, (4) 153-00800 spacers, (2) 154-00500 felt seals, (1) 0543003 axle
tube & (2) 0543037-1 spacers. Inflated wheel IAW POH. No leaks noted. ***END***

Romanair WDR

Signed:

Monty AP3395206

DATE
19__

RECORDING
TACH
TIME

TODAYS
FLIGHT

TOTAL
TIME IN
SERVICE

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS
ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF
MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

REG. #: N66189

DATE: October 10, 2017

TACH: 3190.1

HOBBS: 363.3

TT: N/A

AIRFRAME

Replaced all nose gear torque link bushings w/new. Serviced shimmy damper w/MIL-H-
5606 fluid. ***END***

Romanair WDR

Signed:

Manning AP3736101

Registration # N66189
Make Cessna
Model 172P
Serial # 17275976
Work Order # 13082

Hobbs 368.2
Tach 3193.2
AFTT --

AIRFRAME

GEORGIA AVIONICS

CRS# GX4R222M

841 Ronald Wood Road, Suite B, Winder, GA 30680

The altimeter and static system tests required by FAR Part 91.411 have been accomplished.
The altimeter was tested to an altitude of 20,000 feet and found to comply with FAR 91.411.
The ATC transponder was tested and inspected and found to comply with FAR 91.413.

Aaron Burkhardt
Aaron Burkhardt 6068

27-Feb-18
Date

DATE 2015 RECORDING TACH TIME TODAY'S FLIGHT TOTAL TIME IN SERVICE

7730 8601-188 (BAH)

MAKE CESSNA MODEL 172P

THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY F.A.R. PART 91.411 HAS BEEN PERFORMED THIS DATE 6 OCT. 15

ALTIMETER TESTED IN COMPLIANCE WITH APPENDIX E PART 43 TO 2000 FEET DATE 6 OCT. 15 STATIC SYSTEM CHECK PERFORMED BY RAY ALLEN'S ELECTRONICS, INC. BUTLER, GA. F.A.A. R/S#HS4R243M

SIGNED Ray Allen DATE 6 OCT. 15

UNITED STATES AIRCRAFT

DATE 6 OCT. 15 I CERTIFY THIS ATC TRANSPONDER (MAKE) KING (MODEL) KT-76A

(SERIAL#) — HAS BEEN TESTED, INSPECTED AND FOUND TO COMPLY WITH APPENDIX E OF F.A.R. 43 AND PART 91.413. FAA. R/S#HS4R243M

SIGNED Ray Allen DATE 6 OCT. 15

TESTS PERFORMED BY RAY ALLEN'S ELECTRONICS, INC. BUTLER, GA.

RAY ALLEN'S ELECTRONICS, INC.
53-A6 Hanger Drive • Butler, Georgia 31006
Ph. 478-862-3033 • FAA CRS #HS4R243M

test alt. ft.	tol.	actual +or-ft.	friction	tol.	actual +or-ft.	case leak
-1000	20	+20	1000	70	30	0
0	20	+10	2000	70	20	hysteresis
500	20	0	3000	70	30	+or-ft.
1000	20	0	5000	70	40	50/-20
1500	25	0	10000	80	45	40/-10
2000	30	0	15000	90	45	after effect
3000	30	-10	20000	100	50	tot + ft.
4000	35	-10	25000	120		5
6000	40	-25	30000	140		
8000	60	-25	35000	160		
10000	80	-5	baro scale check tol. +or-ft. + scale error			date
12000	90	0				6 Oct
14000	100	-15				2015
16000	110	0	im.mg	mon.	actual	N66189
18000	120	-5	28.10	-1727	1720	Cessna
20000	130	-5	28.50	-1340	1330	172P
22000	140		29.00	-863	855	KING
25000	155		29.50	-392	380	KT-76A
30000	180		29.92	.0	0	
35000	205		30.50	+531	545	UNITED
			30.90	+893	900	STD ACT
			30.99	+974	990	

DF
S.)

DATE RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS

Glynco Manning Aviation
Brunswick Golden Isles Airport (BQK)
Brunswick, Georgia 31525

2 November 2015

N66189 Cessna: 172P S/N: 17275976

Tach: 3142.5 Total Time: 3142.5 Hobbs: 295.5

Engine Total Time: 3142.5 Engine T.S.M.O.H: 1237.3

AIRFRAME LOG

Removed all inspection panels for inspection. Inspected all pulleys, cables and belcranks using Cessna 172 Service Manual check list and FAR 43, Appendix D.

Removed all wheels. Cleaned, inspected and repacked wheel bearings.

Replaced right main tire, 600 X 6.

Replaced all brake pads. Replaced O-Rings on right brake assy. Serviced brake system with MIL-H-5606 fluid.

Replaced all fuel and oil hoses with new hoses from A.E.R.O hose shop. Certificate of Conformance Ref. Invoice H-27244-1, and H-27254-1 attached.

Replaced ELT battery. New battery replacement date is July 2017. Tested ELT I/A/W FAR 91.207(d) Operation check was normal. Altimeter and Static check was C/W by Ray Allen's Electronics Inc on 6 October 2015.

C/W the following AD's.

AD-78-23-01 Inspection of Bendix Ignition Switches


AD-11-10-09 Inspection of Pilots and Co-Pilots Seat Track Wear and Seat Pin Engagement. Next inspection is due at 3242.5 aircraft hours or next annual inspection.

"I certify that this Airframe has been inspected I/A/W an Annual Inspection and was found to be in an airworthy condition." (END)

Signed:

Richard F. Manning Jr
A&P 256984352 IA

2 November 2015

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2012				
29 March 2012				N66189 Cessna 172P S/N: 17275976
TACH: 3087.5				Performed 100 Hour Inspection using
Hobbs: 223.3				Cessna Service Manual Check List and
				FAR 43 Appendix.
				1) Replaced Left MAIN Tire
				2) Replaced Engine Air Filter (BA-6108)
				3) Checked ELT I/A/W FAR 91.207(d) operation
				check WAS NORMAL.
				4) C/W AD 2011-10-09 Inspection of Seat
				RAILS and Roller Housing.
				5) Seat Tracks and Roller must be replaced
				at next Annual Inspection or 100 Hour Inspection
				Seat Tracks are on order. I certify that this
				Airframe has been inspected I/A/W A 100 Hour
				Inspection and WAS found to be in an Airworthy
				condition (END)
				
				RICHARD F. MANNING, JR.
				256984352 A+P/IA

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2013				
				Glynco Manning Aviation
				Brunswick Golden Isles Airport (BQK)
				Brunswick, Georgia 31525

30 August 2013

N66189 Cessna: 172P S/N: 17275976

Tach: 3135.0 Total Time: 3135.0 Hobbs: 285.5

Engine Total Time: 3135.0 Engine T.S.M.O.H: 1229.8

AIRFRAME LOG

Removed all inspection panels for inspection. Inspected all pulleys, cables and bellcranks using Cessna Service Manual Check List and FAR 43, Appendix D.

Removed all wheels. Cleaned, inspected and repacked wheel bearings.

Inspected brake discs and linings for wear. Checked all flight controls for freedom of movement and proper operation. Checked wing structure and skins for cracks and wrinkles, loose rivets, corrosion and other damage. Checked vertical and horizontal stabilizers, tips and tail cone.

Replaced engine air filter element P/N: BA-6108.

Replaced ELT battery. New battery replacement date is August 2015


Tested ELT I/A/W FAR 91.207(d) Ops checked normal.

C/W the following AD's.

AD-78-23-01 Inspection of Bendix Ignition Switches.

AD-11-10-09 Inspection of Pilots and Co-Pilots Seat Track Wear and Seat Pin Engagement by replacement of both Pilots and Co-Pilots Seat Track Rails and Seat Rollers. Next Inspection Due at 3235.0 Hours or next Annual Inspection.

"I certify that this Airframe has been inspected I/A/W an Annual Inspection and was found to be in an airworthy condition." (END)


Richard F. Manning Jr.
A&P 256984352 IA

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------	---------------------------	------------------	-----------------------------	---

RAY ALLEN'S ELECTRONICS, INC.
53-A6 Hanger Drive • Butler, Georgia 31006
Ph. 478-862-3033 • FAA CRS #HS4R243M

test alt. ft.	tol.	actual +or-ft.	friction	tol.	actual +or-ft.	case leak
-1000	20	+20	1000	70	25	0
0	20	+5	2000	70	30	hysteresis
500	20	+5	3000	70	30	+or-ft.
1000	20	-5	6000	70	30	50/-5
1500	25	+5	10000	80	25	40/-30
2000	30	0	16000	90	25	after effect
4000	35	-20	20000	100	30	tol + ft.
6000	40	-20	25000	120		20
8000	60	-10	30000	140		ANE
10000	80	-35	35000	160		KT-76A
12000	90	-10	40000	180		
14000	100	-5	45000	280		
16000	110	-5	baro scale check			date
18000	120	+5	tol. +or-ft. + scale			
20000	130	+10	error			
22000	140		im.mg	mon.	actual	
25000	155		28.10	-1727	1720	N 66189
30000	180		28.50	-1340	1335	Cessna
35000	205		29.00	-863	860	172 P
			29.50	-392	395	UNITED
			29.92	.0	0	STADAL
			30.00	+71	70	
			30.50	+531	530	
			31.00	+984	985	

DATE 2011	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------	---------------------------	------------------	-----------------------------	---

SOUTHERN AIRCRAFT MAINTENANCE INC
Brunswick Golden Isles Airport (BQK)
Brunswick, Georgia 31525

12 July 2011

N66189 Cessna 172P S/N: 17275976

Tach: 2986.4 Hobbs: 93.7 T.T.A.F: 2986.4

Engine Total Time: 2986.4 T.S.M.O.H: 1081.2

Removed all inspection panels for inspection. Inspected all pulleys, cables and belcranks using Cessna Service Manual Check List and FAR 43, Appendix D.

Removed all wheels, cleaned, inspected and repacked wheel bearings.


Serviced shimmy damper. Inspected all brake pads and disks.

Replaced ELT Battery. New replacement date is **JUNE 2013**.

Tested ELT I/A/W FAR 91.207(d) Operation check was normal.

Replaced Brackett air filter. Checked AD's thru this date using TDATA.

"I certify that this **AIRFRAME** has been inspected I/A/W an **ANNUAL INSPECTION** and was found to be in an airworthy condition." (END)


Richard F. Manning Jr.
A&P 256984352 IA

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
------	---------------------------	------------------	-----------------------------	---

15 June 2009

N66189 Cessna 172P S/N: 17275976

Tach: 2952.0 Hobbs: 48.0

Engine Total Time: 2952.0 T.S.M.O.H: 1046.8

Removed all inspection panels for inspection. Inspected all pulleys, cables and belcranks usin Cessna 172P Service Manual and FAR 43, Appendix D.

- 1) Removed all wheels.
 - 2) Cleaned, inspected and repacked wheel bearings.
 - 3) Inspected all brake pads and disk.
 - 4) Replaced ELT battery.
 - 5) Tested ELT I/A/W FAR 91.207(d) Operation test was normal.
- C/W the following AD"s.


AD-76-07-12 Inspection of Bendix Ignition Switch.

AD-87-20-03R2 Inspection of Pilots and Co-pilots seat tracks and pin engagement.

AD-08-10-02 Inspection of Alternate Static Air Source Selector Valve. This AD does not apply to this aircraft.

AD-2001-23-03 Inspection of Door Post Map Light Switch Insulator.

"I certify that this Airframe has been inspected I/A/W an Annual Inspection and was found to be in an airworthy condition." (END)

Signed:  15 June 2009

Richard F, Manning Jr Southern Aircraft Maintenance Inc
A&P 256984352 IA Brunswick, Georgia 31525

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
------	---------------------------	------------------	-----------------------------	---

10 July 2010

N66189 Cessna 172P S/N 17275976

TACH: 2955.7 T.T.A.F: 2955.7

Removed all inspection panels. Inspected all pulleys, cables and belcranks I/A/W Cessna Service Manual and FAR 43, Appendix D.

Removed wheels. Cleaned, inspected and repacked wheel bearings.

Lubed all pulleys and belcranks.

ELT Battery replacement date is July 2010.

Tested ELT I/A/W FAR 91.207 (D) and found to be operating correctly.

Checked all AD's thru this date using T-DATA disk 2007-07A


C/W AD76-07-12 Inspection of Ignition Switch.

C/W AD87-20-03R2 Inspection of Seat Tracks and Seat Pin Engagement.

C/W AD01-23-03 Inspection of Door Post Map Light Switch Insulator


Sprayed aircraft with CCR-36 corrosion control.

"I certify that this Aircraft has been inspected I/A/W an Annual Inspection and was found to be in an airworthy condition." (END)

Signed:  10 July 2010

Richard F, Manning Jr Southern Aircraft Maintenance
A&P 256984352 IA Brunswick, Georgia 31525

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				Palmetto Aviation Repair, LLC 125 Airport Road Saint Simons Island, GA 31522 912-638-8667 Date: Dec 5, 2008 N: 66189 Log: Airframe Make: Cessna Model: 172P S/N: 17275976 Tach: Hobbs: Removed: Cessna Audio Control, R 402A Marker Receiver, Cessna Marker Antenna, Cessna RT 385A Nav/Com + Mount, Cessna RT 385A Nav/Com + Mount, Cessna R 443B Glidescope Receiver, Cessna IN 381A CDI, Cessna IN 380AC CDI, Nav/Com Wiring, Cessna R 546E ADF 300 Receiver, Cessna IN 346A ADF Indicator, Cessna wire sense antenna, Cessna L 346 A Loop Antenna, ADF Wiring, Cessna RT 359A Transponder, Inoperative FN-200-14v cooling fan. Installed: PS Engineering PMA6000 Audio/ICS C09782-R07799, Bendix/King KMD 250 MFD 1101, Bendix/King KLN 94 GPS 20261, Bendix/King KX 165 Nav/Comm w G/S 59232, Bendix/King KX 165 Nav/Comm w G/S 61432, Bendix/King KI 209A GPS/Nav CDI 8854, Bendix/King KI 204 Nav CDI w G/S 11659, Bendix/King KT76A Transponder 130532, Bendix/King KDR 610 XM Data Receiver 818000806, Comant CI 420-220 GPS Antenna 125933, Comant CI 420-1 XM Data Antenna 200502, FN-200-28v cooling fan. Replaced all Avionics circuit breakers with pullable type. Completed FFA form 337, new aircraft weight & balance. Ops check normal.  Kirk A. Ramsey A&P 250534036 IA

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				Palmetto Aviation Repair, LLC 125 Airport Road Saint Simons Island, GA 31522 912-638-8667 Date: 30 JAN 2009 N: 66189 Log: AIRFRAME Make: CESSNA Model: 172P S/N: 17275976 Tach: 2949.0 Hobbs: 43.9 1. INSTALLED OVERHAULED OIL TEMP/PRESSURE CLUSTER, P/N C669564-0101 S/N 1672. UNIT OVERHAULED BY AIR PARTS OF LOCK HAVEN, INC. OPS CHECK NORMAL. GREASED NOSE LANDING GEAR ASSEMBLY. SERVICED NOSE STRUT WITH DRY NITROGEN. RE-SEALED SHIMMEY DAMPNER AND SERVICED WITH MIL-5606 HYDRAULIC FLUID. ALL WORK DONE IN ACCORDANCE WITH CESSNA 172 M.M. OPS AND LEAK CHECK OK. INSTALLED FUSE IN CLOCK CIRCUIT. OPS CHECK NORMAL. INSTALLED NEW LOW VACCUUM WARNING LIGHT P/N S2519-2. OPS CHECK NORMAL.  Kirk A. Ramsey A&P 250534036 IA

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
------	---------------------------	------------------	-----------------------------	---

2008
20 May 2008

N66189 Cessna 172P S/N 17275976

TACH: 2940.3 T.T.A.F: 2940.3

Removed all inspection panels. Inspected all pulleys, cables and belcranks I/A/W Cessna Service Manual and FAR 43, Appendix D.

Removed wheels. Cleaned, inspected and repacked wheel bearings.

Lubed all pulleys and belcranks.

ELT Battery, New replacement date is **Feb 2009**.

Tested ELT I/A/W FAR 91.207 (D) and found to be operating correctly.

Checked all AD's thru this date using T-DATA disk 2007-07A


C/W AD76-07-12 Inspection of Ignition Switch.

C/W AD87-20-03R2 Inspection of Seat Tracks and Seat Pin Engagement.

C/W AD01-23-03 Inspection of Door Post Map Light Switch Insulator

Sprayed aircraft with CCR-36 corrosion control.

"I certify that this **Aircraft** has been inspected I/A/W an **Annual Inspection** and was found to be in an airworthy condition." (END)

Signed: 
Richard F. Manning Jr
256984352A&P, IA

20 May 2008

Southern Aircraft Maintenance, Inc
Brunswick, Georgia 31525

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
------	---------------------------	------------------	-----------------------------	---


2008

TACH: 2943.0
AUG 28 2008

T.T.A.F. 2943.0

Removed all seats and sent to be
recovered. Reinstalled seats and seat stops.
Aircraft returned to Airworthy condition (END)

AUG 28 2008


Richard Manning Jr
A&P 256984352, IA


19 December 2008

N66189 Cessna 172P S/N: 17275976

Tach: 2945.0 Hobbs: 43.8 T.T.A.F: 2945.0

Removed Engine Starter P/N: PM2401-H, S/N: 85B29419 and installed new overhauled
starter P/N: PM2401-H, S/N: 85E59501.

Replaced Brackett air filter. Ground operations check normal. Aircraft returned to
airworthy condition (END)

Signed: 
Richard F. Manning Jr
256984352A&P, IA

19 December 2008

Southern aircraft Maintenance Inc
Brunswick, Georgia 31525

DATE 2007	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
12 April 2007	N66189	Cessna 172P	S/N 17275976	
	TACH: 2935.8	T.T.A.F: 2935.8		
				Removed all inspection panels. Inspected all pulleys, cables and belcranks I/A/W Cessna Service Manual and FAR 43, Appendix D.
				Removed wheels. Cleaned, inspected and repacked wheel bearings.
				Lubed all pulleys and belcranks.
				Replaced ELT Battery, New replacement date is Feb 2009 .
				Tested ELT I/A/W FAR 91.207 (D) and found to be operating correctly.
				Checked all AD's thru this date using T-DATA disk 2007-07A
				C/W AD76-07-12 Inspection of Ignition Switch.
				C/W AD87-20-03R2 Inspection of Seat Tracks and Seat Pin Engagement.
				C/W AD01-23-03 Inspection of Door Post Map Light Switch Insulator
				Sprayed aircraft with CCR-36 corrosion control.
				"I certify that this <u>Aircraft</u> has been inspected I/A/W an <u>Annual Inspection</u> and was found to be in an airworthy condition." (END)
	Signed:			
	Richard F, Manning Jr		12 April 2007	
	256984352A&P, IA			
	Southern Aircraft Maintenance, Inc			
	Brunswick, Georgia 31525			

REPLACE ELT BATTERY BY:

FEB '09

DATE 2007	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
22 June 2007	Tach: 2936.5	Hobbs: 0042.1		
				Replaced Engine Starter Assy P/N PM2401 with New Starter Assy P/N PM2401.
				Replaced Aircraft Battery with new Gill, G-243 Battery.
				Ground Checked normal. (END)
	Signed:			
	Richard F, Manning Jr	256984352A&P, IA	22 June 2007	
	Southern Aircraft Maintenance Inc			
	Brunswick, Georgia 31525			

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2005				
	2902.9		2902.9	A.D. 2001-23-03 (DOOR POST MAP LIGHT SWITCH INSUL.)
	C/W 134	VISUAL	INSP.	ALL A.D.S THRU 2005-04 C/W.
				I CERTIFY AS OF THIS DATE THAT THIS AIRCRAFT
				HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR
				INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY
				CONDITION. TOTAL TIME 2902.9 TECH. TIME 2902.9 I CERTIFY AS OF THIS DATE THAT THIS AIRCRAFT
				HAS BEEN INSPECTED IN ACCORDANCE WITH
				INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY
	2902.9		2902.9	Edward J. Simpson A4P1327568
3/1/05			3902.9	Edward J. Simpson A4P1327568 I.A.

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19__				
				N66189
				TACH 2927.4
				S/N 17275976
				March-6-2006
				PERFORMED AN ANNUAL INSPECTION. Removed all inspection plates, lubed and
				inspected all control cables and pulleys. Jacked aircraft. Lube landing gear checked
				brakes, tires, wheel bearings ok. C/W AD76-07-12 bendy magi switch C/W all AD notes
				see list Replaced battery Gill Go2246820 I certify that this aircraft has been inspected
				with an annual inspection and found to be in airworthy condition. - END -
				AP259316984IA
				Lewis Keith manning
				Lewis Keith manning

DATE 2004	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
July 8, 2004				Replaced battery with New 24v Hobbs fuse found blown at 3715 Hrs 2 hrs checks with Flite Report # 2.5 hrs additional 3722.5 = 3056.8 TTAF
January 10, 2005				Replaced all 4 front seat tracks by riveting in place using existing holes tracks made by McFarlane Aviation FAP PMA part # MC2414002-1, MC2414002-2 (2 each out LH & RH -1 Lot 10220 -2 Lot #10311 in LH out RH Replaced Landing light TTAF 3058.8 H.F. Ropp A&P/A 264704375
1-10-05				Replaced ^{BTH} Steering Rod Boots New boots made by McFarlane Aviation MC05413015-6 Lot 12269 Lubed control arms

DATE 2005	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
3/12/05	2902.9		2902.9	PERFORMED 100HR INSP. PER CHECKLIST. TACH RECORDING PORTION INOP. REMOVED TACH FOR REPAIR BY RUDY INST. SERV. (TACH WAS READING 2546.7) TACH RESET TO INCLUDE TOTAL FLIGHT TIME PER OWNER'S RECORDS. SERVICED NOSE STRUT WITH 5606 & AIR. REPLACED TWO TORN LORD MOUNTS FOR COWLING. REPAIRED BOTH TOP MOUNTING FLANGES ON TOP OF NOSE WHEEL PANT. CLEANED & REPACKED ALL WHEEL BEARINGS. REPLACED NOSE WHEEL TIRE DUE TO 3 AREAS OF CUPPING & TIRE BADLY WORN & OUT BALANCE. ALSO SERVICED NOSE WHEEL SHIMMY DAMPER & GREASED N/L/G. REPLACED 4509 LANDING LIGHT BULB. REPLACED 1 AMP FUSES IN CLOCK & HOBBS METER. REPLACED BATTERY VENT TUBE. SERVICED BOTH BRAKE W/ CYLS WITH 5606. PITOT HEAT INOP - RECONNECTED WIRE. REPLACED HOBBS METER. REPLACED FOUR BROKEN STATIC WICKS (P.N. C234-200). LUBED & CHECKED ALL FLIGHT & ENGINE CONTROLS. C/W A.D. 83-20-03 R2 (SEAT TRACKS) BY VISUAL INSP. A.D. 96-07-12 (BENDIX MAG SW) C/W ON RUN-UP. A.D. 96-09-06 (BRACKETT AIR FILTER GASKET) C/W BY VISUAL INSP. A.D. 83-22-06 (AL. HANG PINS) & W/ BY VISUAL INSP.

DATE 2003 12	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
March	15			Recording portion Tach loop Hobbs 3713.0 TTAF 3049.3 checked and lubed controls cleaned gascolator New O'Rings serviced Nose Strut Brake Reservoirs Replaced Brake pads both sides greased all wheel bearings Complied with AD 97-20-03 R2 by Inspection C/W 2001-23-03 by Inspection OK. serviced Battery I certify that this aircraft has been inspected in accordance with an Annual Inspection and has been found to be in an air worthy condition H.F. Ropp HEP IA 264709378 ✓
				I inspected the Donin Margolin ELT system in this Aircraft according to applicable Aircraft and ELT manufacturers Instructions and applicable FAA Guidance and found that it meets the Requirements of Sec 91.207(d) H.F. Ropp HEP IA 264709378 ✓ Battery due April 2004

DATE 2004 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
March	10			Recording Portion Tach loop Hobbs Meter failed at 3715.0 according to flight papers A/C flew 5.5 Hrs after failure TTAF 3056.8 checked and lubed control cleaned gascolator New O'Rings serviced Brakes & Battery Complied with 92-20-03 by Inspection C/W 2001-23-03 by Inspection OK. I certify that this aircraft has been inspected in accordance with an Annual Inspection and has been found to be in an air worthy condition H.F. Ropp HEP IA 264709378 ✓
				Replaced ELT Battery new battery Due 7-06 Inspected the Donin Margolin ELT system in this Aircraft according to applicable Aircraft and ELT manufacturers Instructions and applicable FAA Guidance and found that it meets the Requirements of Sec 91.207(d) H.F. Ropp HEP IA 264709378 ✓ 3-10-04

DATE 2001 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
March 1-2001				Tach recording portion hop Hobbs 3692.1 TTAF 3028.4 Checked & lubed controls Cleared Gascelator New O-rings AD 2000-06-01 NA by date. Measured in accordance with AD found OK. Greased wheel bearings serviced battery and brake fluid. CW AD 87-20-0382 by inspection ELT Battery due 6-01. I certify that this Aircraft has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition H.F. Rapp AEP 1A 264709378
5-20-2001				ELT Battery Replaced May 20, 2001 New battery due April 2004 I inspected Doris Margolin ELT system in this Aircraft according to applicable Aircraft and ELT manufacturers instructions and applicable FAA guidance and found that it meets the requirements of sec 91.207(d) H.F. Rapp AEP 1A 264709378

DATE 2002 3	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
March 10				Recording tach Portion hop Hobbs 3702.0 TTAF 3038.3 Checked and lubed controls cleared gascelator New O-rings. serviced Nose Strut and brake reservoirs Complied with AD 87-20-0382 by inspection OK Complied with AD 2001-23-03 by inspection OK I certify that this aircraft has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition H.F. Rapp AEP 1A 264709378
				I inspected the Doris Margolin ELT system in this Aircraft according to applicable Aircraft and ELT manufacturers instructions and applicable FAA guidance and found that it meets the requirements of section 91.207(d) H.F. Rapp AEP 1A 264709378 3-10-2002

DATE 19 ⁹⁹	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------------------	---------------------------	------------------	-----------------------------	---

December 7, 1999 - Tach Time 2548.7 40665 - 3587.7
 T7AF-29244. Repacked wheel bearings. Checked + lubed
 all controls. Inspected + checked all engine controls.
 Replaced both main gear tires + nose wheel tires.
 Drained + cleaned oil sump + replaced gaskets.
 Complied with AD-87-20-03 R2 by inspection. ELT
 checked OK. Battery due date - June 2001.
 I certify this aircraft was inspected in accordance
 with an annual inspection + was found to be in
 an airworthy condition. RU Jones - 1882326

DATE 2000 12	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
--------------------	---------------------------	------------------	-----------------------------	---

December 19, 2000. Tach- 2548.7 40665 = 3677.8. T7AF-2014.4
 Repacked wheel bearings - lubed all controls. Inspected + checked
 all engine controls. Serviced nose strut - Serviced battery
 Complied with AD-87-20-03 by inspection. ELT checks OK
 Battery due June 2001. I certify this aircraft was
 inspected in accordance with an annual inspection + was
 found to be in an airworthy condition
 RU Jones - 1882326/A

DATE	RECORDING TACH TIME	FLIGHT	ALTERATIONS
19__			(SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
MOBILE AVIONICS, INC. 31W 741 North Ave. West Chicago, IL 60185			
Date <u>5-11-98</u>	Work Order No. <u>1632</u>	I certify that the static system checks required by FAR 91.411 have been performed this date and found to comply with Part 43, Appendix E, Para. A.	
Signed for CRS No. M5BR6621 MOBILE AVIONICS, INC. 31W 741 North Ave. West Chicago, IL 60185			
Date <u>5-11-98</u>	Work Order No. <u>1632</u>	I certify that the ATC transponder test and inspections required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F.	
Make <u>ARC</u> Model <u>RT385</u> Serial No. <u>30015</u> <u>7W16640</u>			
Signed for CRS No. M5BR6621 MOBILE AVIONICS, INC. 31W 741 North Ave. West Chicago, IL 60185			
Date <u>5-11-98</u>	Work Order No. <u>1632</u>	I certify that the automatic pressure altitude reporting system checks required by FAR 91.217 and FAR 91.411 have been performed this date and were found to comply with Part 43, Appendix E, Paragraph C.	
Transponder Serial No. <u>30015</u> Encoder Serial No. <u>45088</u> <u>7W16640</u>			
Signed for CRS No. M5BR6621			

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS
19__				ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19 <u>98</u>				December 6, 1998 Tach time 2548 7/10 Hobbs 3362.00 Repacked wheel bearings lubed and checked controls replaced Flexible Baffles in engine compartment Drain cleaned, and replaced Gascolator Gaskets AD <u>87-201-03-Rev</u> c/w by inspection of seat & tracks OK. ELT Checked O.K. Battery Due date June 2001 I certify this AIRFRAME WAS INSPECTED IAW an ANNUAL INSPECTION + was found to be in an AIRWORTHY condition. <u>RUW</u> - 18823261A

DATE 19 <u>96</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
Nov 14	TAF	2402 1/10		Tach time 2402 1/10 Hobbs 30647/10 Serviced Nose strut rebuild shimmy dampner & Robusdell Nose gear Torque links with New AN Bolts. Greased main & Nose wheel bearings lubed all controls C/w AD 87-20-03-RB by inspection ADs checked thru 96-23 None applicable see back log I certify that this Aircraft has been inspected in accordance with an annual inspection and has been found to be in an Airworthy condition H.F. Ropp AEP 1A 264709378 ✓✓ ELT checked a new battery installed Date Dec, 1998
Dec 8, 1996				Installed New Flap rollers, spacer & bolt upper Ressa SEB 95-3 on both flaps & checked flap operation found OK. H.F. Ropp AEP 1A 264-70-9378 ✓✓

DATE 19 <u>97</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
December		3, 1997		Hobbs 3180 0/10 Tach 2498 1/10 Replaced Left & Right brake pads checked & lubed all controls, Replaced outboard Landing light Replaced Alternator Control unit with Zetronics R25-400 STC # SA 84275W Complied with AD 96-09-06 by inspection No new A.D. Thru 12-3-97 Replaced Gasculator Gasket & cleaned Screens I have inspected this Aircraft in accordance with an annual inspection & was found to be in an Airworthy condition. RULOW AID-1A-1885524
April 7, 1998				Replaced Master Switch Battery Connection with New part # 52475-2 supplied by Duncan Aviation (Cessna) Installed New Battery type CB24-11M Ser# 278979 H.F. Ropp AEP 1A 264709378 ✓✓

DATE 19 <u>94</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
	2326-9			PERFORMED AN ANNUAL INSP. USING AN
#1	2326-9			APPROVED & LIST checked all controls for proper
				movement & wiring, oiled & lubed all rollers hinges
				settings drained all fuel sumps & cleaned screens
				Replaced EIT bat due 7/96 OPEC EIT NO/MDL
				changed 93-5-6 installed diode & replaced switch back
				A 3600 inst due 1000 115. clw del 87-20-03 by INSP
				NO Action Required at this time. Ad's chd turn 04-18
				CERTIFY THAT THIS AIRCRAFT/ENGINE HAS BEEN
				INSPECTED IN ACCORDANCE WITH A <u>11 ANNUAL</u>
				INSPECTION AND DETERMINED TO BE IN AIRWORTHY
				CONDITION. PERTINENT DETAILS OF THIS INSPEC-
				TION ARE ON FILE AT THIS AGENCY UNDER WORK
				ORDER NO. <u>3749</u> DATE <u>10/18/94</u>
				WESTOSHA AIRCRAFT
				WILMOT, WISCONSIN
				<u>W. H. C. W.</u> AIP 3325245843 PD

DATE 19 <u>95</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
	Tach	2373	2	At this time the Airframe was insp TAO an
10/26	TT.	2373	2	annual insp. Flt. Controls were checked for
				proper rig and lubed as required fuel sumps
				were drained and screens cleaned Flt Bat
				red due 7/96 AB 87-20-03 c/w by insp.
				NO Action Required at this time AB 95-03-02 c/w
				By insp. of Airfilter gasket & on A/S checked
				THRU 95-21
				CERTIFY THAT THIS AIRCRAFT/ENGINE HAS BEEN
				INSPECTED IN ACCORDANCE WITH A <u>ANNUAL</u>
				INSPECTION AND DETERMINED TO BE IN AIRWORTHY
				CONDITION. PERTINENT DETAILS OF THIS INSPEC-
				TION ARE ON FILE AT THIS AGENCY UNDER WORK
				ORDER NO. <u>4217</u> DATE <u>10-26-95</u>
				WESTOSHA AIRCRAFT
				WILMOT, WISCONSIN <u>W. H. C. W.</u> AIP 3325245843 PD

AIRCRAFT RECORD — GENERAL INFORMATION

MANUFACTURER Cessna MODEL 172P SERIAL 17275976

REGISTRATION NUMBER N66189 DATE MFG. 1983

ENGINE(S) CURRENTLY INSTALLED.

MFG _____ MODEL _____ SERIAL _____

MFG _____ MODEL _____ SERIAL _____

PROPELLER(S) CURRENTLY INSTALLED.

MFG _____ MODEL _____

HUB MODEL _____ SERIAL _____ SERIAL _____

BLADE MODEL _____ SERIAL _____ SERIAL _____ SERIAL _____

BLADE MODEL _____ SERIAL _____ SERIAL _____ SERIAL _____



The Standard

AIRCRAFT LOG



Aircraft Flight and Maintenance Log

SERVICE INFORMATION LETTER AND AIRWORTHINESS DIRECTIVE LOG

[illegible]

AIRCRAFT LOG							
DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IO THS	
19 EACH #	2329. 2329.		performed AN ANNUAL INSPECTION USING AN APPROVED CHECK LIST. checked ALL CONTROLS FOR PROPER MOVEMENT & rigging oiled & Lubed ALL AXLES, WINGS, BEARINGS. drained ALL FUEL SUMPS & cleaned screens REPLACED LEFT AIRLIFTER ON OTHER STATIC DISCHARGER. Replaced elevator inter static discharger replaced ALL Aileron rod ends Rebuilt nose strut SKIN-IF installed. Replaced MAIN FIRE CLW NO 8720-05 by 1452. No further action required at this time done again 2329. check it for operation OK but due AUG 92 ADS checked thru 91-17				
I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THIS INSPECTION ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 3288 DATE 10/6/91							
Michael CCE APP 332545843 JVA				WESLEY AMUNDSON			

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

[illegible]

NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
		HOURS	10THS	
INSPECTION USING AN APPROVED CHECKLIST FOR PROPER MAINTENANCE & REPAIRING. MAINTAINED OILED & LUBED AIR PELLETS. REPLACED LEFT FLAP OPERATION OK BATTERY DUE 3/40 CHARGED REQUIRED AT THIS TIME. BCS CHECKED FIVE				
1) THAT THIS AIRCRAFT/ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>WILMOT</u> INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THIS INSPECTION ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. <u>7/14/87</u> DATE <u>7/14/87</u>				
WESTOSHA AIRCRAFT WILMOT, WISCONSIN				
TIME TO THE TOP OF NEXT PAGE				

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
VOR 1	VOR 2			19	
09/02/90				90	At This Time the Airframe was insp. IAW a annual insp. using an approved Y List. Controls were vcd For proper Rigging and Lubed as Required. Fuel Sumps were cleaned and Drained. The Lt. Outer Brake Pad was Replaced. all wheel Bearings were Packed and The Nose strut was serviced a New ELT Battery was installed Exp. Date Aug 92 AD 87-20-03 was c/w By insp. as Per AD No Action Required at this Time All AD's vcd Thru 9-2-90 See AD List For compliance Dates and Times I certify that this Airframe Has Been insp. IAW an annual insp. and Found To Be in an airworthy condition
		T.T. 2196	O		BRN Pet A+P 339666083IA

AIRCRAFT LOG

[illegible]

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
VOR 1	VOR 2			19__	
		taken 207-1.3			PERFORMED AN ANNUAL INSPECTION USING THE APPROVED CHECKLIST.
		TT.			CHECKED ALL COURSES FOR PROPER MAGNETIC & VARIATION. & LOCATED ALL PIPES
					NUTS & LEAKINGS. REPLACED NOSE WHEEL BEARINGS & RACE. STAINED ALL FUEL Sumps
					& CLEANED SEVERUS. REPLACED GYRO CONTROL FILTER UG-18-1 & XJAC FOR FILTER
					UG-5-1. REPLACED 6 COOL SHOCK MOUNTS S115-29. REPLACED 1 COOL
					RECEPTACLE S115-19. REPLACED VACUUM PUMP SIGMA PER JWF 28-005.
					CLUB 87-20-03. BY INSPIR NO ACTION REQUIRED AT THIS TIME DUE TO
					INSPIR taken 2174.3 CHECKED EGT FOR OPERATION OK BUT DUE MAY 90.
					AOS CHECKED T410 88-9
					I CERTIFY THAT THIS AIRCRAFT/ENGINE HAS BEEN
					INSPECTED IN ACCORDANCE WITH AN <u>ANNUAL</u>
					INSPECTION AND DETERMINED TO BE IN AIRWORTHY
					CONDITION. PERTINENT DETAILS OF THIS INSPEC-
					TION ARE ON FILE AT THIS AGENCY UNDER WORK
					ORDER NO. <u>2422</u> DATE <u>6/6/88</u>
					WESTOSHA AIRCRAFT <u>Mitchell</u>
					WILMOT, WISCONSIN <u>WILMOT</u>

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	10THS	
19							
ALTIMETER (S)							
PILOT'S <u>United</u>	C/PILOT'S <u>W/A</u>	ALTIMETER					
S/N <u>08384</u>	S/N						
TEST TO <u>29,000</u> FT							
TESTED BY FAR 91.171 IN ACCORDANCE WITH FAR 43 APPENDIX "E"							
TESTED DATE <u>1/22/87</u>							
JOLIET AVIONICS, INC.							
FAA REPAIR STATION #3159 CLASS III							
SIGNATURE <u>[Signature]</u>							
SYSTEM TESTED THIS DATE <u>1/22/87</u> AS REQUIRED BY FAR 91.171 IN ACCORDANCE WITH FAR 43 APPENDIX "E" PARAGRAPH (a).							
JOLIET AVIONICS, INC.							
FAA REPAIR STATION #3159 CLASS III							
SIGNATURE <u>[Signature]</u>							
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE							

AIRCRAFT LOG

[illegible]

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOths	
19 86							
04-04	T.T. 1673.0 HRS.						
	1.) CHG. NOSE TYRE.						
	2.) REPAIR CABIN VENT.						
	3.) ELT DUE NOV. 86						
	4.) A.D. 83-10-03 N/A BY S/N						
	5.) A.D. 83-22-06 C/N						
	I HAVE INSP. THIS A/C IN ACCORD. W/AN ANNUAL INSP. & HAVE DETERMINED IT TO BE IN AIRWORTHY CONDITION AT THIS TIME. Alan C. Hingle ARP 1910420 LA.						
07-23-86	T.T. 1780.0						
	I HAVE INSP. THIS A/C IN ACCORD. W/A 100 HR. INSP. & HAVE DETERMINED IT TO BE IN AIRWORTHY CONDITION AT THIS TIME. Alan C. Hingle ARP 1910420.						
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE							

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
	VOR 1	VOR 2		19	
11-26-86	Tach	1880.8	Tot. Time 1880.8		
	I have inspected this aircraft in accordance with a 100 hr inspection and have found it to be in airworthy condition at this time.				
	<i>Steven J. Belch ARP 320600103</i>				
05-15-87	1905.2				
	I HAVE INSP. THIS A/C IN ACCORD. W/AN ANNUAL INSP. & HAVE DETERMINED IT TO BE IN AIRWORTHY CONDITION AT THIS TIME. <i>Alan C. Hingle ARP 1910420 LA</i>				

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	10THS	
19 85 3-8-85	TACH: 1201		I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION, Sam M. Paul, JA 1583532				
36-6-85	TACH: 1301.1		I certify that this Airframe has been inspected in accordance with a 100hr inspection and was determined to be in an airworthy condition Maurice P. Hyl A+P 335545891				
7-20-85	TACH: 1401.1		I certify that this Airframe has been inspected in accordance with an 100hr inspection and was determined to be in an airworthy condition. Maurice P. Hyl A+P 335545891				
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE							

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error VOR 1 VOR 2	Place	Signature		
9/7/85				19	Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
9/7/85					Tach time 1501.0 I certify that this airframe has been inspected in accordance with an 100hr inspection and was determined to be in an airworthy condition - Routine maintenance performed according to Cessna maintenance manuals and checklists Maurice P. Hyl A+P 335545891
12-18-85					1600 Tach Time - I certify that this airframe has been inspected in accordance with an 100hr inspection + was determined to be in an airworthy condition. - Routine Maintenance performed as per Cessna Maint Manual + checklists. Maurice P. Hyl 360503545

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOths	
19							
	5-22-84	TACH	(700.5)				
	DATE: 5-22-84 TACH: 700.5 I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 hr. INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. SIGN: [Signature] CERT. NO. AEP 384625798						
	7-4-84	Tach	(801.0)				
	I certify that this A/c has been inspected in accordance with an 100 hr. inspection & was determined to be in an airworthy condition.						
	8/11/84	Tach	(901.5)				
	I certify that this A/c has been inspected in accordance with an 100 hr. inspection & was determined to be in an airworthy condition.						

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
	VOR 1	VOR 2		19	
9/28/84	(1000.0)				I certify this A/c has been insp. in acc. with an 100 hr. insp. & was det. To be in an airworthy condition.
12/7/84	(1100.1)				I certify that this A/c has been inspected in accordance with an 100 hr. insp. & was det. To be in an airworthy condition. EIT. Replacement DATE NOV 86 - Replaced left battery
3/5/85	1201				I certify that this A/c has been inspected in accordance with an 100 hr. inspection & was det. To be in an airworthy condition. Routine Maint. done in accordance with Cessna checklist & manuals.

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOths	
19 83 200.0 8/9/83	Tach.						
	I certify that this aircraft has been inspected in accordance with a 100 hr. inspection and was determined to be in an airworthy condition. Robert W. Mayer 333-604755 End						
9/12/83 Tach 300.1							
	DATE: 9/12/83 TACH: 300.1 I CERTIFY THAT THIS Aircraft HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 Hr. INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION SIGN: [Signature] CERT. NO. 338 549082						

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
	VOR 1 VOR 2			19	Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
10/30/83					
Tach 400.8					I certify that this aircraft has been inspected in accordance with a 100 hr. inspection and was determined to be in an airworthy condition. Robert W. Mayer AEP 333606355 10/30/83 End
JAN 30 1984					
Tach 500.6					I certify that this Aircraft has been inspected in accordance with a 100 hr. Inspection and was determined to be in airworthy condition Stanley Jast AEP 384625798
4/3/84					
Tach 600.0					I certify this A/c inspected in accordance with an annual inspection + found to be in an airworthy condition Ramon M. Camacho IA 1583532
4/25/84					
244 243					DPA VOR 1 HEND TO HEND

AIRCRAFT LOG

[illegible]

AIRCRAFT LOG

[illegible]

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

REMARKS

REMARKS

Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

[illegible]

This aircraft has been inspected, and found to comply with FAR 21.183. All mandatory changes have been incorporated. The altimeter instrument was tested 03-23-83 to an altitude of 20 thousand feet and found to comply with Appendix E of Part 43. Automatic pressure altitude reporting equipment was tested and found to comply with Appendix E of Part 43, and calibrated 03-23-83 in compliance with FAR 91.36(b). The ATC transponder was tested and inspected 04-14-83 and found to comply with Appendix F of Part 43. The static pressure system was tested and inspected in accordance with FAR 91.171, and a Standard Airworthiness Certificate dated 4-26-83 was issued by me, [Signature] Private Engineer

83 was issued by me
Cessna Aircraft Co., Pawnee Div.
Delegation Option Manufacturer, CE-1
By Daniel L. Goble
Daniel L. Goble