

A/C N# **4654R**Prop M/N <u>M740m-0-61</u>

Prop S/N <u>K 7253</u>

INSPECTION BEFORE FLIGHT

1) CHECK PROP-GUARD FOR DELAMINATION 2) CHECK PROP-GUARD FOR NON-TRANSPARENT CONDITION (IF CONDITION 1 OR 2 EXISTS REMOVE BEFORE FLIGHT)

PROP-GUARD AEROSPACE INC. P.N. FP1001 FAA-PMA P.N. CS1002 ELIGIBILITY: SEE ATTACHED APPROVED MODEL LIST

PROPELLER LOGBOOK

The subject aircraft was involved in an incident / accident on _ rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: **0903177159US**.

Signed: Underwriters Salvage Company

Date: 12/11/2024 AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100

MAINTENANCE RECORD

Date	Time Run	T.T.S.O. Desc	cription of all operations pertainin Os S/Bs, S/Ls, and minor adjustme	ng to nts Signature
Date: 12/15/2022 Tail#: N4654R	Hours: F	PropTT: Unknown / TS	POH: 691.7 / Hobbs: 691.7	
Make: Sensenich	N	/lodel : M74DM-0-58	S/N: K7253	
Appendix D. See PROPELLER has	AD Complia been inspe	nce List in aircraft rec	ance with 14 CFR Part 43 ords for details. I certify that this h an ANNUAL inspection and order	060 TA
Date : 04/15/2024 Fail# : N4654R Make : Sensenich		pTT: Unknown / TSP0 del: M74DM-0-58	DH: 709.7 / Tach: 709.7	
Annual Inspection of Appendix D. See AD PROPELLER has be	f propeller co Compliance een inspecte	ompleted in accordance	ce with 14 CFR Part 43 s for details. I certify that this an ANNUAL inspection and	A

MAINTENANCE RECORD

S/14/18 N4654R Tach: 505.86	ature
I certify that this propeller has been inspected in accordance with a 100 hour inspection and approved for return to service. Removed propeller and Re-Installed to proper position IAW Chero kee Service Manual Par. 8-8. 10601 Observation Road Manassas, VA 20110 N4654R SENSENICH M74DM-0-58 Jun 07 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
Removed propeller and re-Installed to proper position [2/2/19 Removed propeller and re-Installed to proper position IAW Chero kee Service Manual Par. 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
Removed propeller and re-Installed to proper position [2/19] Removed propeller and re-Installed to proper position [AW Chero kee Service Manual Par. 8-8. Con 2/20] [AW Chero kee Service Manual Par. 8-8. Con 2/20] [AW Chero kee Service Manual Par. 8-8. Con 2/20] [AW Chero kee Service Manual Propeller SENSENICH M74DM-0-58 Jun 07 [AM Chero kee Service Manual Propeller N4654R] [AW Chero kee Service Manual Propeller N4	s
Removed propeller and re-Installed to proper position IAW Chero kee Service Manual Par. 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
IAW Chero kee Service Manual Par, 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
IAW Chero kee Service Manual Par. 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
IAW Chero kee Service Manual Par. 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
IAW Chero kee Service Manual Par, 8-8. 10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: 1-15828-27F	
10601 Observation Road Propeller SENSENICH M74DM-0-58 Jun 07 WESTSIDE Manassas, VA 20110 N4654R Tach: 539.67 Prop SN: L-15828-27F	10
Performed a Propeller inspection as part of a Annual Inspection with reference to Piper Cherokee Service Manual inspection checklistinspection check list and the scope and detail of 14 CFR 43 Appendix D. Researched ADs through June 07, 2019	
I certify that this Propeller has been inspected as part of a 100hr/Annual Inspection and determined to be in airworthy condition.	
David Carter A&P 3186493 IA	

MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Descri A/Ds	ption of all s S/Bs, S/Ls, o	operations perta and minor adjust	ining to ments		Signature
WES	SIDE	Man	1 Observation Roadssas, VA 20110 368-8100	N4		SENSENICH Tach: 561.04 09 TTAF: 4354	M74DM-0-58 Prop SN: L-15828- 4.74 TSPOH:561.	
Performe — inspectio	Performed a Propeller inspection as part of an Annual Inspection with reference to Sensenich® Service Manual, Piper® Service Manual inspection check list, and the scope and detail of 14 CFR 43 Appendix D.							
Research	ed Propeller ADs	through June 20	20.					
I certify that this Propeller has been inspected a part of a 100hr/Annual Inspection and determined to be in airworthy condition. Eric Litt A&P 1435253 IA								
RENNER AVIATION								
			3600 Carol	Kennedy Dr., S	San Andreas, Ca. 9524	19		
Da	te:10-1-2021	N4654R	Propeller	Tach:660.41	PropTT:unknown	SPOH:66	60.41	
Complied with the following inspections and airworthiness directives:								
1. Annual/100 Hour inspection per 14 CFR Part 43 Appendix D. 2. AD's checked thru this date, none due at this time. I certify that this propeller has been inspected in accordance with an Annual/100 L.								
I certify that this propeller has been inspected in accordance with an Annual/100 hour inspection and was determined to be in an airworthy condition.								
Renner Brewer A&P/IA 3177530								

MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
9/8/06		0.0	MASOR Overhaul a Static Balance	SU
			Refer to Attached U.O. 5137	W59/2659N
			And 8130-3 # 25752 Per Delails &	MAINENANCE Release
9-17-06	, 1 ₁ .		Supplied a Parallella Col	
4.29.06	·	0.0	INSTAILED PRUPEILER ON ENGIN. TORQUED AND FAFETIED	
			BOITS PET SCIULE MANGEL	Som souge when so
		<u> </u>		